

Effective: 25/06/2020 to 25/06/2025
Service: Accident Claims (All Services)
Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Site: Drum Street (7900664)	Locality: Hyvots Bank, Edinburgh, City of Edinburgh	Area: South East Locality
-----------------------------	-----------------------------------------------------	---------------------------

Customer Services

Enquiry No.: 34009932	Logged by: [REDACTED]	on: 15/05/2025 14:30
Service: Accident Claims (All Services)	Subject: Accident Claim Roads/Lighting	Classification: Accident Claim
Desc.: We are instructed by the above named to claim damages in connection with injuries sustained following a road traffic accident which occurred on or around 1st March 2025. The circumstances of the accident are that on or around the above date, our client was the rider of a motorised scooter travelling South East on Drum Street / A772 Gilmerton, Edinburgh. As he passed the junction with Ferniewell Road there is a pothole approximately 1 meter in from the kerb on the road.		
Location:	Contact:	
Enquiry No.: 34007257	Logged by: Nightshift Squad 1	on: 22/07/2023 21:32
Service: Accident Claims (All Services)	Subject: Accident Claim Roads/Lighting	Classification: Accident Claim
Desc.: Pothole		
Location: 39	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1346964	Logged by: [REDACTED]	on: 17/03/2022 16:17
Service: Accident Claims (All Services)	Subject: Accident Claim Roads/Lighting	Classification: Accident Claim
Desc.: 14th of February, on Gilmerton, Drum street i hit the pothole. IT damaged my wheel. Pothole was way deeper than 10cm. I attach a photo of the pothole.		
Location: Exact location is next to mechanic arm gilmerton as you can see on photo i sent.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Site: Drum Street (7900664)			Locality: Hyvots Bank, Edinburgh, City of Edinburgh			Area: South East Locality		
Condition Survey								
Defect No: Description		Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00		Asset - Locn.: Ward 16 - From Ferniehill Road to Gilmerton Station Road			Feature Type: Road Asset		Area: South East Locality	
Batch: 41230365 - Inspection Batch				Route: Ad hoc Route			Date: 09/06/2025	
42185196	Old cover and box rusty damaged	09/06/2025	Outside gilmerton community centre on RU: Utility Apparatus footpath at main road		Internal		Uncommitted	50181069
Batch: 41230278 - Inspection Batch No actionable defects found				Route: South Mobile Inspection Route			Date: 06/06/2025	
Batch: 41227763 - Inspection Batch No actionable defects found				Route: South Mobile Inspection Route			Date: 07/05/2025	
Batch: 41225604 - Inspection Batch No actionable defects found				Route: South Mobile Inspection Route			Date: 09/04/2025	
Batch: 41224551 - Inspection Batch No actionable defects found				Route: Mobile Inspection Strategic			Date: 30/03/2025	
Batch: 41223875 - Inspection Batch No actionable defects found				Route: Mobile Inspection Strategic			Date: 24/03/2025	
Batch: 41222809 - Inspection Batch No actionable defects found				Route: Mobile Inspection Strategic			Date: 15/03/2025	
Batch: 41222395 - Inspection Batch No actionable defects found				Route: South Mobile Inspection Route			Date: 12/03/2025	
Batch: 41221669 - Inspection Batch No actionable defects found				Route: Mobile Inspection Strategic			Date: 06/03/2025	
Batch: 41221043 - Inspection Batch				Route: Ad hoc Route			Date: 28/02/2025	
42177445	Noisy manhole cover	28/02/2025	At junction of newtoft street and drum street on the side of gilmerton community centre	RU: Utility Apparatus	Internal		Uncommitted	50176132
Batch: 41221007 - Inspection Batch No actionable defects found				Route: Mobile Inspection Strategic			Date: 28/02/2025	
Batch: 41220100 - Inspection Batch No actionable defects found				Route: Mobile Inspection Strategic			Date: 20/02/2025	
Batch: 41218857 - Inspection Batch No actionable defects found				Route: Mobile Inspection Strategic			Date: 12/02/2025	
Batch: 41218714 - Inspection Batch No actionable defects found				Route: South Mobile Inspection Route			Date: 12/02/2025	
Batch: 41217370 - Inspection Batch				Route: Ad hoc Route			Date: 04/02/2025	
42174750	1no surround of catv box low	04/02/2025	At entrance into car wash garage outside no80	RD: FW HRA Pothole	Internal		Committed	50174133
Batch: 41217367 - Inspection Batch				Route: Ad hoc Route			Date: 04/02/2025	
42174744	1no surround of catv box low	04/02/2025	Opposite no 117 next to bus stop on fw	RD: FW HRA Pothole	Internal		Committed	50174130

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type:	Road Asset		Area: South East Locality	
Batch:	41217108 - Inspection Batch			Route:	Mobile Inspection Strategic			Date: 31/01/2025
	No actionable defects found							
Batch:	41215795 - Inspection Batch			Route:	Mobile Inspection Strategic			Date: 21/01/2025
	No actionable defects found							
Batch:	41213619 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 09/01/2025
	No actionable defects found							
Batch:	41213074 - Inspection Batch			Route:	SE_CF1_GilmertonRdSouth1			Date: 07/01/2025
42172274	Renew tar around catv box	07/01/2025	Outside 80	RD: FW HRA Depression/Sunker	Internal		Uncommitted	50172283
42172259	Patch needing renewed approximately .5m x width of road	07/01/2025	Outside 3	RD: CW Cracked/Broken	Internal		Uncommitted	50129976
42172258	x2 rocking slabs	07/01/2025	Outside 11	RD: FW Slabs Rocking	Internal		Uncommitted	50172269
Batch:	41211084 - Inspection Batch			Route:	Ad hoc Route			Date: 16/12/2024
42171205	1 no pothole	16/12/2024	At bustop at Iceland	RD: CW Pothole	Internal		Committed	50171429
Batch:	41210884 - Inspection Batch			Route:	Ad hoc Route			Date: 13/12/2024
42171169	No 1 Edinburgh bollard	13/12/2024	At the corner of ravenscroft street	RD: Bollard Damage/Missing/Ne	Internal		Committed	50171393
Batch:	41210341 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 10/12/2024
	No actionable defects found							
Batch:	41208065 - Inspection Batch			Route:	Ad hoc Route			Date: 19/11/2024
42169398	2no fw potholes	19/11/2024	Outside no3	RD: FW HRA Pothole	Internal		Committed	50169995
Batch:	41207392 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 12/11/2024
	No actionable defects found							
Batch:	41203082 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 11/10/2024
	No actionable defects found							
Batch:	41200315 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 10/09/2024
	No actionable defects found							
Batch:	41198683 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 14/08/2024
	No actionable defects found							
Batch:	41196919 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 18/07/2024
	No actionable defects found							
Batch:	41194689 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 18/06/2024
	No actionable defects found							
Batch:	41191867 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 14/05/2024
	No actionable defects found							
Batch:	41188813 - Inspection Batch			Route:	Ad hoc Route			Date: 09/04/2024
42153988	Cw x1 pothole Road: Defective / Damaged (Enquiry 1727612)	09/04/2024	Opposite nursery at. City bound bus stop	RD: CW Pothole	Internal		Committed	50157720

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type:	Road Asset		Area: South East Locality	
Batch:	41188756 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	08/04/2024
	No actionable defects found							
Batch:	41185768 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	11/03/2024
	No actionable defects found							
Batch:	41183457 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	22/02/2024
	No actionable defects found							
Batch:	41182236 - Inspection Batch			Route:	Ad hoc Route		Date:	12/02/2024
42147283	Signs: General Enquiry - Damage pole and sign (Enquiry 34007744)	12/02/2024	Please install new no through road sign on new pole At the junction with Drum Street as per attached documents	RD: Unlit Sign Damaged/Missing	Internal		Committed	50152734
Batch:	41179416 - Inspection Batch			Route:	Ad hoc Route		Date:	21/01/2024
42144587	Scottish Water cover noisy and sunken	21/01/2024	Outside of 38	RU: Utility Apparatus	Internal		Uncommitted	50150703
Batch:	41179274 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	19/01/2024
	No actionable defects found							
Batch:	41178678 - Inspection Batch			Route:	SE_CF1_GilmertonRdSouth1		Date:	17/01/2024
42144157	Patch required around catv box	16/01/2024	Outside 80	RD: FW HRA Depression/Sunker	Internal		Uncommitted	50129980
42144160	Loose manhole cover	16/01/2024	No38 drum st	RU: Utility Apparatus	Internal		Committed	50150301
42144159	Fw sunken exposing toby	16/01/2024	Drum st outside no42	RD: FW HRA Depression/Sunker	Internal		Uncommitted	50150300
42144161	Replace missing bollard	16/01/2024	Drum street opp royal bingo	RD: Bollard Damage/Missing/Ne	Internal		Uncommitted	50087811
42144155	1no damaged bollard	16/01/2024	Drum st opposite abercorn vets	RD: SFP Damaged Bollard	Internal		Committed	50150291
42144154	Patch needing renewed approximately .5m x width of road	16/01/2024	Outside 3	RD: CW Cracked/Broken	Internal		No Action Required	
42144156	Fw resurface required	16/01/2024	CANCEL BEEN DONE	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50129974
42144158	Footway low/sunken	16/01/2024	O/S 48	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50150297
Batch:	41178311 - Inspection Batch			Route:	Ad hoc Route		Date:	12/01/2024
42143917	Manhole cover loose and noisy	12/01/2024	Opposite the junction for Candlemakers	RU: Utility Apparatus	Internal		Uncommitted	50150039
Batch:	41176569 - Inspection Batch			Route:	Ad hoc Route		Date:	03/01/2024
42143015	Scottish water cover noisy and loose	03/01/2024	At the junction with Candlemakers park	RU: Utility Reinstatement	Internal		Uncommitted	50149125
Batch:	41174934 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	19/12/2023
	No actionable defects found							
Batch:	41172125 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	17/11/2023
	No actionable defects found							
Batch:	41171660 - Inspection Batch			Route:	Ad hoc Route		Date:	10/11/2023
42139306	Uplift damaged / collapsed signs pole and sign cones from footway outside house no 84 and make safe footway.	10/11/2023	Outside house no 84 Drum street at junction with Limefield	RD: Unlit Sign Damaged/Missing	Internal		Committed	50145548
Batch:	41168757 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	16/10/2023
	No actionable defects found							

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type:	Road Asset		Area: South East Locality	
Batch:	41166133 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 21/09/2023
	No actionable defects found							
Batch:	41164954 - Inspection Batch			Route:	Ad hoc Route			Date: 13/09/2023
42136165	Defective cover on fw	13/09/2023	Drum street os 50 on fw	RU: Utility Apparatus	Internal		Uncommitted	50142566
Batch:	41164674 - Inspection Batch			Route:	Ad hoc Route			Date: 12/09/2023
42135975	Defective cover on fw not known but suspect Scottish power	12/09/2023	Drum street city bound os 50 on footway	RU: Utility Apparatus	Internal		Uncommitted	50142444
Batch:	41163400 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 22/08/2023
	No actionable defects found							
Batch:	41161222 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 18/07/2023
	No actionable defects found							
Batch:	41159911 - Inspection Batch			Route:	Ad hoc Route			Date: 26/06/2023
42130655	Cw x5 potholes Road: Defective / Damaged (Enquiry 1571874)	26/06/2023	At the junction of Gilmerton Road and Ferniehill Road	RD: CW Pothole	Internal		Committed	50138303
Batch:	41159242 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 14/06/2023
	No actionable defects found							
Batch:	41158224 - Inspection Batch			Route:	Ad hoc Route			Date: 30/05/2023
42128925	Fw x1 pothole Pavement: Damaged / Defective (Enquiry 1558012)	30/05/2023	Outside of 125	RD: FW HRA Pothole	Internal		Committed	50136955
Batch:	41157649 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 19/05/2023
	No actionable defects found							
Batch:	41155671 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 25/04/2023
	No actionable defects found							
Batch:	41155216 - Inspection Batch			Route:	Ad hoc Route			Date: 19/04/2023
42125569	Please install Keep Clear markings	19/04/2023	Opposite east farm of Gilmerton junction northbound	RD: Markings New	Internal		Committed	50134601
Batch:	41154663 - Ad Hoc Inspection Batch			Route:	Ad hoc Route			Date: 12/04/2023
42125120	Installation of dropped crossing	12/04/2023	Outside No.63 as per attached location plan	RD: NEW Dropped Kerbs	Internal		Committed	50134161
Batch:	41153291 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 27/03/2023
	No actionable defects found							
Batch:	41151341 - Inspection Batch			Route:	Ad hoc Route			Date: 06/03/2023
42121345	Cw x 2 potholes Road: Defective / Damaged (Enquiry 1518420)	06/03/2023	At the junction outside the Chemist and BT box outside of number 2	RD: CW Pothole	Internal		Committed	50131169
Batch:	41150950 - Inspection Batch			Route:	Ad hoc Route			Date: 01/03/2023
42120734	Cw x 2 Road: Defective / Damaged (Enquiry 1516961)	01/03/2023	Outside of Faith Mission, opposite Loyds chemist	RD: CW Pothole	Internal		Committed	50130814

Effective: 25/06/2020 to 25/06/2025
 Service: Roads General
 Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type:	Road Asset		Area: South East Locality	
Batch:	41150323 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 24/02/2023
	No actionable defects found							
Batch:	41150085 - Inspection Batch			Route:	SE_CF1_GilmertonRdSouth1			Date: 22/02/2023
42119636	Patch required around catv box	22/02/2023	Outside 80	RD: FW HRA Depression/Sunker	Internal		No Action Required	
42119625	CW patch required	22/02/2023	Drum street opp 117	RD: CW Subsidence/Heaving	Internal		Uncommitted	50042209
42119628	Patch needing renewed approximately .5m x width of road	22/02/2023	Outside 3	RD: CW Cracked/Broken	Internal		No Action Required	
42119624	Fw resurface required	22/02/2023	CANCEL BEEN DONE	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42119632	Replace missing bollard	22/02/2023	Drum street opp royal bingo	RD: Bollard Damage/Missing/Ne	Internal		No Action Required	
Batch:	41148924 - Inspection Batch			Route:	Ad hoc Route			Date: 13/02/2023
42118436	Bollard and pavement damaged please make safe Pavement: Damaged / Defective (Enquiry 1508986)	13/02/2023	Opposite supperbowl	RD: Bollard Damage/Missing/Ne	Internal		Committed	50129144
Batch:	41147625 - Inspection Batch			Route:	Ad hoc Route			Date: 31/01/2023
42117026	Remove x1 yellow housing development sign for "Kings Cove" from directional sign. Leave sign for "Farrier Fields" if installed.	31/01/2023	At rear of house at entrance to the Drum.	RD: Unlit Sign Damaged/Missing	Internal		Committed	50128067
Batch:	41146294 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 24/01/2023
	No actionable defects found							
Batch:	41143400 - Ad Hoc Inspection Batch			Route:	Ad hoc Route			Date: 12/01/2023
42114977	Install new dropped crossing. 1x LH transition, 1x RH transition & 6 x Whin Bullnose (to be lifted and relayed if possible).	12/01/2023	Near junction with Ferniehill Road as per attached plan	RD: NEW Dropped Kerbs	Internal		Committed	50126061
Batch:	41143392 - Ad Hoc Inspection Batch			Route:	Ad hoc Route			Date: 12/01/2023
42114974	Install new dropped crossing. 1x LH Transition, 1x RH Transition, 16 x Buff Tactiles (sticky) & 6 Bull Nose Whin Kerb (lift and relay if possible)	12/01/2023	Opposite No.87 as per the attached plan.	RD: NEW Dropped Kerbs	Internal		Committed	50126058
Batch:	41143388 - Ad Hoc Inspection Batch			Route:	Ad hoc Route			Date: 12/01/2023
42114970	Install new dropped crossings. 1x LH transition, 1 RH transition, 6x Whin Bullnose Kerb (lift and relay if possible) Tactile paving to be installed at drops suitable for stick down tactiles.	12/01/2023	Opposite No.95 (please refer to drawing attached)	RD: NEW Dropped Kerbs	Internal		Committed	50126054
Batch:	41140045 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 19/12/2022
	No actionable defects found							
Batch:	41138087 - Inspection Batch			Route:	Ad hoc Route			Date: 08/12/2022
42112856	Rocking slabs x3	08/12/2022	Drum st at gilmerton cove	RD: FW Slabs Rocking	Internal		Committed	50123853

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 16 - From Ferniehill Road to Gilmerton Station Road			Feature Type: Road Asset		Area: South East Locality	
Batch: 41137119 - Inspection Batch			Route: South Mobile Inspection Route				Date: 29/11/2022	
No actionable defects found								
Batch: 41133689 - Inspection Batch			Route: South Mobile Inspection Route				Date: 24/10/2022	
No actionable defects found								
Batch: 41131547 - Inspection Batch			Route: South Mobile Inspection Route				Date: 26/09/2022	
No actionable defects found								
Batch: 41129908 - Inspection Batch			Route: South Mobile Inspection Route				Date: 22/08/2022	
No actionable defects found								
Batch: 41128279 - Inspection Batch			Route: South Mobile Inspection Route				Date: 26/07/2022	
No actionable defects found								
Batch: 41125971 - Inspection Batch			Route: SE_CW1_South1				Date: 16/06/2022	
42103509	1no pothole	16/06/2022	At the junction of Candlemakers Park	RD: CW Pothole	Internal		Committed	50115428
Batch: 41124125 - Inspection Batch			Route: Ad hoc Route				Date: 13/05/2022	
42101202	Missing apparatus cover	13/05/2022	Drum street in front of no. 38	RU: Utility Apparatus	Internal		Uncommitted	50113569
Batch: 41124106 - Inspection Batch			Route: SE_CW1_South1				Date: 13/05/2022	
42101199	x2 CW pothole, make safe.	13/05/2022	Outside 54.	RD: CW Pothole	Internal		Committed	50113567
Batch: 41123461 - Inspection Batch			Route: Ad hoc Route				Date: 04/05/2022	
42100577	Parking: Disabled Bay refresh	04/05/2022		RD: Markings Disabled Bay	Internal		Committed	50112994
Batch: 41123460 - Inspection Batch			Route: Ad hoc Route				Date: 04/05/2022	
42100576	Parking: Disabled Bay refresh	04/05/2022		RD: Markings Disabled Bay	Internal		Committed	50112993
Batch: 41123112 - Inspection Batch			Route: Ad hoc Route				Date: 02/05/2022	
42100147	Cw pothole marked on site	02/05/2022	Drum street city bound at limefield	RD: CW Pothole	Internal		Committed	50112694
Batch: 41122280 - Inspection Batch			Route: SE_CW1_South1				Date: 12/04/2022	
No actionable defects found								
Batch: 41121954 - Inspection Batch			Route: Ad hoc Route				Date: 07/04/2022	
42099046	Cw breaking up hot overlays required As discussed with ASCougall	07/04/2022	Drum street city bound from 48 to 40	RD: CW Cracked/Broken	Internal		Committed	50111522
Batch: 41120056 - Inspection Batch			Route: Ad hoc Route				Date: 21/03/2022	
42097170	Cw pothole marked on site	21/03/2022	Drum street opp 61	RD: CW Pothole	Internal		Committed	50109809
Batch: 41120055 - Inspection Batch			Route: Ad hoc Route				Date: 21/03/2022	
42097169	Cw potholes marked on site x3	21/03/2022	Drum street opp 83	RD: CW Pothole	Internal		Committed	50109808

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type:	Road Asset		Area: South East Locality	
Batch:	41119281 - Inspection Batch			Route:	Ad hoc Route			Date: 14/03/2022
42096025	Cw pothole marked on site	14/03/2022	Drum street os 141	RD: CW Pothole	Internal		Committed	50108993
Batch:	41119176 - Inspection Batch			Route:	SE_CW1_South1			Date: 14/03/2022
	No actionable defects found							
Batch:	41118947 - Inspection Batch			Route:	Ad hoc Route			Date: 11/03/2022
42095732	1x pothole marked on site	11/03/2022	Just before junction with Candlemakers Park	RD: CW Pothole	Internal		Committed	50108743
Batch:	41118945 - Inspection Batch			Route:	Ad hoc Route			Date: 11/03/2022
42095731	1x pothole marked on site	11/03/2022	Outside 44	RD: CW Pothole	Internal		Committed	50108742
Batch:	41118732 - Inspection Batch			Route:	Ad hoc Route			Date: 08/03/2022
42095385	Pothole	08/03/2022	O/S entrance to THE DRUM	RD: CW Pothole	Internal		Committed	50108461
Batch:	41118201 - Inspection Batch			Route:	Ad hoc Route			Date: 03/03/2022
42094824	1 number pothole	03/03/2022	Opposite number 90	RD: CW Pothole	Internal		Committed	50108071
Batch:	41117866 - Inspection Batch			Route:	Ad hoc Route			Date: 03/03/2022
42094733	2 number potholes	03/03/2022	Outside number 38 and 42	RD: CW Pothole	Internal		Committed	50107987
Batch:	41115525 - Inspection Batch			Route:	SE_CW1_South1			Date: 14/02/2022
42092729	x1 CW pothole, make safe.	14/02/2022		RD: CW Pothole	Internal		Committed	50106179
Batch:	41114077 - Inspection Batch			Route:	SE_CF1_GilmertonRdSouth1			Date: 26/01/2022
	No actionable defects found							
Batch:	41112955 - Inspection Batch			Route:	SE_CW1_South1			Date: 13/01/2022
42089188	1 carriageway pothole	13/01/2022	Outside 84	RD: CW Pothole	Internal		Committed	50102720
Batch:	41110057 - Inspection Batch			Route:	SE_CW1_South1			Date: 09/12/2021
42086511	1no pothole	09/12/2021	At the junction of Limefield	RD: CW Pothole	Internal		Committed	50099742
Batch:	41106997 - Inspection Batch			Route:	SE_CW1_South1			Date: 09/11/2021
	No actionable defects found							
Batch:	41106429 - Inspection Batch			Route:	Ad hoc Route			Date: 02/11/2021
42082075	Resurface Fw	02/11/2021	Drum street os 129	RD: FW HRA Cracked/Broken	Internal		Committed	50095598
Batch:	41103334 - Inspection Batch			Route:	SE_CW1_South1			Date: 08/10/2021
	No actionable defects found							
Batch:	41099733 - Inspection Batch			Route:	SE_CW1_South1			Date: 08/09/2021
	No actionable defects found							
Batch:	41097533 - Inspection Batch			Route:	SE_CW1_South1			Date: 04/08/2021
	No actionable defects found							
Batch:	41096636 - Inspection Batch			Route:	Ad hoc Route			Date: 21/07/2021
42073894	Replace missing bollard	21/07/2021	Drum street opp royal bingo	RD: Bollard Damage/Missing/New	Internal		No Action Required	

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type:	Road Asset		Area: South East Locality	
Batch:	41095523 - Inspection Batch			Route:	SE_CW1_South1			Date: 06/07/2021
	No actionable defects found							
Batch:	41093602 - Inspection Batch			Route:	Ad hoc Route			Date: 02/06/2021
42070296	Cw potholes marked on site x3	02/06/2021	Drum st at emerald guest house	RD: CW Pothole	Internal		Committed	50084492
Batch:	41093600 - Inspection Batch			Route:	Ad hoc Route			Date: 02/06/2021
42070292	Cw pothole marked on site	02/06/2021	Drum street at ferniehill road	RD: CW Pothole	Internal		Committed	50084490
Batch:	41093583 - Inspection Batch			Route:	SE_CW1_South1			Date: 02/06/2021
42070234	3no potholes	02/06/2021	Outside no57	RD: CW Pothole	Internal		Committed	50084467
42070240	1no pothole	02/06/2021	Outside studio45 opposite mechanic arms	RD: CW Pothole	Internal		Committed	50084470
Batch:	41092481 - Inspection Batch			Route:	Ad hoc Route			Date: 17/05/2021
42069104	Cw pothole marked on site	17/05/2021	Drum street os 119	RD: CW Pothole	Internal		Committed	50083181
Batch:	41092480 - Inspection Batch			Route:	Ad hoc Route			Date: 17/05/2021
42069103	Cw potholes marked on site x2	17/05/2021	Drum street opp 123	RD: CW Pothole	Internal		Committed	50083179
Batch:	41092321 - Inspection Batch			Route:	Ad hoc Route			Date: 13/05/2021
42068873	Lift and relay slabs to stop ponding	13/05/2021	Drum street opp gilmerton community centre	RD: FW Slabs Rocking	Internal		Committed	50083000
Batch:	41091508 - Inspection Batch			Route:	SE_CW1_South1			Date: 29/04/2021
	No actionable defects found							
Batch:	41091356 - Inspection Batch			Route:	Ad hoc Route			Date: 28/04/2021
42067777	Sunken small Scottish water box	28/04/2021	On carriageway at junction of Newtoft Street	RU: Utility Apparatus	Internal		Uncommitted	50081909
Batch:	41089345 - Inspection Batch			Route:	SE_CW1_South1			Date: 31/03/2021
	No actionable defects found							
Batch:	41089099 - Inspection Batch			Route:	Ad hoc Route			Date: 29/03/2021
42065786	Cw pothole marked on site	29/03/2021	Drum st city bound os 62	RD: CW Pothole	Internal		Committed	50079791
Batch:	41087550 - Inspection Batch			Route:	Ad hoc Route			Date: 15/03/2021
42064197	Patching required 10m2	15/03/2021	Drum street opp 117	RD: CW Subsidence/Heaving	Internal		Committed	50078345
Batch:	41087533 - Inspection Batch			Route:	Ad hoc Route			Date: 15/03/2021
42064171	Cw potholes marked on site x4	15/03/2021	Drum street at ravenscroft street	RD: CW Pothole	Internal		Committed	50078290
Batch:	41087531 - Inspection Batch			Route:	Ad hoc Route			Date: 15/03/2021
42064169	Refresh box junction	15/03/2021	Drum Street at ravenscroft st	RD: Markings Refresh	Internal		Committed	50078285
Batch:	41086103 - Inspection Batch			Route:	SE_CW1_South1			Date: 03/03/2021
42063151	1no CW pothole	03/03/2021	Outside no63	RD: CW Pothole	Internal		Committed	50077162
42063154	1no CW pothole	03/03/2021	Opposite W&H Contracts	RD: CW Pothole	Internal		Committed	50077165
42063148	1no CW pothole	03/03/2021	Outside no59	RD: CW Pothole	Internal		Committed	50077160

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type:	Road Asset		Area: South East Locality	
Batch:	41086103 - Inspection Batch		Route: SE_CW1_South1				Date: 03/03/2021	
42063152	1no CW pothole	03/03/2021	Opposite Gilmerton Aned Hand Car Wah	RD: CW Pothole	Internal		Committed	50077163
42063150	3no CW potholes	03/03/2021	Outside 48-50	RD: CW Pothole	Internal		Committed	50077161
42063146	5no CW potholes	03/03/2021	Outside Dominos/Spex Opticians	RD: CW Pothole	Internal		Committed	50077158
Batch:	41079834 - Inspection Batch		Route: Ad hoc Route				Date: 29/01/2021	
42059990	Rocking manhole cover	29/01/2021	Os 123	RU: Utility Apparatus	Internal		Uncommitted	50073365
Batch:	41078319 - Inspection Batch		Route: SE_CW1_South1				Date: 26/01/2021	
	No actionable defects found							
Batch:	41071566 - Inspection Batch		Route: Ad hoc Route				Date: 17/12/2020	
42057736	Refresh bus stop marking	17/12/2020	Drum street os Iceland	RD: Markings Refresh	Internal		Committed	50070455
Batch:	41071482 - Inspection Batch		Route: SE_CW1_South1				Date: 17/12/2020	
	No actionable defects found							
Batch:	41070741 - Inspection Batch		Route: SE_CF1_GilmertonRdSouth1				Date: 10/12/2020	
42056961	Low patch on footway at kerb please top up with tar	10/12/2020	O/S Dominoes	RD: FW HRA Pothole	Internal		Committed	50069601
42056970	CW patch required	10/12/2020	Drum street opp 117	RD: CW Subsidence/Heaving	Internal		No Action Required	
42056965	Fw resurface required	10/12/2020	Drum st 125/129	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42057046	3 x potholes along kerb	10/12/2020	At entrance to Drum Lodge	RD: CW Pothole	Internal		Committed	50069672
42057020	Footway breaking up	10/12/2020	O/S 48	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42057018	Footway depression remove leaves and make safe with tar	10/12/2020	O/S 50	RD: FW HRA Pothole	Internal		Committed	50069658
42056958	2 x rocking low slabs please lift and relay	10/12/2020	O/S Iceland behind bin near bus stop	RD: FW Slabs Rocking	Internal		Committed	50069600
Batch:	41070153 - Inspection Batch		Route: Ad hoc Route				Date: 01/12/2020	
42056326	Cw pothole marked on site	01/12/2020	Drum street south bound at the drum	RD: CW Pothole	Internal		Committed	50068725
Batch:	41069047 - Inspection Batch		Route: SE_CW1_South1				Date: 12/11/2020	
	No actionable defects found							
Batch:	41068476 - Inspection Batch		Route: Ad hoc Route				Date: 04/11/2020	
42055049	Fw resurface required	04/11/2020	Drum st 125/129	RD: FW HRA Cracked/Broken	Internal		No Action Required	
Batch:	41068474 - Inspection Batch		Route: Ad hoc Route				Date: 04/11/2020	
42055047	Cw pothole	04/11/2020	Drum street os dominoes	RD: CW Pothole	Internal		Committed	50066270
Batch:	41066048 - Inspection Batch		Route: SE_CW1_South1				Date: 07/10/2020	
	No actionable defects found							
Batch:	41063210 - Inspection Batch		Route: Ad hoc Route				Date: 15/09/2020	
42053426	Cw / Fw patch required Cw 1.5x3 Fw 2.5x2.5	15/09/2020	Drum street at Dominoes	RD: CW Cracked/Broken	Internal		Committed	50062678

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type:	Road Asset		Area: South East Locality	
Batch:	41062485 - Inspection Batch			Route:	SE_CW1_South1			Date: 28/08/2020
	No actionable defects found							
Batch:	41060119 - Inspection Batch			Route:	SE_CW1_South1			Date: 14/07/2020
	No actionable defects found							
Batch:	41059846 - Inspection Batch			Route:	Ad hoc Route			Date: 06/07/2020
42051374	Missing kerb made safe by inspector please replace as best as you can match kerb	06/07/2020	Drum street side of dominoes pizza	RD: FW Kerbs Damaged/Missing	Internal		Committed	50057904

Customer Services

Enquiry No.:	34009929	Logged by:		on:	14/05/2025 11:49
Service:	Roads General	Subject:	Pavement: Damaged / Defective	Classification:	Request for service
Desc.:	4 drum street, gilmerton community centre the pavement is all broken at the pedestrian crossing at Gilmerton Community Centre				
Location:	4 drum street, gilmerton community centre		Contact:		
Plot Number:	1.00	Feature Id - Location:	Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type:	Road Asset
Enquiry No.:	34007744	Logged by:		on:	09/11/2023 13:50
Service:	Roads General	Subject:	Traffic Sign: General Enquiry	Classification:	General Enquiry
Desc.:	Damage pole and sign				
Location:	At the junction with Drum Street		Contact:		
Plot Number:	1.00	Feature Id - Location:	Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type:	Road Asset
Job Number:	50145548	Defect Number:	42139306		
Enquiry No.:	34006959	Logged by:		on:	29/05/2023 14:34
Service:	Roads General	Subject:	Trees & Foliage: Defect	Classification:	Request for service
Desc.:	overgrown is making visibility difficult, for people driving from Drum Street to East Farm of Gilmerton, please see pic attached.				
Location:	Drum Street		Contact:		
Enquiry No.:	1968578	Logged by:	Verint CRM Connector	on:	25/06/2025 08:11
Service:	Roads General	Subject:	Pavement: Damaged / Defective	Classification:	Request for service
Desc.:					
Location:	Large BT Manhole cover on Pavement, just to north of city bound bus stop (opposite Iceland) The manhole cover looks like it's been lifted & not replaced correctly meaning it's sitting proud of pavement level. Potentially causing accident and/ or injury. Thank you		Contact:		
Plot Number:	1.00	Feature Id - Location:	Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type:	Road Asset

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Customer Services

Enquiry No.: 1958081	Logged by: Verint CRM Connector	on: 03/06/2025 17:46
Service: Roads General	Subject: Covers: Damaged / Defective	Classification: Request for service
Desc.:		
Location: There is a cover on the pavement that has eroding around it but the metal cover is also loose/moves if you stand on it. It doesn't look/feel safe and most definitely is a hazard to wheelchair users/partially sighted people.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50181069	Defect Number: 42185196	
Enquiry No.: 1955887	Logged by: [REDACTED]	on: 30/05/2025 09:16
Service: Roads General	Subject: Roadworks: Defect	Classification: Request for service
Desc.: From: [REDACTED] < [REDACTED] >		
Date: Friday, May 30, 2025 at 8:16:43 AM		
To: < [REDACTED] >		
Subject: Drum St Roadworks.		
Good morning. While roadworks are often needed, the current set of temporary lights is being miss managed as the junction of Drum St and Ferniehill Dr. Date: 30/05/25 Time: 08:00 Location: Drum St and Ferniehill Dr These lights are letting too few cars through the junction at a time and the junction already has problems with too many people turning right onto Ferniehill Dr as they travel north into the city. This has lead to significant delays over and above the usual delay at this junction. There is no problem with the work being done, it is all about adequate planning, timing and the ability for works to understand the ripple effect on the road network. Traffic was backed up a very long way this morning only to find that the workman looking after the lights was sat in his cab eating. The timing must take into account rush hour traffic and I'd suggest that a better way of managing it would have been a restricted 2 way rather than a simple one at a time 4 way. The delay was mostly caused by having to wait for 4 light changes between cars being let through. As I'm now late for work, I don't really appreciate that these works have been there over 24 hours now and most of the places with cones have zero work being done on them. I suspect a different shape to the works would have made it much easier for traffic flow. As always with these complaints, the issue is usually how it ends up being planned an executed on the ground. Having seen other works do stupid things with traffic erroneously put down a one way road, my feeling is that works just don't consider the wider impact. Please arrange for your works planners to sit in the traffic jams they cause. Thanks.		
Location:	Contact:	
Enquiry No.: 1950320	Logged by: Verint CRM Connector	on: 19/05/2025 17:27
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Lovely wave of tarmac and associated whole created by buses	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1930499	Logged by: Verint CRM Connector	on: 08/04/2025 14:23
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The road has ups and downs; it's not smooth, and there are also potholes. My car always gets hit by them, and I'm worried it could damage the exhaust pipe or the engine. If that happens, the council would be responsible for repairing my car.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Customer Services

Enquiry No.: 1922605

Logged by: [REDACTED]

on: 24/03/2025 08:40

Service: Roads General

Subject: Pavement: Damaged / Defective

Classification: Request for service

Desc.: Pavement is not suitable for wheelchair users. I have been reporting the pavements to Edinburgh Council, but they always dismiss my concerns. My daughter was on her scooter, got stuck in a crack, and fell, injuring herself.

Looking at the condition of the pavement, it is not even suitable for wheelchair users or mobility scooters. The council needs to fix the pavements to make them safe and accessible for everyone.

Location:

Contact:

Enquiry No.: 1921983

Logged by: Verint CRM Connector

on: 22/03/2025 11:04

Service: Roads General

Subject: Pavement: Damaged / Defective

Classification: Request for service

Desc.:

Location: Pavement along Drum Cottages near the bus stop heading towards the city.

Contact:

Pavement is cracked and uneven with large dips in places, and is a tripping hazard and causes difficulties for mobility devices.

Plot Number: 1.00

Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road

Feature Type: Road Asset

Enquiry No.: 1921335

Logged by: Verint CRM Connector

on: 20/03/2025 21:57

Service: Roads General

Subject: Pavement: Damaged / Defective

Classification: Request for service

Desc.:

Location: The pavements are full of potholes and cracks. My toddler tripped on a crack and injured her foot because her scooter stuck in the crack.

Contact:

I know a neighbour using a wheelchair and the roads are not safe for her.

I have reported the pavements before and this is my 4th time. A company dug the pavement again to do the wiring.

Could you please fix the pavement and make it suitable for kids and wheelchair people all the way from drum street to Gilmerton crossroads

Plot Number: 1.00

Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road

Feature Type: Road Asset

Enquiry No.: 1901853

Logged by: Verint CRM Connector

on: 11/02/2025 09:35

Service: Roads General

Subject: Pavement: Damaged / Defective

Classification: Request for service

Desc.:

Location: The pavement has a hole. It's so big I'm starting to worry that someone on a mobility scooter or wheelchair will fall in it. Hopefully, a fix is on the way before it turns into a new local landmark.

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road

Feature Type: Road Asset

Enquiry No.: 1900981

Logged by: Verint CRM Connector

on: 09/02/2025 11:31

Service: Roads General

Subject: Pavement: Damaged / Defective

Classification: Request for service

Desc.:

Location: The pavement is cracked and full of potholes. My 4 years old tripped and fell because of it and injured her leg. It is not safe for wheelchair users or mobility scooter users. Please fix it

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road

Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Customer Services

Enquiry No.: 1900980	Logged by: Verint CRM Connector	on: 09/02/2025 11:30
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: The pavement is cracked and full of potholes. My 4 years old tripped and fell because of it and injured her leg. It is not safe for wheelchair users or mobility scooter users. Please fix it	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1900979	Logged by: Verint CRM Connector	on: 09/02/2025 11:30
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: The pavement is cracked and full of potholes. My 4 years old tripped and fell because of it and injured her leg. It is not safe for wheelchair users or mobility scooter users. Please fix it	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1900790	Logged by: Verint CRM Connector	on: 08/02/2025 15:10
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: The pavements in the Gilmerton area need to be redone. I agree that it is a large area, but the pavements are not accessible for wheelchair users, prams, or kids on scooters and bikes. They are even hazardous to walk on, as they can cause trips and lead to serious injuries such as broken legs or hips. Something needs to be done to properly maintain and repair them. some of the damage is caused by telecom companies. They have to fix it Instead of simply patching the areas where they drilled.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1900787	Logged by: Verint CRM Connector	on: 08/02/2025 15:05
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: The pavements in the Gilmerton area need to be redone. I agree that it is a large area, but the pavements are not accessible for wheelchair users, prams, or kids on scooters and bikes. They are even hazardous to walk on, as they can cause trips and lead to serious injuries such as broken legs or hips. Something needs to be done to properly maintain and repair them. some of the damage is caused by telecom companies. They have to fix it Instead of simply patching the areas where they drilled.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Customer Services

Enquiry No.: 1900786	Logged by: Verint CRM Connector	on: 08/02/2025 15:03
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: The pavements in the Gilmerton area need to be redone. I agree that it is a large area, but the pavements are not accessible for wheelchair users, prams, or kids on scooters and bikes. They are even hazardous to walk on, as they can cause trips and lead to serious injuries such as broken legs or hips. Something needs to be done to properly maintain and repair them.	Contact:	
some of the damage is caused by telecom companies. They have to fix it Instead of simply patching the areas where they drilled.		
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1899779	Logged by: Verint CRM Connector	on: 06/02/2025 14:13
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Please fix the road because it is hazard to cars	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1898491	Logged by: Verint CRM Connector	on: 04/02/2025 14:32
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The road is damaged from the traffic lights to morrisons shop. It also has potholes. This is the third time I am reporting this road but no one is taking any action about it.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1887306	Logged by: Verint CRM Connector	on: 15/01/2025 18:37
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Road has a very uneven,(speed bump height and depth) going vertically,down road,beside bus stop,for going into Edinburgh.	Contact:	
Couldn't see it, because of low sunshine,when crossing and [REDACTED] my back more,which caused me,more pain.		
Enquiry No.: 1871510	Logged by: Verint CRM Connector	on: 16/12/2024 07:49
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Cat 1 (cyclists) and Cat 2 (other road users)pothole at the bus stop adjacent to the curb	Contact:	
Looks like the buses have pushed the tarmac		
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50171429	Defect Number: 42171205	

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Customer Services

Enquiry No.: 1869842	Logged by: Verint CRM Connector	on: 11/12/2024 11:22
Service: Roads General	Subject: Street Furniture: Defective	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow		
Location: Bollards at 3 Ravenscroft Street, one has been bumped and is almost horizontal.		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50171393	Defect Number: 42171169	
Enquiry No.: 1860214	Logged by: Verint CRM Connector	on: 18/11/2024 14:14
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: 3 Drum Street.		Contact:
Pothole on road.		
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1826292	Logged by:	on: 03/09/2024 08:38
Service: Roads General	Subject: Roadworks: Defect	Classification: Request for service
Desc.: From: < >		
Date: Monday, September 2, 2024 at 10:39:11 AM		
To: Customer Care < >		
Subject: Road sign		
Good Morning		
I not sure if this is best place contact but there was some work being done by council on our road two weekends ago. The work was complete , however a large road sign was left and blocking the pavement all others where taken .		
I wonder if this could be collected , it's currently outside 125 Drum Street, EH17 8RJ		
Thank you		
Jason		
Location: it's currently outside 125 Drum Street, EH17 8RJ		Contact:
Enquiry No.: 1804048	Logged by: Verint CRM Connector	on: 23/07/2024 22:07
Service: Roads General	Subject: Traffic Sign:Defective/Damaged	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow		
Location: As stated on previous box, old lamppost signage installed by Edinburgh Council (affixed with plastic black bands) are months out of date and can now be removed. These signs are attached to a number of lampposts the length of Drum Street. No longer required. Thank you 48/3, DRUM STREET, EDINBURGH, EH17 8RN		Contact:
Enquiry No.: 1776249	Logged by: Verint CRM Connector	on: 08/06/2024 22:25
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Adjacent to Tanz studio 51 Drum Street. CCTV camera station- front plate has come off , exposing internal electrics.		Contact:
See photo for camera ref number details from Edin.Open Data Portal		
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Customer Services

Enquiry No.: 1762292

Logged by: Verint CRM Connector

on: 24/05/2024 22:49

Service: Roads General

Subject: Trees & Foliage: Defect

Classification: Request for service

Desc.: Problem: Causing Obstruction.

Location:Pavement.

Type:Foliage / Bush

Location: Large shrub significantly overhanging pavement, both in overall height and at eye level. Pedestrians need to walk on the roadway to avoid branches in face.Large shrub/tree with purple flowers. Photo attached. Thanks

Contact:

Opposite the large car wash

Enquiry No.: 1752953

Logged by: [REDACTED]

on: 13/05/2024 15:53

Service: Roads General

Subject: Roadworks: Defect

Classification: Request for service

Desc.: From: [REDACTED] <[REDACTED]>

Date: Sunday, May 12, 2024 at 3:18:47 PM

To: Customer Care <[REDACTED]>

Subject: Fwd: Drum Street EH17 8RJ

> Good Morning

>

> I'm not sure if this is correct dept to contact, we had resurfacing taken place last week any other road was closed.

>

> Yesterday the machinery was removed from the road however they is pile of old tar and two cones which has being left outside 129 Drum street from where the machinery was left.

>

> I notice all the cones and barriers have being removed apart from this and a road works sign out 107

> Drum street .

>

> Could these be arranged to be cleaned and removed.

>

> Thanks

> [REDACTED]

Location:

Contact:

Enquiry No.: 1750209

Logged by: Verint CRM Connector

on: 08/05/2024 13:41

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Desc.:

Location: The road from Gilmerton crossroads to after the pharmacy needs repairs

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road

Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1750000 Logged by: [REDACTED] on: 08/05/2024 09:18

Service: Roads General Subject: Roadworks: General Enquiry Classification: Frontline Resolution (Stage1)

Desc.: From: [REDACTED] <[REDACTED]>

Date: Tuesday, 7 May 2024 at 08:44:41

To: [REDACTED] <[REDACTED]>

Cc: [REDACTED] <[REDACTED]>

Subject: Complaint - Drum Street Closure

Hi there

I'm writing to complain about the ludicrous decision to completely close off Drum Street in Gilmerton, Edinburgh and diverting buses around a 40 minute detour. Just to reiterate - it took the X29 bus 40 minutes to get back around to the lights/junction at Drum Street.

Whoever sanctioned this decision obviously has no consideration for people who live in and around that area. Surely there could have been a better solution that results in less impact - but the council just gets to do what it likes without any regards for the impact on people's everyday life.

A complete joke of a decision made by incompetent council employees. I will be making this complaint to our local MP.

Regards

[REDACTED]

Sent from Outlook for Android

Location: Drum Street

Contact:

Enquiry No.: 1747867 Logged by: Verint CRM Connector on: 03/05/2024 15:28

Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:

Location: There is a pedestrian crossing island on Drum Street, nearest the entrance to Contact:

Candlemaker's Park, which has a dropped kerb on one side of the road but not the

other (it's not a dropped kerb on the side of Candlemaker's Park). I'm not sure if

there should always be dropped kerbs on either side of an island as standard or not,

but it seems dangerous for wheelchair users and anyone pushing a pram to cross

over and then have to go up a full kerb, especially on such a busy road.

Plot Number: 1.00 Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road Feature Type: Road Asset

Enquiry No.: 1734670 Logged by: Verint CRM Connector on: 11/04/2024 07:35

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: Deep pothole, before junction, on left hand side. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road Feature Type: Road Asset

Enquiry No.: 1727667 Logged by: Verint CRM Connector on: 01/04/2024 08:37

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: On Drum Street, next to the junction with Ravenscroft Street. The inspection hole Contact:

cover in the northbound carriageway has sunk a bit, and makes a goddawful noise

every time someone drives over it.

Plot Number: 1.00 Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Customer Services

Enquiry No.: 1727612

Logged by: Verint CRM Connector

on: 31/03/2024 21:35

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Desc.:

Location: Pothole on city bound route at bus stop, in middle of road

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road

Feature Type: Road Asset

Job Number: 50157720

Defect Number: 42153988

Enquiry No.: 1718298

Logged by:

on: 15/03/2024 09:37

Service: Roads General

Subject: Street Furniture: Defective

Classification: Request for service

Desc.: From: kay < >

Date: Wednesday, March 13, 2024 at 9:39:10 AM

To: Customer Care < >

Subject: Road Cones

Good Morning

I'm not sure who I report this to, there is dumped traffic cones on Drum Street outside abbey lodge hotel 137 Drum Street EH17 8RJ.

I not sure where they came from but local kids chucked them on the road last night causing very dangerous for cars. They are now stacked up on pavement and about 5/6 of them, there was works last week near by but this is complete and all other barriers removed, I'm wondering if these could be picked up by your road team please

Thanks

Location: From: < >

Date: Wednesday, March 13, 2024 at 9:39:10 AM

To: Customer Care < >

Subject: Road Cones

Contact:

Good Morning

I'm not sure who I report this to, there is dumped traffic cones on Drum Street outside abbey lodge hotel 137 Drum Street EH17 8RJ.

I not sure where they came from but local kids chucked them on the road last night causing very dangerous for cars. They are now stacked up on pavement and about 5/6 of them, there was works last week near by but this is complete and all other barriers removed, I'm wondering if these could be picked up by your road team please

Thanks

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Customer Services

Enquiry No.: 1711316	Logged by: Verint CRM Connector	on: 04/03/2024 08:30
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: The inspection hole cover in the northbound carriageway at the Ravenscroft Street/Drum Street junction is starting to sink, and makes a horrific noise every time someone drives over it.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1705546	Logged by: Verint CRM Connector	on: 23/02/2024 14:49
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Refer to Ref 101002292141 dated 7th Feb 2024. Also reference 101002305036. The broken drain has still not been repaired despite your 8th Feb reply to my complaint stating this had already been reported previously, date unknown. To date, in almost 3 weeks, no action whatsoever has been taken to repair the broken drain/manhole. The constant traffic on this very busy arterial route is causing constant noise and disturbance to residents up to 24 hours per day. Please get this fixed ASAP!	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1702029	Logged by: Verint CRM Connector	on: 19/02/2024 08:38
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Manhole: two-part cover very loose, and sunken into the roadway. This section of road was recently resurfaced, not that many months ago. The metal cover plates are aggravated with the heavy traffic on this main thoroughfare through Gilmerton Village (Conservation Area) Additionally, the clattering noise every time a vehicle is driven over. Thank you for attending to this	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1701537	Logged by: Verint CRM Connector	on: 17/02/2024 20:57
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Lose manhole cover. Northbound lane, near pavement. Makes a whacking sound each time someone drives over it. This is a noise nuisance.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1699254	Logged by: [REDACTED]	on: 14/02/2024 12:12
Service: Roads General	Subject: Spill: Oil / Petrol / Diesel	Classification: Customer Emergency
Desc.: Team were out this morning to fix bollards and have spilled oil over the front courtyard of this motorcycle business	Contact:	
Location:	Contact:	
Enquiry No.: 1697847	Logged by: Verint CRM Connector	on: 12/02/2024 13:12
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Dropped manhole in Drum Street at the junction with Ravenscroft Street beside the dropped kerb for pedestrians crossing. I reported this two weeks ago but nothing has been done. Apart from vehicles being damaged the people in the houses have to endure the banging noise 24 hours a day	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1694910	Logged by: Verint CRM Connector	on: 07/02/2024 13:36
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a broken manhole/drain cover which bangs very loudly every time a vehicle drives over it causing noise disturbance 24 hours a day. The road is too busy to provide photographic evidence safely. Due to this street being a main arterial route the noise is constant.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1689407	Logged by: Verint CRM Connector	on: 30/01/2024 20:52
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Loose and very noisy manhole cover (non-stop metal clanging), other manhole covers on Drum Street are affected as well.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1688509	Logged by: Verint CRM Connector	on: 29/01/2024 17:46
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Manhole cover at drum street junction with Ravenscroft Street has dropped and extremely noisy every time traffic goes over it (near pedestrian dropped kerb crossing)	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1686233	Logged by: Verint CRM Connector	on: 26/01/2024 09:18
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a loose drain/ manhole cover which is causing a loud noise which has been ongoing for weeks and not being repaired	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1681753	Logged by: Verint CRM Connector	on: 20/01/2024 12:17
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a metal cover on the road, and every time a car / bus etc. drives over it, it makes a loud noise. It is like the metal cover is not secure, and it's rattling when it gets driven over. We live in a house close to this, and can hear the noise (through double glazing) 24 / 7. It's getting louder as more vehicles pass over it.	Contact:	
The metal cover is near a drop curb crossing over Drum Street - outside 38 Drum Street.		
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50150703	Defect Number: 42144587	

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1677045	Logged by: Verint CRM Connector	on: 12/01/2024 16:39
Service: Roads General	Subject: Public Utilities: General	Classification: Request for service
Desc.:		
Location: Re no 101002252603 the drain covering still the same if not louder don't know if been at right place but very loud you couldn't miss it .	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1675923	Logged by: [REDACTED]	on: 11/01/2024 10:05
Service: Roads General	Subject: Covers: Damaged / Defective	Classification: Request for service
Desc.: Loose/noisy manhole cover		
Location: on drum street heading towards town side off road . Opposite the lodge hotel and before u go round the corner to the co op. It's also just beside the crossing island .	Contact:	
Enquiry No.: 1675577	Logged by: Verint CRM Connector	on: 10/01/2024 16:43
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Drain covering loose/ faulty , due to heavy traffic day and night the constant clanging is causing disturbance , could also become looser and cause accident. Drum Street Carter Drive .	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50150039	Defect Number: 42143917	
Enquiry No.: 1670951	Logged by: Verint CRM Connector	on: 04/01/2024 08:04
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Outside 6 Carter mews there is a drain/ cover /manhole cover which has dropped and causing a loud bang ever time car go past which is very distrubting for local people .	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1668895	Logged by: Verint CRM Connector	on: 30/12/2023 22:53
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Heading towards town in front off flats on drum street and before bus stop there is a loose manhole cover that has sank and causing a noise all during day and night which is affecting residents in this street . Could u please fix this or contact company responsible for the manhole cover	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50149125	Defect Number: 42143015	
Enquiry No.: 1643700	Logged by: Verint CRM Connector	on: 13/11/2023 18:19
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Sunken or eroded trench repair across width of southbound carriageway. Please patch or enforce repair.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Customer Services

Enquiry No.: 1623827	Logged by: [REDACTED]	on: 05/10/2023 15:13
Service: Roads General	Subject: Roadworks: Defect	Classification: Request for service
Desc.: Customers Comment: Lower curb on drum street next to the Drum Cottages bus stop, you have recently re-done the path there and somehow forgot to lower the curb at a traffic island?...how is anyone with a wheelchair, buggy or some sort of mobility issue ment to cross now?		
Location: at Drum Cottages bus stop	Contact:	

Enquiry No.: 1621410	Logged by: Verint CRM Connector	on: 01/10/2023 08:25
Service: Roads General	Subject: Roadworks: Defect	Classification: Customer Emergency
Desc.:		
Location: Hi, recently Drum street was down to single lane to allow the building of a new pavement between the bus stop and the corner of Candlemaker's Park. There are a set of keep left's with a dropped curb but the new pavement does not have the corresponding dropped curb. I am a wheelchair user and I now have no safe place to cross the road to access the shops. I cannot understand why this would have been done. Please can you remedy this asap as it affects my ability to safely cross the road.	Contact:	

Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
-------------------	---------------------------------------------------------------------------------	--------------------------

Enquiry No.: 1620913	Logged by: Lynne Surtees	on: 29/09/2023 13:17
Service: Roads General	Subject: Roadworks: General Enquiry	Classification: General Enquiry
Desc.: next to the bus stop where we are doing the pavement lady is worried that there looks like ther is no drop kerb being put in place her daughter is wheelchair user		
Location: next to the bus stop where we are doing the pavement lady is worried that there looks like ther is no drop kerb being put in place her daughter is wheelchair user	Contact:	

Enquiry No.: 1599375	Logged by: Verint CRM Connector	on: 17/08/2023 10:52
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Overgrown.		
Location:Footpath.		
Type:Foliage / Bush		
Location: Trees overgrown and pushing fence over	Contact:	

Enquiry No.: 1576335	Logged by: [REDACTED]	on: 04/07/2023 12:59
Service: Roads General	Subject: Spill: Oil / Petrol / Diesel	Classification: Customer Emergency
Desc.: Diesel spill approx 12 feet long		
Location: o/s 29 - 31	Contact:	

Enquiry No.: 1571874	Logged by: Verint CRM Connector	on: 25/06/2023 21:53
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Number off potholes on gilmeton road at junction beside Lloyds pharmacy and as far as the surgery, most off these are potholes from around the junction and in centre off road on gilmerton road due to volume off traffic	Contact:	

Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
-------------------	---------------------------------------------------------------------------------	--------------------------

Job Number: 50138303	Defect Number: 42130655
----------------------	-------------------------

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Customer Services

Enquiry No.: 1558012	Logged by: Verint CRM Connector	on: 28/05/2023 18:27
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Broken up pavement along the stretch from 121 drum street pasr 127 drum street ,	Contact:	
all loose stones etc		
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50136955	Defect Number: 42128925	
Enquiry No.: 1545319	Logged by: [REDACTED]	on: 01/05/2023 13:52
Service: Roads General	Subject: Traffic Mgmt: General Enquiry	Classification: General Enquiry
Desc.: Traffic Management camera front panel is broken and lying against tower, junction Drum Street/Ravenscroft Street		
Location:	Contact:	
Enquiry No.: 1532190	Logged by: Verint CRM Connector	on: 03/04/2023 18:08
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Other.		
Location:Pavement.		
Type:Grass		
Location: TV Aerial on roof above Post Office looks like my come loose and fall.	Contact:	
Enquiry No.: 1518420	Logged by: Verint CRM Connector	on: 03/03/2023 23:09
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a large wide pothole which is difficult to dodge on a bike if you don't know	Contact:	
it's there due to cars passing on your rhs.		
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50131169	Defect Number: 42121345	
Enquiry No.: 1516961	Logged by: Verint CRM Connector	on: 01/03/2023 08:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole danger to road users and pedestria	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50130814	Defect Number: 42120734	
Enquiry No.: 1508986	Logged by: Verint CRM Connector	on: 13/02/2023 10:03
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Concrete bollard has been knocked over and into the carriageway heading	Contact:	
southbound on Drum Street.		
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50129144	Defect Number: 42118436	

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1493285

Service: Roads General

Desc.:

Location: Outside old bingo hall and now j and s and beside vets on drum street. There is missing black bollards on 1 each side which stops people from parking on the pavement

Logged by: Verint CRM Connector

Subject: Pavement: Damaged / Defective

on: 16/01/2023 11:34

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road

Feature Type: Road Asset

Enquiry No.: 1471371

Service: Roads General

Desc.:

Location: Loose paving - Drum st

Category: Pavements/footpaths

Logged by: Verint CRM Connector

Subject: Pavement: Damaged / Defective

on: 05/12/2022 09:37

Classification: Request for service

Contact:

Several loose paving slabs which could soon become a tripping hazard. On the west side of Drum Street, about 5m north of the door for Gilmerton Cove. Right next to the downpipe.

Location:

Easting/Northing: 329262/668635 (55.905603, -3.13302)

Nearest road to the pin placed on the map (automatically generated by Bing Maps): 16a Drum Street, Hyvots Bank, EH17 8QH, Scotland, United Kingdom

Nearest postcode to the pin placed on the map (automatic

Plot Number: 1.00

Job Number: 50123853

Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road

Defect Number: 42112856

Feature Type: Road Asset

Enquiry No.: 1385602

Service: Roads General

Desc.: I would like to report a traffic sign which was hit sometime yesterday by unknown person and is bent over the payment. Can you please organise for someone to fix it, This is at the entrance of candlemakers park, Drum Street, Gilmerton, Edinburgh details passed to OOH Roads 0131 458 8065

Location:

Logged by:

Subject: Traffic Sign:Defective/Damaged

on: 01/06/2022 07:45

Classification: Request for service

Contact:

Enquiry No.: 1378458

Service: Roads General

Desc.:

Location: Missing drain cover (oval shaped) on pavement, in the middle of pavement area directly in path of pedestrians. Deep angled hole exposed, dangerous to pedestrians etc

Logged by: Verint CRM Connector

Subject: Public Utilities: General

on: 17/05/2022 21:15

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road

Feature Type: Road Asset

Enquiry No.: 1369915

Service: Roads General

Desc.:

Location: Pothole growing and now a danger to cyclists and damaging to vehicular traffic

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 29/04/2022 17:00

Classification: Request for service

Contact:

Plot Number: 1.00

Job Number: 50112694

Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road

Defect Number: 42100147

Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1346570	Logged by: Verint CRM Connector	on: 17/03/2022 09:27
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: 61 Drum Street - a large depression with crumbling surface that is causing debris to fly up into pedestrians on the pavement	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50109809	Defect Number: 42097170	
Enquiry No.: 1346564	Logged by: Verint CRM Connector	on: 17/03/2022 09:24
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: 83 Drum Street - a pothole that has previously been filled is breaking away, a cyclist came off their bike today with this in front of my vehicle	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50109808	Defect Number: 42097169	
Enquiry No.: 1345165	Logged by: Verint CRM Connector	on: 14/03/2022 18:17
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: multiple pot holes	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1345164	Logged by: Verint CRM Connector	on: 14/03/2022 18:16
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: potholes	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1344590	Logged by: Verint CRM Connector	on: 13/03/2022 21:32
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The whole road is in very poor condition - lots of potholes!	Contact:	
Enquiry No.: 1342161	Logged by: Verint CRM Connector	on: 09/03/2022 12:12
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: a whole row of crumbling surface and potholes over a 10 to 20 metre length of the road north bound and some south bound	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50108742	Defect Number: 42095731	
Enquiry No.: 1342155	Logged by: Verint CRM Connector	on: 09/03/2022 12:08
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: pothole and crumbling surface on approach to roundabout on south bound lane	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Customer Services

Enquiry No.: 1340752	Logged by: [REDACTED]	on: 07/03/2022 13:04
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.: Reporting uneven paving surface which is making it impossible for caller to take his disabled wife out in her wheelchair.		
Location: at entrance to street by Taylor Wimpey site		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50108743	Defect Number: 42095732	
Enquiry No.: 1338165	Logged by: Verint CRM Connector	on: 02/03/2022 22:09
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Deep pot holes		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50108071	Defect Number: 42094824	
Enquiry No.: 1337916	Logged by: Verint CRM Connector	on: 02/03/2022 15:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Numerous pot holes both north and south bound		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1336821	Logged by: Verint CRM Connector	on: 01/03/2022 12:05
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Multiple pot holes which are difficult to avoid		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50107987	Defect Number: 42094733	
Enquiry No.: 1335564	Logged by: Verint CRM Connector	on: 27/02/2022 18:15
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole on Drum Street, near Drum estate		Contact:
Category: Potholes		
A pothole in the southbound lane of Drum Street, near the entrance to Drum estate.		
Location:		
Easting/Northing: 329712/668409 (55.903637, -3.125769)		
Nearest road to the pin placed on the map (automatically generated by Bing Maps):		
143 Drum Street, Edinburgh, EH17 8RU		
Nearest postcode to the pin placed on the map (automatically generated): EH17		
8RU (14m away)		
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50108993	Defect Number: 42096025	

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1333895	Logged by: Verint CRM Connector	on: 24/02/2022 18:13
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Multiple pot holes - (historic substandard trench repair causes surface defects along its length from this point to Candlemakers Park)	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1333893	Logged by: Verint CRM Connector	on: 24/02/2022 18:12
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Multiple Pot holes - (historic substandard trench repair causes surface defects along its length from this point to Candlemakers Park)	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1333892	Logged by: Verint CRM Connector	on: 24/02/2022 18:11
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Multiple pot holes (historic substandard trench repair causes surface defects along its length from this point to Candlemakers Park)	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1331137	Logged by: Verint CRM Connector	on: 21/02/2022 14:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole next to the new building development site (infront of the shopfront nearest to the Mechanic Arms public house). Splashes people who are standing next to the bus stop in bad weather whilst also damaging the building site etc.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1305145	Logged by: [REDACTED]	on: 11/01/2022 12:34
Service: Roads General	Subject: Street Furniture: Defective	Classification: Request for service
Desc.: please see document attached		
Location: please see document attached	Contact:	
Enquiry No.: 1268450	Logged by: Verint CRM Connector	on: 02/11/2021 13:38
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Lowered Pavement is broken up, uneven and loose stones. This is worse in bad weather which is causing piles off mud and stones to gather in clumps, also unsafe for myself and my child outside her house at number 127 Drum Street, between us and 129 Drum Street	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50095598	Defect Number: 42082075	
Enquiry No.: 1258024	Logged by: [REDACTED]	on: 11/10/2021 08:53
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Pothole		
Location: just opp bus stop down from sun tanning centre	Contact:	

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1243952	Logged by: Verint CRM Connector	on: 12/09/2021 20:00
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.: Location: Between 127 and 129 Drum Street Edinburgh EH17 8RJ. The pavement is broken up and uneven. There is large bits off broken tarmac and gravel that I am having to sweep up as a result Off this.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1236827	Logged by: Verint CRM Connector	on: 31/08/2021 09:58
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction. Location:Pavement. Type:Foliage / Bush	Contact:	
Location: Hedge next to the Abbey Lodge hotel on Drum St	Contact:	
Enquiry No.: 1220127	Logged by: Verint CRM Connector	on: 02/08/2021 17:52
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.: Location: Between 125 and 129 Drum Street, EH17 8RJ, the pavement is broken up and uneven, which is dangerous for elderly and residents with buggy's. One part off this was fixed but still left the rest unsurfaced.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1211739	Logged by: Verint CRM Connector	on: 20/07/2021 15:19
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.: Location: Bollards have been hit by a vehicle and are a danger to pedestrians outside Gilmerton Cove	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1208876	Logged by: Verint CRM Connector	on: 15/07/2021 15:44
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Invasive weed growth. Location:Footpath. Type:	Contact:	
Location: Well overgrown prickly foliage growing out path which is narrow when you have a wheelchair. The pavements and kerbs are a disgrace in the whole area.	Contact:	
Enquiry No.: 1191561	Logged by: Verint CRM Connector	on: 15/06/2021 21:13
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction. Location:Pavement. Type:Foliage / Bush	Contact:	
Location: Bush overhanging pavement outside 89 Drum St.	Contact:	

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1181827	Logged by: Verint CRM Connector	on: 28/05/2021 09:43
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Deteriorated service trench crossing road.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50084490	Defect Number: 42070292	
Enquiry No.: 1179261	Logged by: Verint CRM Connector	on: 23/05/2021 18:58
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a big gap (sunken section) of the road in the southbound lane, just before the bus stop (lidl)	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50084492	Defect Number: 42070296	
Enquiry No.: 1178208	Logged by: Verint CRM Connector	on: 21/05/2021 01:19
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There are road wide length potholes that needs to be filled as these have now become very deep and is affecting all vehicles on the stretch of the road. These need to be filled ASAP as these are causing damage to vehicles but also causing problems on that stretch of the road for emergency vehicles.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1175022	Logged by: Verint CRM Connector	on: 14/05/2021 13:50
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is two potholes in the road beside 125 Drum Street EH17 8RJ	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50083179	Defect Number: 42069103	
Enquiry No.: 1170585	Logged by: Verint CRM Connector	on: 05/05/2021 15:38
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: There is a sunken section of pavement on the north east corner of Gilmerton crossroads, just at the pedestrian crossing outside the post office. This leads to large puddles forming here whenever it rains, and to large patches of ice when it then freezes.	Contact:	
Could it please be fixed before winter, as lots of folk skite here when it's icy.		
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50083000	Defect Number: 42068873	

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1170105

Service: Roads General

Desc.: Lidl bus stop

Category: Bus stops

Logged by: [REDACTED]

Subject: Road Markings: General Enquiry

on: 04/05/2021 15:55

Classification: General Enquiry

When is the bus stop outside of lidl getting marked up. As people park on it

Location:
Easting/Northing: 329208/668718 (55.906345, -3.133898)
Nearest road to the pin placed on the map (automatically generated by Bing Maps): 7 Drum Street, Edinburgh, EH17 8QG
Nearest postcode to the pin placed on the map (automatically generated): EH17 8QG (36m away)

Location: Lidl bus stop

Contact:

Category: Bus stops

When is the bus stop outside of lidl getting marked up. As people park on it

Location:
Easting/Northing: 329208/668718 (55.906345, -3.133898)
Nearest road to the pin placed on the map (automatically generated by Bing Maps):
7 Drum Street, Edinburgh, EH17 8QG
Nearest postcode to the pin placed on the map (automatically generated): EH17 8QG (36m away)

Enquiry No.: 1158824

Service: Roads General

Desc.:

Location: The whole road has cracked and needs to be repaired. The potholes have gone deeper around 20CM and need to be replaced. The potholes have now fully stretched out the width of the road meaning all cars, buses, emergency vehicles are being affected by this. This is a huge pothole and needs to be repaired urgently.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 13/04/2021 17:10

Classification: Request for service

Contact:

Plot Number: 1.00 Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road Feature Type: Road Asset

Enquiry No.: 1155980

Service: Roads General

Desc.:

Location: The whole street from the traffic lights (chip shop) south to roundabout is in dire need of resurfacing. Currently contains pot holes and collapsing utility works.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 08/04/2021 18:17

Classification: Request for service

Contact:

Enquiry No.: 1153603

Service: Roads General

Desc.:

Location: Previous trench repair across carriageway now failed, surface sunken and potholes within repair.
Please patch and enforce if possible

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 05/04/2021 16:47

Classification: Request for service

Contact:

Plot Number: 1.00 Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1153600	Logged by: Verint CRM Connector	on: 05/04/2021 16:46
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: large/deep pothole at bus stop	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1153599	Logged by: Verint CRM Connector	on: 05/04/2021 16:45
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Badly sunken fire hydrant or SV cover within junction. Please enforce repair by utility.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50081909	Defect Number: 42067777	
Enquiry No.: 1153590	Logged by: Verint CRM Connector	on: 05/04/2021 16:25
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: The whole length of Drum Street between Newtoft Street and Gilmerton Station road is littered with dozens and dozens of holes, depressions, open joints, crumbling surfaces that make it impossible to navigate safely when driving or cycling.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1149807

Service: Roads General

Desc.: From: [REDACTED] <[REDACTED]>

Sent: 28 March 2021 14:39

To: Customer Care <[REDACTED]>

Subject: Potholes

Logged by: Aleshia Chalmers

Subject: Road: Defective / Damaged

on: 29/03/2021 13:35

Classification: Request for service

I tried to report road problem online but to no avail.
There are several potholes on drum street edinburgh.
One in particular, which my son drove over today, hopefully not damaging his car. It is a very busy bottle neck road, used by bikes cars lorries and buses. These potholes are very dangerous to cyclists, and damaging to cars.
As I previously said, there are several, but a big one outside the building which was formerly the gardeners pub, next door to the car wash business.
I hope this problem is investigated and resolved at your earliest convenience.
Regards
[REDACTED]

Location: From: [REDACTED] <[REDACTED]>

Sent: 28 March 2021 14:39

To: Customer Care <[REDACTED]>

Subject: Potholes

Contact:

I tried to report road problem online but to no avail.
There are several potholes on drum street edinburgh.
One in particular, which my son drove over today, hopefully not damaging his car. It is a very busy bottle neck road, used by bikes cars lorries and buses. These potholes are very dangerous to cyclists, and damaging to cars.
As I previously said, there are several, but a big one outside the building which was formerly the gardeners pub, next door to the car wash business.
I hope this problem is investigated and resolved at your earliest convenience.
Regards
[REDACTED]

Enquiry No.: 1149219

Service: Roads General

Desc.: Large pothole damaging cars in gilmerton

Location: The road that it's on isn't very wide so you must drive through it or block traffic to go on the opposite side of the road to drive around it.

I hope my car isn't damaged because the bill will be getting sent to you

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 28/03/2021 14:35

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road

Feature Type: Road Asset

Enquiry No.: 1149216

Service: Roads General

Desc.: Large pothole in this location.

Location: Been here for over 3 weeks

The road is narrow so there is no other option to drive through it

Also no available places to stop and take pictures.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 28/03/2021 14:29

Classification: Request for service

Contact:

Plot Number: 1.00

Job Number: 50079791

Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road

Defect Number: 42065786

Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Customer Services

Enquiry No.: 1140475	Logged by: Verint CRM Connector	on: 15/03/2021 09:14
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Potholes at Drum Cottages	Contact:	
Category: Potholes		
The northbound bus stop at Drum Cottages is completely disintegrating.		
Location:		
Easting/Northing: 329539/668477 (55.904226, -3.128545)		
Nearest road to the pin placed on the map (automatically generated by Bing Maps):		
34 Drum Cottages, Edinburgh, EH17 8RL		
Nearest postcode to the pin placed on the map (automatically generated): EH17 8RL		
(25m away)		
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50078345	Defect Number: 42064197	
Enquiry No.: 1140350	Logged by: Verint CRM Connector	on: 14/03/2021 20:46
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Potholes/rutted surface on Drum Street near Ravenscroft Street junction. Some	Contact:	
patching further north was done recently, but missed some bits just as bad.		
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50078290	Defect Number: 42064171	
Enquiry No.: 1139191	Logged by: Verint CRM Connector	on: 12/03/2021 08:31
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Series of potholes and open joints on this section of road. This is a safety issue. The	Contact:	
road is narrow due to parked cars on both sides. Drivers have to manoeuvre across		
the road to avoid which means there is a risk of a head on crash with opposing		
traffic. Road needs repaired.		
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1139129	Logged by: Verint CRM Connector	on: 11/03/2021 22:12
Service: Roads General	Subject: Road Markings: Defective	Classification: Request for service
Desc.:		
Location: yellow box markings at the bottom of Ravenscroft Street and Drum Street have	Contact:	
eroded and are no longer visible. There is also a large pothole within this area which		
requires to be repaired.		
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50078285	Defect Number: 42064169	
Enquiry No.: 1131120	Logged by: Verint CRM Connector	on: 27/02/2021 15:01
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Customer Services

Enquiry No.: 1131118	Logged by: Verint CRM Connector	on: 27/02/2021 14:57
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Many potholes developing	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1131100	Logged by: Verint CRM Connector	on: 27/02/2021 14:15
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Deep potholes everywhere	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1128565	Logged by: Verint CRM Connector	on: 24/02/2021 08:19
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a massive potholes beside the bus stop, the road has now came up on the pavement, this has left massive hard bits off stones, cement, tar all causing a hazard when going on the bus and walking along this pavement.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1128176	Logged by: Verint CRM Connector	on: 23/02/2021 15:02
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Series of large and deep Potholes along Drum Street from Gala bingo hall to Candlemakers Park/new house construction.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1127803	Logged by: Verint CRM Connector	on: 23/02/2021 10:48
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Potholes and broken road surface along this road	Contact:	
Enquiry No.: 1106294	Logged by: Verint CRM Connector	on: 25/01/2021 08:25
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: The pavement between 125-29 Drum Street is all cracked, uneven, breaking up and man hole cover is now loose due to the pavement breaking up beside this.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1103223	Logged by: Verint CRM Connector	on: 19/01/2021 16:01
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: At entrance to Drum Estate on Drum Street where drop kerb allows vehicle access and where the cycle path crosses has degraded badly. Some haphazard patching has been done which if anything makes the hazards for cyclists	Contact:	

Effective: 25/06/2020 to 25/06/2025

Asset Number: 1.00 to 9.00

Service: Roads General

Display Action Officer: No

Site: Drum Street (7900664)

Customer Services

Enquiry No.: 1102495	Logged by: Verint CRM Connector	on: 18/01/2021 14:33
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Uneven/damaged road surface	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1091615	Logged by: Verint CRM Connector	on: 30/12/2020 13:59
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Big massive gap in the road that has not been repaired correctly previously this is now becoming once big massive dislodged pot hole	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1085334	Logged by: [REDACTED]	on: 15/12/2020 14:22
Service: Roads General	Subject: Road Markings: Defective	Classification: Request for service
Desc.: The bus stop outside of lidl at Gilmerton crossroads needs remarking as idiots keep parking on the bus stop	Contact: @GuyTurn17332395	
Location: outside of lidl at Gilmerton crossroads		
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50070455	Defect Number: 42057736	
Enquiry No.: 1065301	Logged by: Verint CRM Connector	on: 07/11/2020 21:48
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Pothole sufficiently deep to damage tyre/wheel. Difficult to avoid due to oncoming traffic. Outside Dominos Pizza takeaway	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1064162	Logged by: Verint CRM Connector	on: 05/11/2020 11:54
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Massive Pot Hole	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Enquiry No.: 1060752	Logged by: Verint CRM Connector	on: 29/10/2020 09:51
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.: Location: I tried to report this online but your website seems to be down for doing this section. I like to report issues with a broken and dangerous pavement. Between 125-129 Drum Street EH17 8RJ, Edinburgh	Contact:	
This pavement is made up off both tar and concrete and is very loose dangerous and I witnessed a buggy with a young mum about falling over after being caught in the broken areas. Could this pleased be reported and fixed as an emergency.		
Plot Number: 1.00	Feature Id - Location: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset
Job Number: 50129974	Defect Number: 42144156	

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1034489

Service: Roads General

Desc.: What type of sign is it? Road sign problem, type dontknow

Location: Hi, I was driving home & getting near the junction at the top of gilmerton road, approaching the drum street junction. When just before the traffic lights a middle part of a kerbside sign blew out onto the road & hit the front of my car. My car is a Nissan Quashia. This incident happened about 21-40.

Logged by: Verint CRM Connector

Subject: Traffic Sign:Defective/Damaged

Contact:

on: 04/09/2020 22:06

Classification: Request for service

Enquiry No.: 1003568

Service: Roads General

Desc.: Problem: Causing Obstruction.

Location:Footpath.

Type:Foliage / Bush

Location: Fallen branches and large section of a tree has fallen from public green space onto road and pavement , causing a hazard

Logged by: Verint CRM Connector

Subject: Trees & Foliage: Defect

Contact:

on: 05/07/2020 14:10

Classification: Request for service

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 16 - From Ferniehill Road to Gilmerton Station Road		Feature Type: Road Asset		Area: South East Locality	
50040178	Gull blocked / flooding (Gully: Blocked / Flooding)	Drum street southbound bus stop at lidl	RG: Gully - Standard Priority	Job Complete	19/08/2019	02/09/2020	Act. RDGC14/82000379
50057904	Missing kerb made safe by inspector please replace as best as you can match kerb (RD: FW Kerbs Damaged/Missing)	Drum street side of dominoes	RD: Cat 3 - 60 Day	Job Complete	06/07/2020	15/07/2020	Act. ROAD/82037368
50060440	Drum street o/s Domino's pizza shop Drop crossing required (RD: Kerbs)	Drum Street o/s Domino's pizza shop	RD: Cat 3 - 60 Day	Job Complete	17/08/2020	07/09/2020	Act. ROAD/82038699
50062678	Cw / Fw patch required Cw 1.5x3 Fw 2.5x2.5 (RD: CW Cracked/Broken)	Drum street at Dominoes	RD: Cat 3 - 60 Day	Job Complete	15/09/2020	06/10/2020	Act. ROAD/82039469
50066270	Cw pothole (RD: CW Pothole)	Drum street os dominoes	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/11/2020	05/11/2020	Act. ROAD/82040923
50068725	Cw pothole marked on site (RD: CW Pothole)	Drum street south bound at the drum	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	01/12/2020	02/12/2020	Act. ROAD/82041898
50069600	2 x rocking low slabs please lift and relay (RD: FW Slabs Rocking)	O/S Iceland behind bin near bus stop	RD: Cat 3 - 60 Day	Job Complete	10/12/2020	15/12/2020	Act. ROAD/82042324
50069601	Low patch on footway at kerb please top up with tar (RD: FW HRA Pothole)	O/S Dominoes	RD: Cat 3 - 60 Day	Job Complete	10/12/2020	11/12/2020	Act. ROAD/82042325
50069658	Footway depression remove leaves and make safe with tar (RD: FW HRA Pothole)	O/S 50	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/12/2020	11/12/2020	Act. ROAD/82042349
50069672	3 x potholes along kerb (RD: CW Pothole)	At entrance to Drum Lodge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/12/2020	11/12/2020	Act. ROAD/82042358

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 16 - From Ferniehill Road to Gilmerton Station Road		Feature Type: Road Asset		Area: South East Locality	
50070455	Refresh bus stop marking (RD: Markings Refresh)	Drum street os Iceland	Non Routine (One Off Works)	Job Complete	17/12/2020	27/05/2021	Act. ROAD/82049524
50077158	5no CW potholes (RD: CW Pothole)	Outside Dominos/Spex Opticians	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/03/2021	04/03/2021	Act. ROAD/82046217
50077160	1no CW pothole (RD: CW Pothole)	Outside no59	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/03/2021	04/03/2021	Act. ROAD/82046219
50077161	3no CW potholes (RD: CW Pothole)	Outside 48-50	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/03/2021	04/03/2021	Act. ROAD/82046220
50077162	1no CW pothole (RD: CW Pothole)	Outside no63	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/03/2021	04/03/2021	Act. ROAD/82046221
50077163	1no CW pothole (RD: CW Pothole)	Opposite Gilmerton Aned Hand Car Wah	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/03/2021	04/03/2021	Act. ROAD/82046222
50077165	1no CW pothole (RD: CW Pothole)	Opposite W&H Contracts	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/03/2021	04/03/2021	Act. ROAD/82046224
50078285	Refresh box junction (RD: Markings Refresh)	Drum Street at ravenscroft st	Non Routine (One Off Works)	Job Complete	15/03/2021	05/06/2021	Act. ROAD/82049525
50078290	Cw potholes marked on site x4 (RD: CW Pothole)	Drum street at ravenscroft street	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/03/2021	15/03/2021	Act. ROAD/82046874
50078345	Patching required 10m2 (RD: CW Subsidence/Heaving)	Drum street opp 117	RD: Cat 3 - 60 Day	Job Complete	15/03/2021	16/03/2021	Act. ROAD/82046890
50079791	Cw pothole marked on site (RD: CW Pothole)	Drum st city bound os 62	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/03/2021	30/03/2021	Act. ROAD/82047806
50083000	Lift and relay slabs to stop ponding (RD: FW Slabs Rocking)	Drum street opp gilmerton community centre	RD: Cat 3 - 60 Day	Job Complete	13/05/2021	12/06/2021	Act. ROAD/82049655
50083179	Cw potholes marked on site x2 (RD: CW Pothole)	Drum street opp 123	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/05/2021	19/05/2021	Act. ROAD/82049769
50083181	Cw pothole marked on site (RD: CW Pothole)	Drum street os 119	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/05/2021	19/05/2021	Act. ROAD/82049770
50084467	3no potholes (RD: CW Pothole)	Outside no57	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/06/2021	03/06/2021	Act. ROAD/82050493
50084470	1no pothole (RD: CW Pothole)	Outside studio45 opposite mechanic arms	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/06/2021	03/06/2021	Act. ROAD/82050495
50084490	Cw pothole marked on site (RD: CW Pothole)	Drum street at ferniehill road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/06/2021	03/06/2021	Act. ROAD/82050510
50084492	Cw potholes marked on site x3 (RD: CW Pothole)	Drum st at emerald guest house	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/06/2021	03/06/2021	Act. ROAD/82050511
50095598	Resurface Fw (RD: FW HRA Cracked/Broken)	Drum street os 129	RO: Programmed Works	Job Complete	02/11/2021	04/11/2021	Act. ROAD/82055691
50099742	1no pothole (RD: CW Pothole)	At the junction of Limefield	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/12/2021	13/12/2021	Act. ROAD/82057361
50102720	1 carriageway pothole (RD: CW Pothole)	Outside 84	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/01/2022	17/01/2022	Act. ROAD/82058676
50106179	x1 CW pothole, make safe. (RD: CW Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/02/2022	15/02/2022	Act. ROAD/82060168

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 16 - From Ferniehill Road to Gilmerton Station Road		Feature Type: Road Asset		Area: South East Locality	
50107987	2 number potholes (RD: CW Pothole)	Outside number 38 and 42	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/03/2022	04/03/2022	Act. ROAD/82061215
50108071	1 number pothole (RD: CW Pothole)	Opposite number 90	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/03/2022	04/03/2022	Act. ROAD/82061266
50108461	Pothole (RD: CW Pothole)	O/S entrance to THE DRUM	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061435
50108742	1x pothole marked on site (RD: CW Pothole)	Outside 44	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/03/2022	14/03/2022	Act. ROAD/82061568
50108743	1x pothole marked on site (RD: CW Pothole)	Just before junction with Candlemakers Park	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/03/2022	14/03/2022	Act. ROAD/82061569
50108993	Cw pothole marked on site (RD: CW Pothole)	Drum street os 141	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/03/2022	15/03/2022	Act. ROAD/82061695
50109808	Cw potholes marked on site x3 (RD: CW Pothole)	Drum street opp 83	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/03/2022	23/03/2022	Act. ROAD/82062056
50109809	Cw pothole marked on site (RD: CW Pothole)	Drum street opp 61	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/03/2022	23/03/2022	Act. ROAD/82062057
50111522	Cw breaking up hot overlays required As discussed with AScougall (RD: CW Cracked/Broken)	Drum street city bound from 48 to 40	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/04/2022	10/04/2022	Act. ROAD/82062951
50112694	Cw pothole marked on site (RD: CW Pothole)	Drum street city bound at limefield	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/05/2022	02/05/2022	Act. ROAD/82063547
50112993	Parking: Disabled Bay refresh (RD: Markings Disabled Bay)	57 Drum Street Edinburgh City of Edinburgh EH17 8RN	Parking Operations	Job Complete	04/05/2022	10/05/2022	Act. ROAD/82063787
50112994	Parking: Disabled Bay refresh (RD: Markings Disabled Bay)	61 Drum Street Edinburgh City of Edinburgh EH17 8RN	Parking Operations	Job Complete	04/05/2022	10/05/2022	Act. ROAD/82063789
50113567	x2 CW pothole, make safe. (RD: CW Pothole)	Outside 54.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/05/2022	16/05/2022	Act. ROAD/82064074
50115428	1no pothole (RD: CW Pothole)	At the junction of Candlemakers Park	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/06/2022	16/06/2022	Act. ROAD/82065037
50123853	Rocking slabs x3 (RD: FW Slabs Rocking)	Drum st at gilmerton cove	RD: Cat 3 - 60 Day	Job Complete	08/12/2022	06/02/2023	Act. ROAD/82069289
50126054	Install new dropped crossings. 1x LH transition, 1 RH transition, 6x Whin Bullnose Kerb (lift and relay if possible) Tactile paving to be installed at drops suitable for stick down tactiles. (RD: NEW Dropped Kerbs)	Opposite No.95 (please refer to drawing attached)	RO: Programmed Works	RSWT: PU Drawings Attached	12/01/2023	20/08/2024	Est. ROAD/82070752

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 16 - From Ferniehill Road to Gilmerton Station Road		Feature Type: Road Asset		Area: South East Locality	
50126058	Install new dropped crossing. 1x LH Transition, 1x RH Transition, 16 x Buff Tactiles (sticky) & 6 Bull Nose Whin Kerb (lift and relay if possible) (RD: NEW Dropped Kerbs)	Opposite No.87 as per the attached plan.	RO: Programmed Works	RSWT: PU Drawings Attached	12/01/2023	20/08/2024 Est.	ROAD/82070754
50126061	Install new dropped crossing. 1x LH transition, 1x RH transition & 6 x Whin Bullnose (to be lifted and relayed if possible). (RD: NEW Dropped Kerbs)	Near junction with Ferniehill Road as per attached plan	RO: Programmed Works	RSWT: PU Drawings Attached	12/01/2023	12/01/2024 Est.	ROAD/82070757
50128067	Remove x1 yellow housing development sign for "Kings Cove" from directional sign. Leave sign for "Farrier Fields" if installed. (RD: Unlit Sign Damaged/Missing)	At rear of house at entrance to the Drum.	RD: Cat 3 - 60 Day	Job Complete	31/01/2023	01/02/2023 Act.	ROAD/82072134
50129144	Bollard and pavement damaged please make safe Pavement: Damaged / Defective (Enquiry 1508986) (RD: Bollard Damage/Missing/New)	Opposite supperbowl	RD: Cat 2 - 5 Day	Job Complete	13/02/2023	14/02/2023 Act.	ROAD/82072736
50130814	Cw x 2 Road: Defective / Damaged (Enquiry 1516961) (RD: CW Pothole)	Outside of Faith Mission, opposite Lloyds chemist	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/03/2023	02/03/2023 Act.	ROAD/82073664
50131169	Cw x 2 potholes Road: Defective / Damaged (Enquiry 1518420) (RD: CW Pothole)	At the junction outside the Chemist and BT box outside of number 2	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/03/2023	07/03/2023 Act.	ROAD/82073851
50134161	Installation of dropped crossing (RD: NEW Dropped Kerbs)	Outside No.63 as per attached location plan	RO: Programmed Works	Job Complete	12/04/2023	15/07/2023 Act.	ROAD/82075708
50134601	Please install Keep Clear markings (RD: Markings New)	Opposite east farm of Gilmerton junction northbound	RD: Cat 4 - Programmed	Job Complete	19/04/2023	22/04/2023 Act.	ROAD/82076048
50136955	Fw x1 pothole Pavement: Damaged / Defective (Enquiry 1558012) (RD: FW HRA Pothole)	Outside of 125	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/05/2023	30/05/2023 Act.	ROAD/82077763
50138303	Cw x5 potholes Road: Defective / Damaged (Enquiry 1571874) (RD: CW Pothole)	At the junction of Gilmerton Road and Ferniehill Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/06/2023	27/06/2023 Act.	ROAD/82078542
50145548	Uplift damaged / collapsed signs pole and sign cones from footway outside house no 84 and make safe footway. (RD: Unlit Sign Damaged/Missing)	Outside house no 84 Drum street at junction with Limefield	RD: Cat 2 - 5 Day	Job Complete	10/11/2023	15/11/2023 Act.	ROAD/82082602
50150291	1no damaged bollard (RD: SFP Damaged Bollard)	Drum st opposite abercorn vets	RD: Cat 3 - 60 Day	Job Complete	16/01/2024	14/02/2024 Act.	ROAD/82085518

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Drum Street (7900664)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Ward 16 - From Ferniehill Road to Gilmerton Station Road	Feature Type: Road Asset		Area: South East Locality		
50150301	Loose manhole cover (RU: Utility Apparatus)	No38 drum st	RD: Cat 3 - 60 Day	Job Complete	16/01/2024	08/03/2024	Act. ROAD/82085519
50152734	Signs: General Enquiry - Damage pole and sign (Enquiry 34007744) (RD: Unlit Sign Damaged/Missing)	Please install new no through road sign on new pole At the junction with Drum Street as per attached documents	RD: Cat 3 - 60 Day	Job Complete	12/02/2024	26/02/2024	Act. ROAD/82087236
50157720	Cw x1 pothole Road: Defective / Damaged (Enquiry 1727612) (RD: CW Pothole)	Opposite nursery at. City bound bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/04/2024	10/04/2024	Act. ROAD/82090775
50169995	2no fw potholes (RD: FW HRA Pothole)	Outside no3	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/11/2024	19/11/2024	Act. ROAD/82098565
50171393	No 1 Edinburgh bollard (RD: Bollard Damage/Missing/New)	At the corner of ravenicroft street	RD: Cat 3 - 60 Day	Job Complete	13/12/2024	17/12/2024	Act. ROAD/82099594
50171429	1 no pothole (RD: CW Pothole)	At bustop at Iceland	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/12/2024	16/12/2024	Act. ROAD/82099627
50174130	1no surround of catv box low (RD: FW HRA Pothole)	Opposite no 117 next to bus stop on fw	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/02/2025	04/02/2025	Act. ROAD/82101695
50174133	1no surround of catv box low (RD: FW HRA Pothole)	At entrance into car wash garage outside no80	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/02/2025	04/02/2025	Act. ROAD/82101697

Effective: 25/06/2020 to 25/06/2025	Asset Number: 5.00 to 6.00
Service: Accident Claims (All Services)	Display Action Officer: No
Site: Gilmerton Road (7901804)	

Site: Gilmerton Road (7901804)	Locality: Gilmerton, Edinburgh, City of Edinburgh	Area: South East Locality
--------------------------------	---------------------------------------------------	---------------------------

Customer Services

Enquiry No.: 34005933	Logged by: [REDACTED]	on: 20/10/2022 14:50
Service: Accident Claims (All Services)	Subject: Accident Claim Roads/Lighting	Classification: Accident Claim
Desc.: our client crossed the road and her foot caught the edge of the bolard base		
Location: near Star Bright Nursery	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Enquiry No.: 34005140	Logged by: [REDACTED]	on: 14/04/2022 12:35
Service: Accident Claims (All Services)	Subject: Accident Claim Roads/Lighting	Classification: Accident Claim
Desc.: mechanical damage		
Location: 401 Gilmerton Road	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Enquiry No.: 34004528	Logged by: [REDACTED]	on: 10/12/2021 11:45
Service: Accident Claims (All Services)	Subject: Accident Claim Roads/Lighting	Classification: Accident Claim
Desc.: Our client fell from his motorcycle after colliding with the rubber base for a bollard at the edge of a cycle lane		
Location:	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Enquiry No.: 1873177	Logged by: Verint CRM Connector	on: 19/12/2024 11:14
Service: Accident Claims (All Services)	Subject: Accident Claim Roads/Lighting	Classification: Accident Claim
Desc.: large pothole in the pavement lady hit is with her shopping trolley and went over the top landed on her wrists which are both broken and hit her calf whcih is black and blue she is a hairdresser and can't work whcih she will lose alot of money		
Location:	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Enquiry No.: 1838526	Logged by: Verint CRM Connector	on: 30/09/2024 18:43
Service: Accident Claims (All Services)	Subject: Accident Claim Roads/Lighting	Classification: Accident Claim
Desc.: Slid off motorbike due to wet pothole/gash in roundabout. Tried to flag down passing police officer so I could get back on road but they kept driving. In bad connection awaiting RAC so please contact me via [REDACTED] for photos.		
Location:	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Enquiry No.: 1354297	Logged by: [REDACTED]	on: 31/03/2022 08:51
Service: Accident Claims (All Services)	Subject: Accident Claim Roads/Lighting	Classification: Accident Claim
Desc.: I left my home and drove a few yards down the road and went over a very uneven spot on the road then right after went into a pot hole there was a loud noise and later discovered that a coil spring had broken and there was damage to the suspension also tyres had to be replaced - This was due to the bad condition of the road. I have enclosed photos of the damage on the road and also my invoice for the repairs to my car. I would like to make claim for this damage.		
Location: 517 Gilmerton Road Edinburgh EH17 7JB.	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025
 Service: Accident Claims (All Services)
 Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
 Display Action Officer: No

Customer Services

Enquiry No.: 1302955	Logged by: [REDACTED]	on: 07/01/2022 14:19
Service: Accident Claims (All Services)	Subject: Accident Claim Roads/Lighting	Classification: Accident Claim
Desc.: On driving up the Gilmerton Road at approximately 20.50, I hit an unseen pothole causing damage to my front and rear driver side tyres. I was on my way to pick my daughter up from work at new [REDACTED] hall shopping centre. I slowly made my way there and managed a temporary fix by introducing sealant to the tyres. I had phoned green flag but as they couldn't come out until 23.33 I slowly made my way home. The next morning 30 December both tyres now flat , I contacted both green flag and VW road side assistance as VW was quicker I asked them for assistance . AA arrived and as both tyres needed replaced they placed a temporary wheel on the front and inflated the rear tyre and followed me to kwik fit Dundee street for tyre replacement and wheel balance plus tyre replacement sealant cost £278.88. After this repair I made my way to Gilmerton road opposite Morrison's or just past Morrison's to locate this pot hole and photograph it for evidence however it seems to have either been repaired or I missed it - either way I would like to know if I can claim for the damage to my tyres and costs. I look forward to hearing from you.		
Location: Gilmerton road opposite Morrison's or just past Morrison's		Contact:
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station Feature Type: Road Asset	
Enquiry No.: 1273168	Logged by: [REDACTED]	on: 11/11/2021 09:49
Service: Accident Claims (All Services)	Subject: Accident Claim Roads/Lighting	Classification: Accident Claim
Desc.: My name is [REDACTED] burgoyne and today 9/11/2021 at 11.30am I was walking through your bus stop on the gilmerton rd on the inch park surgery side , 3rd one up from lady rd , which has been damaged and vandalised , the middle window has been kicked open and is leaning inwards the window caught my left arm and ripped a hole in my new jacket who's can't be repaired, I have took photos as proof, my jacket cost £150		
Location: Inch park doctors surgery		Contact:
Enquiry No.: 1145753	Logged by: [REDACTED]	on: 22/03/2021 15:30
Service: Accident Claims (All Services)	Subject: Accident Claim Roads/Lighting	Classification: Accident Claim
Desc.: As part of the Spaces for People project on Gilmerton Road, the entrance to Guardwell Crescent (from Gilmerton Road) was narrowed and given a new spend bump. The moment it was installed, numerous complaints were registered that it was too high and risked damaging cars. In early January, [REDACTED] confirmed that the "Council had already raised it with the contractor who had confirmed it was too high and that, weather permitting, it would be re-laid within two weeks." On 15 March, while travelling over the speed bump I heard a loud crack from my car and a subsequent loud noise in turning the wheel. I took it to the garage who confirmed damage to the front suspension. It has been repaired at a cost of £240.05 (inclusive). On 16 March 2021, the speed bump was re-laid		
Location: at junct of Guardwell Crescent by speed bump		Contact:
Enquiry No.: 1065677	Logged by: [REDACTED]	on: 09/11/2020 09:09
Service: Accident Claims (All Services)	Subject: Accident Claim Roads/Lighting	Classification: Request for service
Desc.: Serious issue with narrowing entrances into the areas work carried out multiple entrances all the way up the gilmerton road (new cycle lanes. Work is taking place between gilmerton road and left on to mordon park road. Kerbs not completed resulted in caller bursting tyre on exposed edge of kerb. Instead of 90 degree turn which there was no problem with previously now they have reduced the size of road entrance increasing pavement widths. Car tyre is ripped the tyre. Work incomplete and no cones and signage at all. The whole area requires to be sorted regarding above. Area where this happened was on opposite side of road from post box. Caller has photographic evidence of this.		
Location: Work is taking place between gilmerton road and left on to mordon park road.		Contact:
Enquiry No.: 1049754	Logged by: [REDACTED]	on: 05/10/2020 14:16
Service: Accident Claims (All Services)	Subject: Accident Claim Roads/Lighting	Classification: Accident Claim
Desc.: Good morning , on Sat.3 Oct @ approx 12.15 my rear suspension on my car, reg no [REDACTED] a Jaguar XK , was damaged driving over a broken manhole cover which had collapsed into the manhole & was filled with rainwater together with surface rainwater. I was unable to see the broken manhole & my car ran over it, followed by a loud crack from my rear suspension. I was able to drive my car slowly to my son's house where I had to abandon it . He then had to drive me home to Melrose. The incident took place at the roundabout off the slip road from the city bypass where it meets Gilmerton road. It should be noted that the broken manhole did not have traffic cones to highlight the problem. My car is being picked up from my son's house today & being taken to a garage in Kelso for repair. My insurance company require contact information from you as they intend to follow up this incident with you. Please acknowledge receipt of this email by return. Should you require it I have photos of the broken manhole & my car.		
Location: The incident took place at the roundabout off the slip road from the city bypass where it meets Gilmerton road		Contact:

Effective: 25/06/2020 to 25/06/2025
Service: Accident Claims (All Services)
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Site: Gilmerton Road (7901804)			Locality: Gilmerton, Edinburgh, City of Edinburgh			Area: South East Locality			
Condition Survey									
Defect No: Description		Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.	
Asset: 5.00		Asset - Locn.: Ward 16 - Glenallan Drive to Ferniehill Road.			Gilmerton Station		Feature Type: Road Asset		Area: South East Locality
Batch: 41231541 - Inspection Batch				Route: SfP_SouthEast				Date: 23/06/2025	
No actionable defects found									
Batch: 41230284 - Inspection Batch				Route: South Mobile Inspection Route				Date: 06/06/2025	
No actionable defects found									
Batch: 41228214 - Inspection Batch				Route: SfP_SouthEast				Date: 14/05/2025	
42183492	1no missing bollard	14/05/2025	Opposite high school entrance	RD: SFP Damaged Bollard	Internal		Committed	50179887	
42183493	1no missing bollard	14/05/2025	At Aldi car park	RD: SFP Damaged Bollard	Internal		Committed	50179888	
Batch: 41227765 - Inspection Batch				Route: South Mobile Inspection Route				Date: 07/05/2025	
No actionable defects found									
Batch: 41226182 - Inspection Batch				Route: SfP_SouthEast				Date: 16/04/2025	
No actionable defects found									
Batch: 41225605 - Inspection Batch				Route: South Mobile Inspection Route				Date: 09/04/2025	
No actionable defects found									
Batch: 41224545 - Inspection Batch				Route: Mobile Inspection Strategic				Date: 30/03/2025	
No actionable defects found									
Batch: 41224025 - Inspection Batch				Route: SfP_SouthEast				Date: 24/03/2025	
No actionable defects found									
Batch: 41223837 - Inspection Batch				Route: Mobile Inspection Strategic				Date: 24/03/2025	
42179503	Manhole in centre of raod sunken and surround breaking up.	23/03/2025	10m south of lamppost GEN22 in centre of carriageway	RU: Utility Apparatus	Internal		Uncommitted	50177446	
Batch: 41222810 - Inspection Batch				Route: Mobile Inspection Strategic				Date: 15/03/2025	
No actionable defects found									
Batch: 41222406 - Inspection Batch				Route: South Mobile Inspection Route				Date: 12/03/2025	
No actionable defects found									
Batch: 41221674 - Inspection Batch				Route: Mobile Inspection Strategic				Date: 06/03/2025	
No actionable defects found									
Batch: 41221008 - Inspection Batch				Route: Mobile Inspection Strategic				Date: 28/02/2025	
No actionable defects found									
Batch: 41220539 - Inspection Batch				Route: Ad hoc Route				Date: 25/02/2025	
42176971	Sunken manhole see photo attached	25/02/2025	Gilmerton road 16 meters south of lamppost gen 22	RU: Utility Apparatus	Internal		Uncommitted	50175844	
Batch: 41220298 - Inspection Batch				Route: SfP_SouthEast				Date: 24/02/2025	
42176788	2no missing bollards	24/02/2025	Outside 251	RD: SFP Damaged Bollard	Internal		Committed	50175701	
42176791	Reinstate 2no dislodged bollard bases	24/02/2025	Opposite Southern medical practice	RD: SFP Damaged Bollard	Internal		Committed	50175704	

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
Batch:	41220104 - Inspection Batch			Route: Mobile Inspection Strategic				Date: 20/02/2025
	No actionable defects found							
Batch:	41218856 - Inspection Batch			Route: Mobile Inspection Strategic				Date: 12/02/2025
	No actionable defects found							
Batch:	41218651 - Inspection Batch			Route: South Mobile Inspection Route				Date: 12/02/2025
42175751	1 pothole	12/02/2025	Outside 509	RD: CW Pothole	Internal		Committed	50174889
Batch:	41217116 - Inspection Batch			Route: Mobile Inspection Strategic				Date: 31/01/2025
	No actionable defects found							
Batch:	41216811 - Inspection Batch			Route: SfP_SouthEast				Date: 29/01/2025
	No actionable defects found							
Batch:	41216565 - Inspection Batch			Route: Ad hoc Route				Date: 28/01/2025
42174158	No 1 pothole	28/01/2025	Outside no 290	RD: CW Pothole	Internal		Committed	50173691
Batch:	41215796 - Inspection Batch			Route: Mobile Inspection Strategic				Date: 21/01/2025
	No actionable defects found							
Batch:	41214273 - Inspection Batch			Route: SfP_SouthEast				Date: 13/01/2025
	No actionable defects found							
Batch:	41213620 - Inspection Batch			Route: South Mobile Inspection Route				Date: 09/01/2025
	No actionable defects found							
Batch:	41210852 - Inspection Batch			Route: SfP_SouthEast				Date: 12/12/2024
	No actionable defects found							
Batch:	41210342 - Inspection Batch			Route: South Mobile Inspection Route				Date: 10/12/2024
	No actionable defects found							
Batch:	41208682 - Inspection Batch			Route: Ad hoc Route				Date: 26/11/2024
42169907	2no missing SFP bollards	26/11/2024	Section of SFP outside no368	RD: SFP Damaged Bollard	Internal		Committed	50170402
Batch:	41207801 - Inspection Batch			Route: SfP_SouthEast				Date: 15/11/2024
42169223	1no missing bollard Replace damaged base	15/11/2024	Opposite Craigend park	RD: SFP Damaged Bollard	Internal		Committed	50169842
Batch:	41207393 - Inspection Batch			Route: South Mobile Inspection Route				Date: 12/11/2024
	No actionable defects found							
Batch:	41206151 - Inspection Batch			Route: SE_CF2_InchEast3				Date: 02/11/2024
42168197	Cycle lane bollard dislodged x6 please reinstall	01/11/2024	Outside the Southern Medical Group	RD: SFP Damaged Bollard	Internal		Uncommitted	50148005
42168196	1no pole has been removed leaving the pole base please cut away and make safe with cold tar	01/11/2024	Outside no255 at bus stop	TS: Sign Pole Loose	Internal		Committed	50169060
42168200	Patch required Approx. 4m x 1m	01/11/2024	Outside 543	RD: CW Cracked/Broken	Internal		Uncommitted	50120307

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
Batch:	41206151 - Inspection Batch			Route: SE_CF2_InchEast3				Date: 02/11/2024
42168198	Damaged kerb 630mm	01/11/2024	15m South of Guardwell Crescent	RD: FW Kerbs Damaged/Missing	Internal		Uncommitted	50108500
Batch:	41205430 - Inspection Batch			Route: Ad hoc Route				Date: 28/10/2024
	No actionable defects found							
Batch:	41204483 - Inspection Batch			Route: SfP_SouthEast				Date: 21/10/2024
42167219	1no missing bollard	21/10/2024	Opposite 304	RD: SFP Damaged Bollard	Internal		Committed	50168411
42167217	3no missing bollards	21/10/2024	At the junction with Redgauntlet Terrace and opposite Craigend Park	RD: SFP Damaged Bollard	Internal		Committed	50168409
42167222	2no missing bollards	21/10/2024	Outside 368	RD: SFP Damaged Bollard	Internal		Committed	50168414
Batch:	41203083 - Inspection Batch			Route: South Mobile Inspection Route				Date: 11/10/2024
	No actionable defects found							
Batch:	41200887 - Inspection Batch			Route: SfP_SouthEast				Date: 18/09/2024
42165093	Replace missing SFP bollard	18/09/2024	Opposite craigend park	RD: SFP Damaged Bollard	Internal		Committed	50166707
42165094	Replace x3 missing SFP bollard	18/09/2024	See pin point and photos for location	RD: SFP Damaged Bollard	Internal		Committed	50166708
Batch:	41200316 - Inspection Batch			Route: South Mobile Inspection Route				Date: 10/09/2024
	No actionable defects found							
Batch:	41198684 - Inspection Batch			Route: South Mobile Inspection Route				Date: 14/08/2024
	No actionable defects found							
Batch:	41198394 - Inspection Batch			Route: SfP_SouthEast				Date: 12/08/2024
42163387	3no missing bollards	12/08/2024	Section between [redacted] s [redacted] rd and aldi	RD: SFP Damaged Bollard	Internal		Committed	50165179
42163388	2no damaged bollards 1no broken base	12/08/2024	Opposite Craigend Park	RD: SFP Damaged Bollard	Internal		Committed	50165180
Batch:	41197179 - Inspection Batch			Route: SfP_SouthEast				Date: 22/07/2024
42162192	1no missing bollard	22/07/2024	Opposite 415	RD: SFP Damaged Bollard	Internal		Committed	50164237
Batch:	41196925 - Inspection Batch			Route: South Mobile Inspection Route				Date: 18/07/2024
	No actionable defects found							
Batch:	41194691 - Inspection Batch			Route: South Mobile Inspection Route				Date: 18/06/2024
	No actionable defects found							
Batch:	41194530 - Inspection Batch			Route: SfP_SouthEast				Date: 17/06/2024
	No actionable defects found							
Batch:	41192315 - Inspection Batch			Route: Ad hoc Route				Date: 20/05/2024
42157576	Fw x3 potholes	20/05/2024	Outside of 513	RD: FW HRA Pothole	Internal		Committed	50160669
Batch:	41191869 - Inspection Batch			Route: South Mobile Inspection Route				Date: 14/05/2024
	No actionable defects found							

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
Batch:	41191551 - Inspection Batch			Route: SfP_SouthEast				Date: 09/05/2024
42156897	1no base needs reset	09/05/2024	Opposite Start Bright Nursery	RD: SFP Damaged Bollard	Internal		Committed	50160105
Batch:	41191070 - Inspection Batch			Route: Ad hoc Route				Date: 02/05/2024
42156382	Cw x1 pothole , make safe	02/05/2024	Just before the bridge deck (southbound) , also reported to Scottish Water	RD: CW Pothole	Internal		Committed	50159732
Batch:	41189887 - Inspection Batch			Route: SfP_SouthEast				Date: 18/04/2024
42155118	1no damaged bollard	18/04/2024	Opposite no 284	RD: SFP Damaged Bollard	Internal		Committed	50158724
Batch:	41189764 - Inspection Batch			Route: Ad hoc Route				Date: 17/04/2024
42154973	6x cycle lane bollards, loose and damaged	17/04/2024	Outside new high school	RD: SFP Damaged Bollard	Internal		Committed	50158604
Batch:	41189752 - Inspection Batch			Route: Ad hoc Route				Date: 17/04/2024
42154961	Cycle lane bollard dislodged x6 please reinstall	17/04/2024	Outside the Southern Medical Group	RD: SFP Damaged Bollard	Internal		No Action Required	
Batch:	41189197 - Inspection Batch			Route: Ad hoc Route				Date: 10/04/2024
42154361	1 pothole	10/04/2024	Outside 543	RD: CW Pothole	Internal		Committed	50158045
Batch:	41188865 - Inspection Batch			Route: Ad hoc Route				Date: 09/04/2024
42154015	2 cw potholes	09/04/2024	Outside 290	RD: CW Pothole	Internal		Committed	50157750
Batch:	41188758 - Inspection Batch			Route: South Mobile Inspection Route				Date: 08/04/2024
	No actionable defects found							
Batch:	41187198 - Inspection Batch			Route: Ad hoc Route				Date: 22/03/2024
42152569	Cw x 3 potholes	22/03/2024	Roundabout off bypass eastbound slip	RD: CW Pothole	Internal		Committed	50156585
Batch:	41187097 - Inspection Batch			Route: SfP_SouthEast				Date: 21/03/2024
42152484	1no dislodged base	21/03/2024	Opposite start bright nursery	RD: SFP Damaged Bollard	Internal		Committed	50156499
Batch:	41186778 - Inspection Batch			Route: Ad hoc Route				Date: 19/03/2024
42152130	Collapsed 600x600 carriageway sewer cover	19/03/2024	City bound carriageway 200m south of [REDACTED] Crane Hire, 600 Gilmartin rd Edinburgh EH178RY	RU: Utility Apparatus	Internal		Uncommitted	50156226
Batch:	41185767 - Inspection Batch			Route: South Mobile Inspection Route				Date: 11/03/2024
42151154	1 cw pothole	11/03/2024	Citybound lane See pin location	RD: CW Pothole	Internal		Committed	50155468
Batch:	41183807 - Inspection Batch			Route: SfP_SouthEast				Date: 26/02/2024
	No actionable defects found							
Batch:	41183458 - Inspection Batch			Route: South Mobile Inspection Route				Date: 22/02/2024
	No actionable defects found							
Batch:	41180917 - Inspection Batch			Route: Ad hoc Route				Date: 01/02/2024
42146000	Grano patch failed, please excavate and reinstate (old bus stop pole)	01/02/2024	Opposite number 433	RD: FW Grano Cracked/Broken	Internal		Committed	50151901

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
Batch:	41179748 - Inspection Batch			Route: SIF_SouthEast				Date: 23/01/2024
	No actionable defects found							
Batch:	41179276 - Inspection Batch			Route: South Mobile Inspection Route				Date: 19/01/2024
	No actionable defects found							
Batch:	41174939 - Inspection Batch			Route: South Mobile Inspection Route				Date: 19/12/2023
42142389	1no pothole	19/12/2023	Outside no541	RD: CW Pothole	Internal		Committed	50148501
Batch:	41174863 - Inspection Batch			Route: Ad hoc Route				Date: 18/12/2023
42142335	Cw x1 pothole	18/12/2023	Outside of number 290	RD: CW Pothole	Internal		Committed	50148440
Batch:	41174379 - Inspection Batch			Route: Ad hoc Route				Date: 14/12/2023
42141892	Cycle lane bollard dislodged, please reinstall	14/12/2023	Outside the Southern Medical Group	RD: SFP Damaged Bollard	Internal		No Action Required	
Batch:	41172715 - Inspection Batch			Route: SIF_SouthEast				Date: 24/11/2023
42140386	Reset 2no bollard bases	24/11/2023	Opposite Liberton High School entrance	RD: SFP Damaged Bollard	Internal		Committed	50146563
Batch:	41172511 - Inspection Batch			Route: Ad hoc Route				Date: 21/11/2023
42140177	Fw x1 pothole (makesafe)	21/11/2023	outside 539 Gilmerton Road	RD: FW HRA Pothole	Internal		Committed	50146355
Batch:	41172127 - Inspection Batch			Route: South Mobile Inspection Route				Date: 17/11/2023
	No actionable defects found							
Batch:	41171634 - Inspection Batch			Route: SE_CF2_InchEast3				Date: 10/11/2023
42139288	Footway cracked - broken	10/11/2023		RD: FW HRA Cracked/Broken	Internal		Uncommitted	50108449
42139277		10/11/2023		RD: FW HRA Cracked/Broken	Internal		Uncommitted	50076088
42139286	Patch required	10/11/2023	Outside 543	RD: CW Cracked/Broken	Internal		No Action Required	
	Approx 4m x 1m							
42139273	Cross track broken - cracked in same area. Patch required 6 x 3 sqm	10/11/2023		RD: CW Cracked/Broken	Internal		Uncommitted	50076089
42139287	Patch required	10/11/2023	At crossing outside 523	RD: CW Cracked/Broken	Internal		Uncommitted	50120308
	Approx 3m x 1m							
42139284	Refresh all faded markings	10/11/2023	From gilmerton station road to number 495	RD: Markings Refresh	Internal		Uncommitted	50075935
Batch:	41170558 - Inspection Batch			Route: Ad hoc Route				Date: 31/10/2023
42138389	BT manhole noisy	31/10/2023	At the junction with Greenpark	RU: Utility Apparatus	Internal		Uncommitted	50144762
Batch:	41169197 - Inspection Batch			Route: SIF_SouthEast				Date: 23/10/2023
42137897	1no missing bollard	23/10/2023	Approx 20m south of lamppost GEN35	RD: SFP Damaged Bollard	Internal		Committed	50144367
42137903	1no missing bollard	23/10/2023	Opposite 497	RD: SFP Damaged Bollard	Internal		Committed	50144372
42137905	Reset bollard base	23/10/2023	Opposite 495	RD: SFP Damaged Bollard	Internal		Committed	50144374
	1no missing bollard							
42137898	1no missing bollard	23/10/2023	At lamppost GEN 57	RD: SFP Damaged Bollard	Internal		Committed	50144368
42137761	1no damaged bollard	20/10/2023	Opposite Rutherford drive	RD: SFP Damaged Bollard	Internal		Committed	50144293
42137892	1no missing bollard	23/10/2023	Opposite Lamppost GEN33	RD: SFP Damaged Bollard	Internal		Committed	50144361
42137904	1no missing bollard	23/10/2023	Opposite 497	RD: SFP Damaged Bollard	Internal		Committed	50144373

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
Batch:	41169197 - Inspection Batch			Route: SFP_SouthEast				Date: 23/10/2023
42137901	1no missing bollard	23/10/2023	See pin location	RD: SFP Damaged Bollard	Internal		Committed	50144370
42137900	1no missing bollard	23/10/2023	See pin location	RD: SFP Damaged Bollard	Internal		Committed	50144369
42137760	1no damaged bollard	20/10/2023	10m south of lamppost 22	RD: SFP Damaged Bollard	Internal		Committed	50144292
Batch:	41168764 - Inspection Batch			Route: South Mobile Inspection Route				Date: 16/10/2023
	No actionable defects found							
Batch:	41166134 - Inspection Batch			Route: South Mobile Inspection Route				Date: 21/09/2023
	No actionable defects found							
Batch:	41164000 - Inspection Batch			Route: Ad hoc Route				Date: 30/08/2023
42135134	Fwx 1 pothole Pavement: Damaged / Defective (Enquiry 1605659)	30/08/2023	Outside of 505	RD: CW Pothole	Internal		Committed	50141854
Batch:	41163401 - Inspection Batch			Route: South Mobile Inspection Route				Date: 22/08/2023
	No actionable defects found							
Batch:	41161223 - Inspection Batch			Route: South Mobile Inspection Route				Date: 18/07/2023
	No actionable defects found							
Batch:	41160829 - Inspection Batch			Route: Ad hoc Route				Date: 12/07/2023
42131656	Manhole loose and noisy	12/07/2023	Outside of number 429	RU: Utility Apparatus	Internal		Uncommitted	50139106
Batch:	41159245 - Inspection Batch			Route: South Mobile Inspection Route				Date: 14/06/2023
	No actionable defects found							
Batch:	41157653 - Inspection Batch			Route: South Mobile Inspection Route				Date: 19/05/2023
42128108	1no pothole	19/05/2023	Outside no451	RD: CW Pothole	Internal		Committed	50136386
Batch:	41155709 - Inspection Batch			Route: South Mobile Inspection Route				Date: 25/04/2023
	No actionable defects found							
Batch:	41154012 - Inspection Batch			Route: Ad hoc Route				Date: 05/04/2023
42124629	Cycle lane bollard damaged Road: Defective / Damaged (Enquiry 1532379)	05/04/2023	Outside of Liberton High School	RD: SFP Damaged Bollard	Internal		Committed	50133676
Batch:	41153290 - Inspection Batch			Route: South Mobile Inspection Route				Date: 27/03/2023
	No actionable defects found							
Batch:	41151999 - Inspection Batch			Route: Ad hoc Route				Date: 13/03/2023
42122211		13/03/2023	Traffic island crossing point and cycle lane (Southbound)	RD: CW Pothole	Internal		Committed	50131752
Batch:	41150356 - Inspection Batch			Route: South Mobile Inspection Route				Date: 24/02/2023
	No actionable defects found							
Batch:	41147627 - Inspection Batch			Route: Ad hoc Route				Date: 31/01/2023
42117028	Remove x1 yellow housing development sign for "Gilmerton Heights" from direction sign. Leave sign for "Farrier Fields" if installed.	31/01/2023	Approx 30m north of entrance into Enigma industrial services etc.	RD: Unlit Sign Damaged/Missing	Internal		Committed	50128069

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
Batch:	41146297 - Inspection Batch			Route: South Mobile Inspection Route				Date: 24/01/2023
42116300	Large depression requires hra overlay	24/01/2023	On the pedestrian crossing outside Brite Dental	RD: CW Pothole	Internal		Committed	50127327
Batch:	41143815 - Inspection Batch			Route: Ad hoc Route				Date: 17/01/2023
42115311	Replaced missing bollard	17/01/2023		RD: SFP Damaged Bollard	Internal		Committed	50126435
Batch:	41140044 - Inspection Batch			Route: South Mobile Inspection Route				Date: 19/12/2022
	No actionable defects found							
Batch:	41137121 - Inspection Batch			Route: South Mobile Inspection Route				Date: 29/11/2022
	No actionable defects found							
Batch:	41136861 - Inspection Batch			Route: Ad hoc Route				Date: 28/11/2022
42112178	Replaced missing bollard	28/11/2022		RD: SFP Damaged Bollard	Internal		Committed	50123159
Batch:	41136855 - Inspection Batch			Route: Ad hoc Route				Date: 28/11/2022
42112171	Replaced damaged bollard	28/11/2022		RD: SFP Damaged Bollard	Internal		Committed	50123152
Batch:	41135802 - Inspection Batch			Route: Ad hoc Route				Date: 16/11/2022
42111349	Replaced missing bollard	16/11/2022		RD: SFP Damaged Bollard	Internal		Committed	50122340
Batch:	41135106 - Inspection Batch			Route: Ad hoc Route				Date: 08/11/2022
42110896	1 carriageway pothole	08/11/2022	Outside 290	RD: CW Pothole	Internal		Committed	50121816
Batch:	41135083 - Inspection Batch			Route: Ad hoc Route				Date: 08/11/2022
42110886	Cycle defender is broken away from the road and needs fixed back down..	08/11/2022		RD: SFP Damaged Bollard	Internal		Committed	50121807
Batch:	41134988 - Inspection Batch			Route: Ad hoc Route				Date: 07/11/2022
42110834	Hot overlays required	07/11/2022	Gilmerton road roundabout at bypass off ramp	RD: CW Cracked/Broken	Internal		Committed	50121716
Batch:	41134620 - Inspection Batch			Route: Ad hoc Route				Date: 02/11/2022
42110338	Replaced damaged cycle defender has broken away from road and needs fixed ASAP hazardous to cyclists	02/11/2022		RD: SFP Damaged Bollard	Internal		Committed	50121308
Batch:	41134434 - Inspection Batch			Route: Ad hoc Route				Date: 31/10/2022
42110049	Cycle defender has been hit and needs fixed back down to road asap thanks	31/10/2022		RD: SFP Damaged Bollard	Internal		Committed	50121123
Batch:	41133704 - Inspection Batch			Route: South Mobile Inspection Route				Date: 24/10/2022
42109369	1no pothole	24/10/2022	Outside no290	RD: CW Pothole	Internal		Committed	50120619
Batch:	41133110 - Inspection Batch			Route: Ad hoc Route				Date: 21/10/2022
42108976	Replaced damaged bollard	21/10/2022		RD: SFP Damaged Bollard	Internal		Committed	50120413
Batch:	41132938 - Inspection Batch			Route: SE_CF2_InchEast3				Date: 19/10/2022
42108820	Patch required for broken surface 10x 1 sqm	19/10/2022	At walkway	RD: CW Cracked/Broken	Internal		Uncommitted	50075882

Effective: 25/06/2020 to 25/06/2025
 Service: Roads General
 Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
Batch:	41132938 - Inspection Batch		Route: SE_CF2_InchEast3				Date: 19/10/2022	
42108833	Cw broken. Patch required 10x 2 sqm	19/10/2022	Approximately 30m from bus turning circle as marked on map heading out of town at farmers gate	RD: CW Cracked/Broken	Internal		Uncommitted	50075877
42108836	Old pole stump on footway- remove and make safe with tar	19/10/2022	At lamppost GEN 78A	RD: Other Defect Type	Internal		Uncommitted	50108497
42108823	2 cw potholes	19/10/2022	200m south of [REDACTED] Heading into town	RD: CW Pothole	Internal		Committed	50120297
42108826	Pothole on cw	19/10/2022	Approximately 200m past pipeline technology centre	RD: CW Pothole	Internal		Uncommitted	50075889
42108834	Refresh all cw markings	19/10/2022	From gilmerton station road down to gilmerton roundabout at bypass	RD: Markings Refresh	Internal		Committed	50075928
42108844	Damaged kerb 630mm	19/10/2022	15m South of Guardwell Crescent	RD: FW Kerbs Damaged/Missing	Internal		No Action Required	
42108839	Patch required Approx 4m x 1m	19/10/2022	Outside 543	RD: CW Cracked/Broken	Internal		No Action Required	
42108829	Open joint running round most of roundabout. Approximately 25 x 1.5 sqm patch required	19/10/2022	Gilmerton roundabout see pics	RD: CW Open Joint	Internal		Uncommitted	50075905
42108846	Footway cracked - broken	19/10/2022	O/S no 401 to 403	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42108821	Cracked surface on cw. Patch required 3 x 2 sqm	19/10/2022	At the pipeline technology centre	RD: CW Cracked/Broken	Internal		Uncommitted	50075884
42108840	Patch required Approx 3m x 1m	19/10/2022	At crossing outside 523	RD: CW Cracked/Broken	Internal		No Action Required	
42108859	Cw breaking up Approx 3m x 0.5m	19/10/2022	Outside inch park surgery	RD: CW Cracked/Broken	Internal		Uncommitted	50120321
42108851	Cross track broken - cracked in same area. Patch required 6 x 3 sqm	19/10/2022	Cw across from junction with glenallan drive	RD: CW Cracked/Broken	Internal		No Action Required	
42108827	Pothole on cw 1x 1sqm patch	19/10/2022	At bus stop heading towards pipeline technology centre. Approximately 100m after gilmerton bypass junction	RD: CW Pothole	Internal		Uncommitted	50075893
42108862	1 fw pothole Ramp trip at kerb	19/10/2022	At crossing On fw Opposite speed camera 20m south of Ivanhoe crescent	RD: FW HRA Pothole	Internal		Committed	50120324
42108824	Cracked surface patch required 4 x 2 sqm	19/10/2022	Heading towards pipeline technology centre. Approximately 250m before just past 3 x manhole covers	RD: CW Cracked/Broken	Internal		Uncommitted	50075891
42108841	Missing 5x10 whin kerb Size 630mm	19/10/2022	O/S no 511	RD: FW Kerbs Damaged/Missing	Internal		Uncommitted	50108456
42108842	Old pole stump on footway- please remove and make safe with tar	19/10/2022	Near junction with The Spinney	RD: Other Defect Type	Internal		Uncommitted	50108492
42108831	Cracked surface approximately 20x 2 sqm	19/10/2022	After crossing bypass at mini roundabout	RD: CW Cracked/Broken	Internal		Uncommitted	50075907

Effective: 25/06/2020 to 25/06/2025
 Service: Roads General
 Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset			Area: South East Locality	
Batch:	41132938 - Inspection Batch		Route: SE_CF2_InchEast3				Date: 19/10/2022	
42108828	2 cw potholes	19/10/2022	Just before bus stop As come of roundabout at bypass Heading towards [REDACTED]	RD: CW Pothole	Internal		Committed	50120299
42108847	Footway cracked- broken	19/10/2022	From [REDACTED]'s [REDACTED] Road to Aldi	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50108506
42108822	Cw cracking 2 x 1 sqm patch required	19/10/2022	Adjacent to the pipeline technology centre	RD: CW Cracked/Broken	Internal		Uncommitted	50075885
42108850	Broken footway surface patch required 6 x 1 sqm	19/10/2022	At crossing near glenallan drive	RD: FW HRA Cracked/Broken	Internal		No Action Required	
Batch:	41132688 - Inspection Batch		Route: Ad hoc Route				Date: 14/10/2022	
42108376	Cycle defender broken away from road and needs fixed back down ASAP thanks [REDACTED]	14/10/2022		RD: SFP Damaged Bollard	Internal		Committed	50120023
Batch:	41132685 - Inspection Batch		Route: Ad hoc Route				Date: 14/10/2022	
42108373	Replaced damaged bollard	14/10/2022		RD: SFP Damaged Bollard	Internal		Committed	50120020
Batch:	41131659 - Inspection Batch		Route: South Mobile Inspection Route				Date: 27/09/2022	
	No actionable defects found							
Batch:	41130736 - Inspection Batch		Route: Ad hoc Route				Date: 07/09/2022	
42106886	Replaced missing bollard	07/09/2022		RD: SFP Damaged Bollard	Internal		Committed	50118442
Batch:	41130021 - Inspection Batch		Route: South Mobile Inspection Route				Date: 23/08/2022	
42106286	1no pothole	23/08/2022	30m south of [REDACTED]	RD: CW Pothole	Internal		Committed	50117773
Batch:	41128974 - Inspection Batch		Route: Ad hoc Route				Date: 10/08/2022	
42105810	Replaced missing bollard	10/08/2022		RD: SFP Damaged Bollard	Internal		Committed	50117336
Batch:	41128427 - Inspection Batch		Route: Ad hoc Route				Date: 28/07/2022	
42105240	Replaced damaged bollard	28/07/2022		RD: SFP Damaged Bollard	Internal		Committed	50116930
Batch:	41128291 - Inspection Batch		Route: South Mobile Inspection Route				Date: 26/07/2022	
	No actionable defects found							
Batch:	41127835 - Inspection Batch		Route: Ad hoc Route				Date: 19/07/2022	
42104928	Replaced missing bollard	19/07/2022		RD: SFP Damaged Bollard	Internal		Committed	50116655
Batch:	41126686 - Inspection Batch		Route: Ad hoc Route				Date: 01/07/2022	
42104198	Cycle defender to be moved on to give access to buses southbound yellow markings on the road to where it is to be moved to give bosses more access the bus stop	01/07/2022		RD: SFP Damaged Bollard	Internal		Committed	50116014

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
Batch:	41126685 - Inspection Batch			Route: Ad hoc Route				Date: 01/07/2022
42104197	Cycle defender to be moved to let more access for buses coming into Bus stop heading southbound both cycle defenders to be moved more space for buses entering bus stop	01/07/2022		RD: SFP Damaged Bollard	Internal		Committed	50116013
Batch:	41126416 - Inspection Batch			Route: Ad hoc Route				Date: 27/06/2022
42103881	Replaced missing bollard	27/06/2022		RD: SFP Damaged Bollard	Internal		Committed	50115748
Batch:	41125982 - Inspection Batch No actionable defects found			Route: SE_CW1_South1				Date: 16/06/2022
Batch:	41124122 - Inspection Batch No actionable defects found			Route: SE_CW1_South1				Date: 13/05/2022
Batch:	41122484 - Inspection Batch			Route: Ad hoc Route				Date: 19/04/2022
42099631	Replaced missing bollard	19/04/2022		RD: SFP Damaged Bollard	Internal		Committed	50112074
Batch:	41122317 - Inspection Batch No actionable defects found			Route: SE_CW1_South1				Date: 12/04/2022
Batch:	41121815 - Inspection Batch			Route: Ad hoc Route				Date: 05/04/2022
42098855	Broken catv cover Repeatedly declined by utility companies please infil with sand bags and top with cold tar	05/04/2022	Gilmerton rd at mount [REDACTED] rd	RD: FW Cover Make Safe	Internal		Committed	50111304
Batch:	41121728 - Inspection Batch			Route: Ad hoc Route				Date: 05/04/2022
42098782	Replaced missing bollard	05/04/2022		RD: SFP Damaged Bollard	Internal		Committed	50111240
Batch:	41121632 - Inspection Batch			Route: Ad hoc Route				Date: 04/04/2022
42098632	Broken catv cover on fw risk to public Continually rejected for repair As no one is accepting this we will have to infill with concrete / cold tar after this attempt	04/04/2022	Gilmerton road at mount [REDACTED] road 282b	RU: Utility Apparatus	Internal		Uncommitted	50111088
Batch:	41121498 - Inspection Batch			Route: Ad hoc Route				Date: 31/03/2022
42098411	Broken catv cover on fw First raised December 2021 Again in February 2021	31/03/2022	Gilmerton road os 282a	RU: Utility Apparatus	Internal		Uncommitted	50110913
Batch:	41120713 - Inspection Batch			Route: Ad hoc Route				Date: 28/03/2022
42097903		28/03/2022		RD: SFP Damaged Bollard	Internal		Committed	50110475
Batch:	41119246 - Inspection Batch No actionable defects found			Route: SE_CW1_South1				Date: 14/03/2022

Effective: 25/06/2020 to 25/06/2025
 Service: Roads General
 Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
Batch:	41118723 - Inspection Batch		Route: SE_CF1_GilmertonRd1				Date: 08/03/2022	
42095386	Refresh all cw markings	08/03/2022	From gilmerton station road down to gilmerton roundabout at bypass	RD: Markings Refresh	Internal		No Action Required	
42095408	Pothole as marked	08/03/2022	20m North of bus stop heading to town- see pin on map	RD: CW Pothole	Internal		Committed	50108474
42095367	Footway potholes x 2 as marked	08/03/2022	At first bus stop past Glennallan Drive- Heading out of town	RD: FW HRA Pothole	Internal		Committed	50108444
42095443	Footway toby high causing trip- possibly Scottish water	08/03/2022	O/S no 544	RU: Utility Apparatus	Internal		Uncommitted	50108489
42095398	Cracked surface approximately 20x 2 sqm	08/03/2022	After crossing bypass at mini roundabout	RD: CW Cracked/Broken	Internal		No Action Required	
42095394	Potholes x 2	08/03/2022	O/S entrance to walkway- cycleway	RD: CW Pothole	Internal		Committed	50108468
42095365	Footway pothole as marked	08/03/2022	At bus stop just past Glennallan Drive - heading out of town	RD: FW HRA Pothole	Internal		Committed	50108438
42095455	Old pole stump on footway infill with tar to make safe	08/03/2022	At lamppost GEN 78A	RD: FW HRA Pothole	Internal		Committed	50108496
42095411	Pothole on cw 1x 1sqm patch	08/03/2022	At bus stop heading towards pipeline technology centre. Approximately 100m after gilmerton bypass junction	RD: CW Pothole	Internal		No Action Required	
42095451	Old pole stump on footway- please remove and make safe with tar	08/03/2022	Near junction with The Spinney	RD: Other Defect Type	Internal		No Action Required	
42095393	Cw broken. Patch required 10x 2 sqm	08/03/2022	Approximately 30m from bus turning circle as marked on map heading out of town at farmers gate	RD: CW Cracked/Broken	Internal		No Action Required	
42095470	Broken footway surface patch required 6 x 1 sqm	08/03/2022	At crossing near glenallan drive	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42095467	Footway pothole- depression make safe	08/03/2022	Near lamppost 58	RD: FW HRA Pothole	Internal		Committed	50108508
42095375	Footway pothole	08/03/2022	O/S no 497 at kerb edge	RD: FW HRA Pothole	Internal		Committed	50108451
42095459	Damaged kerb	08/03/2022	15m South of Guardwell Crescent	RD: FW Kerbs Damaged/Missing	Internal		No Action Required	
42095399	Open joint running round most of roundabout. Approximately 25 x 1.5 sqm patch required	08/03/2022	Gilmerton roundabout see pics	RD: CW Open Joint	Internal		No Action Required	
42095461	Trips on footway make safe with tar	08/03/2022	25m North of Aldi exit - 10m North of bus stop	RD: FW HRA Pothole	Internal		Committed	50108502
42095450	Old pole stump - ramp off with tar to make safe	08/03/2022	Near junction with The Spinney on footway	RD: FW HRA Pothole	Internal		Committed	50108491
42095416	Cracked surface patch required 4 x 2 sqm	08/03/2022	Heading towards pipeline technology centre. Approximately 250m before just past 3 x manhole covers	RD: CW Cracked/Broken	Internal		No Action Required	
42095457	Footway potholes x 7 as marked	08/03/2022	Opp no 435- 437	RD: FW HRA Pothole	Internal		Committed	50108498
42095382	Footway pothole at kerb edge	08/03/2022	O/S no 511A	RD: FW HRA Pothole	Internal		Committed	50108458
42095380	Marking kerb	08/03/2022	O/S no 511	RD: FW Kerbs Damaged/Missing	Internal		No Action Required	
42095373	Footway cracked - broken	08/03/2022	O/S no 401 to 403	RD: FW HRA Cracked/Broken	Internal		No Action Required	

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
Batch:	41118723 - Inspection Batch		Route: SE_CF1_GilmertonRd1				Date: 08/03/2022	
42095420	Cracked surface on cw. Patch required 3 x 2 sqm	08/03/2022	At the pipeline technology centre	RD: CW Cracked/Broken	Internal		No Action Required	
42095419	Cw cracking 2 x 1 sqm patch required	08/03/2022	Adjacent to the pipeline technology centre	RD: CW Cracked/Broken	Internal		No Action Required	
42095460	Telecom footway manhole cover wearing away	08/03/2022	On footway with Gardwell Crescent	RU: Utility Apparatus	Internal		Uncommitted	50108501
42095392	Potholes x 2	08/03/2022	Approx 30m South of turning circle-O/S farmers gate heading out of town	RD: CW Pothole	Internal		Committed	50108467
42095417	Pothole on cw	08/03/2022	Approximately 200m past pipeline technology centre	RD: CW Pothole	Internal		No Action Required	
42095476	Trip at crossing make safe with tar	08/03/2022	25m South of Double Hedges Road	RD: FW HRA Pothole	Internal		Committed	50108515
42095471	Cross track broken - cracked in same area. Patch required 6 x 3 sqm	08/03/2022	Cw across from junction with glenallan drive	RD: CW Cracked/Broken	Internal		No Action Required	
42095383	Footway- carriageway pothole at kerb edge	08/03/2022	O/S no 527	RD: FW HRA Pothole	Internal		Committed	50108459
42095448	Refresh all faded markings	08/03/2022	From gilmerton station road to number 495	RD: Markings Refresh	Internal		No Action Required	
42095458	Trip at footway manhole surround make safe with tar	08/03/2022	Near lamppost GE 65	RD: FW HRA Pothole	Internal		Committed	50108499
42095456	Old pole stump on footway- remove and make safe with tar	08/03/2022	At lamppost GEN 78A	RD: Other Defect Type	Internal		No Action Required	
42095462	Footway pothole	08/03/2022	On Bridge over burn See pin on map	RD: FW HRA Pothole	Internal		Committed	50108503
42095404	Pothole	08/03/2022	Approx 25m North of roundabout- heading to town	RD: CW Pothole	Internal		Committed	50108473
42095355	Footway pothole as marked	08/03/2022	At bus stop just past Glennallan Drive - heading out of town	RD: FW HRA Pothole	Internal		No Action Required	
42095395	Patch required for broken surface 10x 1 sqm	08/03/2022	At walkway see pics	RD: CW Cracked/Broken	Internal		No Action Required	
42095465	Footway cracked- broken	08/03/2022	From [REDACTED]'s [REDACTED] Road to Aldi	RD: FW HRA Cracked/Broken	Internal		No Action Required	
Batch:	41115502 - Inspection Batch		Route: SE_CW1_South1				Date: 14/02/2022	
42092713	x1 pothole, make safe.	14/02/2022	Outside 190.	RD: CW Pothole	Internal		Committed	50106164
Batch:	41114820 - Inspection Batch		Route: Ad hoc Route				Date: 07/02/2022	
42092180	Replaced missing bollard	07/02/2022		RD: SFP Damaged Bollard	Internal		Committed	50105558
Batch:	41114687 - Inspection Batch		Route: Ad hoc Route				Date: 04/02/2022	
42091889	Broken catv cover Originally raised 16/12/21	04/02/2022	Gilmerton rd 282a	RU: Utility Apparatus	Internal		Uncommitted	50105301
Batch:	41112943 - Inspection Batch		Route: SE_CW1_South1				Date: 13/01/2022	
	No actionable defects found							
Batch:	41110482 - Inspection Batch		Route: Ad hoc Route				Date: 14/12/2021	
42087032	Collapsed catv cover on fw	14/12/2021	Gilmerton rd at 282a	RU: Utility Apparatus	Internal		Uncommitted	50100208

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
Batch:	41110461 - Inspection Batch			Route: Ad hoc Route				Date: 14/12/2021
42086969	Cw pothole marked on site	14/12/2021	Gilmerton rd os 290 city bound	RD: CW Pothole	Internal		Committed	50100161
Batch:	41110077 - Inspection Batch			Route: SE_CW1_South1				Date: 09/12/2021
42086527	1no pothole	09/12/2021	Outside no207	RD: CW Pothole	Internal		Committed	50099751
Batch:	41108837 - Inspection Batch			Route: Ad hoc Route				Date: 01/12/2021
42085768	Replaced missing bollards	01/12/2021		RD: SFP Damaged Bollard	Internal		Committed	50099037
Batch:	41108258 - Inspection Batch			Route: Ad hoc Route				Date: 25/11/2021
42085185	Replaced missing bollard	25/11/2021		RD: SFP Damaged Bollard	Internal		Committed	50098470
Batch:	41106998 - Inspection Batch			Route: SE_CW1_South1				Date: 09/11/2021
	No actionable defects found							
Batch:	41106629 - Inspection Batch			Route: Ad hoc Route				Date: 04/11/2021
42082441	Cw pothole marked on site	04/11/2021	Gilmerton road from bypass off ramp city bound per map	RD: CW Pothole	Internal		Committed	50095952
Batch:	41105361 - Inspection Batch			Route: Ad hoc Route				Date: 26/10/2021
42081162	Replace missing bollards	26/10/2021		RD: SFP Damaged Bollard	Internal		Committed	50094777
Batch:	41105360 - Inspection Batch			Route: Ad hoc Route				Date: 26/10/2021
42081160	Replace missing bollards	26/10/2021		RD: SFP Damaged Bollard	Internal		Committed	50094773
Batch:	41103730 - Inspection Batch			Route: Ad hoc Route				Date: 12/10/2021
42079998	Replaced missing bollard	12/10/2021		RD: SFP Damaged Bollard	Internal		Committed	50093524
Batch:	41103335 - Inspection Batch			Route: SE_CW1_South1				Date: 08/10/2021
	No actionable defects found							
Batch:	41101504 - Inspection Batch			Route: Ad hoc Route				Date: 24/09/2021
42079104	Replaced missing bollard	24/09/2021		RD: SFP Damaged Bollard	Internal		Committed	50092531
Batch:	41101220 - Inspection Batch			Route: Ad hoc Route				Date: 22/09/2021
42078975	Replaced missing bollard	22/09/2021		RD: SFP Damaged Bollard	Internal		Committed	50092366
Batch:	41100484 - Inspection Batch			Route: Ad hoc Route				Date: 17/09/2021
42078572	Replaced missing bollards	17/09/2021		RD: SFP Damaged Bollard	Internal		Committed	50091990
Batch:	41099761 - Inspection Batch			Route: SE_CW1_South1				Date: 08/09/2021
	No actionable defects found							
Batch:	41099135 - Inspection Batch			Route: Ad hoc Route				Date: 30/08/2021
42076868	Replaced missing bollards	30/08/2021		RD: SFP Damaged Bollard	Internal		Committed	50090662
Batch:	41099132 - Inspection Batch			Route: Ad hoc Route				Date: 30/08/2021
42076865	Replaced missing bollard	30/08/2021		RD: SFP Damaged Bollard	Internal		Committed	50090659
Batch:	41099131 - Inspection Batch			Route: Ad hoc Route				Date: 30/08/2021
42076864	Replaced missing bollard	30/08/2021		RD: SFP Damaged Bollard	Internal		Committed	50090658

Effective: 25/06/2020 to 25/06/2025
 Service: Roads General
 Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset			Area: South East Locality	
Batch:	41099130 - Inspection Batch			Route: Ad hoc Route				Date: 30/08/2021
42076863	Replaced missing bollard	30/08/2021		RD: SFP Damaged Bollard	Internal		Committed	50090657
Batch:	41097557 - Inspection Batch			Route: SE_CW1_South1				Date: 04/08/2021
	No actionable defects found							
Batch:	41097374 - Inspection Batch			Route: Ad hoc Route				Date: 02/08/2021
42074853	Replaced missing bollard	02/08/2021		RD: SFP Damaged Bollard	Internal		Committed	50088698
Batch:	41096354 - Inspection Batch			Route: Ad hoc Route				Date: 16/07/2021
42073648	Replaced damaged cycle defender that's broken away from the Road	16/07/2021		RD: SFP Damaged Bollard	Internal		Committed	50087559
Batch:	41096353 - Inspection Batch			Route: Ad hoc Route				Date: 16/07/2021
42073647	Replaced missing bollard	16/07/2021		RD: SFP Damaged Bollard	Internal		Committed	50087558
Batch:	41096352 - Inspection Batch			Route: Ad hoc Route				Date: 16/07/2021
42073646	Replaced missing red reflective disc form bollard	16/07/2021		RD: SFP Damaged Signage	Internal		Committed	50087557
Batch:	41096351 - Inspection Batch			Route: Ad hoc Route				Date: 16/07/2021
42073645	Replaced missing red reflective disc form bollard	16/07/2021		RD: SFP Damaged Signage	Internal		Committed	50087556
Batch:	41095528 - Inspection Batch			Route: SE_CW1_South1				Date: 06/07/2021
	No actionable defects found							
Batch:	41094433 - Inspection Batch			Route: Ad hoc Route				Date: 16/06/2021
42071199	Replaced damaged bollard	16/06/2021		RD: SFP Damaged Bollard	Internal		Committed	50085328
Batch:	41093613 - Inspection Batch			Route: SE_CW1_South1				Date: 02/06/2021
	No actionable defects found							
Batch:	41092844 - Inspection Batch			Route: Ad hoc Route				Date: 24/05/2021
42069472	Missing bollard	24/05/2021		RD: SFP Damaged Bollard	Internal		Committed	50083631
Batch:	41091507 - Inspection Batch			Route: SE_CW1_South1				Date: 29/04/2021
	No actionable defects found							
Batch:	41089352 - Inspection Batch			Route: SE_CW1_South1				Date: 31/03/2021
	No actionable defects found							
Batch:	41086159 - Inspection Batch			Route: SE_CW1_South1				Date: 03/03/2021
42063230	1no CW depression	03/03/2021	North roundabout near city bypass, section towards road leading to numbers 612-618	RD: CW Rutting	Internal		Committed	50077215
Batch:	41084661 - Inspection Batch			Route: Ad hoc Route				Date: 23/02/2021
42062204	4 x potholes in same area. Patch required 6 x 3 sqm	23/02/2021	Cw across from junction with glenallan drive	RD: CW Pothole	Internal		No Action Required	

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
Batch:	41084660 - Inspection Batch		Route: Ad hoc Route				Date: 23/02/2021	
42062203	Broken footway surface patch required 6 x 1 sqm	23/02/2021	At crossing near glenallan drive	RD: FW HRA Cracked/Broken	Internal		No Action Required	
Batch:	41084651 - Inspection Batch		Route: Ad hoc Route				Date: 23/02/2021	
42062201	Pothole on cw	23/02/2021	Near lampost GEN22	RD: CW Pothole	Internal		Committed	50076085
Batch:	41084650 - Inspection Batch		Route: Ad hoc Route				Date: 23/02/2021	
42062199	Fire hydrant cover is rattling, needs replaced	23/02/2021	As marked on map . Near lampost GEN22	RU: Utility Apparatus	Internal		Uncommitted	50076084
Batch:	41084589 - Inspection Batch		Route: Ad hoc Route				Date: 23/02/2021	
42062155	2 x potholes	23/02/2021	At junction with pipeline technology centre	RD: CW Pothole	Internal		Committed	50076031
Batch:	41084581 - Inspection Batch		Route: Ad hoc Route				Date: 23/02/2021	
42062149	Pothole at cw edge	23/02/2021	At junction with pipeline technology centre heading towards gilmerton station road	RD: CW Pothole	Internal		Committed	50076025
Batch:	41084572 - Inspection Batch		Route: Ad hoc Route				Date: 23/02/2021	
42062144	Gully full of Water, needs cleared	23/02/2021	At roundabout (see pics)	Gully: Blocked - HP Jet Req'd	Internal		Committed	50076017
Batch:	41084569 - Inspection Batch		Route: Ad hoc Route				Date: 23/02/2021	
42062142	Gully full of water and mud	23/02/2021	Between the 2 roundabouts at bypass	Gully: Blocked - Hand Clear	Internal		Committed	50076014
Batch:	41084566 - Inspection Batch		Route: Ad hoc Route				Date: 23/02/2021	
42062141	Gully full of Water, needs cleared	23/02/2021	At roundabout near bypass	Gully: Blocked - HP Jet Req'd	Internal		Committed	50076013
Batch:	41084565 - Inspection Batch		Route: Ad hoc Route				Date: 23/02/2021	
42062140	Gully full of leaves	23/02/2021	Near roundabout heading towards bypass	Gully: Blocked - Hand Clear	Internal		Committed	50076011
Batch:	41084562 - Inspection Batch		Route: Ad hoc Route				Date: 23/02/2021	
42062138	Gully completely blocked with mud	23/02/2021	Approximately 150m past pipeline technology centre heading towards bypass	Gully: Blocked - Hand Clear	Internal		Committed	50076007
Batch:	41084558 - Inspection Batch		Route: Ad hoc Route				Date: 23/02/2021	
42062134	Gully completely blocked with mud	23/02/2021	Approximately 100m past pipeline technology centre heading towards bypass	Gully: Blocked - Hand Clear	Internal		Committed	50076003
Batch:	41084549 - Inspection Batch		Route: Ad hoc Route				Date: 23/02/2021	
42062125	Gully completely blocked. Full of mud	23/02/2021	Approximately 50m past pipeline technology centre heading towards bypass	Gully: Blocked - Hand Clear	Internal		Committed	50075994
Batch:	41084547 - Inspection Batch		Route: Ad hoc Route				Date: 23/02/2021	
42062123	Gully blocked with mud	23/02/2021	Across from pipeline technology centre (see pics)	Gully: Blocked - Hand Clear	Internal		Committed	50075989

Effective: 25/06/2020 to 25/06/2025
 Service: Roads General
 Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
Batch:	41084416 - Inspection Batch		Route: Ad hoc Route				Date: 22/02/2021	
42062020	Cw broken. Patch required 10x 2 sqm	22/02/2021	Approximately 50m from bus turning circle as marked on map	RD: CW Cracked/Broken	Internal		No Action Required	
Batch:	41084412 - Inspection Batch		Route: SE_CF1_GilmertonRd1				Date: 22/02/2021	
42062032	Pothole on cw	22/02/2021	Approximately 200m past pipeline technology centre	RD: CW Pothole	Internal		No Action Required	
42062098	Refresh all cw markings	22/02/2021	From gilmerton station road down to gilmerton roundabout at bypass	RD: Markings Refresh	Internal		No Action Required	
42062017	3 x potholes	22/02/2021	Approximately 50m past bus turning circle at gate to field	RD: CW Pothole	Internal		Committed	50075873
42062040	Pothole on cw	22/02/2021	Approximately 100m from gilmerton junction roundabout	RD: CW Pothole	Internal		Committed	50075895
42062060	Cracked surface approximately 20x 2 sqm	22/02/2021	After crossing bypass at mini roundabout	RD: CW Cracked/Broken	Internal		No Action Required	
42062023	Cracked surface on cw. Patch required 3 x 2 sqm	22/02/2021	At the pipeline technology centre	RD: CW Cracked/Broken	Internal		No Action Required	
42062093		22/02/2021	At liberton road	RD: Capital Assessment Requir	Internal		Uncommitted	3000545
42062056	Open joint running round most of roundabout. Approximately 25 x 1.5 sqm patch required	22/02/2021	Gilmerton roundabout see pics	RD: CW Open Joint	Internal		No Action Required	
42062075	Fw is due to have surface treatment . Due to this 1 x raised utility cover on fw has been left raised and not made safe. Trip hazard. Please either cover or put some temp material round utility cover removing trip hazard	22/02/2021	At lamppost GEN 83	RD: FW Cover Make Safe	Internal		Committed	50075914
42062022	Patch required for broken surface 10x 1 sqm	22/02/2021	At walkway see pics	RD: CW Cracked/Broken	Internal		No Action Required	
42062095	Road: Defective / Damaged (Enquiry 619963)	22/02/2021	Gilmerton Road at Ellens Road On citybound side of road - sunken drain opening, outside parked cars and directly in the line of wheel direction when turning left out of S Road.	Gully: Brander Damaged	Internal		Uncommitted	50003902
42062024	Cw cracking 2 x 1 sqm patch required	22/02/2021	Adjacent to the pipeline technology centre	RD: CW Cracked/Broken	Internal		No Action Required	
42062038	Pothole on cw 1x 1sqm patch	22/02/2021	At bus stop heading towards pipeline technology centre. Approximately 100m after gilmerton bypass junction	RD: CW Pothole	Internal		No Action Required	
42062099	Refresh all faded markings	22/02/2021	From gilmerton station road to number 495	RD: Markings Refresh	Internal		No Action Required	
42062054	Cracked broken surface	22/02/2021	On gilmerton road roundabout	RD: CW Cracked/Broken	Internal		Committed	50075903
42062021	Pothole on cw	22/02/2021	Adjacent to walkway see pics	RD: CW Pothole	Internal		Committed	50075879

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road, Gilmerton Station	Feature Type: Road Asset			Area: South East Locality	
Batch: 41084412 - Inspection Batch			Route: SE_CF1_GilmertonRd1				Date: 22/02/2021	
42062096	Bus stop marking-Markings: Defective - Not sure who is responsible to maintaining the road markings and signage for bus stops in Edinburgh so forgive the multiple recipients here. The bust stop on Gilmerton Road (Erskine Home 209370) is missing the sign and the yellow markings on the road are badly degraded. Bus drivers have missed it a couple of times now. Would be great if you could spruce it up. (Enquiry 682777)	22/02/2021	The bust stop on Gilmerton Road (Erskine Home 209370) os 479 Gilmerton Road	RD: Markings Refresh	Internal		Committed	50012997
42062083	Hydrant cover surround on centre of cw, edges prominent	22/02/2021	Between lamppost GEN 22 and GEN 23	RD: CW Pothole	Internal		Committed	50075916
42062036	Cracked surface patch required 4 x 2 sqm	22/02/2021	Heading towards pipeline technology centre. Approximately 250m before just past 3 x manhole covers	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41078402 - Inspection Batch			Route: SE_CW1_South1				Date: 26/01/2021	
42059492	1no pothole	26/01/2021	On the pedestrian crossing outside no523	RD: CW Pothole	Internal		Committed	50072875
Batch: 41073317 - Inspection Batch			Route: Ad hoc Route				Date: 08/01/2021	
42058477	Cw potholes please make safe	08/01/2021	Gilmerton road roundabout at bypass off ramp	RD: CW Pothole	Internal		Committed	50071572
Batch: 41071769 - Inspection Batch			Route: Ad hoc Route				Date: 22/12/2020	
42058055	Defective manhole	22/12/2020	Gilmerton road at drum street / Gilmerton station road	RU: Utility Apparatus	Internal		Uncommitted	50070811
Batch: 41071539 - Inspection Batch			Route: SE_CW1_South1				Date: 17/12/2020	
42057711	1 CW pothole at fire hydrant.	17/12/2020	In between lamppost GEN22 & 23	RD: CW Pothole	Internal		Committed	50070421
Batch: 41069154 - Inspection Batch			Route: SE_CW1_South1				Date: 13/11/2020	
No actionable defects found								
Batch: 41066079 - Inspection Batch			Route: SE_CW1_South1				Date: 07/10/2020	
No actionable defects found								
Batch: 41062495 - Inspection Batch			Route: SE_CW1_South1				Date: 28/08/2020	
No actionable defects found								
Batch: 41060118 - Inspection Batch			Route: SE_CW1_South1				Date: 14/07/2020	
42051667	Cw potholes marked on site X5	14/07/2020	Gilmerton road os and opp 457	RD: CW Pothole	Internal		Committed	50058489
42051666	Cw potholes marked on site X7	14/07/2020	Gilmerton road opp 368/364	RD: CW Pothole	Internal		Committed	50058488
42051671	Cw potholes marked on site x 4	14/07/2020	Gilmerton road at mount [REDACTED], Kingston Xroads	RD: CW Pothole	Internal		Committed	50058486
42051665	Cw pothole marked on site	14/07/2020	Gilmerton road opp 284	RD: CW Pothole	Internal		Committed	50058487
42051670	Cw pothole marked on site	14/07/2020	Gilmerton road opp 477	RD: CW Pothole	Internal		Committed	50058492

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	5.00	Asset - Locn.:	Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
Batch:	41060118 - Inspection Batch			Route: SE_CW1_South1			Date: 14/07/2020	
42051669	Cw potholes marked on site x2	14/07/2020	Gilmerton road os 471 opp Morrison's	RD: CW Pothole	Internal		Committed	50058491
42051668	Cw potholes marked on site x2	14/07/2020	Gilmerton road os 461	RD: CW Pothole	Internal		Committed	50058490
Asset:	6.00	Asset - Locn.:	Ward 15 - Liberton Road to Glenallan Drive		Feature Type: Road Asset		Area: South East Locality	
Batch:	41231534 - Inspection Batch			Route: SfP_SouthEast			Date: 23/06/2025	
42185954	1no missing bollard	23/06/2025	At lp13	RD: SFP Damaged Bollard	Internal		Committed	50181791
Batch:	41230286 - Inspection Batch			Route: South Mobile Inspection Route			Date: 06/06/2025	
	No actionable defects found							
Batch:	41228245 - Inspection Batch			Route: SfP_SouthEast			Date: 14/05/2025	
	No actionable defects found							
Batch:	41227766 - Inspection Batch			Route: South Mobile Inspection Route			Date: 07/05/2025	
	No actionable defects found							
Batch:	41226179 - Inspection Batch			Route: SfP_SouthEast			Date: 16/04/2025	
	No actionable defects found							
Batch:	41225606 - Inspection Batch			Route: South Mobile Inspection Route			Date: 09/04/2025	
	No actionable defects found							
Batch:	41224544 - Inspection Batch			Route: Mobile Inspection Strategic			Date: 30/03/2025	
	No actionable defects found							
Batch:	41224026 - Inspection Batch			Route: SfP_SouthEast			Date: 24/03/2025	
	No actionable defects found							
Batch:	41223880 - Inspection Batch			Route: Mobile Inspection Strategic			Date: 24/03/2025	
	No actionable defects found							
Batch:	41222813 - Inspection Batch			Route: Mobile Inspection Strategic			Date: 15/03/2025	
	No actionable defects found							
Batch:	41222408 - Inspection Batch			Route: South Mobile Inspection Route			Date: 12/03/2025	
	No actionable defects found							
Batch:	41221675 - Inspection Batch			Route: Mobile Inspection Strategic			Date: 06/03/2025	
	No actionable defects found							
Batch:	41221009 - Inspection Batch			Route: Mobile Inspection Strategic			Date: 28/02/2025	
	No actionable defects found							
Batch:	41220424 - Inspection Batch			Route: SfP_SouthEast			Date: 24/02/2025	
	No actionable defects found							
Batch:	41220048 - Inspection Batch			Route: Mobile Inspection Strategic			Date: 20/02/2025	
42176632	1no pothole	20/02/2025	At orrok paek	RD: CW Pothole	Internal		Committed	50175561
Batch:	41218855 - Inspection Batch			Route: Mobile Inspection Strategic			Date: 12/02/2025	
	No actionable defects found							

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	6.00	Asset - Locn.:	Ward 15 - Liberton Road to Glenallan Drive	Feature Type:	Road Asset		Area: South East Locality	
Batch:	41218721 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 12/02/2025
	No actionable defects found							
Batch:	41217117 - Inspection Batch			Route:	Mobile Inspection Strategic			Date: 31/01/2025
	No actionable defects found							
Batch:	41216801 - Inspection Batch			Route:	SfP_SouthEast			Date: 29/01/2025
	No actionable defects found							
Batch:	41215798 - Inspection Batch			Route:	Mobile Inspection Strategic			Date: 21/01/2025
	No actionable defects found							
Batch:	41214274 - Inspection Batch			Route:	SfP_SouthEast			Date: 13/01/2025
	No actionable defects found							
Batch:	41213622 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 09/01/2025
	No actionable defects found							
Batch:	41210853 - Inspection Batch			Route:	SfP_SouthEast			Date: 12/12/2024
	No actionable defects found							
Batch:	41210343 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 10/12/2024
	No actionable defects found							
Batch:	41207809 - Inspection Batch			Route:	SfP_SouthEast			Date: 15/11/2024
	No actionable defects found							
Batch:	41207394 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 12/11/2024
	No actionable defects found							
Batch:	41206120 - Inspection Batch			Route:	SE_CF2_InchEast3			Date: 02/11/2024
42168188	Railing damaged and leaning into fw making fw narrow	01/11/2024	Opposite side from nether liberton court	RD: Railing Damage/Missing/Nev	Internal		Committed	50169058
42168186		01/11/2024		RD: CW Cracked/Broken	Internal		Uncommitted	50145518
42168180	Footway cracked - broken at kerb edge	01/11/2024	At Old Mill Lane	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50108415
42168179	2no fw potholes either side of triple telecom box	01/11/2024	At bus stop opposite nether liberton court	RD: CW Pothole	Internal		Committed	50169054
42168177	Footway cracked - broken 10m x 1m	01/11/2024	10m North of lamppost GEF14	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50108428
Batch:	41204510 - Inspection Batch			Route:	SfP_SouthEast			Date: 21/10/2024
	No actionable defects found							
Batch:	41203084 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 11/10/2024
	No actionable defects found							
Batch:	41200904 - Inspection Batch			Route:	SfP_SouthEast			Date: 18/09/2024
	No actionable defects found							
Batch:	41200317 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 10/09/2024
	No actionable defects found							

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	6.00	Asset - Locn.:	Ward 15 - Liberton Road to Glenallan Drive	Feature Type:	Road Asset		Area: South East Locality	
Batch:	41198682 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 14/08/2024
	No actionable defects found							
Batch:	41198415 - Inspection Batch			Route:	SfP_SouthEast			Date: 12/08/2024
	No actionable defects found							
Batch:	41197187 - Inspection Batch			Route:	SfP_SouthEast			Date: 22/07/2024
	No actionable defects found							
Batch:	41196926 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 18/07/2024
	No actionable defects found							
Batch:	41194692 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 18/06/2024
	No actionable defects found							
Batch:	41194529 - Inspection Batch			Route:	SfP_SouthEast			Date: 17/06/2024
	No actionable defects found							
Batch:	41191870 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 14/05/2024
42157095	1 no pothole	14/05/2024	Just west of Nether Liberton Courtt	RD: CW Pothole	Internal		Committed	50160288
Batch:	41191552 - Inspection Batch			Route:	SfP_SouthEast			Date: 09/05/2024
	No actionable defects found							
Batch:	41189913 - Inspection Batch			Route:	SfP_SouthEast			Date: 18/04/2024
	No actionable defects found							
Batch:	41188759 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 08/04/2024
42153948	1 cw pothole	08/04/2024	Opposite Ip5	RD: CW Pothole	Internal		Committed	50157678
Batch:	41187142 - Inspection Batch			Route:	SfP_SouthEast			Date: 21/03/2024
	No actionable defects found							
Batch:	41185762 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 11/03/2024
	No actionable defects found							
Batch:	41183810 - Inspection Batch			Route:	SfP_SouthEast			Date: 26/02/2024
	No actionable defects found							
Batch:	41183448 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 22/02/2024
42148726	1 no pothole	22/02/2024	Near the junction with Nether Liberton Lane	RD: CW Pothole	Internal		Committed	50153703
Batch:	41179749 - Inspection Batch			Route:	SfP_SouthEast			Date: 23/01/2024
	No actionable defects found							
Batch:	41179277 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 19/01/2024
	No actionable defects found							
Batch:	41174941 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 19/12/2023
	No actionable defects found							

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	6.00	Asset - Locn.:	Ward 15 - Liberton Road to Glenallan Drive	Feature Type:	Road Asset		Area: South East Locality	
Batch:	41172716 - Inspection Batch			Route:	SfP_SouthEast			Date: 24/11/2023
	No actionable defects found							
Batch:	41172128 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 17/11/2023
	No actionable defects found							
Batch:	41171635 - Inspection Batch			Route:	SE_CF2_InchEast3			Date: 10/11/2023
42139274	Road: Defective / Damaged (Enquiry 1149486)	10/11/2023	CANCEL JUNCTION RESURFACED	RD: CW Cracked/Broken	Internal		No Action Required	
Batch:	41171254 - Inspection Batch			Route:	Ad hoc Route			Date: 06/11/2023
42138764	1no missing bollard	06/11/2023	Outside liberton primary school	RD: SFP Damaged Bollard	Internal		Committed	50145125
Batch:	41169726 - Inspection Batch			Route:	SfP_SouthEast			Date: 23/10/2023
	No actionable defects found							
Batch:	41168767 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 16/10/2023
	No actionable defects found							
Batch:	41166135 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 21/09/2023
	No actionable defects found							
Batch:	41163402 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 22/08/2023
	No actionable defects found							
Batch:	41161225 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 18/07/2023
	No actionable defects found							
Batch:	41160984 - Inspection Batch			Route:	Ad hoc Route			Date: 14/07/2023
42131966	Cycle lane reflective pole damaged, please replace	14/07/2023	After pedestrian crossing heading towards [REDACTED] Toll	RD: SFP Damaged Bollard	Internal		Committed	50139289
Batch:	41160981 - Inspection Batch			Route:	Ad hoc Route			Date: 14/07/2023
42131963	Cycle lane bollard broken, please replace	14/07/2023	Just after pedestrian crossing head to [REDACTED] Toll	RD: SFP Damaged Bollard	Internal		Committed	50139286
Batch:	41159246 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 14/06/2023
	No actionable defects found							
Batch:	41158600 - Inspection Batch			Route:	Ad hoc Route			Date: 06/06/2023
42129461	Cw x1 pothole Road: Defective / Damaged (Enquiry 1561738)	06/06/2023	Outside of Inch House, accessible from 225 Gilmerton Road	RD: CW Pothole	Internal		Committed	50137331
Batch:	41157655 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 19/05/2023
	No actionable defects found							
Batch:	41155716 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 25/04/2023
	No actionable defects found							
Batch:	41153286 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 27/03/2023
	No actionable defects found							

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	6.00	Asset - Locn.:	Ward 15 - Liberton Road to Glenallan Drive	Feature Type:	Road Asset		Area: South East Locality	
Batch:	41150357 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	24/02/2023
	No actionable defects found							
Batch:	41146300 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	24/01/2023
	No actionable defects found							
Batch:	41140038 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	19/12/2022
	No actionable defects found							
Batch:	41137122 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	29/11/2022
	No actionable defects found							
Batch:	41135791 - Inspection Batch			Route:	Ad hoc Route		Date:	16/11/2022
42111327	Defective manhole on cw Not known Photo attached	16/11/2022	Gilmerton rd before nether liberton lane	RU: Utility Apparatus	Internal		Uncommitted	50122320
Batch:	41135790 - Inspection Batch			Route:	Ad hoc Route		Date:	16/11/2022
42111326	Defective manhole Not known Photos attached	16/11/2022	Gilmerton rd from liberton rd	RU: Utility Apparatus	Internal		Uncommitted	50122319
Batch:	41133706 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	24/10/2022
	No actionable defects found							
Batch:	41132951 - Inspection Batch			Route:	SE_CF2_InchEast3		Date:	19/10/2022
42108853	Road: Defective / Damaged (Enquiry 1149486)	19/10/2022	Gilmerton road at Liberton road	RD: CW Cracked/Broken	Internal		No Action Required	
42108854	Footway cracked - broken at kerb edge	19/10/2022	At Old Mill Lane	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42108852	Footway cracked - broken 10m x 1m	19/10/2022	10m North of lamppost GEF14	RD: FW HRA Cracked/Broken	Internal		No Action Required	
Batch:	41132689 - Inspection Batch			Route:	Ad hoc Route		Date:	14/10/2022
42108377	Replaced damaged bollard	14/10/2022		RD: SFP Damaged Bollard	Internal		Committed	50120024
Batch:	41131660 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	27/09/2022
	No actionable defects found							
Batch:	41130023 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	23/08/2022
	No actionable defects found							
Batch:	41128292 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	26/07/2022
	No actionable defects found							
Batch:	41125983 - Inspection Batch			Route:	SE_CW1_South1		Date:	16/06/2022
	No actionable defects found							
Batch:	41124403 - Inspection Batch			Route:	Ad hoc Route		Date:	19/05/2022
42101581	Cw pothole at box	19/05/2022	Gilmerton rd at liberton rd	RD: CW Pothole	Internal		Committed	50113918
Batch:	41124123 - Inspection Batch			Route:	SE_CW1_South1		Date:	13/05/2022
	No actionable defects found							

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	6.00	Asset - Locn.:	Ward 15 - Liberton Road to Glenallan Drive	Feature Type:	Road Asset		Area: South East Locality	
Batch:	41122318 - Inspection Batch			Route:	SE_CW1_South1			Date: 12/04/2022
	No actionable defects found							
Batch:	41119489 - Inspection Batch			Route:	Ad hoc Route			Date: 16/03/2022
42096377	Reset dislodged bullnose kerb x7	16/03/2022	Inch park access rd from gilmerton rd Os inch community sports club	RD: FW Kerb Dislodged/Rocking	Internal		Committed	50109230
Batch:	41119486 - Inspection Batch			Route:	Ad hoc Route			Date: 16/03/2022
42096373	Cw potholes marked on site x8	16/03/2022	Inch Park access rd from gilmerton rd to old Dalkeith rd	RD: CW Pothole	Internal		Committed	50109226
Batch:	41119240 - Inspection Batch			Route:	SE_CW1_South1			Date: 14/03/2022
	No actionable defects found							
Batch:	41118717 - Inspection Batch			Route:	SE_CF1_GilmertonRd1			Date: 08/03/2022
42095323	Footway pothole as marked	08/03/2022	10m North of lamppost GEN05 heading out of town	RD: FW HRA Pothole	Internal		Committed	50108413
42095339	Footway potholes x 2 as marked	08/03/2022	At entrance to Liberton Primary - at kerb edge	RD: FW HRA Pothole	Internal		Committed	50108424
42095332	Cracked surface 3x 2 patch	08/03/2022		RD: CW Cracked/Broken	Internal		Uncommitted	50076094
42095317	Pothole	08/03/2022	At pedestrian crossing Near Liberton Road within studs as marked	RD: CW Pothole	Internal		Committed	50108409
42095315	Road: Defective / Damaged (Enquiry 1149486)	08/03/2022	Gilmerton road at Liberton road	RD: CW Cracked/Broken	Internal		No Action Required	
42095325	Footway cracked - broken at kerb edge	08/03/2022	At Old Mill Lane	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42095344	Footway cracked - broken 10m x 1m	08/03/2022	10m North of lamppost GEF14	RD: FW HRA Cracked/Broken	Internal		No Action Required	
Batch:	41115553 - Inspection Batch			Route:	SE_CW1_South1			Date: 14/02/2022
	No actionable defects found							
Batch:	41112936 - Inspection Batch			Route:	SE_CW1_South1			Date: 13/01/2022
	No actionable defects found							
Batch:	41110078 - Inspection Batch			Route:	SE_CW1_South1			Date: 09/12/2021
	No actionable defects found							
Batch:	41107004 - Inspection Batch			Route:	SE_CW1_South1			Date: 09/11/2021
	No actionable defects found							
Batch:	41103348 - Inspection Batch			Route:	SE_CW1_South1			Date: 08/10/2021
	No actionable defects found							
Batch:	41099891 - Inspection Batch			Route:	Ad hoc Route			Date: 09/09/2021
42077820	Cw potholes marked on site x4	09/09/2021	Gilmerton road , liberton primary Inch park access road by lp2 and lp3	RD: CW Pothole	Internal		Committed	50091418
Batch:	41099763 - Inspection Batch			Route:	SE_CW1_South1			Date: 08/09/2021
	No actionable defects found							
Batch:	41099568 - Inspection Batch			Route:	Ad hoc Route			Date: 03/09/2021
42077320	Cw pothole marked on site	03/09/2021	Gilmerton Rd at nether liberton	RD: CW Pothole	Internal		Committed	50091081

Effective: 25/06/2020 to 25/06/2025
 Service: Roads General
 Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	6.00	Asset - Locn.:	Ward 15 - Liberton Road to Glenallan Drive	Feature Type:	Road Asset		Area: South East Locality	
Batch:	41097558 - Inspection Batch			Route:	SE_CW1_South1			Date: 04/08/2021
	No actionable defects found							
Batch:	41096355 - Inspection Batch			Route:	Ad hoc Route			Date: 16/07/2021
42073649	Replaced missing red reflective disc form bollard	16/07/2021		RD: SFP Damaged Signage	Internal		Committed	50087560
Batch:	41095529 - Inspection Batch			Route:	SE_CW1_South1			Date: 06/07/2021
	No actionable defects found							
Batch:	41095494 - Inspection Batch			Route:	Ad hoc Route			Date: 06/07/2021
42072570	Replaced missing sign for bollard	06/07/2021		RD: SFP Damaged Signage	Internal		Committed	50086549
Batch:	41095493 - Inspection Batch			Route:	Ad hoc Route			Date: 06/07/2021
42072569	Damaged red disc form bollard	06/07/2021		RD: SFP Damaged Signage	Internal		Committed	50086548
Batch:	41094431 - Inspection Batch			Route:	Ad hoc Route			Date: 16/06/2021
42071195	Replaced damaged bollard	16/06/2021		RD: SFP Damaged Bollard	Internal		Committed	50085325
Batch:	41093614 - Inspection Batch			Route:	SE_CW1_South1			Date: 02/06/2021
	No actionable defects found							
Batch:	41091506 - Inspection Batch			Route:	SE_CW1_South1			Date: 29/04/2021
	No actionable defects found							
Batch:	41090939 - Inspection Batch			Route:	Ad hoc Route			Date: 22/04/2021
42067463	Road: Defective / Damaged (Enquiry 1149486)	22/04/2021	Gilmerton road at Liberton road	RD: CW Cracked/Broken	Internal		No Action Required	
Batch:	41089319 - Inspection Batch			Route:	SE_CW1_South1			Date: 31/03/2021
42066041	2no carriageway potholes	31/03/2021	At the junction with libertine rd on pedestrian crossing	RD: CW Pothole	Internal		Committed	50080090
Batch:	41086160 - Inspection Batch			Route:	SE_CW1_South1			Date: 03/03/2021
	No actionable defects found							
Batch:	41084668 - Inspection Batch			Route:	Ad hoc Route			Date: 23/02/2021
42062207	Cracked surface 3x 2 patch	23/02/2021	Outside 207 on cw	RD: CW Cracked/Broken	Internal		No Action Required	
Batch:	41084666 - Inspection Batch			Route:	Ad hoc Route			Date: 23/02/2021
42062205	Pothole	23/02/2021	Outside 207 on cw	RD: CW Pothole	Internal		Committed	50076091
Batch:	41084490 - Inspection Batch			Route:	SE_CF1_GilmertonRd1			Date: 23/02/2021
42062088	Pothole on cw	22/02/2021	Approximately 50m from liberton road	RD: CW Pothole	Internal		Committed	50075919
42062089	Pothole on cw	22/02/2021	Approximately 20m from liberton road	RD: CW Pothole	Internal		Committed	50075920
42062092	Road: Defective / Damaged (Enquiry 715771)	22/02/2021	The bicycle advance stop markings are no longer visible.	RD: Markings Refresh	Internal		Committed	50016514
Batch:	41078412 - Inspection Batch			Route:	SE_CW1_South1			Date: 26/01/2021
	No actionable defects found							

Effective: 25/06/2020 to 25/06/2025
 Service: Roads General
 Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	6.00	Asset - Locn.:	Ward 15 - Liberton Road to Glenallan Drive	Feature Type:	Road Asset		Area: South East Locality	
Batch:	41071540 - Inspection Batch			Route:	SE_CW1_South1			Date: 17/12/2020
	No actionable defects found							
Batch:	41070285 - Inspection Batch			Route:	Ad hoc Route			Date: 03/12/2020
42056553	Damaged barrier	03/12/2020	Gilmerton road at liberton road	RD: Railing Damage/Missing/Ne	Internal		Committed	50069000
Batch:	41070132 - Inspection Batch			Route:	Ad hoc Route			Date: 01/12/2020
42056308	Cw potholes on track	01/12/2020	Gilmerton road south bound at D islands opp double hedges road	RD: CW Pothole	Internal		Committed	50068701
Batch:	41069153 - Inspection Batch			Route:	SE_CW1_South1			Date: 13/11/2020
	No actionable defects found							
Batch:	41067798 - Inspection Batch			Route:	Ad hoc Route			Date: 23/10/2020
42054657	Patching required Bus stop 15mx1.5m Patch 2mx1m Patch 3mx6m Ped crossing needs attention but would require road closure	23/10/2020	Gilmerton road city bound from nether Liberton court to liberton road Bus stop 15m x 1.5m Patch 2mx1m Patch 3mx6m Ped crossing needs attention but would require road closure	RD: CW Subsidence/Heaving	Internal		Committed	50065472
Batch:	41066080 - Inspection Batch			Route:	SE_CW1_South1			Date: 07/10/2020
	No actionable defects found							
Batch:	41063780 - Inspection Batch			Route:	Ad hoc Route			Date: 24/09/2020
42053710	Cw potholes in channel	24/09/2020	Gilmerton road south bound opp nether Liberton court	RD: CW Pothole	Internal		Committed	50063406
Batch:	41063779 - Inspection Batch			Route:	Ad hoc Route			Date: 24/09/2020
42053709	Overbanding required	24/09/2020	Gilmerton road from double hedges road to orrok park	RD: CW Open Joint	Internal		Committed	50063405
Batch:	41063777 - Inspection Batch			Route:	Ad hoc Route			Date: 24/09/2020
42053708	Noisy manholes	24/09/2020	Gilmerton road at double hedges road	RU: Utility Apparatus	Internal		Uncommitted	50063404
Batch:	41062496 - Inspection Batch			Route:	SE_CW1_South1			Date: 28/08/2020
	No actionable defects found							
Batch:	41060110 - Inspection Batch			Route:	SE_CW1_South1			Date: 14/07/2020
42051653	Cw pothole marked on site	14/07/2020	Gilmerton road city bound passed orrok park	RD: CW Pothole	Internal		Committed	50058470
42051652	Cw pothole marked on site	14/07/2020	Gilmerton road city bound at orrok park	RD: CW Pothole	Internal		Committed	50058473
42051651	Cw pothole marked on site	14/07/2020	Gilmerton road city bound at liberton road	RD: CW Pothole	Internal		Committed	50058472
42051650	Cw pothole marked on site	14/07/2020	Gilmerton road city bound before nether Liberton court	RD: CW Pothole	Internal		Committed	50058471

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Customer Services

Enquiry No.: 34008409	Logged by: [REDACTED]	on: 17/04/2024 08:59
Service: Roads General	Subject: Street Furniture: Defective	Classification: Request for service
Desc.: Gilmerton Road, cycle lane defenders that have been knocked loose on the southbound carriageway of Gilmerton Rd at entrance to Liberton High School		
Location: Gilmerton Road	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Job Number: 50148005	Defect Number: 42168197	
Enquiry No.: 34008376	Logged by: [REDACTED]	on: 05/04/2024 10:08
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.: please insect poor condition of the pavement between Gilmerton Crossroads and Morrison's Supermarket on Gilmerton Road.		
Location: Gilmerton Road	Contact:	
Enquiry No.: 34007916	Logged by: [REDACTED]	on: 20/12/2023 10:04
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: please inspect pothole the channel on the road between the speed camera and the traffic island, and the closest property address is 543 Gilmerton Road		
Location: Gilmerton Road	Contact: [REDACTED] davidson	
Enquiry No.: 34007899	Logged by: [REDACTED]	on: 18/12/2023 11:06
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Pothole outside No.290 Gilmerton Road exposing ironwork underneath. please see pics attached.		
Location: Gilmerton Road	Contact: [REDACTED] mcintyre	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Job Number: 50148440	Defect Number: 42142335	
Enquiry No.: 34007407	Logged by: [REDACTED]	on: 23/08/2023 09:49
Service: Roads General	Subject: Street Furniture: Defective	Classification: Request for service
Desc.: Gilmerton Road please inspect for two missing bollards past the spinney heading city bound. please see pics attached.		
Location: Gilmerton Road	Contact: [REDACTED] taylor	
Enquiry No.: 34007193	Logged by: [REDACTED]	on: 07/07/2023 09:55
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Gilmerton Road please inspect road surface poor condition.		
Location: Gilmerton Road	Contact: place direct	
Enquiry No.: 34006234	Logged by: [REDACTED]	on: 04/01/2023 15:09
Service: Roads General	Subject: Drainage: General Enquiry	Classification: General Enquiry
Desc.: Request that the drains are looked at and cleared. I have reported these religiously over a long period of time.		
Location: Up and down Gilmerton road is a similar experience. Outside the GP practice at inch park the drains are visibly blocked		
Enquiry No.: 34006094	Logged by: [REDACTED]	on: 18/11/2022 09:46
Service: Roads General	Subject: Road Markings: Defective	Classification: Request for service
Desc.: test		
Location: test	Contact: [REDACTED]	
Enquiry No.: 34006093	Logged by: [REDACTED]	on: 18/11/2022 09:45
Service: Roads General	Subject: Road Markings: General Enquiry	Classification: General Enquiry
Desc.: Test		
Location: Test	Contact:	

Effective: 25/06/2020 to 25/06/2025
 Service: Roads General
 Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
 Display Action Officer: No

Customer Services

Enquiry No.: 34004821	Logged by: Nightshift Squad 1	on: 24/02/2022 05:42
Service: Roads General	Subject: Public Utilities: General	Classification: General Enquiry
Desc.: Manhole collapsed		
Location: Gilmerton Road City bound just past Aldi	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Enquiry No.: 34004349	Logged by: [REDACTED]	on: 04/11/2021 09:38
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: nasty pothole when turning left at the roundabout into gilmerton station road		
Location: left at roundabout into gilmerton station road	Contact: [REDACTED] davidson	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Job Number: 50095952	Defect Number: 42082441	
Enquiry No.: 34004085	Logged by: [REDACTED]	on: 01/09/2021 09:48
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Potholes		
Location: Gilmerton Rd/Liberton Road junction	Contact:	
Plot Number: 6.00	Feature Id - Location: Ward 15 - Liberton Road to Glenallan Drive	Feature Type: Road Asset
Job Number: 50091081	Defect Number: 42077320	
Enquiry No.: 34003818	Logged by: [REDACTED]	on: 06/07/2021 13:15
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Tree damaging wall and obscuring traffic lights		
Location: Gilmerton road	Contact:	
Plot Number: 6.00	Feature Id - Location: Ward 15 - Liberton Road to Glenallan Drive	Feature Type: Road Asset
Enquiry No.: 34003817	Logged by: [REDACTED]	on: 06/07/2021 13:09
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Tree damaging wall and obscuring traffic lights		
Location: Gilmerton road	Contact:	
Plot Number: 6.00	Feature Id - Location: Ward 15 - Liberton Road to Glenallan Drive	Feature Type: Road Asset
Enquiry No.: 34003160	Logged by: [REDACTED]	on: 22/02/2021 13:48
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Overgrown grass/muck and branches onto footway causing it to be reduced in width. At gilmerton junction branches are obstructing a sign on a lamp post (see pics)		
Location: From the pipeline technology centre down the footway to the gilmerton junction roundabout	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Enquiry No.: 34003159	Logged by: [REDACTED]	on: 22/02/2021 13:26
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Foliage/ muck growing onto footway reducing footway space		
Location: On fw between walkway down to cycle patch and pipeline technology centre	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025
 Service: Roads General
 Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
 Display Action Officer: No

Customer Services

Enquiry No.: 34003142	Logged by: [REDACTED]	on: 18/02/2021 08:02
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: carriageway defects		
Location: near the ped crossing near Liberton Primary	Contact:	
Enquiry No.: 34002961	Logged by: [REDACTED]	on: 08/01/2021 18:11
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: carriageway defect		
Location: at roundabout - east end of Gilmerton Road - just before bypass	Contact:	
Enquiry No.: 34002703	Logged by: [REDACTED]	on: 16/11/2020 19:58
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: carriageway defects - very deep dangerous pot holes		
Location: outside the entrance to Liberton golf club on Gilmerton Road	Contact:	
Enquiry No.: 34002540	Logged by: [REDACTED]	on: 13/10/2020 14:17
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: carriageway defects		
Location: between Double Hedges Road and Liberton Road	Contact:	
Plot Number: 6.00	Feature Id - Location: Ward 15 - Liberton Road to Glenallan Drive	Feature Type: Road Asset
Job Number: 50065472	Defect Number: 42054657	
Enquiry No.: 34002247	Logged by: [REDACTED]	on: 20/08/2020 15:56
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: road defect causing noise when lorries/busses drive over it - NWH Tipper lorries hitting the join between the old road surface and the new repair made to fix the sunken cable trench		
Location: ped crossing near Liberton Primary school	Contact:	
Plot Number: 6.00	Feature Id - Location: Ward 15 - Liberton Road to Glenallan Drive	Feature Type: Road Asset
Enquiry No.: 31603575	Logged by: [REDACTED]	on: 19/05/2025 08:17
Service: Roads General	Subject: Traffic Sign:Defective/Damaged	Classification: Request for service
Desc.: Road signs blocked by multiple tree branches so they are impossible to see properly. Please cut back overgrown trees.		
Location:	Contact:	
Enquiry No.: 31602939	Logged by: [REDACTED]	on: 03/07/2023 22:28
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Major traffic signs at Gilmerton Junction obscured by overgrown trees. Please make signs properly visible for road users.		
Location: Gilmerton Junction	Contact:	
Enquiry No.: 30604059	Logged by: [REDACTED]	on: 14/10/2020 10:04
Service: Roads General	Subject: Road: General Enquiry	Classification: General Enquiry
Desc.: CRM Number: 101000428466		
Customers Comment: Liberton Primary School desperately needs a path installed on the Glenallan side of the school. With the modular units in place, most family now enter the school via the Glenallan gates and the path only leads a short way from Gilmerton Road before it stops. Pedestrians must then either walk on the road (dangerous and not always possible with all the cars dropping children off) or up a very slippery muddy slope. There is no space at all for social distancing.		
Location:	Contact:	

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Customer Services

Enquiry No.: 10063550	Logged by: [REDACTED]	on: 10/12/2020 10:49
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Bottom of Gilmerton Road at the lights oppoiste Nether Liberton Lane refuse driver hit metal barrier. It has been moved next to the other one but needs to be checked for safety please.		
Location:	Contact:	
Enquiry No.: 1958536	Logged by: [REDACTED]	on: 04/06/2025 14:51
Service: Roads General	Subject: Public Utilities: General	Classification: General Enquiry
Desc.: Called this afternoon to report that there appears to be dismantled road signs from previous roadworks that keep being put into her garden. They are currently blowing about the road. Can you please come and collect these		
Location: Outside 519 Gilmerton Road	Contact:	
Enquiry No.: 1958220	Logged by: Verint CRM Connector	on: 04/06/2025 00:20
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction.		
Location:Footpath.		
Type:Foliage / Bush		
Location: Every summer thus gets reported, multiple cases open on this road.	Contact:	
Hoping this year it actually gets actioned and dealt with.		
Enquiry No.: 1889662	Logged by: [REDACTED]	on: 20/01/2025 14:26
Service: Roads General	Subject: Covers: Damaged / Defective	Classification: Request for service
Desc.: please see document attached		
Location: please see document attached	Contact:	
Enquiry No.: 1889589	Logged by: Verint CRM Connector	on: 20/01/2025 12:51
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction.		
Location:Pavement.		
Type:Foliage / Bush		
Location: Overhanging foliage that obstructs the pavement in 3 places opposite the opening to Rutherford Drive on the Gilmerton Road and down towards Glenallan Drive. I have reported this numerous times from 2023 to today 21/1/25.	Contact:	
I have attached photos before but I will do it again!		
Enquiry No.: 1866690	Logged by: Verint CRM Connector	on: 03/12/2024 13:24
Service: Roads General	Subject: Road: General Enquiry	Classification: General Enquiry
Desc.: What is the problem with the gully : flooding.		
What surface is the gully on : road.		
Are cars avoiding the flood : No.		
Is flood affecting a property : No		
Location: Drain in middle of intersection at Gilmerton Road and Mount [REDACTED] and Kingston Avenue. Been running for Days down Gilmerton Road.	Contact:	

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00

Display Action Officer: No

Customer Services

Enquiry No.: 1852561	Logged by: Verint CRM Connector	on: 01/11/2024 09:26
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction.		
Location:Cycleway.		
Type:Foliage / Bush		
Location: Bushes on the stretch of off-road shared use cycle/pedestrian path leading down from Gilmerton Road to the bypass are overgrown and blocking the path, making it difficult for two cyclists or cyclists and pedestrians to pass each other and pushing cyclists towards the road - need to be trimmed.	Contact:	
There is also (as of this w/b 28th Oct) a small dead deer, presumably hit by a car, blocking the pavement on the same stretch.		
Enquiry No.: 1846142	Logged by: Verint CRM Connector	on: 18/10/2024 09:53
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction.		
Location:Cycleway.		
Type:Foliage / Bush		
Location: There is obstructing foliage on the Dalkeith to Gilmerton Cycle path the full length of Gilmerton Road. The obstructs extends from the roundabout at the bottom of Gilmerton Road to the roundabout with Gilmerton Station Road.	Contact:	
Enquiry No.: 1845381	Logged by: Verint CRM Connector	on: 16/10/2024 15:18
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction.		
Location:Cycleway.		
Type:Foliage / Bush		
Location: Hedges over grown and obstructing access, Leaves and broken glass on cycle path from Dobbies Garden centre to Bernard Hunter Cranes	Contact:	
Enquiry No.: 1838981	Logged by: Verint CRM Connector	on: 01/10/2024 16:47
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: bottom of Gilmerton road (612-618 gilmerton road) by the cottages, end of the road is used by public and works vehicles to turn and has caused a damaging pot hole.	Contact:	
Enquiry No.: 1837566	Logged by: Verint CRM Connector	on: 28/09/2024 10:23
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Overgrown.		
Location:Footpath.		
Type:Foliage / Bush		
Location: From twitter: can you please trim the bushes and clear the shared path from Gilmerton to the Edinburgh bypass (towards Dobbie's). Getting v narrow for passing. Thanks!	Contact:	

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00

Display Action Officer: No

Customer Services

Enquiry No.: 1834812	Logged by: Verint CRM Connector	on: 21/09/2024 13:11
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction.		
Location:Pavement.		
Type:Foliage / Bush		
Location: A tree belonging to Gilmerton Primary School is obstructing most of the pavement on Gilmerton Road. Someone recently cut some of it back, but it still has branches at head height, and an averagely-tall blind person would likely walk straight into them.	Contact:	

Enquiry No.: 1825499	Logged by: Verint CRM Connector	on: 01/09/2024 16:19
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction.		
Location:Pavement.		
Type:Foliage / Bush		
Location: Tree belonging to Gilmerton Primary School is causing an obstruction of the pavement right beside the bus stop on Gilmerton Road.	Contact:	

Enquiry No.: 1821712	Logged by: Verint CRM Connector	on: 24/08/2024 16:44
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Obscuring sight line.		
Location:Footpath.		
Type:Foliage / Bush		
Location: The issue is the trees in the playground of Gilmerton Primary School the branches are over hanging onto Gilmerton Road, so low. Near the bus stop on the Gilmerton Road, Edinburgh right around the corner from Moredun Dykes Road.	Contact:	

Enquiry No.: 1820352	Logged by: Verint CRM Connector	on: 21/08/2024 21:26
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction.		
Location:Pavement.		
Type:Foliage / Bush		
Location: Overhanging trees and bushes are causing the pavement footpath hard to walk on without hitting the overhanging bushes causing obstruction (whole garden area is health hazard)	Contact:	

Enquiry No.: 1797538	Logged by: Verint CRM Connector	on: 12/07/2024 23:14
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction.		
Location:Pavement.		
Type:Foliage / Bush		
Location: 101002521023	Contact:	
I have reported this on 2 previous occasions and still nothing has been done. This problem is getting worse and people are breaking bits off the overgrown privet to get by on the pavement. The problem is on the opposite site of the road from Rutherford Drive and between Cumnor Crescent. There are a couple more problem in roughly the same area pictures attached.		

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00

Display Action Officer: No

Customer Services

Enquiry No.: 1787981

Logged by: [REDACTED]

on: 26/06/2024 08:10

Service: Roads General

Subject: Roadworks: General Enquiry

Classification: General Enquiry

Desc.: From: [REDACTED] <[REDACTED]>

Date: Tuesday, 25 June 2024 at 19:13:41

To: [REDACTED] <[REDACTED]>

Subject: Complaint regarding roadworks and traffic delays on Gilmerton Road today

Dear Customer Care Team

I am writing to let you know about the dreadful traffic delays I encountered when travelling on the Service 29 from Gilmerton this morning regarding the roadworks (possible resurfacing but not clear from the bus to see what is actually happening) towards the end of Gilmerton Road Northbound / heading towards Lady Road. There was at least a 35 mins in bus journey time delay. Whilst I appreciate that resurfacing is most definitely needed throughout Edinburgh (given the shocking state of both roads and pavements - Princes St, for example, is a disgrace in terms of the state of some of the loose and dangerous slabs to name but just one main and important street), however, to have this kind of delay happen at peak morning travel is really unacceptable. Also, I could find no reference to this information on the Council roadworks list nor does it appear that Lothian Buses were aware of it until around 8.30 am this morning when they updated their Alerts page.

I am only glad that I was not travelling to the WGH for a hospital appointment as I would have been at least 45 mins late.

I am also assuming the same will happen tomorrow morning from the looks of the road this evening?

Please can you confirm the above and what is actually happening/what plans are in place going forward for commuters to avoid this in the coming days?

I look forward to hearing back from you as soon as possible.

Many thanks.

Yours sincerely

[REDACTED]

Location: Gilmerton Road

Contact:

Enquiry No.: 1787414

Logged by: [REDACTED]

on: 25/06/2024 08:57

Service: Roads General

Subject: Traffic Mgmt: General Enquiry

Classification: Frontline Resolution (Stage1)

Desc.: Case RefGBL676P6-101002521311 [GBL676P6]

ClassificationFeedback >> Compliment, suggestion or complaint >> Make a compliment, suggestion or complaint

Associated with27, LIMEFIELD, HYVOTS BANK, EDINBURGH, EDINBURGH, EH17 8PF

TitleRoad Works

Temporary Traffic lights and Road works

Length waits during busy periods on the Gilmerton Road heading into town causing major delays

DescriptionFirst Name: Lynne

Last name: Mantle

Contact Telephone Number: 07846986290

Email: [REDACTED]

What kind of feedback would you like to provide? complaint

Account Number:

Short description of complaint: Road Works

Temporary Traffic lights and Road works

Length waits during busy periods on the Gilmerton Road heading into town causing major delays

Please provide the details of the complaint: Road works at the bottom of the Gilmerton road were it's taken 26 minutes to move 150 yards due temporary traffic lights and blob one having a common sense approach to busy morning commutes by public transport or car

Date 25/06 8.28am

How would you like us to deal with this? Man traffic lights at this time of the day . Assess if they're required at that time of the day and in general do a better job

What really frustrates me is there doesn't seem to be a need for them as they weren't there 17.30 on the 24/06 and no one is working the road .

Location: Gilmerton Road

Contact:

Effective: 25/06/2020 to 25/06/2025

Asset Number: 5.00 to 6.00

Service: Roads General

Display Action Officer: No

Site: Gilmerton Road (7901804)

Customer Services

Enquiry No.: 1775753	Logged by: Verint CRM Connector	on: 07/06/2024 20:59
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Multiple large holes in the middle of the road which I fell in and have injured my ankle Inside inch park	Contact:	
Enquiry No.: 1775200	Logged by: [REDACTED]	on: 07/06/2024 11:08
Service: Roads General	Subject: Covers: Missing	Classification: Customer Emergency
Desc.: Temp cover missing on road and needs re-covered ASAP as large hole	Contact:	
Location: opp Old Mill Lane		
Enquiry No.: 1762958	Logged by: Verint CRM Connector	on: 26/05/2024 06:47
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction. Location:Footpath. Type:Foliage / Bush	Contact:	
Location: same issue as always needs to be cutbck onshared pavement		
Enquiry No.: 1756254	Logged by: Verint CRM Connector	on: 18/05/2024 19:49
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.: Location: Pavement at bus stop, heading south towards Gilmerton Village. The tarmac pavement along the kerbside at either side of actual bus stop , is broken up. When passenger alight from bus, the broken Pavement is dangerous, on stepping down off the bus. Especially for those with mobility issues, / young children , and those with shopping bags. Please could this stretch of tarmac be repaired. Thank you. Photos attached.	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Job Number: 50160669	Defect Number: 42157576	
Enquiry No.: 1750553	Logged by: Verint CRM Connector	on: 09/05/2024 07:31
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Can you take of road signs saying the road is closed.The road was opened yesterday afternoon,but road signs still there,confusing me,and other drivers.And please tidy it up.	Contact:	

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00

Display Action Officer: No

Customer Services

Enquiry No.: 1746125

Service: Roads General

Desc.:
Location: Busted manhole
Category: Potholes

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 01/05/2024 09:02

Classification: Request for service

Contact:

Another bad area of damage created by buses. Exceeds Edinburgh Council guidelines for size.

Location:
Easting/Northing: 327392/670574 (55.922747, -3.163449)
Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 217F, Gilmerton Road, Nether Liberton, Gilmerton/Inch, City of Edinburgh, Alba / Scotland, EH16 5UN, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH16 5UB (52m away)

Enquiry No.: 1746122

Service: Roads General

Desc.:
Location: Potholes not repaired
Category: Potholes

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 01/05/2024 08:59

Classification: Request for service

Contact:

Marked for repair but still not repaired. Major damage to road. Not being adequately addressed by Edinburgh Council

Location:
Easting/Northing: 327406/670555 (55.922572, -3.163216)
Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 217F, Gilmerton Road, Nether Liberton, Gilmerton/Inch, City of Edinburgh, Alba / Scotland, EH16 5UN, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): E

Enquiry No.: 1746120

Service: Roads General

Desc.:
Location: Busted manhole cover
Category: Potholes

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 01/05/2024 08:57

Classification: Request for service

Contact:

Buses destroying road surface and manhole is loose. Needs repair sooner rather than later

Location:
Easting/Northing: 327383/670582 (55.922813, -3.163583)
Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 217F, Gilmerton Road, Nether Liberton, Gilmerton/Inch, City of Edinburgh, Alba / Scotland, EH16 5UN, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH16 5UB (46m away)

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00

Display Action Officer: No

Customer Services

Enquiry No.: 1734825	Logged by: Verint CRM Connector	on: 11/04/2024 11:02
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Outside inch View care home inside Inch Park	Contact:	
Enquiry No.: 1731716	Logged by: Verint CRM Connector	on: 06/04/2024 18:00
Service: Roads General	Subject: Road: General Enquiry	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type unlit		
Location: The bike lane markers opposite the road up to Liberton High School are dangerously either leaning into the traffic or into the bike lane.	Contact:	
Enquiry No.: 1721837	Logged by: Verint CRM Connector	on: 20/03/2024 22:12
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction.		
Location:Pavement.		
Type:Foliage / Bush		
Location: There are a few areas on the Gilmerton Road between Glenallan Drive and Walter Scot Avenue where foliage from the over the wall obstructs you walking on the Gilmerton Road. I think it really needs to be cut back from the gardens side to clear the road. There are more areas affected but pictures limited. Pictures attached.	Contact:	
Enquiry No.: 1721664	Logged by:	on: 20/03/2024 17:04
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: There are a couple of potholes just before the traffic lights, and vehicles are likely to hit both wheels at the same time.		
Location: 290, Gilmerton Road,	Contact:	
Enquiry No.: 1721405	Logged by:	on: 20/03/2024 12:14
Service: Roads General	Subject: Spill: General	Classification: Request for service
Desc.: @edinhelp Gilmerton rd from Liberton High School to at least Guardwell crescent the Rd is absolutely covered in mud from the lorry's		
Location: Gilmerton rd from Liberton High School to at least Guardwell crescen	Contact:	
Enquiry No.: 1702666	Logged by:	on: 19/02/2024 19:13
Service: Roads General	Subject: Road Safety: General Enquiry	Classification: General Enquiry
Desc.: These bollards and junction layout don't work well. Because of these bollards, one cannot turn right if they are in the cycle lane (because they extend past the junctions). In addition they led to the lost of central reservations which was previously here Meaning one cannot safely stop to turn right, unlike previously. They are located at junction at Gilmerton Road with Double Hedges Park, and junction at Gilmerton Road and Inch Park, there are more further down. This design put cyclist turning right at a vulnerable position		
Location: at junction at Gilmerton Road with Double Hedges Park, and junction at Gilmerton Road and Inch Park,	Contact:	
Enquiry No.: 1690165	Logged by: Verint CRM Connector	on: 31/01/2024 16:40
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: There has been a post/sign removed near the busstop on the side of gilmerton road into town between morisson and aldi 55.912222, -3.144393 long /lat on google maps. There is still a hole and a slightly sticking up remnant of the old pole. I tripped on it today grazing my hand, elbow and knee and I think I have cracked a rib. Could the pavement be fixed.	Contact:	

Plot Number: 5.00

Job Number: 50151901

Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station

Defect Number: 42146000

Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00

Display Action Officer: No

Customer Services

Enquiry No.: 1689533	Logged by: Verint CRM Connector	on: 31/01/2024 08:18
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction.		
Location:Cycleway.		
Type:Foliage / Bush		
Location: The cycle path on Gilmerton road between Drum street roundabout and Gilmerton junction roundabout.	Contact:	
The hedging alongside the cycle path needs trimmed as it is catching out my legs - there is no street lighting and it's dark on my commute and my legs are getting covered in scratches.		
Enquiry No.: 1683807	Logged by: Verint CRM Connector	on: 23/01/2024 14:00
Service: Roads General	Subject: Traffic Sign:Defective/Damaged	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type unlit		
Location: Ok main road the 60mph speed limit sign is missing. Many vehicles don't know what the speed limit is on this road. It's the sign on the road heading into Edinburgh.	Contact:	
Enquiry No.: 1661501	Logged by: [REDACTED]	on: 14/12/2023 10:02
Service: Roads General	Subject: Street Furniture: Defective	Classification: Request for service
Desc.: Cylce Lane Bolards have been Knocked over and Causing people to walk on road.		
Location: Outside the Southern Medical Group	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Job Number: 50148005	Defect Number: 42168197	
Enquiry No.: 1655277	Logged by: Verint CRM Connector	on: 04/12/2023 13:14
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Overgrown.		
Location:Footpath.		
Type:Foliage / Bush		
Location: twigs causing hazard to cyclists	Contact:	
Enquiry No.: 1654635	Logged by: Verint CRM Connector	on: 03/12/2023 10:50
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Overgrown.		
Location:Park.		
Type:Foliage / Bush		
Location: Our property lies on the boundary with Inch Park.	Contact:	
We appreciated the Council taking action, some 3 years ago, to remove some of the large, lower branches of the chestnut tree near the Gilmerton Road entrance. One remaining large branch now significantly overhangs our boundary wall to the south of our property and, should it break in winter storms, would cause extensive damage to our greenhouse which lies underneath/adjacent. Please would you arrange to have this limb removed?		

Effective: 25/06/2020 to 25/06/2025

Asset Number: 5.00 to 6.00

Service: Roads General

Display Action Officer: No

Site: Gilmerton Road (7901804)

Customer Services

Enquiry No.: 1654560	Logged by: Verint CRM Connector	on: 02/12/2023 19:28
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction.		
Location:Pavement.		
Type:Foliage / Bush		
Location: Branches protruding into the pavement area along the length of dentist frontage.	Contact:	
Really dangerous for pedestrians, children and those in mobility scooters. Thank you		
Enquiry No.: 1647281	Logged by: [REDACTED]	on: 20/11/2023 10:48
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: uneven surface at end of drive needs to be attended too before rough edges around drain burst tyres and gives way		
Location: outside 539 Gilmerton Road	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Job Number: 50146355	Defect Number: 42140177	
Enquiry No.: 1635817	Logged by: Verint CRM Connector	on: 30/10/2023 23:03
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The manhole cover on the road is uneven and makes a noise every time a car passes over it. It is on the Gilmerton Road, near the junction with [REDACTED]'s Glen Road, driving in the direction towards Gilmerton Crossroads	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Job Number: 50144762	Defect Number: 42138389	
Enquiry No.: 1632739	Logged by: Verint CRM Connector	on: 24/10/2023 17:27
Service: Roads General	Subject: Traffic Sign:Defective/Damaged	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow		
Location: Cycling signage required due to vehicles turning into Guardwell Glen from Gilmerton	Contact:	
Road not giving way to cyclists. I have been hit by 1 car, and 2 near misses (emergency stops). Hi customer contact centre I have emailed details of this enquiry on to road safety team, can you pass this enquiry on to road safety team please.		
Enquiry No.: 1613586	Logged by: Verint CRM Connector	on: 13/09/2023 16:15
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction.		
Location:Pavement.		
Type:Foliage / Bush		
Location: This tree is overgrown and obstructing the pavement	Contact: #	
Enquiry No.: 1608828	Logged by: [REDACTED]	on: 05/09/2023 08:13
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Overgrown foliage causing cyclists and pedestrians to go road when passing each other		
Location:	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset

Effective: 25/06/2020 to 25/06/2025	Asset Number: 5.00 to 6.00
Service: Roads General	Display Action Officer: No
Site: Gilmerton Road (7901804)	

Customer Services

Enquiry No.: 1605659	Logged by: Verint CRM Connector	on: 29/08/2023 15:44
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.: Location: Tarmac on pavement broken. Trip hazard. Reported this however only repaired outside house numbers 501 and 503. Repair was requested for outside 505 and this has not been done as requested. Daughter has tripped outside whilst visiting grandparents.	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Job Number: 50141854	Defect Number: 42135134	
Enquiry No.: 1600588	Logged by: Verint CRM Connector	on: 19/08/2023 13:28
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow		
Location: Those Temporary bollards put up for Temporary Cycle Lanes during Covid, three years ago. Two consecutive bollards are missing. Just past The Spinney, heading city bound. See photo 500 GILMERTON ROAD, GILMERTON, EDINBURGH, EH17 7JF	Contact:	
Enquiry No.: 1591044	Logged by: Verint CRM Connector	on: 02/08/2023 08:28
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction. Location:Cycleway. Type:Foliage / Bush		
Location: The entire Gilmerton road cycle/foot path (between the bypass and Drum st) bushes are overgrown and make it difficult for passing safely. They also cut your arms when cycling unless you wear long sleeves. It is also difficult to see if pedestrians or cyclists are coming off of the paths onto this pavement (many wear headphones so cannot hear your bell and with the overgrown bushes cannot see you.) I cycle down here 6-10 times a week and it's getting more difficult to safely cycle here.	Contact:	
Enquiry No.: 1591043	Logged by: Verint CRM Connector	on: 02/08/2023 08:23
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Obscuring sight line. Location:Footpath. Type:Foliage / Bush		
Location: The trees overhanging from the property are low and make it difficult to see around the corner. Additionally they are so low they hit me whilst I already duck my head whilst cycling here.	Contact:	
Enquiry No.: 1581547	Logged by: Verint CRM Connector	on: 14/07/2023 09:07
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Opposite entrance to Inch Park Sports Club. Bollard on one of the cycle lane markers has been knocked off and is lying on its side.	Contact:	
Plot Number: 6.00	Feature Id - Location: Ward 15 - Liberton Road to Glenallan Drive	Feature Type: Road Asset
Job Number: 50139286	Defect Number: 42131963	

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Customer Services

Enquiry No.: 1579642	Logged by: [REDACTED]	on: 11/07/2023 10:48
Service: Roads General	Subject: Covers: Damaged / Defective	Classification: Request for service
Desc.: Loose and very noisy manhole cover		
Location: o/s no 427/429 on road	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Job Number: 50139106	Defect Number: 42131656	
Enquiry No.: 1574640	Logged by: Verint CRM Connector	on: 30/06/2023 17:23
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Overgrown.		
Location:Pavement.		
Type:Foliage / Bush		
Location:	Contact:	
Enquiry No.: 1561738	Logged by: Verint CRM Connector	on: 04/06/2023 15:40
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pot hole on the road through inch park near inch house just near the road to the playing fields	Contact:	
Plot Number: 6.00	Feature Id - Location: Ward 15 - Liberton Road to Glenallan Drive	Feature Type: Road Asset
Job Number: 50137331	Defect Number: 42129461	
Enquiry No.: 1559837	Logged by: [REDACTED]	on: 31/05/2023 12:51
Service: Roads General	Subject: Street Furniture: Defective	Classification: Request for service
Desc.: Black bollards on road with poles in the middle are actually missing the poles from them		
Location: opp Double Hedges Road	Contact:	
Enquiry No.: 1535170	Logged by: Verint CRM Connector	on: 10/04/2023 15:41
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow		
Location: cycle lane bollard missing; just the dark grey base remains. Dangerous, as cannot see this when it's dark. Easy for someone to trip over / cyclist to have an accident / bus pulling in to the adjacent bus stop	Contact:	
Enquiry No.: 1532379	Logged by: Verint CRM Connector	on: 04/04/2023 09:25
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: On Gilmerton Road, opposite entry to Liberton High School one of the bollards at the cycle lane has been dislodged and is leaning over into the cycle lane.	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Job Number: 50133676	Defect Number: 42124629	
Enquiry No.: 1494510	Logged by: Verint CRM Connector	on: 17/01/2023 19:09
Service: Roads General	Subject: Traffic Sign:Defective/Damaged	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type unlit		
Location: As described earlier part of form, the bollard is missing from the stantion base - very dangerous as the base is hardly visible, easy to trip over, drive into or cycle into	Contact:	

Effective: 25/06/2020 to 25/06/2025
 Service: Roads General
 Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
 Display Action Officer: No

Customer Services

Enquiry No.: 1489735	Logged by: [REDACTED]	on: 11/01/2023 10:36
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Pothole		
Location: at Mount [REDACTED] junct	Contact:	
Enquiry No.: 1484709	Logged by: Verint CRM Connector	on: 05/01/2023 07:47
Service: Roads General	Subject: Roadworks: Defect	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type unlit		
Location: Signs left behind x3	Contact:	
Stored folded behind bus stop		
Enquiry No.: 1464896	Logged by: Verint CRM Connector	on: 21/11/2022 17:40
Service: Roads General	Subject: Traffic Sign:Defective/Damaged	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type unlit		
Location: Leading Temporary Bollard (with RED circle) is totally missing. Very dangerous as the foundation block is almost invisible to road users and pedestrians 284 GILMERTON ROAD, GILMERTON, EDINBURGH, EH17 7PR	Contact:	
Enquiry No.: 1457809	Logged by: Verint CRM Connector	on: 08/11/2022 18:28
Service: Roads General	Subject: Street Furniture: Defective	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type unlit		
Location: Relatively new traffic island in centre of Road requires attention. One of the signs is totally flattened posing a very high risk to road users and pedestrians. The little kerbed island is now unmarked/unlit.	Contact:	
Enquiry No.: 1456451	Logged by: Verint CRM Connector	on: 06/11/2022 17:10
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Uneven road surface on roundabout - previous repair to potholes has deteriorated significantly.	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Job Number: 50121716	Defect Number: 42110834	
Enquiry No.: 1453798	Logged by: Verint CRM Connector	on: 01/11/2022 09:34
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Cycle lane bollard has been hit and is now leaning into the cycle lane	Contact:	
Plot Number: 5.00	Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station	Feature Type: Road Asset
Enquiry No.: 1450179	Logged by: [REDACTED]	on: 24/10/2022 13:12
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Jsut before traffic lights next to the church	Contact:	
Enquiry No.: 1414631	Logged by: [REDACTED]	on: 29/07/2022 08:15
Service: Roads General	Subject: Road: General Enquiry	Classification: General Enquiry
Desc.: permisison to access private road. please see doucment attached		
Location: permisison to access private road. please see doucment attached	Contact:	

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Customer Services

Enquiry No.: 1398361	Logged by: [REDACTED]	on: 27/06/2022 11:54
Service: Roads General	Subject: Traffic Sign:Defective/Damaged	Classification: Request for service
Desc.: I am writing to advise that, further to its closure, there may still be signage referencing Edinburgh Butterfly and Insect World on some local authority routes. Edinburgh Butterfly & Insect World at Dobbies Garden World Melville Nursery Lasswade Midlothian EH18 1AZ Bear Scotland confirmed that all signs within their responsibility of the South East Unit area have now had Edinburgh Butterfly and Insect World covered, but asked me to contact Midlothian, City of Edinburgh and The Scottish Borders Councils to double check for local		
Location: north side of the bypass for any Edinburgh Butterfly & Insect World - redundant	Contact:	signage thanks
Enquiry No.: 1397762	Logged by: Verint CRM Connector	on: 25/06/2022 15:50
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction. Location:Cycleway. Type:Foliage / Bush		
Location: Trees belonging to the houses just off Gilmerton junction are blocking the cycleway.	Contact:	
Enquiry No.: 1380762	Logged by: [REDACTED]	on: 23/05/2022 09:41
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: The tree branches near the southbound Gilmerton junction bus stop are obstructing the cycle path.		
Location: The tree branches near the southbound Gilmerton junction bus stop are obstructing the cycle path.	Contact:	
Enquiry No.: 1378888	Logged by: Verint CRM Connector	on: 18/05/2022 17:25
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: The crossing at Liberton Road and Gilmerton Road! I was in my car stopped at the traffic lights. An elderly lady was crossing at the green man with a tripod walker when it dipped into a large pothole and she fell down. Had to get out of the car at the lights with others to help her get up and onto the pavement! No photo but there are huge gouged areas not suitable for elderly with walking aids!		
Plot Number: 6.00	Feature Id - Location: Ward 15 - Liberton Road to Glenallan Drive	Feature Type: Road Asset
Job Number: 50113918	Defect Number: 42101581	
Enquiry No.: 1346310	Logged by: [REDACTED]	on: 16/03/2022 16:20
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Pothole Location: just down from bus terminus		
Enquiry No.: 1341436	Logged by: [REDACTED]	on: 08/03/2022 11:59
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Pothole Location: o/s church		
Contact:		

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Customer Services

Enquiry No.: 1338113	Logged by: Verint CRM Connector	on: 02/03/2022 19:28
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction.		
Location: Cycleway.		
Type: Foliage / Bush		
Location: Untrimmed hawthorn bush now over halfway across pavement/cycleway. Previously reported as YND8I035-101000958195, 28 October 2021, and NFA99107-101001078795, 18 January 2022, but problem persists and, with this season's growth already showing, is getting worse.		
Contact: Thanks, [REDACTED]		
Enquiry No.: 1335735	Logged by: [REDACTED]	on: 28/02/2022 08:40
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Please can this very deep pothole on the road that runs through Inch Park be repaired. When the road floods as it always does in heavy rain, the pothole is invisible. My cycling friend hurt herself last week when she cycled through what she assumed was just a shallow puddle.		
Location: The road running through Inch Park		
Contact:		
Plot Number: 6.00	Feature Id - Location: Ward 15 - Liberton Road to Glenallan Drive	Feature Type: Road Asset
Job Number: 50109226	Defect Number: 42096373	
Enquiry No.: 1333781	Logged by: [REDACTED]	on: 24/02/2022 15:54
Service: Roads General	Subject: Covers: Damaged / Defective	Classification: Request for service
Desc.: Collapsed manhole cover		
Category: Roads/highways		
On northbound side of the road.		
Location:		
Easting/Northing: 328636/669339 (55.911837, -3.143209)		
Nearest road to the pin placed on the map (automatically generated by Bing Maps): 445 Gilmerton Road, Edinburgh, EH17 7JJ		
Nearest postcode to the pin placed on the map (automatically generated): EH17 7JR (81m away)		
Location: Collapsed manhole cover		
Category: Roads/highways		
On northbound side of the road.		
Location:		
Easting/Northing: 328636/669339 (55.911837, -3.143209)		
Nearest road to the pin placed on the map (automatically generated by Bing Maps): 445 Gilmerton Road, Edinburgh, EH17 7JJ		
Nearest postcode to the pin placed on the map (automatically generated): EH17 7JR (81m away)		
Contact:		
Enquiry No.: 1311985	Logged by: [REDACTED]	on: 22/01/2022 19:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: @Edinburgh_CC stupidity knows no bounds in pothole repairs @mrpotholeuk , this is a pothole in a pothole and they only repaired the small bit, not the whole thing. What hope do we have? Pedestrian crossing too.		
Location: It's where Gilmerton Road meets Liberton Road, it's been like this for more than a year.		
Contact:		

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Customer Services

Enquiry No.: 1297479 Logged by: [REDACTED] on: 29/12/2021 13:20
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.: Hello, I would like to report a deep pothole on the corner of Gilmerton Rd and Fernihill Rd. The pothole is approx 1 foot deep and about 2 feet wide. This could cause serious damage to vehicles passing over and severe injuries to any biker or cyclist unlucky enough to go over it.
This need to be repaired as a matter of urgency.
Thank you
[REDACTED]

Location: on the corner of Gilmerton Rd and Fernihill Rd

Contact:

Enquiry No.: 1289938 Logged by: [REDACTED] on: 13/12/2021 15:44
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.: Sunken/damaged manhole cover

Location: just down from no 290 heading towards traffic lights

Contact:

Plot Number: 5.00 Feature Id - Location: Ward 16 - Glenallan Drive to Ferniehill Road. Gilmerton Station Feature Type: Road Asset
Job Number: 50100161 Defect Number: 42086969

Enquiry No.: 1245911 Logged by: [REDACTED] on: 16/09/2021 09:41
Service: Roads General Subject: Road: General Enquiry Classification: General Enquiry
Desc.: Blocked drain (not on map)
Location: o/s no 479 on pavement

Contact:

Enquiry No.: 1243734 Logged by: Verint CRM Connector on: 12/09/2021 11:28
Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service
Desc.: Problem: Overgrown.
Location: Pavement.
Type: Foliage / Bush

Location: Overgrown vegetation severely reducing the width of the pavement between the roundabout inside the bypass up to the junction with Gilmerton Station Rd.

Contact:

Enquiry No.: 1240863 Logged by: Verint CRM Connector on: 07/09/2021 08:53
Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service
Desc.: Problem: Overgrown.
Location: Pavement.
Type: Foliage / Bush

Location: Hello the hedge outside the flats is overgrown outside 251/2 Gilmerton Road Edinburgh EH16 5DT.

Contact:

Enquiry No.: 1240533 Logged by: [REDACTED] on: 06/09/2021 15:25
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.: Potholes in the road beside liberton primary school and inch view care home. My son fell while walking to school this way today, he staggered several times but could not save himself due to the unstable road I see while trying to report there is an active issue reported previously.
Location: BEA6AX98-101000878823

Contact:

Plot Number: 6.00 Feature Id - Location: Ward 15 - Liberton Road to Glenallan Drive Feature Type: Road Asset
Job Number: 50091418 Defect Number: 42077820

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Customer Services

Enquiry No.: 1236830 Logged by: Verint CRM Connector on: 31/08/2021 10:00
Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service
Desc.: Problem: Causing Obstruction.
Location: Cycleway.
Type: Foliage / Bush
Location: Shared use pavement on east side of Gilmerton Road. South of Gilmerton Station Contact:
Road and north of the bypass.

Enquiry No.: 1223532 Logged by: [REDACTED] on: 07/08/2021 18:02
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.: Numerous potholes
Location: Gilmerton Road meets Nether Liberton Ln Contact:

Enquiry No.: 1221096 Logged by: Verint CRM Connector on: 04/08/2021 09:04
Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service
Desc.: Problem: Causing Obstruction.
Location: Cycleway.
Type: Foliage / Bush
Location: On the cycle path between the Gilmerton Road interchange and the Loanhead interchange, the shrubbery/tree growth has flourished over the last couple of months and is close the blocking the path in points Contact:

Enquiry No.: 1221094 Logged by: Verint CRM Connector on: 04/08/2021 09:01
Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service
Desc.: Problem: Causing Obstruction.
Location: Footpath.
Type: Foliage / Bush
Location: The combined path/cycle path from the city bypass bridge to the Drum estate entrance has become badly overgrown in the last few months and makes some sections of the path/cycle path hazardous Contact:

Enquiry No.: 1200941 Logged by: Verint CRM Connector on: 03/07/2021 13:20
Service: Roads General Subject: Traffic Sign: Defective/Damaged Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow
Location: As prev described, the bollard things being erected everywhere across the city, several are missing at this location . Extremely dangerous as the unmarked base units still in situ. These are at a sharp bend on Gilmerton Rd/ junction Moredun Park Rd, also dangerous for pedestrians as well 3road users. These structures in general are difficult to see on approach at the best of times. Why dont all leading bollards have proper reflective discs? Accident waiting to happen unless attended to. TY Contact:

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00

Display Action Officer: No

Customer Services

Enquiry No.: 1198983	Logged by: Verint CRM Connector	on: 30/06/2021 11:17	
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service	
Desc.: Problem: Causing Obstruction.			
Location:Footpath.			
Type:Foliage / Bush			
Location: Overhanging branches on Gilmerton Road	Contact:		
Category: Pavements/footpaths			
There's a couple of places on the eastern pavement in the northern half of Gilmerton Road with low hanging tree branches.			
Location:			
Easting/Northing: 327763/670214 (55.919563, -3.157405)			
Nearest road to the pin placed on the map (automatically generated by Bing Maps): 245b/12 Gilmerton Road, Edinburgh, EH16 5TH			
Nearest postcode to the pin placed on the map (automatically generated): EH16 5TH (47m away)			
Enquiry No.: 1189696	Logged by: Verint CRM Connector	on: 11/06/2021 16:47	
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service	
Desc.: Problem: Causing Obstruction.			
Location:Pavement.			
Type:Foliage / Bush			
Location: Hawthorn hedge growing in field overhanging onto shared cycleway and pavement .	Contact:		
I am unable to pass this hedge safely when cycling commuting to work every day.			
The only way to pass is to dismount or cycle off the pavement into fast flowing oncoming road traffic (60mph).			
Enquiry No.: 1155389	Logged by: Aleshia Chalmers	on: 08/04/2021 09:29	
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service	
Desc.: there are 3 recent repairs that have actually made the problem worse than we had before. In fact, there is a whole section of this road that has been repaired to a very poor standard and continues to create problems with vibration through the houses nearby. Every time a bus goes by, the houses shake.			
Aldrin Spire			
CRM Number: 101000618042			
Contact details: [REDACTED]			
Customers Comment: Enquiry Reference: 101000608117 Request to repair potholes/damage to road surface, has now resulted in a far worse result since the work has not been conducted to an adequate standard. There has been far too much material inserted into the repair so rather than having a hole as we did before, we now have a large lump of tar material. This is causing far more racket and vibration from vehicles than we had previously. Please remove the repair so that we can at least get back to where it was before which would be better than what we have now.			
Customers previous reported issue: Enquiry Reference: 101000608117			
Location: Hello, the location is at the West Gate of Inch Park on Gilmerton Road,	Contact:		
Enquiry No.: 1149984	Logged by: [REDACTED]	on: 29/03/2021 16:40	
Service: Roads General	Subject: Roadworks: Defect	Classification: Request for service	
Desc.: Hi @edinhelp can these roadworks signs just North of Guardwell Crescent on Gilmerton Road be removed. The works they refer to finished days ago.			
Location: North of Guardwell Crescent on Gilmerton Road	Contact:		

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00

Display Action Officer: No

Customer Services

Enquiry No.: 1149486	Logged by: Verint CRM Connector	on: 29/03/2021 08:49
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: 23 separate road defects	Contact:	
Category: Roads/highways		
23 separate road defects in one junction, 2 other larger ones to the East of the photograph. Evidence if any was needed of the lack of maintenance of infrastructure		
Location:		
Easting/Northing: 327186/670749 (55.924285, -3.166791)		
Nearest road to the pin placed on the map (automatically generated by Bing Maps):		
1 Nether Liberton Lane, Edinburgh, EH16 5QT		
Nearest postcode to the pin placed on the map (automatically generated): EH16 5QL (69m away)		
Plot Number: 6.00	Feature Id - Location: Ward 15 - Liberton Road to Glenallan Drive	Feature Type: Road Asset
Job Number: 50145518	Defect Number: 42168186	
Enquiry No.: 1141964	Logged by: Verint CRM Connector	on: 17/03/2021 10:14
Service: Roads General	Subject: Road Markings: General Enquiry	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type unlit		
Location: Following resurfacing the Keep Clear sign painted on the road surface between 302 and 304 Gilmerton Road has not been reinstated	Contact:	
Enquiry No.: 1140483	Logged by: Verint CRM Connector	on: 15/03/2021 09:18
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Decaying and damaged surface	Contact:	
Category: Roads/highways		
Several areas of missing road surface and decaying surface		
Location:		
Easting/Northing: 327551/670399 (55.921197, -3.160856)		
Nearest road to the pin placed on the map (automatically generated by Bing Maps):		
13 East Clapperfield, Edinburgh, EH16 6TU		
Nearest postcode to the pin placed on the map (automatically generated): EH16 5QU (76m away)		
Enquiry No.: 1127810	Logged by: Verint CRM Connector	on: 23/02/2021 10:51
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole	Contact:	
Enquiry No.: 1103105	Logged by: Aleshia Chalmers	on: 19/01/2021 13:52
Service: Roads General	Subject: Roadworks: General Enquiry	Classification: Request for service
Desc.: Gilmerton Road. Can this sign be permanently disappeared? [REDACTED]@edinhelp [REDACTED]		
Location: Gilmerton Road. Can this sign be permanently disappeared? [REDACTED]	Contact:	
@edinhelp [REDACTED]		

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00

Display Action Officer: No

Customer Services

Enquiry No.: 1089392	Logged by: Verint CRM Connector	on: 24/12/2020 12:03
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location:	Contact:	
Enquiry No.: 1081648	Logged by: Verint CRM Connector	on: 08/12/2020 12:46
Service: Roads General	Subject: Traffic Sign:Defective/Damaged	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type unlit		
Location: sign has been spray painted over (obscured)	Contact:	
Enquiry No.: 1073940	Logged by: Verint CRM Connector	on: 23/11/2020 16:09
Service: Roads General	Subject: Roadworks: General Enquiry	Classification: General Enquiry
Desc.: Cycle lane has recently be constructed. Road is currently being resurfaced which means the road is uneven. the cycle lane is around 80mm-100mm above the road. If a cyclist goes to the edge this may force them onto the road. Location gilmerton road opposite ellenglens road. Callers suggestion would be to have this as a right angle and a ramp rather than pointing out into the road		
Location: Cycle lane has recently be constructed. Road is currently being resurfaced which means the road is uneven. the cycle lane is around 80mm-100mm above the road. If a cyclist goes to the edge this may force them onto the road. Location gilmerton road opposite ellenglens road. Callers suggestion would be to have this as a right angle and a ramp rather than pointing out into the road	Contact:	
Enquiry No.: 1053713	Logged by: [REDACTED]	on: 14/10/2020 09:20
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: claim paper not sent. please see attachment		
Location: claim paper not sent. please see attachment	Contact:	
Enquiry No.: 1042616	Logged by: Verint CRM Connector	on: 20/09/2020 20:59
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: large gap and crack in road surface	Contact:	
Plot Number: 6.00	Feature Id - Location: Ward 15 - Liberton Road to Glenallan Drive	Feature Type: Road Asset
Job Number: 50063405	Defect Number: 42053709	
Enquiry No.: 1042614	Logged by: Verint CRM Connector	on: 20/09/2020 20:58
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: uneven and damaged road surface south bound	Contact:	
Plot Number: 6.00	Feature Id - Location: Ward 15 - Liberton Road to Glenallan Drive	Feature Type: Road Asset
Job Number: 50063406	Defect Number: 42053710	
Enquiry No.: 1041794	Logged by: Verint CRM Connector	on: 18/09/2020 12:00
Service: Roads General	Subject: Road: Missing Setts / Blocks	Classification: Customer Emergency
Desc.:		
Location: There has been kerb/paving stones put on gilmerton road near to Morrison's supermarket which is about 4 feet out from pavement?? This is accident waiting to happen ? For what reason were they put in blocking practically a whole lane ?? Is this for cyclists?? If they are to be permanent surely these must be painted so they can be seen in the dark I struck one last night and was astounded to quite a few of these it's absolutely ridiculous to have these on nearly the middle of the road and is this	Contact:	

Effective: 25/06/2020 to 25/06/2025

Service: Roads General

Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00

Display Action Officer: No

Customer Services

Enquiry No.: 1040698	Logged by: [REDACTED] Shilling	on: 16/09/2020 10:32
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Overgrown bushes on the pavement from Gilmerton Road to the bypass.		
Location: From Gilmerton Road to the bypass.		Contact: @SpokesDalkeith
Enquiry No.: 1038051	Logged by: Verint CRM Connector	on: 11/09/2020 09:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: [REDACTED] Water leak		Contact:
Category: Other		
There has been a water leak here for months now and nothing has been done about it		
Location:		
Easting/Northing: 329143/668822 (55.907269, -3.134971)		
Nearest road to the pin placed on the map (automatically generated by Bing Maps):		
541 Gilmerton Road, Edinburgh, EH17 7JB		
Nearest postcode to the pin placed on the map (automatically generated): EH17 7AB (66m away)		
Enquiry No.: 1037646	Logged by: Verint CRM Connector	on: 10/09/2020 12:58
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Overgrown.		
Location:Verge / Grass area .		
Type:Foliage / Bush		
Location: over hanging hedge from 277 Gilmerton Road blocking light		Contact:
Enquiry No.: 1027132	Logged by: Verint CRM Connector	on: 24/08/2020 11:40
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction.		
Location:Pavement.		
Type:Foliage / Bush		
Location: Ferniehill Road pavement blocked		Contact: [REDACTED] french
Category: Pavements/footpaths		
The pavement on the corner of Ferniehill Road and Gilmerton Road is blocked by the overgrown Leylandii		
Location:		
Easting/Northing: 329173/668804 (55.907109, -3.134486)		
Nearest road to the pin placed on the map (automatically generated by Bing Maps):		
543 Gilmerton Road, Edinburgh, EH17 7JB		
Nearest postcode to the pin placed on the map (automatically generated): EH17 7AB (42m away)		
Enquiry No.: 1018797	Logged by: Verint CRM Connector	on: 07/08/2020 12:33
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Overgrown.		
Location:Verge / Grass area .		
Type:Foliage / Bush		
Location: Tree located in Summertrees Court is over hanging onto the private property of 237B Gilmerton Road. The homeowners have requested it is significantly cut back.		Contact:

Effective: 25/06/2020 to 25/06/2025
 Service: Roads General
 Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 5.00	Asset - Locn.: Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
50039699	Polychannel lids broken (RG: Polychannel Damaged)	Gilmerton road 338	RD: Cat 3 - 60 Day	Job Complete	12/08/2019	13/10/2020	Act. ROAD/82024966
50051986	Gully: Blocked / Needs Clean - Gully's blocked machine clean and flush (Enquiry 34001893)	Gilmerton road os and opp Bernard hunters	RG: Gully - High Priority	Job Complete	14/02/2020	06/09/2020	Act. RDGC14/82000782
50055354	Gully: Blocked / Needs Clean - Gully blocked machine clean and flush (Enquiry 34002060)	Gilmerton road at bypass off ramp	RG: Gully - High Priority	Job Complete	24/03/2020	06/08/2020	Act. RDGC14/82000901
50055371	Gully: Blocked / Needs Clean - Gully blocked machine clean and flush (Enquiry 34002064)	Gilmerton road city bound past Morrison's opp 459	RG: Gully - High Priority	Job Complete	25/03/2020	11/08/2020	Act. RDGC14/82000906
50057113	Gully: Blocked / Needs Clean - Gully blocked , flooding , machine clean and flush (Enquiry 34002148)	Gilmerton road south bound from Gilmerton station road towards Bernard hunter	RG: Gully - High Priority	Job Complete	24/06/2020	02/07/2020	Act. RDGC14/82000937
50057114	Gully: Blocked / Needs Clean - Gully blocked machine clean and flush (Enquiry 34002149)	Gilmerton road south bound opp Bernard hunter	RG: Gully - High Priority	Job Complete	24/06/2020	02/07/2020	Act. RDGC14/82000938
50057115	Gully: Blocked / Needs Clean - Gully blocked machine clean and flush (Enquiry 34002150)	Gilmerton road north bound past Bernard hunter	RG: Gully - High Priority	Job Complete	24/06/2020	02/07/2020	Act. RDGC14/82000939
50057116	Gully: Blocked / Needs Clean - Gully blocked machine clean and flush (Enquiry 34002151)	Gilmerton road southbound past Bernard hunter	RG: Gully - High Priority	Job Complete	24/06/2020	02/07/2020	Act. RDGC14/82000940
50057117	Gully: Blocked / Needs Clean - Gully's blocked machine clean and flush x2 (Enquiry 34002152)	Gilmerton both sides 300m from Bernard hunters	RG: Gully - High Priority	Job Complete	24/06/2020	02/07/2020	Act. RDGC14/82000941
50057118	Gully: Blocked / Needs Clean - Gully blocked machine clean and flush x2 (Enquiry 34002153)	Gilmerton road 400m from Bernard hunters	RG: Gully - High Priority	Job Complete	24/06/2020	02/07/2020	Act. RDGC14/82000942
50058486	Cw potholes marked on site x 4 (RD: CW Pothole)	Gilmerton road at mount [REDACTED], Kingston Xroads	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/07/2020	20/07/2020	Act. ROAD/82037747
50058487	Cw pothole marked on site (RD: CW Pothole)	Gilmerton road opp 284	RD: Cat 2 - 5 Day	Job Complete	14/07/2020	15/07/2020	Act. ROAD/82037747
50058488	Cw potholes marked on site X7 (RD: CW Pothole)	Gilmerton road opp 368/364	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/07/2020	15/07/2020	Act. ROAD/82037747
50058489	Cw potholes marked on site X5 (RD: CW Pothole)	Gilmerton road os and opp 457	RD: Cat 2 - 5 Day	Job Complete	14/07/2020	15/07/2020	Act. ROAD/82037747
50058490	Cw potholes marked on site x2 (RD: CW Pothole)	Gilmerton road os 461	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/07/2020	15/07/2020	Act. ROAD/82037747
50058491	Cw potholes marked on site x2 (RD: CW Pothole)	Gilmerton road os 471 opp Morrison's	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/07/2020	15/07/2020	Act. ROAD/82037747
50058492	Cw pothole marked on site (RD: CW Pothole)	Gilmerton road opp 477	RD: Cat 2 - 5 Day	Job Complete	14/07/2020	15/07/2020	Act. ROAD/82037747
50070421	1 CW pothole at fire hydrant. (RD: CW Pothole)	In between lamppost GEN22 & 23	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/12/2020	17/12/2020	Act. ROAD/82042694

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 5.00	Asset - Locn.: Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
50071572	Cw potholes please make safe (RD: CW Pothole)	Gilmerton road roundabout at bypass off ramp	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/01/2021	12/01/2021	Act. ROAD/82043144
50072875	1no pothole (RD: CW Pothole)	On the pedestrian crossing outside no523	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	26/01/2021	27/01/2021	Act. ROAD/82043726
50075873	3 x potholes (RD: CW Pothole)	Approximately 50m past bus turning circle at gate to field	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/02/2021	25/02/2021	Act. ROAD/82045363
50075879	Pothole on cw (RD: CW Pothole)	Adjacent to walkway see pics	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/02/2021	24/02/2021	Act. ROAD/82045366
50075895	Pothole on cw (RD: CW Pothole)	Approximately 100m from gilmerton junction roundabout	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/02/2021	24/02/2021	Act. ROAD/82045371
50075903	Cracked broken surface (RD: CW Cracked/Broken)	On gilmerton road roundabout	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/02/2021	23/03/2021	Act. ROAD/82045378
50075914	Fw is due to have surface treatment . Due to this 1 x raised utility cover on fw has been left raised and not made safe. Trip hazard. Please either cover or put some temp material round utility cover removing trip hazard (RD: FW Cover Make Safe)	At lamppost GEN 83	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/02/2021	23/03/2021	Act. ROAD/82045385
50075916	Hydrant cover surround on centre of cw, edges prominent (RD: CW Pothole)	Between lamppost GEN 22 and GEN 23	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/02/2021	24/02/2021	Act. ROAD/82045387
50075928	Refresh all cw markings (RD: Markings Refresh)	From gilmerton station road down to gilmerton roundabout at bypass	RD: Cat 4 - Programmed	Job Complete	22/02/2021	09/12/2024	Act. ROAD/82095587
50075989	Gully blocked with mud (Gully: Blocked - Hand Clear)	Across from pipeline technology centre (see pics)	RG: Gully - Standard Priority	RD: Made Safe Job Complete	23/02/2021	28/02/2021	Act. RDGC14/82002525
50075994	Gully completely blocked. Full of mud (Gully: Blocked - Hand Clear)	Approximately 50m past pipeline technology centre heading towards bypass	RG: Gully - Standard Priority	Job Complete	23/02/2021	28/02/2021	Act. RDGC14/82002526
50076003	Gully completely blocked with mud (Gully: Blocked - Hand Clear)	Approximately 100m past pipeline technology centre heading towards bypass	RG: Gully - Standard Priority	Job Complete	23/02/2021	28/02/2021	Act. RDGC14/82002527
50076007	Gully completely blocked with mud (Gully: Blocked - Hand Clear)	Approximately 150m past pipeline technology centre heading towards bypass	RG: Gully - Standard Priority	Job Complete	23/02/2021	28/02/2021	Act. RDGC14/82002528
50076011	Gully full of leaves (Gully: Blocked - Hand Clear)	Near roundabout heading towards bypass	RG: Gully - Standard Priority	Job Complete	23/02/2021	28/02/2021	Act. RDGC14/82002529
50076013	Gully full of Water, needs cleared (Gully: Blocked - HP Jet Req'd)	At roundabout near bypass	RG: Gully - Standard Priority	RD: Made Safe Job Complete	23/02/2021	02/03/2021	Act. RDGC14/82002530
50076014	Gully full of water and mud (Gully: Blocked - Hand Clear)	Between the 2 roundabouts at bypass	RG: Gully - Standard Priority	Job Complete	23/02/2021	20/10/2021	Act. RDGC14/82002531
50076017	Gully full of Water, needs cleared (Gully: Blocked - HP Jet Req'd)	At roundabout (see pics)	RG: Gully - Standard Priority	Job Complete	23/02/2021	02/03/2021	Act. RDGC14/82002532

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 5.00	Asset - Locn.: Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
50076025	Pothole at cw edge (RD: CW Pothole)	At junction with pipeline technology centre heading towards gilmerton station road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2021	24/02/2021	Act. ROAD/82045441
50076031	2 x potholes (RD: CW Pothole)	At junction with pipeline technology centre	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2021	24/02/2021	Act. ROAD/82045447
50076085	Pothole on cw (RD: CW Pothole)	Near lampost GEN22	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2021	24/02/2021	Act. ROAD/82045482
50076087	Gully: Blocked / Needs Clean - Blocked gully, needs cleaned out (Enquiry 34003171)	On opposite side of cw from lampost GEN21	RG: Gully - High Priority	Job Complete	23/02/2021	03/05/2021	Act. RDGC14/82002537
50077215	1no CW depression (RD: CW Rutting)	North roundabout near city bypass, section towards road leading to numbers 612-618	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/03/2021	23/03/2021	Act. ROAD/82046265
50083631	Missing bollard (RD: SFP Damaged Bollard)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/05/2021	24/05/2021	Act. ROAD/82050024
50085328	Replaced damaged bollard (RD: SFP Damaged Bollard)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/06/2021	16/06/2021	Act. ROAD/82050983
50087556	Replaced missing red reflective disc form bollard (RD: SFP Damaged Signage)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	16/07/2021	16/07/2021	Act. ROAD/82052061
50087557	Replaced missing red reflective disc form bollard (RD: SFP Damaged Signage)		RD: Cat 2 - 5 Day	Job Complete	16/07/2021	16/07/2021	Act. ROAD/82052062
50087558	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	16/07/2021	16/07/2021	Act. ROAD/82052063
50087559	Replaced damaged cycle defender that's broken away from the Road (RD: SFP Damaged Bollard)		RD: Cat 3 - 60 Day	Job Complete	16/07/2021	26/07/2021	Act. ROAD/82052064
50088698	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/08/2021	02/08/2021	Act. ROAD/82052713
50090657	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/08/2021	30/08/2021	Act. ROAD/82053803
50090658	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	30/08/2021	03/09/2021	Act. ROAD/82053804
50090659	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/08/2021	30/08/2021	Act. ROAD/82053805
50090662	Replaced missing bollards (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/08/2021	30/08/2021	Act. ROAD/82053808
50091990	Replaced missing bollards (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/09/2021	17/09/2021	Act. ROAD/82054419
50092366	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	22/09/2021	22/09/2021	Act. ROAD/82054513
50092531	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	24/09/2021	24/09/2021	Act. ROAD/82054575

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 5.00	Asset - Locn.: Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
50093524	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	12/10/2021	12/10/2021	Act. ROAD/82054900
50094773	Replace missing bollards (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	26/10/2021	26/10/2021	Act. ROAD/82055329
50094777	Replace missing bollards (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	26/10/2021	26/10/2021	Act. ROAD/82055330
50095952	Cw pothole marked on site (RD: CW Pothole)	Gilmerton road from bypass off ramp city bound per map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/11/2021	09/11/2021	Act. ROAD/82055823
50098470	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	25/11/2021	25/11/2021	Act. ROAD/82056834
50099037	Replaced missing bollards (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	01/12/2021	01/12/2021	Act. ROAD/82057031
50099751	1no pothole (RD: CW Pothole)	Outside no207	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/12/2021	13/12/2021	Act. ROAD/82057368
50100161	Cw pothole marked on site (RD: CW Pothole)	Gilmerton rd os 290 city bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/12/2021	15/12/2021	Act. ROAD/82057557
50105558	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	07/02/2022	07/02/2022	Act. ROAD/82059852
50106164	x1 pothole, make safe. (RD: CW Pothole)	Outside 190.	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/02/2022	15/02/2022	Act. ROAD/82060155
50108438	Footway pothole as marked (RD: FW HRA Pothole)	At bus stop just past Glennallan Drive - heading out of town	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	08/03/2022	Act. ROAD/82061423
50108444	Footway potholes x 2 as marked (RD: FW HRA Pothole)	At first bus stop past Glennallan Drive- Heading out of town	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061424
50108451	Footway pothole (RD: FW HRA Pothole)	O/S no 497 at kerb edge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061427
50108458	Footway pothole at kerb edge (RD: FW HRA Pothole)	O/S no 511A	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061432
50108459	Footway- carriageway pothole at kerb edge (RD: FW HRA Pothole)	O/S no 527	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061433
50108467	Potholes x 2 (RD: CW Pothole)	Approx 30m South of turning circle-O/S farmers gate heading out of town	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061441
50108468	Potholes x 2 (RD: CW Pothole)	O/S entrance to walkway-cycleway	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061442
50108473	Pothole (RD: CW Pothole)	Approx 25m North of roundabout- heading to town	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061447
50108474	Pothole as marked (RD: CW Pothole)	20m North of bus stop heading to town- see pin on map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061448
50108491	Old pole stump - ramp off with tar to make safe (RD: FW HRA Pothole)	Near junction withThe Spinney on footway	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061459

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 5.00	Asset - Locn.: Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
50108496	Old pole stump on footway infill with tar to make safe (RD: FW HRA Pothole)	At lamppost GEN 78A	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061462
50108498	Footway potholes x 7 as marked (RD: FW HRA Pothole)	Opp no 435- 437	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061463
50108499	Trip at footway manhole surround make safe with tar (RD: FW HRA Pothole)	Near lamppost GE 65	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061464
50108502	Trips on footway make safe with tar (RD: FW HRA Pothole)	25m North of Aldi exit - 10m North of bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061465
50108503	Footway pothole (RD: FW HRA Pothole)	On Bridge over burn See pin on map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061466
50108508	Footway pothole- depression make safe (RD: FW HRA Pothole)	Near lamppost 58	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061469
50108515	Trip at crossing make safe with tar (RD: FW HRA Pothole)	25m South of Double Hedges Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	09/03/2022	Act. ROAD/82061473
50110475	RD: SFP Damaged Bollard		RD: Cat 2 - 5 Day	Job Complete	28/03/2022	28/03/2022	Act. ROAD/82062420
50111240	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	05/04/2022	05/04/2022	Act. ROAD/82062803
50111304	Broken catv cover Repeatedly declined by utility companies please infill with sand bags and top with cold tar (RD: FW Cover Make Safe)	Gilmerton rd at mount [REDACTED] rd	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	05/04/2022	06/04/2022	Act. ROAD/82062838
50112074	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	19/04/2022	19/04/2022	Act. ROAD/82063258
50115748	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	27/06/2022	27/06/2022	Act. ROAD/82065201
50116013	Cycle defender to be moved to let more access for buses coming into Bus stop heading southbound both cycle defenders to be moved more space for buses entering bus stop (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	01/07/2022	04/07/2022	Act. ROAD/82065336
50116014	Cycle defender to be moved on to give access to buses southbound yellow markings on the road to where it is to be moved to give bosses more access the bus stop (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	01/07/2022	04/07/2022	Act. ROAD/82065337
50116655	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	19/07/2022	19/07/2022	Act. ROAD/82065632

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 5.00	Asset - Locn.: Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
50116930	Replaced damaged bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	28/07/2022	28/07/2022	Act. ROAD/82065813
50117336	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	10/08/2022	10/08/2022	Act. ROAD/82066103
50117773	1no pothole (RD: CW Pothole)	30m south of Bernard Hunter	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/08/2022	24/08/2022	Act. ROAD/82066382
50118442	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	07/09/2022	07/09/2022	Act. ROAD/82066760
50120020	Replaced damaged bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	14/10/2022	14/10/2022	Act. ROAD/82067535
50120023	Cycle defender broken away from road and needs fixed back down ASAP thanks Matthew (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	14/10/2022	17/10/2022	Act. ROAD/82067537
50120297	2 cw potholes (RD: CW Pothole)	200m south of bernard hunter Heading into town	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/10/2022	20/10/2022	Act. ROAD/82067659
50120299	2 cw potholes (RD: CW Pothole)	Just before bus stop As come of roundabout at bypass Heading towards Bernard hunter	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/10/2022	20/10/2022	Act. ROAD/82067660
50120324	1 fw pothole Ramp trip at kerb (RD: FW HRA Pothole)	At crossing On fw Opposite speed camera 20m south of Ivanhoe crescent	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/10/2022	20/10/2022	Act. ROAD/82067670
50120413	Replaced damaged bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	21/10/2022	21/10/2022	Act. ROAD/82067699
50120619	1no pothole (RD: CW Pothole)	Outside no290	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/10/2022	25/10/2022	Act. ROAD/82067787
50121123	Cycle defender has been hit and needs fixed back down to road asap thanks Matthew (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	31/10/2022	04/11/2022	Act. ROAD/82068023
50121308	Replaced damaged cycle defender has broken away from road and needs fixed ASAP hazardous to cyclists (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	02/11/2022	04/11/2022	Act. ROAD/82068114
50121716	Hot overlays required (RD: CW Cracked/Broken)	Gilmerton road roundabout at bypass off ramp	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/11/2022	13/11/2022	Act. ROAD/82068282
50121807	Cycle defender is broken away from the road and needs fixed back down.. (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	08/11/2022	11/11/2022	Act. ROAD/82068310
50121816	1 carriageway pothole (RD: CW Pothole)	Outside 290	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/11/2022	09/11/2022	Act. ROAD/82068315
50122340	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	16/11/2022	16/11/2022	Act. ROAD/82068564

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 5.00	Asset - Locn.: Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
50123152	Replaced damaged bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	28/11/2022	28/11/2022	Act. ROAD/82068908
50123159	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	28/11/2022	28/11/2022	Act. ROAD/82068913
50126435	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	17/01/2023	17/01/2023	Act. ROAD/82070976
50127327	Large depression requires hra overlay (RD: CW Pothole)	On the pedestrian crossing outside Brite Dental	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/01/2023	29/01/2023	Act. ROAD/82071606
50128069	Remove x1 yellow housing development sign for "Gilmerton Heights" from direction sign. Leave sign for "Farrier Fields" if installed. (RD: Unlit Sign Damaged/Missing)	Approx 30m north of entrance into Enigma industrial services etc.	RD: Cat 3 - 60 Day	Job Complete	31/01/2023	01/02/2023	Act. ROAD/82072136
50131752	RD: CW Pothole	Traffic island crossing point and cycle lane (Southbound)	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/03/2023	14/03/2023	Act. ROAD/82074165
50133676	Cycle lane bollard damaged Road: Defective / Damaged (Enquiry 1532379) (RD: SFP Damaged Bollard)	Outside of Liberton High School	RD: Cat 4 - Programmed	Job Complete	05/04/2023	04/05/2023	Act. ROAD/82076369
50136386	1no pothole (RD: CW Pothole)	Outside no451	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/05/2023	22/05/2023	Act. ROAD/82077368
50141854	Fwx 1 pothole Pavement: Damaged / Defective (Enquiry 1605659) (RD: CW Pothole)	Outside of 505	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/08/2023	31/08/2023	Act. ROAD/82080358
50144292	1no damaged bollard (RD: SFP Damaged Bollard)	10m south of lamppost 22	RD: Cat 3 - 60 Day	Job Complete	20/10/2023	23/10/2023	Act. ROAD/82081796
50144293	1no damaged bollard (RD: SFP Damaged Bollard)	Opposite Rutherford drive	RD: Cat 3 - 60 Day	Job Complete	20/10/2023	23/10/2023	Act. ROAD/82081797
50144361	1no missing bollard (RD: SFP Damaged Bollard)	Opposite Lamppost GEN33	RD: Cat 3 - 60 Day	Job Complete	23/10/2023	23/10/2023	Act. ROAD/82081825
50144367	1no missing bollard (RD: SFP Damaged Bollard)	Approx 20m south of lamppost GEN35	RD: Cat 3 - 60 Day	Job Complete	23/10/2023	23/10/2023	Act. ROAD/82081829
50144368	1no missing bollard (RD: SFP Damaged Bollard)	At lamppost GEN 57	RD: Cat 3 - 60 Day	Job Complete	23/10/2023	23/10/2023	Act. ROAD/82081830
50144369	1no missing bollard (RD: SFP Damaged Bollard)	See pin location	RD: Cat 3 - 60 Day	Job Complete	23/10/2023	23/10/2023	Act. ROAD/82081831
50144370	1no missing bollard (RD: SFP Damaged Bollard)	See pin location	RD: Cat 3 - 60 Day	Job Complete	23/10/2023	23/10/2023	Act. ROAD/82081832
50144372	1no missing bollard (RD: SFP Damaged Bollard)	Opposite 497	RD: Cat 3 - 60 Day	Job Complete	23/10/2023	23/10/2023	Act. ROAD/82081834
50144373	1no missing bollard (RD: SFP Damaged Bollard)	Opposite 497	RD: Cat 3 - 60 Day	Job Complete	23/10/2023	23/10/2023	Act. ROAD/82081835
50144374	Reset bollard base 1no missing bollard (RD: SFP Damaged Bollard)	Opposite 495	RD: Cat 3 - 60 Day	Job Complete	23/10/2023	23/10/2023	Act. ROAD/82081836

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 5.00	Asset - Locn.: Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
50146355	Fw x1 pothole (makesafe) (RD: FW HRA Pothole)	outside 539 Gilmerton Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/11/2023	27/11/2023	Act. ROAD/82083040
50146563	Reset 2no bollard bases (RD: SFP Damaged Bollard)	Opposite Liberton High School entrance	RD: Cat 3 - 60 Day	Job Complete	24/11/2023	28/11/2023	Act. ROAD/82083168
50148440	Cw x1 pothole (RD: CW Pothole)	Outside of number 290	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/12/2023	19/12/2023	Act. ROAD/82084314
50148501	1no pothole (RD: CW Pothole)	Outside no541	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	19/12/2023	20/12/2023	Act. ROAD/82084351
50151901	Grano patch failed, please excavate and reinstate (old bus stop pole) (RD: FW Grano Cracked/Broken)	Opposite number 433	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/02/2024	08/04/2024	Act. ROAD/82086629
50155468	1 cw pothole (RD: CW Pothole)	Citybound lane See pin location	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	11/03/2024	12/03/2024	Act. ROAD/82089173
50156499	1no dislodged base (RD: SFP Damaged Bollard)	Opposite start bright nursery	RD: Cat 3 - 60 Day	Job Complete	21/03/2024	09/05/2024	Act. ROAD/82089853
50156585	Cw x 3 potholes (RD: CW Pothole)	Roundabout off bypass eastbound slip	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	22/03/2024	23/03/2024	Act. ROAD/82089916
50157750	2 cw potholes (RD: CW Pothole)	Outside 290	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/04/2024	10/04/2024	Act. ROAD/82090799
50158045	1 pothole (RD: CW Pothole)	Outside 543	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/04/2024	11/04/2024	Act. ROAD/82091025
50158604	6x cycle lane bollards, loose and damaged (RD: SFP Damaged Bollard)	Outside new high school	RD: Cat 3 - 60 Day	Job Complete	17/04/2024	09/05/2024	Act. ROAD/82091453
50158724	1no damaged bollard (RD: SFP Damaged Bollard)	Opposite no 284	RD: Cat 3 - 60 Day	Job Complete	18/04/2024	09/05/2024	Act. ROAD/82091530
50159732	Cw x1 pothole , make safe (RD: CW Pothole)	Just before the bridge deck (southbound) , also reported to Scottish Water	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/05/2024	06/05/2024	Act. ROAD/82092175
50160105	1no base needs reset (RD: SFP Damaged Bollard)	Opposite Start Bright Nursery	RD: Cat 3 - 60 Day	Job Complete	09/05/2024	22/05/2024	Act. ROAD/82092382
50160669	Fw x3 potholes (RD: FW HRA Pothole)	Outside of 513	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/05/2024	22/05/2024	Act. ROAD/82092698
50164237	1no missing bollard (RD: SFP Damaged Bollard)	Opposite 415	RD: Cat 3 - 60 Day	Job Complete	22/07/2024	24/07/2024	Act. ROAD/82094889
50165179	3no missing bollards (RD: SFP Damaged Bollard)	Section between Ellen's glen rd and aldi west side	RD: Cat 3 - 60 Day	Job Complete	12/08/2024	12/08/2024	Act. ROAD/82095540
50165180	2no damaged bollards 1no broken base (RD: SFP Damaged Bollard)	Opposite Craigend Park	RD: Cat 3 - 60 Day	Job Complete	12/08/2024	12/08/2024	Act. ROAD/82095541
50166707	Replace missing SFP bollard (RD: SFP Damaged Bollard)	Opposite craigend park	RD: Cat 3 - 60 Day	Job Complete	18/09/2024	23/09/2024	Act. ROAD/82096359
50166708	Replace x3 missing SFP bollard (RD: SFP Damaged Bollard)	See pin point and photos for location	RD: Cat 3 - 60 Day	Job Complete	18/09/2024	19/09/2024	Act. ROAD/82096360

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 5.00	Asset - Locn.: Ward 16 - Glenallan Drive to Ferniehill Road.	Gilmerton Station	Feature Type: Road Asset		Area: South East Locality	
50168409	3no missing bollards (RD: SFP Damaged Bollard)	At the junction with Redgauntlet Terrace and opposite Craigend Park	RD: Cat 3 - 60 Day	Job Complete	21/10/2024	28/10/2024	Act. ROAD/82097545
50168411	1no missing bollard (RD: SFP Damaged Bollard)	Opposite 304	RD: Cat 3 - 60 Day	Job Complete	21/10/2024	30/10/2024	Act. ROAD/82097546
50168414	2no missing bollards (RD: SFP Damaged Bollard)	Outside 368	RD: Cat 3 - 60 Day	Job Complete	21/10/2024	28/10/2024	Act. ROAD/82097548
50169060	1no pole has been removed leaving the pole base please cut away and make safe with cold tar (TS: Sign Pole Loose)	Outside no255 at bus stop	RD: Cat 3 - 60 Day	Job Complete	01/11/2024	12/11/2024	Act. ROAD/82097947
50169842	1no missing bollard Replace damaged base (RD: SFP Damaged Bollard)	Opposite Craigend park	RD: Cat 3 - 60 Day	Job Complete	15/11/2024	18/11/2024	Act. ROAD/82098474
50170402	2no missing SFP bollards (RD: SFP Damaged Bollard)	Section of SFP outside no368	RD: Cat 3 - 60 Day	Job Complete	26/11/2024	04/12/2024	Act. ROAD/82098849
50173691	No 1 pothole (RD: CW Pothole)	Outside no 290	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/01/2025	28/01/2025	Act. ROAD/82101352
50174889	1 pothole (RD: CW Pothole)	Outside 509	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	12/02/2025	12/02/2025	Act. ROAD/82102322
50175701	2no missing bollards (RD: SFP Damaged Bollard)	Outside 251	RD: Cat 3 - 60 Day	Job Complete	24/02/2025	26/02/2025	Act. ROAD/82103017
50175704	Reinstate 2no dislodged bollard bases (RD: SFP Damaged Bollard)	Opposite Southern medical practice	RD: Cat 3 - 60 Day	Job Complete	24/02/2025	26/02/2025	Act. ROAD/82103019
50179887	1no missing bollard (RD: SFP Damaged Bollard)	Opposite high school entrance	RD: Cat 3 - 60 Day	Job Complete	14/05/2025	14/05/2025	Act. ROAD/82106015
50179888	1no missing bollard (RD: SFP Damaged Bollard)	At Aldi car park	RD: Cat 3 - 60 Day	Job Complete	14/05/2025	15/05/2025	Act. ROAD/82106016
	Asset: 6.00	Asset - Locn.: Ward 15 - Liberton Road to Glenallan Drive		Feature Type: Road Asset		Area: South East Locality	
50019289	Gully flooding (Gully: Blocked / Flooding)	By Ip 05 Gilmerton Road	RD: Cat 2 - 5 Day	Job Complete	21/11/2018	07/08/2020	Act. ROAD/82014872
50058470	Cw pothole marked on site (RD: CW Pothole)	Gilmerton road city bound passed orrok park	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/07/2020	15/07/2020	Act. ROAD/82037737
50058471	Cw pothole marked on site (RD: CW Pothole)	Gilmerton road city bound before nether Liberton court	RD: Cat 2 - 5 Day	Job Complete	14/07/2020	15/07/2020	Act. ROAD/82037737
50058472	Cw pothole marked on site (RD: CW Pothole)	Gilmerton road city bound at liberton road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/07/2020	20/07/2020	Act. ROAD/82037737
50058473	Cw pothole marked on site (RD: CW Pothole)	Gilmerton road city bound at orrok park	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/07/2020	15/07/2020	Act. ROAD/82037737
50063405	Overbanding required (RD: CW Open Joint)	Gilmerton road from double hedges road to orrok park	RD: Cat 3 - 60 Day	Job Complete	24/09/2020	19/10/2020	Act. ROAD/82039702
50063406	Cw potholes in channel (RD: CW Pothole)	Gilmerton road south bound opp nether Liberton court	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/09/2020	25/09/2020	Act. ROAD/82039703

Effective: 25/06/2020 to 25/06/2025
 Service: Roads General
 Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 6.00	Asset - Locn.: Ward 15 - Liberton Road to Glenallan Drive		Feature Type: Road Asset		Area: South East Locality	
50065472	Patching required Bus stop 15mx1.5m Patch 2mx1m Patch 3mx6m Ped crossing needs attention but would require road closure (RD: CW Subsidence/Heaving)	Gilmerton road city bound from nether Liberton court to liberton road Bus stop 15m x 1.5m Patch 2mx1m Patch 3mx6m Ped crossing needs attention but would require road closure	RD: Cat 3 - 60 Day	Job Complete	23/10/2020	29/10/2020	Act. ROAD/82040561
50068701	Cw potholes on track (RD: CW Pothole)	Gilmerton road south bound at D islands opp double hedges road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/12/2020	03/12/2020	Act. ROAD/82041852
50069000	Damaged barrier (RD: Railing Damage/Missing/New)	Gilmerton road at liberton road	RD: Cat 2 - 5 Day	Job Complete	03/12/2020	10/12/2020	Act. ROAD/82042050
50075919	Pothole on cw (RD: CW Pothole)	Approximately 50m from liberton road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/02/2021	24/02/2021	Act. ROAD/82045390
50075920	Pothole on cw (RD: CW Pothole)	Approximately 20m from liberton road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/02/2021	24/02/2021	Act. ROAD/82045391
50076091	Pothole (RD: CW Pothole)	Outside 207 on cw	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2021	24/02/2021	Act. ROAD/82045484
50076096	Gully: Blocked / Needs Clean - Blocked gully, full of mud (Enquiry 34003172)	Outside 207 on cw	RG: Gully - High Priority	Job Complete	23/02/2021	03/05/2021	Act. RDGC14/82002538
50080090	2no carriageway potholes (RD: CW Pothole)	At the junction with libertine rd on pedestrian crossing	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/03/2021	13/04/2021	Act. ROAD/82047957
50085325	Replaced damaged bollard (RD: SFP Damaged Bollard)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/06/2021	16/06/2021	Act. ROAD/82050981
50086548	Damaged red disc form bollard (RD: SFP Damaged Signage)		RD: Cat 2 - 5 Day	Job Complete	06/07/2021	06/07/2021	Act. ROAD/82051610
50086549	Replaced missing sign for bollard (RD: SFP Damaged Signage)		RD: Cat 2 - 5 Day	Job Complete	06/07/2021	06/07/2021	Act. ROAD/82051611
50087560	Replaced missing red reflective disc form bollard (RD: SFP Damaged Signage)		RD: Cat 2 - 5 Day	Job Complete	16/07/2021	16/07/2021	Act. ROAD/82052065
50091081	Cw pothole marked on site (RD: CW Pothole)	Gilmerton Rd at nether liberton	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/09/2021	06/09/2021	Act. ROAD/82054052
50091418	Cw potholes marked on site x4 (RD: CW Pothole)	Gilmerton road , liberton primary Inch park access road by lp2 and lp3	Non Routine (One Off Works)	RD: Made Safe Job Complete	09/09/2021	13/09/2021	Act. ROAD/82054220
50108409	Pothole (RD: CW Pothole)	At pedestrian crossing Near Liberton Road within studs as marked	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/03/2022	08/03/2022	Act. ROAD/82061415
50108413	Footway pothole as marked (RD: FW HRA Pothole)	10m North of lamppost GEN05 heading out of town	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	08/03/2022	Act. ROAD/82061416
50108424	Footway potholes x 2 as marked (RD: FW HRA Pothole)	At entrance to Liberton Primary - at kerb edge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/03/2022	08/03/2022	Act. ROAD/82061422
50109226	Cw potholes marked on site x8 (RD: CW Pothole)	Inch Park access rd from gilmerton rd to old Dalkeith rd	Non Routine (One Off Works)	RD: Made Safe Job Complete	16/03/2022	18/03/2022	Act. ROAD/82061806

Effective: 25/06/2020 to 25/06/2025
Service: Roads General
Site: Gilmerton Road (7901804)

Asset Number: 5.00 to 6.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 6.00	Asset - Locn.: Ward 15 - Liberton Road to Glenallan Drive		Feature Type: Road Asset		Area: South East Locality	
50109230	Reset dislodged bullnose kerb x7 (RD: FW Kerb Dislodged/Rocking)	Inch park access rd from gilmerton rd Os inch community sports club	Non Routine (One Off Works)	Job Complete	16/03/2022	22/03/2022	Act. ROAD/82061808
50113918	Cw pothole at box (RD: CW Pothole)	Gilmerton rd at liberton rd	RD: Cat 3 - 60 Day	Job Complete	19/05/2022	24/05/2022	Act. ROAD/82064259
50120024	Replaced damaged bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	14/10/2022	14/10/2022	Act. ROAD/82067538
50137331	Cw x1 pothole Road: Defective / Damaged (Enquiry 1561738) (RD: CW Pothole)	Outside of Inch House, accessible from 225 Gilmerton Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/06/2023	08/06/2023	Act. ROAD/82077996
50139286	Cycle lane bollard broken, please replace (RD: SFP Damaged Bollard)	Just after pedestrian crossing head to Cameron Toll	RD: Cat 4 - Programmed	Job Complete	14/07/2023	08/08/2023	Act. ROAD/82079664
50139289	Cycle lane reflective pole damaged, please replace (RD: SFP Damaged Bollard)	After pedestrian crossing heading towards Cameron Toll	RD: Cat 4 - Programmed	Job Complete	14/07/2023	08/08/2023	Act. ROAD/82079667
50145125	1no missing bollard (RD: SFP Damaged Bollard)	Outside liberton primary school	RD: Cat 3 - 60 Day	Job Complete	06/11/2023	09/11/2023	Act. ROAD/82082379
50153703	1no pothole (RD: CW Pothole)	Near the junction with Nether Liberton Lane	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/02/2024	27/02/2024	Act. ROAD/82087925
50157678	1 cw pothole (RD: CW Pothole)	Opposite lp5	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/04/2024	10/04/2024	Act. ROAD/82090740
50160288	1no pothole (RD: CW Pothole)	Just west of Nether Liberton Courtt	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/05/2024	17/05/2024	Act. ROAD/82092486
50169054	2no fw potholes either side of triple telecom box (RD: CW Pothole)	At bus stop opposite nether liberton court	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/11/2024	01/11/2024	Act. ROAD/82097944
50169058	Railing damaged and leaning into fw making fw narrow (RD: Railing Damage/Missing/New)	Opposite side from nether liberton court	RD: Cat 3 - 60 Day	Job Complete	01/11/2024	21/11/2024	Act. ROAD/82097946
50175561	1no pothole (RD: CW Pothole)	At orrok paek	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/02/2025	24/02/2025	Act. ROAD/82102886
50181791	1no missing bollard (RD: SFP Damaged Bollard)	At lp13	RD: Cat 3 - 60 Day	Job Complete	23/06/2025	24/06/2025	Act. ROAD/82107192