

Effective: 01/02/2025 to 31/05/2025

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Maybury Road (7900466)

Site: Maybury Road (7900466)

Locality: Cammo, Edinburgh, City of Edinburgh

Area: North West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 1 - Barnton Junction to Craigs Road			Feature Type: Road Asset		Area: North West Locality	
Batch: 41229480 - Inspection Batch			Route: Ad hoc Route				Date: 28/05/2025	
42184532	Pothole on carriageway	28/05/2025	Heading north before Meadowsweet Drive north junction	RD: CW Pothole	Internal		Committed	50180531
Batch: 41228358 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route				Date: 15/05/2025	
Batch: 41226378 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route				Date: 22/04/2025	
Batch: 41224815 - Inspection Batch			Route: Ad hoc Route				Date: 01/04/2025	
42180400	1no pothole	01/04/2025	At lamppost 117	RD: CW Pothole	Internal		Committed	50177977
Batch: 41224467 - Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 30/03/2025	
Batch: 41223801 - Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 22/03/2025	
Batch: 41223132 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route				Date: 17/03/2025	
Batch: 41223057 - Inspection Batch			Route: Ad hoc Route				Date: 17/03/2025	
42178834	Sign left on footway	17/03/2025	Outside 14	RU: Utility Reinstatement	Internal		Uncommitted	50177044
Batch: 41222948 - Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 16/03/2025	
Batch: 41222225 - Inspection Batch			Route: Ad hoc Route				Date: 11/03/2025	
42178344	Pothole on carriageway	11/03/2025	Heading south after number 15	RD: CW Pothole	Internal		Committed	50176733
Batch: 41221414 - Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 05/03/2025	
Batch: 41220683 - Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 26/02/2025	
Batch: 41220230 - Inspection Batch			Route: Ad hoc Route				Date: 21/02/2025	
42176751	Pothole at kerb edge	21/02/2025	At the driveway entrance to 12-10	RD: CW Pothole	Internal		Committed	50175665
Batch: 41219772 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route				Date: 19/02/2025	
Batch: 41219586 - Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 19/02/2025	
Batch: 41219043 - Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 13/02/2025	
Batch: 41217677 - Inspection Batch			Route: Ad hoc Route				Date: 05/02/2025	
42175065	Permanent repair required	05/02/2025	Junction Queensferry Road heading east	RD: CW Rutting	Internal		Uncommitted	50174347

Effective: 01/02/2025 to 31/05/2025

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Maybury Road (7900466)

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	1.00	<b>Asset - Locn.:</b> Ward 1 - Barnton Junction to Craigs Road		<b>Feature Type:</b> Road Asset		<b>Area:</b> North West Locality		
<b>Batch:</b>	41217600 - Inspection Batch		<b>Route:</b> Ad hoc Route			<b>Date:</b> 05/02/2025		
42175012	Permanent repair required	05/02/2025	Heading north from Maybury roundabout	RD: CW Rutting	Internal		Uncommitted	50174315
<b>Batch:</b>	41217599 - Inspection Batch		<b>Route:</b> Ad hoc Route			<b>Date:</b> 05/02/2025		
42175011	Pothole on carriageway inside lane	05/02/2025	Heading north after Meadowsweet Drive	RD: CW Pothole	Internal		Committed	50174314
<b>Batch:</b>	41217597 - Inspection Batch		<b>Route:</b> Ad hoc Route			<b>Date:</b> 05/02/2025		
42175009	Permanent repair required	05/02/2025	Heading north from Meadowsweet Drive	RD: CW Rutting	Internal		Uncommitted	50174312
<b>Batch:</b>	41217392 - Inspection Batch		<b>Route:</b> Ad hoc Route			<b>Date:</b> 04/02/2025		
42174789	Permanent repair required	04/02/2025	Outside 5	RD: CW Rutting	Internal		Uncommitted	50174153
<b>Batch:</b>	41217390 - Inspection Batch		<b>Route:</b> Ad hoc Route			<b>Date:</b> 04/02/2025		
42174787	Pothole on carriageway	04/02/2025	Outside 15	RD: CW Pothole	Internal		Committed	50174151
<b>Asset:</b>	2.00	<b>Asset - Locn.:</b> Ward 3 - Craigs Road to Glasgow Road		<b>Feature Type:</b> Road Asset		<b>Area:</b> North West Locality		
<b>Batch:</b>	41229591 - Inspection Batch		<b>Route:</b> Ad hoc Route			<b>Date:</b> 29/05/2025		
42184684	Refresh yellow box markings	29/05/2025	Junction North Gyle Terrace	RD: Markings Refresh	Internal		Uncommitted	50180623
<b>Batch:</b>	41229350 - Inspection Batch		<b>Route:</b> SfP_NorthWest			<b>Date:</b> 27/05/2025		
No actionable defects found								
<b>Batch:</b>	41228359 - Inspection Batch		<b>Route:</b> North Mobile Inspection Route			<b>Date:</b> 15/05/2025		
No actionable defects found								
<b>Batch:</b>	41226833 - Inspection Batch		<b>Route:</b> SfP_NorthWest			<b>Date:</b> 25/04/2025		
No actionable defects found								
<b>Batch:</b>	41226380 - Inspection Batch		<b>Route:</b> North Mobile Inspection Route			<b>Date:</b> 22/04/2025		
No actionable defects found								
<b>Batch:</b>	41224468 - Inspection Batch		<b>Route:</b> Mobile Inspection Strategic			<b>Date:</b> 30/03/2025		
No actionable defects found								
<b>Batch:</b>	41223802 - Inspection Batch		<b>Route:</b> Mobile Inspection Strategic			<b>Date:</b> 22/03/2025		
No actionable defects found								
<b>Batch:</b>	41223716 - Inspection Batch		<b>Route:</b> SfP_NorthWest			<b>Date:</b> 22/03/2025		
No actionable defects found								
<b>Batch:</b>	41223133 - Inspection Batch		<b>Route:</b> North Mobile Inspection Route			<b>Date:</b> 17/03/2025		
No actionable defects found								
<b>Batch:</b>	41222949 - Inspection Batch		<b>Route:</b> Mobile Inspection Strategic			<b>Date:</b> 16/03/2025		
No actionable defects found								
<b>Batch:</b>	41221413 - Inspection Batch		<b>Route:</b> Mobile Inspection Strategic			<b>Date:</b> 05/03/2025		
No actionable defects found								

Effective: 01/02/2025 to 31/05/2025

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Maybury Road (7900466)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 3 - Craigs Road to Glasgow Road		Feature Type: Road Asset		Area: North West Locality		
Batch: 41220681 - Inspection Batch				Route: Mobile Inspection Strategic		Date: 26/02/2025		
No actionable defects found								
Batch: 41220530 - Inspection Batch				Route: SfP_NorthWest		Date: 25/02/2025		
No actionable defects found								
Batch: 41219762 - Inspection Batch				Route: North Mobile Inspection Route		Date: 19/02/2025		
No actionable defects found								
Batch: 41219587 - Inspection Batch				Route: Mobile Inspection Strategic		Date: 19/02/2025		
No actionable defects found								
Batch: 41219044 - Inspection Batch				Route: Mobile Inspection Strategic		Date: 13/02/2025		
No actionable defects found								
Batch: 41217274 - Inspection Batch				Route: SfP_NorthWest		Date: 03/02/2025		
No actionable defects found								