

57152 Crosswood Avenue, Balerno

All records relating to the inspection on 21st June 2023 and 15th June 2022 in regards the 'open joint outside number 2'.

Please see the attached:

[42130286 20.06.2023](#)

[42103438 15.06.2022](#)

All records relating to repair/maintenance that was undertaken and completed on 30th January 2024 relating to the open joint noted above.

Please see the attached. These are duplicates as there are two records on the system.

[50115385 – 30.01.2024](#)

[50150192 – 30.01.2024](#)

In relation to the records you previously provided for Crosswood Crescent, Balerno:

All records, including photographs, relating to the inspection on 12th May 2022 regarding defect number 42101018 – carriageway potholes between 2 & 4.

Please see attached.

All records, including photographs relating to the repair/maintenance on 13th May 2022 – works order number ROAD/82063971.

[Records for 50113433 attached.](#)

All records, including photographs relating to the inspection on 12/07/22 regarding defect number 42104553 and 42104554.

Please see attached.

All records including photographs relating to the repair/maintenance on 12/07/22 – works order ROAD/82065510

[Records relating to Job 50116387 attached](#)

All records including photographs relating to the inspection on 20/06/23 regarding the broken/cracked carriageway outside number 1 & number 4 (job number 50137990). It states that this job was completed on 20/06/2024, however no works order has been noted.

[Defect 42130272 20.06.2023](#)

[Job 50137990 attached – this Job is not marked as completed on our system](#)