

57456 Status of Double Red Lines on Pilrig Street, Southwest of Pilrig Church

Please advise the legal enforcement status of the area marked with double red lines on your online atlas. I note that this particular data layer was last updated in 2021.

This section of road is covered by a written Traffic Regulation Order (as opposed to the map-based TRO that covers most parking controls), which was introduced during the implementation of the tram line on Leith Walk. The data layers shown on the Council's online Atlas may therefore not be correct at this location.

Please advise why this [the online atlas] is not continuously updated, subsequent to the successful completion of a TRO process to ensure decision making is always based on quality data.

The Council has recently transitioned to a new online GIS Atlas and Traffic Regulation Order mapping system and Application Programming Interfaces (APIs) to integrate the systems are still being configured.