

Site History Report

Effective: 01/01/2014 to 09/10/2025
Service: Roads General
Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Site: Saughton Mains Street (7903230)

Locality: Saughton, Edinburgh, City of Edinburgh

Area: South West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	South West Locality
Batch:	41232029 - Inspection Batch		Route:	Ad hoc Route			Date:	01/07/2025
42186309	5 potholes	01/07/2025	From royal engineers memorial home to number 79	RD: CW Pothole	Internal		Committed	50182157
Batch:	41229948 - Inspection Batch		Route:	Ad hoc Route			Date:	04/06/2025
42184979	Remove 5no pcc kerb and install 3no active travel sockets and bollards, infill with hra.	04/06/2025	At end of service rd at allotment entrance.	RD: Bollard Damage/Missing/Ne	Internal		Committed	50180878
Batch:	41218189 - Inspection Batch		Route:	SW_CF2_SaughtonEast1			Date:	10/02/2025
42175424	Cracked broken fw surface	10/02/2025	Outside school gates	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50097610
42175416	Broken cracked cw	10/02/2025	At junction with stenhouse street west	RD: CW Cracked/Broken	Internal		Uncommitted	50097602
42175408	Broken cracked cw	10/02/2025	At speed bump near number 79	RD: CW Cracked/Broken	Internal		Uncommitted	50097589
42175404	Broken cw.	10/02/2025	Near junction	RD: CW Cracked/Broken	Internal		Uncommitted	50128454
42175401	Cracked broken fw surface	10/02/2025	Outside number 81	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50097599
42175411	Broken cracked cw	10/02/2025	Outside number 14	RD: CW Cracked/Broken	Internal		Uncommitted	50097583
42175427	Cracked broken cw	10/02/2025	As marked	RD: CW Cracked/Broken	Internal		Uncommitted	50152980
42175425	1no pothole	10/02/2025	Outside school gates	RD: FW HRA Pothole	Internal		Committed	50174643
42175422	Cracked broken fw surface	10/02/2025	Near number 11	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50097604
42175448	Extensive patching required	10/02/2025	Entire length of cw is old and broken	RD: CW Cracked/Broken	Internal		Uncommitted	50128477
42175406	1no pothole	10/02/2025	At junction with Saughton mains Terrace	RD: CW Pothole	Internal		Committed	50174635
42175400	Cracked broken fw surface	10/02/2025	Outside number 83	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50097598
42175423	Cracked broken fw surface	10/02/2025	Outside number 9	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50097605
42175399	Damaged railings	10/02/2025	Between numbers 85 and 87	RD: Railing Damage/Missing/Ne	Internal		Uncommitted	50097597
42175410	Cracked broken cw	10/02/2025	Outside 16	RD: CW Cracked/Broken	Internal		Uncommitted	50152972
42175402	Broken cracked cw	10/02/2025	From outside 83 upto Junction with stenhouse drive	RD: CW Cracked/Broken	Internal		Uncommitted	50097596
42175418	6no potholes	10/02/2025	At junction with Saughton street west	RD: CW Pothole	Internal		Committed	50174640
42175405	Broken cracked cw	10/02/2025	At junction with saughton mains terrace	RD: CW Cracked/Broken	Internal		Uncommitted	50097592
Batch:	41218114 - Inspection Batch		Route:	Ad hoc Route			Date:	07/02/2025
42175354	Potholes	07/02/2025	Entrance of kerrs removals to other side of emg autos	RD: CW Pothole	Internal		Committed	50174589
Batch:	41218104 - Inspection Batch		Route:	Ad hoc Route			Date:	07/02/2025
42175353	Road: Defective / Damaged (Enquiry 1900337)	07/02/2025	Between bargain autos and kerrs removals	RD: CW Pothole	Internal		Committed	50174588
Batch:	41218103 - Inspection Batch		Route:	Ad hoc Route			Date:	07/02/2025
42175352	Potholes	07/02/2025	From bargain autos entrance to kerrs removals	RD: CW Pothole	Internal		Committed	50174587
Batch:	41218102 - Inspection Batch		Route:	Ad hoc Route			Date:	07/02/2025
42175351	Potholes	07/02/2025	Juncton to entrance of baigain autos	RD: CW Pothole	Internal		Committed	50174586

Site History Report

Effective: 01/01/2014 to 09/10/2025
Service: Roads General
Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South West Locality		
Batch: 41212084 - Inspection Batch			Route: Ad hoc Route				Date: 27/12/2024	
42171867	Manhole loose and noisy on cw	27/12/2024	Corstorphine bound lane in between rail RU: Utility Apparatus and tram bridges		Internal		Uncommitted	50171922
Batch: 41195494 - Inspection Batch			Route: Ad hoc Route				Date: 27/06/2024	
42160440	Gully choked	27/06/2024	Outside St Salvador's Church	Gully: Blocked / Flooding	Internal		Committed	50162975
Batch: 41182442 - Inspection Batch			Route: SW_CF2_SaughtonEast1				Date: 14/02/2024	
42147608	Cracked broken fw surface	14/02/2024	Outside number 81	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42147622	Pothole	14/02/2024	Outside church	RD: CW Pothole	Internal		Committed	50152974
42147637	Utility surround	14/02/2024	Outside 16	RD: FW HRA Pothole	Internal		Committed	50152983
42147603		14/02/2024		RD: CW Pothole	Internal		Archived	50135522
42147619	Broken cracked cw	14/02/2024	Outside number 14	RD: CW Cracked/Broken	Internal		No Action Required	
42147616	Broken cw.	14/02/2024		RD: CW Cracked/Broken	Internal		Archived	50128458
42147613	Broken cracked cw	14/02/2024	At junction with saughton mains terrace	RD: CW Cracked/Broken	Internal		No Action Required	
42147627	Pothole	14/02/2024	Outside school gates	RD: CW Pothole	Internal		Committed	50152976
42147634	Cracked broken cw	14/02/2024	As marked	RD: CW Cracked/Broken	Internal		No Action Required	
42147609		14/02/2024		RD: CW Cracked/Broken	Internal		Archived	50128453
42147607	Cracked broken fw surface	14/02/2024	Outside number 83	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42147631	Extensive patching required	14/02/2024	Entire length of cw is old and broken	RD: CW Cracked/Broken	Internal		No Action Required	
42147606	Pothole	14/02/2024	Outside 85	RD: CW Pothole	Internal		Committed	50152967
42147615	Broken cracked cw	14/02/2024	At speed bump near number 79	RD: CW Cracked/Broken	Internal		No Action Required	
42147605	Broken cracked cw	14/02/2024	From outside 83 upto Junction with stenhouse drive	RD: CW Cracked/Broken	Internal		No Action Required	
42147621	Jammed brander, replace	14/02/2024	At junction with street west	Gully: Brander Jammed	Internal		Committed	50152973
42147617	Pothole	14/02/2024	Outside 36	RD: CW Pothole	Internal		Committed	50152971
42147629		14/02/2024		RD: CW Cracked/Broken	Internal		Archived	50097586
42147628	Refresh markings	14/02/2024	Entire cw including all junctions	RD: Markings Refresh	Internal		Uncommitted	50097584
42147633	Pothole	14/02/2024	At lamppost 02	RD: CW Pothole	Internal		Committed	50152979
42147625	Cracked broken fw surface	14/02/2024	Outside number 9	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42147604	Damaged railings	14/02/2024	Between numbers 85 and 87	RD: Railing Damage/Missing/New	Internal		No Action Required	
42147626	Cracked broken fw surface	14/02/2024	Outside school gates	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42147610	Broken cw.	14/02/2024	Near junction	RD: CW Cracked/Broken	Internal		No Action Required	
42147620	Broken cracked cw	14/02/2024	At junction with stenhouse street west	RD: CW Cracked/Broken	Internal		No Action Required	
42147612	Pothole	14/02/2024	Near junction with mains terrace	RD: CW Pothole	Internal		Committed	50152969
42147623	Cracked broken fw surface	14/02/2024	Near number 11	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42147640	Extensive patching required	14/02/2024	Entire length of cw is old and broken	RD: CW Cracked/Broken	Internal		No Action Required	
42147618	Cracked broken cw	14/02/2024	Outside 16	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41178117 - Inspection Batch			Route: Ad hoc Route				Date: 10/01/2024	
42143691	10no potholes	10/01/2024	Between Bargain Autos and Kerr removals	RD: CW Pothole	Internal		Committed	50149844

Site History Report

Effective: 01/01/2014 to 09/10/2025
Service: Roads General
Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South West Locality	
Batch: 41178116 - Inspection Batch		Route: Ad hoc Route			Date: 10/01/2024			
42143690	10no potholes	10/01/2024	Outside Kerr removals gate	RD: CW Pothole	Internal		Committed	50149843
Batch: 41156566 - Inspection Batch		Route: Ad hoc Route			Date: 04/05/2023			
42126707	Road: Defective / Damaged (Enquiry 1546565)	04/05/2023	Road breaking up just before traffic lights	RD: CW Pothole	Internal		No Action Required	
Batch: 41154464 - Inspection Batch		Route: Ad hoc Route			Date: 11/04/2023			
42124945	Road: Defective / Damaged (Enquiry 1534729)	11/04/2023	C/way breaking up opp No 81	RD: CW Pothole	Internal		Committed	50133981
Batch: 41154000 - Inspection Batch		Route: Ad hoc Route			Date: 04/04/2023			
42124621	Parking: Disabled Bay refresh (Enquiry 34005917)	04/04/2023	o/s 66 Saughton Mains Street	RD: Markings Disabled Bay	Internal		Committed	50133667
Batch: 41152284 - Inspection Batch		Route: Ad hoc Route			Date: 15/03/2023			
42122548	signage for St Salvador's Church. The total cost for the 2no new directional signs installation for 'St. Salvador's Church' as requested is estimated at £1180.00 - traffic signs team to arrange for the new signs to be fabricated	15/03/2023	St Salvador's Church	RD: Unlit Sign Damaged/Missing	Internal		Committed	50132042
42122549		15/03/2023	001PK - St Salvador Church Directional Sign .. to be installed as per attached drawings at Stenhouse Drive - Saughton Mains Street. Signs in stock.	RD: Unlit Sign Damaged/Missing	Internal		Committed	50132041
Batch: 41151798 - Inspection Batch		Route: Ad hoc Route			Date: 09/03/2023			
42121858	Road: Defective / Damaged (Enquiry 1517628)	09/03/2023	Just before traffic lights	RD: CW Pothole	Internal		Committed	50131563
Batch: 41148054 - Inspection Batch		Route: SW_CF2_SaughtonEast1			Date: 06/02/2023			
42117474	Cracked broken fw surface	06/02/2023	Outside number 83	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42117510	Broken cracked cw	06/02/2023	Outside emg autos	RD: CW Cracked/Broken	Internal		Archived	50097635
42117476	Broken cw.	06/02/2023	Outside 81	RD: CW Cracked/Broken	Internal		No Action Required	
42117475	Cracked broken fw surface	06/02/2023	Outside number 81	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42117478	Pothole at manhole	06/02/2023	Near junction with Saughton mains terrace	RD: CW Pothole	Internal		Committed	50128455
42117508	Broken cracked cw	06/02/2023	Outside bargain autos	RD: CW Cracked/Broken	Internal		Archived	50097628
42117507	Broken cracked cw	06/02/2023	Outside bargain autos	RD: CW Cracked/Broken	Internal		Archived	50097625
42117488		06/02/2023		RD: FW HRA Cracked/Broken	Internal		Archived	50097603
42117482		06/02/2023		RD: FW HRA Cracked/Broken	Internal		Archived	50097590
42117469	Damaged railings	06/02/2023	Between numbers 85 and 87	RD: Railing Damage/Missing/Ne	Internal		No Action Required	
42117513	Broken cracked cw	06/02/2023	As ma	RD: CW Cracked/Broken	Internal		Archived	50097639
42117511	Broken cracked cw	06/02/2023	Outside emg	RD: CW Cracked/Broken	Internal		Archived	50097637
42117516	Pothole . Overlay required	06/02/2023	Outside bargain autos	RD: CW Pothole	Internal		Committed	50128475
42117497	Broken cracked cw	06/02/2023	On bend	RD: CW Cracked/Broken	Internal		Archived	50097608

Site History Report

Effective: 01/01/2014 to 09/10/2025
Service: Roads General
Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	South West Locality
Batch:	41148054 - Inspection Batch		Route:	SW_CF2_SaughtonEast1			Date:	06/02/2023
42117485	Broken cracked cw	06/02/2023	Outside number 14	RD: CW Cracked/Broken	Internal		No Action Required	
42117514	Pothole	06/02/2023	As marked	RD: CW Pothole	Internal		Committed	50128473
42117499	Missing bollard	06/02/2023	Opposite school	RD: Bollard Damage/Missing/Nev	Internal		Committed	50128464
42117483	Broken cracked cw	06/02/2023	At speed bump near number 79	RD: CW Cracked/Broken	Internal		No Action Required	
42117518	Extensive patching required	06/02/2023	Entire length of cw is old and broken	RD: CW Cracked/Broken	Internal		No Action Required	
42117517	Pothole	06/02/2023	Outside bargain autos	RD: CW Pothole	Internal		Committed	50128476
42117480	Broken cracked cw	06/02/2023	At junction with saughton mains terrace	RD: CW Cracked/Broken	Internal		No Action Required	
42117496	Missing bollard, trip hazard,	06/02/2023	Adjacent to school	RD: Bollard Damage/Missing/Nev	Internal		No Action Required	
42117492	Refresh markings	06/02/2023	Entire cw including all junctions	RD: Markings Refresh	Internal		No Action Required	
42117484	Broken cw.	06/02/2023	Outside 36	RD: CW Cracked/Broken	Internal		No Action Required	
42117489	Cracked broken fw surface	06/02/2023	Near number 11	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42117477	Broken cw.	06/02/2023	Near junction	RD: CW Cracked/Broken	Internal		No Action Required	
42117502	Pothole	06/02/2023	At junction	RD: FW HRA Pothole	Internal		Committed	50128468
42117512	Broken cracked cw	06/02/2023	Near stairs to tram crossing	RD: CW Cracked/Broken	Internal		Archived	50097638
42117491	Cracked broken fw surface	06/02/2023	Outside school gates	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42117472	Broken cracked cw	06/02/2023	Junction with stenhouse drive	RD: CW Cracked/Broken	Internal		No Action Required	
42117509	Broken cracked cw	06/02/2023	Outside emg autos	RD: CW Cracked/Broken	Internal		Archived	50097634
42117486	Broken cracked cw	06/02/2023	At junction with stenhouse street west	RD: CW Cracked/Broken	Internal		No Action Required	
42117494	Cracked broken fw surface	06/02/2023	On corner	RD: FW HRA Cracked/Broken	Internal		Archived	50097606
42117490	Cracked broken fw surface	06/02/2023	Outside number 9	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42117471	Pothole	06/02/2023	At junction	RD: CW Pothole	Internal		Committed	50128451
42117498	Missing bollard, trip hazard,	06/02/2023	Adjacent to school	RD: Bollard Damage/Missing/Nev	Internal		Committed	50128463
Batch:	41107752 - Inspection Batch		Route:	SW_CF2_SaughtonEast1			Date:	17/11/2021
42084274	Broken cracked cw	17/11/2021	Outside number 14	RD: CW Cracked/Broken	Internal		No Action Required	
42084284	Cracked broken fw surface	17/11/2021	Adjacent to saughton mains terrace ju	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42084306	Cracked broken fw surface	17/11/2021	Near number 11	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42084374	Broken cracked cw	17/11/2021	Near stairs to tram crossing	RD: CW Cracked/Broken	Internal		No Action Required	
42084370	Broken cracked cw	17/11/2021	Outside emg autos	RD: CW Cracked/Broken	Internal		No Action Required	
42084361	Pothole	17/11/2021	Outside bargain autos	RD: CW Pothole	Internal		Committed	50097626
42084286	Broken cracked cw	17/11/2021	At junction with saughton mains terrace	RD: CW Cracked/Broken	Internal		No Action Required	
42084293	Pothole	17/11/2021	Outside number 79	RD: CW Pothole	Internal		Committed	50097594
42084320	Cracked broken fw surface	17/11/2021	Outside school gates	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42084319	Sharp jagged edge of base of pole. Please make safe	17/11/2021	Right outside school	RD: Other Defect Type	Internal		Committed	50097609
42084313	Broken cracked cw	17/11/2021	On bend	RD: CW Cracked/Broken	Internal		No Action Required	
42084298	Damaged railings	17/11/2021	Between numbers 85 and 87	RD: Railing Damage/Missing/Nev	Internal		No Action Required	
42084304	Broken cracked cw	17/11/2021	At junction with stenhouse street west	RD: CW Cracked/Broken	Internal		No Action Required	
42084277	Refresh markings	17/11/2021	Entire cw including all junctions	RD: Markings Refresh	Internal		No Action Required	
42084375	Broken cracked cw	17/11/2021	As ma	RD: CW Cracked/Broken	Internal		No Action Required	
42084302	Cracked broken fw surface	17/11/2021	Outside number 81	RD: FW HRA Cracked/Broken	Internal		No Action Required	

Site History Report

Effective: 01/01/2014 to 09/10/2025
Service: Roads General
Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South West Locality		
Batch: 41107752 - Inspection Batch		Route: SW_CF2_SaughtonEast1				Date: 17/11/2021		
42084308	Cracked broken fw surface	17/11/2021	On corner	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42084301	Cracked broken fw surface	17/11/2021	Outside number 83	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42084305	Cracked broken fw surface	17/11/2021	Outside number 13	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42084372	Broken cracked cw	17/11/2021	Outside emg	RD: CW Cracked/Broken	Internal		No Action Required	
42084367	Pothole	17/11/2021	Outside bar	RD: CW Pothole	Internal		Committed	50097632
42084365	Pothole	17/11/2021	Outside bargain autos	RD: CW Pothole	Internal		Committed	50097630
42084322	low kerb at dropped crossing	09/05/2016	at Stenhouse Primary School earlier, at the Nursery Entrance on Saughton Mains Street	RD: FW HRA Cracked/Broken	Internal		Archived	4007529
42084323	Damaged plastic bollard on f / way.	17/11/2021	Saughton Mains Street at junction with Stenhouse Street West.	RD: FW Grano Cracked/Broken	Internal		Archived	4007530
42084296	Broken cracked cw	17/11/2021	Junction with stenhouse drive	RD: CW Cracked/Broken	Internal		No Action Required	
42084360	Broken cracked cw	17/11/2021	Outside bargain autos	RD: CW Cracked/Broken	Internal		No Action Required	
42084279	Broken cracked cw	17/11/2021	Outside number 36	RD: CW Cracked/Broken	Internal		No Action Required	
42084369	Broken cracked cw	17/11/2021	Outside emg autos	RD: CW Cracked/Broken	Internal		No Action Required	
42084368	Pothole	17/11/2021	Outside amg autos	RD: CW Pothole	Internal		Committed	50097633
42084307	Cracked broken fw surface	17/11/2021	Outside number 9	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42084282	Broken cracked cw	17/11/2021	At speed bump near number 79	RD: CW Cracked/Broken	Internal		No Action Required	
42084364	Broken cracked cw	17/11/2021	Outside bargain autos	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41092355 - Inspection Batch		Route: Ad hoc Route				Date: 13/05/2021		
42068906	Potholes	13/05/2021	From Bargin Autos to EMG autos	RD: CW Pothole	Internal		Committed	50083021
Batch: 41092354 - Inspection Batch		Route: Ad hoc Route				Date: 13/05/2021		
42068904	Potholes(Enquiry 1167711)	13/05/2021	From junction to Bargain Autos	RD: CW Pothole	Internal		Committed	50083020
Batch: 41091699 - Inspection Batch		Route: Ad hoc Route				Date: 05/05/2021		
42068229	Potholes	05/05/2021	At junction with Saughton Mains Terrace	RD: CW Pothole	Internal		Committed	50082348
Batch: 41091695 - Inspection Batch		Route: Ad hoc Route				Date: 05/05/2021		
42068225	Potholes(Enquiry 1170177)	05/05/2021	Just before traffic lights.	RD: CW Pothole	Internal		Committed	50082345
Batch: 41065731 - Inspection Batch		Route: Ad hoc Route				Date: 06/10/2020		
42054062	Pavement: Damaged / Defective (Enquiry 1029310)make safe footway	06/10/2020	Pole sticking out of pavement (see photo)outside 14	RD: FW HRA Pothole	Internal		Committed	50064129
Batch: 41060887 - Inspection Batch		Route: SW_CF2_SaughtonEast1				Date: 30/07/2020		
No actionable defects found								
Batch: 41059011 - Inspection Batch		Route: Ad hoc Route				Date: 22/06/2020		
42050928	Open joint	22/06/2020	Opp Stenhouse street west jct	RD: CW Open Joint	Internal		Committed	50056968
Batch: 41059010 - Inspection Batch		Route: Ad hoc Route				Date: 22/06/2020		
42050927	Potholes	22/06/2020	At jct with Stenhouse street west	RD: FW HRA Pothole	Internal		Committed	50056967

Site History Report

Effective: 01/01/2014 to 09/10/2025
Service: Roads General
Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South West Locality		
Batch: 41059009 - Inspection Batch				Route: Ad hoc Route		Date: 22/06/2020		
42050926	Potholes	22/06/2020	At jct into classroom cafe	RD: CW Pothole	Internal		Committed	50056966
Batch: 41055249 - Inspection Batch				Route: Ad hoc Route		Date: 11/03/2020		
42048661	Potholes	11/03/2020	Os 81	RD: CW Pothole	Internal		Committed	50054512
Batch: 41055248 - Inspection Batch				Route: Ad hoc Route		Date: 11/03/2020		
42048660	Pothole	11/03/2020	Opp jct with saughton mains terrace	RD: CW Pothole	Internal		Committed	50054511
Batch: 41054363 - Inspection Batch				Route: Ad hoc Route		Date: 29/02/2020		
42047961	Pothole	29/02/2020	At jct	RD: CW Pothole	Internal		Committed	50053769
Batch: 41054206 - Inspection Batch				Route: Ad hoc Route		Date: 27/02/2020		
42047765	Potholes	27/02/2020	Os 14	RD: CW Pothole	Internal		Committed	50053574
Batch: 41028127 - Inspection Batch				Route: Ad hoc Route		Date: 26/02/2019		
42026947	2 Ph's	26/02/2019	Outside no 79 & no 77	RD: CW Pothole	Internal		Committed	50027113
Batch: 41027678 - Inspection Batch				Route: Ad hoc Route		Date: 20/02/2019		
42026607	Refresh junction markings and anti skid	20/02/2019	At jct with Stenhouse drive	RD: Markings Refresh	Internal		Archived	50026618
Batch: 41025651 - Inspection Batch				Route: SW_CF2_SaughtonEast1		Date: 16/01/2019		
42024688	Various locations for p / holes. As discussed with team leader on site.	16/01/2019	Throughout street	RD: CW Pothole	Internal		Committed	50023561
Batch: 41012520 - Inspection Batch				Route: Ad hoc Route		Date: 29/05/2018		
42012282	Road: Defective / Damaged (Enquiry 664018) 10 p / holes	29/05/2018	Potholes Saughton mains street outside car dealers.. Saughton Mains Street outside entry to Bargain Auto's garages.	RD: CW Pothole	Internal		Committed	50010664
Batch: 41005638 - Inspection Batch				Route: Ad hoc Route		Date: 12/03/2018		
42005277	3 P / hole	12/03/2018	Between no 85 & no 87 on approach to t/ lights.	RD: CW Pothole	Internal		Committed	50004700
Batch: 24011715 - Inspection Batch				Route: SW_CF2_SaughtonEast1		Date: 03/09/2017		
No actionable defects found								
Batch: 24011430 - Inspection Batch				Route: RD: Ad-Hoc Inspection SW		Date: 14/08/2017		
24012039	Road: Defective / Damaged (Enquiry 535394) 5 ph's in c / way	14/08/2017	Saughton mains street. Outside car repair site near entrance to Bargain autos	RD: CLARENCE Response	Internal		Archived	4012033
Batch: 24009505 - Inspection Batch				Route: RD: Ad-Hoc Inspection SW		Date: 07/02/2017		
24010564	Pavement: Damaged / Defective - see above report (Enquiry 465332) red & white barrier on f / way.	07/02/2017	Saughton Mains Street opposite Saughton Mains Terrace.	RD: CLARENCE Response	Internal		Archived	4010558
Batch: 24006813 - Inspection Batch				Route: SW_CF2_SaughtonEast1		Date: 10/05/2016		
24007543	10 phs	09/05/2016	Between l / post no 4 & l / post no 3	RD: CLARENCE Response	Internal		Archived	4007534
24007541	Ph	09/05/2016	At l / post no 8	RD: CLARENCE Response	Internal		Archived	4007532

Site History Report

Effective: 01/01/2014 to 09/10/2025
Service: Roads General
Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South West Locality	
Batch: 24006813 - Inspection Batch		Route: SW_CF2_SaughtonEast1			Date: 10/05/2016			
24007544	22 phs	09/05/2016	Between l / post no 3 & l / post no 2	RD: CLARENCE Response	Internal		Archived	4007535
24007545	7 phs	09/05/2016	Between l / post no 1 & l / post no 2	RD: CLARENCE Response	Internal		Archived	4007536
24007542	6 ph's	09/05/2016	Between l / post no 4 & l / post no 5	RD: CLARENCE Response	Internal		Archived	4007533
24007540	Ph	09/05/2016	At l / post no 8 on blister.	RD: CLARENCE Response	Internal		Archived	4007531
Batch: 24006812 - Inspection Batch		Route: RD: Ad-Hoc Inspection SW			Date: 09/05/2016			
24007539	Damaged plastic bollard on f / way.	09/05/2016	Saughton Mains Street at junction with Stenhouse Street West.	RD: Street Furniture	Internal		No Action Required	
Batch: 24006811 - Inspection Batch		Route: RD: Ad-Hoc Inspection SW			Date: 09/05/2016			
24007538	Road: Defective / Damaged - Good afternoon, Councillor Fullerton was at Stenhouse Primary School earlier, at the Nursery Entrance on Saughton Mains Street, and a [REDACTED] in a wheelchair got stuck trying to get up the dropped kerb and [REDACTED] said it had happened before. Could one of the Roads Inspectors have a look at it when they have an opportunity please to see what the issue is? Many thanks [REDACTED] [REDACTED] Assistant to Councillor Catherine Fullerton (Enquiry 30106005) low kerb at dropped crossing to be resett and area of f / way to be renewed.	09/05/2016	at Stenhouse Primary School earlier, at the Nursery Entrance on Saughton Mains Street	RD: Asphalt / Bitmac Surface	Internal		No Action Required	
Batch: 24006626 - Inspection Batch		Route: RD: Ad-Hoc Inspection SW			Date: 28/04/2016			
24007406	Make safe along the channel and 2 c/w p/h	28/04/2016	Opp 13 at the junction	RD: CLARENCE Response	Internal		Archived	4007397
Batch: 24006543 - Inspection Batch		Route: RD: Ad-Hoc Inspection SW			Date: 21/04/2016			
24007205	7 ph's	21/04/2016	Between no 85 and no 87	RD: CLARENCE Response	Internal		Archived	4007211
Batch: 24006542 - Inspection Batch		Route: RD: Ad-Hoc Inspection SW			Date: 21/04/2016			
24007204	6 ph's	21/04/2016	Between no 81 and junction with Saughton Mains Terrace.	RD: CLARENCE Response	Internal		Archived	4007210
Batch: 24005563 - Inspection Batch		Route: RD: Ad-Hoc Inspection SW			Date: 21/02/2016			
24006196	4 ph's	21/02/2016	Opposite no 87 near t / lights.	RD: CLARENCE Response	Internal		Archived	4006197
Batch: 24005562 - Inspection Batch		Route: RD: Ad-Hoc Inspection SW			Date: 21/02/2016			
24006195	2 ph's	21/02/2016	Outside no 76	RD: CLARENCE Response	Internal		Archived	4006196

Site History Report

Effective: 01/01/2014 to 09/10/2025

Service: Roads General

Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South West Locality	
Batch: 24005420 - Inspection Batch		Route: RD: Ad-Hoc Inspection SW				Date: 12/02/2016		
24006062	Street Furniture: Defective - missing plastic bollards (Enquiry 310941) 3 x mid steel bollards and 1 plastic glasdon bollard missing.	12/02/2016	opposite stenhouse primary school	RD: Street Furniture	Internal		Archived	4006062
Batch: 24004732 - Inspection Batch		Route: RD: Ad-Hoc Inspection SW				Date: 14/01/2016		
24005291	Ph in channel.	14/01/2016	under the bridge Saughton Mains Street. Approximately 50mtrs from junction with Saughton Road at bargain autos poster.	RD: CLARENCE Response	Internal		Archived	4005288
Batch: 24004442 - Inspection Batch		Route: RD: Ad-Hoc Inspection SW				Date: 21/12/2015		
24005050	2 ph's	21/12/2015	At junction with Saughton Mains Terrace	RD: CLARENCE Response	Internal		Archived	4005047
Batch: 24004441 - Inspection Batch		Route: RD: Ad-Hoc Inspection SW				Date: 21/12/2015		
24005049	Ph	21/12/2015	Between no 81 Saughton Mains Street and junction with Saughton Mains Terrace near m / hole.	RD: CLARENCE Response	Internal		Archived	4005046
Batch: 24004440 - Inspection Batch		Route: RD: Ad-Hoc Inspection SW				Date: 21/12/2015		
24005048		21/12/2015		RD: CLARENCE Response	Internal		Archived	4005045
Batch: 24003752 - Inspection Batch		Route: RD: Ad-Hoc Inspection SW				Date: 05/11/2015		
24004454	2 ph's in c / way	05/11/2015	Outside no 8 and opposite no 8 Saughton Mains Street.	RD: CLARENCE Response	Internal		Archived	4004450
Batch: 24002685 - Inspection Batch		Route: RD: Ad-Hoc Inspection SW				Date: 23/06/2015		
24002693	20 phs all marked on site	23/06/2015	Between auto bargains premises and EGG Autos premises.	RD: CLARENCE Response	Internal		Archived	4002687
Batch: 24002614 - Inspection Batch		Route: RD: Ad-Hoc Inspection SW				Date: 04/06/2015		
24002622	4 ph's	04/06/2015	O/s no 87	RD: CLARENCE Response	Internal		Archived	4002616
Batch: 18600761 - SW_CF2_SaughtonEast1 No actionable defects found		Route: SW_CF2_SaughtonEast1				Date: 13/06/2014		

Site History Report

Effective: 01/01/2014 to 09/10/2025
Service: Roads General
Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: South West Locality		
42705639	Gully: Flooding - on the corner outside the church is blocked and flooding called over was reported on the 22 july. Passed to [REDACTED] 9:30am ([REDACTED]). (Enquiry 867821)	on the corner outside the church is blocked and flooding called over was reported on the 22 july	RG: Gully - High Priority	Job Complete	01/08/2019	03/08/2019	Act. RDGC14/10004617
50023561	Various locations for p / holes. As discussed with team leader on site. (RD: CW Pothole)	Throughout street	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/01/2019	08/02/2019	Act. ROAD/82016583
50027113	2 Ph's (RD: CW Pothole)	Outside no 79 & no 77	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/02/2019	11/03/2019	Act. ROAD/82018170
50053574	Potholes (RD: CW Pothole)	Os 14	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/02/2020	09/06/2020	Act. ROAD/82034062
50053769	Pothole (RD: CW Pothole)	At jct	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	29/02/2020	13/03/2020	Act. ROAD/82034246
50054511	Pothole (RD: CW Pothole)	Opp jct with saughton mains terrace	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/03/2020	09/06/2020	Act. ROAD/82034861
50054512	Potholes (RD: CW Pothole)	Os 81	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	11/03/2020	17/03/2020	Act. ROAD/82034862
50056966	Potholes (RD: CW Pothole)	At jct into glassroom cafe	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	22/06/2020	23/06/2020	Act. ROAD/82036780
50056967	Potholes (RD: FW HRA Pothole)	At jct with Stenhouse street west	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/06/2020	23/06/2020	Act. ROAD/82036781
50056968	Open joint (RD: CW Open Joint)	Opp Stenhouse street west jct	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/06/2020	23/06/2020	Act. ROAD/82036782
50064129	Pavement: Damaged / Defective (Enquiry 1029310)make safe footway (RD: FW HRA Pothole)	Pole sticking out of pavement (see photo)outside 14	RD: Cat 2 - 5 Day	Job Complete	06/10/2020	06/10/2020	Act. ROAD/82040018
50082345	Potholes(Enquiry 1170177) (RD: CW Pothole)	Just before traffic lights.	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	05/05/2021	06/05/2021	Act. ROAD/82049271
50082348	Potholes (RD: CW Pothole)	At junction with Saughton Mains Terrace	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/05/2021	07/05/2021	Act. ROAD/82049274
50083020	Potholes(Enquiry 1167711) (RD: CW Pothole)	From junction to Bargain Autos	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/05/2021	18/05/2021	Act. ROAD/82049667

Site History Report

Effective: 01/01/2014 to 09/10/2025
Service: Roads General
Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: South West Locality		
50083021	Potholes (RD: CW Pothole)	From Bargin Autos to EMG autos	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/05/2021	18/05/2021	Act. ROAD/82049668
50097594	Pothole (RD: CW Pothole)	Outside number 79	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/11/2021	19/11/2021	Act. ROAD/82056486
50097609	Sharp jagged edge of base of pole. Please make safe (RD: Other Defect Type)	Right outside school	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/11/2021	18/11/2021	Act. ROAD/82056489
50097626	Pothole (RD: CW Pothole)	Outside bargain autos	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/11/2021	19/11/2021	Act. ROAD/82056497
50097630	Pothole (RD: CW Pothole)	Outside bargain autos	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/11/2021	19/11/2021	Act. ROAD/82056499
50097632	Pothole (RD: CW Pothole)	Outside bar	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/11/2021	19/11/2021	Act. ROAD/82056501
50097633	Pothole (RD: CW Pothole)	Outside amg autos	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/11/2021	19/11/2021	Act. ROAD/82056502
50104273	please refresh all white junction and centre markings after recent RTA	At Stenhouse Street West	Non Routine (One Off Works)	Job Complete	26/01/2022	27/01/2022	Act. ROAD/82059328
50128451	Pothole (RD: CW Pothole)	At junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2023	08/02/2023	Act. ROAD/82072347
50128455	Pothole at manhole (RD: CW Pothole)	Near junction with Saughton mains terrace	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2023	08/02/2023	Act. ROAD/82072348
50128463	Missing bollard, trip hazard, (RD: Bollard Damage/Missing/New)	Adjacent to school	RD: Cat 3 - 60 Day	Job Complete	06/02/2023	07/02/2023	Act. ROAD/82072352
50128464	Missing bollard (RD: Bollard Damage/Missing/New)	Opposite school	RD: Cat 3 - 60 Day	Job Complete	06/02/2023	14/04/2023	Act. ROAD/82072353
50128468	Pothole (RD: FW HRA Pothole)	At junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2023	08/02/2023	Act. ROAD/82072354
50128473	Pothole (RD: CW Pothole)	As marked	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2023	08/02/2023	Act. ROAD/82072359
50128475	Pothole . Overlay required (RD: CW Pothole)	Outside bargain autos	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2023	08/02/2023	Act. ROAD/82072361
50128476	Pothole (RD: CW Pothole)	Outside bargain autos	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2023	08/02/2023	Act. ROAD/82072362
50131563	Road: Defective / Damaged (Enquiry 1517628) (RD: CW Pothole)	Just before traffic lights	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/03/2023	09/03/2023	Act. ROAD/82074071

Site History Report

Effective: 01/01/2014 to 09/10/2025
 Service: Roads General
 Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South West Locality	
50132041	Signs: Defective / Damaged -	001PK - St Salvador Church	RD: Cat 3 - 60 Day	Job Complete	15/03/2023	16/03/2023	Act. ROAD/82074324

Directional Sign .. to be installed
 as per attached drawings at
 Stenhouse Drive - Saughton
 Mains Street. Signs in stock.

Date: Tuesday, July 5, 2022 at
 5:00:17 PM

To:

@edinburgh.gov.uk

@edinburgh.c

@edinburgh.gov.uk:

@edinburgh.gov.uk:

Traffic Signs

<TrafficSigns@edinburgh.gov.uk>

Customer Care

<Customer.Care@edinburgh.gov.

Subject: RE: from
 re signage for St Salvador's
 Church

Afternoon

Thank you for the update and
 confirmation you would like us to
 go ahead with the work as
 requested as per the attached
 document.

The total cost for the 2no new
 directional signs installation for
 'St. Salvador's Church' as
 requested is estimated at
 £1180.00

I will liaise with the team in order
 that the signs are fabricated and

Site History Report

Effective: 01/01/2014 to 09/10/2025
Service: Roads General
Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
---------	-------------	----------	----------	------------	---------	------------	-------------

the work is scheduled to be carried out on site when the Traffic Signs Squad become free from current commitments.

You will not be invoiced until after the works are completed.

Apologies if you have provided this information before, please can you clarify the name of the person the invoice should be made out to and what address it should be sent thanks.

Should you wish to discuss any of the above further please do not hesitate to contact me thanks

Afternoon Customer Care

Please log on confirm against the Traffic Signs Team Project Bank 'SNPB' for the traffic signs team to arrange for the new signs to be fabricated and that the works are scheduled in due course thanks.

Regards



Senior Engineer, Traffic Signs
(Existing permanent road sign

Site History Report

Effective: 01/01/2014 to 09/10/2025
Service: Roads General
Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Street Lighting and Traffic Signs Place City of Edinburgh Council Bankhead Depot 14 Bankhead Avenue, Edinburgh EH11 4HD Tel email : @edinburgh. (Enquiry 1402710) (RD: Unlit Sign Damaged/Missing)						

Site History Report

Effective: 01/01/2014 to 09/10/2025
 Service: Roads General
 Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South West Locality	
50132042	Signs: Defective / Damaged - From: [REDACTED] @edinburgh.gov.uk Date: Tuesday, July 5, 2022 at 5:00:17 PM To: [REDACTED] [REDACTED] > [REDACTED] @edinburgh.gov.uk [REDACTED] @edinburgh.g [REDACTED] @edinburgh.gov.uk [REDACTED] @edinburgh.gov.uk Traffic Signs <TrafficSigns@edinburgh.gov.uk> Customer Care <Customer.Care@edinburgh.gov. Subject: RE: from Andrew Bain re signage for St Salvador's Church	St Salvador's Church	RD: Cat 3 - 60 Day	Job Complete	15/03/2023	16/03/2023	Act. ROAD/82074324

Afternoon [REDACTED]
 [REDACTED]

Thank you for the update and
 confirmation you would like us to
 go ahead with the work as
 requested as per the attached
 document.

The total cost for the 2no new
 directional signs installation for
 'St. Salvador's Church' as
 requested is estimated at
 £1180.00

I will liaise with the team in order
 that the signs are fabricated and

Site History Report

Effective: 01/01/2014 to 09/10/2025
Service: Roads General
Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
---------	-------------	----------	----------	------------	---------	------------	-------------

the work is scheduled to be carried out on site when the Traffic Signs Squad become free from current commitments.

You will not be invoiced until after the works are completed.

Apologies if you have provided this information before, please can you clarify the name of the person the invoice should be made out to and what address it should be sent thanks.

Should you wish to discuss any of the above further please do not hesitate to contact me thanks

Afternoon Customer Care

Please log on confirm against the Traffic Signs Team Project Bank 'SNPB' for the traffic signs team to arrange for the new signs to be fabricated and that the works are scheduled in due course thanks.

Regards



Senior Engineer, Traffic Signs
(Existing permanent road sign

Site History Report

Effective: 01/01/2014 to 09/10/2025
Service: Roads General
Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Street Lighting and Traffic Signs Place City of Edinburgh Council Bankhead Depot 14 Bankhead Avenue, Edinburgh EH11 4HD Tel: [REDACTED] email: [REDACTED] [REDACTED]@edinburgh. (Enquiry 14002740) / PO: 11611						
50133667	Parking: Disabled Bay refresh (Enquiry 34005917) (RD: Markings Disabled Bay)	o/s 66 Saughton Mains Street	Parking Operations	Job Complete	04/04/2023	06/04/2023	Act. ROAD/82075309
50133981	Road: Defective / Damaged (Enquiry 1534729) (RD: CW Pothole)	C/way breaking up opp No 81	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/04/2023	11/04/2023	Act. ROAD/82075564
50149843	10no potholes (RD: CW Pothole)	Outside Kerr removals gate	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/01/2024	15/01/2024	Act. ROAD/82085204
50149844	10no potholes (RD: CW Pothole)	Between Bargain Autos and Kerr removals	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/01/2024	12/01/2024	Act. ROAD/82085205
50152967	Pothole (RD: CW Pothole)	Outside 85	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2024	18/02/2024	Act. ROAD/82087390
50152969	Pothole (RD: CW Pothole)	Near junction with mains terrace	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2024	18/02/2024	Act. ROAD/82087392
50152971	Pothole (RD: CW Pothole)	Outside 36	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2024	18/02/2024	Act. ROAD/82087394
50152973	Jammed brander, replace (Gully: Brander Jammed)	At junction with street west	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2024	17/02/2024	Act. ROAD/82087395
50152974	Pothole (RD: CW Pothole)	Outside church	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2024	18/02/2024	Act. ROAD/82087396
50152976	Pothole (RD: CW Pothole)	Outside school gates	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2024	18/02/2024	Act. ROAD/82087397
50152979	Pothole (RD: CW Pothole)	At lamppost 02	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2024	18/02/2024	Act. ROAD/82087400
50152983	Utility surround (RD: FW HRA Pothole)	Outside 16	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2024	18/02/2024	Act. ROAD/82087402
50162975	Gully choked (Gully: Blocked / Flooding)	Outside St Salvador's Church	RG: Gully - Standard Priority	Cleaned and Working	27/06/2024	27/09/2024	Est. RDGC14/82006579
50174586	Potholes (RD: CW Pothole)	Juncton to entrance of baigain autos	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/02/2025	10/02/2025	Act. ROAD/82102071
50174587	Potholes (RD: CW Pothole)	From bargain autos entrance to kerrs removals	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/02/2025	10/02/2025	Act. ROAD/82102072
50174588	Road: Defective / Damaged (Enquiry 1900337) (RD: CW Pothole)	Between bargain autos and kerrs removals	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	07/02/2025	10/02/2025	Act. ROAD/82102073
50174589	Potholes (RD: CW Pothole)	Entrance of kerrs removals to other side of emg autos	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/02/2025	10/02/2025	Act. ROAD/82102074
50174635	1no pothole (RD: CW Pothole)	At junction with Saughton mains Terrace	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/02/2025	10/02/2025	Act. ROAD/82102118

Site History Report

Effective: 01/01/2014 to 09/10/2025

Service: Roads General

Site: Saughton Mains Street (7903230)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South West Locality	
50174640	6no potholes (RD: CW Pothole)	At junction with Saughton street west	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/02/2025	10/02/2025	Act. ROAD/82102123
50174643	1no pothole (RD: FW HRA Pothole)	Outside school gates	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/02/2025	11/02/2025	Act. ROAD/82102125
50180878	Remove 5no pcc kerb and install 3no active travel sockets and bollards, infill with hra. (RD: Bollard Damage/Missing/New)	At end of service rd at allotment entrance.	RD: Cat 3 - 60 Day	Job Complete	04/06/2025	28/07/2025	Act. ROAD/82106657
50182157	5 potholes (RD: CW Pothole)	From royal engineers memorial home to number 79	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/07/2025	02/07/2025	Act. ROAD/82107426