

58455 Damaged Drain Cover

When the drain cover outside Tesco at Haymarket (by Magdala Cres) was first reported broken/damaged?

16/09/2025

List dates/number of times it has been reported broken.

16/09/2025/once as medium risk to be repaired within one month period.

When the broken cover was passed from Council to utility responsible for repair and dates of this being followed up.

16/09/2025, initially remedial works were planned on 29/09/2025 to be done between 30/10/2025 to 3/11/2025 and then on 31/10/2025 has been re-proposed for 11-14 January 2026.

What utility firm is responsible for the repair?

Scottish Water

When do fines kick in for non-compliance in completing repair and when this was communicated to utility responsible?

This information is not held. A fine is not applicable for non-compliance.