

Defect list

Site: Cleekim Drive (7902352)

Asset Number: (1.00)

Logged Date: 01/01/2021 to 23/12/2025

Defect No.	Defect Type	Description / Location	Logged	Officer	Organisation/Priority	Status	Notes
Site: Cleekim Drive (7902352), Newcraighall, Edinburgh, City of Edinburgh				Area: North East Locality (NEL)			
Asset No : 1.00	Asst / Location :	Whole Street (Road Asset)					
42084085	RD: CW Pothole	1 number pothole - At junction of Cleekim Road	16/11/2021	BRFO	RD: Cat 3 - 60 Day	Job 50097430-RD: Made Safe Job Complete	Imported Defect via Connector
42085936	RD: FW Kerbs Damaged/Missing	Damaged kerb - O/S no 12	02/12/2021	SCCA	RD: Cat 4 - Programmed	Job 50099198-Job Complete	Imported Defect via Connector
42085939	RD: FW HRA Cracked/Broken	Footway cracked- broken - O/S no 27-25	02/12/2021	SCCA	RD: Cat 4 - Programmed	No Action Required	Imported Defect via Connector
42085944	RD: FW HRA Cracked/Broken	Footway cracked- broken 4m x 2m - On corner at no 2/1	02/12/2021	SCCA	RD: Cat 4 - Programmed	No Action Required	Imported Defect via Connector
42106969	RD: Markings Refresh	Refresh slow marking - Outside number 11	07/09/2022	BRFO	RD: Cat 4 - Programmed	No Action Required	Imported Defect via Connector
42106973	RD: Markings Refresh	Refresh give way markings - Outside number 59	07/09/2022	BRFO	RD: Cat 4 - Programmed	No Action Required	Imported Defect via Connector
42107858	RD: Unlit Sign Damaged/Missing	Please install new signs 546 children going to school and 547.1 . Collect signs from stores - Outside 9 Cleekim Drive	07/10/2022	LARU	RD: Cat 3 - 60 Day	Job 50119579-Job Complete	Imported Defect via Connector
42113936	RD: CW Pothole	1 number pothole - Outside number 2	30/12/2022	BRFO	RD: Cat 3 - 60 Day	Job 50125084-RD: Made Safe Job Complete	Imported Defect via Connector
42122057	RU: Utility Apparatus	Rocking P.O manhole - Outside 15	11/03/2023	MIDO	RU: Fail Low Risk	Job 50131677-Job Complete	Imported Defect via Connector
42122058	RD: Markings Refresh	Refresh give way markings - Outside number 59	11/03/2023	MIDO	RD: Cat 4 - Programmed	Job 50118499-Job Complete	Imported Defect via Connector
42122059	RD: FW HRA Cracked/Broken	-	11/03/2023	MIDO	RD: Cat 4 - Programmed	Job 50099202-Job Annulled	Imported Defect via Connector
42122060	RD: FW HRA Cracked/Broken	-	11/03/2023	MIDO	RD: Cat 4 - Programmed	Job 50099207-Job Annulled	Imported Defect via Connector
42122061	RD: Markings Refresh	Refresh slow marking - Outside number 11	11/03/2023	MIDO	RD: Cat 4 - Programmed	Job 50118498-Job Complete	Imported Defect via Connector
42134185	RD: Markings Disabled Bay	Parking: Disabled Bay new (Enquiry 34004884) - 28 Cleekim Drive Edinburgh City of Edinburgh EH15 3QP	15/08/2023	ROYS	Parking Operations	Job 50141092-Job Complete	Imported Defect via Connector
42142240	RD: CW Pothole	1 number pothole - Outside number 11	18/12/2023	BRFO	RD: Cat 3 - 60 Day	Job 50148364-RD: Made Safe Job Complete	Imported Defect via Connector
42176085	RD: CW Pothole	3 number potholes - Opposite number 2/1	17/02/2025	BRFO	RD: Cat 3 - 60 Day	Job 50175157-RD: Made Safe Job Complete	Imported Defect via Connector
42179536	RD: Markings Refresh	Refresh give way markings - Junction with duddingston road south	24/03/2025	MIDO	RD: Cat 4 - Programmed	Job 50177465-No code allocated	Imported Defect via Connector
42179537	RD: CW Cracked/Broken	.5x.5m patch - Outside 1	24/03/2025	MIDO	RD: Cat 4 - Programmed	Job 50177466-No code allocated	Imported Defect via Connector
42179540	RD: CW Cracked/Broken	.5x.5m patch - Outside 8	24/03/2025	MIDO	RD: Cat 4 - Programmed	Job 50177467-No code allocated	Imported Defect via Connector
42183926	RD: CW Pothole	1 number pothole - Outside number 1	21/05/2025	BRFO	RD: Cat 3 - 60 Day	Job 50180159-RD: Made Safe Job Complete	Imported Defect via Connector
42191589	RD: CW Pothole	1 number pothole - Opposite number 8	22/10/2025	BRFO	RD: Cat 3 - 60 Day	Job 50185893-RD: Made Safe Job Complete	Imported Defect via Connector
42194040	RD: CW Pothole	1 number pothole - At kerb outside farmfoods	26/11/2025	BRFO	RD: Cat 3 - 60 Day	Job 50187563-RD: Made Safe Job Complete	Imported Defect via Connector