

59821

Please see the attached noting that the site history report covers the full length of the road asset and not just the specific location, it also covers footway as well as carriageway records.

Inspection Records Copies of all pavement/footway inspection records for this exact location for the 12 months prior to 02/08/2025, including:

- dates and times of inspections
- name/role of the inspector
- defects recorded and any measurements taken
- action taken or recommended following each inspection

[Please refer to the attached site history report – Condition Survey](#)

[Inspections are undertaken by Roads Inspectors](#)

[We do not record the time of the inspections](#)

Inspection Policy & Standards

The Council's inspection policy and risk assessment criteria applicable to this location at that time, including:

- the required inspection frequency for this category of
- defect intervention levels (e.g., depth/height thresholds requiring repair
- target timescales for repair once a defect is identified.

[Please refer to the attached Risk Based Approach document. New Market Road is inspected annually.](#)

Maintenance & Repair History Copies of any maintenance, repair, or works records for this location between 02/08/2024 and 12/08/2025, including works orders, contractor reports, and completion dates.

[Please refer to the attached site history report – Maintenance Management.](#)

Previous Reports or Complaints Details of any complaints, enquiries, or reports received about this section of pavement in the same 12-month period.

[Please refer to the attached site history report – Customer Services](#)

Post-Incident Inspection Copies of the inspection carried out on 12/08/2025, including photographs, measurements, and the assessment used to determine that no hazardous defect existed.

[Please see the attached New Market Road Inspection 12.08.25, together with photographs.](#)