

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Site: Granton Road (7901430)

Locality: Trinity, Edinburgh, City of Edinburgh

Area: North West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Ward 4 - Ferry Road to south-east corner of Granton Square			Feature Type: Road Asset			Area: North West Locality	
Batch: 41251789	- Inspection Batch No actionable defects found			Route: North Mobile Inspection Route				Date: 04/02/2026
Batch: 41251351	- Inspection Batch			Route: Ad hoc Route				Date: 31/01/2026
42198184	Patch required approx 1.5x15m	31/01/2026	Outside 136	RD: CW Cracked/Broken	Internal		Committed	50190874
Batch: 41250851	- Inspection Batch			Route: Ad hoc Route				Date: 28/01/2026
42197805	1no Po	28/01/2026	Outside 125.	RD: CW Pothole	Internal		Committed	50190590
Batch: 41250840	- Inspection Batch			Route: Ad hoc Route				Date: 28/01/2026
42197799	1no pothole	28/01/2026	Outside 158	RD: CW Pothole	Internal		Committed	50190586
Batch: 41249879	- Inspection Batch			Route: Ad hoc Route				Date: 24/01/2026
42197450	2no potholes	24/01/2026	Outside 138	RD: CW Pothole	Internal		Committed	50190294
Batch: 41248767	- Inspection Batch			Route: Ad hoc Route				Date: 16/01/2026
42196732	2 cw potholes	16/01/2026	At wardie crescent	RD: CW Pothole	Internal		Committed	50189737
Batch: 41246522	- Inspection Batch No actionable defects found			Route: North Mobile Inspection Route				Date: 30/12/2025
Batch: 41246092	- Inspection Batch			Route: Ad hoc Route				Date: 23/12/2025
42195685	1 number pothole	23/12/2025	Outside number 164	RD: CW Pothole	Internal		Committed	50188841
Batch: 41245219	- Inspection Batch			Route: Ad hoc Route				Date: 18/12/2025
42195500	2 number potholes	18/12/2025	Outside number 140	RD: CW Pothole	Internal		Committed	50188678
Batch: 41242548	- Inspection Batch			Route: North Mobile Inspection Route				Date: 25/11/2025
42193814	1no pothole	25/11/2025	Opposite Patch Pet Supplies	RD: CW Pothole	Internal		Committed	50187410
Batch: 41240027	- Inspection Batch			Route: NW_CF2_TrinitySouth1				Date: 28/10/2025
42192027	Patch required Approx 1.5m x 0.5m	28/10/2025	Outside 79	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50168124
42192021	Patch required Approx 3m x 1.5m	28/10/2025	Opposite 142	RD: CW Cracked/Broken	Internal		Uncommitted	50168122
42192019	Patch required Approx 5m x 0.5m	28/10/2025	Outside 166	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50168137
Batch: 41239417	- Inspection Batch No actionable defects found			Route: North Mobile Inspection Route				Date: 22/10/2025
Batch: 41237248	- Inspection Batch No actionable defects found			Route: North Mobile Inspection Route				Date: 23/09/2025
Batch: 41234825	- Inspection Batch No actionable defects found			Route: North Mobile Inspection Route				Date: 18/08/2025
Batch: 41233574	- Inspection Batch			Route: Ad hoc Route				Date: 22/07/2025
42187519	Replace missing kerb	22/07/2025	Outside 12	RD: FW Kerbs Damaged/Missing	Internal		Committed	50182974

Site History Report

Effective: 01/01/2023 to 11/02/2026

Service: Roads General

Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 4 - Ferry Road to south-east corner of Granton Square		Feature Type: Road Asset		Area: North West Locality		
Batch:	41233234 - Inspection Batch			Route: North Mobile Inspection Route			Date: 18/07/2025	
	No actionable defects found							
Batch:	41230972 - Inspection Batch			Route: North Mobile Inspection Route			Date: 16/06/2025	
	No actionable defects found							
Batch:	41230752 - Inspection Batch			Route: Ad hoc Route			Date: 12/06/2025	
42185449	Pothole on carriageway	12/06/2025	Junction Inverleith Gardens heading east	RD: CW Pothole	Internal		Committed	50181249
Batch:	41229500 - Inspection Batch			Route: Ad hoc Route			Date: 28/05/2025	
42184570	Permanent repair required	28/05/2025	Outside 138.	RD: CW Cracked/Broken	Internal		Committed	50180547
Batch:	41229082 - Inspection Batch			Route: Ad hoc Route			Date: 26/05/2025	
42184183	Pothole on carriageway	26/05/2025	Outside 136	RD: CW Pothole	Internal		Committed	50180324
Batch:	41228312 - Inspection Batch			Route: North Mobile Inspection Route			Date: 15/05/2025	
	No actionable defects found							
Batch:	41226313 - Inspection Batch			Route: North Mobile Inspection Route			Date: 22/04/2025	
	No actionable defects found							
Batch:	41225890 - Inspection Batch			Route: Ad hoc Route			Date: 14/04/2025	
42181177	Pothole on carriageway	14/04/2025	Outside Wardie residents club	RD: CW Pothole	Internal		Committed	50178492
Batch:	41225549 - Inspection Batch			Route: Ad hoc Route			Date: 09/04/2025	
42180971	Pothole on carriageway	09/04/2025	Outside 164	RD: CW Pothole	Internal		Committed	50178324
Batch:	41225115 - Inspection Batch			Route: Ad hoc Route			Date: 03/04/2025	
42180667	Pothole on carriageway	03/04/2025	Entrance to Broughton Rugby Club	RD: CW Pothole	Internal		Committed	50178158
Batch:	41225114 - Inspection Batch			Route: Ad hoc Route			Date: 03/04/2025	
42180666	Pothole on carriageway	03/04/2025	Junction Rosebank Road, outside 79,99	RD: CW Pothole	Internal		Committed	50178157
Batch:	41223020 - Inspection Batch			Route: North Mobile Inspection Route			Date: 17/03/2025	
	No actionable defects found							
Batch:	41221081 - Inspection Batch			Route: Ad hoc Route			Date: 28/02/2025	
42177457	1 number pothole	28/02/2025	105 Granton Road. Pothole on road, outside number 138	RD: CW Pothole	Internal		Committed	50176145
Batch:	41221080 - Inspection Batch			Route: Ad hoc Route			Date: 28/02/2025	
42177456	1 number pothole	28/02/2025	Outside number 105	RD: CW Pothole	Internal		Committed	50176144
Batch:	41219806 - Inspection Batch			Route: North Mobile Inspection Route			Date: 19/02/2025	
	No actionable defects found							
Batch:	41214712 - Inspection Batch			Route: North Mobile Inspection Route			Date: 15/01/2025	
	No actionable defects found							
Batch:	41211702 - Inspection Batch			Route: North Mobile Inspection Route			Date: 23/12/2024	
	No actionable defects found							

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 4 - Ferry Road to south-east corner of Granton Square		Feature Type: Road Asset		Area: North West Locality		
Batch: 41209571 - Inspection Batch			Route: Ad hoc Route			Date: 04/12/2024		
42170417	Loose / leaning pole angled dangerously into the road. Please cut down below ground level, dispose and make the hole safe from trips. Cheers	04/12/2024	Opposite Patch's Pet Supplies	RD: Unlit Sign Damaged/Missing	Internal		Committed	50170778
Batch: 41208733 - Inspection Batch			Route: Ad hoc Route			Date: 27/11/2024		
42169924	Pothole on carriageway	27/11/2024	Outside 178	RD: CW Pothole	Internal		Committed	50170419
Batch: 41208728 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route			Date: 27/11/2024		
Batch: 41205768 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route			Date: 30/10/2024		
Batch: 41203618 - Inspection Batch			Route: NW_CF2_TrinitySouth1			Date: 15/10/2024		
42166837	1 cw pothole	15/10/2024	Opposite waterfront takeaway	RD: CW Pothole	Internal		Committed	50168141
42166810	Patch required Approx 1.5m x 0.5m	15/10/2024	Outside 79	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42166804	Patch required Approx 3m x 0.5m	15/10/2024	At junction with boswall road	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50168119
42166808	Patch required Approx 3m x 1.5m	15/10/2024	Opposite 142	RD: CW Cracked/Broken	Internal		No Action Required	
42166807	Permanent carriageway repair required	15/10/2024	Outside 158	RO: Permanent Patching	Internal		Uncommitted	50157303
42166832	Patch required Approx 5m x 0.5m	15/10/2024	Outside 166	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42166829	Permanent repair required	15/10/2024	Outside 138	RO: Permanent Patching	Internal		Uncommitted	50160808
Batch: 41202431 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route			Date: 07/10/2024		
Batch: 41201954 - Inspection Batch			Route: Ad hoc Route			Date: 02/10/2024		
42165721	Pothole on carriageway	02/10/2024	Outside 44	RD: CW Pothole	Internal		Committed	50167330
Batch: 41201953 - Inspection Batch			Route: Ad hoc Route			Date: 02/10/2024		
42165720	Pothole on footway	02/10/2024	Outside 11,entrance to nursery	RD: CW Pothole	Internal		Committed	50167329
Batch: 41199748 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route			Date: 03/09/2024		
Batch: 41199700 - Inspection Batch			Route: Ad hoc Route			Date: 02/09/2024		
42164460	Void in the carriageway at pedestrian crossing Please excavate investigate and reinstate	02/09/2024	Outside no132	RD: CW Subsidence/Heaving	Internal		Committed	50166020
Batch: 41199046 - Inspection Batch			Route: Ad hoc Route			Date: 19/08/2024		
42163818	Depression on carriageway	19/08/2024	Outside 134	RD: CW Pothole	Internal		Committed	50165519

Site History Report

Effective: 01/01/2023 to 11/02/2026

Service: Roads General

Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 4 - Ferry Road to south-east corner of Granton Square		Feature Type: Road Asset		Area: North West Locality		
Batch:	41197928 - Inspection Batch			Route: North Mobile Inspection Route			Date: 05/08/2024	
	No actionable defects found							
Batch:	41196900 - Inspection Batch			Route: Ad hoc Route			Date: 18/07/2024	
42162009	Permanent repair required	18/07/2024	Outside 95	RO: Permanent Patching	Internal		Uncommitted	50160867
Batch:	41195662 - Inspection Batch			Route: North Mobile Inspection Route			Date: 01/07/2024	
	No actionable defects found							
Batch:	41194811 - Inspection Batch			Route: Ad hoc Route			Date: 19/06/2024	
42159974	Pothole on carriageway	19/06/2024	Outside 138	RD: CW Pothole	Internal		Committed	50162595
Batch:	41193325 - Inspection Batch			Route: North Mobile Inspection Route			Date: 03/06/2024	
	No actionable defects found							
Batch:	41192801 - Inspection Batch			Route: Ad hoc Route			Date: 27/05/2024	
42158067	Sink hole appearing at Carriageway reinstatement	27/05/2024	Outside 95	RU: Utility Reinstatement	Internal		Uncommitted	50161100
Batch:	41192657 - Inspection Batch			Route: Ad hoc Route			Date: 24/05/2024	
42157904	Pothole on carriageway	24/05/2024	Outside 105a,primary school,99	RD: CW Pothole	Internal		Committed	50160946
Batch:	41192577 - Inspection Batch			Route: Ad hoc Route			Date: 23/05/2024	
42157827	Permanent repair required	23/05/2024	Outside 95	RO: Permanent Patching	Internal		No Action Required	
Batch:	41192576 - Inspection Batch			Route: Ad hoc Route			Date: 23/05/2024	
42157826	Pothole on carriageway	23/05/2024	Outside 95	RD: CW Pothole	Internal		Committed	50160866
Batch:	41192528 - Inspection Batch			Route: Ad hoc Route			Date: 22/05/2024	
42157763	Permanent repair required	22/05/2024	Outside 138	RO: Permanent Patching	Internal		No Action Required	
Batch:	41191241 - Inspection Batch			Route: North Mobile Inspection Route			Date: 07/05/2024	
42156537	1no pothole	07/05/2024	At the junction with Fraser Avenue	RD: CW Pothole	Internal		Committed	50159906
Batch:	41190892 - Inspection Batch			Route: Ad hoc Route			Date: 01/05/2024	
42156161	Pothole on carriageway	01/05/2024	Outside 26,20,11	RD: CW Pothole	Internal		Committed	50159586
Batch:	41189609 - Inspection Batch			Route: Ad hoc Route			Date: 15/04/2024	
42154795	Pothole on carriageway	15/04/2024	Junction Wardie Crescent	RD: CW Pothole	Internal		Committed	50158442
Batch:	41188809 - Inspection Batch			Route: Ad hoc Route			Date: 09/04/2024	
42153984	Pothole on carriageway	09/04/2024	Heading south from Rosebank Road	RD: CW Pothole	Internal		Committed	50157716
Batch:	41188290 - Inspection Batch			Route: Ad hoc Route			Date: 03/04/2024	
42153567	Permanent carriageway repair required	03/04/2024	Outside 158	RO: Permanent Patching	Internal		No Action Required	
Batch:	41188215 - Inspection Batch			Route: North Mobile Inspection Route			Date: 03/04/2024	
	No actionable defects found							
Batch:	41185815 - Inspection Batch			Route: Ad hoc Route			Date: 12/03/2024	
42151174	Permanent repair required	12/03/2024	Outside 19 at bus stop	RO: Permanent Patching	Internal		Uncommitted	50155501

Site History Report

Effective: 01/01/2023 to 11/02/2026
 Service: Roads General
 Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 4 - Ferry Road to south-east corner of Granton Square		Feature Type: Road Asset		Area: North West Locality		
Batch:	41185296 - Inspection Batch			Route: Ad hoc Route		Date: 08/03/2024		
42150568	Road: Defective / Damaged (Enquiry 1706507)	08/03/2024	Outside drive to 138 remove loose and make safe	RD: CW Pothole	Internal		Committed	50155111
Batch:	41184477 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route		Date: 03/03/2024		
Batch:	41182847 - Inspection Batch			Route: Ad hoc Route		Date: 19/02/2024		
42148071	Pothole on footway	19/02/2024	Junction Granton Square	RD: FW HRA Pothole	Internal		Committed	50153287
Batch:	41182845 - Inspection Batch			Route: Ad hoc Route		Date: 19/02/2024		
42148070	Gully choked	19/02/2024	Junction Granton Square	Gully: Blocked / Flooding	Internal		Committed	50153286
Batch:	41182372 - Inspection Batch			Route: Ad hoc Route		Date: 13/02/2024		
42147471	Pothole on carriageway	13/02/2024	Outside Waterfront Cafe	RD: CW Pothole	Internal		Committed	50152882
Batch:	41181192 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route		Date: 05/02/2024		
Batch:	41180726 - Inspection Batch			Route: Ad hoc Route		Date: 31/01/2024		
42145787	Pothole on carriageway	31/01/2024	Outside 164,174	RD: CW Pothole	Internal		Committed	50151740
Batch:	41180722 - Inspection Batch			Route: Ad hoc Route		Date: 31/01/2024		
42145785	Pothole on carriageway	31/01/2024	Outside Wardie residents club	RD: CW Pothole	Internal		Committed	50151737
Batch:	41177574 - Inspection Batch			Route: Ad hoc Route		Date: 05/01/2024		
42143306	Pavement: Damaged / Defective (Enquiry 1671770) uplift sign	05/01/2024	Outside 215	RD: Other Defect Type	Internal		Committed	50149410
Batch:	41176551 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route		Date: 03/01/2024		
Batch:	41174107 - Inspection Batch			Route: Ad hoc Route		Date: 12/12/2023		
42141627	Road: Defective / Damaged (Enquiry 1658384) pothole on carriageway	12/12/2023	Outside 138	RD: CW Pothole	Internal		Committed	50147728
Batch:	41173059 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route		Date: 30/11/2023		
Batch:	41173005 - Inspection Batch			Route: Ad hoc Route		Date: 29/11/2023		
42140715	Pothole on carriageway	29/11/2023	Outside 11	RD: CW Pothole	Internal		Committed	50146844
Batch:	41172924 - Inspection Batch			Route: Ad hoc Route		Date: 28/11/2023		
42140622	Road: Defective / Damaged (Enquiry 1652092) pothole on carriageway	28/11/2023	Outside 136	RD: CW Pothole	Internal		Committed	50146771
Batch:	41172923 - Inspection Batch			Route: Ad hoc Route		Date: 28/11/2023		
42140621	Pothole on carriageway	28/11/2023	Junction Grirson Avenue	RD: CW Pothole	Internal		Committed	50146770
Batch:	41172922 - Inspection Batch			Route: Ad hoc Route		Date: 28/11/2023		
42140620	Pothole on footway	28/11/2023	Outside 146	RD: FW HRA Pothole	Internal		Committed	50146769

Site History Report

Effective: 01/01/2023 to 11/02/2026

Service: Roads General

Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 4 - Ferry Road to south-east corner of Granton Square		Feature Type: Road Asset		Area: North West Locality		
Batch:	41172232 - Inspection Batch			Route: NW_CF2_TrinitySouth1		Date: 18/11/2023		
42139920		18/11/2023		RD: CW Rutting	Internal		Uncommitted	50109822
42139921	Patch required approx 1x2m	18/11/2023	Outside no146	RD: CW Cracked/Broken	Internal		Uncommitted	50146112
Batch:	41170829 - Inspection Batch			Route: Ad hoc Route		Date: 02/11/2023		
42138490	Pothole on carriageway	02/11/2023	Outside Waterfront Takeaway	RD: CW Pothole	Internal		Committed	50144859
Batch:	41170827 - Inspection Batch			Route: Ad hoc Route		Date: 02/11/2023		
42138488	Flooding carriageway and footway	02/11/2023	Junction Granton Square	Gully: Blocked / Flooding	Internal		Committed	50144857
Batch:	41170039 - Inspection Batch			Route: North Mobile Inspection Route		Date: 26/10/2023		
	No actionable defects found							
Batch:	41169064 - Inspection Batch			Route: Ad hoc Route		Date: 19/10/2023		
42137723	Pothole on carriageway	19/10/2023	Outside 95	RD: CW Pothole	Internal		Committed	50144240
Batch:	41167259 - Inspection Batch			Route: North Mobile Inspection Route		Date: 02/10/2023		
	No actionable defects found							
Batch:	41163661 - Inspection Batch			Route: North Mobile Inspection Route		Date: 28/08/2023		
	No actionable defects found							
Batch:	41163203 - Inspection Batch			Route: Ad hoc Route		Date: 21/08/2023		
42134454	Road: Defective / Damaged (Enquiry 1600942) pothole on carriageway	21/08/2023	Outside 138	RD: CW Pothole	Internal		Committed	50141271
Batch:	41163096 - Inspection Batch			Route: Ad hoc Route		Date: 17/08/2023		
42134317	Pothole on carriageway	17/08/2023	Traffic island outside 30	RD: CW Pothole	Internal		Committed	50141173
Batch:	41162736 - Inspection Batch			Route: Ad hoc Route		Date: 10/08/2023		
42133790	Pothole on carriageway	10/08/2023	Outside 174	RD: CW Pothole	Internal		Committed	50140801
Batch:	41162413 - Inspection Batch			Route: Ad hoc Route		Date: 04/08/2023		
42133347	Public Utilities: General - Pls can temporary traffic light sign be removed from pavement (Enquiry 1592051) signs left after recent work	04/08/2023	Outside 18 + 28	RU: Utility Reinstatement	Internal		Uncommitted	50140459
Batch:	41162255 - Inspection Batch			Route: Ad hoc Route		Date: 01/08/2023		
42133102	Repair damaged coping and replace missing railings	01/08/2023	Opposite Lufra Bank	RD: Railing Damage/Missing/New	Internal		Committed	50140231
Batch:	41161932 - Inspection Batch			Route: North Mobile Inspection Route		Date: 28/07/2023		
	No actionable defects found							
Batch:	41160227 - Inspection Batch			Route: North Mobile Inspection Route		Date: 03/07/2023		
	No actionable defects found							
Batch:	41159860 - Inspection Batch			Route: Ad hoc Route		Date: 23/06/2023		
42130632	Sign left on traffic island	23/06/2023	Outside 91	RU: Utility Reinstatement	Internal		Uncommitted	50138274

Site History Report

Effective: 01/01/2023 to 11/02/2026

Service: Roads General

Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 4 - Ferry Road to south-east corner of Granton Square		Feature Type: Road Asset		Area: North West Locality		
Batch:	41159859 - Inspection Batch			Route: Ad hoc Route		Date: 23/06/2023		
42130631	Public Utilities: General (Enquiry 1570504) sign left after recent work	23/06/2023	Outside 97	RU: Utility Reinstatement	Internal		Uncommitted	50138273
Batch:	41158712 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route		Date: 06/06/2023		
Batch:	41158373 - Inspection Batch			Route: Ad hoc Route		Date: 02/06/2023		
42129224	Pothole on carriageway	02/06/2023	Outside 7	RD: CW Pothole	Internal		Committed	50137139
Batch:	41158372 - Inspection Batch			Route: Ad hoc Route		Date: 02/06/2023		
42129223	Pothole on carriageway	02/06/2023	Junction Granton Square	RD: CW Pothole	Internal		Committed	50137138
Batch:	41158217 - Inspection Batch			Route: Ad hoc Route		Date: 30/05/2023		
42128904	Public Utilities: General - Loose metal cover/manhole causing noise on Granton Road at junction with Afton Terrace. (Enquiry 34006958) noisy carriageway box	30/05/2023	Outside 88	RU: Utility Apparatus	Internal		Uncommitted	50136949
Batch:	41157023 - Inspection Batch			Route: Ad hoc Route		Date: 11/05/2023		
42127257	1 carriageway pothole	11/05/2023	Opposite waterfront cafe	RD: CW Pothole	Internal		Committed	50135907
Batch:	41156125 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route		Date: 01/05/2023		
Batch:	41155400 - Inspection Batch			Route: Ad hoc Route		Date: 24/04/2023		
42125812	Road: Defective / Damaged (Enquiry 1541200) pothole on carriageway	24/04/2023	Outside entrance to Millennium motors	RD: CW Pothole	Internal		Committed	50134789
Batch:	41154050 - Inspection Batch			Route: North Mobile Inspection Route		Date: 05/04/2023		
42124652	2no potholes	05/04/2023	Outside no144	RD: CW Pothole	Internal		Committed	50133699
Batch:	41152567 - Inspection Batch			Route: Ad hoc Route		Date: 17/03/2023		
42122713	Pothole on carriageway	17/03/2023	Outside 1 at traffic lights	RD: CW Pothole	Internal		Committed	50132185
Batch:	41152506 - Inspection Batch			Route: Ad hoc Route		Date: 16/03/2023		
42122694	Pothole on carriageway	16/03/2023	Outside 164	RD: CW Pothole	Internal		Committed	50132157
Batch:	41151458 - Inspection Batch			Route: North Mobile Inspection Route		Date: 07/03/2023		
42121471	1no pothole	07/03/2023	Outside Patchs pet supplies	RD: CW Pothole	Internal		Committed	50131278
Batch:	41149185 - Inspection Batch			Route: North Mobile Inspection Route		Date: 15/02/2023		
42118588	1 carriageway pothole	15/02/2023	Outside 142	RD: CW Pothole	Internal		Committed	50129321
Batch:	41148376 - Inspection Batch			Route: Ad hoc Route		Date: 08/02/2023		
42117957	Gully: Blocked/Needs Clean - What is the problem with the gully : blocked. What surface is the gully on : road (Enquiry 1505928)gully chocked	08/02/2023	Outside 189	Gully: Blocked / Flooding	Internal		Committed	50128780

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 4 - Ferry Road to south-east corner of Granton Square		Feature Type: Road Asset		Area: North West Locality		
Batch:	41147768 - Inspection Batch			Route: Ad hoc Route		Date: 02/02/2023		
42117212	Road: Defective / Damaged (Enquiry 1502857) pothole on carriageway	02/02/2023	Outside Waterfront Takeaway	RD: CW Pothole	Internal		Committed	50128193
Batch:	41147767 - Inspection Batch			Route: Ad hoc Route		Date: 02/02/2023		
42117211	Gully: Blocked/Needs Clean - What is the problem with the gully : blocked. What surface is the gully on : road (Enquiry 1502636)gully chocked	02/02/2023	Outside Ashworth and Thomson	Gully: Blocked / Flooding	Internal		Committed	50128192
Batch:	41143260 - Inspection Batch			Route: North Mobile Inspection Route		Date: 12/01/2023		
42114876	1no pothole	12/01/2023	Outside no136	RD: CW Pothole	Internal		Committed	50125971
Batch:	41142174 - Inspection Batch			Route: Ad hoc Route		Date: 05/01/2023		
42114179	Road: Defective / Damaged (Enquiry 1482713) pothole on carriageway	05/01/2023	Junction Granton Square	RD: CW Pothole	Internal		Committed	50125379

Customer Services

Enquiry No.: 34010433 **Logged by:** [REDACTED] **on:** 06/10/2025 12:00
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: please inspect foliage several of the small 20mph signs are obscured by branches on Granton Road, especially the part driving up from Granton Square towards the Boswell Road junction.
Location: Granton Road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 34006958 **Logged by:** [REDACTED] **on:** 29/05/2023 14:31
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.: Loose metal cover/manhole causing noise on Granton Road at junction with Afton Terrace.
Location: Granton Road **Contact:** Sanne dijckstra

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50136949 **Defect Number:** 42128904

Enquiry No.: 31603374 **Logged by:** [REDACTED] **on:** 10/12/2024 13:24
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: [REDACTED] has pointed me in your direction to report a road sign pole hanging into the carriageway on Granton Road Southbound.
Location: **Contact:**

Enquiry No.: 2092585 **Logged by:** Verint CRM Connector **on:** 11/02/2026 11:06
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Various potholes at junction of Granton Road and Wardie Crescent. One in particular has had at least two attempts in recent months to rectify but is still full of water, although I'm unsure if this is a drainage rather than a pothole problem. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50191690 **Defect Number:** 42199230

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2092281 **Logged by:** Verint CRM Connector **on:** 10/02/2026 19:22
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Large and deep pothole in the carriageway, filled with standing water, making it difficult to see in dark and wet conditions. The defect is substantial and appears to have been present for some time. **Contact:**

While driving at normal speed and exercising due care, my vehicle struck the pothole as it was unavoidable due to its position and lack of visibility. The impact caused immediate damage to my tyre and alloy wheel, rendering the tyre unroadworthy.

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 2089107 **Logged by:** Verint CRM Connector **on:** 05/02/2026 08:43
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Large delamination and pothole at traffic lights turning onto left onto ferry road from granton road. **Contact:**

There are also multiple potholes when turning right from ferry road onto graton road at junction. (Not pictured)

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50191664 **Defect Number:** 42199198

Enquiry No.: 2088385 **Logged by:** Verint CRM Connector **on:** 04/02/2026 08:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Road down from the bus stop is severely rutted including multiple potholes of various sizes and depths. Additionally services cover has subsided and worn away, so it now contains a sharp edged hole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 2087104 **Logged by:** Verint CRM Connector **on:** 02/02/2026 09:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Bad potholes by bus stop **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50191678 **Defect Number:** 42199214

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2085212 **Logged by:** Verint CRM Connector **on:** 29/01/2026 12:55
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Ref No: 102000137772

Contact:

I reported a manhole/pothole which caused a serious cycle accident last week. You have indicated that it has been solved. I have been to look and the place/site where it occurred (manhole/pothole outside 164-166 Granton Raod) has no change and is still a hazard. There seems to have been some basic tarmac infill on the hole outside 154 Granton Road, but other remaining hazrds nearby. So I do not think that this job has been responded to effectively.

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 2084161 **Logged by:** Verint CRM Connector **on:** 28/01/2026 00:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: The busses have eroded the kerb and the drop from our drive to the road has become unsafe. The earlier remedial tarmac repairs have not lasted.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50190874

Defect Number: 42198184

Enquiry No.: 2067369 **Logged by:** Verint CRM Connector **on:** 02/01/2026 09:07
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: 2 more Saltire flags on lamposts, presumably racist again

Contact:

Enquiry No.: 2062217 **Logged by:** Verint CRM Connector **on:** 22/12/2025 13:25
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Pothole

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50188841

Defect Number: 42195685

Enquiry No.: 2053782 **Logged by:** Verint CRM Connector **on:** 05/12/2025 10:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: 2 potholes by boswall green bus stop

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50188678

Defect Number: 42195500

Enquiry No.: 2046554 **Logged by:** Verint CRM Connector **on:** 21/11/2025 09:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: junction of Ferry road and Granton road at the bus stop on RHS as going down Ferry road - large pothole to be assessed and repaired

Contact:

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2045844 **Logged by:** Verint CRM Connector **on:** 19/11/2025 21:11
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Overhanging badge blocking half of the pavement just near the lights, double decker buses turn left at the lights at the top of the street which leaves an extremely narrow space to get past. Only one pedestrian at a time can get past and it's unsuitable for prams to get past safely. Very close encounters with bus wing mirrors. **Contact:**

Enquiry No.: 2040968 **Logged by:** Verint CRM Connector **on:** 10/11/2025 15:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: A pothole between the crossing and the bus stop **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 2039885 **Logged by:** Verint CRM Connector **on:** 07/11/2025 23:26
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Pavement.
Type:Foliage / Bush
Location: This hedge has recently been cut back but still takes up nearly a foot of already narrow pavement. Needs to be cut back to the actual boundary to be safe - I walk past every day with a buggy, half on the road because of the overgrowth. **Contact:**

Enquiry No.: 2028402 **Logged by:** Verint CRM Connector **on:** 15/10/2025 10:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: re: 172 Granton Road. On 13 October, I was told that the road had been repaired, copy email below. Not so! So I reported the issue again (ref 101001527243). Perhaps now it will get fixed!
"The job associated with your enquiry has now been completed. Thanks again for taking the time to report this.

If you have any further questions or concerns about this enquiry, please contact us using the reference number 101001499301. **Contact:**

Enquiry No.: 2023033 **Logged by:** Verint CRM Connector **on:** 03/10/2025 10:20
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Traffic island at 187/189 Granton Road **Contact:**
Surface is badly potholed affecting elderly neighbour who uses a walker to cross the road and has to change route from the traffic island to the pavement. Please repair.

Also: Planned double yellow lines and cross walk promised in early 2000s still not implemented on the west side of the road and barely visible on the east side now. What is the status of this, please?

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2014920 **Logged by:** Verint CRM Connector **on:** 16/09/2025 14:39
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Collapsed/ broken manhole cover at Granton Road at the junction of Ferry Road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 1990558 **Logged by:** Verint CRM Connector **on:** 05/08/2025 09:10
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Cycleway.
Type:Foliage / Bush
Location: Tree blown across cyclepath **Contact:**

Enquiry No.: 1983814 **Logged by:** Verint CRM Connector **on:** 23/07/2025 11:28
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Please cut this hedge back so there is proper space on the pavement **Contact:**

Enquiry No.: 1982695 **Logged by:** Verint CRM Connector **on:** 21/07/2025 16:47
Service: Roads General **Subject:** Pavement: Missing Slab / Kerb **Classification:** Customer Emergency
Desc.:
Location: missing kerb stone outside 12 Granton Road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50182974 **Defect Number:** 42187519

Enquiry No.: 1966413 **Logged by:** Verint CRM Connector **on:** 20/06/2025 08:51
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: There is a overgrown hedge in front of 1 Granton road which is blocking the pavement. It is near a nursery and many kids walk to school past it. **Contact:**

Enquiry No.: 1966385 **Logged by:** Verint CRM Connector **on:** 20/06/2025 08:21
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.:
Location: On Granton Road just as you cross from ferry road on the side where the sheriff motors is there is a overgrown hedge which makes it difficult to use the pavement. This area is right next to a nursery and on the way to school **Contact:**

Enquiry No.: 1962036 **Logged by:** Verint CRM Connector **on:** 12/06/2025 00:10
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Left lane at traffic lights going from Granton Road towards Inverleith Gardens there is a damaged manhole cover **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50181249 **Defect Number:** 42185449

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1953990 **Logged by:** Verint CRM Connector **on:** 27/05/2025 12:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Hello, we had a repair made yesterday but it was done, again, with tarmac and the first bus thats come along has flattened it and re-hollowed the pothole making the drop of the kerb too large for our cars. Can a more long-term solution be made? We have these potholes repaired several times a year but the heavy traffic means its a band aid. Can the kerb be properly dropped to the road?

Contact:

Our cars are bottoming out when we leave the drive.

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset
Job Number: 50180547 **Defect Number:** 42184570

Enquiry No.: 1952839 **Logged by:** Verint CRM Connector **on:** 24/05/2025 14:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: The kerb has erroded again, due to heavy bus use restricting the access to the drive way for the cars. The potholes are crumbling and getting worse.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset
Job Number: 50180324 **Defect Number:** 42184183

Enquiry No.: 1932656 **Logged by:** Verint CRM Connector **on:** 12/04/2025 14:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Potholes appeared in previous patched area. Just before streetbins heading south on Granton Road

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 1932458 **Logged by:** Verint CRM Connector **on:** 11/04/2025 21:22
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Two potholes (potentially >100mm) directly on bus path.

Contact:

Depth of potholes risk to car damage and cars do slow down

Close to school entrance

Potholes are on an previously repaired piece of road due to pothole (suggest poor previous repair)

Previous issues with sinkholes within proximity of issue

Bus / Heavy vehicles passing over pot hole can be felt in surrounding buildings

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset
Job Number: 50178492 **Defect Number:** 42181177

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1932154 **Logged by:** [REDACTED] **on:** 11/04/2025 10:45
Service: Roads General **Subject:** Traffic Sign: General Enquiry **Classification:** General Enquiry
Desc.: the possibility of install signs for example "No Fly tipping" or please dispose of rubbish/litter responsibly"
Location: all the way from Granton Road to Newhaven m(where there are traveller's caravans) **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 1929356 **Logged by:** Verint CRM Connector **on:** 06/04/2025 15:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Sunken section of road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50178324 **Defect Number:** 42180971

Enquiry No.: 1926525 **Logged by:** Verint CRM Connector **on:** 31/03/2025 22:11
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There are several potholes at the entrance of Wardie school and within the car park. **Contact:**
See photos but the holes are getting bigger daily. Please can they be fixed as a trip hazard for kids at the school.

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50178158 **Defect Number:** 42180667

Enquiry No.: 1926415 **Logged by:** Verint CRM Connector **on:** 31/03/2025 17:55
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: At junction **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50178157 **Defect Number:** 42180666

Enquiry No.: 1925469 **Logged by:** Verint CRM Connector **on:** 29/03/2025 14:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Big pothole developing just before the turn into wardie fields. Granton Road **Contact:**
generally in poor state.

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 1909435 **Logged by:** Verint CRM Connector **on:** 25/02/2025 14:32
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 105 Granton Road. **Contact:**
Pothole on road.

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50176144 **Defect Number:** 42177456

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1882542 **Logged by:** Verint CRM Connector **on:** 08/01/2025 07:22
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The drains sinking into the ground make the road very difficult to drive on. Trying to avoid them is near impossible. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 1873324 **Logged by:** Verint CRM Connector **on:** 19/12/2024 14:22
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Exact Address is 138 Granton Road - end of the driveway along the kerbside. There are large pot holes at the end of the driveway that are continuing to deteriorate. Due to the unmarked bus stop the heavy buses are using this location to stop, making it worse. My car is being scraped on entering and exiting the driveway due to these holes. My partner has reported this issue several times over the last year and only very temporary fixes are being done. Please can you arrange for a permanent fix. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 1866201 **Logged by:** Verint CRM Connector **on:** 02/12/2024 12:57
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type unlit
Location: Opposite Patch's Pet Supplies there is a sign pole that is leaning slightly towards the road and there is no sign on it **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50170778 **Defect Number:** 42170417

Enquiry No.: 1821266 **Logged by:** Verint CRM Connector **on:** 23/08/2024 14:43
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Verge / Grass area .
Type:Foliage / Bush
Location: Rear 131 Lower Granton Road area **Contact:**

Enquiry No.: 1820040 **Logged by:** [REDACTED] **on:** 21/08/2024 12:27
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Sunken road surface
Location: o/s 169 **Contact:**

Enquiry No.: 1818385 **Logged by:** Verint CRM Connector **on:** 18/08/2024 22:27
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Massive dip, increased x5 over a few days with sink hole less than 100mtrs further up **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50165519 **Defect Number:** 42163818

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1807252 **Logged by:** Verint CRM Connector **on:** 29/07/2024 14:27
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Called to report a hole about 4 foot from the pavement. He put his hose into this hole **Contact:**
to see how deep it is, and no water was coming back, and he is worried that this
could be the start of another sink hole.

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 1805236 **Logged by:** [REDACTED] **on:** 25/07/2024 14:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: large hole
Location: opp no 1 by bus stop **Contact:**

Enquiry No.: 1802011 **Logged by:** Verint CRM Connector **on:** 20/07/2024 15:03
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: 143 ground floor pavement left, tree/bush overhanging pavement by 2-3 feet at bust **Contact:**
stop.

Enquiry No.: 1800438 **Logged by:** Verint CRM Connector **on:** 17/07/2024 23:33
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Big, deep hole, south of boswall green bus stop **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50160867 **Defect Number:** 42162009

Enquiry No.: 1781542 **Logged by:** Verint CRM Connector **on:** 14/06/2024 22:46
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There ar 3 massive potholes that recur outside 138 granton road. The busses have **Contact:**
eroded them.

This is in relation to ticket 101002457603 which as come back because the repairs
are inadequate.

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 1775274 **Logged by:** Verint CRM Connector **on:** 07/06/2024 11:55
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: A sinking hole has appeared on Granton Road , opposite 102. This is the same **Contact:**
location as a previous large sink hole in 2020 . I have attached photo from 2020 ,
Granton Road was closed for months in August of that year

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1765344 Service: Roads General Desc.: Location: Sinkhole appearing under the tamac at white lines	Logged by: Verint CRM Connector Subject: Public Utilities: General	on: 28/05/2024 13:59 Classification: Request for service Contact:
Plot Number: 1.00 Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Feature Type: Road Asset		
Enquiry No.: 1764904 Service: Roads General Desc.: Location: Sink hole appearing.	Logged by: Verint CRM Connector Subject: Public Utilities: General	on: 28/05/2024 08:58 Classification: Request for service Contact:
Plot Number: 1.00 Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Feature Type: Road Asset		
Enquiry No.: 1761755 Service: Roads General Desc.: Location: **URGENT** - SINKHOLE FROM A COUPLE OF YEARS AGO HAS STARTED TO OPEN UP IN THE ROAD AGAIN TODAY	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 24/05/2024 13:12 Classification: Request for service Contact:
Plot Number: 1.00 Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Feature Type: Road Asset		
Enquiry No.: 1759411 Service: Roads General Desc.: Location: sink hole appeared overnight on Granton Road between 95 & 95A Granton Road in the middle of the road hole is quite deep as there used to be a railway running beneath the street - this needs to be made safe ASAP - before it gets any bigger	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 22/05/2024 14:58 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50160866	Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Defect Number: 42157826	Feature Type: Road Asset
Enquiry No.: 1758694 Service: Roads General Desc.: Location: Outside 138 Granton road the busses continue to heavily erode the gutter and cause resident cars to bottom out. The potholes are now several inches deep again and we can't get cars into the drive without scuffing the underside.	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 21/05/2024 20:33 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50160808	Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Defect Number: 42166829	Feature Type: Road Asset
Enquiry No.: 1758692 Service: Roads General Desc.: Description: The kerb outside number 138 Granton road needs dropped to the road as the busses are eroding the gutter heavily and residents cars are bottoming out. This has been 'repaired' 5 or 6 times times in the last year and everytime a bus comes along and flattens out the tar mac. We need a permanent solution. Reason: Existing, nor dropped kerb, causing damage to vehicles and resulting in a half dozen repairs a year. Looking for a permanent solution. Location: The kerb outside number 138 Granton road needs dropped to the road as the busses are eroding the gutter heavily and residents cars are bottoming out. This has been 'repaired' 5 or 6 times times in the last year and everytime a bus comes along and flattens out the tar mac. We need a permanent solution.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 21/05/2024 20:31 Classification: Request for service Contact:

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1746037 Service: Roads General Desc.: Location: Pothole	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 30/04/2024 23:15 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50159586	Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Defect Number: 42156161	Feature Type: Road Asset
Enquiry No.: 1735351 Service: Roads General Desc.: Location: just at bridge	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 12/04/2024 09:34 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50157303	Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Defect Number: 42166807	Feature Type: Road Asset
Enquiry No.: 1726316 Service: Roads General Desc.: Location: The road surface outside 158 Granton Rd in the middle of the road is badly cracked and when it rains fountains appear in the middle of the road .	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 28/03/2024 15:20 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50157303	Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Defect Number: 42166807	Feature Type: Road Asset
Enquiry No.: 1721247 Service: Roads General Desc.: What type of sign is it? Road sign problem, type unlit Location: Bus stop closed for no apparent reason	Logged by: Verint CRM Connector Subject: Roadworks: Defect	on: 20/03/2024 09:04 Classification: Request for service Contact:
Enquiry No.: 1713376 Service: Roads General Desc.: Location: At the bus stop between Rosebank Road and Rosebank Grove.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 06/03/2024 22:41 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50155501	Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Defect Number: 42151174	Feature Type: Road Asset
Enquiry No.: 1707870 Service: Roads General Desc.: not looking for claim form please see 4 documents attached thanks Location: not looking for claim form please see 4 documents attached thanks	Logged by: [REDACTED] Subject: Road: Defective / Damaged	on: 27/02/2024 14:16 Classification: Request for service Contact:
Enquiry No.: 1706507 Service: Roads General Desc.: Location: Outside drive to 138	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 25/02/2024 16:57 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50155111	Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Defect Number: 42150568	Feature Type: Road Asset

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1705107 Logged by: Verint CRM Connector on: 23/02/2024 01:45
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: near Edinburgh colleague Contact:

Enquiry No.: 1698261 Logged by: Verint CRM Connector on: 12/02/2024 22:37
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Multiple pot holes next to cafe Contact:

Plot Number: 1.00 Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Feature Type: Road Asset
Job Number: 50152882 Defect Number: 42147471

Enquiry No.: 1693013 Logged by: [REDACTED] on: 05/02/2024 08:26
Service: Roads General Subject: Street Furniture: Defective Classification: Request for service
Desc.: [REDACTED]
Mentioned @Edinburgh_CC
an hour ago
@Edinburgh_CC there is one of the bollards at the side of the road on Granton road
Location: Granton Road Contact:

Enquiry No.: 1690833 Logged by: Verint CRM Connector on: 01/02/2024 13:29
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Road is crumbling and extremely rutted on corner of granton square and granton road, just outside the takaway. Drivers swerving to avoid it. Getting worse daily. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Feature Type: Road Asset

Enquiry No.: 1688804 Logged by: Verint CRM Connector on: 30/01/2024 10:09
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Massive pothole in road. Damage to my vehicle. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Feature Type: Road Asset

Enquiry No.: 1687561 Logged by: Verint CRM Connector on: 28/01/2024 15:42
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: There is liquid leaking in the middle of the road. Liquid coming out of the road. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Feature Type: Road Asset

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1671770 **Logged by:** Verint CRM Connector **on:** 04/01/2024 22:22
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: There is an road sign that has not been picked up at this location. It's either a 'Diversion' or 'Road Work' street sign which must have been left when the work was finished. Would it be possible to have it removed ?
Contact:
Many thanks

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset
Job Number: 50149410 **Defect Number:** 42143306

Enquiry No.: 1664335 **Logged by:** Verint CRM Connector **on:** 19/12/2023 21:30
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Pavement atbus stop 245010 subsiding
Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 1658384 **Logged by:** Verint CRM Connector **on:** 09/12/2023 10:32
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Hello, recurring pothole outside number 138 drive is back in less than a week. We need a better sollution that tarmac top up as the first bus that comes along flattens it and the problem is back in 3 days. Both vehicles belonging to 138 leave the drive and are getting damaged because of this. We'd like to discuss dropping the kerb further as a longer term solution. Please get in touch and not have an automated reply. I'd like to speak to a human about this.
Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset
Job Number: 50147728 **Defect Number:** 42141627

Enquiry No.: 1652092 **Logged by:** Verint CRM Connector **on:** 28/11/2023 13:13
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Hello, there is another 2 potholes infront of our drive caused by busses pulling in. The pot hole has been repaired repeatedly but after a few weeks returns and it is causing damage to the underside of our vehicles.
Contact:

Can it be repaired and could we discuss having the payment lowered so there is less of a drop for our cars in the expectation that is is going eroding away as long as this is a bus stop is there?

Many thanks

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset
Job Number: 50146771 **Defect Number:** 42140622

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1650236 **Logged by:** Verint CRM Connector **on:** 24/11/2023 14:49
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Other.
Location:Pavement.
Type:Foliage / Bush
Location: 144/146 Granton Road eh5 3rf **Contact:**

Enquiry No.: 1644976 **Logged by:** Verint CRM Connector **on:** 15/11/2023 15:24
Service: Roads General **Subject:** Road: Missing Setts / Blocks **Classification:** Customer Emergency
Desc.:
Location: the drains are overflowing with weeds and debris, they are causing large puddles making it dangerous to cross the road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 1600942 **Logged by:** Verint CRM Connector **on:** 20/08/2023 16:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Outside house 138 there is a series of potholes in the run up to the bus stop getting worse. They are now causing vehicles leaving 138s drive to bottom out. The erosion is after the kerb and has eroded away the yellow lines completely. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50141271 **Defect Number:** 42134454

Enquiry No.: 1600759 **Logged by:** Verint CRM Connector **on:** 20/08/2023 00:11
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Verge / Grass area .
Type:Foliage / Bush
Location: Neighbour's garden is absolutely disgusting. Rats and foxes run amock as the garden hasn't been maintained in the four years i have lived here. Is becoming a health hazard now. The garden is in the communal area. The flat is usually rented out. The address the garden belongs to is [REDACTED]. Also their wheelie bins are overflowing. **Contact:**

Enquiry No.: 1592051 **Logged by:** Stuart Wright **on:** 03/08/2023 16:25
Service: Roads General **Subject:** Public Utilities: General **Classification:** General Enquiry
Desc.: Pls can temporary traffic light sign be removed from pavement
Location: o/s no 18 **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Job Number: 50140459 **Defect Number:** 42133347

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1590356 Logged by: Verint CRM Connector on: 31/07/2023 21:48
Service: Roads General Subject: Public Utilities: General Classification: Request for service
Desc.:

Location: Sorry this is not a fault as such but I didn't know where else to report it. I am going to have to make up a 'dummy' defect in order to continue with this form. Temporary traffic lights were set up on Granton Road (at old railway bridge) on Wed 26th July and (as far as I can see) there has been no works done whatsoever. I do not even think anyone has been working there, as I have never seen anyone there. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Feature Type: Road Asset

Enquiry No.: 1579317 Logged by: Verint CRM Connector on: 10/07/2023 16:21
Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service
Desc.: Problem: Causing Obstruction.

Location: Pavement.
Type: Foliage / Bush
Location: Overhanging bushes/trees causing obstruction to pedestrians. Contact:

Enquiry No.: 1570504 Logged by: Verint CRM Connector on: 22/06/2023 11:05
Service: Roads General Subject: Public Utilities: General Classification: Request for service
Desc.:

Location: There are two sandbags and an 'end of diversion' road sign that has been left on the pavement for many weeks now. It is leaning against the wall of [redacted] by the lamppost there. It was previously left blocking [redacted] vision when exiting their drive so my [redacted] and I moved it next to some other work signs on the pavement, hoping the workmen would take it when they removed their temporary traffic light signs, but they have gone this morning but not the old signs. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Feature Type: Road Asset

Job Number: 50138273 Defect Number: 42130631

Enquiry No.: 1563474 Logged by: Verint CRM Connector on: 07/06/2023 14:10
Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service
Desc.: Problem: Causing Obstruction.

Location: Pavement.
Type: Foliage / Bush
Location: Overhanging bushes and hedging on pavement making it hard to pass, also at bus stop. Contact:

Enquiry No.: 1541200 Logged by: Verint CRM Connector on: 22/04/2023 10:33
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:

Location: Two huge potholes immediately outside the entrance to Millenum Garage Contact:

Plot Number: 1.00 Feature Id - Location: Ward 4 - Ferry Road to south-east corner of Granton Square Feature Type: Road Asset

Job Number: 50134789 Defect Number: 42125812

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1505976 **Logged by:** Verint CRM Connector **on:** 06/02/2023 20:30
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Hedge outside 1a Granton Road is so bushy, impossible for 2 people to pass safely. **Contact:**
Given v busy road, with traffic lights just close-by, if someone is coming one-way,
you have to signal to him/her to go ahead, wait since if try to pass by at same time,
one of you has to step into road. Incredibly dangerous. Have seen mums with
buggies and young children struggling to get by safely. Same for older people with
sticks, rollators etc. If hedge aligned with wall on which it sits, would be safer. Much

Enquiry No.: 1502857 **Logged by:** Verint CRM Connector **on:** 31/01/2023 22:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There's several potholes on the road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset
Job Number: 50128193 **Defect Number:** 42117212

Enquiry No.: 1498743 **Logged by:** Verint CRM Connector **on:** 24/01/2023 21:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Debris left over from cabling works in the road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 1498357 **Logged by:** Verint CRM Connector **on:** 24/01/2023 12:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Debris from cable installation blocking gutter, drain, and hazard to cyclists and traffic. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 1493864 **Logged by:** Verint CRM Connector **on:** 16/01/2023 21:20
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There are pretty big potholes appeared in the road. One is long and thin where the tarmac has collapsed in on itself and the other is a deeper hole at the same area of the road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset

Enquiry No.: 1482713 **Logged by:** Verint CRM Connector **on:** 01/01/2023 21:23
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: At the bottom of the road before entering granton square from granton road potholes and cracked crumbling road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 4 - Ferry Road to south-east corner of Granton Square **Feature Type:** Road Asset
Job Number: 50125379 **Defect Number:** 42114179

Site History Report

Effective: 01/01/2023 to 11/02/2026
 Service: Roads General
 Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 4 - Ferry Road to south-east corner of Granton Square		Feature Type: Road Asset		Area: North West Locality	
50125379	Road: Defective / Damaged (Enquiry 1482713) pothole on carriageway (RD: CW Pothole)	Junction Granton Square	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/01/2023	10/01/2023	Act. ROAD/82070270
50125971	1no pothole (RD: CW Pothole)	Outside no136	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/01/2023	30/01/2023	Act. ROAD/82070691
50128192	Gully: Blocked/Needs Clean - What is the problem with the gully : blocked. What surface is the gully on : road (Enquiry 1502636)gully chocked (Gully: Blocked / Flooding)	Outside Ashworth and Thomson	RG: Gully - Standard Priority	Cleaned and Working	02/02/2023	18/02/2023	Act. RDGC/14/82005195
50128193	Road: Defective / Damaged (Enquiry 1502857) pothole on carriageway (RD: CW Pothole)	Outside Waterfront Takeaway	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/02/2023	05/02/2023	Act. ROAD/82072217
50128780	Gully: Blocked/Needs Clean - What is the problem with the gully : blocked. What surface is the gully on : road (Enquiry 1505928)gully chocked (Gully: Blocked / Flooding)	Outside 189	RG: Gully - Standard Priority	Job Complete	08/02/2023	18/02/2023	Act. ROAD/82072532
50129321	1 carriageway pothole (RD: CW Pothole)	Outside 142	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/02/2023	17/02/2023	Act. ROAD/82072854
50131278	1no pothole (RD: CW Pothole)	Outside Patches pet supplies	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/03/2023	08/03/2023	Act. ROAD/82073919
50132157	Pothole on carriageway (RD: CW Pothole)	Outside 164	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	16/03/2023	17/03/2023	Act. ROAD/82074407
50132185	Pothole on carriageway (RD: CW Pothole)	Outside 1 at traffic lights	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/03/2023	20/03/2023	Act. ROAD/82074424
50133699	2no potholes (RD: CW Pothole)	Outside no144	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/04/2023	06/04/2023	Act. ROAD/82075339
50134789	Road: Defective / Damaged (Enquiry 1541200) pothole on carriageway (RD: CW Pothole)	Outside entrance to Millennium motors	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	24/04/2023	24/04/2023	Act. ROAD/82076186
50135907	1 carriageway pothole (RD: CW Pothole)	Opposite waterfront cafe	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/05/2023	12/05/2023	Act. ROAD/82077044
50137138	Pothole on carriageway (RD: CW Pothole)	Junction Granton Square	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/06/2023	02/06/2023	Act. ROAD/82077863
50137139	Pothole on carriageway (RD: CW Pothole)	Outside 7	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/06/2023	02/06/2023	Act. ROAD/82077864
50140231	Repair damaged coping and replace missing railings (RD: Railing Damage/Missing/New)	Opposite Lufra Bank	RD: Cat 3 - 60 Day	Job Complete	01/08/2023	12/09/2023	Act. ROAD/82079613
50140801	Pothole on carriageway (RD: CW Pothole)	Outside 174	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/08/2023	10/08/2023	Act. ROAD/82079917

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 4 - Ferry Road to south-east corner of Granton Square		Feature Type: Road Asset		Area: North West Locality	
50141173	Pothole on carriageway (RD: CW Traffic island outside 30 Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/08/2023	18/08/2023	Act. ROAD/82080069
50141271	Road: Defective / Damaged (Enquiry 1600942) pothole on carriageway (RD: CW Pothole)	Outside 138	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/08/2023	21/08/2023	Act. ROAD/82080119
50144240	Pothole on carriageway (RD: CW Pothole)	Outside 95	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	19/10/2023	19/10/2023	Act. ROAD/82081767
50144857	Flooding carriageway and footway (Gully: Blocked / Flooding)	Junction Granton Square	RG: Gully - Standard Priority	Job Complete	02/11/2023	22/11/2023	Act. RDGC14/82005856
50144859	Pothole on carriageway (RD: CW Pothole)	Outside Waterfront Takeaway	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/11/2023	02/11/2023	Act. ROAD/82082238
50146769	Pothole on footway (RD: FW HRA Pothole)	Outside 146	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/11/2023	29/11/2023	Act. ROAD/82083260
50146770	Pothole on carriageway (RD: CW Pothole)	Junction Grirson Avenue	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/11/2023	29/11/2023	Act. ROAD/82083261
50146771	Road: Defective / Damaged (Enquiry 1652092) pothole on carriageway (RD: CW Pothole)	Outside 136	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/11/2023	29/11/2023	Act. ROAD/82083262
50146844	Pothole on carriageway (RD: CW Pothole)	Outside 11	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/11/2023	01/12/2023	Act. ROAD/82083308
50147728	Road: Defective / Damaged (Enquiry 1658384) pothole on carriageway (RD: CW Pothole)	Outside 138	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/12/2023	13/12/2023	Act. ROAD/82083822
50149410	Pavement: Damaged / Defective (Enquiry 1671770) uplift sign (RD: Other Defect Type)	Outside 215	RD: Cat 3 - 60 Day	Job Complete	05/01/2024	22/02/2024	Act. ROAD/82084961
50151737	Pothole on carriageway (RD: CW Pothole)	Outside Wardie residents club	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/01/2024	01/02/2024	Act. ROAD/82086528
50151740	Pothole on carriageway (RD: CW Pothole)	Outside 164,174	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/01/2024	06/02/2024	Act. ROAD/82086530
50152882	Pothole on carriageway (RD: CW Pothole)	Outside Waterfront Cafe	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/02/2024	14/02/2024	Act. ROAD/82087339
50153286	Gully choked (Gully: Blocked / Flooding)	Junction Granton Square	RG: Gully - Standard Priority	Gully: Investigation Required	19/02/2024	19/05/2024	Est. RDGC14/82006130
50153287	Pothole on footway (RD: FW HRA Pothole)	Junction Granton Square	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/02/2024	28/02/2024	Act. ROAD/82087595
50155111	Road: Defective / Damaged (Enquiry 1706507) (RD: CW Pothole)	Outside drive to 138 remove loose and make safe	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/03/2024	09/03/2024	Act. ROAD/82088922
50157716	Pothole on carriageway (RD: CW Pothole)	Heading south from Rosebank Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/04/2024	17/04/2024	Act. ROAD/82090773
50158442	Pothole on carriageway (RD: CW Pothole)	Junction Wardie Crescent	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/04/2024	16/04/2024	Act. ROAD/82091334

Site History Report

Effective: 01/01/2023 to 11/02/2026
Service: Roads General
Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 4 - Ferry Road to south-east corner of Granton Square		Feature Type: Road Asset		Area: North West Locality	
50159586	Pothole on carriageway (RD: CW Outside 26,20,11 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	01/05/2024	02/05/2024	Act. ROAD/82092086
50159906	1no pothole (RD: CW Pothole)	At the junction with Fraser Avenue	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/05/2024	08/05/2024	Act. ROAD/82092274
50160866	Pothole on carriageway (RD: CW Outside 95 Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/05/2024	31/05/2024	Act. ROAD/82092804
50160946	Pothole on carriageway (RD: CW Outside 105a,primary school,99 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	24/05/2024	27/05/2024	Act. ROAD/82092841
50162595	Pothole on carriageway (RD: CW Outside 138 Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/06/2024	19/06/2024	Act. ROAD/82093938
50165519	Depression on carriageway (RD: CW Pothole)	Outside 134	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	19/08/2024	20/08/2024	Act. ROAD/82095722
50166020	Void in the carriageway at pedestrian crossing Please excavate investigate and reinstate (RD: CW Subsidence/Heaving)	Outside no132	RD: Cat 3 - 60 Day	Job Complete	02/09/2024	08/09/2024	Act. ROAD/82096002
50167329	Pothole on footway (RD: CW Pothole)	Outside 11,entrance to nursery	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/10/2024	04/10/2024	Act. ROAD/82096819
50167330	Pothole on carriageway (RD: CW Pothole)	Outside 44	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/10/2024	04/10/2024	Act. ROAD/82096820
50168141	1 cw pothole (RD: CW Pothole)	Opposite waterfront takeaway	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/10/2024	16/10/2024	Act. ROAD/82097339
50170419	Pothole on carriageway (RD: CW Pothole)	Outside 178	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/11/2024	28/11/2024	Act. ROAD/82098865
50170778	Loose / leaning pole angled dangerously into the road. Please cut down below ground level, dispose and make the hole safe from trips. Cheers (RD: Unlit Sign Damaged/Missing)	Opposite Patch's Pet Supplies	RD: Cat 2 - 5 Day	Job Complete	04/12/2024	05/12/2024	Act. ROAD/82099099
50176144	1 number pothole (RD: CW Pothole)	Outside number 105	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/02/2025	03/03/2025	Act. ROAD/82103383
50176145	1 number pothole (RD: CW Pothole)	105 Granton Road. Pothole on road.outside number 138	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	28/02/2025	03/03/2025	Act. ROAD/82103384
50178157	Pothole on carriageway (RD: CW Pothole)	Junction Rosebank Road,outside 79,99	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/04/2025	04/04/2025	Act. ROAD/82104841
50178158	Pothole on carriageway (RD: CW Pothole)	Entrance to Broughton Rugby Club	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/04/2025	04/04/2025	Act. ROAD/82104842
50178324	Pothole on carriageway (RD: CW Pothole)	Outside 164	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/04/2025	09/04/2025	Act. ROAD/82104957
50178492	Pothole on carriageway (RD: CW Pothole)	Outside Wardie residents club	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/04/2025	14/04/2025	Act. ROAD/82105066

Site History Report

Effective: 01/01/2023 to 11/02/2026
 Service: Roads General
 Site: Granton Road (7901430)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 4 - Ferry Road to south-east corner of Granton Square		Feature Type: Road Asset		Area: North West Locality	
50180324	Pothole on carriageway (RD: CW Pothole)	Outside 136	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/05/2025	26/05/2025	Act. ROAD/82106321
50180547	Permanent repair required (RD: CW Cracked/Broken)	Outside 138.	RD: Cat 3 - 60 Day	Job Committed	28/05/2025	20/08/2025	Est. ROAD/82106472
50181249	Pothole on carriageway (RD: CW Pothole)	Junction Inverleith Gardens heading east	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/06/2025	13/06/2025	Act. ROAD/82106902
50182974	Replace missing kerb (RD: FW Kerbs Damaged/Missing)	Outside 12	RD: Cat 3 - 60 Day	Job Complete	22/07/2025	11/08/2025	Act. ROAD/82107993
50187410	1no pothole (RD: CW Pothole)	Opposite Patch Pet Supplies	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/11/2025	27/11/2025	Act. ROAD/82110844
50188678	2 number potholes (RD: CW Pothole)	Outside number 140	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/12/2025	19/12/2025	Act. ROAD/82111797
50188841	1 number pothole (RD: CW Pothole)	Outside number 164	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/12/2025	29/12/2025	Act. ROAD/82111923
50189737	2 cw potholes (RD: CW Pothole)	At wardie crescent	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/01/2026	19/01/2026	Act. ROAD/82112676
50190294	2no potholes (RD: CW Pothole)	Outside 138	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/01/2026	27/01/2026	Act. ROAD/82113121
50190586	1no pothole (RD: CW Pothole)	Outside 158	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/01/2026	29/01/2026	Act. ROAD/82113359
50190590	1no Po (RD: CW Pothole)	Outside 125.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/01/2026	29/01/2026	Act. ROAD/82113361
50190874	Patch required approx 1.5x15m (RD: CW Cracked/Broken)	Outside 136	RD: Cat 4 - Programmed	Job Committed	31/01/2026		ROAD/82113742