

Site History Report

Effective: 24/12/2022 to 31/01/2025
Service: Roads General
Site: St Clair Street (7901314)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Site: St Clair Street (7901314)

Locality: Leith, Edinburgh, City of Edinburgh

Area: North East Locality

Customer Services

Enquiry No.: 1850166 **Logged by:** Verint CRM Connector **on:** 27/10/2024 20:26
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.: Edge of cover to inspection chamber on public footpath is sitting above the level of footpath causing serious trip hazard. I have tripped and fallen due to this hazard.
Location: **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50168724 **Defect Number:** 42167629

Enquiry No.: 1842779 **Logged by:** Verint CRM Connector **on:** 10/10/2024 08:33
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: hedge/bush growing across pavement forcing pedestrians into the road **Contact:**

Enquiry No.: 1830166 **Logged by:** Verint CRM Connector **on:** 11/09/2024 08:25
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Covers over half the pavement. **Contact:**

Enquiry No.: 1829975 **Logged by:** Verint CRM Connector **on:** 10/09/2024 18:40
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Due to the overgrown bush, the path is no longer passable when cars are parked adjacent. Pushing a buggy I had to cross the street to get down the road **Contact:**

Enquiry No.: 1594410 **Logged by:** Verint CRM Connector **on:** 08/08/2023 13:13
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: A very large tree in the block is completely blocking the pavement. It is in a front garden at [REDACTED], but spilling over the entire pavement rendering it unusable. **Contact:**

Enquiry No.: 1498198 **Logged by:** Verint CRM Connector **on:** 24/01/2023 09:45
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pot hole or holes... as soon as you turn off Easter road. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50127651 **Defect Number:** 42116603

Site History Report

Effective: 24/12/2022 to 31/01/2025

Service: Roads General

Site: St Clair Street (7901314)

Asset Number: 1.00 to 9.00

Display Action Officer: No
