

Effective: 18/02/2025 to 18/02/2026

Display Action Officer: No

Site: Meadows Magnet Sand Area Play Park (PL1227)

Site: Meadows Magnet Sand Area Play Park (PL1227)

Locality:

Area: South East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	9,001.00	Asset - Locn.:	East side of Melville drive	Feature Type:	PL: Play Area		Area:	South East Locality
Batch:	2015966 - Inspection Batch			Route:	PR: South East Route 2		Date:	21/01/2026
	No actionable defects found							
Batch:	2015489 - Inspection Batch			Route:	PR: South East Route 2		Date:	03/12/2025
	No actionable defects found							
Batch:	2013857 - Inspection Batch			Route:	PR: South East Route 2		Date:	06/11/2025
	No actionable defects found							
Batch:	2013574 - Inspection Batch			Route:	PR: South East Route 2		Date:	17/10/2025
	No actionable defects found							
Batch:	2013487 - Inspection Batch			Route:	PR: South East Route 2		Date:	01/10/2025
	No actionable defects found							
Batch:	2013353 - Inspection Batch			Route:	PR: South East Route 2		Date:	29/08/2025
	No actionable defects found							
Batch:	2011805 - Inspection Batch			Route:	PR: South East Route 2		Date:	20/03/2025
	No actionable defects found							
Asset:	9,002.00	Asset - Locn.:	SURFACE_59 - Play Safety Surface - Sand Surface	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015077 - Inspection Batch			Route:	Meadows Magnet Sand Area Play		Date:	27/11/2025
	No actionable defects found							
Batch:	2011991 - Inspection Batch			Route:	Meadows Magnet Sand Area Play		Date:	27/03/2025
	No actionable defects found							
Asset:	9,003.00	Asset - Locn.:	EQUIPMENT_221 - Multiplay - Toddler - Sandworks	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015083 - Inspection Batch			Route:	Meadows Magnet Sand Area Play		Date:	27/11/2025
	No actionable defects found							
Batch:	2011998 - Inspection Batch			Route:	Meadows Magnet Sand Area Play		Date:	27/03/2025
	No actionable defects found							
Asset:	9,004.00	Asset - Locn.:	EQUIPMENT_294 - Multiplay - Junior - Fantasia Adventure Hou:	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015082 - Inspection Batch			Route:	Meadows Magnet Sand Area Play		Date:	27/11/2025
	No actionable defects found							
Batch:	2011997 - Inspection Batch			Route:	Meadows Magnet Sand Area Play		Date:	27/03/2025
	No actionable defects found							
Asset:	9,005.00	Asset - Locn.:	EQUIPMENT_459 - Rocking - Superspring See-Saw	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015081 - Inspection Batch			Route:	Meadows Magnet Sand Area Play		Date:	27/11/2025
	No actionable defects found							
Batch:	2011996 - Inspection Batch			Route:	Meadows Magnet Sand Area Play		Date:	27/03/2025
	No actionable defects found							

Effective: 18/02/2025 to 18/02/2026

Display Action Officer: No

Site: Meadows Magnet Sand Area Play Park (PL1227)

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	9,006.00	Asset - Locn.:	EQUIPMENT_548 - Sand - Sand Table, Starfish	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015080 - Inspection Batch			Route:	Meadows Magnet Sand Area Play			Date: 27/11/2025
	No actionable defects found							
Batch:	2011994 - Inspection Batch			Route:	Meadows Magnet Sand Area Play			Date: 27/03/2025
	No actionable defects found							
Asset:	9,007.00	Asset - Locn.:	EQUIPMENT_549 - Sand - Sand Table, Starfish	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015079 - Inspection Batch			Route:	Meadows Magnet Sand Area Play			Date: 27/11/2025
	No actionable defects found							
Batch:	2011993 - Inspection Batch			Route:	Meadows Magnet Sand Area Play			Date: 27/03/2025
	No actionable defects found							
Asset:	9,008.00	Asset - Locn.:	EQUIPMENT_550 - Sand - Rotating Table	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015078 - Inspection Batch			Route:	Meadows Magnet Sand Area Play			Date: 27/11/2025
	No actionable defects found							
Batch:	2011992 - Inspection Batch			Route:	Meadows Magnet Sand Area Play			Date: 27/03/2025
	No actionable defects found							
Asset:	9,010.00	Asset - Locn.:	FIXTURE_154 - Seating - Seating	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015085 - Inspection Batch			Route:	Meadows Magnet Sand Area Play			Date: 27/11/2025
	No actionable defects found							
Batch:	2012000 - Inspection Batch			Route:	Meadows Magnet Sand Area Play			Date: 27/03/2025
	No actionable defects found							
Asset:	9,011.00	Asset - Locn.:	FIXTURE_253 - Table - Picnic Table	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015084 - Inspection Batch			Route:	Meadows Magnet Sand Area Play			Date: 27/11/2025
	No actionable defects found							
Batch:	2011999 - Inspection Batch			Route:	Meadows Magnet Sand Area Play			Date: 27/03/2025
	No actionable defects found							
Asset:	9,012.00	Asset - Locn.:	BIN_81 - Bin - BIN	Feature Type:	Play Equipment		Area:	South East Locality
Batch:	2015086 - Inspection Batch			Route:	Meadows Magnet Sand Area Play			Date: 27/11/2025
	No actionable defects found							
Batch:	2012001 - Inspection Batch			Route:	Meadows Magnet Sand Area Play			Date: 27/03/2025
	No actionable defects found							

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order	
Asset:	9,001.00	Asset - Locn.:	East side of Melville drive	Feature Type:	PL: Play Area		Area:	South East Locality
30000784	Trip hazard on worn surface (PL: Magnet sand Play Surface Damaged Worn)		Parks - Low	Job Complete	01/10/2024	29/04/2025	Act. PGPT14/642	
Asset:	9,002.00	Asset - Locn.:	SURFACE_59 - Play Safety Surface - Sand Surface	Feature Type:	Play Equipment		Area:	South East Locality
30000426	Sand level low		Parks - Medium	Job Complete	28/02/2024	29/04/2025	Act.	

Effective: 18/02/2025 to 18/02/2026

Display Action Officer: No

Site: Meadows Magnet Sand Area Play Park (PL1227)
