

Effective: 18/02/2025 to 18/02/2026

Display Action Officer: No

Site: Meadows Toddlers Play Park (PL1193)

Site: Meadows Toddlers Play Park (PL1193)

Locality:

Area: South East Locality

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	9,000.00	<b>Asset - Locn.:</b>	East side of Melville drive	<b>Feature Type:</b>	PL: Play Area		<b>Area:</b>	South East Locality
<b>Batch:</b>	2015964 - Inspection Batch			<b>Route:</b>	PR: South East Route 2		<b>Date:</b>	21/01/2026
	No actionable defects found							
<b>Batch:</b>	2015487 - Inspection Batch			<b>Route:</b>	PR: South East Route 2		<b>Date:</b>	03/12/2025
	No actionable defects found							
<b>Batch:</b>	2013860 - Inspection Batch			<b>Route:</b>	PR: South East Route 2		<b>Date:</b>	06/11/2025
	No actionable defects found							
<b>Batch:</b>	2013572 - Inspection Batch			<b>Route:</b>	PR: South East Route 2		<b>Date:</b>	17/10/2025
	No actionable defects found							
<b>Batch:</b>	2013485 - Inspection Batch			<b>Route:</b>	PR: South East Route 2		<b>Date:</b>	01/10/2025
	No actionable defects found							
<b>Batch:</b>	2013350 - Inspection Batch			<b>Route:</b>	PR: South East Route 2		<b>Date:</b>	29/08/2025
	No actionable defects found							
<b>Batch:</b>	2011713 - Inspection Batch			<b>Route:</b>	PR: South East Route 2		<b>Date:</b>	20/03/2025
	No actionable defects found							
<b>Asset:</b>	9,065.00	<b>Asset - Locn.:</b>	SURFACE_35 - Play Safety Surface - Grass Surface	<b>Feature Type:</b>	Play Equipment		<b>Area:</b>	South East Locality
<b>Batch:</b>	2015070 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	27/11/2025
	No actionable defects found							
<b>Batch:</b>	2012733 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	17/04/2025
	No actionable defects found							
<b>Asset:</b>	9,066.00	<b>Asset - Locn.:</b>	EQUIPMENT_283 - Multiplay - Junior - Tot-Lot No4 Multiunit	<b>Feature Type:</b>	Play Equipment		<b>Area:</b>	South East Locality
<b>Batch:</b>	2015068 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	27/11/2025
	No actionable defects found							
<b>Batch:</b>	2012736 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	17/04/2025
	No actionable defects found							
<b>Asset:</b>	9,068.00	<b>Asset - Locn.:</b>	EQUIPMENT_89 - Carousel - Tulip Roundabout	<b>Feature Type:</b>	Play Equipment		<b>Area:</b>	South East Locality
<b>Batch:</b>	2015066 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	27/11/2025
	No actionable defects found							
<b>Batch:</b>	2012732 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	17/04/2025
	No actionable defects found							
<b>Asset:</b>	9,069.00	<b>Asset - Locn.:</b>	EQUIPMENT_658 - Swing - 2 Bay, 4 Cradles Swing	<b>Feature Type:</b>	Play Equipment		<b>Area:</b>	South East Locality
<b>Batch:</b>	2015069 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	27/11/2025
	No actionable defects found							
<b>Batch:</b>	2012731 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	17/04/2025
	No actionable defects found							

Effective: 18/02/2025 to 18/02/2026

Display Action Officer: No

Site: Meadows Toddlers Play Park (PL1193)

**Condition Survey**

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	9,070.00	<b>Asset - Locn.:</b>	FIXTURE_132 - Seating - Seating	<b>Feature Type:</b>	Play Equipment		<b>Area:</b>	South East Locality
<b>Batch:</b>	2015073 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	27/11/2025
	No actionable defects found							
<b>Batch:</b>	2012737 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	17/04/2025
	No actionable defects found							
<b>Asset:</b>	9,071.00	<b>Asset - Locn.:</b>	FIXTURE_249 - Table - Picnic Table	<b>Feature Type:</b>	Play Equipment		<b>Area:</b>	South East Locality
<b>Batch:</b>	2015072 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	27/11/2025
	No actionable defects found							
<b>Batch:</b>	2012734 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	17/04/2025
	No actionable defects found							
<b>Asset:</b>	9,072.00	<b>Asset - Locn.:</b>	FIXTURE_29 - Play Area Gate - Gate	<b>Feature Type:</b>	Play Equipment		<b>Area:</b>	South East Locality
<b>Batch:</b>	2015071 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	27/11/2025
	No actionable defects found							
<b>Batch:</b>	2012729 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	17/04/2025
	No actionable defects found							
<b>Asset:</b>	9,073.00	<b>Asset - Locn.:</b>	FIXTURE_308 - Play Area Boundary - Fencing	<b>Feature Type:</b>	Play Equipment		<b>Area:</b>	South East Locality
<b>Batch:</b>	2015074 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	27/11/2025
2001184	Requires repaired.	27/11/2025		PL: Vandalised Equip or Mater	Internal		Committed	30001209
<b>Batch:</b>	2012739 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	17/04/2025
	No actionable defects found							
<b>Asset:</b>	9,074.00	<b>Asset - Locn.:</b>	EQUIPMENT_436 - Rocking - Tube See-Saw	<b>Feature Type:</b>	Play Equipment		<b>Area:</b>	South East Locality
<b>Batch:</b>	2015067 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	27/11/2025
	No actionable defects found							
<b>Batch:</b>	2012730 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	17/04/2025
	No actionable defects found							
<b>Asset:</b>	9,076.00	<b>Asset - Locn.:</b>	FIXTURE_700 - Fencing	<b>Feature Type:</b>	Play Equipment		<b>Area:</b>	South East Locality
<b>Batch:</b>	2015076 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	27/11/2025
	No actionable defects found							
<b>Batch:</b>	2012735 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	17/04/2025
	No actionable defects found							
<b>Asset:</b>	9,079.00	<b>Asset - Locn.:</b>	Play Safety Surface - Rubber	<b>Feature Type:</b>	Play Equipment		<b>Area:</b>	South East Locality
<b>Batch:</b>	2015075 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	27/11/2025
	No actionable defects found							
<b>Batch:</b>	2012738 - Inspection Batch			<b>Route:</b>	Meadows Toddlers Play Park		<b>Date:</b>	17/04/2025
	No actionable defects found							

Effective: 18/02/2025 to 18/02/2026

Display Action Officer: No

Site: Meadows Toddlers Play Park (PL1193)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 9,000.00	<b>Asset - Locn.:</b> East side of Melville drive		<b>Feature Type:</b> PL: Play Area		<b>Area:</b> South East Locality	
30000663	Worn soils by main gate trip hazard on slabs (PL: Play Surface Damaged Worn)		Parks - Low	Job Complete	21/08/2024	30/04/2025 Act.	PGPT14/524
30000685	Nettles (PL: Vegetation overgrown)	Right of entrance gate	Parks - Low	Job Committed	28/08/2024		PGPT14/546
	<b>Asset:</b> 9,073.00	<b>Asset - Locn.:</b> FIXTURE_308 - Play Area Boundary - Fencing		<b>Feature Type:</b> Play Equipment		<b>Area:</b> South East Locality	
30001209	Requires repaired. (PL: Vandalised Equip or Mater)		Parks - Low	Job Complete	27/11/2025	29/01/2026 Act.	PGPT14/1056
	<b>Asset:</b> 9,074.00	<b>Asset - Locn.:</b> EQUIPMENT_436 - Rocking - Tube See-Saw		<b>Feature Type:</b> Play Equipment		<b>Area:</b> South East Locality	
30000590	Clicking new external (PL: Worn Equipment)		Parks - Low	PL: Pass to Contractor	15/05/2024		PGPT14/463