

Site History Report

Effective: 24/01/2023 to 23/02/2026
Service: Roads General
Site: Brunton Place (7903969)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Site: Brunton Place (7903969)

Locality: Broughton, Edinburgh, City of Edinburgh

Area: South East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Whole Street			Feature Type: Road Asset			Area: South East Locality	
Batch: 41254979	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 23/02/2026
Batch: 41253350	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 14/02/2026
Batch: 41252158	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 07/02/2026
Batch: 41251241	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 31/01/2026
Batch: 41250823	- Inspection Batch No actionable defects found			Route: SfP_NorthEast				Date: 28/01/2026
Batch: 41250612	- Inspection Batch No actionable defects found			Route: South Mobile Inspection Route				Date: 27/01/2026
Batch: 41250345	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 26/01/2026
Batch: 41249004	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 19/01/2026
Batch: 41247919	- Inspection Batch			Route: Ad hoc Route				Date: 12/01/2026
42196401	6 no potholes	12/01/2026	Opposite no 12 Brunton place	RD: CW Pothole	Internal		Committed	50189491
Batch: 41247917	- Inspection Batch			Route: Ad hoc Route				Date: 12/01/2026
42196398	Gully brander needs reset and tar surround	12/01/2026	brunton place bus stop city bound opposite no 12	RD: Gully Damaged/Sunken	Internal		Committed	50189489
Batch: 41247528	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 10/01/2026
Batch: 41247354	- Inspection Batch No actionable defects found			Route: NE_LondonRd_3Month				Date: 08/01/2026
Batch: 41245841	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 22/12/2025
Batch: 41245254	- Inspection Batch No actionable defects found			Route: South Mobile Inspection Route				Date: 18/12/2025
Batch: 41244843	- Inspection Batch No actionable defects found			Route: SfP_NorthEast				Date: 16/12/2025
Batch: 41244172	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 11/12/2025
Batch: 41243060	- Inspection Batch No actionable defects found			Route: SfP_NorthEast				Date: 28/11/2025

Site History Report

Effective: 24/01/2023 to 23/02/2026
Service: Roads General
Site: Brunton Place (7903969)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41241879 - Inspection Batch				Route: South Mobile Inspection Route			Date: 18/11/2025	
42193505	2no potholes	18/11/2025	Opposite no11	RD: CW Pothole	Internal		Committed	50187143
42193504	1no pothole	18/11/2025	Opposite no9	RD: CW Pothole	Internal		Committed	50187142
Batch: 41239270 - Inspection Batch				Route: SfP_NorthEast			Date: 21/10/2025	
No actionable defects found								
Batch: 41238840 - Inspection Batch				Route: South Mobile Inspection Route			Date: 15/10/2025	
No actionable defects found								
Batch: 41238230 - Inspection Batch				Route: NE_LondonRd_3Month			Date: 08/10/2025	
No actionable defects found								
Batch: 41236727 - Inspection Batch				Route: South Mobile Inspection Route			Date: 12/09/2025	
No actionable defects found								
Batch: 41235865 - Inspection Batch				Route: SfP_NorthEast			Date: 02/09/2025	
No actionable defects found								
Batch: 41235319 - Inspection Batch				Route: Ad hoc Route			Date: 25/08/2025	
42188935	Please refresh yellow box junction markings	25/08/2025	At the junction with Easter Road	RD: Markings Refresh	Internal		Uncommitted	50183986
Batch: 41234582 - Inspection Batch				Route: South Mobile Inspection Route			Date: 12/08/2025	
No actionable defects found								
Batch: 41234134 - Inspection Batch				Route: SfP_NorthEast			Date: 04/08/2025	
No actionable defects found								
Batch: 41233200 - Inspection Batch				Route: SfP_NorthEast			Date: 17/07/2025	
No actionable defects found								
Batch: 41232908 - Inspection Batch				Route: South Mobile Inspection Route			Date: 14/07/2025	
No actionable defects found								
Batch: 41232009 - Inspection Batch				Route: NE_LondonRd_3Month			Date: 30/06/2025	
No actionable defects found								
Batch: 41230730 - Inspection Batch				Route: SfP_NorthEast			Date: 11/06/2025	
No actionable defects found								
Batch: 41230410 - Inspection Batch				Route: South Mobile Inspection Route			Date: 09/06/2025	
No actionable defects found								
Batch: 41228115 - Inspection Batch				Route: SfP_NorthEast			Date: 13/05/2025	
No actionable defects found								
Batch: 41227834 - Inspection Batch				Route: South Mobile Inspection Route			Date: 07/05/2025	
No actionable defects found								
Batch: 41226814 - Inspection Batch				Route: NE_LondonRd_3Month			Date: 26/04/2025	
42182182	1 pothole	25/04/2025	Opposite 12 on crossing point	RD: CW Pothole	Internal		Committed	50179087

Site History Report

Effective: 24/01/2023 to 23/02/2026

Service: Roads General

Site: Brunton Place (7903969)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41225977	- Inspection Batch No actionable defects found			Route: SfP_NorthEast				Date: 14/04/2025
Batch: 41225697	- Inspection Batch No actionable defects found			Route: South Mobile Inspection Route				Date: 09/04/2025
Batch: 41224563	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 30/03/2025
Batch: 41223862	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 24/03/2025
Batch: 41223634	- Inspection Batch No actionable defects found			Route: SfP_NorthEast				Date: 20/03/2025
Batch: 41222915	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 16/03/2025
Batch: 41222477	- Inspection Batch No actionable defects found			Route: South Mobile Inspection Route				Date: 12/03/2025
Batch: 41221578	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 05/03/2025
Batch: 41220973	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 28/02/2025
Batch: 41220418	- Inspection Batch No actionable defects found			Route: SfP_NorthEast				Date: 24/02/2025
Batch: 41219882	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 20/02/2025
Batch: 41218831	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 12/02/2025
Batch: 41218529	- Inspection Batch No actionable defects found			Route: South Mobile Inspection Route				Date: 11/02/2025
Batch: 41218105	- Inspection Batch No actionable defects found			Route: NE_LondonRd_3Month				Date: 07/02/2025
Batch: 41217013	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 30/01/2025
Batch: 41216047	- Inspection Batch No actionable defects found			Route: SfP_NorthEast				Date: 22/01/2025
Batch: 41215649	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic				Date: 20/01/2025
Batch: 41215182	- Inspection Batch			Route: NE_LondonRd_3Month				Date: 17/01/2025
42173344	Renew grano at catv box	17/01/2025	At brunton terrace	RD: FW Grano Cracked/Broken	Internal		Committed	50173078

Site History Report

Effective: 24/01/2023 to 23/02/2026
 Service: Roads General
 Site: Brunton Place (7903969)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch:	41213842 - Inspection Batch			Route: South Mobile Inspection Route			Date: 10/01/2025	
42172647	2no potholes	10/01/2025	Opposite no11	RD: CW Pothole	Internal		Committed	50172590
42172644	1no pothole	10/01/2025	At the corner of Hillside Crescent	RD: CW Pothole	Internal		Committed	50172587
42172648	4no potholes	10/01/2025	Opposite no7	RD: CW Pothole	Internal		Committed	50172591
Batch:	41211218 - Inspection Batch			Route: SfP_NorthEast			Date: 16/12/2024	
No actionable defects found								
Batch:	41210415 - Inspection Batch			Route: South Mobile Inspection Route			Date: 10/12/2024	
No actionable defects found								
Batch:	41208449 - Inspection Batch			Route: SfP_NorthEast			Date: 22/11/2024	
No actionable defects found								
Batch:	41207459 - Inspection Batch			Route: South Mobile Inspection Route			Date: 12/11/2024	
No actionable defects found								
Batch:	41206023 - Inspection Batch			Route: NE_LondonRd_3Month			Date: 31/10/2024	
42168135	Grano broken at catv box	31/10/2024	Outside no12	RD: FW Grano Cracked/Broken	Internal		Uncommitted	50144337
Batch:	41204450 - Inspection Batch			Route: SfP_NorthEast			Date: 21/10/2024	
No actionable defects found								
Batch:	41203152 - Inspection Batch			Route: South Mobile Inspection Route			Date: 11/10/2024	
No actionable defects found								
Batch:	41201489 - Inspection Batch			Route: SfP_NorthEast			Date: 26/09/2024	
No actionable defects found								
Batch:	41201415 - Inspection Batch			Route: NE_LondonRd_3Month			Date: 25/09/2024	
No actionable defects found								
Batch:	41200387 - Inspection Batch			Route: South Mobile Inspection Route			Date: 10/09/2024	
No actionable defects found								
Batch:	41200004 - Inspection Batch			Route: SfP_NorthEast			Date: 05/09/2024	
No actionable defects found								
Batch:	41198850 - Inspection Batch			Route: South Mobile Inspection Route			Date: 15/08/2024	
No actionable defects found								
Batch:	41198247 - Inspection Batch			Route: SfP_NorthEast			Date: 07/08/2024	
No actionable defects found								
Batch:	41198187 - Inspection Batch			Route: NE_LondonRd_3Month			Date: 06/08/2024	
No actionable defects found								
Batch:	41197563 - Inspection Batch			Route: SfP_NorthEast			Date: 26/07/2024	
No actionable defects found								
Batch:	41197004 - Inspection Batch			Route: South Mobile Inspection Route			Date: 18/07/2024	
No actionable defects found								

Site History Report

Effective: 24/01/2023 to 23/02/2026

Service: Roads General

Site: Brunton Place (7903969)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch:	41196651 - Inspection Batch No actionable defects found			Route: SfP_NorthEast		Date: 15/07/2024		
Batch:	41195378 - Inspection Batch			Route: NE_LondonRd_3Month		Date: 26/06/2024		
42160306	Grano broken at catv box	26/06/2024	Outside no12	RD: FW Grano Cracked/Broken	Internal	No Action Required		
Batch:	41194787 - Inspection Batch No actionable defects found			Route: SfP_NorthEast		Date: 18/06/2024		
Batch:	41194764 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route		Date: 18/06/2024		
Batch:	41192233 - Inspection Batch No actionable defects found			Route: SfP_NorthEast		Date: 17/05/2024		
Batch:	41191964 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route		Date: 14/05/2024		
Batch:	41189568 - Inspection Batch			Route: NE_LondonRd_3Month		Date: 15/04/2024		
42154758	Grano broken at catv box	15/04/2024	Outside no12	RD: FW Grano Cracked/Broken	Internal	No Action Required		
Batch:	41188967 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route		Date: 09/04/2024		
Batch:	41187618 - Inspection Batch			Route: Ad hoc Route		Date: 26/03/2024		
42153005	10no potholes	26/03/2024	Opposite no12	RD: CW Pothole	Internal	Committed	50156821	
Batch:	41187589 - Inspection Batch No actionable defects found			Route: SfP_NorthEast		Date: 25/03/2024		
Batch:	41185887 - Inspection Batch			Route: South Mobile Inspection Route		Date: 12/03/2024		
42151229	8 cw potholes	12/03/2024	Opposite brunton terrace	RD: CW Pothole	Internal	Committed	50155539	
Batch:	41185650 - Inspection Batch			Route: Ad hoc Route		Date: 11/03/2024		
42151054	1 pothole	11/03/2024	Outside 10	RD: CW Pothole	Internal	Committed	50155403	
Batch:	41184182 - Inspection Batch No actionable defects found			Route: SfP_NorthEast		Date: 28/02/2024		
Batch:	41183194 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route		Date: 21/02/2024		
Batch:	41179967 - Inspection Batch No actionable defects found			Route: SfP_NorthEast		Date: 25/01/2024		
Batch:	41179890 - Inspection Batch			Route: NE_LondonRd_3Month		Date: 24/01/2024		
42144958	Grano broken at catv box	24/01/2024	Outside no12	RD: FW Grano Cracked/Broken	Internal	No Action Required		
Batch:	41179518 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route		Date: 22/01/2024		
Batch:	41175322 - Inspection Batch No actionable defects found			Route: SfP_NorthEast		Date: 21/12/2023		

Site History Report

Effective: 24/01/2023 to 23/02/2026

Service: Roads General

Site: Brunton Place (7903969)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch:	41175120 - Inspection Batch			Route: South Mobile Inspection Route			Date: 20/12/2023	
42142539	7no potholes	20/12/2023	Opposite between nos8-10	RD: CW Pothole	Internal		Committed	50148639
Batch:	41173751 - Inspection Batch			Route: SfP_NorthEast			Date: 07/12/2023	
No actionable defects found								
Batch:	41172860 - Inspection Batch			Route: Ad hoc Route			Date: 27/11/2023	
42140562	1 number pothole at crossing	27/11/2023	Opposite number 12	RD: CW Pothole	Internal		Committed	50146696
Batch:	41172364 - Inspection Batch			Route: South Mobile Inspection Route			Date: 20/11/2023	
No actionable defects found								
Batch:	41170811 - Inspection Batch			Route: SfP_NorthEast			Date: 01/11/2023	
No actionable defects found								
Batch:	41170595 - Inspection Batch			Route: Ad hoc Route			Date: 31/10/2023	
42138427	1 number pothole	31/10/2023	Opposite number 12	RD: CW Pothole	Internal		Committed	50144797
Batch:	41169636 - Inspection Batch			Route: NE_LondonRd_3Month			Date: 22/10/2023	
42137869	Grano broken at catv box	22/10/2023	Outside no12	RD: FW Grano Cracked/Broken	Internal		No Action Required	
Batch:	41168979 - Inspection Batch			Route: South Mobile Inspection Route			Date: 17/10/2023	
No actionable defects found								
Batch:	41166200 - Inspection Batch			Route: South Mobile Inspection Route			Date: 21/09/2023	
No actionable defects found								
Batch:	41163478 - Inspection Batch			Route: South Mobile Inspection Route			Date: 22/08/2023	
No actionable defects found								
Batch:	41163056 - Inspection Batch			Route: Ad hoc Route			Date: 16/08/2023	
42134286	Please replace 1no missing sfp bollard	16/08/2023	Opposite no6	RD: SFP Damaged Bollard	Internal		Committed	50141146
Batch:	41161017 - Inspection Batch			Route: South Mobile Inspection Route			Date: 17/07/2023	
No actionable defects found								
Batch:	41160907 - Inspection Batch			Route: NE_LondonRd_3Month			Date: 12/07/2023	
No actionable defects found								
Batch:	41159316 - Inspection Batch			Route: South Mobile Inspection Route			Date: 14/06/2023	
No actionable defects found								
Batch:	41157712 - Inspection Batch			Route: South Mobile Inspection Route			Date: 19/05/2023	
42128133	1no pothole	19/05/2023	Outside no10	RD: CW Pothole	Internal		Committed	50136405
Batch:	41155866 - Inspection Batch			Route: South Mobile Inspection Route			Date: 26/04/2023	
No actionable defects found								
Batch:	41154710 - Inspection Batch			Route: NE_LondonRd_3Month			Date: 13/04/2023	
42125155	1 rocking crosscut 600x900	13/04/2023	Outside 23	RD: FW Slabs Rocking	Internal		Committed	50134197
Batch:	41153098 - Inspection Batch			Route: South Mobile Inspection Route			Date: 24/03/2023	
42123484	10no potholes	24/03/2023	Opposite no7-11	RD: CW Pothole	Internal		Committed	50132752

Site History Report

Effective: 24/01/2023 to 23/02/2026
Service: Roads General
Site: Brunton Place (7903969)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch:	41150599 - Inspection Batch			Route: South Mobile Inspection Route			Date: 27/02/2023	
	No actionable defects found							
Batch:	41146386 - Inspection Batch			Route: South Mobile Inspection Route			Date: 24/01/2023	
	No actionable defects found							

Customer Services

Enquiry No.:	2061036	Logged by:	Verint CRM Connector	on:	19/12/2025 11:16	Classification:	Request for service
Service:	Roads General	Subject:	Road: Defective / Damaged				
Desc.:	Series of potholes making cyclists move into the bike lane dangerous						
Location:	Contact:						
Plot Number:	1.00	Feature Id - Location:	Whole Street	Feature Type: Road Asset			
Job Number:	50189491	Defect Number:	42196401				
Enquiry No.:	2006386	Logged by:	Verint CRM Connector	on:	30/08/2025 22:44	Classification:	Request for service
Service:	Roads General	Subject:	Pavement: Damaged / Defective				
Desc.:	Broken paving slabs from Easter road junction Traffic lights ,West bound to bus shelter, Brunton Place.						
Location:	Contact:						
Plot Number:	1.00	Feature Id - Location:	Whole Street	Feature Type: Road Asset			
Enquiry No.:	2000891	Logged by:	Verint CRM Connector	on:	21/08/2025 15:36	Classification:	Request for service
Service:	Roads General	Subject:	Road: Defective / Damaged				
Desc.:	Yellow box junction faded. Drivers travelling along London Road blocking junction, creating hold-up of traffic heading up/down Easter Road.						
Location:	Contact:						
Plot Number:	1.00	Feature Id - Location:	Whole Street	Feature Type: Road Asset			
Job Number:	50183986	Defect Number:	42188935				
Enquiry No.:	1993050	Logged by:	Verint CRM Connector	on:	08/08/2025 19:49	Classification:	Request for service
Service:	Roads General	Subject:	Trees & Foliage: Defect				
Desc.:	Problem: Other. Location:Footpath. Type:Foliage / Bush						
Location:	As previously detailed. Street cleaners are unable to clear up the foliage waste, detritus and accumulation of fag ends on the footpath owing to hedge overgrowth.						
Location:	Contact:						
Enquiry No.:	1854084	Logged by:	Verint CRM Connector	on:	04/11/2024 21:44	Classification:	Request for service
Service:	Roads General	Subject:	Road: Defective / Damaged				
Desc.:	I fell of my bike because of it hurt my hand ankle and elbow broke my phone screen it is a problem						
Location:	Contact:						
Plot Number:	1.00	Feature Id - Location:	Whole Street	Feature Type: Road Asset			

Site History Report

Effective: 24/01/2023 to 23/02/2026
Service: Roads General
Site: Brunton Place (7903969)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1852298 Service: Roads General Desc.: Location: Drain with road missing from around the outside of it	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 31/10/2024 15:48 Classification: Request for service Contact:
Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset		
Enquiry No.: 1817495 Service: Roads General Desc.: Location: Recently two cables have been laid across the road presumably to monitor the traffic though there is no indication or notice as to why these cables have been laid. The noise generated from the traffic going over the cables is intolerable. It is disturbing the residents of the tenement closest to the cables. Could we please be told how long we will be subjected to these cables outside our tenement and also why were the cables placed at this location and not opposite Hillside Gardens.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 16/08/2024 18:45 Classification: Request for service Contact:
Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset		
Enquiry No.: 1724336 Service: Roads General Desc.: Problem: Overgrown. Location:Footpath. Type:Foliage / Bush Location: over grown hedge obstructing pavement	Logged by: Verint CRM Connector Subject: Trees & Foliage: Defect	on: 25/03/2024 17:02 Classification: Request for service Contact:
Enquiry No.: 1597735 Service: Roads General Desc.: Location: Cycle lane separation wand missing from temporary rubber kerb unit. Wand is at start of cycle lane and risks car hitting kerb at speed and needs replacing.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 15/08/2023 08:59 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50141146 Feature Id - Location: Whole Street Defect Number: 42134286 Feature Type: Road Asset		
Enquiry No.: 1575385 Service: Roads General Desc.: Location: Unprotected large hole in pavement, high risk of injury (sign saying risk of death)	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 02/07/2023 20:40 Classification: Request for service Contact:
Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset		
Enquiry No.: 1550915 Service: Roads General Desc.: Problem: Overgrown. Location:Pavement. Type:Foliage / Bush Location: Two large trees (sycamore and elm I think) are growing in the garden of 10 Brunton Place. The Sycamore and other foliage are growing over the pavement. Both trees pose a significant risk to the building structure and must be taken out. I am a neighbour and have tried contacting the landlord and letting agency directly about this issue - but have had no response.	Logged by: Verint CRM Connector Subject: Trees & Foliage: Defect	on: 14/05/2023 16:15 Classification: Request for service Contact:

Site History Report

Effective: 24/01/2023 to 23/02/2026
 Service: Roads General
 Site: Brunton Place (7903969)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: South East Locality		
50132752	10no potholes (RD: CW Pothole)	Opposite no7-11	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/03/2023	25/03/2023	Act. ROAD/82074750
50134197	1 rocking crosscut 600x900 (RD: FW Slabs Rocking)	Outside 23	RD: Cat 3 - 60 Day	Job Complete	13/04/2023	14/04/2023	Act. ROAD/82075739
50136405	1no pothole (RD: CW Pothole)	Outside no10	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/05/2023	22/05/2023	Act. ROAD/82077381
50141146	Please replace 1no missing sfp bollard (RD: SFP Damaged Bollard)	Opposite no6	RD: Cat 3 - 60 Day	Job Complete	16/08/2023	17/08/2023	Act. ROAD/82080053
50144797	1 number pothole (RD: CW Pothole)	Opposite number 12	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/10/2023	01/11/2023	Act. ROAD/82082191
50146696	1 number pothole at crossing (RD: CW Pothole)	Opposite number 12	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/11/2023	28/11/2023	Act. ROAD/82083218
50148639	7no potholes (RD: CW Pothole)	Opposite between nos8-10	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/12/2023	21/12/2023	Act. ROAD/82084450
50155403	1 pothole (RD: CW Pothole)	Outside 10	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	11/03/2024	12/03/2024	Act. ROAD/82089120
50155539	8 cw potholes (RD: CW Pothole)	Opposite brunton terrace	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/03/2024	02/04/2024	Act. ROAD/82089207
50156821	10no potholes (RD: CW Pothole)	Opposite no12	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/03/2024	04/04/2024	Act. ROAD/82090090
50172587	1no pothole (RD: CW Pothole)	At the corner of Hillside Crescent	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/01/2025	13/01/2025	Act. ROAD/82100550
50172590	2no potholes (RD: CW Pothole)	Opposite no11	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/01/2025	13/01/2025	Act. ROAD/82100552
50172591	4no potholes (RD: CW Pothole)	Opposite no7	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/01/2025	13/01/2025	Act. ROAD/82100553
50173078	Renew grano at catv box (RD: FW Grano Cracked/Broken)	At brunton terrace	RD: Cat 3 - 60 Day	Job Complete	17/01/2025	21/01/2025	Act. ROAD/82100927
50179087	1 pothole (RD: CW Pothole)	Opposite 12 on crossing point	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/04/2025	28/04/2025	Act. ROAD/82105435
50187142	1no pothole (RD: CW Pothole)	Opposite no9	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/11/2025	19/11/2025	Act. ROAD/82110604
50187143	2no potholes (RD: CW Pothole)	Opposite no11	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/11/2025	19/11/2025	Act. ROAD/82110605
50189489	Gully brander needs reset and tar surround (RD: Gully Damaged/Sunken)	brunton place bus stop city bound opposite no 12	RD: Cat 3 - 60 Day	RD: Phase 2 Surfacing Required	12/01/2026	06/04/2026	Est. ROAD/82112483
50189491	6 no potholes (RD: CW Pothole)	Opposite no 12 Brunton place	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/01/2026	13/01/2026	Act. ROAD/82112484