

60472 Braehead View

Location - Braehead View

The inspection and maintenance records for this section of road for the 12 months prior to the incident.

[Please refer to the 'Condition Survey' and 'Maintenance Management' sections of the attached Site History Report.](#)

Records of complaints or reports received in relation to the pothole, including dates and any actions taken.

[Please refer to the 'Customer Services' section of the attached Site History Report. The 'Maintenance Management' section includes all actions taken in this period.](#)

The intervention criteria relied upon when deciding not to repair the defect prior to my incident.

[Please refer to the Risk Based Approach to Road Safety Inspections guidance document.](#)