

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Site: Glasgow Road (7902481)

Locality: Edinburgh, City of Edinburgh

Area: North West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Ward 3 - East side of Gogar Roundabout to Drum Brae South in		Feature Type: Road Asset		Area: North West Locality		
Batch:	41254615 - Inspection Batch		Route: Mobile Inspection Strategic			Date: 22/02/2026		
No actionable defects found								
Batch:	41253467 - Inspection Batch		Route: Mobile Inspection Strategic			Date: 14/02/2026		
42199434	1no pothole	14/02/2026	Outside the Shell garage	RD: CW Pothole	Internal		Committed	50191863
42199421	Collapsed gully with missing brander	14/02/2026	Outside the Delta Hotel	RD: Gully Damaged/Sunken	Internal		Committed	50191852
42199423	1no pothole	14/02/2026	At Ip gfc98	RD: CW Pothole	Internal		Committed	50191854
Batch:	41252782 - Inspection Batch		Route: Ad hoc Route			Date: 10/02/2026		
42199078	Pothole	10/02/2026	Right hand lane before traffic lights	RD: CW Pothole	Internal		Committed	50191554
Batch:	41252213 - Inspection Batch		Route: Mobile Inspection Strategic			Date: 07/02/2026		
No actionable defects found								
Batch:	41251874 - Inspection Batch		Route: Ad hoc Route			Date: 04/02/2026		
42198545	Cracked broken surface patch required 2x4	04/02/2026	Just as you come off on slipway to Gogar Roundabout.	RD: CW Cracked/Broken	Internal		Uncommitted	50191141
Batch:	41251872 - Inspection Batch		Route: Ad hoc Route			Date: 04/02/2026		
No actionable defects found								
Batch:	41251860 - Inspection Batch		Route: North Mobile Inspection Route			Date: 04/02/2026		
No actionable defects found								
Batch:	41251719 - Inspection Batch		Route: Ad hoc Route			Date: 04/02/2026		
42198435	Please reinstate faded yellow box	04/02/2026	Junction with Gyle Park Gardens	RD: Markings Refresh	Internal		Committed	50191062
Batch:	41251292 - Inspection Batch		Route: Mobile Inspection Strategic			Date: 31/01/2026		
42198140	1no pothole	31/01/2026	At Ip 98	RD: CW Pothole	Internal		Committed	50190832
42198139	1no pothole	31/01/2026	At the junction of Meadow Place Road	RD: CW Pothole	Internal		Committed	50190831
Batch:	41251216 - Inspection Batch		Route: Ad hoc Route			Date: 30/01/2026		
42198110	Pothole	30/01/2026	Heading for the gyle at lamp post 98	RD: CW Pothole	Internal		Committed	50190802
Batch:	41249927 - Inspection Batch		Route: Mobile Inspection Strategic			Date: 25/01/2026		
No actionable defects found								
Batch:	41249378 - Inspection Batch		Route: Ad hoc Route			Date: 21/01/2026		
42197269	Pothole	21/01/2026	Just after lights city bound	RD: CW Pothole	Internal		Committed	50190142
Batch:	41249377 - Inspection Batch		Route: Ad hoc Route			Date: 21/01/2026		
42197268	Pothole	21/01/2026	City bound outside shell garage	RD: CW Pothole	Internal		Committed	50190141
Batch:	41248905 - Inspection Batch		Route: Mobile Inspection Strategic			Date: 18/01/2026		
No actionable defects found								
Batch:	41248827 - Inspection Batch		Route: Ad hoc Route			Date: 17/01/2026		
42196803	Pothole	17/01/2026	Just past b&m exit in right hand lane	RD: CW Pothole	Internal		Committed	50189808

Site History Report

Effective: 01/09/2025 to 23/02/2026

Service: Roads General

Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.:	Ward 3 - East side of Gogar Roundabout to Drum Brae South in	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41248826 - Inspection Batch			Route:	Ad hoc Route			Date: 17/01/2026
42196802	Pothole	17/01/2026	At the big Gyle sign at slip off to gyle	RD: CW Pothole	Internal		Committed	50189807
Batch:	41247803 - Inspection Batch			Route:	Mobile Inspection Strategic			Date: 11/01/2026
	No actionable defects found							
Batch:	41246735 - Inspection Batch			Route:	North Mobile Inspection Route			Date: 31/12/2025
42195973	1no pothole	31/12/2025	At the bus stop opposite Geely cars	RD: CW Pothole	Internal		Committed	50189117
Batch:	41245733 - Inspection Batch			Route:	Mobile Inspection Strategic			Date: 22/12/2025
	No actionable defects found							
Batch:	41244626 - Inspection Batch			Route:	Ad hoc Route			Date: 15/12/2025
42195268	Pothole	15/12/2025	Outside shell garage at lane merge	RD: CW Pothole	Internal		Committed	50188511
Batch:	41244544 - Inspection Batch			Route:	Mobile Inspection Strategic			Date: 15/12/2025
	No actionable defects found							
Batch:	41243650 - Inspection Batch			Route:	Ad hoc Route			Date: 03/12/2025
42194630	Pothole	03/12/2025	On drumbrae roundabout heading west from saint johns rod	RD: CW Pothole	Internal		Committed	50188013
Batch:	41243465 - Inspection Batch			Route:	Ad hoc Route			Date: 02/12/2025
42194508	Pothole	02/12/2025	east bound carriage way of Glasgow Road the corner of the Shell petrol station	RD: CW Pothole	Internal		Committed	50187924
Batch:	41242892 - Inspection Batch			Route:	Ad hoc Route			Date: 26/11/2025
42194035	All lane markings and junction lines refresh	26/11/2025	From maybury junction to south gyle	RD: Markings Refresh	Internal		Uncommitted	50187560
Batch:	41242890 - Inspection Batch			Route:	Ad hoc Route			Date: 26/11/2025
42194034	Pothole	26/11/2025	Right hand lane just after B&M exit slip	RD: CW Pothole	Internal		Committed	50187559
Batch:	41242888 - Inspection Batch			Route:	Ad hoc Route			Date: 26/11/2025
42194033	Refresh all lane markings	26/11/2025	From north gyle junction to dechmont road junction	RD: Markings Refresh	Internal		Committed	50187558
Batch:	41242685 - Inspection Batch			Route:	Ad hoc Route			Date: 25/11/2025
42193900	Noisy manhole cover	25/11/2025	Outside no 64 on carriageway	RU: Utility Apparatus	Internal		Uncommitted	50187476
Batch:	41242684 - Inspection Batch			Route:	North Mobile Inspection Route			Date: 25/11/2025
	No actionable defects found							
Batch:	41242682 - Inspection Batch			Route:	Ad hoc Route			Date: 25/11/2025
42193898	Noisy/ manhole cover	25/11/2025	Outside. No 62 on carriageway	RU: Utility Apparatus	Internal		Uncommitted	50187474
Batch:	41242280 - Inspection Batch			Route:	Ad hoc Route			Date: 21/11/2025
42193662	No 1 pothole	21/11/2025	In middle lane just before roundabout heading into town at Chinese Manor House restaurant	RD: CW Pothole	Internal		Committed	50187276

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Ward 3 - East side of Gogar Roundabout to Drum Brae South in		Feature Type: Road Asset		Area: North West Locality		
Batch:	41240895 - Inspection Batch			Route: Ad hoc Route		Date: 07/11/2025		
42192826	Parking: Other - What type of sign is it? Road sign problem, type unlit No loading sign. Pole it's on is heavily leaning and needs to be removed. (Enquiry 2017342) Suggest removal as nearby greenway sign on LP OS 101/103.	07/11/2025	Leaning pole OS 99 Glasgow Road	NSL: Pole Sign Remove Defect	Internal		Committed	50186590
Batch:	41239536 - Inspection Batch			Route: North Mobile Inspection Route		Date: 22/10/2025		
	No actionable defects found							
Batch:	41237156 - Inspection Batch			Route: North Mobile Inspection Route		Date: 22/09/2025		
	No actionable defects found							
Batch:	41236021 - Inspection Batch			Route: Ad hoc Route		Date: 05/09/2025		
42189600	Permanent repair required	05/09/2025	Lpost 102	RD: CW Rutting	Internal		Uncommitted	50184494

Customer Services

Enquiry No.: 2100919	Logged by: Verint CRM Connector	on: 23/02/2026 20:33
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: It's a long and deep pothole right next to shell garage on Glasgow road, opposite Delta hotel Edinburgh. It keep on puncturing tyres of many cars. Pretty dangerous not to mention		Contact:
Plot Number: 3.00	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in	
Feature Type: Road Asset		
Enquiry No.: 2100885	Logged by: Verint CRM Connector	on: 23/02/2026 19:37
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: That's a few gaps and holes just as you leave Glasgow road onto the slip road.		Contact:
Plot Number: 3.00	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in	
Feature Type: Road Asset		
Enquiry No.: 2100729	Logged by: Verint CRM Connector	on: 23/02/2026 16:10
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Absolutely not safe to provide a photo as this is a busy road. There are two large deep potholes on the Drum Brae side of the Manor House Restaurant.		Contact:
Plot Number: 3.00	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in	
Feature Type: Road Asset		
Enquiry No.: 2097763	Logged by: Verint CRM Connector	on: 18/02/2026 12:55
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: large pot hole in vehicle tyre line		Contact:
Plot Number: 3.00	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in	
Feature Type: Road Asset		

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2096428 **Logged by:** Verint CRM Connector **on:** 16/02/2026 17:54
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: This is near the shell petrol pump turn when u turn from maybury road to glasgow road its near the divider on the other side, my tyre got flat because of this and charged 212 pounds the other day, am not happy and very sad to spend so much money because of pothole **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2096107 **Logged by:** Verint CRM Connector **on:** 16/02/2026 12:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The pothole was on the left side of the road travelling west on Glasgow road just after the delta hotel. The pothole was filled with water and therefore didn't realise the severity of how deep it was. The impact of the pothole blew my tyre completely. I was unable to go back and take photos as it was not safe to do so. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2095960 **Logged by:** [REDACTED] **on:** 16/02/2026 10:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: I had to swerve into the other lane to avoid this large deep pothole. So dangerous.
Location: **Contact:**

Enquiry No.: 2095858 **Logged by:** [REDACTED] **on:** 16/02/2026 08:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Pothole on road at shell garage near maybury shell garage
Location: **Contact:**

Enquiry No.: 2095728 **Logged by:** Verint CRM Connector **on:** 15/02/2026 19:29
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: deep pothole that will damage cars if hit. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2095724 **Logged by:** Verint CRM Connector **on:** 15/02/2026 19:20
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: On Glasgow Road at railway bridge between Maybury Road junction and Gogar roundabout. Cant miss it, it's near the kerb, god help any poor cyclist that hits it. Not a place to stop and get a photo safely. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2095506 **Logged by:** Verint CRM Connector **on:** 15/02/2026 14:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Just before slip towards Gyle centre **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2095231 Service: Roads General Desc.: Location: Several potholes causing vehicles to swerv	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 14/02/2026 20:02 Classification: Request for service Contact:
Plot Number: 3.00	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in	Feature Type: Road Asset
Enquiry No.: 2095025 Service: Roads General Desc.: Location: Pot hole on road	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 14/02/2026 12:48 Classification: Request for service Contact:
Plot Number: 3.00	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in	Feature Type: Road Asset
Enquiry No.: 2094887 Service: Roads General Desc.: Location: Today, February 14, 2026, at approximately 3:30 AM, I damaged a tire and probably a rim due to a huge, deep pothole in the road. It's generally invisible when driving at night. The damage to the road is not marked in any way and is therefore dangerous to traffic and vehicles. I was leaving Maybury Rd when my right wheel fell into the pothole. I would like a refund after the damage is repaired. Sincerely, [REDACTED]	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 14/02/2026 07:09 Classification: Request for service Contact:
Plot Number: 3.00	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in	Feature Type: Road Asset
Enquiry No.: 2094752 Service: Roads General Desc.: Location: Between shops and roundabout heading out of the city. Lane 1....hole in road at least 200mm deep by 1m long and 1m wide Saw a car nearly flip over and another car grounded in it	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 13/02/2026 18:27 Classification: Request for service Contact:
Enquiry No.: 2094712 Service: Roads General Desc.: Location: On left of road	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 13/02/2026 17:40 Classification: Request for service Contact:
Plot Number: 3.00	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in	Feature Type: Road Asset
Enquiry No.: 2094625 Service: Roads General Desc.: Location: Very large pothole n inside lane causing vehicles to swerve at short notice	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 13/02/2026 15:42 Classification: Request for service Contact:
Plot Number: 3.00	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in	Feature Type: Road Asset
Enquiry No.: 2094544 Service: Roads General Desc.: Location: Large pothole. Causing people to swerve and break at a dangerous section of road	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 13/02/2026 14:03 Classification: Request for service Contact:
Plot Number: 3.00	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in	Feature Type: Road Asset

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2094543 **Logged by:** Verint CRM Connector **on:** 13/02/2026 14:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The pothole is on Glasgow road, at the bit where you come out of maybury road. It's right next the shell garage **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2094101 **Logged by:** Verint CRM Connector **on:** 12/02/2026 22:25
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge pothole just as coming off round about heading north **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2094040 **Logged by:** Verint CRM Connector **on:** 12/02/2026 20:24
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The pothole is located on Glasgow Road, just before the entrance to the Shell garage, opposite the traffic lights at the junction of Glasgow Road and Maybury Road. It is positioned in the middle of the two lanes heading down Glasgow Road towards Drumbrae Roundabout. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2093925 **Logged by:** Verint CRM Connector **on:** 12/02/2026 17:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There is a very large pothole in the left lane heading west towards Gogar roundabout. It is so large that you have to drive partly in the right lane. This is impossible if a car is in the outer lane causing you to hit a very large pothole. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2093907 **Logged by:** Verint CRM Connector **on:** 12/02/2026 17:30
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Near garage **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2090782 **Logged by:** Verint CRM Connector **on:** 08/02/2026 13:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The whole of Edinburgh **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2088823 **Logged by:** Verint CRM Connector **on:** 04/02/2026 16:18
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: . **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2088215 **Logged by:** Verint CRM Connector **on:** 03/02/2026 18:17
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large and deep pothole on left lane of westbound carriage way of Glasgow Road. **Contact:**
Has been there for some time and delsite having been reported previously has not been fixed

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2087539 **Logged by:** Verint CRM Connector **on:** 02/02/2026 17:51
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Every day, cars using the David Lloyd's sports centre on Glasgow Road make illegal **Contact:**
right turns towards the city
There have been near-misses, a danger to themselves and other motorists and cyclists.
As they have to rush the manoeuvre to avoid oncoming traffic. And don't want to take a circuitous safer route.
A barrier, a traffic light or a mini roundabout will help.
Also seen a case where a motorist turned right coming in from the airport even though there is a clear 'No Right Turn'

Enquiry No.: 2087256 **Logged by:** Verint CRM Connector **on:** 02/02/2026 12:10
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep Pothole underneath the gantry to the left hand side of the road. Dangerous, as **Contact:**
cars should swerve to avoid it, the lanes are busy, which is not ideal.

Not safe to stop, do not have a photo.

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2086948 **Logged by:** Verint CRM Connector **on:** 01/02/2026 19:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There is a dropped mean/large pothole **Contact:**
In the road which will definitely damage cars - been there for some time
And nothing done about it! Can this be fixed asap please
A danger to cats, bikes and motorbikes !

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2086906 **Logged by:** Verint CRM Connector **on:** 01/02/2026 17:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole as after the B&M exit in the left lane **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2086903 Service: Roads General Desc.: Location: East Bound Glasgow Road on slipway to Gogar Roundabout.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 01/02/2026 17:33 Classification: Request for service Contact:
Plot Number: 3.00 Job Number: 50191141	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in Defect Number: 42198545	Feature Type: Road Asset
Enquiry No.: 2086889 Service: Roads General Desc.: Location: Just past the crest of the slope where can't see it before being right on top of it. Any way u should know were it is you've been filling it with cheap tar for the last 20+ years.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 01/02/2026 17:13 Classification: Request for service Contact:
Plot Number: 3.00	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in	Feature Type: Road Asset
Enquiry No.: 2086802 Service: Roads General Desc.: Location: Potholes & craters	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 01/02/2026 14:47 Classification: Request for service Contact:
Plot Number: 3.00	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in	Feature Type: Road Asset
Enquiry No.: 2086222 Service: Roads General Desc.: Location: 2 separate big potholes, v deep near the kerb on the main road after the exit from b&m. One is impossible to avoid without crossing into other lane	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 30/01/2026 23:52 Classification: Request for service Contact:
Plot Number: 3.00	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in	Feature Type: Road Asset
Enquiry No.: 2086151 Service: Roads General Desc.: Location: Pothole here heading towards town	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 30/01/2026 19:54 Classification: Request for service Contact:
Plot Number: 3.00	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in	Feature Type: Road Asset
Enquiry No.: 2084832 Service: Roads General Desc.: Location: holes	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 28/01/2026 21:02 Classification: Request for service Contact:
Plot Number: 3.00	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in	Feature Type: Road Asset
Enquiry No.: 2084831 Service: Roads General Desc.: Location: There are multiple deep holes as you head towards the bypass. Don't know exact spots.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 28/01/2026 21:01 Classification: Request for service Contact:
Plot Number: 3.00	Feature Id - Location: Ward 3 - East side of Gogar Roundabout to Drum Brae South in	Feature Type: Road Asset

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2084325 **Logged by:** Verint CRM Connector **on:** 28/01/2026 09:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: When heading towards the gyle from maybury road, taking a right turn onto Glasgow Road, just after B&M there is an extremely deep pothole **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset
Job Number: 50190802 **Defect Number:** 42198110

Enquiry No.: 2080014 **Logged by:** Verint CRM Connector **on:** 20/01/2026 16:41
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Multiple pot holes which are quite deep along this stretch of road. When you turn onto the Glasgow Road from the Maybury Road. Too busy and dangerous to take photos of the pot holes. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset
Job Number: 50190141 **Defect Number:** 42197268

Enquiry No.: 2079492 **Logged by:** Verint CRM Connector **on:** 19/01/2026 21:51
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep pothole. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2079379 **Logged by:** Verint CRM Connector **on:** 19/01/2026 17:29
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge pothole westbound at location marked in left hand lane before going through underpass at Gogar Roundabout **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2078424 **Logged by:** Verint CRM Connector **on:** 18/01/2026 07:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2078423 **Logged by:** Verint CRM Connector **on:** 18/01/2026 07:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2078318 **Logged by:** Verint CRM Connector **on:** 17/01/2026 18:53
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: We have received a complaint from a member of public stating that the business is pouring the water onto the pavement which is then icing over and is extremely dangerous for pedestrians , The has tried to contact the council by phone as has no internet with no success. then contacted police scotland who is now reporting this on behalf

Contact:

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2077198 **Logged by:** Verint CRM Connector **on:** 15/01/2026 18:48
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Previously dug up part of road has sunk causing a dangerous dip on a 40mph road. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2076953 **Logged by:** Verint CRM Connector **on:** 15/01/2026 14:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: pothole **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2076182 **Logged by:** Verint CRM Connector **on:** 14/01/2026 13:30
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Huge unable to see until your wheel is in it. Pothole is deep. Made my car alert to me when i hit it that its knocked something on car to alert me!
Sorry its such a busy road it isnt safe. But its on the road againt railings as yiu go under the bridge as if your going to go under the rpad about but i was heading to hermiston so merged lane when incident happened

Contact:

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Job Number: 50189807 **Defect Number:** 42196802

Enquiry No.: 2075911 **Logged by:** Verint CRM Connector **on:** 14/01/2026 08:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Pothole on the bridge over the railway on the inside lane going west on the A8 **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2072352 **Logged by:** Verint CRM Connector **on:** 08/01/2026 11:48
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: West-bound carriageway, outside or north-most lane **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2058506 **Logged by:** Verint CRM Connector **on:** 15/12/2025 07:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Very deep, very sharp pothole, approx 30cm wide (maybe more, hard to tell) **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2056590 **Logged by:** Verint CRM Connector **on:** 11/12/2025 08:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large potholes
Report ID: 8531233
Contact:

Category: Potholes

Dangerous pothole forcing you into the other lane of traffic or damaging your car.
Really dangerous.

Location:
Easting/Northing: 317773/672684 (55.940148, -3.31797)
Nearest road to the pin placed on the map (automatically generated by
OpenStreetMap): Glasgow Road, North Gyle, South Gyle, City of Edinburgh, Alba /
Scotland, EH12 8NP, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH12
8NP (69m away)

Enquiry No.: 2056361 **Logged by:** Verint CRM Connector **on:** 10/12/2025 16:19
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: This morning I hit a pothole here it was on the left lane just after the junction for B&M **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2055687 **Logged by:** Verint CRM Connector **on:** 09/12/2025 19:11
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2055288 **Logged by:** Verint CRM Connector **on:** 09/12/2025 09:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Big pothole on Glasgow Road before turning off to South Gyle. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2055116 **Logged by:** Verint CRM Connector **on:** 08/12/2025 20:17
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset
Job Number: 50188511 **Defect Number:** 42195268

Enquiry No.: 2054950 **Logged by:** Verint CRM Connector **on:** 08/12/2025 14:45
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: A very deep and wide pothole about 20 m west of B&M access road junction with westbound Glasgow Road (A8) **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2053089 **Logged by:** Verint CRM Connector **on:** 03/12/2025 20:39
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Heading out of town on Glasgow road after B&M but before slip road to Gyle shopping centre, pothole next to pavement on inside lane **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2052841 **Logged by:** Verint CRM Connector **on:** 03/12/2025 12:30
Service: Roads General **Subject:** Road Markings: Defective **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow The length of Glasgow Road has been neglected for years regarding road markings. The west side of the road is a disgrace. People parking over driveways as the white lines have disappeared.
Location: The white lines which should be over the homeowners driveways have disappeared. People parking over driveways causing people to be blocked in. The west side of Glasgow Road in particular have no lane/road markings. Drivers are continually driving on the wrong side causing close calls. The markings on Glasgow Road havent been touched for years. **Contact:**

Enquiry No.: 2052054 **Logged by:** Verint CRM Connector **on:** 01/12/2025 23:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: From the traffic Camera to the tram bridge on Meadow house Road there have been numerous potholes, drain and road subsidence near entrance to Forrester Park for at least a few years now with no evidence of road inspectors reporting this and arranging to have this rectified. This stretch of road is one of the busiest in Edinburgh due to the cars and commercial vehicles travelling to and from the industrial estates , Colleges and Schools In this and nearby areas. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset
Job Number: 50188013 **Defect Number:** 42194630

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2051575 **Logged by:** Verint CRM Connector **on:** 01/12/2025 10:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large and deep pot hole on east bound carriage way of Glasgow Road at junction with Maybury Road and close to the corner of the Shell petrol station **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset
Job Number: 50187924 **Defect Number:** 42194508

Enquiry No.: 2050745 **Logged by:** Verint CRM Connector **on:** 28/11/2025 20:33
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Wide pothole in the middle of the road and I was unable to avoid it. Pothole hit at 2020 on 28 November 2025. My car had new suspension arms fitted on Tuesday and if they are broken again due to your awful roads you will hear from me. This is the second suspension fault caused by potholes in this town. Fix it. Cannot provide a photo as its main road and its 0830, its dark. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2050081 **Logged by:** Verint CRM Connector **on:** 27/11/2025 19:43
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Big pothole **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2049005 **Logged by:** [REDACTED] **on:** 26/11/2025 09:19
Service: Roads General **Subject:** Road Markings: Defective **Classification:** Request for service
Desc.:
Location: Poor line visibility
Report ID: 8464477 **Contact:** paul shabbir

Category: Roads/highways

Line decay

Location:

Easting/Northing: 318482/672774 (55.941076, -3.306652)

Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 116, Glasgow Road, North Gyle, South Gyle, City of Edinburgh, Alba / Scotland, EH12 8LR, United Kingdom

Nearest postcode to the pin placed on the map (automatically generated): EH12 8JB (55m away)

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset
Job Number: 50187558 **Defect Number:** 42194033

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2048966 **Logged by:** [REDACTED] **on:** 26/11/2025 08:48
Service: Roads General **Subject:** Road Markings: Defective **Classification:** Request for service
Desc.:

Location: Painted lines decayed **Contact:** paul shabbir
Report ID: 8464485

Category: Roads/highways

No middle line markings

Location:

Easting/Northing: 316788/672388 (55.937314, -3.333633)
Nearest road to the pin placed on the map (automatically generated by
OpenStreetMap): Glasgow Road, Gogar, City of Edinburgh, Alba / Scotland, EH12
9BH, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH12
9BR (158m away)

Enquiry No.: 2048947 **Logged by:** [REDACTED] **on:** 26/11/2025 08:23
Service: Roads General **Subject:** Road Markings: Defective **Classification:** Request for service
Desc.: Line markings decayed

Location: **Contact:** Anon

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset
Job Number: 50187560 **Defect Number:** 42194035

Enquiry No.: 2048774 **Logged by:** Verint CRM Connector **on:** 25/11/2025 17:47
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: hole in road **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2048754 **Logged by:** Verint CRM Connector **on:** 25/11/2025 17:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: pothole in road where tyres will often drive over **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset
Job Number: 50187559 **Defect Number:** 42194034

Enquiry No.: 2046627 **Logged by:** [REDACTED] **on:** 21/11/2025 10:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Very deep pothole

Location: **Contact:**

Enquiry No.: 2045587 **Logged by:** [REDACTED] **on:** 19/11/2025 13:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Large pothole

Location: at Drum Brae roundabout **Contact:**

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2043750 **Logged by:** Verint CRM Connector **on:** 15/11/2025 20:21
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Severe jarring from a pothole heading west before the underpass at the end of the bypass. It was dark and unsafe to stop to take a photo. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2043479 **Logged by:** Verint CRM Connector **on:** 15/11/2025 09:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Significant pothole in middle of 3 lanes at the approach to the roundabout. It surrounds a small metal drain/access cover. Could cause car damage as it is quite deep. Sorry was driving past it, but will endeavour to take and send photo later **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset
Job Number: 50187276 **Defect Number:** 42193662

Enquiry No.: 2043242 **Logged by:** Verint CRM Connector **on:** 14/11/2025 14:27
Service: Roads General **Subject:** Covers: Damaged / Defective **Classification:** Request for service
Desc.:
Location: The drain cover on the north side of the road heading towards the city centre is not fitting properly and there is noise every time a vehicle drives over the cover. The tarmac around the cover is cracked and worn. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset
Job Number: 50187474 **Defect Number:** 42193898

Enquiry No.: 2042882 **Logged by:** Verint CRM Connector **on:** 13/11/2025 21:51
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: unfortunately the map wasnt working as you approach Gogar leaving Edinburgh if you are going under the round about just before the fork right lane massive pot hole. If this were a motor bike they would have come off.

This damaged my wheel and this has to get my alloy repaired.

The roads in Edinburgh are abysmal **Contact:**

Enquiry No.: 2042645 **Logged by:** Verint CRM Connector **on:** 13/11/2025 14:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Called this afternoon to report that there is some tarpaulin hanging off the overhead road at the roundabout as if you were going into town **Contact:**

Enquiry No.: 2042171 **Logged by:** Verint CRM Connector **on:** 12/11/2025 17:30
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There is a deep pothole on the road **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2039833 **Logged by:** Verint CRM Connector **on:** 07/11/2025 18:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The road markings have worn away making it dangerous for cars going east, turning right into Gyle Park Gardens but also for cars going West trying to turn into the car garage / North Gyle Grove. Many drivers just driving up the middle lane with no road awareness for oncoming traffic also wanting to turn off Glasgow Road **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2039634 **Logged by:** Verint CRM Connector **on:** 07/11/2025 13:18
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Hole in road causing loud bang when driving over. Likely to cause damage to tyres and wheels. It's been obvious for a week or two ans getting worse. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2035042 **Logged by:** Verint CRM Connector **on:** 29/10/2025 13:48
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Road.
Type:Foliage / Bush
Location: Foliage is growing into a lane on the road, causing you to have to cut into another lane to pass. **Contact:**
On Glasgow road joining the gogar roundabout coming from Edinburgh going out of town

Enquiry No.: 2027210 **Logged by:** Verint CRM Connector **on:** 12/10/2025 18:27
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Before the underpass heading west Too dangerous to stop **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2019062 **Logged by:** [REDACTED] **on:** 25/09/2025 10:09
Service: Roads General **Subject:** Road Markings: Defective **Classification:** Request for service
Desc.: the yellow box is so faded you can't pull out and turn right its so accinent in the awiaiting
Location: [REDACTED] **Contact:**

Enquiry No.: 2017328 **Logged by:** Verint CRM Connector **on:** 21/09/2025 21:29
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road breaking up near pedestrian island. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Customer Services

Enquiry No.: 2017022 **Logged by:** Verint CRM Connector **on:** 20/09/2025 22:27
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Surface around drain deteriorating. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2016370 **Logged by:** Verint CRM Connector **on:** 19/09/2025 09:22
Service: Roads General **Subject:** Roadworks: Defect **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type unlit Diversion sign has eventually been removed from the pavement at EH12 8HL - Glasgow Road but sandbags have been left behind
Location: Sandbags require to be uplifted **Contact:**

Enquiry No.: 2013926 **Logged by:** Verint CRM Connector **on:** 14/09/2025 15:17
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Hole on Glasgow Road near the traffic lights. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Enquiry No.: 2008932 **Logged by:** Verint CRM Connector **on:** 04/09/2025 11:30
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole around here **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 3 - East side of Gogar Roundabout to Drum Brae South in **Feature Type:** Road Asset

Job Number: 50184494 **Defect Number:** 42189600

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 3.00	Asset - Locn.: Ward 3 - East side of Gogar Roundabout to Drum Brae South in		Feature Type: Road Asset		Area: North West Locality	
50096960	Refresh lane markings (RD: Markings Refresh)	Lamppost GFC102	RD: Cat 4 - Programmed	Job Scheduled	12/11/2021	12/11/2022	Est. ROAD/82097229
50170912	Gully choked (Gully: Blocked / Flooding)	Outside 100	RG: Gully - Standard Priority	Job Committed	06/12/2024	06/03/2025	Est. RDGC14/82006860
50171605	Lane for right turn into North Gyle Road faded (RD: Markings Refresh)	Junction North Gyle Road	RD: Cat 4 - Programmed	Job Complete	18/12/2024	27/10/2025	Act. ROAD/82109266
50174839	Refresh yellow junction box (RD: Markings Refresh)	Junction Gyle Park Gardens	RD: Cat 4 - Programmed	Reschedule: TM Required	11/02/2025		ROAD/82105614
50178308	Refresh bus lane markings (RD: Markings Refresh)	Junction Maybury Road	RD: Cat 4 - Programmed	Job Committed	08/04/2025		ROAD/82114538
50179707	Refresh lane markings (RD: Markings Refresh)	From Gyle Park Gardens to Maybury Road	RD: Cat 4 - Programmed	Job Committed	08/05/2025		ROAD/82114539
50184072	Replace missing and damaged railings (RD: Railing Damage/Missing/New)	Outside 107(Select Motors)	RD: Cat 3 - 60 Day	Job Complete	26/08/2025	01/10/2025	Act. ROAD/82108621

Site History Report

Effective: 01/09/2025 to 23/02/2026
 Service: Roads General
 Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 3.00		Asset - Locn.: Ward 3 - East side of Gogar Roundabout to Drum Brae South in		Feature Type: Road Asset		Area: North West Locality	
50186590	Parking: Other - What type of sign is it? Road sign problem, type unlit No loading sign. Pole it's on is heavily leaning and needs to be removed. (Enquiry 2017342) Suggest removal as nearby greenway sign on LP OS 101/103. (NSL: Pole Sign Remove Defect)	Leaning pole OS 99 Glasgow Road	Parking Operations	NSL Job Complete	07/11/2025	13/01/2026	Act. NSL/40021
50187276	No 1 pothole (RD: CW Pothole)	In middle lane just before roundabout heading into town at Chinese Manor House restaurant	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/11/2025	24/11/2025	Act. ROAD/82110737
50187558	Refresh all lane markings (RD: Markings Refresh)	From north gyle junction to dechmont road junction	RD: Cat 4 - Programmed	Job Committed	26/11/2025		ROAD/82114541
50187559	Pothole (RD: CW Pothole)	Right hand lane just after B&M exit slip	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/11/2025	03/12/2025	Act. ROAD/82110936
50187924	Pothole (RD: CW Pothole)	east bound carriage way of Glasgow Road the corner of the Shell petrol station	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/12/2025	03/12/2025	Act. ROAD/82111210
50188013	Pothole (RD: CW Pothole)	On drumbrae roundabout heading west from saint johns rod	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/12/2025	04/12/2025	Act. ROAD/82111284
50188511	Pothole (RD: CW Pothole)	Outside shell garage at lane merge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/12/2025	18/12/2025	Act. ROAD/82111673
50189117	1no pothole (RD: CW Pothole)	At the bus stop opposite Geely cars	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/12/2025	06/01/2026	Act. ROAD/82112176
50189807	Pothole (RD: CW Pothole)	At the big Gyle sign at slip off to gyle	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/01/2026	20/01/2026	Act. ROAD/82112733
50189808	Pothole (RD: CW Pothole)	Just past b&m exit in right hand lane	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/01/2026	20/01/2026	Act. ROAD/82112734
50190141	Pothole (RD: CW Pothole)	City bound outside shell garage	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	21/01/2026	22/01/2026	Act. ROAD/82112986
50190142	Pothole (RD: CW Pothole)	Just after lights city bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/01/2026	22/01/2026	Act. ROAD/82112987
50190802	Pothole (RD: CW Pothole)	Heading for the gyle at lamp post 98	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/01/2026	04/02/2026	Act. ROAD/82113520
50190831	1no pothole (RD: CW Pothole)	At the junction of Meadow Place Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/01/2026	04/02/2026	Act. ROAD/82113546
50190832	1no pothole (RD: CW Pothole)	At lp 98	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/01/2026	01/02/2026	Act. ROAD/82113547
50191062	Please reinstate faded yellow box (RD: Markings Refresh)	Junction with Gyle Park Gardens	RD: Cat 4 - Programmed	Job Complete	04/02/2026	04/02/2026	Act. ROAD/82113734
50191554	Pothole (RD: CW Pothole)	Right hand lane before traffic lights	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/02/2026	13/02/2026	Act. ROAD/82114151

Site History Report

Effective: 01/09/2025 to 23/02/2026
Service: Roads General
Site: Glasgow Road (7902481)

Asset Number: 3.00 to 3.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 3.00		Asset - Locn.: Ward 3 - East side of Gogar Roundabout to Drum Brae South in		Feature Type: Road Asset		Area: North West Locality	
50191852	Collapsed gully with missing brander (RD: Gully Damaged/Sunken)	Outside the Delta Hotel	RD: Cat 1 - 24 Hours	RD: Made Safe Job Complete	14/02/2026	14/02/2026	Act. ROAD/82114395
50191854	1no pothole (RD: CW Pothole)	At Ip gfc98	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/02/2026	16/02/2026	Act. ROAD/82114397
50191863	1no pothole (RD: CW Pothole)	Outside the Shell garage	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/02/2026	16/02/2026	Act. ROAD/82114403