

60534 Kilgraston Road, South of Grange Loan - Road Maintenance

A copy of your current road maintenance policy relating to that road. Please send me the full policy, but this should include details of the intended frequency of road safety inspections, how these inspections should be conducted and the maximum time between identification of a defect and repairs being carried out.

[Document Attached](#)

A copy of the road repair history for that road over the past year. Again, please send me the full road repair history, but this should include:  
dates of all safety inspections between 1st January 2026 and 28th February 2026- details of how safety inspections were undertaken (walked or driven, speed of inspection vehicle etc)  
details of all carriageway defects identified, with description, date and time  
details of how the authority handled these defects, what repairs were undertaken and the time between the identification of each defect and a repair being carried out.

[Report attached](#)

Please provide details of all claims made for pothole damage for the stretch of road from Kilgraston Road, South of Grange Loan made between 1st January 2026 and 28th February 2026- whether settled or not.

[Report attached.](#)