

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Site: Peffermill Road (7902091)

Locality: Prestonfield, Edinburgh, City of Edinburgh

Area: South East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Ward 15 - Cameron Terrace to King's Haugh			Feature Type: Road Asset			Area: South East Locality	
Batch: 41255197 - Inspection Batch				Route: Ad hoc Route				Date: 24/02/2026
42200419	No 2 potholes	24/02/2026	Just before Cameron park nursing home heading east from shopping centre	RD: CW Pothole	Internal		Committed	50192674
Batch: 41252952 - Inspection Batch				Route: Ad hoc Route				Date: 12/02/2026
42199184	No 2 potholes	12/02/2026	Opposite no 68 heading east just past bustop	RD: CW Pothole	Internal		Committed	50191656
Batch: 41250677 - Inspection Batch				Route: Ad hoc Route				Date: 27/01/2026
42197671	No 2 potholes	27/01/2026	Outside no 66 Peffermill road heading east opposite Cameron park nursing home	RD: CW Pothole	Internal		Committed	50190497
Batch: 41250668 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route				Date: 27/01/2026
Batch: 41247887 - Inspection Batch				Route: SE_CF2_PriestfieldSouth1				Date: 12/01/2026
42196399	Bus stop road markings need refreshed	12/01/2026	Outside Prestonfield primary school	RD: Markings Refresh	Internal		Uncommitted	50172639
42196376	2no area needs ramped at box	12/01/2026	Next to junction with Prestonfield avenue	RD: FW HRA Pothole	Internal		Committed	50189479
42196360	1 dislodged kerb	12/01/2026	At entrance outside nairns oatcakes	RD: FW Kerb Dislodged/Rocking	Internal		Uncommitted	50131087
42196361	1no Cw pothole	12/01/2026	At bus stop opposite Nairns oatcakes	RD: CW Pothole	Internal		Committed	50189470
42196358	1no sunken gully	12/01/2026	Next to vehicle entrance into Nairns oatcakes	RD: Gully Damaged/Sunken	Internal		Uncommitted	50189468
42196356	3no Cw potholes	12/01/2026	At bus stop west of Cameron park nursing home	RD: CW Pothole	Internal		Committed	50189466
42196353	1no Cw pothole	12/01/2026	Outside Prestonfield primary school	RD: CW Pothole	Internal		Committed	50189463
42196373	1no Cw pothole	12/01/2026	Opposite Lp no21	RD: CW Pothole	Internal		Committed	50189476
Batch: 41247875 - Inspection Batch				Route: Ad hoc Route				Date: 12/01/2026
42196346	No 1 pothole	12/01/2026	Just before the morgan playing fields bustop heading east	RD: CW Pothole	Internal		Committed	50189459
Batch: 41247873 - Inspection Batch				Route: Ad hoc Route				Date: 12/01/2026
42196345	No3 potholes	12/01/2026	Next to Morgan playing field bustop heading east from Cameron toll shopping centre	RD: CW Pothole	Internal		Committed	50189458
Batch: 41245407 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route				Date: 19/12/2025
Batch: 41244307 - Inspection Batch				Route: Ad hoc Route				Date: 11/12/2025
42195054	No 1 pothole	11/12/2025	Near lamppost PDR34 on CW near bustop heading east	RD: CW Pothole	Internal		Committed	50188339

Site History Report

Effective: 01/01/2023 to 27/02/2026
 Service: Roads General
 Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Ward 15 - Cameron Terrace to King's Haugh			Feature Type: Road Asset			Area: South East Locality	
Batch: 41243627 - Inspection Batch				Route: Ad hoc Route				Date: 03/12/2025
42194608	No 2 potholes	03/12/2025	10 metres east of Morgan playing fields bustop near Cameron park nursing home	RD: CW Pothole	Internal		Committed	50187998
Batch: 41243626 - Inspection Batch				Route: Ad hoc Route				Date: 03/12/2025
42194607	No 1 pothole	03/12/2025	.at kings haugh bustop heading east	RD: CW Pothole	Internal		Committed	50187997
Batch: 41243214 - Inspection Batch				Route: Ad hoc Route				Date: 01/12/2025
42194300	No 1 pothole	01/12/2025	At kings haugh bus stop	RD: CW Pothole	Internal		Committed	50187776
Batch: 41243211 - Inspection Batch				Route: Ad hoc Route				Date: 01/12/2025
42194297	2 no potholes	01/12/2025	At Morgan playing fields bustop near entrance to Cameron park nursing home	RD: CW Pothole	Internal		Committed	50187773
Batch: 41241766 - Inspection Batch				Route: South Mobile Inspection Route				Date: 18/11/2025
42193430	3no potholes	18/11/2025	Opposite Nairns Oatcakes	RD: CW Pothole	Internal		Committed	50187094
Batch: 41241075 - Inspection Batch				Route: Ad hoc Route				Date: 10/11/2025
42193005	No 1 pothole	10/11/2025	At kings haugh bustop just west of lampost PDR34 on CW	RD: CW Pothole	Internal		Committed	50186695
Batch: 41238751 - Inspection Batch				Route: South Mobile Inspection Route				Date: 15/10/2025
	No actionable defects found							
Batch: 41236652 - Inspection Batch				Route: South Mobile Inspection Route				Date: 12/09/2025
	No actionable defects found							
Batch: 41235391 - Inspection Batch				Route: Ad hoc Route				Date: 26/08/2025
42189018	No 1 pothole)	26/08/2025	Middle of the road opposite entrance to 60 Peffermill Road flats.	RD: CW Pothole	Internal		Committed	50184031
Batch: 41234507 - Inspection Batch				Route: South Mobile Inspection Route				Date: 12/08/2025
	No actionable defects found							
Batch: 41234040 - Inspection Batch				Route: Ad hoc Route				Date: 01/08/2025
42187980	No 2 potholes	01/08/2025	At kings haugh bustop heading east just before opening to peffermill industrial estate	RD: CW Pothole	Internal		Committed	50183300
Batch: 41232838 - Inspection Batch				Route: South Mobile Inspection Route				Date: 14/07/2025
	No actionable defects found							
Batch: 41230256 - Inspection Batch				Route: South Mobile Inspection Route				Date: 06/06/2025
	No actionable defects found							
Batch: 41227756 - Inspection Batch				Route: South Mobile Inspection Route				Date: 07/05/2025
	No actionable defects found							
Batch: 41227247 - Inspection Batch				Route: Ad hoc Route				Date: 01/05/2025
42182653	No 2 potholes	01/05/2025	Near lampost no 22	RD: CW Pothole	Internal		Committed	50179369

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Ward 15 - Cameron Terrace to King's Haugh			Feature Type: Road Asset			Area: South East Locality	
Batch: 41226310 - Inspection Batch				Route: Ad hoc Route				Date: 22/04/2025
42181613	2 no potholes	22/04/2025	Opposite lampost pdr 27	RD: CW Pothole	Internal		Committed	50178756
Batch: 41226305 - Inspection Batch				Route: Ad hoc Route				Date: 22/04/2025
42181612	1 no pothole	22/04/2025	5 m east of lampost pdr32	RD: CW Pothole	Internal		Committed	50178755
Batch: 41225594 - Inspection Batch				Route: South Mobile Inspection Route				Date: 09/04/2025
	No actionable defects found							
Batch: 41222338 - Inspection Batch				Route: South Mobile Inspection Route				Date: 12/03/2025
	No actionable defects found							
Batch: 41218645 - Inspection Batch				Route: South Mobile Inspection Route				Date: 12/02/2025
42175748	3 potholes	12/02/2025	At entrance to 54-60	RD: CW Pothole	Internal		Committed	50174886
Batch: 41218396 - Inspection Batch				Route: Ad hoc Route				Date: 11/02/2025
42175651	No 3 potholes	11/02/2025	At junction with peffermill road 54-60	RD: CW Pothole	Internal		Committed	50174801
Batch: 41216692 - Inspection Batch				Route: Ad hoc Route				Date: 29/01/2025
42174268	3 no potholes	29/01/2025	Outside no 66 before and after east bound	RD: CW Pothole	Internal		Committed	50173787
Batch: 41214254 - Inspection Batch				Route: SE_CF2_PriestfieldSouth1				Date: 13/01/2025
42172711	Bus stop road markings need refreshed	13/01/2025	Outside Prestonfield primary school	RD: Markings Refresh	Internal		No Action Required	
42172776	1no Cw pothole at manhole	13/01/2025	At junction with Prestonfield avenue	RD: CW Pothole	Internal		Committed	50172666
42172725	1no missing section of bars in railing	13/01/2025	Outside Prestonfield primary school	RD: Railing Damage/Missing/New	Internal		Uncommitted	50172640
42172716	1no missing section of bars in railing	13/01/2025	Outside Prestonfield primary school	RD: Railing Damage/Missing/New	Internal		No Action Required	
42172779	1no FW pothole	13/01/2025	Opposite nairns oatcakes	RD: FW HRA Pothole	Internal		Committed	50172669
42172796	2no pole stumps on fw need cut away and made safe with hra	13/01/2025	Opposite Cameron house avenue	TS: Sign Pole Loose	Internal		Committed	50172682
42172727	1no missing section of bars in railing	13/01/2025	Outside Prestonfield primary school	RD: Railing Damage/Missing/New	Internal		Committed	50172646
42172790	1 dislodged kerb	13/01/2025	At entrance outside nairns oatcakes	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
Batch: 41213598 - Inspection Batch				Route: South Mobile Inspection Route				Date: 09/01/2025
42172601	2no potholes	09/01/2025	At the entrance to no54-60	RD: CW Pothole	Internal		Committed	50172545
Batch: 41212719 - Inspection Batch				Route: Ad hoc Route				Date: 03/01/2025
42172024	1 no pothole	03/01/2025	At kings Haugh bustop on CW	RD: CW Pothole	Internal		Committed	50172069
Batch: 41210302 - Inspection Batch				Route: South Mobile Inspection Route				Date: 10/12/2024
	No actionable defects found							
Batch: 41210184 - Inspection Batch				Route: Ad hoc Route				Date: 09/12/2024
42170876	2 no potholes	09/12/2024	At junction with Peffermill road	RD: CW Pothole	Internal		Committed	50171138
Batch: 41207375 - Inspection Batch				Route: South Mobile Inspection Route				Date: 12/11/2024
	No actionable defects found							
Batch: 41206801 - Inspection Batch				Route: Ad hoc Route				Date: 07/11/2024
42168524	3 pot holes	07/11/2024	At bus stop opposite nairns biscuit factory	RD: CW Pothole	Internal		Committed	50169308

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Ward 15 - Cameron Terrace to King's Haugh			Feature Type: Road Asset			Area: South East Locality	
Batch: 41203593 - Inspection Batch				Route: Ad hoc Route				Date: 15/10/2024
42166779	Cw x1 pothole Road: Defective / Damaged (Enquiry 1844312)	15/10/2024	Outside of 53	RD: CW Pothole	Internal		Committed	50168099
Batch: 41203078 - Inspection Batch				Route: South Mobile Inspection Route				Date: 11/10/2024
42166431	1no pothole	11/10/2024	At the entrance to no54-60	RD: CW Pothole	Internal		Committed	50167905
Batch: 41201148 - Inspection Batch				Route: Ad hoc Route				Date: 23/09/2024
42165270	Cw x2 potholes Road: Defective / Damaged (Enquiry 1835140)	23/09/2024	Before and after bus stop opposite new development	RD: CW Pothole	Internal		Committed	50166881
Batch: 41200303 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route				Date: 10/09/2024
Batch: 41198839 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route				Date: 15/08/2024
Batch: 41196908 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route				Date: 18/07/2024
Batch: 41196701 - Inspection Batch				Route: Ad hoc Route				Date: 16/07/2024
42161869	Test	16/07/2024	Test	TS: Housing Dev Sign Remove	Internal		Uncommitted	50163989
Batch: 41194640 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route				Date: 18/06/2024
Batch: 41193347 - Inspection Batch				Route: Ad hoc Route				Date: 03/06/2024
42158705	Cw x2 potholes Road: Defective / Damaged (Enquiry 1769615)	03/06/2024	Bus Stop opposite biscuit factory, just before the junction with Kings Haugh	RD: CW Pothole	Internal		Committed	50161601
Batch: 41193169 - Inspection Batch				Route: Ad hoc Route				Date: 31/05/2024
42158536	Cw x2 potholes	31/05/2024	Centre of the road opposite new development	RD: CW Pothole	Internal		Committed	50161459
Batch: 41192125 - Inspection Batch				Route: Ad hoc Route				Date: 16/05/2024
42157378	Fence: Damaged / Defective - railings bent inwards towards pavement due to being struck by a bus (Enquiry 1656417)	16/05/2024	peffermill road heading towards Cameron Toll just after the Niarn Biscuit factory	EXPJ-B.Joint Crck/BrkUp Sealnt	Internal		Action Required	
Batch: 41191861 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route				Date: 14/05/2024
Batch: 41188849 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route				Date: 09/04/2024
Batch: 41186654 - Inspection Batch				Route: Ad hoc Route				Date: 18/03/2024
42151938	Cw x1 pothole Road: Defective / Damaged (Enquiry 1718803)	18/03/2024	After bus stop , opposite new development (eastbound)	RD: CW Pothole	Internal		Committed	50156105
Batch: 41186651 - Inspection Batch				Route: Ad hoc Route				Date: 18/03/2024
42151935	Cw x1 pothole Road: Defective / Damaged (Enquiry 1718804)	18/03/2024	Opposite new development (eastbound)	RD: CW Pothole	Internal		Committed	50156103

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Ward 15 - Cameron Terrace to King's Haugh			Feature Type: Road Asset			Area: South East Locality	
Batch: 41185998 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route				Date: 12/03/2024
Batch: 41185198 - Inspection Batch				Route: Ad hoc Route				Date: 07/03/2024
42150495	Cw x3 potholes Road: Defective / Damaged (Enquiry 1713420)	07/03/2024	Opposite the Nairns biscuit factory (bus stop)	RD: CW Pothole	Internal		Committed	50155024
Batch: 41184355 - Inspection Batch				Route: Ad hoc Route				Date: 01/03/2024
42149638	Scottish Telecom cover damaged	01/03/2024	At the junction with Cameron House Crescent	RU: Utility Apparatus	Internal		Uncommitted	50154463
Batch: 41183780 - Inspection Batch				Route: Ad hoc Route				Date: 26/02/2024
42149019	Cw x2 potholes Road: Defective / Damaged (Enquiry 1704917)	26/02/2024	Eastbound just after bus stop opposite new development	RD: CW Pothole	Internal		Committed	50154055
Batch: 41183764 - Inspection Batch				Route: Ad hoc Route				Date: 26/02/2024
42148986	Replace faded no right turn 600mm sign diagram no 612	26/02/2024	On west footway at peffermill road at junction with Cameron house avenue	TS: Sign Face Faded (SSO)	Internal		Committed	50154039
Batch: 41183445 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route				Date: 22/02/2024
Batch: 41181059 - Inspection Batch				Route: Ad hoc Route				Date: 02/02/2024
42146191	Cw x1 pothole Road: Defective / Damaged (Enquiry 1691238)	02/02/2024	Opposite side to the Primary School	RD: CW Pothole	Internal		Committed	50152012
Batch: 41181057 - Inspection Batch				Route: Ad hoc Route				Date: 02/02/2024
42146189	Cw x3 potholes Road: Defective / Damaged (Enquiry 1691237)	02/02/2024	Opposite the junction with Cameron House Crescent	RD: CW Pothole	Internal		Committed	50152010
Batch: 41180919 - Inspection Batch				Route: Ad hoc Route				Date: 01/02/2024
42146005	Cw x2 potholes Road: Defective / Damaged (Enquiry 1690249)	01/02/2024	Centre of the Road opposite New Development	RD: CW Pothole	Internal		Committed	50151905
Batch: 41179266 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route				Date: 19/01/2024
Batch: 41179114 - Inspection Batch				Route: SE_CF2_PriestfieldSouth1				Date: 18/01/2024
42144435	1 dislodged kerb	18/01/2024	At entrance outside nairns oatcakes	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
Batch: 41178876 - Inspection Batch				Route: Ad hoc Route				Date: 17/01/2024
42144280	Cw x1 pothole Road: Defective / Damaged (Enquiry 1678511)	17/01/2024	At the junction with Prestonfield Ave (Bus gate)	RD: CW Pothole	Internal		Committed	50150423
Batch: 41177869 - Inspection Batch				Route: Ad hoc Route				Date: 09/01/2024
42143522	Cw 1 pothole Road: Defective / Damaged (Enquiry 1673980)	09/01/2024	Just before the bus heading towards Craigmiller	RD: CW Pothole	Internal		Committed	50149675
Batch: 41177584 - Inspection Batch				Route: Ad hoc Route				Date: 05/01/2024
42143313	Cw x1 pothole Road: Defective / Damaged (Enquiry 1672025)	05/01/2024	Just after Prestonfield Ave	RD: CW Pothole	Internal		Committed	50149416
Batch: 41174921 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route				Date: 19/12/2023

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 15 - Cameron Terrace to King's Haugh	Feature Type:	Road Asset		Area:	South East Locality
Batch:	41174051 - Inspection Batch			Route:	Ad hoc Route			Date: 11/12/2023
42141541	Cw x1 pothole Road: Defective / Damaged (Enquiry 1657956)	11/12/2023	Opposite New Development	RD: CW Pothole	Internal		Committed	50147661
Batch:	41174050 - Inspection Batch			Route:	Ad hoc Route			Date: 11/12/2023
42141540	Cw x1 pothole Road: Defective / Damaged (Enquiry 1658659)	11/12/2023	Opposite the Biscuit Factory	RD: CW Pothole	Internal		Committed	50147660
Batch:	41173632 - Inspection Batch			Route:	Ad hoc Route			Date: 06/12/2023
42141165	Railings damaged, please replace. Damaged railings uplifted by Inspector. Please see attached photos	06/12/2023	Outside number 66	RD: Railing Damage/Missing/New	Internal		Uncommitted	50147278
Batch:	41172799 - Inspection Batch			Route:	Ad hoc Route			Date: 27/11/2023
42140497	Cw x1 pothole Road: Defective / Damaged (Enquiry 1650689)	27/11/2023	Opposite Cameron Park Nursing Home	RD: CW Pothole	Internal		Committed	50146642
Batch:	41172105 - Inspection Batch No actionable defects found			Route:	South Mobile Inspection Route			Date: 17/11/2023
Batch:	41172094 - Inspection Batch			Route:	Ad hoc Route			Date: 17/11/2023
42139748	Road: Defective / Damaged (Enquiry 1645943)	17/11/2023	Bus stop opposite number 7	RD: CW Pothole	Internal		Committed	50145982
Batch:	41171969 - Inspection Batch			Route:	Ad hoc Route			Date: 16/11/2023
42139687	Cw x1 pothole	16/11/2023	Outside of Nairns biscuits	RD: CW Pothole	Internal		Committed	50145898
Batch:	41170421 - Inspection Batch			Route:	Ad hoc Route			Date: 30/10/2023
42138254	Cw x1 pothole Road: Defective / Damaged (Enquiry 1634346)	30/10/2023	Opposite Nursing Home (heading towards Craigmillier	RD: CW Pothole	Internal		Committed	50144629
Batch:	41170420 - Inspection Batch			Route:	Ad hoc Route			Date: 30/10/2023
42138253	Cw x1 pothole Road: Defective / Damaged (Enquiry 1634338)	30/10/2023	Outside of Nairns biscuit factory head towards Cameron Toll	RD: CW Pothole	Internal		Committed	50144628
Batch:	41168752 - Inspection Batch No actionable defects found			Route:	South Mobile Inspection Route			Date: 16/10/2023
Batch:	41168401 - Inspection Batch			Route:	Ad hoc Route			Date: 12/10/2023
42137422	1 carriageway pothole	12/10/2023	Junction with kings haugh	RD: CW Pothole	Internal		Committed	50143909
Batch:	41166239 - Inspection Batch			Route:	Ad hoc Route			Date: 21/09/2023
42136543	1no pothole	21/09/2023	Just east of lp22	RD: CW Pothole	Internal		Committed	50142968
Batch:	41166121 - Inspection Batch No actionable defects found			Route:	South Mobile Inspection Route			Date: 21/09/2023
Batch:	41163387 - Inspection Batch No actionable defects found			Route:	South Mobile Inspection Route			Date: 22/08/2023
Batch:	41161208 - Inspection Batch No actionable defects found			Route:	South Mobile Inspection Route			Date: 18/07/2023

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 15 - Cameron Terrace to King's Haugh	Feature Type:	Road Asset		Area:	South East Locality
Batch:	41160831 - Inspection Batch			Route:	Ad hoc Route			Date: 12/07/2023
42131658	Cw x1 pothole Road: Defective / Damaged (Enquiry 1578922)	12/07/2023	Opposite new development near bus stop	RD: CW Pothole	Internal		Committed	50139108
Batch:	41160830 - Inspection Batch			Route:	Ad hoc Route			Date: 12/07/2023
42131657	Cw x2 potholes Road: Defective / Damaged (Enquiry 1578337)	12/07/2023	At crossing point outside of primary school	RD: CW Pothole	Internal		Committed	50139107
Batch:	41159233 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 14/06/2023
	No actionable defects found							
Batch:	41157582 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 18/05/2023
	No actionable defects found							
Batch:	41155477 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 24/04/2023
	No actionable defects found							
Batch:	41154404 - Inspection Batch			Route:	Ad hoc Route			Date: 06/04/2023
42124901	Cw x1 Road: Defective / Damaged (Enquiry 1530355)	06/04/2023	Opposite new development	RD: CW Pothole	Internal		Committed	50133933
Batch:	41153591 - Inspection Batch			Route:	Ad hoc Route			Date: 30/03/2023
42124166	Remove Collapsed sign pole make safe footway and leave signs at Bankhead Depot stores.	30/03/2023	On footway opposite junction with Prestonfield Avenue	RD: Unlit Sign Damaged/Missing	Internal		Committed	50133265
Batch:	41153310 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 27/03/2023
	No actionable defects found							
Batch:	41151296 - Inspection Batch			Route:	SE_CF2_PriestfieldSouth1			Date: 05/03/2023
42121185	1 dislodged kerb	05/03/2023	At entrance outside nairns oatcakes	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42121198	1 carriageway pothole	05/03/2023	Opposite 50	RD: CW Pothole	Internal		Committed	50131092
42121189	2 carriageway potholes	05/03/2023	Opposite 5 at bus stop	RD: CW Pothole	Internal		Committed	50131089
42121188	2 carriageway potholes	05/03/2023	Opposite prestonfield avenue	RD: CW Pothole	Internal		Committed	50131088
Batch:	41150709 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 27/02/2023
	No actionable defects found							
Batch:	41150267 - Inspection Batch			Route:	Ad hoc Route			Date: 23/02/2023
42119730	Cw x1 Road: Defective / Damaged (Enquiry 1510430)	23/02/2023	Opposite new housing developments	RD: CW Pothole	Internal		Committed	50130099
Batch:	41148374 - Inspection Batch			Route:	Ad hoc Route			Date: 08/02/2023
42117954	Hole in manhole cover Pavement: Damaged / Defective (Enquiry 1500875)	08/02/2023	Peffermill Road at Cameron house avenue	RU: Utility Apparatus	Internal		Uncommitted	50128777
Batch:	41146481 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 25/01/2023
	No actionable defects found							

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Ward 15 - Cameron Terrace to King's Haugh		Feature Type: Road Asset		Area: South East Locality			
Batch: 41144850 - Inspection Batch		Route: Ad hoc Route		Date: 20/01/2023				
42115914	Cw pothole marked on site Road: Defective / Damaged (Enquiry 1490589)	20/01/2023	Peffermill Road opposite 1	RD: CW Pothole	Internal		Committed	50126939
Batch: 41144800 - Inspection Batch		Route: Ad hoc Route		Date: 20/01/2023				
42115880	1 number pothole	20/01/2023	At Lampost number PDR21	RD: CW Pothole	Internal		Committed	50126896
Batch: 41143348 - Inspection Batch		Route: Ad hoc Route		Date: 12/01/2023				
42114938	Cw pothole marked on site Road: Defective / Damaged (Enquiry 1487686)	12/01/2023	Peffermill Road junction with Cameron Toll roundabout as per map	RD: CW Pothole	Internal		Committed	50126026
Batch: 41142124 - Inspection Batch		Route: Ad hoc Route		Date: 05/01/2023				
42114141	Cw potholes at bus stop	05/01/2023	Peffermill road east bound opp nairns	RD: CW Pothole	Internal		Committed	50125355
Asset: 2.00	Asset - Locn.: Ward 17 - King's Haugh to Duddingston Road West		Feature Type: Road Asset		Area: North East Locality			
Batch: 41255202 - Inspection Batch		Route: Ad hoc Route		Date: 24/02/2026				
42200424	No 1 pothole	24/02/2026	No 1 pothole at crossing point at lights heading east oppisite dentist	RD: CW Pothole	Internal		Committed	50192679
Batch: 41250667 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route		Date: 27/01/2026				
Batch: 41247894 - Inspection Batch		Route: SE_CF2_PriestfieldSouth1		Date: 12/01/2026				
42196363	1no Cw pothole	12/01/2026	Between studs At pedestrian crossing outside Flat no180	RD: CW Pothole	Internal		Committed	50189471
42196365	x5 kerbs need raised slightly and tar work re done around box to cover exposed edge	12/01/2026	Outside dentist at crossing point	RD: FW HRA Depression/Sunker	Internal		Uncommitted	50131106
42196370	CW cracked - broken	12/01/2026	O/S lamppost PDR 60 at pedestrian crossing	RD: CW Cracked/Broken	Internal		Uncommitted	50106269
42196369	1no area needs ramped at double Bt box	12/01/2026	At junction with craigmillar castle road	RD: FW HRA Pothole	Internal		Committed	50189474
Batch: 41245396 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route		Date: 19/12/2025				
Batch: 41243219 - Inspection Batch		Route: Ad hoc Route		Date: 01/12/2025				
42194306	3 no potholes	01/12/2025	At junction of duddingston road west and pieffermill road and at crossing point	RD: CW Pothole	Internal		Committed	50187779
Batch: 41241764 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route		Date: 18/11/2025				
Batch: 41238752 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route		Date: 15/10/2025				
Batch: 41237355 - Inspection Batch		Route: Ad hoc Route		Date: 25/09/2025				
42190281	Please replace 1no missing weebol	25/09/2025	At the crossroads at Niddrie	RD: Weebol Damage/Missing/Ne	Internal		Committed	50184999

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 17 - King's Haugh to Duddingston Road West		Feature Type: Road Asset		Area: North East Locality		
Batch:	41236651 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route		Date: 12/09/2025		
Batch:	41234506 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route		Date: 12/08/2025		
Batch:	41233922 - Inspection Batch			Route: Ad hoc Route		Date: 31/07/2025		
42187895	Renew damaged Weebol	31/07/2025	Opposite number 200	RD: Bollard Damage/Missing/Nev	Internal		Committed	50183242
Batch:	41232837 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route		Date: 14/07/2025		
Batch:	41230255 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route		Date: 06/06/2025		
Batch:	41227755 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route		Date: 07/05/2025		
Batch:	41225593 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route		Date: 09/04/2025		
Batch:	41222339 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route		Date: 12/03/2025		
Batch:	41219167 - Inspection Batch			Route: Ad hoc Route		Date: 14/02/2025		
42176054	3 no potholes	14/02/2025	At kings haugh bustop opposite biscuit factory	RD: CW Pothole	Internal		Committed	50175131
Batch:	41219161 - Inspection Batch			Route: Ad hoc Route		Date: 14/02/2025		
42176053	No 2 pothole	14/02/2025	At crossing out side craigmiller dentist	RD: CW Pothole	Internal		Committed	50175130
Batch:	41218723 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route		Date: 12/02/2025		
Batch:	41216549 - Inspection Batch			Route: Ad hoc Route		Date: 28/01/2025		
42174137	Renew missing weebol base and grano infill	28/01/2025	At junction of Craigmillar Castle Avenue	RD: Weebol Damage/Missing/Ne	Internal		Committed	50173677
Batch:	41216544 - Inspection Batch			Route: Ad hoc Route		Date: 28/01/2025		
42174132	1 number pothole on pedestrian crossing at traffic lights	28/01/2025	At junction	RD: CW Pothole	Internal		Committed	50173673
Batch:	41214323 - Inspection Batch			Route: SE_CF2_PriestfieldSouth1		Date: 13/01/2025		
42172787	CW cracked - broken	13/01/2025	O/S lamppost PDR 60 at pedestrian crossing	RD: CW Cracked/Broken	Internal		No Action Required	
42172784	Refresh arrows and 20 mph roundels road markings	13/01/2025	On approach to traffic lights opposite Bristo church	RD: Markings Refresh	Internal		Committed	50172674
42172785	x5 kerbs need raised slightly and tar work re done around box to cover exposed edge	13/01/2025	Outside dentist at crossing point	RD: FW HRA Depression/Sunken	Internal		No Action Required	
Batch:	41213574 - Inspection Batch			Route: South Mobile Inspection Route		Date: 09/01/2025		
42172577	1no pothole	09/01/2025	On the pedestrian crossing outside no200	RD: CW Pothole	Internal		Committed	50172525

Site History Report

Effective: 01/01/2023 to 27/02/2026
 Service: Roads General
 Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 17 - King's Haugh to Duddingston Road West		Feature Type: Road Asset		Area: North East Locality		
Batch:	41210301 - Inspection Batch			Route: South Mobile Inspection Route			Date: 10/12/2024	
	No actionable defects found							
Batch:	41207374 - Inspection Batch			Route: South Mobile Inspection Route			Date: 12/11/2024	
	No actionable defects found							
Batch:	41203077 - Inspection Batch			Route: South Mobile Inspection Route			Date: 11/10/2024	
	No actionable defects found							
Batch:	41200302 - Inspection Batch			Route: South Mobile Inspection Route			Date: 10/09/2024	
	No actionable defects found							
Batch:	41198746 - Inspection Batch			Route: South Mobile Inspection Route			Date: 15/08/2024	
	No actionable defects found							
Batch:	41196905 - Inspection Batch			Route: South Mobile Inspection Route			Date: 18/07/2024	
	No actionable defects found							
Batch:	41194639 - Inspection Batch			Route: South Mobile Inspection Route			Date: 18/06/2024	
	No actionable defects found							
Batch:	41191859 - Inspection Batch			Route: South Mobile Inspection Route			Date: 14/05/2024	
	No actionable defects found							
Batch:	41188848 - Inspection Batch			Route: South Mobile Inspection Route			Date: 09/04/2024	
	No actionable defects found							
Batch:	41185997 - Inspection Batch			Route: South Mobile Inspection Route			Date: 12/03/2024	
	No actionable defects found							
Batch:	41185655 - Inspection Batch			Route: Ad hoc Route			Date: 11/03/2024	
42151057	1 number pothole at gully	11/03/2024	At Lampost number PDR59	RD: CW Pothole	Internal		Committed	50155406
Batch:	41183443 - Inspection Batch			Route: South Mobile Inspection Route			Date: 22/02/2024	
	No actionable defects found							
Batch:	41183192 - Inspection Batch			Route: Ad hoc Route			Date: 21/02/2024	
42148486	1 number pothole on pedestrian crossing	21/02/2024	Just before left turn to Duddingston Road West	RD: CW Pothole	Internal		Committed	50153558
Batch:	41179265 - Inspection Batch			Route: South Mobile Inspection Route			Date: 19/01/2024	
	No actionable defects found							
Batch:	41179073 - Inspection Batch			Route: SE_CF2_PriestfieldSouth1			Date: 18/01/2024	
42144409	Approx .5x3m patch	18/01/2024	Junction with Craigmillar castle gardens	RD: CW Cracked/Broken	Internal		Uncommitted	50131108
42144408	CW cracked - broken	18/01/2024	O/S lamppost PDR 60 at pedestrian crossing	RD: CW Cracked/Broken	Internal		No Action Required	
42144413	Damaged box lid	18/01/2024	Peffermill road at junction Cameron house avenue	RU: Utility Apparatus	Internal		Committed	50150539
Batch:	41174920 - Inspection Batch			Route: South Mobile Inspection Route			Date: 19/12/2023	
	No actionable defects found							

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 17 - King's Haugh to Duddingston Road West		Feature Type: Road Asset		Area: North East Locality		
Batch:	41172104 - Inspection Batch			Route: South Mobile Inspection Route		Date: 17/11/2023		
No actionable defects found								
Batch:	41170509 - Inspection Batch			Route: Ad hoc Route		Date: 31/10/2023		
42138344	1 number pothole in bus stop	31/10/2023	At bus stop just passed Craigmillar Castle Gardens	RD: CW Pothole	Internal		Committed	50144720
Batch:	41168751 - Inspection Batch			Route: South Mobile Inspection Route		Date: 16/10/2023		
No actionable defects found								
Batch:	41168100 - Inspection Batch			Route: Ad hoc Route		Date: 09/10/2023		
42137293	1 number pothole at bus stop	09/10/2023	Just passed Craigmillar Castle Gardens	RD: CW Pothole	Internal		Committed	50143783
Batch:	41166119 - Inspection Batch			Route: South Mobile Inspection Route		Date: 21/09/2023		
42136524	1no pothole	21/09/2023	At the bus stop at Peffermill Court	RD: CW Pothole	Internal		Committed	50142949
Batch:	41163386 - Inspection Batch			Route: South Mobile Inspection Route		Date: 22/08/2023		
No actionable defects found								
Batch:	41161206 - Inspection Batch			Route: South Mobile Inspection Route		Date: 18/07/2023		
No actionable defects found								
Batch:	41159232 - Inspection Batch			Route: South Mobile Inspection Route		Date: 14/06/2023		
No actionable defects found								
Batch:	41157584 - Inspection Batch			Route: South Mobile Inspection Route		Date: 18/05/2023		
42128053	1no pothole	18/05/2023	Opposite Ip PDR51	RD: CW Pothole	Internal		Committed	50136346
Batch:	41155898 - Inspection Batch			Route: Ad hoc Route		Date: 27/04/2023		
42126139	1 number pothole at bus stop	27/04/2023	Just passed Craigmillar Castle Gardens	RD: CW Pothole	Internal		Committed	50135142
Batch:	41155799 - Inspection Batch			Route: Ad hoc Route		Date: 26/04/2023		
42126077	1 carriageway pothole	26/04/2023	Outside 188	RD: CW Pothole	Internal		Committed	50135084
Batch:	41155478 - Inspection Batch			Route: South Mobile Inspection Route		Date: 24/04/2023		
No actionable defects found								
Batch:	41154594 - Inspection Batch			Route: Ad hoc Route		Date: 12/04/2023		
42125061	Cw x1 pothole Road: Defective / Damaged (Enquiry 1534749)	12/04/2023	Just at the junction with Kings Haugh industrial estate	RD: CW Pothole	Internal		Committed	50134098
Batch:	41154362 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124869	1 number pothole	06/04/2023	At Lampost number PDR47	RD: CW Pothole	Internal		Committed	50133900
Batch:	41154361 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124868	Permanent patch approx 8m x 1.5	06/04/2023	At Lampost number PDR47	RO: Permanent Patching	Internal		Committed	50133899
Batch:	41154360 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124867	Permanent patch approx 10m x 1.5	06/04/2023	At Lampost number PDR47	RO: Permanent Patching	Internal		Committed	50133898
Batch:	41154359 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124866	Permanent patch approx	06/04/2023	At Lampost number PDR47	RO: Permanent Patching	Internal		Committed	50133897

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 17 - King's Haugh to Duddingston Road West		Feature Type: Road Asset		Area: North East Locality		
Batch:	41154358 - Inspection Batch	Route: Ad hoc Route		Date: 06/04/2023				
42124865	Permanent patch approx 3m x 1m	06/04/2023	At Lampost number PDR47 and turning into Craigmillar Castle Gardens	RO: Permanent Patching	Internal		Committed	50133896
Batch:	41154357 - Inspection Batch	Route: Ad hoc Route		Date: 06/04/2023				
42124864	Permanent patch approx 1m x 1m	06/04/2023	At Lampost number PDR47	RO: Permanent Patching	Internal		Committed	50133895
Batch:	41154356 - Inspection Batch	Route: Ad hoc Route		Date: 06/04/2023				
42124863	Permanent patch approx 2m x 1m	06/04/2023	At Lampost number PDR47	RO: Permanent Patching	Internal		Committed	50133894
Batch:	41154355 - Inspection Batch	Route: Ad hoc Route		Date: 06/04/2023				
42124862	Permanent patch approx 2.5m x 2.5m	06/04/2023	At Lampost number PDR47	RO: Permanent Patching	Internal		Committed	50133893
Batch:	41154354 - Inspection Batch	Route: Ad hoc Route		Date: 06/04/2023				
42124861	Permanent patch approx 4m x 1m	06/04/2023	At Lampost number PDR42	RO: Permanent Patching	Internal		Committed	50133892
Batch:	41154353 - Inspection Batch	Route: Ad hoc Route		Date: 06/04/2023				
42124860	Permanent patch approx 7m x 1m	06/04/2023	At Lampost number PDR42	RO: Permanent Patching	Internal		Committed	50133891
Batch:	41154352 - Inspection Batch	Route: Ad hoc Route		Date: 06/04/2023				
42124859	Permanent patch approx 4m x 1m	06/04/2023	At Lampost number PDR42	RO: Permanent Patching	Internal		Committed	50133890
Batch:	41154351 - Inspection Batch	Route: Ad hoc Route		Date: 06/04/2023				
42124858	Permanent patch approx 3m x 1m	06/04/2023	At Lampost number PDR42	RO: Permanent Patching	Internal		Committed	50133889
Batch:	41154350 - Inspection Batch	Route: Ad hoc Route		Date: 06/04/2023				
42124857	Permanent patch approx 1m x 1m	06/04/2023	Between Lampost number PDR40 and PDR42	RO: Permanent Patching	Internal		Committed	50133888
Batch:	41154349 - Inspection Batch	Route: Ad hoc Route		Date: 06/04/2023				
42124856	Permanent patch approx 2m x 1m	06/04/2023	Between Lampost number PDR40 and PDR42	RO: Permanent Patching	Internal		Committed	50133887
Batch:	41154348 - Inspection Batch	Route: Ad hoc Route		Date: 06/04/2023				
42124855	Permanent patch approx 1m x 1m	06/04/2023	Between Lampost number PDR40 and PDR42	RO: Permanent Patching	Internal		Committed	50133886
Batch:	41154347 - Inspection Batch	Route: Ad hoc Route		Date: 06/04/2023				
42124854	Permanent patch approx 7m x 1.5	06/04/2023	Between Lampost number PDR40 and PDR42	RO: Permanent Patching	Internal		Committed	50133885
Batch:	41154346 - Inspection Batch	Route: Ad hoc Route		Date: 06/04/2023				
42124853	Permanent patch approx 2m x 1m	06/04/2023	Between Lampost number PDR40 and PDR42	RO: Permanent Patching	Internal		Committed	50133884
Batch:	41154344 - Inspection Batch	Route: Ad hoc Route		Date: 06/04/2023				
42124851	Permanent patch approx 1m x 1m	06/04/2023	Between Lampost number PDR40 and PDR42	RO: Permanent Patching	Internal		Committed	50133882
Batch:	41154342 - Inspection Batch	Route: Ad hoc Route		Date: 06/04/2023				
42124849	Permanent patch approx 3m x 1m	06/04/2023	Between Lampost number PDR40 and PDR42	RO: Permanent Patching	Internal		Committed	50133880

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 17 - King's Haugh to Duddingston Road West		Feature Type: Road Asset		Area: North East Locality		
Batch:	41154341 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124848	Permanent patch approx 1.5m x 1m	06/04/2023	Between Lampost PDR40 and ODR42	RO: Permanent Patching	Internal		Committed	50133879
Batch:	41154338 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124846	Permanent patch approx 5m x 1m	06/04/2023	At Lampost number PDR40	RO: Permanent Patching	Internal		Committed	50133877
Batch:	41154333 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124845	Permanent patch approx	06/04/2023	At Lampost number PDR37	RO: Permanent Patching	Internal		Committed	50133876
Batch:	41154314 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124837	Permanent patch approx 1m x 1m	06/04/2023	Opposite Lampost number PDR37	RO: Permanent Patching	Internal		Committed	50133868
Batch:	41154312 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124836	Permanent patch approx 3m x 1m	06/04/2023	Opposite Lampost number PDR37	RO: Permanent Patching	Internal		Committed	50133867
Batch:	41154301 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124827	Permanent patch approx 1m x 1m	06/04/2023	Opposite Lampost number PDR37	RO: Permanent Patching	Internal		Committed	50133858
Batch:	41154298 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124824	Permanent patch approx 1m x 1m	06/04/2023	Opposite Lampost number PDR37	RO: Permanent Patching	Internal		Committed	50133855
Batch:	41154291 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124819	Permanent patch approx 2m x 1.5	06/04/2023	At Lampost number PDR38A	RO: Permanent Patching	Internal		Committed	50133847
Batch:	41154289 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124817	Permanent patch approx 4m x 1.5	06/04/2023	At Lampost number PDR38A	RO: Permanent Patching	Internal		Committed	50133845
Batch:	41154282 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124813	Permanent patch approx 1.5m x 1.5m	06/04/2023	Opposite Lampost number PDR42	RO: Permanent Patching	Internal		Committed	50133841
Batch:	41154281 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124812	Permanent patch approx 6m x 1.5m	06/04/2023	Opposite Lampost number PDR42	RO: Permanent Patching	Internal		Committed	50133840
Batch:	41154280 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124811	Permanent patch approx 1m x 1m	06/04/2023	Outside number 166	RO: Permanent Patching	Internal		Committed	50133839
Batch:	41154269 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124803	Permanent patch approx 2m x 1m	06/04/2023	Outside number 168	RO: Permanent Patching	Internal		Committed	50133830
Batch:	41154262 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124801	Permanent patch approx 1m x 1m	06/04/2023	Outside number 168	RO: Permanent Patching	Internal		Committed	50133828
Batch:	41154258 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124798	Permanent patch approx 1m x 1m	06/04/2023	At Lampost number PDR45	RO: Permanent Patching	Internal		Committed	50133825
Batch:	41154257 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124797	Permanent patch approx 1m x 1m	06/04/2023	At Lampost number PDR45	RO: Permanent Patching	Internal		Committed	50133824
Batch:	41154255 - Inspection Batch			Route: Ad hoc Route		Date: 06/04/2023		
42124795	Permanent patch approx 3m x 1m	06/04/2023	At junction of Craigmillar Castle Gardens	RO: Permanent Patching	Internal		Committed	50133822

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.:	Ward 17 - King's Haugh to Duddingston Road West	Feature Type:	Road Asset		Area:	North East Locality
Batch:	41154254 - Inspection Batch			Route:	Ad hoc Route			Date: 06/04/2023
42124794	Permanent patch approx 9m x1m	06/04/2023	At junction of Craigmillar Castle Gardens	RO: Permanent Patching	Internal		Committed	50133821
Batch:	41154252 - Inspection Batch			Route:	Ad hoc Route			Date: 06/04/2023
42124792	4 number potholes	06/04/2023	At junction of Craigmillar Castle Gardens	RD: CW Pothole	Internal		Committed	50133819
Batch:	41154250 - Inspection Batch			Route:	Ad hoc Route			Date: 06/04/2023
42124790	Permanent patch approx 1m x1m	06/04/2023	Outside number 182	RO: Permanent Patching	Internal		Committed	50133817
Batch:	41154249 - Inspection Batch			Route:	Ad hoc Route			Date: 06/04/2023
42124789	Permanent patch approx 7m x 1.5m	06/04/2023	Outside number 186	RO: Permanent Patching	Internal		Committed	50133816
Batch:	41153309 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 27/03/2023
	No actionable defects found							
Batch:	41151304 - Inspection Batch			Route:	SE_CF2_PriestfieldSouth1			Date: 05/03/2023
42121247	1 carriageway pothole	05/03/2023	Opposite lamppost 37	RD: CW Pothole	Internal		Committed	50131111
42121242	Approx .5x3m patch	05/03/2023	Junction with Craigmillar castle gardens	RD: CW Cracked/Broken	Internal		No Action Required	
42121240	x5 kerbs need raised slightly and tar work re done around box to cover exposed edge	05/03/2023	Outside dentist at crossing point	RD: FW HRA Depression/Sunken	Internal		No Action Required	
42121237	CW cracked - broken	05/03/2023	O/S lamppost PDR 60 at pedestrian crossing	RD: CW Cracked/Broken	Internal		No Action Required	
42121234	6 carriageway potholes	05/03/2023	From lamppost 42 to opposite 168	RD: CW Pothole	Internal		Committed	50131103
42121246	6 carriageway potholes	05/03/2023	Opposite lamppost 42	RD: CW Pothole	Internal		Committed	50131110
Batch:	41150917 - Inspection Batch			Route:	Ad hoc Route			Date: 01/03/2023
42120713	Cw x1 pothole Road: Defective / Damaged (Enquiry 1515501)	01/03/2023	Bus stop before the railway bridge heading to Cameron Toll	RD: CW Pothole	Internal		Committed	50130740
Batch:	41150852 - Inspection Batch			Route:	Ad hoc Route			Date: 28/02/2023
42120658	Cw x1 pothole Road: Defective / Damaged (Enquiry 1515501)	28/02/2023	Bus stop before the railway bridge heading to Cameron Toll	RD: CW Pothole	Internal		No Action Required	
Batch:	41150702 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 27/02/2023
42120498	1 cw pothole	27/02/2023	At bus stop near Ip45	RD: CW Pothole	Internal		Committed	50130582
Batch:	41150251 - Inspection Batch			Route:	Ad hoc Route			Date: 23/02/2023
42119722	Cw pothole x3 Road: Defective / Damaged (Enquiry 1514031)	23/02/2023	At traffic island	RD: CW Pothole	Internal		Committed	50130091
Batch:	41146482 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 25/01/2023
	No actionable defects found							
Batch:	41144773 - Inspection Batch			Route:	Ad hoc Route			Date: 20/01/2023
42115869	8 number potholes	20/01/2023	Heading to Niddrie Mains Road between Lampost number PDR40 and PDR42	RD: CW Pothole	Internal		Committed	50126890

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 2.00	Asset - Locn.: Ward 17 - King's Haugh to Duddingston Road West		Feature Type: Road Asset		Area: North East Locality			
Batch: 41144757 - Inspection Batch		Route: Ad hoc Route		Date: 20/01/2023				
42115863	7 number potholes	20/01/2023	Opposite junction of Craigmillar Castle Gardens	RD: CW Pothole	Internal		Committed	50126884
Batch: 41143335 - Inspection Batch		Route: Ad hoc Route		Date: 12/01/2023				
42114925	Cw pothole marked on site Road: Defective / Damaged (Enquiry 1486786)	12/01/2023	Peffermill Road at Craigmillar castle Gardens bus stop	RD: CW Pothole	Internal		Committed	50126013
Batch: 41142759 - Inspection Batch		Route: Ad hoc Route		Date: 09/01/2023				
42114444	1 number pothole	09/01/2023	Outside number 168	RD: CW Pothole	Internal		Committed	50125617
Batch: 41142758 - Inspection Batch		Route: Ad hoc Route		Date: 09/01/2023				
42114442	1 number pothole	09/01/2023	Opposite Peffermill park	RD: CW Pothole	Internal		Committed	50125615
Batch: 41142757 - Inspection Batch		Route: Ad hoc Route		Date: 09/01/2023				
42114440	1 number pothole	09/01/2023	Opposite Peffermill park	RD: CW Pothole	Internal		Committed	50125613
Asset: 3.00	Asset - Locn.: Ward 15 - Branch south then south-west at No.54		Feature Type: Road Asset		Area: South East Locality			
Batch: 41247900 - Inspection Batch		Route: SE_CF2_PriestfieldSouth1		Date: 12/01/2026				
42196374	Give way road markings need refreshed	12/01/2026	At junction with peffermill road	RD: Markings Refresh	Internal		Uncommitted	50189477
Batch: 41214445 - Inspection Batch		Route: SE_CF2_PriestfieldSouth1		Date: 13/01/2025				
No actionable defects found								
Batch: 41179136 - Inspection Batch		Route: SE_CF2_PriestfieldSouth1		Date: 18/01/2024				
No actionable defects found								
Batch: 41172796 - Inspection Batch		Route: Ad hoc Route		Date: 27/11/2023				
42140494	Cw x1 pothole Road: Defective / Damaged (Enquiry 1650687)	27/11/2023	At the entrance to new development car park	RD: CW Pothole	Internal		Committed	50146641
Batch: 41168505 - Inspection Batch		Route: Ad hoc Route		Date: 13/10/2023				
42137463	Cw x3 potholes Road: Defective / Damaged (Enquiry 1627387)	13/10/2023	Opposite new development	RD: CW Pothole	Internal		Committed	50143946
Batch: 41151329 - Inspection Batch		Route: SE_CF2_PriestfieldSouth1		Date: 05/03/2023				
No actionable defects found								
Batch: 41143342 - Inspection Batch		Route: Ad hoc Route		Date: 12/01/2023				
42114932	Cw pothole marked on site Road: Defective / Damaged (Enquiry 1488367)	12/01/2023	Peffermill Road No 58 at junction.	RD: CW Pothole	Internal		Committed	50126020

Customer Services

Enquiry No.: 34008625

Logged by: Jackie Grant

on: 06/06/2024 09:52

Service: Roads General

Subject: Trees & Foliage: Defect

Classification: Request for service

Desc.: please inspect Hedgerows badly overgrown at the walkway at metal fence at back of Prestonfield Primary School on right hand side at Cameron House Avenue

Location: Prestonfield Primary School

Contact: p

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 31603916 **Logged by:** Colin Cook **on:** 07/12/2025 20:22
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: Please log on confirm for an inspector to visit site to determine suitable location for Warning signs diagram 562 and associated plate 'Ambulance Station', as per image below.
Speed of Road = 30mph.
Warning signs and associated plates are to be installed 45m in advance of junction of Peffermill Road/ Kings Haugh-Peffermill Industrial Estate junction leading to the ambulance station.
Also to be considered, warning sign to be located where it can be seen by driver from 60m away approaching the warning sign.
Positioning of the sign can vary as advised in Traffic Signs Manual 4 – Warning Signs - depending on site conditions.

Note to inspector, phone P Keggie to discuss briefly before site visit and please update P Keggie on outcome of site visit.
New sign faces, posts, and foundation required to be designed, for project bank.

Location:

Contact:

Enquiry No.: 31603104 **Logged by:** Colin Cook **on:** 22/02/2024 19:03
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: Please logon confirm for inspector to visit site, check condition and regulation compliance of existing no right turn signs on approach to Cameron House Avenue and provide an update on the outcome thanks.

Location:

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50154039 **Defect Number:** 42148986

Enquiry No.: 2103655 **Logged by:** Verint CRM Connector **on:** 27/02/2026 14:59
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Previously reported and indications were that the path had been cleared of debris. **Contact:**
You recently reported an issue with a road(ref number 102000177560
There has been no change and very disappointing to be reporting completed works
falsely
Updated picture and image of map of the specific location shown by the blue dot
looking into the industrial estate area. Area remains very muddy / leaf debris on the
pavement

Enquiry No.: 2101089 **Logged by:** Verint CRM Connector **on:** 24/02/2026 09:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Several holes at the lights/bicycle box, outside the dentist. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset
Job Number: 50192679 **Defect Number:** 42200424

Enquiry No.: 2100624 **Logged by:** Verint CRM Connector **on:** 23/02/2026 14:14
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 2 deep potholes one after the other. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50192674 **Defect Number:** 42200419

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 2096972 **Logged by:** Verint CRM Connector **on:** 17/02/2026 14:05
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Pavement from peffermill road going into the industrial estate **Contact:**
Part of the pavement has been cleaned though the rest remains very leafy / muddy
having never been cleaned for many years.
Images show the area and how muddy plus a picture of the map indicating the
approximate area this concerns

Enquiry No.: 2092581 **Logged by:** Verint CRM Connector **on:** 11/02/2026 11:06
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Other side of road from nursing home/biscuit factory...heading towards fort. My tyres **Contact:**
been in hole twice his week.. was dark so no idea how big but the bump was
enough!! Bill to you if i need to take car to garage

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50191656 **Defect Number:** 42199184

Enquiry No.: 2092120 **Logged by:** Verint CRM Connector **on:** 10/02/2026 14:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Opp.50 Peffermill Road. **Contact:**
Potholes on road.

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 2085346 **Logged by:** Verint CRM Connector **on:** 29/01/2026 14:59
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: This is a path/pavement from Peffermill Road between Laurence McIntosh and the **Contact:**
Large House. It is a main walkway from Peffermill Road into Peffermill Industrial
Estate joining onto Kings Haugh.

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Enquiry No.: 2083460 **Logged by:** Verint CRM Connector **on:** 26/01/2026 21:33
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There are two potholes the east bound carriageway near 66 Peffermill road they are **Contact:**
quite deep, and caused the front nearside suspension to bottom out I am arranging
to have this inspected,and will claim any costs incurred from The City of Edinburgh
Council

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50190497 **Defect Number:** 42197671

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 2070876 **Logged by:** Verint CRM Connector **on:** 06/01/2026 12:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Yet ANOTHER (or the same pothole badly repaired again!) pothole near to the bus stop on Peffermill Road (as the bus turns left from Peffermill Avenue). Difficult to avoid when a bus is at the bus stop!!

There are regularly many potholes around that area - can they be repaired well please and not ignored or big lumps of tarmac just dumped! Sorry and thanks

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50189458 **Defect Number:** 42196345

Enquiry No.: 2067184 **Logged by:** Verint CRM Connector **on:** 01/01/2026 13:39
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: Bus stop outside Two Wheels Motorbike Showroom (EH16 5LN). Bus sign pole has been damaged and is hanging down and could constitute a danger to anyone standing at the bus stop or passing, if it falls any further.

Enquiry No.: 2056717 **Logged by:** Verint CRM Connector **on:** 11/12/2025 10:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50188339 **Defect Number:** 42195054

Enquiry No.: 2053097 **Logged by:** Verint CRM Connector **on:** 03/12/2025 21:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: 2 x large potholes one after the other on Peffermill Road - just after the bus stop heading towards Craigmillar from Cameron Toll and just past the junction of Prestonfield Avenue **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 2050942 **Logged by:** Verint CRM Connector **on:** 29/11/2025 14:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Large pothole at traffic lights, unable to see when filled with water. Unable to avoid due to crossroad junction **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset
Job Number: 50187779 **Defect Number:** 42194306

Enquiry No.: 2050918 **Logged by:** Verint CRM Connector **on:** 29/11/2025 13:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Pot hole opposite bus shelter **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50187776 **Defect Number:** 42194300

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 2039877 **Logged by:** Verint CRM Connector **on:** 07/11/2025 22:15
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: POT HOLE IS AT THE BUS SHELTER OPPOSITE NAIRNS BISCUIT FACTORY. **Contact:**
THANK YOU

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50186695 **Defect Number:** 42193005

Enquiry No.: 2039333 **Logged by:** Verint CRM Connector **on:** 06/11/2025 21:32
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Just after prestonfeild avenue very large pothole. **Contact:**

Enquiry No.: 2020982 **Logged by:** Verint CRM Connector **on:** 29/09/2025 15:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow The keep left sign at the junction with Peffermill Road and Duddingston Road West is missing and only the raised kerb is left dangerous for traffic turning right onto Peffermill Road
Location: At the junction of Peffermill road and Duddingston road west **Contact:**

Enquiry No.: 2018332 **Logged by:** Verint CRM Connector **on:** 23/09/2025 21:15
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Dangerous traffic island. The keep left sign is missing and a car just drove over the traffic island when turning right from Duddingston. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset
Job Number: 50184999 **Defect Number:** 42190281

Enquiry No.: 2015147 **Logged by:** Verint CRM Connector **on:** 16/09/2025 20:46
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Massive unsafe pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 2014318 **Logged by:** Verint CRM Connector **on:** 15/09/2025 12:37
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Verge / Grass area .
Type:Foliage / Bush
Location: Hedging is high and pushing against boundary line fence and covering fence of 21 castle view drive.
Requiring cut down to a lower height and cut in width. **Contact:**

Enquiry No.: 2001971 **Logged by:** Verint CRM Connector **on:** 23/08/2025 18:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Middle of the road opposite entrance to 60 Peffermill Road flats. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50184031 **Defect Number:** 42189018

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1990926 **Logged by:** Verint CRM Connector **on:** 05/08/2025 16:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Hello, I previously reported this - ref number 101001329434 - and you said you were monitoring it. There are TWO potholes side by side which are deep and will cause a problem to vehicles. It would be appreciated if this can be looked at again please. Impossible to take a photos when driving, but it needs attention many thanks.
Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1988754 **Logged by:** Verint CRM Connector **on:** 01/08/2025 09:23
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Large pothole just after junction to Prestonfield Avenue and before (I am sure) bus stop on left hand side going towards Craigmillar. Difficult to get exact location when concentrating driving!! Thanks in advance
Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1987000 **Logged by:** Verint CRM Connector **on:** 29/07/2025 14:05
Service: Roads General **Subject:** Street Furniture: Defective **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow One of the bollards that are placed on top of road Islands at traffic lights is missing. As a result it is easy to misjudge and miss the isl at the location and drive over it.

Location: Warning bollard at the lights of this junction is missing. Making it easy to drive over the raised curb.
Contact:

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Job Number: 50183242 **Defect Number:** 42187895

Enquiry No.: 1977969 **Logged by:** Verint CRM Connector **on:** 14/07/2025 12:16
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: This area at the junction floods continuously and it gets quite deep. Bus passengers have to walk out onto the road beyond the bus stop to get on board the buses. This has been a problem for years!
Contact:

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Enquiry No.: 1977889 **Logged by:** Verint CRM Connector **on:** 14/07/2025 11:03
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: Manhole cover sticking up about 1.5 inches above the pavement surface causing a trip hazard
Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1950593 **Logged by:** Verint CRM Connector **on:** 20/05/2025 10:35
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush

Location: From Craigmillar Crossroad towards Cameron Toll on left hand side just past dentist. people having to duck to get past. This needs to be cut back
Contact:

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1947432 **Logged by:** Verint CRM Connector **on:** 13/05/2025 15:07
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Pavement.
Type:Foliage / Bush
Location: OVERHANDING BRANCHES BESIDE 176/1 PEFFERMILL ROAD, EDINBURGH EH16 4AH. NEED TO BE CUT BACK AS PEOPLE HAVING TO DUCK TO GET PAST **Contact:**

Enquiry No.: 1940046 **Logged by:** Verint CRM Connector **on:** 28/04/2025 18:43
Service: Roads General **Subject:** Roadworks: Defect **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow There are road works signs that have fallen over in the turn into Peffermill road, EH16 5LL. This has been here for weeks now and sh be removed. It's a tripping hazard for residents.
Location: As described earlier. Fallen road works sign on the pavement that has not been collected. It is a tripping hazard to resident. Please remove. I am trying to upload photos but it won't let me. **Contact:**

Enquiry No.: 1938746 **Logged by:** Verint CRM Connector **on:** 25/04/2025 14:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Dangerous potholes on Peffermill Road **Contact:**
Category: Potholes

Three big potholes near 'Morgan Playing Fields' bus stop on Peffermill Road. You can feel a mini earthquake when buses and HGVs go over them.

Location:
Easting/Northing: 327985/671645 (55.932454, -3.154251)
Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 66, Peffermill Road, Prestonfield, City of Edinburgh, Alba / Scotland, EH16 5UU, United Kingdom
Nearest postcode to the pin placed on the map (auto

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50179369 **Defect Number:** 42182653

Enquiry No.: 1935293 **Logged by:** Verint CRM Connector **on:** 17/04/2025 22:06
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Multiple deep potholes on east bound carriage way between Cameron House Avenue and Kings Haugh. It's very unsafe for cyclists **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50178755 **Defect Number:** 42181612

Enquiry No.: 1906210 **Logged by:** Verint CRM Connector **on:** 19/02/2025 18:51
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: rough and uneven road at the junction **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1902513 **Logged by:** Verint CRM Connector **on:** 12/02/2025 11:27
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Just past traffic lights in front of dentist heading to Peffermill. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset
Job Number: 50175130 **Defect Number:** 42176053

Enquiry No.: 1899006 **Logged by:** Verint CRM Connector **on:** 05/02/2025 10:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Numerous potholes here again **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50174801 **Defect Number:** 42175651

Enquiry No.: 1894814 **Logged by:** Verint CRM Connector **on:** 29/01/2025 07:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50173787 **Defect Number:** 42174268

Enquiry No.: 1884144 **Logged by:** Verint CRM Connector **on:** 10/01/2025 10:16
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 2 potholes causing me to have to change my line on my bike **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1878492 **Logged by:** Verint CRM Connector **on:** 03/01/2025 09:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pot hole in front of bus stop peffermill rd. bust my car tyre **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50172069 **Defect Number:** 42172024

Enquiry No.: 1877560 **Logged by:** Verint CRM Connector **on:** 31/12/2024 21:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole is at the bus stop opposite the biscuit factory. Thank you **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1868726 **Logged by:** Verint CRM Connector **on:** 09/12/2024 09:11
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 2 large potholes, it was only repaired last year, now has reappeared! **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50171138 **Defect Number:** 42170876

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1858647 **Logged by:** Verint CRM Connector **on:** 14/11/2024 13:46
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Claim form emailed - The specific date and time I can not remember as it happened a while back and the damage was not immediately noticed, as explained in detail in my previous email.
Location: About a month ago, not got exact date, I hit 2 pot holes directly next to each other, at the above location, it was fine until the next day I noticed the pressure dropped, I filled and it dropped again next day, I assumed it might just be a nail, my tyres are not cheap so I had to wait until I had spare cash to repair it, upon getting new tyre I was informed that there are 2 cracks in my alloy that was causing the loss of air, you have repaired holes now but I have photos before it was done. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1853626 **Logged by:** Verint CRM Connector **on:** 04/11/2024 10:44
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Two large potholes heading eastwards on Peffermill Road close to bus shelter at no 73. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50169308 **Defect Number:** 42168524

Enquiry No.: 1848850 **Logged by:** Verint CRM Connector **on:** 24/10/2024 13:33
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Earlier this year the Peffermill Road was resurfaced, when the lines were repainted for the road they missed the double yellow lines between the entrance for the University Playing fields and Two Wheels Motorcycles. The parking has caused chaos when the playing fields are busy, with Ambulances and trucks struggling to get passed the central island. If you check on Google maps, you can see in both Street View and Satellite where the lines were previously. Can they be reinstated please? **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1844312 **Logged by:** Verint CRM Connector **on:** 14/10/2024 12:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Outside 53 Peffermill Road. Deep pothole in roadway. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50168099 **Defect Number:** 42166779

Enquiry No.: 1839398 **Logged by:** Stacey Devine **on:** 02/10/2024 13:40
Service: Roads General **Subject:** Traffic Sign: General Enquiry **Classification:** General Enquiry
Desc.: Difficulties with Emergency services and deliveries finding properties 16-30 on Craigmillar Castle Road as these fork off, sit behind the main road and no street signage to advise of this?
Location: No street signage for properties 16-30 Craigmillar Castle Road, Edinburgh, EH16 4AR Difficulties with Emergency services and deliveries finding properties 16-30 on Craigmillar Castle Road as these fork off, sit behind the main road and no street signage to advise of this? **Contact:**

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1835140 **Logged by:** Verint CRM Connector **on:** 22/09/2024 18:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Very deep pothole just before the east bound bus stop, likely caused by buses **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50166881 **Defect Number:** 42165270

Enquiry No.: 1832238 **Logged by:** Verint CRM Connector **on:** 15/09/2024 22:51
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Called this morning to report that he has received a letter from ourselves regarding overgrown foilage. The picture accompanying the letter is for a property 2 doors away from him at no. 2 so he wonders why he has received this.
Location: My daughter of 10 walked into this very very overgrown bush and scratched her face, I had to take her to the pharmacy to get her cuts checked. If a child can scratch their face, you can imagine how adults, wheelchair helping person, or child pushing moms walk here, they almost have to step onto the road. Two people going opposite direction can't walk at the same time either. It's council property with council tenants. Please send someone to not only cut the overgrowth but cut it way back. Thanks **Contact:**

Enquiry No.: 1810101 **Logged by:** Verint CRM Connector **on:** 02/08/2024 17:51
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Footpath.
Type:Foliage / Bush
Location: Overgrown trees causing people to walk on road, including bus lane **Contact:**

Enquiry No.: 1808997 **Logged by:** Verint CRM Connector **on:** 01/08/2024 07:31
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Footpath.
Type:Foliage / Bush
Location: 101002594436 **Contact:**

Enquiry No.: 1808949 **Logged by:** Verint CRM Connector **on:** 31/07/2024 22:39
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Footpath.
Type:Foliage / Bush
Location: The bushes and trees are protruding over the fences onto the walkway in the entire area including the bus stop outside the church. People are using the overgrown foliage to hide unwanted discarded furniture its that bad! **Contact:**

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1808391 **Logged by:** Verint CRM Connector **on:** 31/07/2024 07:36
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Verge / Grass area .
Type:Foliage / Bush
Location: The overgrown bushes and trees all the way from Craigmillar Bristo Parish Church right along Peffermill Road and around the semi circle is an absolute disgrace. It's bad enough with the abandoned furniture and white goods strewn about the streets but the vegetation is almost jungle like. The area is very badly neglected, it's embarrassing. **Contact:**

Enquiry No.: 1799411 **Logged by:** Verint CRM Connector **on:** 16/07/2024 14:14
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Trees on the pavement are so overgrown we have to duck to walk down the street. **Contact:**
The grass is very overgrown

Enquiry No.: 1796273 **Logged by:** Verint CRM Connector **on:** 11/07/2024 06:38
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Overgrown hedges obstructing the footpath. **Contact:**

Enquiry No.: 1795946 **Logged by:** Verint CRM Connector **on:** 10/07/2024 14:11
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: Hedge and trees growing over onto pavement meaning pedestrians need to bend over to pass under the branches, or walk on busy road to avoid. **Contact:**

Enquiry No.: 1774022 **Logged by:** Verint CRM Connector **on:** 06/06/2024 09:57
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Footpath.
Type:Foliage / Bush
Location: Twitter- overgrowth of bushes etc. unfortunately the overgrowth is so much that it's occluding most of the pavement. So much so that when I'm walking my children to school, it's pushing them almost onto the road, I feel it's quite dangerous as it's a busy road also. Can you advise who would be responsible for cutting this **Contact:**

Enquiry No.: 1769615 **Logged by:** Verint CRM Connector **on:** 01/06/2024 20:04
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 2 potholes at bus stop opposite Nairns biscuit factory **Contact:**

Plot Number: 1.00

Feature Id - Location: Ward 15 - Cameron Terrace to King's Haugh

Feature Type: Road Asset

Job Number: 50161601

Defect Number: 42158705

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1747887 **Logged by:** Verint CRM Connector **on:** 03/05/2024 16:03
Service: Roads General **Subject:** Road Safety: General Enquiry **Classification:** Request for service
Desc.:
Location: Lane indicators are marked incorrectly. Left lane should be straight on and left-turn lane. Right lane should be right turn lane. Markings are unclear and wrong way around and cause traffic accidents. Buses cannot enter right lane after bus stop. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Enquiry No.: 1735606 **Logged by:** Verint CRM Connector **on:** 12/04/2024 13:55
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Number of potholes along Peffermill Road from the bus gate to past the factory on both side of road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1727568 **Logged by:** Verint CRM Connector **on:** 31/03/2024 19:21
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: There is a dropped drain manhole cover at the lights as you wait to turn left onto Duddingston Road West or go straight on from Peffermill Road onto Nuddrie Mains Road. Thank you. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Enquiry No.: 1720665 **Logged by:** Verint CRM Connector **on:** 19/03/2024 12:20
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 12inch potholes **Contact:**
Category: Potholes

Potholes been there for 4 weeks

Location:
Easting/Northing: 327543/671292 (55.929218, -3.161216)
Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): Peffermill Road, Prestonfield, City of Edinburgh, Alba / Scotland, EH16 5LD, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH16 5LD (67m away)

Enquiry No.: 1718804 **Logged by:** Verint CRM Connector **on:** 15/03/2024 19:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Job Number: 50156103 **Defect Number:** 42151935

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1718803 **Logged by:** Verint CRM Connector **on:** 15/03/2024 19:55
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole on road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50156105 **Defect Number:** 42151938

Enquiry No.: 1713420 **Logged by:** Verint CRM Connector **on:** 07/03/2024 07:48
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Several deep potholes in middle of road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50155024 **Defect Number:** 42150495

Enquiry No.: 1709504 **Logged by:** Verint CRM Connector **on:** 29/02/2024 14:54
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type unlit
Location: There are two "ambulance station" signs on Peffermill Road. These are fairly small, unlit and not in prominent view. King's Haugh houses the city's largest ambulance station in addition to various businesses. Peffermill Road is immensely busy and there is a constant flow of ambulances and transport ambulances entering and exiting from there, often being ignored by other road users. Please consider amplifying the signage and adding red box road markings similar to every fire station in town. **Contact:**

Enquiry No.: 1706565 **Logged by:** Verint CRM Connector **on:** 25/02/2024 19:16
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road works on Peffermill Road- There are absolutely no signs to say the road is closed from east.... Pretty ridiculous given the (very) long detour and resulting queues of cars doing u turns when finally arriving at road closure. **Contact:**

Enquiry No.: 1704917 **Logged by:** Verint CRM Connector **on:** 22/02/2024 17:41
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50154055 **Defect Number:** 42149019

Enquiry No.: 1704301 **Logged by:** Verint CRM Connector **on:** 22/02/2024 07:14
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: In line with the lights on the lane going straight over to Niddrie mains road / turn up to craigmillar castle **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1701187 **Logged by:** Verint CRM Connector **on:** 17/02/2024 10:25
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole heading east **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset
Job Number: 50153558 **Defect Number:** 42148486

Enquiry No.: 1697034 **Logged by:** Verint CRM Connector **on:** 10/02/2024 19:29
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: This absolute crater in the road going towards Cameron toll roundabout opposite the junction for Cameron house avenue. It's in excess of 3-5inches in depth and about a foot and a half in diameter minimum. Not just that but the roundabout its self is an absolute joke. Its damaged the bloody powder coating on the inside of the driver side wheel. The roads around that area are absolutely shocking. The cross roads (traffic lights) at peffermill road/ duddingstin road west is the same. Sort it! **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1695690 **Logged by:** Verint CRM Connector **on:** 08/02/2024 14:14
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 2 rather deep potholes in the middle of the road causing splashes to the public standing waiting for a bus and causing damage to suspension of vehicles. I think they were fixed a few weeks ago but they have deteriorated badly since. Not a solid enough repair for such heavy traffic! Located opposite new flats 54-60 Peffermill Road. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1694579 **Logged by:** Verint CRM Connector **on:** 07/02/2024 00:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: It's a big pot hole just before the nairns biscuit factory. On the left side of the road as if you are coming from Cameron till. Just after Preston field housing state coming out of the side street where only buses have access to. U go left as if you are going to niddrie **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1691239 **Logged by:** Verint CRM Connector **on:** 01/02/2024 20:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Absolute crater in the middle of the road. Reported previously but not repaired **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1691238 **Logged by:** Verint CRM Connector **on:** 01/02/2024 20:33
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: One of many potholes on this stretch of road. Reported previously but not repaired but critical risk to roads users and their vehicles. One for the overnight team. Outside a school !! **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50152012 **Defect Number:** 42146191

Enquiry No.: 1691237 **Logged by:** Verint CRM Connector **on:** 01/02/2024 20:32
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: One of many potholes on this stretch of road. Reported previously but not repaired but critical risk to roads users and their vehicles. One for the overnight team. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50152010 **Defect Number:** 42146189

Enquiry No.: 1690249 **Logged by:** Verint CRM Connector **on:** 31/01/2024 18:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole opened again **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50151905 **Defect Number:** 42146005

Enquiry No.: 1678966 **Logged by:** Stacey Devine **on:** 16/01/2024 09:20
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Deep pot hole on middle of road heading towards niddrie from cameron toll
Location: Deep pot hole on middle of road heading towards niddrie from cameron toll **Contact:**

Enquiry No.: 1678511 **Logged by:** Verint CRM Connector **on:** 15/01/2024 14:22
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: On he junction in the middle of the road where the buses come out **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50150423 **Defect Number:** 42144280

Enquiry No.: 1678509 **Logged by:** Verint CRM Connector **on:** 15/01/2024 14:21
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole west of the bus top on niddrie bound side **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1678317 **Logged by:** Stewart McGregor **on:** 15/01/2024 10:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Pls inspect Peffermill Road/ Dalkeith Road to Cameron Toll Roundabout as potholes
Location: **Contact:**

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1673980 **Logged by:** Verint CRM Connector **on:** 08/01/2024 15:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole is on Peffermill Road between Prestonfield Avenue and the bus shelter on Peffermill Road as you head towards Craigmillar awsy from Cameron Toll. Opposite the new flats. Thank you. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50149675 **Defect Number:** 42143522

Enquiry No.: 1672025 **Logged by:** Verint CRM Connector **on:** 05/01/2024 10:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole middle of carriageway **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50149416 **Defect Number:** 42143313

Enquiry No.: 1660966 **Logged by:** Verint CRM Connector **on:** 13/12/2023 13:32
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Two huge potholes at the east bound lane around the corner - right opposite the Nairn's sign **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1660559 **Logged by:** Verint CRM Connector **on:** 12/12/2023 20:47
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.: claim form emailed 14/12/23 - Julie callaghan

5 foxglove close Edinburgh

Eh16 4wy

07412898772

ryhalle@gmail.com

10/12/23 approx 3.30pm

incident - Peffermill Road just after peffermill primary school (coming from cameron toll heading towards craigmillar) across from Cameron Park nursing home.

Driving along on sunday afternoon coming from cameron toll towards craigmillar when my tyre suddenly made a huge bang giving me and my teenage daughter a fright. We were in traffic and couldnt pull over straight away , we made it to a side street in craigmillar where we pulled over to discover my front (drivers side) tyre was shot. I had to call my breakdown cover and myself and my daughter were left waiting in the cold and rain untill my breskdown arrived.

I recently had a MOT and had my tyres replaced so iam unhappy that I now have to go to garage to get my spare taken off and purchase a new tyre, and this time of year in particular its someth that i cant afford easily.

There are many big , dangerous pot holes around my area Eh16 and this is the second time my car has been affected, after a puncture earlier this year.

Location: Coming from cameron toll towards craigmillar just past the primary school and outside the care home theres a large deep pothole in the road that startled myself and my daughter and burst my front wheel (drivers side) **Contact:**

Enquiry No.: 1660167 **Logged by:** Verint CRM Connector **on:** 12/12/2023 11:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Massive holes in this street **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1658659 **Logged by:** Verint CRM Connector **on:** 09/12/2023 22:14
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole is approx opposite the goods yard entrance to Nairne Biscuit Factory as you head away from Cameron Toll towards Craigmillar. Thank you **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50147660 **Defect Number:** 42141540

Enquiry No.: 1657956 **Logged by:** Verint CRM Connector **on:** 08/12/2023 12:41
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole is beside bus shelter just before Cameron Park Nursing Home as you head away from Cameron Toll towards Craigmillar. This is a continuous pot hole needing repaired frequently. Thank you. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50147661 **Defect Number:** 42141541

Enquiry No.: 1656417 **Logged by:** Ronnie Kirton Vaughan **on:** 06/12/2023 09:22
Service: Roads General **Subject:** Fence: Damaged / Defective **Classification:** Request for service
Desc.: railings bent inwards towards pavement due to being struck by a bus
Location: peffermill road heading towards Cameron Toll just after the Niarn Biscuit factory **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50147278 **Defect Number:** 42141165

Enquiry No.: 1650689 **Logged by:** Verint CRM Connector **on:** 25/11/2023 15:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole middle of carriageway **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50146642 **Defect Number:** 42140497

Enquiry No.: 1650687 **Logged by:** Verint CRM Connector **on:** 25/11/2023 15:48
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole on Peter mill road in the middle of the carriageway **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 15 - Branch south then south-west at No.54 **Feature Type:** Road Asset
Job Number: 50146641 **Defect Number:** 42140494

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1645943 **Logged by:** Verint CRM Connector **on:** 17/11/2023 08:22
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Large pothole **Contact:**
Category: Potholes

Large pothole on the eastbound carriageway. It is a significant danger to cyclists and other road users.

Location:
Easting/Northing: 327588/671312 (55.929398, -3.160513)
Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 3, Peffermill Road, Prestonfield, City of Edinburgh, Alba / Scotland, EH16 5LD, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH16 5LD (29m away)

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50145982 **Defect Number:** 42139748

Enquiry No.: 1639265 **Logged by:** Stuart Wright **on:** 06/11/2023 08:55
Service: Roads General **Subject:** Roadworks: General Enquiry **Classification:** General Enquiry
Desc.: Road work on peffermill road Nov 5th 2023. Can clearly see all road work has been completed by temp taffic light left in place with parts of the barrier also left in place. Poor work ethnic in completing the job
Location: Peffermill Road **Contact:**

Enquiry No.: 1635426 **Logged by:** Verint CRM Connector **on:** 30/10/2023 12:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Good morning **Contact:**
I had a bad experience with pothole yesterday morning. I was driving in Peffermill road west bound and i took a pothole very badly and i've damaged the steering rack of my car. Who will pay for this big damage? I pay road tax already and this shouldn't happen or at least council must be responsible of it. Location is Peffermill road at Kings Haugh bus stop
Sunday 29th of October 2023 at 5.25 a.m.
My name is Marco Iodice
Address 25 Moffat way
contact number 07904943988

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Enquiry No.: 1634346 **Logged by:** Verint CRM Connector **on:** 27/10/2023 16:06
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Near to bus stop just before Cameron Park Nursing Home which is on opposite side **Contact:**
of road as you head away from Cameron Toll

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50144629 **Defect Number:** 42138254

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1634338 **Logged by:** Verint CRM Connector **on:** 27/10/2023 16:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Outside biscuit factory before the traffic island as you head towards Cameron Toll **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50144628 **Defect Number:** 42138253

Enquiry No.: 1634337 **Logged by:** Verint CRM Connector **on:** 27/10/2023 15:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: At the bus stop just before Craimillar Castle Gardens as you head towards Cameron Toll **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset
Job Number: 50144720 **Defect Number:** 42138344

Enquiry No.: 1627387 **Logged by:** Verint CRM Connector **on:** 12/10/2023 20:48
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 15 - Branch south then south-west at No.54 **Feature Type:** Road Asset
Job Number: 50143946 **Defect Number:** 42137463

Enquiry No.: 1625168 **Logged by:** Verint CRM Connector **on:** 08/10/2023 18:30
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large Pothole, large enough for buses to get a wheel into. located at the bus stop craigmillar castle gardens bus stop citybound **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset
Job Number: 50143783 **Defect Number:** 42137293

Enquiry No.: 1587098 **Logged by:** Verint CRM Connector **on:** 25/07/2023 16:13
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: Reporting for a second time - Privet hedge almost completely blocking use of pavement **Contact:**

Enquiry No.: 1578922 **Logged by:** Verint CRM Connector **on:** 10/07/2023 08:54
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge pothole which is damaging cars **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50139108 **Defect Number:** 42131658

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1578345 **Logged by:** Verint CRM Connector **on:** 08/07/2023 09:06
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: large pothole filled hole that protrudes out of the road very dangerously causing cyclist to serve to avoid..... also 2-3 potholes between here and bust stop ats side of road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1578337 **Logged by:** Verint CRM Connector **on:** 08/07/2023 08:55
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 2 potholes having to avoid on bike **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Job Number: 50139107 **Defect Number:** 42131657
Enquiry No.: 1570449 **Logged by:** Verint CRM Connector **on:** 22/06/2023 09:52
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Verge / Grass area .
Type:Foliage / Bush
Location: overgrown tree which needs cut back causing obstruction of light and d a safety hazard **Contact:**

Enquiry No.: 1542897 **Logged by:** Verint CRM Connector **on:** 25/04/2023 20:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There are several pot holes in the area just before the bus stop that caused me severe damage to my vehicle the main hole is over 15" long by 8"wide and 5" deep there are several others on this part of the road my car was thrown upwards towards the pavement and almost into the bus shelter on the evening of 23rd March this whole area of the road as you can see requires to be resurfaced as soon as possible. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Enquiry No.: 1534749 **Logged by:** Verint CRM Connector **on:** 09/04/2023 11:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There is a massive deep pothole on the left side of the road coming from Cameron toll towards Craigmillar. I haven't noticed it and it has damaged my vehicle. I now have to exchange the tyre due to a bulge on it. I want some one to contact me as soon as possible **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Job Number: 50134098 **Defect Number:** 42125061
Enquiry No.: 1530355 **Logged by:** Verint CRM Connector **on:** 30/03/2023 09:19
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole on the main road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Job Number: 50133933 **Defect Number:** 42124901

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1528700 **Logged by:** Verint CRM Connector **on:** 27/03/2023 10:34
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type unlit
Location: The pole has been damaged and partially collapsed. The mounted sign is now posing a hazard to pedestrians on the footway. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50133265 **Defect Number:** 42124166

Enquiry No.: 1515501 **Logged by:** Verint CRM Connector **on:** 25/02/2023 22:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole is at the bus stop as you head towards Cameron Toll **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset
Job Number: 50130740 **Defect Number:** 42120713

Enquiry No.: 1515500 **Logged by:** Verint CRM Connector **on:** 25/02/2023 21:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole is opposite the site lorry entrance to Nairns biscuit Factory. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1515471 **Logged by:** Verint CRM Connector **on:** 25/02/2023 20:06
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: At the bus stop **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Enquiry No.: 1515167 **Logged by:** Verint CRM Connector **on:** 24/02/2023 18:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset
Job Number: 50130740 **Defect Number:** 42120713

Enquiry No.: 1514031 **Logged by:** Verint CRM Connector **on:** 22/02/2023 19:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes are atrocious in this area, causing cars to either swerve lanes or potentially damage wheels ir shock absorbers on car. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset
Job Number: 50130091 **Defect Number:** 42119722

Enquiry No.: 1510430 **Logged by:** Verint CRM Connector **on:** 15/02/2023 19:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 2 massive potholes on this stretch **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50130099 **Defect Number:** 42119730

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1507874 **Logged by:** Leigh Finlay **on:** 10/02/2023 09:24
Service: Roads General **Subject:** Roadworks: General Enquiry **Classification:** General Enquiry
Desc.: Lorry Stuck under bridge at camron toll and need crewe to attend with barriers
Location: **Contact:**

Enquiry No.: 1506730 **Logged by:** Verint CRM Connector **on:** 08/02/2023 09:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge potholes causing problems to vehicles. Including buses. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Enquiry No.: 1506725 **Logged by:** Verint CRM Connector **on:** 08/02/2023 09:55
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Multiple big pot holes on both sides of road running from peffermill Road to Craigmillar Castle Road.
The huge cluster of multiple pot holes runs from kinghaugh junction to Craigmillar Castle Road of peffermill Road. **Contact:**

Enquiry No.: 1504309 **Logged by:** Verint CRM Connector **on:** 03/02/2023 10:18
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Big Pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1502773 **Logged by:** Verint CRM Connector **on:** 31/01/2023 18:39
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes on the road **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Enquiry No.: 1502612 **Logged by:** Verint CRM Connector **on:** 31/01/2023 15:07
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Lots of pot holes **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Enquiry No.: 1502606 **Logged by:** Verint CRM Connector **on:** 31/01/2023 15:04
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Lots of large pot holes **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Enquiry No.: 1502591 **Logged by:** Verint CRM Connector **on:** 31/01/2023 14:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Several yards of potholes on Peffermill Road travelling east beyond Peffermill Industrial Estate towards Niddrie Mains Road. Particularly bad on inside lane towards railway bridge and inside lane at pedestrian crossing. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1500875 **Logged by:** Verint CRM Connector **on:** 28/01/2023 10:44
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Pothole in drain cover maybe for a sewer or gas supply on the corner of Cameron House Avenue and Peffermill Road. **Contact:**

Trip hazard.

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset
Job Number: 50128777 **Defect Number:** 42117954

Enquiry No.: 1497813 **Logged by:** Verint CRM Connector **on:** 23/01/2023 14:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**
Category: Potholes

Danger to traffic

Location:
Easting/Northing: 327621/671335 (55.929611, -3.159991)
Nearest road to the pin placed on the map (automatically generated by Bing Maps):
4 Peffermill Road, Prestonfield, EH16 5LH, Scotland, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH16 5LH
(19m away)

Enquiry No.: 1497812 **Logged by:** Verint CRM Connector **on:** 23/01/2023 14:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Abysmal Road condition **Contact:**
Category: Potholes

Road surface absolutely atrocious

Location:
Easting/Northing: 327559/671280 (55.929106, -3.160968)
Nearest road to the pin placed on the map (automatically generated by Bing Maps):
Peffermill Road, Prestonfield, EH16 5LD, Scotland, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH16 5LD
(68m away)

Enquiry No.: 1494961 **Logged by:** Verint CRM Connector **on:** 18/01/2023 12:46
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Manhole cover in eastbound carrigeway just past crossing is dislodged, one corner is raised about 50mm, not sure if it may also be loose. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset
Job Number: 50126890 **Defect Number:** 42115869

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1494345 **Logged by:** Verint CRM Connector **on:** 17/01/2023 15:22
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: outside the ambulance station travelling east - huge potholes to be repaired - the same at ladywell road at the cameron toll roundabout **Contact:**

Enquiry No.: 1492809 **Logged by:** Verint CRM Connector **on:** 15/01/2023 16:45
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Enquiry No.: 1492734 **Logged by:** Verint CRM Connector **on:** 15/01/2023 14:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep potholes on the eastbound side of peffermill road just before the flats at Dryburgh Crescent. Just before bus stop **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Enquiry No.: 1492383 **Logged by:** Verint CRM Connector **on:** 14/01/2023 18:04
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: MASSIVE HOLES IN ROAD **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Job Number: 50126896 **Defect Number:** 42115880

Enquiry No.: 1491263 **Logged by:** Verint CRM Connector **on:** 13/01/2023 08:16
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: large pothole easting/northing: 328677/671610 - nearest address: 190 peffermill road, eh16 4aj **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 17 - King's Haugh to Duddingston Road West **Feature Type:** Road Asset

Enquiry No.: 1490589 **Logged by:** Verint CRM Connector **on:** 12/01/2023 10:33
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep pothole, risk to cars and cyclists. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Job Number: 50126939 **Defect Number:** 42115914

Enquiry No.: 1490497 **Logged by:** Verint CRM Connector **on:** 12/01/2023 09:19
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: multiple potholes from roundabout along Peffermill road. dangerous for cyclists **Contact:**

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1489773 **Logged by:** Anne Frase **on:** 11/01/2023 11:14
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: 2 potholes
Category: Potholes
2 potholes at the bus stop. Dangerous for cyclists.
Location: Location:
Easting/Northing: 328213/671622 (55.932277, -3.150596)
Nearest road to the pin placed on the map (automatically generated by Bing Maps): 73 Peffermill Road, Prestonfield, EH16 5LR, Scotland, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH16 5LR (19m away)
Location: 2 potholes **Contact:**
Category: Potholes
2 potholes at the bus stop. Dangerous for cyclists.
Location: Location:
Easting/Northing: 328213/671622 (55.932277, -3.150596)
Nearest road to the pin placed on the map (automatically generated by Bing Maps):
73 Peffermill Road, Prestonfield, EH16 5LR, Scotland, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH16 5LR
(19m away)

Enquiry No.: 1489686 **Logged by:** Verint CRM Connector **on:** 11/01/2023 09:54
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: large pothole - nearest address: 1/6 Peffermill Road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1489636 **Logged by:** Verint CRM Connector **on:** 11/01/2023 08:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Enquiry No.: 1488367 **Logged by:** Verint CRM Connector **on:** 09/01/2023 14:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Peffermill Road, No 58 on junction.
pothole on road. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 15 - Branch south then south-west at No.54 **Feature Type:** Road Asset

Job Number: 50126020 **Defect Number:** 42114932

Enquiry No.: 1487686 **Logged by:** Verint CRM Connector **on:** 08/01/2023 20:13
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: As you get off the first left exit towards Niddrie & Musselburgh sign at the **Contact:**
roundabout coming down from Cameron crescent adjacent to the traffic lights which
go across to peffermile road there is a deep pothole which can't be avoided due to
the narrow turning of that road

Plot Number: 1.00 **Feature Id - Location:** Ward 15 - Cameron Terrace to King's Haugh **Feature Type:** Road Asset

Job Number: 50126026 **Defect Number:** 42114938

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 15 - Cameron Terrace to King's Haugh		Feature Type: Road Asset		Area: South East Locality	
10565055	WS: Replace Residual Ind Grey - replace as old is contaminated by others (Enquiry 2081074)	Flat 6 192 Peffermill Road Prestonfield Edinburgh City of Edinburgh EH16 4AJ	WS: Waste Bin Replace	Job Complete	22/01/2026	10/03/2026	Act.
10565056	WS: Replace Box BLUE - replace as new service (Enquiry 2081076)	Flat 6 192 Peffermill Road Prestonfield Edinburgh City of Edinburgh EH16 4AJ	WS: Waste Bin Replace	Job Complete	22/01/2026	10/03/2026	Act.
50116562	Clean Advanced directional sign opposite no 3 (RD: Unlit Sign Damaged/Missing)	Opposite no 3	RD: Cat 3 - 60 Day	Job Complete	14/07/2022	02/05/2023	Act. ROAD/8206555
50125355	Cw potholes at bus stop (RD: CW Pothole)	Peffermill road east bound opp nairns	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/01/2023	15/01/2023	Act. ROAD/8207024
50126026	Cw pothole marked on site Road: Defective / Damaged (Enquiry 1487686) (RD: CW Pothole)	Peffermill Road junction with Cameron Toll roundabout as per map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/01/2023	15/01/2023	Act. ROAD/8207072
50126896	1 number pothole (RD: CW Pothole)	At Lampost number PDR21	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/01/2023	01/02/2023	Act. ROAD/8207125
50126939	Cw pothole marked on site Road: Defective / Damaged (Enquiry 1490589) (RD: CW Pothole)	Peffermill Road opposite 1	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/01/2023	01/02/2023	Act. ROAD/8207132
50128777	Hole in manhole cover Pavement: Damaged / Defective (Enquiry 1500875) (RU: Utility Apparatus)	Peffermill Road at Cameron house avenue	RU: Fail Med.Risk (Apparatus)	Job Complete	08/02/2023	08/02/2023	Act.
50130099	Cw x1Road: Defective / Damaged (Enquiry 1510430) (RD: CW Pothole)	Opposite new housing developments	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2023	27/02/2023	Act. ROAD/8207327
50131087	1 dislodged kerb (RD: FW Kerb Dislodged/Rocking)	At entrance outside nairns oatcakes	RD: Cat 4 - Programmed	No code allocated	05/03/2023	05/03/2024	Est.
50131088	2 carriageway potholes (RD: CW Pothole)	Opposite prestonfield avenue	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/03/2023	07/03/2023	Act. ROAD/8207382
50131089	2 carriageway potholes (RD: CW Pothole)	Opposite 5 at bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/03/2023	07/03/2023	Act. ROAD/8207382
50131092	1 carriageway pothole (RD: CW Pothole)	Opposite 50	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/03/2023	07/03/2023	Act. ROAD/8207382
50133265	Remove Collapsed sign pole make safe footway and leave signs at Bankhead Depot stores. (RD: Unlit Sign Damaged/Missing)	On footway opposite junction with Prestonfield Avenue	RD: Cat 1 - 24 Hours	Job Complete	30/03/2023	30/03/2023	Act. ROAD/8207503

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 15 - Cameron Terrace to King's Haugh		Feature Type: Road Asset		Area: South East Locality	
50133933	Cw x1 Road: Defective / Damaged (Enquiry 1530355) (RD: CW Pothole)	Opposite new development	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	06/04/2023	07/04/2023	Act. ROAD/820755C
50139107	Cw x2 potholes Road: Defective / Damaged (Enquiry 1578337) (RD: CW Pothole)	At crossing point outside of primary school	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/07/2023	12/07/2023	Act. ROAD/8207901
50139108	Cw x1 pothole Road: Defective / Damaged (Enquiry 1578922) (RD: CW Pothole)	Opposite new development near bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/07/2023	12/07/2023	Act. ROAD/8207901
50142968	1no pothole (RD: CW Pothole)	Just east of Ip22	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/09/2023	22/09/2023	Act. ROAD/8208091
50143909	1 carriageway pothole (RD: CW Pothole)	Junction with kings haugh	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/10/2023	13/10/2023	Act. ROAD/8208157
50144628	Cw x1 pothole Road: Defective / Damaged (Enquiry 1634338) (RD: CW Pothole)	Outside of Nairns biscuit factory head towards Cameron Toll	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/10/2023	30/10/2023	Act. ROAD/8208203
50144629	Cw x1 pothole Road: Defective / Damaged (Enquiry 1634346) (RD: CW Pothole)	Opposite Nursing Home (heading towards Craigmiller	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/10/2023	30/10/2023	Act. ROAD/8208203
50145898	Cw x1 pothole (RD: CW Pothole)	Outside of Nairns biscuits	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/11/2023	17/11/2023	Act. ROAD/8208278
50145982	Road: Defective / Damaged (Enquiry 1645943) (RD: CW Pothole)	Bus stop opposite number 7	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/11/2023	20/11/2023	Act. ROAD/8208283
50146642	Cw x1 pothole Road: Defective / Damaged (Enquiry 1650689) (RD: CW Pothole)	Opposite Cameron Park Nursing Home	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/11/2023	03/12/2023	Act. ROAD/8208318
50147278	Railings damaged, please replace. Damaged railings uplifted by Inspector. Please see attached photos (RD: Railing Damage/Missing/New)	Outside number 66	RD: Cat 4 - Programmed	No code allocated	06/12/2023		
50147660	Cw x1 pothole Road: Defective / Damaged (Enquiry 1658659) (RD: CW Pothole)	Opposite the Biscuit Factory	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/12/2023	12/12/2023	Act. ROAD/8208377
50147661	Cw x1 pothole Road: Defective / Damaged (Enquiry 1657956) (RD: CW Pothole)	Opposite New Development	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/12/2023	12/12/2023	Act. ROAD/8208377
50149416	Cw x1 pothole Road: Defective / Damaged (Enquiry 1672025) (RD: CW Pothole)	Just after Prestonfield Ave	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/01/2024	19/01/2024	Act. ROAD/8208496
50149675	Cw 1 pothole Road: Defective / Damaged (Enquiry 1673980) (RD: CW Pothole)	Just before the bus heading towards Craigmiller	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/01/2024	19/01/2024	Act. ROAD/8208511
50150423	Cw x1 pothole Road: Defective / Damaged (Enquiry 1678511) (RD: CW Pothole)	At the junction with Prestonfield Ave (Bus gate)	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/01/2024	19/01/2024	Act. ROAD/820855E

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 15 - Cameron Terrace to King's Haugh		Feature Type: Road Asset		Area: South East Locality	
50151905	Cw x2 potholes Road: Defective / Damaged (Enquiry 1690249) (RD: CW Pothole)	Centre of the Road opposite New Development	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/02/2024	12/02/2024	Act. ROAD/8208663
50152010	Cw x3 potholes Road: Defective / Damaged (Enquiry 1691237) (RD: CW Pothole)	Opposite the junction with Cameron House Crescent	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/02/2024	12/02/2024	Act. ROAD/8208670
50152012	Cw x1 pothole Road: Defective / Damaged (Enquiry 1691238) (RD: CW Pothole)	Opposite side to the Primary School	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/02/2024	12/02/2024	Act. ROAD/8208671
50154039	Replace faded no right turn 600mm sign diagram no 612 (TS: Sign Face Faded (SSO))	On west footway at peffermill road at junction with Cameron house avenue	RD: Cat 3 - 60 Day	Job Complete	26/02/2024	06/03/2024	Act. ROAD/8208810
50154055	Cw x2 potholes Road: Defective / Damaged (Enquiry 1704917) (RD: CW Pothole)	Eastbound just after bus stop opposite new development	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/02/2024	19/03/2024	Act. ROAD/8208811
50154463	Scottish Telecom cover damaged (RU: Utility Apparatus)	At the junction with Cameron House Crescent	RU: Fail Med.Risk (Apparatus)	Job Complete	01/03/2024	01/03/2024	Act.
50155024	Cw x3 potholes Road: Defective / Damaged (Enquiry 1713420) (RD: CW Pothole)	Opposite the Nairns biscuit factory (bus stop)	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/03/2024	19/03/2024	Act. ROAD/8208886
50156103	Cw x1 pothole Road: Defective / Damaged (Enquiry 1718804) (RD: CW Pothole)	Opposite new development (eastbound)	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/03/2024	19/03/2024	Act. ROAD/8208956
50156105	Cw x1 pothole Road: Defective / Damaged (Enquiry 1718803) (RD: CW Pothole)	After bus stop , opposite new development (eastbound)	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/03/2024	19/03/2024	Act. ROAD/8208956
50161459	Cw x2 potholes (RD: CW Pothole)	Centre of the road opposite new development	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/05/2024	02/06/2024	Act. ROAD/8209315
50161601	Cw x2 potholes Road: Defective / Damaged (Enquiry 1769615) (RD: CW Pothole)	Bus Stop opposite biscuit factory, just before the junction with Kings Haugh	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/06/2024	05/06/2024	Act. ROAD/8209322
50163989	Test (TS: Housing Dev Sign Remove)	Test	RD: Cat 4 - Programmed	No code allocated	16/07/2024		
50166881	Cw x2 potholes Road: Defective / Damaged (Enquiry 1835140) (RD: CW Pothole)	Before and after bus stop opposite new development	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/09/2024	24/09/2024	Act. ROAD/8209646
50167905	1no pothole (RD: CW Pothole)	At the entrance to no54-60	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/10/2024	14/10/2024	Act. ROAD/8209717
50168099	Cw x1 pothole Road: Defective / Damaged (Enquiry 1844312) (RD: CW Pothole)	Outside of 53	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/10/2024	16/10/2024	Act. ROAD/8209731
50169308	3 pot holes (RD: CW Pothole)	At bus stop opposite nairns biscuit factory	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/11/2024	08/11/2024	Act. ROAD/8209812
50171138	2 no potholes (RD: CW Pothole)	At junction with Peffermill road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/12/2024	09/12/2024	Act. ROAD/8209934
50172069	1 no pothole (RD: CW Pothole)	At kings Haugh bustop on CW	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/01/2025	06/01/2025	Act. ROAD/8210011

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 15 - Cameron Terrace to King's Haugh	Feature Type: Road Asset		Area: South East Locality		
50172545	2no potholes (RD: CW Pothole)	At the entrance to no54-60	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/01/2025	10/01/2025	Act. ROAD/8210048
50172639	Bus stop road markings need refreshed (RD: Markings Refresh)	Outside Prestonfield primary school	RD: Cat 4 - Programmed	No code allocated	13/01/2025		
50172640	1no missing section of bars in railing (RD: Railing Damage/Missing/New)	Outside Prestonfield primary school	RD: Cat 4 - Programmed	Job Annulled	13/01/2025	13/01/2025	Act.
50172646	1no missing section of bars in railing (RD: Railing Damage/Missing/New)	Outside Prestonfield primary school	RD: Cat 3 - 60 Day	Job Complete	13/01/2025	13/02/2025	Act. ROAD/8210058
50172666	1no Cw pothole at manhole (RD: CW Pothole)	At junction with Prestonfield avenue	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/01/2025	14/01/2025	Act. ROAD/821006C
50172669	1no FW pothole (RD: FW HRA Pothole)	Opposite nairns oatcakes	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/01/2025	14/01/2025	Act. ROAD/821006C
50172682	2no pole stumps on fw need cut away and made safe with hra (TS: Sign Pole Loose)	Opposite Cameron house avenue	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/01/2025	18/01/2025	Act. ROAD/8210062
50173787	3 no potholes (RD: CW Pothole)	Outside no 66 before and after east bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/01/2025	30/01/2025	Act. ROAD/8210142
50174801	No 3 potholes (RD: CW Pothole)	At junction with peffermill road 54-60	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	11/02/2025	12/02/2025	Act. ROAD/8210222
50174886	3 potholes (RD: CW Pothole)	At entrance to 54-60	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/02/2025	12/02/2025	Act. ROAD/8210231
50178755	1 no pothole (RD: CW Pothole)	5 m east of lamppost pdr32	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/04/2025	23/04/2025	Act. ROAD/8210524
50178756	2 no potholes (RD: CW Pothole)	Opposite lamppost pdr 27	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/04/2025	23/04/2025	Act. ROAD/8210524
50179369	No 2 potholes (RD: CW Pothole)	Near lamppost no 22	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/05/2025	01/05/2025	Act. ROAD/8210562
50183300	No 2 potholes (RD: CW Pothole)	At kings haugh bustop heading east just before opening to peffermill industrial estate	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/08/2025	04/08/2025	Act. ROAD/8210817
50184031	No 1 pothole (RD: CW Pothole)	Middle of the road opposite entrance to 60 Peffermill Road flats.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/08/2025	26/08/2025	Act. ROAD/821086C
50186695	No 1 pothole (RD: CW Pothole)	At kings haugh bustop just west of lamppost PDR34 on CW	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/11/2025	11/11/2025	Act. ROAD/8211031
50187094	3no potholes (RD: CW Pothole)	Opposite Nairns Oatcakes	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	18/11/2025	18/11/2025	Act. ROAD/8211058
50187773	2 no potholes (RD: CW Pothole)	At Morgan playing fields bustop near entrance to Cameron park nursing home	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/12/2025	04/12/2025	Act. ROAD/821111C
50187776	No 1 pothole (RD: CW Pothole)	At kings haugh bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/12/2025	04/12/2025	Act. ROAD/821111C
50187997	No 1 pothole (RD: CW Pothole)	.at kings haugh bustop heading east	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/12/2025	04/12/2025	Act. ROAD/8211126

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 15 - Cameron Terrace to King's Haugh		Feature Type: Road Asset		Area: South East Locality	
50187998	No 2 potholes (RD: CW Pothole)	10 metres east of Morgan playing fields bustop near Cameron park nursing home	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/12/2025	04/12/2025	Act. ROAD/8211126
50188339	No 1 pothole (RD: CW Pothole)	Near lampost PDR34 on CW near bustop heading east	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/12/2025	12/12/2025	Act. ROAD/8211154
50189458	No3 potholes (RD: CW Pothole)	Next to Morgan playing field bustop heading east from Cameron toll shopping centre	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/01/2026	13/01/2026	Act. ROAD/8211246
50189459	No 1 pothole (RD: CW Pothole)	Just before the morgan playing fields bustop heading east	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/01/2026	13/01/2026	Act. ROAD/8211246
50189463	1no Cw pothole (RD: CW Pothole)	Outside Prestonfield primary school	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/01/2026	13/01/2026	Act. ROAD/8211246
50189466	3no Cw potholes (RD: CW Pothole)	At bus stop west of Cameron park nursing home	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/01/2026	13/01/2026	Act. ROAD/8211246
50189468	1no sunken gully (RD: Gully Damaged/Sunken)	Next to vehicle entrance into Nairns oatcakes	RD: Cat 4 - Programmed	No code allocated	12/01/2026		
50189470	1no Cw pothole (RD: CW Pothole)	At bus stop opposite Nairns oatcakes	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/01/2026	13/01/2026	Act. ROAD/8211246
50189476	1no Cw pothole (RD: CW Pothole)	Opposite Lp no21	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/01/2026	13/01/2026	Act. ROAD/8211247
50189479	2no area needs ramped at box (RD: FW HRA Pothole)	Next to junction with Prestonfield avenue	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/01/2026	13/01/2026	Act. ROAD/8211247
50190497	No 2 potholes (RD: CW Pothole)	Outside no 66 Peffermill road heading east opposite Cameron park nursing home	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/01/2026	29/01/2026	Act. ROAD/8211328
50191656	No 2 potholes (RD: CW Pothole)	Opposite no 68 heading east just past bustop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/02/2026	13/02/2026	Act. ROAD/8211423
50192674	No 2 potholes (RD: CW Pothole)	Just before Cameron park nursing home heading east from shopping centre	RD: Cat 3 - 60 Day	Job Committed	24/02/2026	19/05/2026	Est. ROAD/8211511
Asset: 2.00		Asset - Locn.: Ward 17 - King's Haugh to Duddingston Road West		Feature Type: Road Asset		Area: North East Locality	
50106269	CW cracked - broken (RD: CW Cracked/Broken)	O/S lamppost PDR 60 at pedestrian crossing	RD: Cat 4 - Programmed	No code allocated	15/02/2022	15/02/2023	Est.
50125613	1 number pothole (RD: CW Pothole)	Opposite Peffermill park	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/01/2023	11/01/2023	Act. ROAD/8207042
50125615	1 number pothole (RD: CW Pothole)	Opposite Peffermill park	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/01/2023	15/01/2023	Act. ROAD/8207042
50125617	1 number pothole (RD: CW Pothole)	Outside number 168	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/01/2023	15/01/2023	Act. ROAD/8207042
50126013	Cw pothole marked on site Road: Defective / Damaged (Enquiry 1486786) (RD: CW Pothole)	Peffermill Road at Craigmillar castle Gardens bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/01/2023	15/01/2023	Act. ROAD/8207071
50126884	7 number potholes (RD: CW Pothole)	Opposite junction of Craigmillar Castle Gardens	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/01/2023	08/02/2023	Act. ROAD/8207128

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 2.00	Asset - Locn.: Ward 17 - King's Haugh to Duddingston Road West		Feature Type: Road Asset		Area: North East Locality	
50126890	8 number potholes (RD: CW Pothole)	Heading to Niddrie Mains Road between Lampost number PDR40 and PDR42	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/01/2023	08/02/2023	Act. ROAD/8207129
50130091	Cw pothole x3 Road: Defective / Damaged (Enquiry 1514031) (RD: CW Pothole)	At traffic island	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2023	03/03/2023	Act. ROAD/8207326
50130582	1 cw pothole (RD: CW Pothole)	At bus stop near Ip45	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/02/2023	03/03/2023	Act. ROAD/8207353
50130740	Cw x1 pothole Road: Defective / Damaged (Enquiry 1515501) (RD: CW Pothole)	Bus stop before the railway bridge heading to Cameron Toll	RD: Cat 3 - 60 Day	Job Annulled	28/02/2023	28/02/2023	Act. ROAD/8207362
50131103	6 carriageway potholes (RD: CW Pothole)	From lamppost 42 to opposite 168	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/03/2023	08/03/2023	Act. ROAD/8207382
50131106	x5 kerbs need raised slightly and tar work re done around box to cover exposed edge (RD: FW HRA Depression/Sunken)	Outside dentist at crossing point	RD: Cat 4 - Programmed	No code allocated	05/03/2023	05/03/2024	Est.
50131108	Approx .5x3m patch (RD: CW Cracked/Broken)	Junction with Craigmillar castle gardens	RD: Cat 4 - Programmed	Job Annulled	05/03/2023	05/03/2023	Act.
50131110	6 carriageway potholes (RD: CW Pothole)	Opposite lamppost 42	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/03/2023	08/03/2023	Act. ROAD/8207382
50131111	1 carriageway pothole (RD: CW Pothole)	Opposite lamppost 37	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/03/2023	07/03/2023	Act. ROAD/8207382
50133816	Permanent patch approx 7m x 1.5m (RO: Permanent Patching)	Outside number 186	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207543
50133817	Permanent patch approx 1m x1m (RO: Permanent Patching)	Outside number 182	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207543
50133819	4 number potholes (RD: CW Pothole)	At junction of Craigmillar Castle Gardens	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/04/2023	07/04/2023	Act. ROAD/8207539
50133821	Permanent patch approx 9m x1m (RO: Permanent Patching)	At junction of Craigmillar Castle Gardens	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207543
50133822	Permanent patch approx 3m x1m (RO: Permanent Patching)	At junction of Craigmillar Castle Gardens	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207543
50133824	Permanent patch approx 1m x1m (RO: Permanent Patching)	At Lampost number PDR45	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207544
50133825	Permanent patch approx 1m x1m (RO: Permanent Patching)	At Lampost number PDR45	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207544
50133828	Permanent patch approx 1m x1m (RO: Permanent Patching)	Outside number 168	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207544
50133830	Permanent patch approx 2m x1m (RO: Permanent Patching)	Outside number 168	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207544
50133839	Permanent patch approx 1m x 1m (RO: Permanent Patching)	Outside number 166	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207544
50133840	Permanent patch approx 6m x 1.5m (RO: Permanent Patching)	Opposite Lampost number PDR42	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207544
50133841	Permanent patch approx 1.5m x 1.5m (RO: Permanent Patching)	Opposite Lampost number PDR42	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207544

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 2.00		Asset - Locn.: Ward 17 - King's Haugh to Duddingston Road West	Feature Type: Road Asset		Area: North East Locality		
50133845	Permanent patch approx 4m x 1.5 (RO: Permanent Patching)	At Lampost number PDR38A	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207544
50133847	Permanent patch approx 2m x 1.5 (RO: Permanent Patching)	At Lampost number PDR38A	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207544
50133855	Permanent patch approx 1m x 1m (RO: Permanent Patching)	Opposite Lampost number PDR37	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207544
50133858	Permanent patch approx 1m x 1m (RO: Permanent Patching)	Opposite Lampost number PDR37	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133867	Permanent patch approx 3m x 1m (RO: Permanent Patching)	Opposite Lampost number PDR37	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133868	Permanent patch approx 1m x 1m (RO: Permanent Patching)	Opposite Lampost number PDR37	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133876	Permanent patch approx (RO: Permanent Patching)	At Lampost number PDR37	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133877	Permanent patch approx 5m x 1m (RO: Permanent Patching)	At Lampost number PDR40	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133879	Permanent patch approx 1.5m x 1m (RO: Permanent Patching)	Between Lampost PDR40 and ODR42	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133880	Permanent patch approx 3m x 1m (RO: Permanent Patching)	Between Lampost number PDR40 and PDR42	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133882	Permanent patch approx 1m x 1m (RO: Permanent Patching)	Between Lampost number PDR40 and PDR42	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133884	Permanent patch approx 2m x 1m (RO: Permanent Patching)	Between Lampost number PDR40 and PDR42	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133885	Permanent patch approx 7m x 1.5 (RO: Permanent Patching)	Between Lampost number PDR40 and PDR42	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133886	Permanent patch approx 1m x 1m (RO: Permanent Patching)	Between Lampost number PDR40 and PDR42	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133887	Permanent patch approx 2m x 1m (RO: Permanent Patching)	Between Lampost number PDR40 and PDR42	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133888	Permanent patch approx 1m x 1m (RO: Permanent Patching)	Between Lampost number PDR40 and PDR42	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133889	Permanent patch approx 3m x 1m (RO: Permanent Patching)	At Lampost number PDR42	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133890	Permanent patch approx 4m x 1m (RO: Permanent Patching)	At Lampost number PDR42	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133891	Permanent patch approx 7m x 1m (RO: Permanent Patching)	At Lampost number PDR42	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133892	Permanent patch approx 4m x 1m (RO: Permanent Patching)	At Lampost number PDR42	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133893	Permanent patch approx 2.5m x 2.5m (RO: Permanent Patching)	At Lampost number PDR47	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207545
50133894	Permanent patch approx 2m x 1m (RO: Permanent Patching)	At Lampost number PDR47	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207547
50133895	Permanent patch approx 1m x 1m (RO: Permanent Patching)	At Lampost number PDR47	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207547

Site History Report

Effective: 01/01/2023 to 27/02/2026

Service: Roads General

Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 2.00		Asset - Locn.: Ward 17 - King's Haugh to Duddingston Road West		Feature Type: Road Asset		Area: North East Locality	
50133896	Permanent patch approx 3m x 1m (RO: Permanent Patching)	At Lampost number PDR47 and turning into Craigmillar Castle Gardens	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207547
50133897	Permanent patch approx (RO: Permanent Patching)	At Lampost number PDR47	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207547
50133898	Permanent patch approx 10m x 1.5 (RO: Permanent Patching)	At Lampost number PDR47	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207547
50133899	Permanent patch approx 8m x 1.5 (RO: Permanent Patching)	At Lampost number PDR47	RO: Programmed Works	RD: Made Safe Job Complete	06/04/2023	31/05/2023	Act. ROAD/8207547
50133900	1 number pothole (RD: CW Pothole)	At Lampost number PDR47	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/04/2023	07/04/2023	Act. ROAD/8207543
50134098	Cw x1 pothole Road: Defective / Damaged (Enquiry 1534749) (RD: CW Pothole)	Just at the junction with Kings Haugh industrial estate	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/04/2023	13/04/2023	Act. ROAD/8207565
50135084	1 carriageway pothole (RD: CW Pothole)	Outside 188	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/04/2023	27/04/2023	Act. ROAD/8207641
50135142	1 number pothole at bus stop (RD: CW Pothole)	Just passed Craigmillar Castle Gardens	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/04/2023	28/04/2023	Act. ROAD/8207646
50136346	1no pothole (RD: CW Pothole)	Opposite Ip PDR51	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/05/2023	19/05/2023	Act. ROAD/8207734
50142949	1no pothole (RD: CW Pothole)	At the bus stop at Peffermill Court	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/09/2023	22/09/2023	Act. ROAD/8208089
50143783	1 number pothole at bus stop (RD: CW Pothole)	Just passed Craigmillar Castle Gardens	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/10/2023	10/10/2023	Act. ROAD/8208145
50144720	1 number pothole in bus stop (RD: CW Pothole)	At bus stop just passed Craigmillar Castle Gardens	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/10/2023	31/10/2023	Act. ROAD/8208213
50150539	Damaged box lid (RU: Utility Apparatus)	Peffermill road at junction Cameron house avenue	RD: Cat 3 - 60 Day	Job Complete	18/01/2024	08/03/2024	Act. ROAD/8208567
50153558	1 number pothole on pedestrian crossing (RD: CW Pothole)	Just before left turn to Duddingston Road West	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	21/02/2024	22/02/2024	Act. ROAD/8208783
50155406	1 number pothole at gully (RD: CW Pothole)	At Lampost number PDR59	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/03/2024	02/04/2024	Act. ROAD/8208912
50172525	1no pothole (RD: CW Pothole)	On the pedestrian crossing outside no200	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/01/2025	10/01/2025	Act. ROAD/8210047
50172674	Refresh arrows and 20 mph roundels road markings (RD: Markings Refresh)	On approach to traffic lights opposite Bristo church	RD: Cat 4 - Programmed	Job Complete	13/01/2025	18/01/2025	Act. ROAD/8210085
50173673	1 number pothole on pedestrian crossing at traffic lights (RD: CW Pothole)	At junction	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	28/01/2025	28/01/2025	Act. ROAD/8210133
50173677	Renew missing weebol base and grano infill (RD: Weebol Damage/Missing/New)	At junction of Craigmillar Castle Avenue	RD: Cat 3 - 60 Day	Job Complete	28/01/2025	11/02/2025	Act. ROAD/8210134
50175130	No 2 pothole (RD: CW Pothole)	At crossing out side craigmillar dentist	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/02/2025	16/02/2025	Act. ROAD/8210253
50175131	3 no potholes (RD: CW Pothole)	At kings haugh bustop opposite biscuit factory	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/02/2025	16/02/2025	Act. ROAD/8210253

Site History Report

Effective: 01/01/2023 to 27/02/2026
Service: Roads General
Site: Peffermill Road (7902091)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 2.00		Asset - Locn.: Ward 17 - King's Haugh to Duddingston Road West		Feature Type: Road Asset		Area: North East Locality	
50183242	Renew damaged Weebol (RD: Bollard Damage/Missing/New)	Opposite number 200	RD: Cat 3 - 60 Day	Job Complete	31/07/2025	12/08/2025	Act. ROAD/8210814
50184999	Please replace 1no missing weebol (RD: Weebol Damage/Missing/New)	At the crossroads at Niddrie	RD: Cat 2 - 5 Day	Job Complete	25/09/2025	01/10/2025	Act. ROAD/8210925
50187779	3 no potholes (RD: CW Pothole)	At junction of duddingston road west and pieffermill road and at crossing point	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/12/2025	02/12/2025	Act. ROAD/821111C
50189471	1no Cw pothole (RD: CW Pothole)	Between studs At pedestrian crossing outside Flat no180	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	12/01/2026	13/01/2026	Act. ROAD/8211247
50189474	1no area needs ramped at double Bt box (RD: FW HRA Pothole)	At junction with craigmillar castle road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/01/2026	13/01/2026	Act. ROAD/8211247
50192679	No 1 pothole (RD: CW Pothole)	No 1 pothole at crossing point at lights heading east oppisite dentist	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/02/2026	04/03/2026	Act. ROAD/8211511
Asset: 3.00		Asset - Locn.: Ward 15 - Branch south then south-west at No.54		Feature Type: Road Asset		Area: South East Locality	
50126020	Cw pothole marked on site Road: Defective / Damaged (Enquiry 1488367) (RD: CW Pothole)	Peffermill Road No 58 at junction.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/01/2023	15/01/2023	Act. ROAD/8207072
50143946	Cw x3 potholes Road: Defective / Damaged (Enquiry 1627387) (RD: CW Pothole)	Opposite new development	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/10/2023	13/10/2023	Act. ROAD/820816C
50146641	Cw x1 pothole Road: Defective / Damaged (Enquiry 1650687) (RD: CW Pothole)	At the entrance to new development car park	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/11/2023	03/12/2023	Act. ROAD/8208318
50189477	Give way road markings need refreshed (RD: Markings Refresh)	At junction with peffermill road	RD: Cat 4 - Programmed	No code allocated	12/01/2026		