

Site History Report

Effective: 29/05/2023 to 05/03/2026  
Service: Roads General  
Site: Westbank Street (7902464)

Asset Number: 1.00 to 1.00  
Display Action Officer: No

Site: Westbank Street (7902464)      Locality: Portobello West, Edinburgh, City of Edinburgh      Area: North East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	North East Locality
Batch:	41223392 - Inspection Batch			Route:	NE_CF2_PortobelloWest1		Date:	18/03/2025
42179120	Footway cracked- broken approx 25m x 1.2m	18/03/2025	From opp Westbank Place to Portobello High St	RD: FW HRA Cracked/Broken	Internal		No Action Required	
Batch:	41185507 - Inspection Batch			Route:	NE_CF2_PortobelloWest1		Date:	10/03/2024
42150898	Footway cracked- broken approx 25m x 1.2m	10/03/2024	From opp Westbank Place to Portobello High St	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42150901		10/03/2024		RD: CW Cracked/Broken	Internal		Uncommitted	50131058

Customer Services

Enquiry No.: 1789276      Logged by: Verint CRM Connector      on: 28/06/2024 09:22  
Service: Roads General      Subject: Trees & Foliage: Defect      Classification: Request for service  
Desc.: Problem: Obscuring sight line.  
Location:Verge / Grass area .  
Type:Foliage / Bush  
Location: There are trees overhanging from the street/garden across the rd. It is so overgrown it obstructs sunlight and completely blocks the view from the properties at Westbank Street.  
The properties are small as it is, without getting the sun it becomes rather depressing.