

# Site History Report

Effective: 06/03/2025 to 06/03/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Scotstoun Avenue (7900293)

Site: Scotstoun Avenue (7900293)

Locality: South Queensferry, Edinburgh, City of Edinburgh

Area: North West Locality

## Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Whole Street			<b>Feature Type:</b> Road Asset			<b>Area:</b> North West Locality	
<b>Batch:</b> 41254552 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 21/02/2026
42200164	Pothole	21/02/2026	As you turn onto scotstoun avenue	RD: CW Pothole	Internal		Committed	50192493
<b>Batch:</b> 41253551 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 14/02/2026
42199513	Potholes	14/02/2026	At bus stops	RD: CW Pothole	Internal		Committed	50191920
<b>Batch:</b> 41253549 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 14/02/2026
42199511	Pothole	14/02/2026	At junction with atheling grove	RD: CW Pothole	Internal		Committed	50191918
<b>Batch:</b> 41253547 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 14/02/2026
42199509	Pothole	14/02/2026	At no17	RD: CW Pothole	Internal		Committed	50191916
<b>Batch:</b> 41253546 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 14/02/2026
42199508	Pothole	14/02/2026	On bend next to gully	RD: CW Pothole	Internal		Committed	50191915
<b>Batch:</b> 41253545 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 14/02/2026
42199507	Potholes	14/02/2026	On the bend to just past scotstoun green junction	RD: CW Pothole	Internal		Committed	50191914
<b>Batch:</b> 41253544 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 14/02/2026
42199506	Pothole	14/02/2026	Just before the junction	RD: CW Pothole	Internal		Committed	50191913
<b>Batch:</b> 41251281 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 31/01/2026
42198127	Potholes	31/01/2026	Before and after bend	RD: CW Pothole	Internal		Committed	50190819
<b>Batch:</b> 41250556 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 27/01/2026
42197649	Flooding gully blocked	27/01/2026	Just before junction of Kirk Liston road	Gully: Blocked / Flooding	Internal		Committed	50190475
<b>Batch:</b> 41250554 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 27/01/2026
42197647	Gully loose rocking	27/01/2026	At the bus stop	RD: Gully Damaged/Sunken	Internal		Committed	50190473
<b>Batch:</b> 41249852 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 24/01/2026
42197423	Cracked broke surface 2x2m patch	24/01/2026	At bus stop heading west	RD: CW Cracked/Broken	Internal		Uncommitted	50190267
<b>Batch:</b> 41249850 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 24/01/2026
42197421	Pothole	24/01/2026	At the junction	RD: CW Pothole	Internal		Committed	50190265
<b>Batch:</b> 41249849 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 24/01/2026
42197420	Pothole	24/01/2026	Just before bend	RD: CW Pothole	Internal		Committed	50190264
<b>Batch:</b> 41249552 - Inspection Batch				<b>Route:</b> NW_CW1_West1				<b>Date:</b> 22/01/2026
	No actionable defects found							
<b>Batch:</b> 41248802 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 17/01/2026
42196778	Potholes	17/01/2026	As you turn onto scotstoun avenue to the corner	RD: CW Pothole	Internal		Committed	50189783
<b>Batch:</b> 41247425 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 09/01/2026
42196277	Pothole	09/01/2026	On bend	RD: CW Pothole	Internal		Committed	50189395
<b>Batch:</b> 41247357 - Inspection Batch				<b>Route:</b> Ad hoc Route				<b>Date:</b> 08/01/2026
42196257	Pothole	08/01/2026	Outside 120	RD: CW Pothole	Internal		Committed	50189376

# Site History Report

Effective: 06/03/2025 to 06/03/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Scotstoun Avenue (7900293)

## Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	1.00	<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> North West Locality		
<b>Batch:</b> 41246280 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 24/12/2025		
42195760	2 potholes	24/12/2025	At the bus stops	RD: CW Pothole	Internal		Committed	50188916
<b>Batch:</b> 41244457 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 12/12/2025		
42195164	Potholes	12/12/2025	At bend	RD: CW Pothole	Internal		Committed	50188433
<b>Batch:</b> 41243525 - Inspection Batch				<b>Route:</b> NW_CW1_West1		<b>Date:</b> 02/12/2025		
No actionable defects found								
<b>Batch:</b> 41243150 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 28/11/2025		
42194274	Cracked broken surface	28/11/2025	on Scotstoun Avenue opposite 120 Moubray Grove.	RD: CW Cracked/Broken	Internal		Uncommitted	50187751
<b>Batch:</b> 41243148 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 28/11/2025		
42194272	Pothole	28/11/2025	At bus stop east bound	RD: CW Pothole	Internal		Committed	50187749
<b>Batch:</b> 41241296 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 12/11/2025		
42193111	Refresh all markings	12/11/2025	SCOTSTOUN AVENUE	RD: Markings Refresh	Internal		Uncommitted	50186802
<b>Batch:</b> 41239468 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 22/10/2025		
42191634	1no pothole	22/10/2025	At the junction with Kirkliston Road	RD: CW Pothole	Internal		Committed	50185915
<b>Batch:</b> 41236353 - Inspection Batch				<b>Route:</b> NW_CW1_West1		<b>Date:</b> 10/09/2025		
No actionable defects found								
<b>Batch:</b> 41233043 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 16/07/2025		
42187117	Pothole on carriageway	16/07/2025	Junction Scotstoun Green	RD: CW Pothole	Internal		Committed	50182720
<b>Batch:</b> 41233041 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 16/07/2025		
42187113	Pothole on carriageway	16/07/2025	Lpost 02	RD: CW Pothole	Internal		Committed	50182718
<b>Batch:</b> 41230642 - Inspection Batch				<b>Route:</b> NW_CW1_West1		<b>Date:</b> 11/06/2025		
No actionable defects found								
<b>Batch:</b> 41229279 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 27/05/2025		
42184348	Permanent repair required	27/05/2025	From Scotstoun Avenue remote footpath running along Atheling Grove	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50180428
<b>Batch:</b> 41229109 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 26/05/2025		
42184201	Permanent repair required	26/05/2025	Junction Kirkliston Road to lpost 06	RD: CW Rutting	Internal		Uncommitted	50180337
<b>Batch:</b> 41228599 - Inspection Batch				<b>Route:</b> NW_CF1_ScotstounAvenue1		<b>Date:</b> 19/05/2025		
42183770	Reset sunken gully frame	19/05/2025	At Sommerville gardens bus stop to city	RD: Gully Damaged/Sunken	Internal		Uncommitted	50180065
42183773	Patch required	19/05/2025	Outside 2	RD: CW Cracked/Broken	Internal		Uncommitted	50138834
Approx 9m x 1.5m								
42183756	Patching required	19/05/2025	At lp28	RD: CW Cracked/Broken	Internal		Uncommitted	50180061
Approx 4m x 1m & 1.5m x 1.5m								
42183774	Patch required	19/05/2025	Opposite junction with Scotstoun green	RD: CW Cracked/Broken	Internal		Uncommitted	50160903
Approx 9m x 3m								
42183753	Road: Defective / Damaged (Enquiry 1545069)permanent repair required to carriageway	19/05/2025	Between lpost 23-24	RD: CW Pothole	Internal		Uncommitted	50135440
42183776	Permanent repair required	19/05/2025	Junction Kirkliston Road	RD: CW Rutting	Internal		Uncommitted	50179589

# Site History Report

Effective: 06/03/2025 to 06/03/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Scotstoun Avenue (7900293)

## Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
<b>Asset:</b>	1.00	<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> North West Locality		
<b>Batch:</b> 41228599 - Inspection Batch				<b>Route:</b> NW_CF1_ScotstounAvenue1		<b>Date:</b> 19/05/2025		
42183778	Patch required Approx 2m x 1m	19/05/2025	Approx 20m from kirkliston road	RD: CW Cracked/Broken	Internal		Uncommitted	50180068
42183750	Permanent repair required	19/05/2025	Junction Atheling Court	RD: CW Rutting	Internal		Uncommitted	50177976
42183775	Patching required Approx 4m x 2m & 1.5m x 1m	19/05/2025	At crossing point Approx 10m from kirkliston road	RD: CW Cracked/Broken	Internal		Uncommitted	50160902
<b>Batch:</b> 41227609 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 06/05/2025		
42182976	Permanent repair required	06/05/2025	Junction Kirkliston Road	RD: CW Rutting	Internal		No Action Required	
<b>Batch:</b> 41227608 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 06/05/2025		
42182975	Pothole on carriageway	06/05/2025	Junction Scoutstoun Green	RD: CW Pothole	Internal		Committed	50179588
<b>Batch:</b> 41226537 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 23/04/2025		
42181843	Noisy carriageway manhole	23/04/2025	Lpost 25	RU: Utility Apparatus	Internal		Uncommitted	50178881
<b>Batch:</b> 41224812 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 01/04/2025		
42180395	Permanent repair required	01/04/2025	Junction Atheling Court	RD: CW Rutting	Internal		No Action Required	
<b>Batch:</b> 41224811 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 01/04/2025		
42180394	Pothole on carriageway	01/04/2025	Lpost 23-24	RD: CW Pothole	Internal		Committed	50177975
<b>Batch:</b> 41224806 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 01/04/2025		
42180392	Pothole on carriageway	01/04/2025	Lpost 03	RD: CW Pothole	Internal		Committed	50177974
<b>Batch:</b> 41224804 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 01/04/2025		
42180390	Pothole on carriageway	01/04/2025	Junction Kirkliston Road	RD: CW Pothole	Internal		Committed	50177973
<b>Batch:</b> 41221985 - Inspection Batch				<b>Route:</b> NW_CW1_West1		<b>Date:</b> 10/03/2025		
No actionable defects found								
<b>Batch:</b> 41221625 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 06/03/2025		
42177894	Pothole on carriageway	06/03/2025	Junction Kirkliston Road	RD: CW Pothole	Internal		Committed	50176450
<b>Batch:</b> 41221624 - Inspection Batch				<b>Route:</b> Ad hoc Route		<b>Date:</b> 06/03/2025		
42177893	Pothole on carriageway	06/03/2025	Lpost 05,04	RD: CW Pothole	Internal		Committed	50176449

## Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
<b>Asset:</b>	1.00	<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> North West Locality	
50048863	Refresh white centre lines and junction markings. Road: Defective / Damaged (Enquiry 908900) (RD: Markings Refresh)	Entire length of road from Kirkliston Road to Lp SFD27	RD: Cat 4 - Programmed	Job Complete	03/01/2020	22/10/2025	Act. ROAD/821056C
50176449	Pothole on carriageway (RD: CW Pothole)	Lpost 05,04	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/03/2025	06/03/2025	Act. ROAD/8210362
50176450	Pothole on carriageway (RD: CW Pothole)	Junction Kirkliston Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/03/2025	06/03/2025	Act. ROAD/8210362
50177973	Pothole on carriageway (RD: CW Pothole)	Junction Kirkliston Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/04/2025	02/04/2025	Act. ROAD/8210471

# Site History Report

Effective: 06/03/2025 to 06/03/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Scotstoun Avenue (7900293)

## Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> North West Locality	
50177974	Pothole on carriageway (RD: CW Lpost 03 Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/04/2025	02/04/2025	Act. ROAD/8210471
50177975	Pothole on carriageway (RD: CW Lpost 23-24 Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/04/2025	02/04/2025	Act. ROAD/8210471
50179588	Pothole on carriageway (RD: CW Junction Scoutstoun Green Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/05/2025	08/05/2025	Act. ROAD/821058C
50182718	Pothole on carriageway (RD: CW Lpost 02 Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/07/2025	17/07/2025	Act. ROAD/821078C
50182720	Pothole on carriageway (RD: CW Junction Scotstoun Green Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/07/2025	17/07/2025	Act. ROAD/821078C
50185915	1no pothole (RD: CW Pothole)	At the junction with Kirkliston Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/10/2025	23/10/2025	Act. ROAD/821098E
50187749	Pothole (RD: CW Pothole)	At bus stop east bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/11/2025	01/12/2025	Act. ROAD/821110E
50188433	Potholes (RD: CW Pothole)	At bend	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/12/2025	15/12/2025	Act. ROAD/8211161
50188916	2 potholes (RD: CW Pothole)	At the bus stops	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/12/2025	29/12/2025	Act. ROAD/821120C
50189376	Pothole (RD: CW Pothole)	Outside 120	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/01/2026	09/01/2026	Act. ROAD/821123E
50189395	Pothole (RD: CW Pothole)	On bend	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/01/2026	13/01/2026	Act. ROAD/821124C
50189783	Potholes (RD: CW Pothole)	As you turn onto scotstoun avenue to the corner	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/01/2026	19/01/2026	Act. ROAD/8211271
50190264	Pothole (RD: CW Pothole)	Just before bend	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/01/2026	26/01/2026	Act. ROAD/821130E
50190265	Pothole (RD: CW Pothole)	At the junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/01/2026	26/01/2026	Act. ROAD/821130E
50190473	Gully loose rocking (RD: Gully Damaged/Sunken)	At the bus stop	RD: Cat 3 - 60 Day	Job Complete	27/01/2026	25/02/2026	Act. ROAD/8211327
50190475	Flooding gully blocked (Gully: Blocked / Flooding)	Just before junction of Kirk Liston road	RG: Gully - High Priority	Job Committed	27/01/2026	24/02/2026	Est. RDGC14/82007
50190819	Potholes (RD: CW Pothole)	Before and after bend	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/01/2026	04/02/2026	Act. ROAD/821135E
50191913	Pothole (RD: CW Pothole)	Just before the junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2026	22/02/2026	Act. ROAD/8211444
50191914	Potholes (RD: CW Pothole)	On the bend to just past scotstoun green junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2026	22/02/2026	Act. ROAD/8211444
50191915	Pothole (RD: CW Pothole)	On bend next to gully	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/02/2026	16/02/2026	Act. ROAD/8211444
50191916	Pothole (RD: CW Pothole)	At no17	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2026	22/02/2026	Act. ROAD/8211444
50191918	Pothole (RD: CW Pothole)	At junction with atheling grove	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2026	22/02/2026	Act. ROAD/821144E
50191920	Potholes (RD: CW Pothole)	At bus stops	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2026	22/02/2026	Act. ROAD/821144E
50192493	Pothole (RD: CW Pothole)	As you turn onto scotstoun avenue	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	21/02/2026	22/02/2026	Act. ROAD/8211497

# Site History Report

---

**Effective:** 06/03/2025 to 06/03/2026

**Display Action Officer:** No

**Asset Number:** 1.00 to 9.00

**Site:** Scotstoun Avenue (7900293)

---