

| Admin Unit Name | Raised Date | Reported Completion Date | Trade                      | Description  |
|-----------------|-------------|--------------------------|----------------------------|--|
| 449 GORGIE ROAD | 26/05/2016  | 27/05/2016               | Stairlighting              | 99 - 1D - 449 Gorgie Road - Dangerous hanging covering from light on ground floor - please attend asap.  |
| 449 GORGIE ROAD | 14/12/2016  | 15/12/2016               | Stairlighting              | Please fix timer in stair, more than 50 percent of lights out at night time.   |
| 449 GORGIE ROAD | 28/08/2017  | 31/08/2017               | Slater Works               | tnt called regarding rhones - clean out rhones - tnt advised "strange smell" is also there. please attend.   |
| 449 GORGIE ROAD | 09/11/2018  | 09/11/2018               | TMS owners                 | Supply and fit door intercom - MFA security solutions  |
| 449 GORGIE ROAD | 26/04/2019  | 10/05/2019               | Plastering Work            | Plasterer required to cut out existing debris from cracks and plaster where necessary. Cracks are at the top landing of communal stair.  |
| 449 GORGIE ROAD | 07/05/2019  |                          | Plastering Work            | Gorgie Road - additional works on top landing to repair cracks, only 45 mins on first job  |
| 449 GORGIE ROAD | 14/05/2019  | 01/08/2019               | Slater Works               | Roofer required to check roof for leaks access as leak is shown in tenants bathroom ceiling.   |
| 449 GORGIE ROAD | 17/05/2019  |                          | Slater Works               | Roofer required to check roof for leaks access as leak is shown in tenants bathroom ceiling.   |
| 449 GORGIE ROAD | 13/06/2019  | 14/06/2019               | Slater Works               | Roofer required to check roof for leaks access as leak is shown in tenants bathroom ceiling.   |
| 449 GORGIE ROAD | 26/06/2019  | 26/06/2019               | Scaffolding                | 09 COVER ORDER SUB CONTRACTOR SUPPORT 3079964/3  |
| 449 GORGIE ROAD | 26/06/2019  | 26/06/2019               | Scaffolding                | 09 COVER ORDER SUB CONTRACTOR SUPPORT 3079964/2  |
| 449 GORGIE ROAD | 19/07/2019  | 02/08/2019               | Slater Works               | @ least 2 slates missing above flat 5 bedroom window to front of property  |
| 449 GORGIE ROAD | 26/07/2019  | 29/08/2019               | Plastering Work            | plastering still required for ceiling of top floor in the landing, 449 Gorgie Road, Edinburgh  |
| 449 GORGIE ROAD | 05/08/2019  | 22/08/2019               | Slater Works               | @ least 2 slates missing above flat 5 bedroom window to front of property  |
| 449 GORGIE ROAD | 03/09/2019  | 03/09/2019               | Scaffolding                | 09 COVER ORDER SUB CONTRACTOR SUPPORT 3103756/2  |
| 449 GORGIE ROAD | 03/02/2020  | 13/03/2020               | Jetting                    | please clear out tnts drains as getting sewage smell coming through house from the left hand side.   |
| 449 GORGIE ROAD | 09/03/2020  | 23/03/2020               | Mason Work                 | 09/01 as per Lee Anderson HO - (left gable end and below of the left windowsill) experiencing water  |
| 449 GORGIE ROAD | 09/03/2020  | 23/03/2020               | Scaffolding                | 09/01 as per Lee Anderson HO - (left gable end and below of the left windowsill) experiencing water  |
| 449 GORGIE ROAD | 19/03/2020  | 02/04/2020               | Joinery Work               | 02 - as per h/o Lee Anderson - Repair fault with the main door lock - Yale box lock that is catching   |
| 449 GORGIE ROAD | 20/07/2020  | 20/07/2020               | Central Emergency Services | 02 - Lee Anderson Housing Officer - Secure lock on main stair door - The lock can be forced open by pushing it hard and the residents are having issues with people entering the stair                               |
| 449 GORGIE ROAD | 23/07/2020  | 23/07/2020               | Joinery Work               | 02 - Lee Anderson Housing Officer - Secure lock on main stair door - The lock can be forced open by pushing it hard and the residents are having issues with people entering the stair                               |
| 449 GORGIE ROAD | 04/08/2020  | 04/08/2020               | Joinery Work               | 02 - Lee Anderson Housing Officer - Secure lock on main stair door - The lock can be forced open by pushing it hard and the residents are having issues with people entering the stair                               |
| 449 GORGIE ROAD | 04/08/2020  | 04/08/2020               | Window Repair Works        | 02 - Lee Anderson Housing Officer - Secure lock on main stair door - The lock can be forced open by pushing it hard and the residents are having issues with people entering the stair                               |
| 449 GORGIE ROAD | 05/08/2020  | 05/08/2020               | Door Entry Systems         | 02 - Lee Anderson Housing Officer - Test/repair intercom system as this is not working   |
| 449 GORGIE ROAD | 26/08/2020  | 26/08/2020               | Central Emergency Services | 02 - Lee Anderson Housing Officer - Joiner to replace the Yale lock on main door as key is getting stuck when tenants are putting them in the lock to access the stair   |
| 449 GORGIE ROAD | 26/08/2020  | 26/08/2020               | Joinery Work               | 02 - Lee Anderson Housing Officer - Joiner to replace the Yale lock on main door as key is getting stuck when tenants are putting them in the lock to access the stair   |
| 449 GORGIE ROAD | 26/08/2020  | 06/10/2020               | Slater Works               | 04 - Lee Anderson Housing Officer - FAO Contractor - - @ least 2 slates missing above flat 5 bedroom window to front of property - Meaning more water is getting in and soaking below the window sill in living room |
| 449 GORGIE ROAD | 27/08/2020  | 03/09/2020               | Joinery Work               | Joiner to replace the Yale lock on main door as key is getting stuck when tenants are putting them in the lock to access the stair. Pick up keys and lock from Travis Perkins.                                       |
| 449 GORGIE ROAD | 23/10/2020  | 26/10/2020               | Plumbing Work              | check blockage in outside communal pipe as affecting flatx (private) previously affected flat x (council)  |
| 449 GORGIE ROAD | 08/12/2020  |                          | Slater Works               | please clear out rhones as full of debris and grass, blocked   |
| 449 GORGIE ROAD | 18/02/2021  | 18/02/2021               | Slater Works               | please clear out rhones as full of debris and grass, blocked   |
| 449 GORGIE ROAD | 22/02/2021  | 23/02/2021               | Slater Works               | please clear out rhones as full of debris and grass, blocked. Cherry picker req . ECM06  |
| 449 GORGIE ROAD | 11/12/2021  | 26/01/2022               | Scaffolding                | 04/09 - As per Tracey Lawrie - Defective roof coverings are suspected to the left upper gable wall. flashings and copes should be inspected and repaired as necessary.   |
| 449 GORGIE ROAD | 11/12/2021  | 26/01/2022               | Slater Works               | 04/09 - As per Tracey Lawrie - Defective roof coverings are suspected to the left upper gable wall. flashings and copes should be inspected and repaired as necessary.   |
| 449 GORGIE ROAD | 11/12/2021  |                          | Slater Works               | 04 - As per Tracey Lawrie, roof repair work above 2f1 required as causing dampness inside property   |
| 449 GORGIE ROAD | 04/02/2022  | 28/02/2022               | Mason Work                 | Please inspect roof for leak as going into livingroom window coming from outside FO required.  |
| 449 GORGIE ROAD | 04/02/2022  | 28/02/2022               | Scaffolding                | Please inspect roof for leak as going into livingroom window coming from outside FO required.  |
| 449 GORGIE ROAD | 24/08/2022  | 08/10/2022               | Mason Work                 | leaking coming from roof coming through Livingroom wall. please assess and repair.   |
| 449 GORGIE ROAD | 24/08/2022  | 08/10/2022               | Scaffolding                | leaking coming from roof coming through Livingroom wall. please assess and repair.   |
| 449 GORGIE ROAD | 10/11/2022  | 14/11/2022               | Central Emergency Services | chimney making very loud noise tnt cant even hear tv   |
| 449 GORGIE ROAD | 14/11/2022  | 06/01/2023               | Scaffolding                | 04, as per cath saltire f/o - chimney cowl needs refixed as loose - scaffold will be required  |
| 449 GORGIE ROAD | 14/11/2022  | 06/01/2023               | Slater Works               | 04, as per cath saltire f/o - chimney cowl needs refixed as loose - scaffold will be required  |
| 449 GORGIE ROAD | 30/11/2022  | 06/01/2023               | Slater Works               | please trace and repair leak roof as water ingress in flat in front bedroom  |
| 449 GORGIE ROAD | 16/01/2023  | 17/01/2023               | Joinery Work               | Reporting mechanism in stair window broken on first and 2nd level access as tnt explaining dangerous   |
| 449 GORGIE ROAD | 16/01/2023  | 17/01/2023               | Slater Works               | Confirmed with Tracey Lawrie - Leak still ongoing, Saltire recommend 'strip & re-slate,' Please asses for works.   |
| 449 GORGIE ROAD | 08/02/2023  |                          | Slater Works               | chimney cowl needs refaxed as loose - Please attend asap as been raise before and no follow on been done.  |

| Admin Unit Name | Raised Date | Reported Completion Date | Trade                      | Description   |
|-----------------|-------------|--------------------------|----------------------------|---|
| 449 GORGIE ROAD | 08/08/2023  | 10/08/2023               | Slater Works               | Livingroom outside wall at front(left hand side first window) needing repointed water coming through living room wall   |
| 449 GORGIE ROAD | 25/09/2023  | 06/10/2023               | Slater Works               | Tenant is reporting chimney looking in a very bad condition, can you please assess for repairs and follow-on. (3 Floors Up).  |
| 449 GORGIE ROAD | 30/11/2023  | 30/11/2023               | Slater Works               | please trace and repair leak roof as water ingress in front bedroom   |
| 449 GORGIE ROAD | 15/12/2023  | 16/12/2023               | Central Emergency Services | Please assess and repair roof area as water ingress into tnt's property   |
| 449 GORGIE ROAD | 18/12/2023  | 22/12/2023               | Scaffolding                | 09 - F/O Stuart O'Rourke - FAO Saltire - scaffolding required   |
| 449 GORGIE ROAD | 18/12/2023  | 22/12/2023               | Slater Works               | 04 - f/o Stuart O'Rourke - FAO Saltire - renew slates at front right hand side above bedroom of flat 6  |
| 449 GORGIE ROAD | 23/12/2023  | 23/12/2023               | Central Emergency Services | requesting stair light timings to be altered to come on earlier. currently lights come on at 6/7pm and on until 12pm next day.  |
| 449 GORGIE ROAD | 23/12/2023  | 23/12/2023               | Electrical Work            | requesting stair light timings to be altered to come on earlier. currently lights come on at 6/7pm and on until 12pm next day.  |
| 449 GORGIE ROAD | 22/01/2024  | 29/01/2024               | Slater Works               | please check dn repair faulty chimney as loose due to high winds  |
| 449 GORGIE ROAD | 26/04/2024  |                          | Mason Work                 | assess and repair holes in wall outside Livingroom  |
| 449 GORGIE ROAD | 07/05/2024  |                          | Mason Work                 | assess and repair holes in wall outside bathroom window out the back.   |
| 449 GORGIE ROAD | 28/05/2024  |                          | Slater Works               | Please asses roof space as tnt has started getting dampness and leak in the Livingroom again.   |
| 449 GORGIE ROAD | 31/05/2024  | 31/05/2024               | Central Emergency Services | 02 - 449- top windows unsafe falling to bit please make safe and foolow ladder required up about 8 9 feet - first floor window also cracked please ases and repair                            |
| 449 GORGIE ROAD | 31/05/2024  | 03/06/2024               | Mason Work                 | back steps crumbling away holes in it very dangerous safety hazard  |
| 449 GORGIE ROAD | 24/06/2024  | 25/06/2024               | Slater Works               | 04 pls assess water ingress from roof leak (water gate mentioned by tnt).   |
| 449 GORGIE ROAD | 23/08/2024  | 23/08/2024               | Slater Works               | please trace and repair leaking roof as water ingress into the property at (right handside)please go to the property to see where is coming from exactly) ongoing issues                      |
| 449 GORGIE ROAD | 18/09/2024  | 18/12/2024               | Scaffolding                | repair mortar where missing at living room and bathroom windows   |
| 449 GORGIE ROAD | 05/11/2024  | 18/12/2024               | Slater Works               | PROVIDE PICTURES . Assess water ingress at roof   |
| 449 GORGIE ROAD | 30/12/2024  | 17/01/2025               | Slater Works               | (04) - please assess chimney for repair as wind is rattling fireplace   |
| 449 GORGIE ROAD | 30/12/2024  |                          | Mason Work                 | please assess chimney for repair as wind rattling through fireplace   |
| 449 GORGIE ROAD | 07/01/2025  | 17/01/2025               | Slater Works               | 04-RPRTD BY 449-FAO SALTRIE-ong issue-living room is still same issue-and front bedroom above window is getting leaked into-at window-please investigate-raise on works req-not repaired prev |
| 449 GORGIE ROAD | 29/01/2025  |                          | Slater Works               | tnt reporting leak ongoing from roof- please asses and repair- trace leak- saltire been out and unable to find anything asked for council tradesmen to try-                                   |
| 449 GORGIE ROAD | 05/02/2025  |                          | Slater Works               | Please assess gutters to be cleaned as tnt believes they are blocked at the front of the property.  |
| 449 GORGIE ROAD | 18/11/2025  | 19/11/2025               | Slater Works               | water ingress into front bedroom .  |
| 449 GORGIE ROAD | 07/01/2026  | 08/01/2026               | Scaffolding                | Water ingress from roof into front and back bedroom - Tnt also claiming that the rhones are blocked and causing water ingress at both front and back of flat                                  |
| 449 GORGIE ROAD | 07/01/2026  | 08/01/2026               | Slater Works               | Water ingress from roof into front and back bedroom - Tnt also claiming that the rhones are blocked and causing water ingress at both front and back of flat                                  |
| 449 GORGIE ROAD | 27/01/2026  | 27/01/2026               | Slater Works               | Water ingress from roof into front bedroom - Tnt also claiming that the rhones are blocked and causing water ingress at front of flat   |