

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Site: Frederick Street (7901794)

Locality: New Town, Edinburgh, City of Edinburgh

Area: South East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	South East Locality
Batch:	41254424 - Inspection Batch			Route:	Ad hoc Route		Date:	20/02/2026
42200050	1 number pothole	20/02/2026	Outside number 52	RD: CW Pothole	Internal		Committed	50192389
Batch:	41253209 - Inspection Batch			Route:	SE_FW1_NewTownSouth1		Date:	14/02/2026
42199331	1no sunken electricity utility box on Fw	13/02/2026	Queen street on Fw outside no56	RU: Utility Apparatus	Internal		Uncommitted	50191764
42199342	1no Cw pothole	13/02/2026	At pedestrian crossing at junction with rose street	RD: CW Pothole	Internal		Committed	50191774
42199335	Cw breaking up approx 2m x 1.5m	13/02/2026	At pedestrian crossing between Rose street	RD: CW Cracked/Broken	Internal		Committed	50189774
Batch:	41252541 - Inspection Batch			Route:	Ad hoc Route		Date:	09/02/2026
42198887	2no potholes	09/02/2026	At the bus stop outside House of Souvenirs	RD: CW Pothole	Internal		Committed	50191395
Batch:	41252538 - Inspection Batch			Route:	Ad hoc Route		Date:	09/02/2026
42198885	1no pothole	09/02/2026	Outside no25	RD: CW Pothole	Internal		Committed	50191393
Batch:	41252536 - Inspection Batch			Route:	Ad hoc Route		Date:	09/02/2026
42198884	Cracked and broken asphalt approx 8mx2m	09/02/2026	On the zebra crossing outside Laings	RD: CW Cracked/Broken	Internal		Committed	50191392
Batch:	41252532 - Inspection Batch			Route:	Ad hoc Route		Date:	09/02/2026
42198880	Large depression requires hra overlay	09/02/2026	On the zebra crossing outside Laings	RD: CW Pothole	Internal		Committed	50191389
Batch:	41252528 - Inspection Batch			Route:	Ad hoc Route		Date:	09/02/2026
42198876	1no pothole	09/02/2026	Outside Fat Face	RD: CW Pothole	Internal		Committed	50191386
Batch:	41249204 - Inspection Batch			Route:	Ad hoc Route		Date:	20/01/2026
42197082	1no pothole	20/01/2026	Outside Laings near zebra crossing	RD: CW Pothole	Internal		Committed	50190006
Batch:	41248796 - Inspection Batch			Route:	SE_FW1_NewTownSouth1		Date:	17/01/2026
42196770	2no Cw potholes Make safe	17/01/2026	At pedestrian crossing between Rose street	RD: CW Pothole	Internal		Committed	50189775
42196766	1no broken 900 x 600 pcc slab 1no rocking cut pcc slab	17/01/2026	Outside vacheron constantin	RD: FW Slabs Broken/Missing	Internal		Committed	50189771
42196772	1no Cw pothole	17/01/2026	Opposite Barbour shop	RD: CW Pothole	Internal		Committed	50189777
42196773	1no Cw pothole	17/01/2026	Outside vision express	RD: CW Pothole	Internal		Committed	50189778
42196774	1no Cw pothole	17/01/2026	Outside Fat Face Next to pedestrian crossing at George st junction	RD: CW Pothole	Internal		Committed	50189779
42196769	Cw breaking up approx 2m x 2m	17/01/2026	At pedestrian crossing between Rose street	RD: CW Cracked/Broken	Internal		No Action Required	
Batch:	41248136 - Inspection Batch No actionable defects found			Route:	SE_CW1_Central1		Date:	13/01/2026
Batch:	41245541 - Inspection Batch No actionable defects found			Route:	SE_FW1_NewTownSouth1		Date:	19/12/2025

Site History Report

Effective: 01/02/2023 to 28/02/2026

Service: Roads General

Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41244551 - Inspection Batch				Route: Ad hoc Route		Date: 15/12/2025		
42195209	2no broken 900 x 600 pcc slabs	15/12/2025	Outside size shop	RD: FW Slabs Broken/Missing	Internal		Committed	50188470
Batch: 41242209 - Inspection Batch				Route: SE_FW1_NewTownSouth1		Date: 20/11/2025		
No actionable defects found								
Batch: 41241295 - Inspection Batch				Route: Ad hoc Route		Date: 12/11/2025		
42193110	1no pothole	12/11/2025	At the junction with George Street	RD: CW Pothole	Internal		Committed	50186801
Batch: 41239128 - Inspection Batch				Route: SE_FW1_NewTownSouth1		Date: 18/10/2025		
42191351	Fw Grano broken at box	18/10/2025	Outside laings the jewellers at pedestrian crossing	RD: FW Grano Cracked/Broken	Internal		Committed	50185719
Batch: 41238432 - Inspection Batch				Route: SE_CW1_Central1		Date: 10/10/2025		
No actionable defects found								
Batch: 41236861 - Inspection Batch				Route: SE_FW1_NewTownSouth1		Date: 17/09/2025		
42190057	Granite patch required Approx 1m x1m	17/09/2025	Outside 29	RD: FW Grano Cracked/Broken	Internal		Committed	50184869
42190039	Relay 1 rocking 300 x 300 slab	17/09/2025	Outside the queens arms	RD: FW Slabs Rocking	Internal		Committed	50184857
Batch: 41234792 - Inspection Batch				Route: SE_FW1_NewTownSouth1		Date: 15/08/2025		
42188556	Both sides of junction need existing 8no whin kerbs dropped	15/08/2025	Frederick st junction with hill st	RD: NEW Dropped Kerbs	Internal		No Action Required	
Batch: 41233632 - Inspection Batch				Route: Ad hoc Route		Date: 23/07/2025		
42187589	2no No entry signs have stickers defacing them	23/07/2025	At junction with hill street	TS: Sign Face Vand/ Graf (SSO)	Internal		Committed	50183002
Batch: 41233620 - Inspection Batch				Route: Ad hoc Route		Date: 23/07/2025		
42187537	Broken grano on Fw approx 1m x 0.2	23/07/2025	Frederick street outside Barbour shop	RD: FW Grano Cracked/Broken	Internal		Committed	50182991
Batch: 41232302 - Inspection Batch				Route: SE_CW1_Central1		Date: 07/07/2025		
No actionable defects found								
Batch: 41232125 - Inspection Batch				Route: SE_FW1_NewTownSouth1		Date: 02/07/2025		
42186399	1no open grano joint on fw at manhole	02/07/2025	Outside all saint's shop opposite le creuset shoo	RD: FW Grano Open Joint	Internal		Committed	50182237
Batch: 41231291 - Inspection Batch				Route: Ad hoc Route		Date: 18/06/2025		
42185748	1no pothole	18/06/2025	Outside the Scottish Building Society	RD: CW Pothole	Internal		Committed	50181635
Batch: 41229127 - Inspection Batch				Route: SE_FW1_NewTownSouth1		Date: 26/05/2025		
42184224	Both sides of junction need existing 8no whin kerbs dropped	26/05/2025	Frederick st junction with hill st	RD: NEW Dropped Kerbs	Internal		No Action Required	
42184228	1no rocking 900 x 600 pcc slab	26/05/2025	Outside costcutter shop	RD: FW Slabs Rocking	Internal		Committed	50180349
Batch: 41227025 - Inspection Batch				Route: SE_FW1_NewTownSouth1		Date: 29/04/2025		
42182437	Zebra crossing markings need refreshed	29/04/2025	Pedestrian crossing outside fat face	RD: Markings Refresh	Internal		Committed	50167815
42182431	Both sides of junction need existing 8no whin kerbs dropped	29/04/2025	Frederick st junction with hill st	RD: NEW Dropped Kerbs	Internal		No Action Required	

Site History Report

Effective: 01/02/2023 to 28/02/2026

Service: Roads General

Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41227025 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 29/04/2025		
42182444	1no pole has been removed and needs infilled with grano	29/04/2025	Outside no55	RD: FW Grano Pothole	Internal		Committed	50179246
Batch: 41225170 - Inspection Batch			Route: SE_CW1_Central1			Date: 03/04/2025		
No actionable defects found								
Batch: 41224667 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 01/04/2025		
42180256	2no rocking 900 x 600 pcc slabs	31/03/2025	Outside size shop	RD: FW Slabs Rocking	Internal		Committed	50177887
42180245	Both sides of junction need existing 8no whin kerbs dropped	31/03/2025	Frederick st junction with hill st	RD: NEW Dropped Kerbs	Internal		No Action Required	
42180252	1no Cw pothole	31/03/2025	At pedestrian crossing outside laings the jewellers shop	RD: CW Pothole	Internal		Committed	50177884
42180273	1no broken 900 x 600 pcc slab	31/03/2025	Outside costcutter shop on FW	RD: FW Slabs Broken/Missing	Internal		Committed	50177895
42180254	2no grano potholes	31/03/2025	Outside five guys on fw	RD: FW Grano Pothole	Internal		Committed	50177885
42180247	Zebra crossing markings need refreshed	31/03/2025	Pedestrian crossing outside fat face	RD: Markings Refresh	Internal		No Action Required	
Batch: 41223981 - Inspection Batch			Route: Ad hoc Route			Date: 24/03/2025		
42179571	2no potholes	24/03/2025	Outside Schuh	RD: CW Pothole	Internal		Committed	50177493
Batch: 41222522 - Inspection Batch			Route: Ad hoc Route			Date: 12/03/2025		
42178557	Cracked broken grano at manhole and tactiles	12/03/2025	Opposite fat face shop	RD: FW Grano Cracked/Broken	Internal		Committed	50176876
Batch: 41222228 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 11/03/2025		
42178348	Zebra crossing markings need refreshed	11/03/2025	Pedestrian crossing outside fat face	RD: Markings Refresh	Internal		No Action Required	
42178347	Both sides of junction need existing 8no whin kerbs dropped	11/03/2025	Frederick st junction with hill st	RD: NEW Dropped Kerbs	Internal		No Action Required	
Batch: 41219269 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 17/02/2025		
42176134	Zebra crossing markings need refreshed	17/02/2025	Pedestrian crossing outside fat face	RD: Markings Refresh	Internal		No Action Required	
Batch: 41217996 - Inspection Batch			Route: SE_CW1_Central1			Date: 07/02/2025		
No actionable defects found								
Batch: 41216231 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 23/01/2025		
42173935	Both sides of junction need existing 8no whin kerbs dropped	23/01/2025	Frederick st junction with hill st	RD: NEW Dropped Kerbs	Internal		No Action Required	
42173934	1no pole stump needs made safe and infilled with grano	23/01/2025	Outside no53	RD: FW Grano Pothole	Internal		Committed	50173524
Batch: 41216178 - Inspection Batch			Route: Ad hoc Route			Date: 23/01/2025		
42173898	Broken cover on Scottish Power manhole	23/01/2025	On the footway outside no45	RU: Utility Apparatus	Internal		Uncommitted	50173487
Batch: 41212569 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 31/12/2024		
42171955	Broken grano surrounding catv box	31/12/2024	Outside skipton building society next to junction with rise street	RD: FW Grano Cracked/Broken	Internal		Committed	50172000
42171960	Broken grano in track	31/12/2024	Outside no25 next to trespass shop	RD: FW Grano Cracked/Broken	Internal		Committed	50172005
42171958	1no grano pothole at gas Toby	31/12/2024	Outside no 26 Frederick street	RD: FW Grano Pothole	Internal		Committed	50172003

Site History Report

Effective: 01/02/2023 to 28/02/2026

Service: Roads General

Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41212071 - Inspection Batch			Route: Ad hoc Route			Date: 27/12/2024		
42171865	1no pothole	27/12/2024	Outside Rosas Thai	RD: CW Pothole	Internal		Committed	50171920
Batch: 41211390 - Inspection Batch			Route: SE_CW1_Central1			Date: 18/12/2024		
No actionable defects found								
Batch: 41210386 - Inspection Batch			Route: Ad hoc Route			Date: 10/12/2024		
42170996	1no cut pcc slab rocking	10/12/2024	Outside fat face shop next to pedestrian crossing	RD: FW Slabs Rocking	Internal		Committed	50171236
Batch: 41209634 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 04/12/2024		
No actionable defects found								
Batch: 41207236 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 11/11/2024		
42168807	2no rocking tactile slabs	11/11/2024	Outside all saint's shop at pedestrian crossing	RD: FW Slabs Rocking	Internal		Committed	50169581
42168810	1no grano open joint at kerb edge at pedestrian crossing	11/11/2024	Outside laings jewellers	RD: FW Grano Open Joint	Internal		Committed	50169584
Batch: 41204487 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 21/10/2024		
42167226	1no broken 900 x 600 pcc slab	21/10/2024	Outside costcutter	RD: FW Slabs Broken/Missing	Internal		Committed	50168418
42167225	1no broken 900 x 600 pcc slab	21/10/2024	Outside skirting building society	RD: FW Slabs Broken/Missing	Internal		Committed	50168417
42167223	4no cut 900 x 600 pcc slabs	21/10/2024	Next to pedestrian crossing outside fat face	RD: FW Slabs Broken/Missing	Internal		Committed	50168415
Batch: 41202916 - Inspection Batch			Route: Ad hoc Route			Date: 09/10/2024		
42166341	Zebra crossing markings need refreshed	09/10/2024	Pedestrian crossing outside fat face	RD: Markings Refresh	Internal		No Action Required	
Batch: 41201315 - Inspection Batch			Route: SE_CW1_Central1			Date: 25/09/2024		
No actionable defects found								
Batch: 41201236 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 24/09/2024		
42165329	1no fw pothole on mono blocks where existing pole stump is please make safe	24/09/2024	At junction with rose street	RD: FW HRA Pothole	Internal		Committed	50166949
42165331	Grano surrounding box needs renewed	24/09/2024	On central section of FW opposite Laings jewellers shop	RD: FW Grano Cracked/Broken	Internal		Committed	50166951
Batch: 41200085 - Inspection Batch			Route: Ad hoc Route			Date: 06/09/2024		
42164658	3no potholes	06/09/2024	At the junction with Princes Street	RD: CW Pothole	Internal		Committed	50166217
Batch: 41199517 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 28/08/2024		
42164262	4 no fw grano potholes	28/08/2024	Outside miller and carter steakhouse	RD: FW Grano Pothole	Internal		Committed	50165882
Batch: 41197780 - Inspection Batch			Route: Ad hoc Route			Date: 31/07/2024		
42162878	Broken grano at kerb trip hazard	31/07/2024	Near 14	RD: FW Grano Pothole	Internal		Committed	50164779
Batch: 41197779 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 31/07/2024		
42162877	Rocking block	31/07/2024	Outside queens arms	RD: FW Blocks Dislodged/Loose	Internal		Committed	50164778

Site History Report

Effective: 01/02/2023 to 28/02/2026

Service: Roads General

Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41195874 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 02/07/2024		
42160800	2 no areas of grano cracked broken on fw needs replaced	02/07/2024	Outside Laing's the jewellers	RD: FW Grano Cracked/Broken	Internal		Committed	50163275
42160801	Both sides of junction need existing whin kerbs dropped	02/07/2024	Frederick st junction with hill st	RD: NEW Dropped Kerbs	Internal		No Action Required	
Batch: 41194942 - Inspection Batch			Route: SE_CW1_Central1			Date: 20/06/2024		
42160038	1 cw pothole	20/06/2024	Outside barbour	RD: CW Pothole	Internal		Committed	50162667
Batch: 41194013 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 11/06/2024		
42159451	Box and lining needs refreshed	10/06/2024	At crossing with rose st	RD: Markings Refresh	Internal		Committed	50162086
42159518	5 no loose / rocking grey tactiles 1no cross cut 800 x 600 pcc slab	11/06/2024	Outside fat face at pedestrian crossing	RD: FW Slabs Rocking	Internal		Committed	50162144
42159452	5no grano potholes	10/06/2024	Outside no 30 next to co opshop	RD: FW Grano Cracked/Broken	Internal		Committed	50162087
Batch: 41193559 - Inspection Batch			Route: Ad hoc Route			Date: 04/06/2024		
42158974	1no pothole	04/06/2024	On the zebra crossing outside Laings	RD: CW Pothole	Internal		Committed	50161733
Batch: 41192548 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 22/05/2024		
42157800	1no broken 600 x 600 pcc slab	22/05/2024	Outside skipton building society	RD: FW Slabs Broken/Missing	Internal		Committed	50160837
42157811	Grano missing please reinstate	22/05/2024	Outside no 29 next to trespass	RD: FW Grano Depression/Sunk	Internal		Committed	50160841
42157801	Grano missing please reinstate	22/05/2024	Outside Barbour shop	RD: FW Grano Depression/Sunk	Internal		Committed	50160838
Batch: 41191979 - Inspection Batch			Route: Ad hoc Route			Date: 14/05/2024		
42157207	1no large pothole	14/05/2024	On the pedestrian crossing at the junction with Princes Street	RD: CW Pothole	Internal		Committed	50160348
Batch: 41190952 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 02/05/2024		
42156269	3no broken 900 x 600 pcc slabs 1no broken 600 x 600 pcc slab 4 no rocking 900 x 600 pcc slabs	01/05/2024	Opposite house of Scotland	RD: FW Slabs Broken/Missing	Internal		Committed	50159647
42156268	Section of grano broken needs reinstated	01/05/2024	Outside vision express	RD: FW Grano Cracked/Broken	Internal		Committed	50159646
Batch: 41189442 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 12/04/2024		
No actionable defects found								
Batch: 41187992 - Inspection Batch			Route: Ad hoc Route			Date: 28/03/2024		
42153297	4no potholes	28/03/2024	Outside no8	RD: CW Pothole	Internal		Committed	50157058
Batch: 41187866 - Inspection Batch			Route: SE_CW1_Central1			Date: 27/03/2024		
42153215	1no Cw pothole	27/03/2024	Next to pedestrian crossing to rose st	RD: CW Pothole	Internal		Committed	50156971
Batch: 41187255 - Inspection Batch			Route: SE_FW1_NewTownSouth1			Date: 23/03/2024		
No actionable defects found								
Batch: 41186991 - Inspection Batch			Route: Ad hoc Route			Date: 20/03/2024		
42152346	1no pothole	20/03/2024	On the pedestrian crossing at the junction with Princes Street	RD: CW Pothole	Internal		Committed	50156391

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Whole Street			Feature Type: Road Asset			Area: South East Locality	
Batch: 41186911 - Inspection Batch				Route: Ad hoc Route				Date: 20/03/2024
42152243	Depression and potholes requires hra overlay	20/03/2024	On the zebra crossing outside Laings	RD: CW Pothole	Internal		Committed	50156322
Batch: 41184151 - Inspection Batch				Route: Ad hoc Route				Date: 28/02/2024
42149450	Please refresh give way markings	28/02/2024	At the junction with Queen Street	RD: Markings Refresh	Internal		Committed	50154326
Batch: 41183757 - Inspection Batch				Route: SE_FW1_NewTownSouth1				Date: 26/02/2024
42148980	1no Cw pothole	26/02/2024	Frederick st at bus stop GE	RD: CW Pothole	Internal		Committed	50154033
42148983	2no Cw pothole	26/02/2024	Frederick st outside Barbour shop	RD: CW Pothole	Internal		Committed	50154036
Batch: 41183421 - Inspection Batch				Route: Ad hoc Route				Date: 22/02/2024
42148680	1no blocked gully needs cleaned and flushed	22/02/2024	At the corner of Princes Street	Gully: Blocked / Flooding	Internal		Committed	50153678
Batch: 41181603 - Inspection Batch				Route: SE_FW1_NewTownSouth1				Date: 06/02/2024
42146624	Missing grano at gas toby	06/02/2024	Frederick st outside no 63 next to pawnbrokers	RD: FW Grano Cracked/Broken	Internal		Committed	50152333
Batch: 41180936 - Inspection Batch				Route: Ad hoc Route				Date: 01/02/2024
42146055	1no pothole	01/02/2024	On the pedestrian crossing at Princes Street	RD: CW Pothole	Internal		Committed	50151922
Batch: 41178861 - Inspection Batch				Route: SE_FW1_NewTownSouth1				Date: 17/01/2024
42144256	Grano infill required	17/01/2024	Frederick st outside Barbour shop	RD: FW Grano Depression/Sunk	Internal		Committed	50150404
Batch: 41178682 - Inspection Batch				Route: Ad hoc Route				Date: 16/01/2024
42144162	Road: Defective / Damaged (Enquiry 1679219)	16/01/2024	On the pedestrian crossing at Princes Street	RD: CW Pothole	Internal		Committed	50150302
Batch: 41178401 - Inspection Batch				Route: SE_CW1_Central1				Date: 15/01/2024
	No actionable defects found							
Batch: 41176495 - Inspection Batch				Route: SE_FW1_NewTownSouth1				Date: 29/12/2023
	No actionable defects found							
Batch: 41175172 - Inspection Batch				Route: Ad hoc Route				Date: 20/12/2023
42142588	1no pothole	20/12/2023	On the pedestrian crossing at the junction with Princes Street	RD: CW Pothole	Internal		Committed	50148676
Batch: 41174483 - Inspection Batch				Route: Ad hoc Route				Date: 15/12/2023
42141993	Rocking uneven 900x600 slab	15/12/2023	Outside Chisholm hunter	RD: FW Slabs Rocking	Internal		Committed	50148128
Batch: 41173760 - Inspection Batch				Route: SE_FW1_NewTownSouth1				Date: 07/12/2023
42141281	Sunken gas toby on fw causing trip hazard	07/12/2023	Outside 63	RU: Utility Apparatus	Internal		Uncommitted	50147409
Batch: 41171619 - Inspection Batch				Route: SE_FW1_NewTownSouth1				Date: 09/11/2023
	No actionable defects found							
Batch: 41171390 - Inspection Batch				Route: Ad hoc Route				Date: 07/11/2023
42138942	1no pothole	07/11/2023	On the pedestrian crossing at the junction with Princes Street	RD: CW Pothole	Internal		Committed	50145274

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41171388 - Inspection Batch				Route: Ad hoc Route		Date: 07/11/2023		
42138940	1no pothole	07/11/2023	Opposite Barbour shop	RD: CW Pothole	Internal		Committed	50145272
Batch: 41168172 - Inspection Batch				Route: SE_CW1_Central1		Date: 10/10/2023		
42137311	1 carriageway pothole	10/10/2023	Outside schuh	RD: CW Pothole	Internal		Committed	50143802
Batch: 41168080 - Inspection Batch				Route: SE_FW1_NewTownSouth1		Date: 09/10/2023		
42137282	Renew granite Approx 2m x 1.2m	09/10/2023	Outside trespass Behind bus stop	RD: FW Grano Cracked/Broken	Internal		Committed	50143773
Batch: 41164568 - Inspection Batch				Route: SE_FW1_NewTownSouth1		Date: 11/09/2023		
42135954	Relay 1 rocking 600 x 600 slab Renew small granite strip	11/09/2023	Outside laings	RD: FW Slabs Broken/Missing	Internal		Committed	50142411
42135943	Replace 2 broken 300 x 300 slabs & 1 broken cut slab (300x 150)	11/09/2023	Outside queens arms	RD: FW Slabs Broken/Missing	Internal		Committed	50142404
42135941	Replace 2 broken 750 x 600 slabs & 1 broken 900 x 600 slab	11/09/2023	Outside cote brassiere	RD: FW Slabs Broken/Missing	Internal		Committed	50142402
Batch: 41162712 - Inspection Batch No actionable defects found				Route: SE_FW1_NewTownSouth1		Date: 09/08/2023		
Batch: 41161713 - Inspection Batch				Route: Ad hoc Route		Date: 25/07/2023		
42132728	Infill grano pothole	25/07/2023	Outside Barbour	RD: FW Grano Pothole	Internal		Committed	50139882
Batch: 41161712 - Inspection Batch				Route: Ad hoc Route		Date: 25/07/2023		
42132726	Infill grano pothole	25/07/2023	Outside Barbour	RD: FW Grano Pothole	Internal		Committed	50139880
Batch: 41161675 - Inspection Batch No actionable defects found				Route: SE_CW1_Central1		Date: 25/07/2023		
Batch: 41160694 - Inspection Batch				Route: SE_FW1_NewTownSouth1		Date: 10/07/2023		
42131511	1no grano pothole	10/07/2023	Outside Schuh	RD: FW Grano Pothole	Internal		Committed	50138988
Batch: 41159413 - Inspection Batch				Route: SE_FW1_NewTownSouth1		Date: 15/06/2023		
42130047	1no broken cut perfecta slab 450x370 Infill grano joint	15/06/2023	Outside Royal House of Scotland	RD: FW Slabs Broken/Missing	Internal		Committed	50137815
Batch: 41157443 - Inspection Batch No actionable defects found				Route: SE_FW1_NewTownSouth1		Date: 18/05/2023		
Batch: 41155143 - Inspection Batch No actionable defects found				Route: SE_CW1_Central1		Date: 19/04/2023		
Batch: 41154673 - Inspection Batch No actionable defects found				Route: SE_FW1_NewTownSouth1		Date: 12/04/2023		
Batch: 41152196 - Inspection Batch No actionable defects found				Route: SE_FW1_NewTownSouth1		Date: 15/03/2023		
Batch: 41148535 - Inspection Batch				Route: SE_FW1_NewTownSouth1		Date: 12/02/2023		
42118211	2no rocking 600x900 slabs 1no broken 600x600 pcc slab	10/02/2023	Outside Chisholm Hunter	RD: FW Slabs Rocking	Internal		Committed	50128987

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41148535 - Inspection Batch				Route: SE_FW1_NewTownSouth1			Date: 12/02/2023	
42118210	Infill grano pothole	10/02/2023	Outside Barbour	RD: FW Grano Pothole	Internal		Committed	50128986

Customer Services

Enquiry No.: 34010316 **Logged by:** [REDACTED] **on:** 28/08/2025 14:49
Service: Roads General **Subject:** Road Markings: Defective **Classification:** Request for service
Desc.: Frederick Street The road markings have worn away and it's dangerous when heading east. Three lanes go to two lanes, so the inside lane before Frederick St becomes the middle lane after. However cars in the middle lane before Frederick St keep going straight on rather than moving to the right hand lane as the marking has gone
Location: Frederick Street **Contact:** 0

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 34008236 **Logged by:** [REDACTED] **on:** 07/03/2024 13:47
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Frederick Street @ Thistle Street – Carriageway Void within City Fibres excavation
Location: Frederick Street **Contact:**

Enquiry No.: 34008174 **Logged by:** [REDACTED] **on:** 26/02/2024 09:35
Service: Roads General **Subject:** Street Furniture: Defective **Classification:** Request for service
Desc.: please inspect the broken manhole cover on the corner of princes street & hanover, at the junction of the two. please see pic attached.
Location: Frederick Street **Contact:**

Enquiry No.: 2103676 **Logged by:** [REDACTED] **on:** 27/02/2026 15:13
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Pothole
Location: at crossing halfway up frederick street **Contact:**

Enquiry No.: 2098469 **Logged by:** Verint CRM Connector **on:** 19/02/2026 13:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: At the crossroad between Hill Street and Thistle Street. The tarmac has not been replaced after recent utility work. The cobbles are now shown and have sunk and are loose. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50192389 **Defect Number:** 42200050

Enquiry No.: 2095647 **Logged by:** Verint CRM Connector **on:** 15/02/2026 17:23
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The pothole/ uneven surface is on the road crossing over Frederick Street going to Rose Street. [REDACTED] Wildfire Restaurant which was close by and the postcode for it is EH2 4AZ **Contact:**

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2092416 Service: Roads General Desc.: Location: Massive big pothole. Really dangerous	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 11/02/2026 04:29 Classification: Request for service Contact:
Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset		
Enquiry No.: 2092103 Service: Roads General Desc.: Location: I would like to report a pot hole in Frederick street. As you can see it's in the opposite side of the road to the Cote restaurant. More or less in front of Toni& Guy the hairdresser!	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 10/02/2026 14:29 Classification: Request for service Contact:
Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset		
Enquiry No.: 2091752 Service: Roads General Desc.: Location: What3words: ///forget.panel.alone Large pot hole to the near side of the road prior to joining George Street front Frederick Street, Edinburgh.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 10/02/2026 08:47 Classification: Request for service Contact:
Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset		
Enquiry No.: 2090335 Service: Roads General Desc.: Location: Depressions and potholes in zebra crossing causing trip hazard	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 07/02/2026 11:41 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50191392 Feature Id - Location: Whole Street Defect Number: 42198884 Feature Type: Road Asset		
Enquiry No.: 2090299 Service: Roads General Desc.: Location: Pothole at zebra Crossing	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 07/02/2026 10:36 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50191386 Feature Id - Location: Whole Street Defect Number: 42198876 Feature Type: Road Asset		
Enquiry No.: 2090298 Service: Roads General Desc.: Location: Pothole at bus stop	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 07/02/2026 10:35 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50191393 Feature Id - Location: Whole Street Defect Number: 42198885 Feature Type: Road Asset		
Enquiry No.: 2089884 Service: Roads General Desc.: Location: There is a huge pothole at the pedestrian crossing at the Frederick St/George St junction.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 06/02/2026 11:57 Classification: Request for service Contact:

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2088624 Logged by: Verint CRM Connector on: 04/02/2026 13:03
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Large indentation in road surface over zebra crossing. difficult to pass with a pram and for wheelchair users. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset
Job Number: 50191389 Defect Number: 42198880

Enquiry No.: 2086693 Logged by: Verint CRM Connector on: 01/02/2026 11:10
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Two large, deep potholes in the Northbound bus stop. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset
Job Number: 50191395 Defect Number: 42198887

Enquiry No.: 2058685 Logged by: Verint CRM Connector on: 15/12/2025 11:15
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Several potholes and sunken manhole cover between Rose St and George Street. Pedestrian crossing badly cracked and surface breaking up. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 2039633 Logged by: Verint CRM Connector on: 07/11/2025 13:18
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Sharp, deep pothole IN the pedestrian crossing. I nearly fell over when my crutch and shoe caught it. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 2034747 Logged by: Verint CRM Connector on: 29/10/2025 07:34
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
Desc.:
Location: I was visiting Edinburgh on Monday 27 th with [redacted] and I tripped on the uneven pavement as we were crossing over Frederck Street outside Laings. [redacted]
[redacted] I have noticed the poor state of Edinburgh's pavements on previous occasions so I plan to avoid shopping trips to the city now. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 2021966 Logged by: Verint CRM Connector on: 01/10/2025 12:04
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Frederick Street @ rose St yellow box junction road is crumbling, sunken and in need of repair. This has been in poor condition since it was reported in April 2025 Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2009027 Service: Roads General Desc.: Location: Fredrick St bus stop northbound Road very crumbly at bus stop	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 04/09/2025 13:28 Classification: Request for service Contact:
Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset		
Enquiry No.: 1991641 Service: Roads General Desc.: Location: Cables coming through the road surface, some bare wire middle of lane on side closest to Hotel Chocolat	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 06/08/2025 18:16 Classification: Request for service Contact:
Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset		
Enquiry No.: 1968963 Service: Roads General Desc.: Location: Tarmac breaking up and sinking.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 25/06/2025 16:20 Classification: Request for service Contact:
Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset		
Enquiry No.: 1936896 Service: Roads General Desc.: Location: On and just after the box junction with rose street northbound. The road surface is breaking up	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 22/04/2025 14:28 Classification: Request for service Contact:
Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset		
Enquiry No.: 1922546 Service: Roads General Desc.: Location: Potholes in box junction	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 24/03/2025 07:27 Classification: Request for service Contact:
Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset		
Enquiry No.: 1917458 Service: Roads General Desc.: Location: Potholes forming in bus stop	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 13/03/2025 10:09 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50177493 Feature Id - Location: Whole Street Defect Number: 42179571 Feature Type: Road Asset		
Enquiry No.: 1908381 Service: Roads General Desc.: What type of sign is it? Road sign problem, type dontknow I can't find anywhere to report this problem properly but the road markings on Queen's Street are really degraded and people don't realise it's a 2 lane street so they are all over the place. Location: Lack of road markings causing near miss accidents	Logged by: Verint CRM Connector Subject: Road Markings: Defective	on: 24/02/2025 08:40 Classification: Request for service Contact:

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1904849 **Logged by:** Verint CRM Connector **on:** 17/02/2025 12:23
Service: Roads General **Subject:** Roadworks: Defect **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type unlit The sign is lying flat and no longer being used it is near 58 Frederick St adjacent to the bus stop.
Location: Near 58 Frederick St ,The temporary road sign is no longer required? and is lying flat adjacent to the bus stop. **Contact:**

Enquiry No.: 1903417 **Logged by:** Verint CRM Connector **on:** 13/02/2025 22:30
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Shame on you!! Saw photos of the "repave" of Frederick St....absolutely disgusting that you would pave over the cobbles!
What were you thinking?!! Saving money!?? Awful and im from [REDACTED] .. visited there in October and the whole draw in the city is its beauty. Your whole council should be fired for allowing this to happen!! [REDACTED] **Contact:**

Enquiry No.: 1898493 **Logged by:** Verint CRM Connector **on:** 04/02/2025 14:33
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: REF: 101002904037, THIS IS THE THIRD TIME I HAVE WRITTEN TO ABOUT THIS STRETCHOF ROAD BETWEEN FREDRICK STREET AND QUEEN STREET, WHAT A MESS WORKMANSIP AT IT'S WORST. THE ROAD NEEDS COMPLETELY DUG UP RESURFACED COMPLETELY **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1898322 **Logged by:** Verint CRM Connector **on:** 04/02/2025 11:21
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Collapsing manhole on Princes Street at Fredrick Street East Bound. Manhole cover flips up and tarmac around it is breaking up **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1898211 **Logged by:** [REDACTED] **on:** 04/02/2025 08:54
Service: Roads General **Subject:** Road: General Enquiry **Classification:** General Enquiry
Desc.: From: [REDACTED]
Date: Sunday 2 February 2025 at 14:28:44
To: <customer.care@edinburgh.gov.uk>
Subject: Frederick Street Road Surface

Good afternoon

I'm actually a former resident of Edinburgh and watch with interest what's happening in my old city. Whilst I agree with the frustrations of many residents on a number of matters, I do think many people do complain about anything they can think of, and too much spare time on their hands. If I hear anything else about the trams, "the jobby" or the Clowncil, I'll go through the roof.

That said I can only concur with every negative comment about the newly laid tarmac surface to Frederick Street, in summary, whoever authorised this work needs FIRED, what an absolute disgrace to ruin such a street. Without being accused of any inappropriate comments, it looks like a bunch of navvies arrived at the Council offices and asked if they could get rid of some spare asphalt. Come on City of Edinburgh Council, you can do better than this for the residents of your city, the very people who voted you in, and pay your salaries.

Talk about shooting yourselves in the foot. Extremely poor.

An acknowledgment of this communication would be appreciated, however if you can't reply as someone is too busy getting it all removed, that's acceptable

Sent from my [REDACTED]

Location:

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1893072 **Logged by:** [REDACTED] **on:** 27/01/2025 08:17
Service: Roads General **Subject:** Road: General Enquiry **Classification:** General Enquiry
Desc.: Case Details
Case RefXE47XQ36-101002924525 [XE47XQ36]
ClassificationFeedback >> Compliment, suggestion or complaint >> Make a compliment, suggestion or complaint
Associated with [REDACTED]
TitleIt appears that work is underway to tarmac over the cobbles on Frederick Street.
DescriptionFirst Name: [REDACTED]
Last name: [REDACTED]
Contact Telephone Number: [REDACTED]
Email: [REDACTED]
What kind of feedback would you like to provide? complaint What area does your complaint relate to ? : road_travel_parking

If your comments relate to a council service for which you have an account then please provide an account number :

Short description of complaint : It appears that work is underway to tarmac over the cobbles on Frederick Street.

Please provide the details of the complaint : It appears that work is underway to tarmac over the cobbles on Frederick Street. This is very disappointing and a real shame, as these cobbles add immensely to the character and attraction of the New Town.

How would you like us to deal with this? : Ideally, the council would reconsider and perhaps undo this action. At the very least I would urge the council to consider very carefully before enlarging the scope of this project beyond Frederick Street.

Location: Frederick Street

Contact:

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1888056 **Logged by:** Verint CRM Connector **on:** 17/01/2025 07:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The road surface from Queen street to George street is a disgrace and has been patched to a standard that can only be described as embarrassing and amateur. This road is damaging cars and is almost unusable to cyclists and poses a serious risk of danger. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1885648 **Logged by:** Verint CRM Connector **on:** 13/01/2025 11:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The entirety of north Frederick street is a danger to motorcycles and is damaging cars. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1884340 **Logged by:** Verint CRM Connector **on:** 10/01/2025 13:05
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: The pavement and glass block grate directly on front of our stores main entrance at Frederick Street (Five Guys, 12 Frederick Street, EH2 2HB) is heavy cracked and uneven. This is obviously a H&S risk to our customers, staff, and the public in general and needs repairing ASAP. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1879958 **Logged by:** Verint CRM Connector **on:** 05/01/2025 01:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: This whole part of Frederick Street is a disgrace it's full of potholes and uneven tarmac on cables very dangerous! **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1873859 **Logged by:** Verint CRM Connector **on:** 20/12/2024 19:27
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep potholes in middle of the road. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50171920

Defect Number: 42171865

Enquiry No.: 1868538 **Logged by:** Verint CRM Connector **on:** 08/12/2024 15:06
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: This Road is a complete disaster! full of potholes and crumbling tarmac very dangerous **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1865316 **Logged by:** Verint CRM Connector **on:** 29/11/2024 15:45
Service: Roads General **Subject:** Road: Missing Setts / Blocks **Classification:** Customer Emergency
Desc.:
Location: I WOULD LIKE TO REPORT THE SHOCKING MESS THAT THIS STRETCH OF ROAD IS IN, IT IS JUST NOT SAFE **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1864387 **Logged by:** Verint CRM Connector **on:** 27/11/2024 19:27
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The road is an absolute mess on both sides. This causes damage to mine and my friends suspension and bumpers, simply not on and needs something done. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1860329 **Logged by:** Verint CRM Connector **on:** 18/11/2024 17:25
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The road is all crumbling abd full of potholes - it is very dangerous **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1848479 **Logged by:** Verint CRM Connector **on:** 23/10/2024 17:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Frederick street between george street and queen street heavily potholed **Contact:**

Enquiry No.: 1845656 **Logged by:** Verint CRM Connector **on:** 17/10/2024 09:51
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole formed outside Miller and carter citybound at bus stop **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1830343 **Logged by:** Verint CRM Connector **on:** 11/09/2024 12:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Manhole cover loose and large hole around. Dangerous for cycles. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1827831 **Logged by:** Verint CRM Connector **on:** 05/09/2024 16:54
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Multiple deep potholes which are a danger to pedestrians crossing the road and cyclists. No doubt doing damage to vehicles too. I witnessed someone trip on one of the potholes ...likely a regular occurrence. The road is a disgrace. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1825317 Service: Roads General Desc.: Location: Sunken road surface northbound bus stop	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 01/09/2024 07:52 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50166217	Feature Id - Location: Whole Street Defect Number: 42164658	Feature Type: Road Asset
Enquiry No.: 1812711 Service: Roads General Desc.: Location: Around 45 Fredrick Street south bound, sunken tarmac and cobbles	Logged by: Verint CRM Connector Subject: Road: Missing Setts / Blocks	on: 08/08/2024 14:42 Classification: Customer Emergency Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1811729 Service: Roads General Desc.: Location: The length of Frederick Street between George Street and Queens Street is very uneven. I was standing to get off the bus and despite the driver going very slowly I nearly fell over.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 06/08/2024 18:15 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1809347 Service: Roads General Desc.: Location: The whole of north Frederick street is dangerous for motorcycles. The entire street is a disgrace.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 01/08/2024 13:16 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1795319 Service: Roads General Desc.: Location: Horrible potholes for cyclist.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 09/07/2024 13:49 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1793715 Service: Roads General Desc.: Location: The whole road is an absolute disgrace uneven tarmac loose cobbles very dangerous	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 06/07/2024 14:21 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1789164 Service: Roads General Desc.: Location: Multiple potholes, broken tarmac and missing sets between George Street and Queen Street	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 28/06/2024 01:25 Classification: Request for service Contact:

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1785781 Logged by: Verint CRM Connector on: 21/06/2024 18:25
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
Desc.:

Location: From: [REDACTED] Contact:
Date: Friday, June 21, 2024 at 5:57:52 PM
To: <customer.care@edinburgh.gov.uk>
Subject: Dangerous uneven pavement

I'd like to report a problem with the pavement on Frederick Street east side going from George Street down towards Princes Street.

I had a terrible fall there yesterday because my foot caught on a raised part and I tripped and fell.

[REDACTED] As I'm
sure you can imagine I'm not at all happy about this!!

I'd really appreciate it if you could arrange for this to be dealt with as soon as possible.

Thank you.
[REDACTED]

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1765626 Logged by: Verint CRM Connector on: 28/05/2024 17:37
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:

Location: Crossing the street at the corner of Frederick street and Thistle street on the side where the Queens Arms pub is located, the cobblestones are so greasy and dirty that I slipped on them, fell and injured [REDACTED]. The state of the city is disgusting, people fall all the time because of uneven broken tiles. You're asking to report an issue with broken or moving tiles but where do I even begin? All tiles are broken and shaky! Clean up and do something! I'm left limping because of your negligence

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1751723 Logged by: Verint CRM Connector on: 10/05/2024 17:51
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:

Location: Road surface at foot of street. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1744037 Logged by: Verint CRM Connector on: 27/04/2024 10:23
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
Desc.:

Location: Proud slab at pedestrian crossing causing trip hazard Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1730113 Service: Roads General Desc.: Location: Frederick Street from George Street to Queen Street on both sides is an incredibly bumpy state. It needs drastic action !!!	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 04/04/2024 14:38 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50157058	Feature Id - Location: Whole Street Defect Number: 42153297	Feature Type: Road Asset
Enquiry No.: 1724833 Service: Roads General Desc.: Location: Potholes within northbound bus stop.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 26/03/2024 14:22 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50157058	Feature Id - Location: Whole Street Defect Number: 42153297	Feature Type: Road Asset
Enquiry No.: 1720934 Service: Roads General Desc.: Location: Zebra crossing , road in very bad condition for disabled person	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 19/03/2024 16:42 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50156322	Feature Id - Location: Whole Street Defect Number: 42152243	Feature Type: Road Asset
Enquiry No.: 1717740 Service: Roads General Desc.: Location: Princes Street, Edinburgh at its junction with Frederick Street. The street corner is potholed, worn, tough and uneven, everything a good army tank training ground should be.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 14/03/2024 11:24 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50156391	Feature Id - Location: Whole Street Defect Number: 42152346	Feature Type: Road Asset
Enquiry No.: 1710352 Service: Roads General Desc.: Location: lots of pot holes, road surface almost un-drivable. disgrace of a road in the capital of Scotland.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 01/03/2024 18:30 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50154326	Feature Id - Location: Whole Street Defect Number: 42149450	Feature Type: Road Asset
Enquiry No.: 1706915 Service: Roads General Desc.: Location: South bound lane Frederick Street at the junction with Queen Street There is no road markings all the white paint has faded and mostly disappeared which is dangerous	Logged by: Verint CRM Connector Subject: Road: Missing Setts / Blocks	on: 26/02/2024 11:37 Classification: Customer Emergency Contact:
Plot Number: 1.00 Job Number: 50154326	Feature Id - Location: Whole Street Defect Number: 42149450	Feature Type: Road Asset

Site History Report

Effective: 01/02/2023 to 28/02/2026
 Service: Roads General
 Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
 Display Action Officer: No

Customer Services

Enquiry No.: 1704578	Logged by: Verint CRM Connector	on: 22/02/2024 12:17
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: pothole opposite - 29A-31, FREDERICK STREET, EDINBURGH, EH2 2ND	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1694860	Logged by: Verint CRM Connector	on: 07/02/2024 12:47
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Road surface at junction with Frederick Street.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1685661	Logged by: Verint CRM Connector	on: 25/01/2024 14:13
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: TRAFFIC SIGNALS NOT FACING CORRECT WAY AT THIS LOCATION	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1684224	Logged by: Verint CRM Connector	on: 23/01/2024 23:18
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Well. The road surface is awful, its absolutely not suitable for driving. It had potholes everywhere and making vehicle to drive on the opposite side of the road to avoid breaking the car wheels or suspension.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1679219	Logged by: Verint CRM Connector	on: 16/01/2024 13:36
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Carriageway surfacing broken up.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50150302	Defect Number: 42144162	
Enquiry No.: 1660442	Logged by: Verint CRM Connector	on: 12/12/2023 16:31
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: There is a rocking slab 10-20 yards up from Princes Street on the right hand pavement, in the middle. I stepped on it. [REDACTED]. As I stood on it, it went down. [REDACTED] side went up and [REDACTED] fell [REDACTED] full length onto the. Pavement. We did not need assistance but we saw other people unbalanced on the slab while [REDACTED] was recovering.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1659441 Logged by: [REDACTED] on: 11/12/2023 11:53
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.: Hello,

I wanted to contact you to discuss an issue that we experienced yesterday.

When crossing Frederick Street in the heavy rain, my [REDACTED] tripped over one of the many holes in the road and fell flat on [REDACTED] face in the middle of the road during the green man. [REDACTED]

Can you advise who I can escalate this to within the Council. The state of that road is an absolute disgrace.

Best wishes,
[REDACTED]

Location: Frederick Street

Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset
Job Number: 50148676 Defect Number: 42142588

Enquiry No.: 1658024 Logged by: Verint CRM Connector on: 08/12/2023 13:44
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: The north side of fredrick street Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1638656 Logged by: Verint CRM Connector on: 04/11/2023 12:49
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Pothole/tarmac crumbling Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset
Job Number: 50145272 Defect Number: 42138940

Enquiry No.: 1601155 Logged by: Verint CRM Connector on: 21/08/2023 09:14
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:

Location: Road surface here from Queen Street to George Street is extremely embarrassing Contact:
for any big city, particularly a capital city. It's like the world war 1 Somme. Very rough
going even for my 4x4. Random patching; irregular sizes and shapes of tarmac
mixed with cobbles, looks like those charged with maintaining the appearance and
character of our world heritage site just don't care. Uneven surface is like a sea in a
very heavy swell.

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1560545 **Logged by:** Verint CRM Connector **on:** 01/06/2023 14:32
Service: Roads General **Subject:** Roadworks: General Enquiry **Classification:** Request for service
Desc.:

Location: Significant Site compound on this section for the 20/05757/FUL redevelopment of the building into the corner as an apartment hotel. **Contact:**
This compound takes up a significant amount of space and disruption on a key part of Frederick Street. The external works seem to be done now, and the contractors GHI seem to really just be using it as a car park. Photo attached.
Was permission granted for this? The planning officer is unsure and directed me your way. Also is car parking really the icorrect use?

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1554988 **Logged by:** Verint CRM Connector **on:** 23/05/2023 10:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Significant depression in road surface (cobble meeting tarmac??) around drain cover at traffic lights at the junction of Frederick Street and Queen Street in left lane for going straight ahead (north) towards Stockbridge or left (west) along Queen Street. In practice, many drivers stake the two lanes and a few stay in the right lane, leading to confusion and possible collision when traffic from both lanes go straight ahead. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1539854 **Logged by:** Verint CRM Connector **on:** 19/04/2023 18:34
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Broken cable in cobble opposite bus stop on west side with exposed wires. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1534437 **Logged by:** Verint CRM Connector **on:** 07/04/2023 20:03
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:

Location: Collapsed utility chamber on eastbound lane 1 of Princes Street at the junction with Frederick Street. There is a significant depression on the typical cyclist road position which creates a major hazard and danger for the most vulnerable road users. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1521607 **Logged by:** Verint CRM Connector **on:** 11/03/2023 21:53
Service: Roads General **Subject:** Roadworks: General Enquiry **Classification:** Request for service
Desc.:

Location: 101001700152 **Contact:**
Metal road sign on pavement by phone booth outside Royal House of Scotland near junction with Princes Street. Been there months. Already reported this issue.

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1515758 **Logged by:** Verint CRM Connector **on:** 26/02/2023 19:03
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: URGENT **Contact:**

My [redacted] and I (and other bystanders) today witnessed a cyclist coming down Frederick Street onto Princes Street who hit a manhole cover that was partially sunken and exposing the corner edge of the metal manhole and get thrown over handle bars onto the tram tracks.

I have taken a picture of the manhole cover and general road condition at this junction and would ask if this can be urgently attended to to avoid any major incidents occurring with cyclists.

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1513809 **Logged by:** Verint CRM Connector **on:** 22/02/2023 13:30
Service: Roads General **Subject:** Roadworks: General Enquiry **Classification:** Request for service
Desc.:
Location: Road sign, sand bags and cones have been lying here, redundant, for weeks. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1512306 **Logged by:** Verint CRM Connector **on:** 20/02/2023 08:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: road is a mass of potholes and poor surfacing **Contact:**
 easting/northing: 325105/674086

Enquiry No.: 1508027 **Logged by:** Verint CRM Connector **on:** 10/02/2023 11:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Shocking condition **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50128986	Infill grano pothole (RD: FW Grano Pothole)	Outside Barbour	RD: Cat 3 - 60 Day	Job Complete	10/02/2023	15/02/2023 Act.	ROAD/82072656
50128987	2no rocking 600x900 slabs 1no broken 600x600 pcc slab (RD: FW Slabs Rocking)	Outside Chisholm Hunter	RD: Cat 3 - 60 Day	Job Complete	10/02/2023	20/02/2023 Act.	ROAD/82072657
50137815	1no broken cut perfecta slab 450x370 Infill grano joint (RD: FW Slabs Broken/Missing)	Outside Royal House of Scotland	RD: Cat 2 - 5 Day	Job Complete	15/06/2023	19/06/2023 Act.	ROAD/82078295
50138988	1no grano pothole (RD: FW Grano Pothole)	Outside Schuh	RD: Cat 3 - 60 Day	Job Complete	10/07/2023	26/07/2023 Act.	ROAD/82078957

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50139880	Infill grano pothole (RD: FW Grano Pothole)	Outside Barbour	RD: Cat 2 - 5 Day	Job Complete	25/07/2023	26/07/2023	Act. ROAD/82079411
50139882	Infill grano pothole (RD: FW Grano Pothole)	Outside Barbour	RD: Cat 2 - 5 Day	Job Cancelled	25/07/2023	01/08/2023	Est. ROAD/82079413
50142402	Replace 2 broken 750 x 600 slabs & 1 broken 900 x 600 slab (RD: FW Slabs Broken/Missing)	Outside cote brassiere	RD: Cat 3 - 60 Day	Job Complete	11/09/2023	14/09/2023	Act. ROAD/82080600
50142404	Replace 2 broken 300 x 300 slabs & 1 broken cut slab (300x150) (RD: FW Slabs Broken/Missing)	Outside queens arms	RD: Cat 3 - 60 Day	Job Complete	11/09/2023	14/09/2023	Act. ROAD/82080601
50142411	Relay 1 rocking 600 x 600 slab Renew small granite strip (RD: FW Slabs Broken/Missing)	Outside laings	RD: Cat 3 - 60 Day	Job Complete	11/09/2023	14/09/2023	Act. ROAD/82080604
50143773	Renew granite Approx 2m x 1.2m (RD: FW Grano Cracked/Broken)	Outside trespass Behind bus stop	RD: Cat 3 - 60 Day	Job Complete	09/10/2023	24/10/2023	Act. ROAD/82081453
50143802	1 carriageway pothole (RD: CW Pothole)	Outside schuh	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/10/2023	10/10/2023	Act. ROAD/82081473
50145272	1no pothole (RD: CW Pothole)	Opposite Barbour shop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/11/2023	08/11/2023	Act. ROAD/82082448
50145274	1no pothole (RD: CW Pothole)	On the pedestrian crossing at the junction with Princes Street	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/11/2023	07/11/2023	Act. ROAD/82082450
50148128	Rocking uneven 900x600 slab (RD: FW Slabs Rocking)	Outside Chisholm hunter	RD: Cat 2 - 5 Day	Job Complete	15/12/2023	18/12/2023	Act. ROAD/82084084
50148676	1no pothole (RD: CW Pothole)	On the pedestrian crossing at the junction with Princes Street	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/12/2023	21/12/2023	Act. ROAD/82084479
50150302	Road: Defective / Damaged (Enquiry 1679219) (RD: CW Pothole)	On the pedestrian crossing at Princes Street	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/01/2024	19/01/2024	Act. ROAD/82085520
50150404	Grano infill required (RD: FW Grano Depression/Sunken)	Frederick st outside Barbour shop	RD: Cat 3 - 60 Day	Job Complete	17/01/2024	13/03/2024	Act. ROAD/82085585
50151922	1no pothole (RD: CW Pothole)	On the pedestrian crossing at Princes Street	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/02/2024	18/02/2024	Act. ROAD/82086639
50152333	Missing grano at gas toby (RD: FW Grano Cracked/Broken)	Frederick st outside no 63 next to pawnbrokers	RD: Cat 3 - 60 Day	Job Complete	06/02/2024	21/05/2024	Act. ROAD/82086943
50153678	1no blocked gully needs cleaned and flushed (Gully: Blocked / Flooding)	At the corner of Princes Street	RG: Gully - High Priority	Gully: Investigation Required	22/02/2024	21/03/2024	Est. RDGC/14/82006139
50154033	1no Cw pothole (RD: CW Pothole)	Frederick st at bus stop GE	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/02/2024	28/02/2024	Act. ROAD/82088100
50154036	2no Cw pothole (RD: CW Pothole)	Frederick st outside Barbour shop	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	26/02/2024	28/02/2024	Act. ROAD/82088103
50154326	Please refresh give way markings (RD: Markings Refresh)	At the junction with Queen Street	RD: Cat 4 - Programmed	Job Complete	28/02/2024	31/05/2024	Act. ROAD/82093041

Site History Report

Effective: 01/02/2023 to 28/02/2026

Service: Roads General

Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50156322	Depression and potholes requires hra overlay (RD: CW Pothole)	On the zebra crossing outside Laings	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/03/2024	21/03/2024	Act. ROAD/82089733
50156391	1no pothole (RD: CW Pothole)	On the pedestrian crossing at the junction with Princes Street	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/03/2024	09/04/2024	Act. ROAD/82089788
50156971	1no Cw pothole (RD: CW Pothole)	Next to pedestrian crossing to rose st	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/03/2024	08/04/2024	Act. ROAD/82090194
50157058	4no potholes (RD: CW Pothole)	Outside no8	RD: Cat 3 - 60 Day	Job Complete	28/03/2024	08/04/2024	Act. ROAD/82090258
50159646	Section of grano broken needs reinstated (RD: FW Grano Cracked/Broken)	Outside vision express	RD: Cat 3 - 60 Day	Job Complete	01/05/2024	12/06/2024	Act. ROAD/82092120
50159647	3no broken 900 x 600 pcc slabs 1no broken 600 x 600 pcc slab 4 no rocking 900 x 600 pcc slabs (RD: FW Slabs Broken/Missing)	Opposite house of Scotland	RD: Cat 3 - 60 Day	Job Complete	01/05/2024	01/07/2024	Act. ROAD/82092121
50160348	1no large pothole (RD: CW Pothole)	On the pedestrian crossing at the junction with Princes Street	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/05/2024	02/06/2024	Act. ROAD/82092532
50160837	1no broken 600 x 600 pcc slab (RD: FW Slabs Broken/Missing)	Outside skipton building society	RD: Cat 3 - 60 Day	Job Complete	22/05/2024	12/06/2024	Act. ROAD/82092794
50160838	Grano missing please reinstate (RD: FW Grano Depression/Sunken)	Outside Barbour shop	RD: Cat 3 - 60 Day	Job Complete	22/05/2024	12/06/2024	Act. ROAD/82092795
50160841	Grano missing please reinstate (RD: FW Grano Depression/Sunken)	Outside no 29 next to trespass	RD: Cat 3 - 60 Day	Job Complete	22/05/2024	12/06/2024	Act. ROAD/82092797
50161733	1no pothole (RD: CW Pothole)	On the zebra crossing outside Laings	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/06/2024	05/06/2024	Act. ROAD/82093306
50162086	Box and lining needs refreshed (RD: Markings Refresh)	At crossing with rose st	RD: Cat 4 - Programmed	Job Complete	10/06/2024	22/06/2024	Act. ROAD/82093990
50162087	5no grano potholes (RD: FW Grano Cracked/Broken)	Outside no 30 next to co opshop	RD: Cat 3 - 60 Day	Job Complete	10/06/2024	18/06/2024	Act. ROAD/82093669
50162144	5 no loose / rocking grey tactiles 1no cross cut 800 x 600 pcc slab (RD: FW Slabs Rocking)	Outside fat face at pedestrian crossing	RD: Cat 3 - 60 Day	Job Complete	11/06/2024	19/06/2024	Act. ROAD/82093711
50162667	1 cw pothole (RD: CW Pothole)	Outside barbour	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/06/2024	20/06/2024	Act. ROAD/82093999
50163275	2 no areas of grano cracked broken on fw needs replaced (RD: FW Grano Cracked/Broken)	Outside Laing's the jewellers	RD: Cat 3 - 60 Day	Job Complete	02/07/2024	24/07/2024	Act. ROAD/82094346
50164778	Rocking block (RD: FW Blocks Dislodged/Loose)	Outside queens arms	RD: Cat 3 - 60 Day	Job Complete	31/07/2024	02/08/2024	Act. ROAD/82095281
50164779	Broken grano at kerb trip hazard (RD: FW Grano Pothole)	Near 14	RD: Cat 3 - 60 Day	Job Complete	31/07/2024	01/08/2024	Act. ROAD/82095282
50165882	4 no fw grano potholes (RD: FW Grano Pothole)	Outside miller and carter steakhouse	RD: Cat 3 - 60 Day	Job Complete	28/08/2024	03/09/2024	Act. ROAD/82095904

Site History Report

Effective: 01/02/2023 to 28/02/2026
Service: Roads General
Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: South East Locality		
50166217	3no potholes (RD: CW Pothole)	At the junction with Princes Street	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/09/2024	10/09/2024	Act. ROAD/82096112
50166949	1no fw pothole on mono blocks where existing pole stump is please make safe (RD: FW HRA Pothole)	At junction with rose street	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/09/2024	24/09/2024	Act. ROAD/82096503
50166951	Grano surrounding box needs renewed (RD: FW Grano Cracked/Broken)	On central section of FW opposite Laings jewellers shop	RD: Cat 3 - 60 Day	Job Complete	24/09/2024	25/09/2024	Act. ROAD/82096505
50167815	Zebra crossing markings need refreshed (RD: Markings Refresh)	Pedestrian crossing outside fat face	RD: Cat 4 - Programmed	Job Complete	09/10/2024	10/05/2025	Act. ROAD/82102388
50168415	4no cut 900 x 600 pcc slabs (RD: FW Slabs Broken/Missing)	Next to pedestrian crossing outside fat face	RD: Cat 3 - 60 Day	Job Complete	21/10/2024	08/11/2024	Act. ROAD/82097549
50168417	1no broken 900 x 600 pcc slab (RD: FW Slabs Broken/Missing)	Outside skirting building society	RD: Cat 3 - 60 Day	Job Complete	21/10/2024	24/10/2024	Act. ROAD/82097551
50168418	1no broken 900 x 600 pcc slab (RD: FW Slabs Broken/Missing)	Outside costcutter	RD: Cat 3 - 60 Day	Job Complete	21/10/2024	24/10/2024	Act. ROAD/82097552
50169581	2no rocking tactile slabs (RD: FW Slabs Rocking)	Outside all saint's shop at pedestrian crossing	RD: Cat 3 - 60 Day	Job Complete	11/11/2024	12/11/2024	Act. ROAD/82098271
50169584	1no grano open joint at kerb edge at pedestrian crossing (RD: FW Grano Open Joint)	Outside laings jewellers	RD: Cat 3 - 60 Day	Job Complete	11/11/2024	12/11/2024	Act. ROAD/82098273
50171236	1no cut pcc slab rocking (RD: FW Slabs Rocking)	Outside fat face shop next to pedestrian crossing	RD: Cat 3 - 60 Day	Job Complete	10/12/2024	11/12/2024	Act. ROAD/82099452
50171920	1no pothole (RD: CW Pothole)	Outside Rosas Thai	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/12/2024	27/12/2024	Act. ROAD/82100004
50172000	Broken grano surrounding catv box (RD: FW Grano Cracked/Broken)	Outside skipton building society next to junction with rise street	RD: Cat 3 - 60 Day	Job Complete	31/12/2024	15/01/2025	Act. ROAD/82100056
50172003	1no grano pothole at gas Toby (RD: FW Grano Pothole)	Outside no 26 Frederick street	RD: Cat 3 - 60 Day	Job Complete	31/12/2024	15/01/2025	Act. ROAD/82100058
50172005	Broken grano in track (RD: FW Grano Cracked/Broken)	Outside no25 next to trespass shop	RD: Cat 3 - 60 Day	Job Complete	31/12/2024	15/01/2025	Act. ROAD/82100060
50173524	1no pole stump needs made safe and infilled with grano (RD: FW Grano Pothole)	Outside no53	RD: Cat 3 - 60 Day	Job Complete	23/01/2025	28/01/2025	Act. ROAD/82101226
50176876	Cracked broken grano at manhole and tactiles (RD: FW Grano Cracked/Broken)	Opposite fat face shop	RD: Cat 3 - 60 Day	Job Complete	12/03/2025	17/03/2025	Act. ROAD/82103964
50177493	2no potholes (RD: CW Pothole)	Outside Schuh	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/03/2025	25/03/2025	Act. ROAD/82104380
50177884	1no Cw pothole (RD: CW Pothole)	At pedestrian crossing outside laings the jewellers shop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/03/2025	01/04/2025	Act. ROAD/82104641
50177885	2no grano potholes (RD: FW Grano Pothole)	Outside five guys on fw	RD: Cat 3 - 60 Day	Job Complete	31/03/2025	02/04/2025	Act. ROAD/82104642

Site History Report

Effective: 01/02/2023 to 28/02/2026

Service: Roads General

Site: Frederick Street (7901794)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50177887	2no rocking 900 x 600 pcc slabs (RD: FW Slabs Rocking)	Outside size shop	RD: Cat 3 - 60 Day	Job Complete	31/03/2025	02/04/2025	Act. ROAD/82104643
50177895	1no broken 900 x 600 pcc slab (RD: FW Slabs Broken/Missing)	Outside costcutter shop on FW	RD: Cat 3 - 60 Day	Job Complete	31/03/2025	02/04/2025	Act. ROAD/82104649
50179246	1no pole has been removed and needs infilled with grano (RD: FW Grano Pothole)	Outside no55	RD: Cat 3 - 60 Day	Job Complete	29/04/2025	30/04/2025	Act. ROAD/82105540
50180349	1no rocking 900 x 600 pcc slab (RD: FW Slabs Rocking)	Outside costcutter shop	RD: Cat 3 - 60 Day	Job Complete	26/05/2025	03/06/2025	Act. ROAD/82106339
50181635	1no pothole (RD: CW Pothole)	Outside the Scottish Building Society	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/06/2025	18/06/2025	Act. ROAD/82107103
50182237	1no open grano joint on fw at manhole (RD: FW Grano Open Joint)	Outside all saint's shop opposite le creuset shoo	RD: Cat 3 - 60 Day	Job Complete	02/07/2025	09/07/2025	Act. ROAD/82107494
50182991	Broken grano on Fw approx 1m x 0.2 (RD: FW Grano Cracked/Broken)	Frederick street outside Barbour shop	RD: Cat 2 - 5 Day	Job Complete	23/07/2025	24/07/2025	Act. ROAD/82108006
50183002	2no No entry signs have stickers defacing them (TS: Sign Face Vand/ Graf (SSO))	At junction with hill street	RD: Cat 3 - 60 Day	Job Complete	23/07/2025	31/07/2025	Act. ROAD/82108010
50184857	Relay 1 rocking 300 x 300 slab (RD: FW Slabs Rocking)	Outside the queens arms	RD: Cat 3 - 60 Day	Job Complete	17/09/2025	18/09/2025	Act. ROAD/82109092
50184869	Granite patch required Approx 1m x1m (RD: FW Grano Cracked/Broken)	Outside 29	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/09/2025	22/09/2025	Act. ROAD/82109102
50185719	Fw Grano broken at box (RD: FW Grano Cracked/Broken)	Outside laings the jewellers at pedestrian crossing	RD: Cat 3 - 60 Day	Job Complete	18/10/2025	20/10/2025	Act. ROAD/82109755
50186801	1no pothole (RD: CW Pothole)	At the junction with George Street	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/11/2025	13/11/2025	Act. ROAD/82110406
50188470	2no broken 900 x 600 pcc slabs (RD: FW Slabs Broken/Missing)	Outside size shop	RD: Cat 3 - 60 Day	Job Complete	15/12/2025	16/12/2025	Act. ROAD/82111640
50189771	1no broken 900 x 600 pcc slab 1no rocking cut pcc slab (RD: FW Slabs Broken/Missing)	Outside vacheron constantin	RD: Cat 3 - 60 Day	Job Complete	17/01/2026	20/01/2026	Act. ROAD/82112700
50189774	Cw breaking up approx 2m x 2m (RD: CW Cracked/Broken)	At pedestrian crossing between Rose street	RD: Cat 3 - 60 Day	Job Complete	17/01/2026	06/03/2026	Act. ROAD/82112703
50189775	2no Cw potholes Make safe (RD: CW Pothole)	At pedestrian crossing between Rose street	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/01/2026	19/01/2026	Act. ROAD/82112704
50189777	1no Cw pothole (RD: CW Pothole)	Opposite Barbour shop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/01/2026	19/01/2026	Act. ROAD/82112706
50189778	1no Cw pothole (RD: CW Pothole)	Outside vision express	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/01/2026	19/01/2026	Act. ROAD/82112707
50189779	1no Cw pothole (RD: CW Pothole)	Outside Fat Face Next to pedestrian crossing at George st junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/01/2026	19/01/2026	Act. ROAD/82112708