

Effective: 16/08/2023 to 15/08/2025
Service: Roads General
Site: Calder Road (7906096)

Asset Number: 4.00 to 4.00
Display Action Officer: No

Site: Calder Road (7906096)

Locality: Sighthill, Edinburgh, City of Edinburgh

Area: South West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	4.00	Asset - Locn.: Ward 7 - Various remote footpaths through underpasses beneat			Feature Type: Road Asset		Area: South West Locality	
Batch: 41220719 - Inspection Batch			Route: SW_CF2_CalderRdServ1				Date: 27/02/2025	
42177177	Broken grano	26/02/2025	Walk way down to underpass. Entire walkway damaged	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42177150	Broken slab	26/02/2025	In underpass	RD: FW Slabs Broken/Missing	Internal		Committed	50175958
42177175	Pothole	26/02/2025	Broken up potholed walkway	RD: FW Grano Pothole	Internal		Committed	50175972
42177190	Broken grano	26/02/2025	Walkway to underpass	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42177186	Broken grano	26/02/2025	As marked	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42177188	Broken brander needs replaced	26/02/2025	At underpass entrance	RD: Gully Damaged/Sunken	Internal		Committed	50175980
42177156	Uneven slabs	26/02/2025	As marked	RD: FW Slabs Rocking	Internal		No Action Required	
42177149	Pothole	26/02/2025	As marked	RD: FW Grano Pothole	Internal		No Action Required	
42177178	Broken grano	26/02/2025	Walkway down to underpass	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42177157	Pothole	26/02/2025	Near lamppost 82A	RD: FW Grano Pothole	Internal		Committed	50175962
42177185	Damaged brander	26/02/2025	As marked	RD: Gully Brander Missing	Internal		Uncommitted	50129766
42177193	Rocking slab	26/02/2025	At entrance to underpass	RD: FW Slabs Rocking	Internal		No Action Required	
42177169	Broken fw	26/02/2025	At railings	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42177184	Broken grano	26/02/2025	Walkway to underpass	RD: FW Grano Cracked/Broken	Internal		Uncommitted	50129768
42177191	Jammed brander	26/02/2025	At entrance to underpass	Gully: Brander Jammed	Internal		Uncommitted	50129775
42177151	Broken grano	26/02/2025	As marked	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42177194	Broken grano	26/02/2025	At top of steps	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42177192	Damaged slabs	26/02/2025	At entrance to roundabout	RD: FW Slabs Rocking	Internal		Uncommitted	50154194
Batch: 41201144 - Inspection Batch			Route: Ad hoc Route				Date: 23/09/2024	
42165267	Repair damaged grano	23/09/2024	Exit at Longstone Road	RD: FW Grano Cracked/Broken	Internal		Committed	50166878
Batch: 41183939 - Inspection Batch			Route: SW_CF2_CalderRdServ1				Date: 27/02/2024	
42149274	Broken fw	27/02/2024	At railings	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42149244	Broken grano	27/02/2024	Walkway to underpass	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42149261	Damaged brander	27/02/2024	As marked	RD: Gully Brander Missing	Internal		No Action Required	
42149245	Jammed brander	27/02/2024	At entrance to underpass	Gully: Brander Jammed	Internal		No Action Required	
42149260	Broken grano	27/02/2024	Walkway to underpass	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42149249	New cover required trip hazard	27/02/2024	At entrance to underpass	RD: FW Cover Make Safe	Internal		Committed	50154197
42149254	Pothole	27/02/2024	As marked	RD: FW Grano Pothole	Internal		No Action Required	
42149266	Broken grano	27/02/2024	Walkway down to underpass	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42149264	Broken grano	27/02/2024	Walkway to underpass	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42149243	Damaged slabs	27/02/2024	At entrance to roundabout	RD: FW Slabs Rocking	Internal		No Action Required	
42149255	Uneven slabs	27/02/2024	As marked	RD: FW Slabs Rocking	Internal		No Action Required	
42149250	Damaged cover needs replaced. Not sure if this belongs to utility or council, have raised with both.	27/02/2024	At underpass	RU: Utility Apparatus	Internal		Uncommitted	50154198
42149265	Broken grano	27/02/2024	Walk way down to underpass	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42149242	Rocking slab	27/02/2024	At entrance to underpass	RD: FW Slabs Rocking	Internal		No Action Required	
42149246		27/02/2024		RD: FW Cover Make Safe	Internal		Uncommitted	50129776

Effective: 16/08/2023 to 15/08/2025
Service: Roads General
Site: Calder Road (7906096)

Asset Number: 4.00 to 4.00
Display Action Officer: No

Customer Services

Enquiry No.: 1977980	Logged by: [REDACTED]	on: 14/07/2025 12:20
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Caller reporting road is full of potholes		
Location: section from Whinpark clinic down to bottom of Stenhouse area		Contact:
Enquiry No.: 1974146	Logged by: Verint CRM Connector	on: 06/07/2025 23:22
Service: Roads General	Subject: Road Safety: General Enquiry	Classification: General Enquiry
Desc.: What type of sign is it? Road sign problem, type unlit Calder Road has just changed to a 30 zone from a 40. There are no signs notifying of new speed limit. Additionally the sign at the top of the slip-road from City Bypass indicated the road as 40mph.		
Location: The speed sign at the top of the bypass slip-road indicates 40mph when it is now a 30. There are also no signage re: recent change of speed limit.		Contact:
Enquiry No.: 1971758	Logged by: Verint CRM Connector	on: 01/07/2025 15:27
Service: Roads General	Subject: Traffic Sign:Defective/Damaged	Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type unlit Sign is starting to fall down. This is the one on the eastbound carriageway just before the roundabout at Saughton Road/Longstone Road		
Location: Calder Road before Longstone roundabout eastbound		Contact:
Enquiry No.: 1955233	Logged by: [REDACTED]	on: 29/05/2025 11:08
Service: Roads General	Subject: Street Furniture: Defective	Classification: Request for service
Desc.: Dangerous very large sheet of metal around 2 x 3 feet in size and very noisy when cars driving over this ..cars swerving round this too...i phoned this to [REDACTED] on standby roads sheet		
Location: Lady from kitchen window back of house looking on to calder road/renault garage heading west and also close to bankhead/sighthill roundabout		Contact:
Enquiry No.: 1943199	Logged by: [REDACTED]	on: 05/05/2025 08:31
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Large pothole		
Location:		Contact:
Enquiry No.: 1922589	Logged by: Verint CRM Connector	on: 24/03/2025 08:23
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Police Scotland - [REDACTED] refers. Informant advised that damage has been caused to a traffic island at this round about. The damage was caused by a vehicle, and unconfirmed if the traffic island is still standing.		Contact:
Plot Number: 4.00	Feature Id - Location: Ward 7 - Various remote footpaths through underpasses beneath	
Feature Type: Road Asset		
Enquiry No.: 1888198	Logged by: Verint CRM Connector	on: 17/01/2025 10:32
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: on Calder Road roundabout just before the Edinburgh bound / east bound exit. To avoid them and likely wheel damage you need to go into lane 2. There is also a second pit hole just after you exit the roundabout going eastbound on the Calder Road. This is also in lane 1.		Contact:
Plot Number: 4.00	Feature Id - Location: Ward 7 - Various remote footpaths through underpasses beneath	
Feature Type: Road Asset		

Effective: 16/08/2023 to 15/08/2025

Service: Roads General

Site: Calder Road (7906096)

Asset Number: 4.00 to 4.00

Display Action Officer: No

Customer Services

Enquiry No.: 1877702	Logged by: Verint CRM Connector	on: 01/01/2025 14:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Massive pothole on roundabout at Saughton Road North on slip.	Contact:	
Plot Number: 4.00	Feature Id - Location: Ward 7 - Various remote footpaths through underpasses beneath	Feature Type: Road Asset
Enquiry No.: 1869178	Logged by: Verint CRM Connector	on: 09/12/2024 21:23
Service: Roads General	Subject: Road: Missing Setts / Blocks	Classification: Customer Emergency
Desc.:		
Location: Big pothole on roundabout When entering roundabout from saughton road	Contact:	
Plot Number: 4.00	Feature Id - Location: Ward 7 - Various remote footpaths through underpasses beneath	Feature Type: Road Asset
Enquiry No.: 1838577	Logged by: Verint CRM Connector	on: 30/09/2024 21:04
Service: Roads General	Subject: Road Markings: General Enquiry	Classification: Request for service
Desc.:		
Location: This is a general comment about road marking on Edinburgh roads. On Sunday night, after dark, I came towards my home in Greenbank mainly via B701 and Calder Rd. Coming upon several roundabouts, I find that in many instances the lane markings and labeling were missing to the extent as to be nearly useless. This makes conditions dangerous - especially at night and especially for drivers not familiar with the roads (independent of whether they have Sat Nav). Please spend some money on Paint-Please.	Contact:	
Enquiry No.: 1832132	Logged by: Verint CRM Connector	on: 15/09/2024 16:36
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: South west entrance to subway down slope side, corner where you turn from slope into tunnel. Approx 3ft by 3ft break up of concrete. Large chunks. Trip hazard	Contact:	
Plot Number: 4.00	Feature Id - Location: Ward 7 - Various remote footpaths through underpasses beneath	Feature Type: Road Asset
Job Number: 50166878	Defect Number: 42165267	
Enquiry No.: 1801760	Logged by: Verint CRM Connector	on: 19/07/2024 21:12
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Very deep pothole,in the inside lane, adjacent to the shops. You will definitely know,when you hit it,as it jars the car,as well as the driver and passengers.	Contact:	
Plot Number: 4.00	Feature Id - Location: Ward 7 - Various remote footpaths through underpasses beneath	Feature Type: Road Asset
Enquiry No.: 1749340	Logged by:	on: 07/05/2024 09:35
Service: Roads General	Subject: Street Furniture: Defective	Classification: Request for service
Desc.: outside the men have put 1 bollard at house they wanted to put 2 but would not get out drive please dont come back and put in another		
Location: outside the men have put 1 bollard at house they wanted to put 2 but would not get out drive please dont come back and put in another	Contact:	

Effective: 16/08/2023 to 15/08/2025

Service: Roads General

Site: Calder Road (7906096)

Asset Number: 4.00 to 4.00

Display Action Officer: No

Customer Services

Enquiry No.: 1738723 Logged by: [REDACTED] on: 18/04/2024 10:20

Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service

Desc.: customer has advised the tree outside [REDACTED] home has been dead for years and it is now pulling up the pavement. [REDACTED]

Location: Outside [REDACTED] Contact:

Enquiry No.: 1711073 Logged by: Verint CRM Connector on: 03/03/2024 16:19

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: From 229 to 243 Calder Road centre seam split open with pot holes Contact:

Reported on behalf of Sighthill, Broomhouse & Parkhead Community Council

Enquiry No.: 1709386 Logged by: [REDACTED] on: 29/02/2024 12:28

Service: Roads General Subject: Street Furniture: Defective Classification: Request for service

Desc.: On calder road between hermiston park and ride roundabout and city bypass roundabout there is a traffic management sign and sandbags been left on the grass verge

Location: On calder road between hermiston park and ride roundabout and city bypass roundabout there is a traffic management sign and sandbags been left on the grass verge Contact:

Enquiry No.: 1699373 Logged by: Verint CRM Connector on: 14/02/2024 14:07

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: on slip road from whinpark clinic towards the city lots of pot holes to be filled in ASAP Contact:

Enquiry No.: 1674553 Logged by: Verint CRM Connector on: 09/01/2024 12:53

Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:

Location: from slip road at Finpark Clinic on calder road to turning onto Saughton Road north Contact:
- road full of potholes needing to be repaired before any major incidents - potholes
have been repaired on several occasions - inspect whole of the area as seems to
happen every other month

Effective: 16/08/2023 to 15/08/2025

Service: Roads General

Site: Calder Road (7906096)

Asset Number: 4.00 to 4.00

Display Action Officer: No

Customer Services

Enquiry No.: 1651268

Service: Roads General

Desc.: Hi

Logged by:

Subject: Roadworks: Defect

on: 27/11/2023 09:44

Classification: Request for service

Heading towards Saughton.

I saw your signs highlight no road markings but no signs regarding ramps.

My car has now been damaged going over the roundabout.

Suspension on the drivers side is impacted and burning coming from when I drive

Location - sighthill, Edinburgh, round a bout - heading towards saughton

Location: Sighthill roundabout

Contact:

Enquiry No.: 1649920

Service: Roads General

Desc.: Hi

Logged by:

Subject: Roadworks: General Enquiry

on: 24/11/2023 09:01

Classification: General Enquiry

I wish to make a formal complaint.

On the 6th November roadworks going on right outside my bedroom window at 3am

This work was not communicated to any of the residents

Many thanks

Contact:

Effective: 16/08/2023 to 15/08/2025
Service: Roads General
Site: Calder Road (7906096)

Asset Number: 4.00 to 4.00
Display Action Officer: No

Customer Services

Enquiry No.: 1649649 Service: Roads General Desc.: Location: Near 189 Calder Road. There is a tree that has over rooted and made the pavement a DANGEROUS level and gradient. It is ruining the passageway for all pedestrians including children, elderly and people with disabilities with walking and wheelchair users. Many years as this tree has grown it is now at a stage where injury claims WILL be submitted. Needs removed and ground made level. This message has been recorded. Thanks.	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 23/11/2023 16:59 Classification: Request for service Contact:
Enquiry No.: 1638257 Service: Roads General Desc.: Various potholes Location: Broomhouse roundabout	Logged by: Subject: Road: Defective / Damaged	on: 03/11/2023 14:03 Classification: Request for service Contact:
Enquiry No.: 1636757 Service: Roads General Desc.: please see document attached thanks Very large pothole here heading eastbound Category: Potholes Very large pothole here heading eastbound Location: Easting/Northing: 320003/670825 (55.923826, -3.281723) Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): Calder Road, Sighthill, Broomhouse and Parkhead, City of Edinburgh, Alba / Scotland, EH11 3TA, United Kingdom Nearest postcode to the pin placed on the map (automatically generated): EH11 4AL (65m away) Location: please see document attached thanks Very large pothole here heading eastbound Category: Potholes Very large pothole here heading eastbound Location: Easting/Northing: 320003/670825 (55.923826, -3.281723) Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): Calder Road, Sighthill, Broomhouse and Parkhead, City of Edinburgh, Alba / Scotland, EH11 3TA, United Kingdom Nearest postcode to the pin placed on the map (automatically generated): EH11 4AL (65m away)	Logged by: Subject: Road: Defective / Damaged	on: 01/11/2023 13:27 Classification: Request for service Contact:
Enquiry No.: 1613587 Service: Roads General Desc.: Location: Never saw the hole just felt the bang.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 13/09/2023 16:16 Classification: Request for service Contact:
Plot Number: 4.00	Feature Id - Location: Ward 7 - Various remote footpaths through underpasses beneath	Feature Type: Road Asset

Effective: 16/08/2023 to 15/08/2025

Service: Roads General

Site: Calder Road (7906096)

Asset Number: 4.00 to 4.00

Display Action Officer: No

Customer Services

Enquiry No.: 1598893

Service: Roads General

Desc.:

Logged by: Verint CRM Connector

Subject: Road: Missing Setts / Blocks

on: 16/08/2023 16:24

Classification: Customer Emergency

Location: A large block from the roundabout has come loose and is lying proud of the edge. A previous one was removed so now there are 2 missing from the edge.

Contact:

Plot Number: 4.00

Feature Id - Location: Ward 7 - Various remote footpaths through underpasses beneath

Feature Type: Road Asset

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 4.00		Asset - Locn.: Ward 7 - Various remote footpaths through underpasses beneat			Feature Type: Road Asset		Area: South West Locality
50154197	New cover required trip hazard (RD: FW Cover Make Safe)	At entrance to underpass	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/02/2024	11/09/2024	Act. ROAD/82088214
50154205	Rocking slab (RD: FW Slabs Rocking)	At half way point in underpass	RD: Cat 3 - 60 Day	Job Complete	27/02/2024	21/03/2024	Act. ROAD/82088220
50154212	Broken fw (RD: FW Grano Cracked/Broken)	At railings	RD: Cat 4 - Programmed	Job Committed	27/02/2024		ROAD/82117387
50166878	Repair damaged grano (RD: FW Grano Cracked/Broken)	Exit at Longstone Road	RD: Cat 3 - 60 Day	Job Complete	23/09/2024	24/09/2024	Act. ROAD/82096460
50175958	Broken slab (RD: FW Slabs Broken/Missing)	In underpass	RD: Cat 3 - 60 Day	Job Complete	26/02/2025	07/03/2025	Act. ROAD/82103228
50175962	Pothole (RD: FW Grano Pothole)	Near lamppost 82A	RD: Cat 3 - 60 Day	Job Complete	26/02/2025	06/03/2025	Act. ROAD/82103232
50175972	Pothole (RD: FW Grano Pothole)	Broken up potholed walkway	RD: Cat 3 - 60 Day	Job Complete	26/02/2025	12/03/2025	Act. ROAD/82103242
50175980	Broken brander needs replaced (RD: Gully Damaged/Sunken)	At underpass entrance	RD: Cat 3 - 60 Day	Job Complete	26/02/2025	14/03/2025	Act. ROAD/82103248