

Site History Report

Effective: 15/03/2026 to 22/03/2026

Asset Number: 1.00 to 1.00

Display Action Officer: No

Site: A90 - Cramond Bridge to Dalmeny (7906082)

Site: A90 - Cramond Bridge to Dalmeny (7906082)

Locality: South Queensferry, Edinburgh, City of Edinburgh

Area: North West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street except cyclepath/footpath		Feature Type: Road Asset		Area: North West Locality		
Batch:	41258882 - Inspection Batch			Route: Mobile Inspection Strategic			Date: 22/03/2026	
No actionable defects found								
Batch:	41258715 - Inspection Batch			Route: Ad hoc Route			Date: 20/03/2026	
42202568	1 number pothole	20/03/2026	Before gantry heading north	RD: CW Pothole	Internal		Committed	50194244
Batch:	41258495 - Inspection Batch			Route: Ad hoc Route			Date: 18/03/2026	
42202393	1 number pothole	18/03/2026	About 50m from entrance to Miller & Carter	RD: CW Pothole	Internal		Committed	50194126
Batch:	41258490 - Inspection Batch			Route: Ad hoc Route			Date: 18/03/2026	
42202389	1 number pothole	18/03/2026	Bottom of slip road on A90 heading towards Barnton	RD: CW Pothole	Internal		Committed	50194122
Batch:	41258080 - Inspection Batch			Route: Mobile Inspection Strategic			Date: 15/03/2026	
42202059	1 no pothole	15/03/2026	Southbound lane next to bus priority sign	RD: CW Pothole	Internal		Committed	50193890
42202060	1 no pothole	15/03/2026	Northbound lane under sign gantry Excuse photo there is a pothole at the location	RD: CW Pothole	Internal		Committed	50193891

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Whole Street except cyclepath/footpath		Feature Type: Road Asset		Area: North West Locality	
50176954	Replace missing and damaged anti glare bollards (RD: Bollard Damage/Missing/New)	Central reservation at slip road to Kirkliston	RD: Cat 3 - 60 Day	Job Committed	14/03/2025	06/06/2025	Est. ROAD/82104024
50193890	1 no pothole (RD: CW Pothole)	Southbound lane next to bus priority sign	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/03/2026	15/03/2026	Act. ROAD/82116090
50193891	1 no pothole (RD: CW Pothole)	Northbound lane under sign gantry Excuse photo there is a pothole at the location	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/03/2026	18/03/2026	Act. ROAD/82116091
50194122	1 number pothole (RD: CW Pothole)	Bottom of slip road on A90 heading towards Barnton	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/03/2026	31/03/2026	Act. ROAD/82116275
50194126	1 number pothole (RD: CW Pothole)	About 50m from entrance to Miller & Carter	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	18/03/2026	21/03/2026	Act. ROAD/82116279
50194244	1 number pothole (RD: CW Pothole)	Before gantry heading north	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	20/03/2026	21/03/2026	Act. ROAD/82116365