

Environmental & Consumer Services Department

Noise measurement Report

DATE: 1/7/25
TIME: 21.30

LOCATION:

COMPLAINT DETAILS:

30-32 Clerk St

METER TYPE:

B+k 2250

METER SERIAL NUMBER:

4231 2463824

MEASURING POSITION:

Bedroom 1st floor

WEATHER CONDITIONS:

13.13°C
Overcast, roads damp
light wind from ENE
25 mph, dry

FREQUENCY (Hz)	(1)	(2)	(3)	(4)	(5)	(6)	NR 20	NR 25	NR 30
31.5	42.2	45.1	41.1	42.8			69	72	76
63	34.7	36.2	36.2	36.9			51	55	59
125	38.5	34.6	40.1	40.0			39	44	48
250	28.3	24.9	27.0	28.1			31	35	40
500	24.4	22.6	27.6	27.6			24	29	34
1000	20.4	21.5	23.6	23.7			20	25	30
2000	16.7	17.2	18.4	18.3			17	22	27
4000	14.0	14.7	14.3	13.8			14	20	25
8000	13.3	14.0	13.8	14.6			13	18	23
A	27.8	26.7	29.3	29.5					
LIN	49.8	54.9	49.9	51.7					

- 1) Bkg
- 2) apply pen
- 3) Ext. activity highest 80% used. 33.8 + supply
- 4) Everything except a/c

DETAILS:

calibration check start = 93.8dB and = 93.9dB

Business has 2 external extract duct supply fan = appeared as though it x 1 a/c unit may be the noisiest x 1 small basement extract fan when it was quite noisy — dead outside

OFFICERS PRESENT:

- 1) Music from pub - loud bass
- 2) Couldn't really hear - no music so more like a bkg
- 3) - 1 confirmed. recorded how it sounds, is - no music