

Site History Report

Effective: 12/04/2023 to 12/04/2024
Service: Roads General
Site: Rankeillor Street (7902119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Site: Rankeillor Street (7902119)

Locality: Newington, Edinburgh, City of Edinburgh

Area: South East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	South East Locality
Batch:	41167426 - Inspection Batch			Route:	Ad hoc Route			Date: 02/10/2023
42136891	Cw x3 potholes Road: Defective / Damaged (Enquiry 1620735)	02/10/2023	Outside of number 8	RD: CW Pothole	Internal		Committed	50143405
Batch:	41163393 - Inspection Batch			Route:	SE_CF2_NewingtonNorth1			Date: 22/08/2023
42134582	Refresh all markings	22/08/2023	Entire cw including all junctions safety markings etc	RD: Markings Refresh	Internal		No Action Required	
42134583	Broken cw	22/08/2023	Outside 28	RD: CW Cracked/Broken	Internal		No Action Required	
Batch:	41155408 - Inspection Batch			Route:	Ad hoc Route			Date: 24/04/2023
42125820	Cw x1 pothole	24/04/2023	Outside of number 33	RD: CW Pothole	Internal		Committed	50134805
Batch:	41155407 - Inspection Batch			Route:	Ad hoc Route			Date: 24/04/2023
42125819	Cw x 2 potholes Road: Defective / Damaged (Enquiry 1540609)	24/04/2023	Outside of number 28	RD: CW Pothole	Internal		Committed	50134804

Customer Services

Enquiry No.: 1702039 **Logged by:** [REDACTED] **on:** 19/02/2024 08:52
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Multiple potholes along the entire road
Location: Rankeillor Street **Contact:**

Enquiry No.: 1620735 **Logged by:** Verint CRM Connector **on:** 29/09/2023 09:17
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Hi, I've recently noticed that a lot of streets in Edinburgh that are a shared road between cars and cyclists, and typically a continuation of a cycle track, are in a really bad state. Rankeillor St. is particularly bad, crisscrossed with repairs, I literally need a hip and knee replacement after cycling down that one. Gifford Park and Brunswick Street are other examples
Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50143405 **Defect Number:** 42136891

Enquiry No.: 1607829 **Logged by:** Verint CRM Connector **on:** 02/09/2023 19:20
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: Overgrown hedge taking up approx 1/3 of pavement space **Contact:**

Site History Report

Effective: 12/04/2023 to 12/04/2024
Service: Roads General
Site: Rankeillor Street (7902119)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1599012 **Logged by:** Verint CRM Connector **on:** 16/08/2023 18:51
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
 Location:Footpath.
 Type:Foliage / Bush
Location: Several of the properties on the odd-numbered side of Rankeillor Street have hedges in the front garden which are badly overgrown and taking up space on the pavement. This is forcing pedestrians into the road. **Contact:**

Enquiry No.: 1598112 **Logged by:** Verint CRM Connector **on:** 15/08/2023 15:35
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
 Location:Pavement.
 Type:Foliage / Bush
Location: Overhanging hedges on north side of Rankeillor st **Contact:**

Enquiry No.: 1595144 **Logged by:** Verint CRM Connector **on:** 09/08/2023 17:09
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Overhanging foliage >50 CM. Half of path occluded. 5 Rankeillor street. EH8 9JA **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1540609 **Logged by:** Verint CRM Connector **on:** 21/04/2023 09:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The street is full of holes; part of a busy cycle way scheme and bikes are swerving all over to avoid the holes. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50134804 **Defect Number:** 42125819

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50134804	Cw x 2 potholes Road: Defective / Damaged (Enquiry 1540609) (RD: CW Pothole)	Outside of number 28	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/04/2023	24/04/2023	Act. ROAD/82076190
50134805	Cw x1 pothole (RD: CW Pothole)	Outside of number 33	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/04/2023	24/04/2023	Act. ROAD/82076191
50143405	Cw x3 potholes Road: Defective / Damaged (Enquiry 1620735) (RD: CW Pothole)	Outside of number 8	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/10/2023	03/10/2023	Act. ROAD/82081178