

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Site: Gorgie Road (7902864)

Locality: Gorgie, Edinburgh, City of Edinburgh

Area: South West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 7 - Ardmillan Terrace to Stenhouse Drive	Feature Type:	Road Asset		Area:	South West Locality
Batch:	41237005 - Inspection Batch			Route:	Ad hoc Route			Date: 20/09/2025
42190135	Noisy BT manhole cover	20/09/2025	Outside 8	RU: Utility Apparatus	Internal		Uncommitted	50184916
Batch:	41236815 - Inspection Batch			Route:	SW_FW1_Gorgie			Date: 16/09/2025
42189993	Relay 4 sunken slabs	16/09/2025	Outside murshid & co accountants	RD: FW Slabs Rocking	Internal		Committed	50184832
Batch:	41236555 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 11/09/2025
	No actionable defects found							
Batch:	41235781 - Inspection Batch			Route:	Ad hoc Route			Date: 01/09/2025
42189347	Loose pole and damaged 20mph sign with stickers	01/09/2025	Outside 18	TS: Sign Pole Loose	Internal		Committed	50184326
Batch:	41234833 - Inspection Batch			Route:	SW_FW1_Gorgie			Date: 18/08/2025
42188567	Renew grano at catv box	18/08/2025	Outside christines	RD: FW Grano Cracked/Broken	Internal		Committed	50183682
42188575	x2 rocking slabs	18/08/2025	Outside good food	RD: FW Slabs Rocking	Internal		Committed	50183690
42188579	Renew grano around double manhole							
42188579	Remove marked cut slabs and replace with grano	18/08/2025	Outside aquatic shop	RD: FW Slabs Rocking	Internal		Committed	50183694
	Relay marked 900 slab with cross cut as marked to suit existing height							
42188576	1 rocking slab	18/08/2025	Outside baguette express	RD: FW Slabs Rocking	Internal		Committed	50183691
42188566	Relay x3 marked slabs	18/08/2025	Outside pepes	RD: FW Slabs Broken/Missing	Internal		Committed	50183681
	Replace broken 400x400							
	Renew grano around manhole							
42188564	Road island damaged in accident	18/08/2025	Outside pure gym on Gorgie road	RD: Railing Damage/Missing/New	Internal		Committed	50180296
	Renew 3xrail/safety barriers							
Batch:	41234404 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 11/08/2025
	No actionable defects found							
Batch:	41234275 - Inspection Batch			Route:	Ad hoc Route			Date: 07/08/2025
42188235	2x double sky manhole covers sunken loose and noisy	07/08/2025	On Gorgie road at junction with Mcleod Street.	RU: Utility Apparatus	Internal		Uncommitted	50183459
Batch:	41234239 - Inspection Batch			Route:	Ad hoc Route			Date: 06/08/2025
42188201	Bt phone box has been damaged	06/08/2025	Outside the polish shop 364 Gorgie road on footway	RU: Utility Apparatus	Internal		Uncommitted	50183441
Batch:	41234165 - Inspection Batch			Route:	Ad hoc Route			Date: 05/08/2025
42188099	Road surface cracked and broken	05/08/2025	at junct with Dalry Road	RD: CW Cracked/Broken	Internal		Uncommitted	50183375
Batch:	41233683 - Inspection Batch			Route:	Ad hoc Route			Date: 24/07/2025
42187668	4nr PCC flags to be replaced (900x600)(450x600) cutting required around ironwork.	24/07/2025	Outside 144	RD: FW Slabs Broken/Missing	Internal		Uncommitted	50153745

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 7 - Ardmillan Terrace to Stenhouse Drive		Feature Type: Road Asset		Area: South West Locality		
Batch: 41233322 - Inspection Batch			Route: Ad hoc Route			Date: 18/07/2025		
42187368	Pothole	18/07/2025	at bus stop	RD: CW Pothole	Internal		Committed	50182876
Batch: 41233058 - Inspection Batch			Route: Ad hoc Route			Date: 16/07/2025		
42187148	Steel plate sunken and moving please take away and renew manhole/double manhole	16/07/2025	Outside 398 spice of Asia shop	RU: Utility Apparatus	Internal		Uncommitted	50182735
Batch: 41233013 - Inspection Batch			Route: SW_FW1_Dalry1			Date: 15/07/2025		
No actionable defects found								
Batch: 41232790 - Inspection Batch			Route: Ad hoc Route			Date: 11/07/2025		
42186929	Pothole over over utility defect as it's not been picked up yet as it's on the crossing.	11/07/2025	At crossing at rail bridge	RD: CW Pothole	Internal		Committed	50182596
Batch: 41232744 - Inspection Batch			Route: South Mobile Inspection Route			Date: 11/07/2025		
No actionable defects found								
Batch: 41232032 - Inspection Batch			Route: Ad hoc Route			Date: 01/07/2025		
42186312	Large patch needing overlaid in areas	01/07/2025	Outside the flats next to gym	RD: CW Pothole	Internal		Committed	50182160
Batch: 41231895 - Inspection Batch			Route: Ad hoc Route			Date: 27/06/2025		
42186232	Cracked and broken carriageway	27/06/2025	Gorgie Road opposite junction with McLeod Street.	RD: CW Cracked/Broken	Internal		Uncommitted	50182087
Batch: 41231893 - Inspection Batch			Route: Ad hoc Route			Date: 27/06/2025		
42186230	Sunken and noisy bt manhole	27/06/2025	Outside Gorgie laundrette	RU: Utility Apparatus	Internal		Uncommitted	50182085
Batch: 41231890 - Inspection Batch			Route: Ad hoc Route			Date: 27/06/2025		
42186227	Sunken gully Renew sunken gully and infill around with hra	27/06/2025	Outside McLaren's murdoch and Hamilton on carriageway	RD: Gully Damaged/Sunken	Internal		Uncommitted	50182082
Batch: 41231889 - Inspection Batch			Route: Ad hoc Route			Date: 27/06/2025		
42186226	Double bt manhole loose and noisy on carriageway	27/06/2025	Coming off balgreen left to Gorgie road at mclaren murdoch and hamilton	RU: Utility Apparatus	Internal		Uncommitted	50182081
Batch: 41231729 - Inspection Batch			Route: Ad hoc Route			Date: 25/06/2025		
42186102	Bollard loose Reset bollard 1x (no damage to bollard) reuse Reset small granite blocks around bollard 10 or 11	25/06/2025	On wardlaw street ar corner of Gorgie Road	RD: Bollard Damage/Missing/Neve	Internal		Committed	50181966
Batch: 41231521 - Inspection Batch			Route: Ad hoc Route			Date: 23/06/2025		
42185951	Replace and cut to size 4x 600x900 Reset 1 x rocking slab	23/06/2025	Outside 106 Gorgie Road hair art by Eva	RD: FW Slabs Broken/Missing	Internal		Committed	50181788
Batch: 41231061 - Inspection Batch			Route: Ad hoc Route			Date: 16/06/2025		
42185645	Pothole	16/06/2025	Outside 109 on crossing	RD: CW Pothole	Internal		Committed	50181517

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 7 - Ardmillan Terrace to Stenhouse Drive		Feature Type: Road Asset		Area: South West Locality		
Batch: 41231053 - Inspection Batch			Route: Ad hoc Route			Date: 16/06/2025		
42185640	Grano pothole repair needed at manhole on footway (existing grano still in pothole)	16/06/2025	Outside 320 just before rail bridge	RD: FW Grano Pothole	Internal		Committed	50181512
Batch: 41231035 - Inspection Batch			Route: Ad hoc Route			Date: 16/06/2025		
42185625	Small double manhole on footway broken and rocking (walkboard placed over it)	16/06/2025	outside the Salvation Army on footway	RU: Utility Apparatus	Internal		Uncommitted	50181497
Batch: 41230907 - Inspection Batch			Route: SW_FW1_Dalry1			Date: 16/06/2025		
42185574	3no rocking slabs	13/06/2025	Opposite Orwell Terrace	RD: FW Slabs Rocking	Internal		No Action Required	
42185577	9no rocking tactile slabs	13/06/2025	At Dalry gait	RD: FW Slabs Rocking	Internal		No Action Required	
42185575	Renew grano surround approx 1m	13/06/2025	At side of bus stop next to British heart foundation	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42185593	3no rocking slabs	13/06/2025	Opposite Orwell Terrace	RD: FW Slabs Rocking	Internal		Committed	50181417
42185563	Replace broken grano approx 0.2x0.4 1no broken 600x900 pcc slab 1no rocking 600x600 pcc slab	13/06/2025	Outside 320	RD: FW Grano Cracked/Broken	Internal		Committed	50181394
42185572	2no broken 400x400 tactile slabs 3no rocking 400x400 tactile slabs	13/06/2025	At Cathcart place	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42185571	1no rocking slab	13/06/2025	Approx 10m east of Murieston crescent lane	RD: FW Slabs Rocking	Internal		No Action Required	
42185591	3no rocking slabs	13/06/2025	Opposite Orwell Terrace	RD: FW Slabs Rocking	Internal		No Action Required	
42185597	1no rocking slab	13/06/2025	Approx 10m east of Murieston crescent lane	RD: FW Slabs Rocking	Internal		Committed	50181402
42185565	7no rocking slabs	13/06/2025	Outside 296	RD: FW Slabs Rocking	Internal		Committed	50181396
42185595	2no broken 400x400 tactile slabs 3no rocking 400x400 tactile slabs	13/06/2025	At Cathcart place	RD: FW Slabs Broken/Missing	Internal		Committed	50181403
42185604	9no rocking tactile slabs	13/06/2025	At Dalry gait	RD: FW Slabs Rocking	Internal		Committed	50181408
42185569	1no rocking slab	13/06/2025	Behind bus stop at Smithfield st	RD: FW Slabs Rocking	Internal		Committed	50181400
42185573	Renew grano surround	13/06/2025	Outside co-op	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42185568	1no broken 600x900 pcc slab	13/06/2025	Outside Hospices of hope	RD: FW Slabs Broken/Missing	Internal		Committed	50181399
42185590	Renew grano surround	13/06/2025	Outside co-op	RD: FW Grano Cracked/Broken	Internal		Committed	50181404
42185576	Renew grano surround	13/06/2025	Outside Locanda de gusti	RD: FW Grano Cracked/Broken	Internal		No Action Required	
42185586	Renew grano surround approx 1m	13/06/2025	At side of bus stop next to British heart foundation	RD: FW Grano Cracked/Broken	Internal		Committed	50181406
42185561	2no rocking cut slabs	13/06/2025	Outside Brass	RD: FW Slabs Rocking	Internal		Committed	50181392
42185589	3no rocking slabs	13/06/2025	Opposite Orwell Terrace	RD: FW Slabs Rocking	Internal		Committed	50181405
42185559	1no f/w pothole	13/06/2025	Outside Four Square	RD: FW HRA Pothole	Internal		Committed	50181390
42185566	3no rocking 600x900 slabs 1no broken 600x900 slab	13/06/2025	Outside 266	RD: FW Slabs Rocking	Internal		Committed	50181397
42185607	Manhole on footway collapsed. Made safe with cones.	13/06/2025	Outside The Salvation Army	RU: Utility Apparatus	Internal		Uncommitted	50181429
42185582	Renew grano surround	13/06/2025	Outside Locanda de gusti	RD: FW Grano Cracked/Broken	Internal		Committed	50181407

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 7 - Ardmillan Terrace to Stenhouse Drive		Feature Type: Road Asset		Area: South West Locality		
Batch:	41230843 - Inspection Batch			Route: Ad hoc Route		Date: 12/06/2025		
42185509	Carriageway cracked and broken	12/06/2025	At bus stop outside gym	RD: CW Cracked/Broken	Internal		Uncommitted	50181295
Batch:	41230302 - Inspection Batch			Route: Ad hoc Route		Date: 06/06/2025		
42185173	Carriageway cracked and broken	06/06/2025	Outside the flats at the gym	RD: CW Cracked/Broken	Internal		Uncommitted	50181051
Batch:	41230107 - Inspection Batch			Route: South Mobile Inspection Route		Date: 05/06/2025		
No actionable defects found								
Batch:	41229478 - Inspection Batch			Route: Ad hoc Route		Date: 28/05/2025		
42184529	Reinstate loose Radius kerb and infill behind with hra.	28/05/2025	At the junction of Gorgie road and Robertson avenue	RD: FW Kerb Dislodged/Rocking	Internal		Committed	50180530
Batch:	41229440 - Inspection Batch			Route: Ad hoc Route		Date: 28/05/2025		
42184468	Vodafone double concrete manhole broken	28/05/2025	Outside 351 on footway	RU: Utility Apparatus	Internal		Uncommitted	50180501
Batch:	41229054 - Inspection Batch			Route: Ad hoc Route		Date: 23/05/2025		
42184136	Road island damaged in accident Renew 3xrail/safety barriers	23/05/2025	Outside pure gym on Gorgie road	RD: Railing Damage/Missing/New	Internal		No Action Required	
Batch:	41228825 - Inspection Batch			Route: Ad hoc Route		Date: 21/05/2025		
42183968	Scottish water tobys raised above footway	21/05/2025	Outside 12 on footway	RU: Utility Apparatus	Internal		Uncommitted	50180192
Batch:	41228822 - Inspection Batch			Route: Ad hoc Route		Date: 21/05/2025		
42183965	Manhole sinking making footway uneven	21/05/2025	Outside 18 on footway	RU: Utility Apparatus	Internal		Uncommitted	50180189
Batch:	41228821 - Inspection Batch			Route: Ad hoc Route		Date: 21/05/2025		
42183964	At gas Toby on fw	21/05/2025	.outside 12	RD: FW Grano Pothole	Internal		Committed	50180188
Batch:	41228813 - Inspection Batch			Route: Ad hoc Route		Date: 21/05/2025		
42183956	Cracked carriageway surface	21/05/2025	Outside 140	RD: CW Cracked/Broken	Internal		Uncommitted	50180182
Batch:	41228769 - Inspection Batch			Route: Ad hoc Route		Date: 20/05/2025		
42183919	Cracked/broken carriageway in the pedestrian crossing	20/05/2025	West bound lane just before the bridge	RD: CW Cracked/Broken	Internal		Uncommitted	50180152
Batch:	41228620 - Inspection Batch			Route: Ad hoc Route		Date: 19/05/2025		
42183797	Remove Gorgie city farm signs from from signs pole as no longer required	19/05/2025	On footway outside old Gorgie city farm on signs pole	RD: Unlit Sign Damaged/Missing	Internal		Committed	50180080
Batch:	41228619 - Inspection Batch			Route: Ad hoc Route		Date: 19/05/2025		
42183796	Remove two Gorgie city farm signs from lamppost as no longer required	19/05/2025	On lamppost at Gorgie road outside Tynecastle school	RD: Unlit Sign Damaged/Missing	Internal		Committed	50180079
Batch:	41228617 - Inspection Batch			Route: Ad hoc Route		Date: 19/05/2025		
42183792	Turn 20mph speed limit roundal sign to face oncoming vehicle	19/05/2025	On footway outside Patisserie Adlai	RD: Unlit Sign Damaged/Missing	Internal		Committed	50180075
Batch:	41228614 - Inspection Batch			Route: Ad hoc Route		Date: 19/05/2025		
42183784	Turn 20mph & 30mph speed limit signs to face oncoming vehicles	19/05/2025	On footway outside Kaspas's desert shop	RD: Unlit Sign Damaged/Missing	Internal		Committed	50180072

Site History Report

Effective: 27/09/2024 to 27/09/2025
Service: Roads General
Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 7 - Ardmillan Terrace to Stenhouse Drive		Feature Type: Road Asset		Area: South West Locality		
Batch: 41228321 - Inspection Batch			Route: Ad hoc Route			Date: 15/05/2025		
42183548	Traffic Sign:Defective/Damaged - What type of sign is it? Road sign problem, type unlit Pole with 20mph speed limit sign on it is leaning. Also damage to the sign face of the 20mph sign as well. (Enquiry 1939531)	15/05/2025	Please remove existing 20mph sign and pole and replace with new as per attached sign design detail documents.	RD: Unlit Sign Damaged/Missing	Internal		Committed	50179939
Batch: 41227613 - Inspection Batch			Route: South Mobile Inspection Route			Date: 06/05/2025		
No actionable defects found								
Batch: 41227488 - Inspection Batch			Route: SW_FW1_Dalry1			Date: 05/05/2025		
No actionable defects found								
Batch: 41227277 - Inspection Batch			Route: Ad hoc Route			Date: 01/05/2025		
42182686	Manhole cover loose and noisy	01/05/2025	At traffic lights at the junction to balgreen road	RU: Utility Apparatus	Internal		Uncommitted	50179400
Batch: 41226085 - Inspection Batch			Route: Ad hoc Route			Date: 15/04/2025		
42181475	Toby low sunken on crossing	15/04/2025	At the rail bridge crossing in carriageway	RU: Utility Apparatus	Internal		Uncommitted	50178628
Batch: 41226080 - Inspection Batch			Route: Ad hoc Route			Date: 15/04/2025		
42181470	2x double manholes low and noisy- says Norwood telecom on them. Please see customer comments and attached photos	15/04/2025	Under the rail bridge in bus right turn lane	RU: Utility Apparatus	Internal		Uncommitted	50178623
Batch: 41225494 - Inspection Batch			Route: South Mobile Inspection Route			Date: 08/04/2025		
No actionable defects found								
Batch: 41225096 - Inspection Batch			Route: SW_FW1_Dalry1			Date: 03/04/2025		
42180646	Pothole	03/04/2025	Outside els house	RD: CW Pothole	Internal		Committed	50178137
42180647	Pothole	03/04/2025	Opposite 572 gorgie road	RD: CW Pothole	Internal		Committed	50178138
Batch: 41224448 - Inspection Batch			Route: Mobile Inspection Strategic			Date: 30/03/2025		
No actionable defects found								
Batch: 41223795 - Inspection Batch			Route: Mobile Inspection Strategic			Date: 22/03/2025		
No actionable defects found								
Batch: 41223178 - Inspection Batch			Route: Ad hoc Route			Date: 17/03/2025		
42178933	Pothole	17/03/2025	Just after junction of westfield road	RD: CW Pothole	Internal		Committed	50177096
Batch: 41223176 - Inspection Batch			Route: Ad hoc Route			Date: 17/03/2025		
42178931	Pothole	17/03/2025	At junction with Westfield street	RD: CW Pothole	Internal		Committed	50177095
Batch: 41223169 - Inspection Batch			Route: Ad hoc Route			Date: 17/03/2025		
42178917	Rocking and noisy manhole at pedestrian crossing in carriageway please see pictures	17/03/2025	At Traffic lights at VPZ shop road near to wardlaw place	RU: Utility Apparatus	Internal		Uncommitted	50177089

Site History Report

Effective: 27/09/2024 to 27/09/2025
 Service: Roads General
 Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 7 - Ardmillan Terrace to Stenhouse Drive		Feature Type: Road Asset		Area: South West Locality		
Batch: 41222868 - Inspection Batch				Route: Mobile Inspection Strategic			Date: 15/03/2025	
No actionable defects found								
Batch: 41222692 - Inspection Batch				Route: South Mobile Inspection Route			Date: 14/03/2025	
No actionable defects found								
Batch: 41221520 - Inspection Batch				Route: Mobile Inspection Strategic			Date: 05/03/2025	
No actionable defects found								
Batch: 41221318 - Inspection Batch				Route: SW_FW1_Dalry1			Date: 05/03/2025	
42177708	Pothole	04/03/2025	At junction with chesser avenue	RD: CW Pothole	Internal		Committed	50176322
42177709	Pothole	04/03/2025	Opposite 451 at bus stop	RD: CW Pothole	Internal		Committed	50176323
Batch: 41220873 - Inspection Batch				Route: Mobile Inspection Strategic			Date: 27/02/2025	
42177358	2no potholes at manhole	27/02/2025	At the bus stop at Smithfield Street	RD: CW Pothole	Internal		Committed	50176067
42177312	1no pothole	27/02/2025	At the junction with Chesser Avenue	RD: CW Pothole	Internal		Committed	50176042
42177399	4no potholes	27/02/2025	On the pedestrian crossing at the corner of Ardmillan Terrace	RD: CW Pothole	Internal		Committed	50176093
42177353	3no potholes	27/02/2025	At the bus stop opposite no451	RD: CW Pothole	Internal		Committed	50176064
Batch: 41220867 - Inspection Batch				Route: Ad hoc Route			Date: 27/02/2025	
42177307	Potholes around manhole	27/02/2025	At bus stop outside Salvation Army shop	RD: CW Pothole	Internal		Committed	50176037
Batch: 41220362 - Inspection Batch				Route: Ad hoc Route			Date: 24/02/2025	
42176866	Pothole	24/02/2025	Just before the crossroads pothole on city bound lane	RD: CW Pothole	Internal		Committed	50175754
Batch: 41220361 - Inspection Batch				Route: Ad hoc Route			Date: 24/02/2025	
42176865	Pothole	24/02/2025	On crossing outside McDonald's	RD: CW Pothole	Internal		Committed	50175753
Batch: 41219691 - Inspection Batch				Route: Ad hoc Route			Date: 19/02/2025	
42176490		19/02/2025	On Gorgie road city bound at the junction with stenhouse drive	RD: CW Pothole	Internal		Committed	50175451
Batch: 41219581 - Inspection Batch				Route: Mobile Inspection Strategic			Date: 19/02/2025	
No actionable defects found								
Batch: 41219540 - Inspection Batch				Route: Ad hoc Route			Date: 18/02/2025	
42176338	Damage to drainage Clay pipe causing subsidence on footway at manhole, made safe with walkboard. Please see photos.	18/02/2025	Outside Stratfords bar 227-229 Gorgie Road	RU: Utility Apparatus	Internal		Uncommitted	50175363
Batch: 41218590 - Inspection Batch				Route: South Mobile Inspection Route			Date: 11/02/2025	
No actionable defects found								
Batch: 41218514 - Inspection Batch				Route: Mobile Inspection Strategic			Date: 11/02/2025	
No actionable defects found								

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 7 - Ardmillan Terrace to Stenhouse Drive		Feature Type: Road Asset		Area: South West Locality		
Batch: 41217804 - Inspection Batch			Route: Ad hoc Route			Date: 06/02/2025		
42175150	Missing kerb renew kerb cut to size	06/02/2025	At speed camera	RD: FW Kerbs Damaged/Missing	Internal		Committed	50174428
Batch: 41217795 - Inspection Batch			Route: Ad hoc Route			Date: 06/02/2025		
42175144	2 potholes	06/02/2025	Outside flowers by mcDowell	RD: CW Pothole	Internal		Committed	50174423
Batch: 41217782 - Inspection Batch			Route: Ad hoc Route			Date: 06/02/2025		
42175135	Keep left weebol damaged	06/02/2025	Outside 355	RD: Weebol Damage/Missing/Ne	Internal		Committed	50174417
Renew keep left weebol								
Batch: 41217779 - Inspection Batch			Route: Ad hoc Route			Date: 06/02/2025		
42175134	Loose and noisy bt manhole on city bound carriageway	06/02/2025	Outside 352 Gorgie road	RU: Utility Apparatus	Internal		Uncommitted	50174416
Batch: 41217411 - Inspection Batch			Route: SW_FW1_Dalry1			Date: 04/02/2025		
42174820	Broken cracked cw at crossing	04/02/2025	Outside McDonald's at crossing	RD: CW Cracked/Broken	Internal		Uncommitted	50174175
42174816	Damaged weebol	04/02/2025	Outside 355	RD: Weebol Damage/Missing/Ne	Internal		Committed	50174172
42174818	Pothole	04/02/2025	Outside mcdonalds	RD: CW Pothole	Internal		Committed	50174173
Batch: 41217287 - Inspection Batch			Route: Ad hoc Route			Date: 03/02/2025		
42174701	Renew Broken 600x 900 pcc flag	03/02/2025	Opposite 158 gorgie road on footway	RD: FW Slabs Broken/Missing	Internal		Committed	50174095
Batch: 41216973 - Inspection Batch			Route: Mobile Inspection Strategic			Date: 30/01/2025		
42174503	1no pothole	30/01/2025	At the junction with Chesser Avenue	RD: CW Pothole	Internal		Committed	50173945
Batch: 41216487 - Inspection Batch			Route: Ad hoc Route			Date: 27/01/2025		
42174101	Renew frame and brander, rocking Sunken gully	27/01/2025	Outside bite & go	RD: Gully Damaged/Sunken	Internal		Committed	50173639
Batch: 41216457 - Inspection Batch			Route: Ad hoc Route			Date: 27/01/2025		
42174077	Previously inspected and raised as unknown however this is a sunken Virgin Media box (please see attached photos)	27/01/2025	At the pedestrian crossing on the footway at the corner with Murieston Road	RU: Utility Apparatus	Internal		Uncommitted	50173617
Batch: 41216033 - Inspection Batch			Route: Ad hoc Route			Date: 22/01/2025		
42173810	Bollard reversed into and pushing up the slabs and tactiles around it, bollard and tactiles, slabs need reset, bollard not removed from site as is reusable	22/01/2025	On footway outside Costa coffee	RD: Bollard Damage/Missing/Ne	Internal		Committed	50173427
Batch: 41215615 - Inspection Batch			Route: Mobile Inspection Strategic			Date: 20/01/2025		
No actionable defects found								
Batch: 41215022 - Inspection Batch			Route: Ad hoc Route			Date: 16/01/2025		
42173279	Sunken slabs round manhole cover on footway excavate investigate and reinstate	16/01/2025	Outside stratford pub	RD: FW Slabs Broken/Missing	Internal		Committed	50173024

Site History Report

Effective: 27/09/2024 to 27/09/2025
 Service: Roads General
 Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 7 - Ardmillan Terrace to Stenhouse Drive		Feature Type: Road Asset		Area: South West Locality		
Batch: 41214542 - Inspection Batch		Route: Ad hoc Route			Date: 14/01/2025			
42172944	Sunken utility cover on footway see attached photos	14/01/2025	On the footway at junction of dalry/Murieston road at tactiles	RU: Utility Apparatus	Internal		Uncommitted	50172783
Batch: 41214512 - Inspection Batch		Route: Ad hoc Route			Date: 14/01/2025			
42172937	Sunken cover on footway at tactiles	14/01/2025	On the footway crossing at Murieston Road/dalry junction	RU: Utility Apparatus	Internal		Uncommitted	50172786
Batch: 41214507 - Inspection Batch		Route: Ad hoc Route			Date: 14/01/2025			
42172930	Sunken utility cover on footway see attached photos	14/01/2025	On the footway at junction of dalry/Murieston road at ductiles	RU: Utility Apparatus	Internal		No Action Required	
Batch: 41213621 - Inspection Batch		Route: Ad hoc Route			Date: 09/01/2025			
42172602	Scottish water sunken slabbed area around manhole	09/01/2025	Outside Stratford bar	RU: Utility Apparatus	Internal		Uncommitted	50172546
Batch: 41213362 - Inspection Batch		Route: South Mobile Inspection Route			Date: 08/01/2025			
42172458	1no pothole	08/01/2025	At the bus stop at Smithfield Street	RD: CW Pothole	Internal		Committed	50172420
42172456	2no potholes	08/01/2025	At the junction with Fords Road	RD: CW Pothole	Internal		Committed	50172418
Batch: 41213225 - Inspection Batch		Route: SW_FW1_Dalry1			Date: 08/01/2025			
42172344	Pothole x 2	08/01/2025	At bus stop opposite 451	RD: CW Pothole	Internal		Committed	50172346
Batch: 41212942 - Inspection Batch		Route: Ad hoc Route			Date: 06/01/2025			
42172148	Renew broken 600x900 occ flag	06/01/2025	Behind bins at pin location	RD: FW Slabs Broken/Missing	Internal		Committed	50172189
Batch: 41212721 - Inspection Batch		Route: Ad hoc Route			Date: 03/01/2025			
42172026	Potholes	03/01/2025	In bus stop city bound lane	RD: CW Pothole	Internal		Committed	50172071
Batch: 41212706 - Inspection Batch		Route: Ad hoc Route			Date: 03/01/2025			
42172011	Pothole	03/01/2025	City bound lane at McDonald's traffic lights	RD: CW Pothole	Internal		Committed	50172056
Batch: 41212705 - Inspection Batch		Route: Ad hoc Route			Date: 03/01/2025			
42172010	Pothole	03/01/2025	City bound lane before bridge	RD: CW Pothole	Internal		Committed	50172055
Batch: 41211614 - Inspection Batch		Route: Ad hoc Route			Date: 20/12/2024			
42171645	Renew broken and rocking 600x900 pic flag	20/12/2024	Outside the koffee pot cafe	RD: FW Slabs Broken/Missing	Internal		Committed	50171741
Batch: 41211440 - Inspection Batch		Route: SW_FW1_Dalry1			Date: 18/12/2024			
42171507	Sunken cover, damaged surround	18/12/2024	Between 387 and 389	RU: Utility Apparatus	Internal		Uncommitted	50171631
42171505	Sunken cover, damaged surround	18/12/2024	Adjacent to 466 gorgie road	RU: Utility Apparatus	Internal		Uncommitted	50171630
Batch: 41210170 - Inspection Batch		Route: South Mobile Inspection Route			Date: 09/12/2024			
42170862	1no pothole	09/12/2024	At the bus stop opposite the Salvation Army	RD: CW Pothole	Internal		Committed	50171126
42170866	2no potholes	09/12/2024	At the bus stop at Smithfield Street	RD: CW Pothole	Internal		Committed	50171128
Batch: 41209732 - Inspection Batch		Route: Ad hoc Route			Date: 05/12/2024			
42170590		05/12/2024	Outside 501	RD: Gully Damaged/Sunken	Internal		Committed	50170899

Site History Report

Effective: 27/09/2024 to 27/09/2025
 Service: Roads General
 Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 7 - Ardmillan Terrace to Stenhouse Drive		Feature Type: Road Asset		Area: South West Locality		
Batch: 41209730 - Inspection Batch				Route: Ad hoc Route		Date: 05/12/2024		
42170586		05/12/2024	Outside 498	RD: Gully Damaged/Sunken	Internal		Committed	50170895
Batch: 41209728 - Inspection Batch				Route: Ad hoc Route		Date: 05/12/2024		
42170585		05/12/2024	Outsides Stevensons	RD: Gully Damaged/Sunken	Internal		Committed	50170894
Batch: 41209727 - Inspection Batch				Route: Ad hoc Route		Date: 05/12/2024		
42170584	Brander damaged	05/12/2024	Gorgie road @ped crossing	RD: Gully Damaged/Sunken	Internal		Committed	50170893
Batch: 41209716 - Inspection Batch				Route: Ad hoc Route		Date: 05/12/2024		
42170561	Traffic Sign:Defective/Damaged - What type of sign is it? Road sign problem, type lit. Issue : SL28. (Enquiry 1853001)	05/12/2024	At the junction with Robertson avenue. Please remove no right turn sign and supplemental plate and replace with new. Signs ordered and ready to collect from stores. Mounting height 2300mm	RD: Unlit Sign Damaged/Missing	Internal		Committed	50170874
Batch: 41208985 - Inspection Batch				Route: Ad hoc Route		Date: 28/11/2024		
42170100	Pothole around gully frame	28/11/2024	Outside 475	RD: CW Pothole	Internal		Committed	50170549
Batch: 41208796 - Inspection Batch				Route: Ad hoc Route		Date: 27/11/2024		
42169950	Sunken broken manhole cover in Cw possibly Scottish water	27/11/2024	Cw westbound lane under rail bridge Gorgie road .	RU: Utility Apparatus	Internal		Uncommitted	50170442
Batch: 41208580 - Inspection Batch				Route: Ad hoc Route		Date: 25/11/2024		
42169821	3 Broken and missing slabs also concrete needs redone around other manhole	25/11/2024	See pin location around catv box	RD: FW Slabs Broken/Missing	Internal		Committed	50170334
Batch: 41208354 - Inspection Batch				Route: SW_FW1_Dalry1		Date: 21/11/2024		
42169578	Sunken gully	21/11/2024	Opposite 501	RD: Gully Damaged/Sunken	Internal		Committed	50170144
Batch: 41207235 - Inspection Batch				Route: South Mobile Inspection Route		Date: 11/11/2024		
42168806	2no potholes	11/11/2024	At the bus stop opposite no451	RD: CW Pothole	Internal		Committed	50169580
Batch: 41206865 - Inspection Batch				Route: Ad hoc Route		Date: 07/11/2024		
42168592	Defective Scottish power cover on fw Photos attached	07/11/2024	Gorgie rd 256 at Smithfield st	RU: Utility Apparatus	Internal		Uncommitted	50169355
Batch: 41206187 - Inspection Batch				Route: Ad hoc Route		Date: 01/11/2024		
42168215	New frame and brander required	01/11/2024	Outside 580	RD: Gully Damaged/Sunken	Internal		Committed	50169075
Batch: 41206046 - Inspection Batch				Route: SW_FW1_Dalry1		Date: 31/10/2024		
No actionable defects found								
Batch: 41203907 - Inspection Batch				Route: Ad hoc Route		Date: 17/10/2024		
42166945	Damaged footway box	17/10/2024	Outside 256	RU: Utility Apparatus	Internal		Uncommitted	50168196
Batch: 41203038 - Inspection Batch				Route: SW_FW1_Dalry1		Date: 10/10/2024		
No actionable defects found								
Batch: 41202858 - Inspection Batch				Route: South Mobile Inspection Route		Date: 09/10/2024		
No actionable defects found								

Site History Report

Effective: 27/09/2024 to 27/09/2025
Service: Roads General
Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 7 - Ardmillan Terrace to Stenhouse Drive	Feature Type:	Road Asset		Area:	South West Locality
Batch:	41202554 - Inspection Batch			Route:	Ad hoc Route		Date:	07/10/2024
42166110	Cw x1 pothole Road: Defective / Damaged (Enquiry 1837828)	07/10/2024	Pedestrian crossing at the junction with Ardmillan Terrace	RD: CW Pothole	Internal		Committed	50167659

Customer Services

Enquiry No.:	34010085	Logged by:	[REDACTED]	on:	24/06/2025 13:36			
Service:	Roads General	Subject:	Street Furniture: Defective	Classification:	Request for service			
Desc.:	Please inspect damaged bollard at the Gorgie Road end of Wardlaw Terrace. please see pic attached.							
Location:	Gorgie Road	Contact:						
Plot Number:	1.00	Feature Id - Location:	Ward 7 - Ardmillan Terrace to Stenhouse Drive	Feature Type:	Road Asset			
Job Number:	50181966	Defect Number:	42186102					
Enquiry No.:	34010069	Logged by:	[REDACTED]	on:	20/06/2025 14:09			
Service:	Roads General	Subject:	Pavement: Damaged / Defective	Classification:	Request for service			
Desc.:	Gorgie Road, please inspect loose blocks o/s no 106 gorgie road .							
Location:	Gorgie Road	Contact:						
Plot Number:	1.00	Feature Id - Location:	Ward 7 - Ardmillan Terrace to Stenhouse Drive	Feature Type:	Road Asset			
Job Number:	50181788	Defect Number:	42185951					
Enquiry No.:	34010045	Logged by:	[REDACTED]	on:	16/06/2025 11:07			
Service:	Roads General	Subject:	Road: Defective / Damaged	Classification:	Request for service			
Desc.:	Please inspect water leak in the road/pavement on the eastbound carriageway of Gorgie Road under the bridge at the Robertson Ave/Wheatfield junction coming from the paving stones .							
Location:	Gorgie Road	Contact:						
Plot Number:	1.00	Feature Id - Location:	Ward 7 - Ardmillan Terrace to Stenhouse Drive	Feature Type:	Road Asset			
Enquiry No.:	34009939	Logged by:	[REDACTED]	on:	19/05/2025 12:21			
Service:	Roads General	Subject:	Road Markings: Defective	Classification:	Request for service			
Desc.:	Speed limit road markings need refreshed							
Location:	Faded speed limit road markings on road outside & opposite The Koffee pot							
Plot Number:	1.00	Feature Id - Location:	Ward 7 - Ardmillan Terrace to Stenhouse Drive	Feature Type:	Road Asset			
Job Number:	50185349	Defect Number:	42190807					
Enquiry No.:	34009938	Logged by:	[REDACTED]	on:	19/05/2025 12:05			
Service:	Roads General	Subject:	Road Markings: Defective	Classification:	Request for service			
Desc.:	Faded 20mph & 30mph road markings							
Location:	Faded road markings outside and opposite Kaspas' desert shop & Faded 20mph & 30mph road markings outside Stephanie Bayne							
Plot Number:	1.00	Feature Id - Location:	Ward 7 - Ardmillan Terrace to Stenhouse Drive	Feature Type:	Road Asset			
Job Number:	50185347	Defect Number:	42190806					

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 34009894

Logged by: [REDACTED]

on: 05/05/2025 12:51

Service: Roads General

Subject: Public Utilities: General

Classification: Request for service

Desc.: please inspect loose manhole cover Gorgie Road on the on the corner of Balgreen Road at the entrance to Saughton Park. Closest postcode is EH11 3AA..

Location: Gorgie Road

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive

Feature Type: Road Asset

Enquiry No.: 34009627

Logged by: [REDACTED]

on: 10/02/2025 12:48

Service: Roads General

Subject: Street Furniture: Defective

Classification: Request for service

Desc.: Road island keep left collapsed, already raised, made safe with keep left sign

Location: Outside 355

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive

Feature Type: Road Asset

Enquiry No.: 34009476

Logged by: [REDACTED]

on: 06/01/2025 13:16

Service: Roads General

Subject: Pavement: Damaged / Defective

Classification: Request for service

Desc.: Saughton Avenue, please inspect broken slab tripping hazard. please see pic attached.

Location: Saughton Avenue

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive

Feature Type: Road Asset

Job Number: 50172189

Defect Number: 42172148

Enquiry No.: 31603573

Logged by: [REDACTED]

on: 15/05/2025 20:47

Service: Roads General

Subject: Traffic Sign:Defective/Damaged

Classification: Request for service

Desc.: Please log on confirm for inspector to visit Gorgie Road between Alaxander Drive and its junction with Dalry Road and check the intervals of - 20mph repeaters, check double sided and are approx. 100m apart on alternative sides of the road. Please email [REDACTED] update on outcome of site visit.

Location:

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive

Feature Type: Road Asset

Job Number: 50180072

Defect Number: 42183784

Enquiry No.: 2015262

Logged by: Verint CRM Connector

on: 17/09/2025 08:47

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Desc.:

Location: loose manhole cover at traffic lights, in the middle of bicycle section on Gorgie Road on the same side as number 12 Gorgie Road

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive

Feature Type: Road Asset

Job Number: 50184916

Defect Number: 42190135

Enquiry No.: 2001203

Logged by: Verint CRM Connector

on: 22/08/2025 09:24

Service: Roads General

Subject: Trees & Foliage: Defect

Classification: Request for service

Desc.: Problem: Causing Obstruction.

Location:Footpath.

Type:Foliage / Bush

Location: Overgrown thorny spiky bush hitting my head each time I walk on this pavement coming from the house here opposite the pub

Contact:

Enquiry No.: 1997804

Logged by: Verint CRM Connector

on: 16/08/2025 20:56

Service: Roads General

Subject: Public Utilities: General

Classification: Request for service

Desc.:

Location: Drain cover loose. Every car that goes over it there is a very loud noise.

Contact:

Plot Number: 1.00

Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive

Feature Type: Road Asset

Site History Report

Effective: 27/09/2024 to 27/09/2025
Service: Roads General
Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1991770 **Logged by:** Verint CRM Connector **on:** 07/08/2025 01:25
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Two utility covers are failing and sunken metal work. This is immediately at the junction with Mcleod Street. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50183459 **Defect Number:** 42188235

Enquiry No.: 1991526 **Logged by:** [REDACTED] **on:** 06/08/2025 15:33
Service: Roads General **Subject:** Spill: General **Classification:** Request for service
Desc.: Called as information passed that there is piles of plastic on both side of the road
Location: Near the Calder Road side just before the last speed camera towards Saughton Prison **Contact:**

Enquiry No.: 1991207 **Logged by:** Verint CRM Connector **on:** 06/08/2025 09:04
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: ref 101001319337 reported around 28 July 2025, apparently it was assessed, I was round there yesterday and it has deteriorated. So much it is dangerously low and you have to duck , not good for blind people , photo attached . This heading along John Weir walk path heading from pedestrian crossing and along opposite Buyrite **Contact:**

Enquiry No.: 1990412 **Logged by:** Verint CRM Connector **on:** 04/08/2025 19:08
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Broken up pavement slabs near to Fade Lounge. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1990382 **Logged by:** Verint CRM Connector **on:** 04/08/2025 18:48
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Telephone booth has been pushed over and pavers have lifted **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50183441 **Defect Number:** 42188201

Enquiry No.: 1990003 **Logged by:** [REDACTED] **on:** 04/08/2025 09:14
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Potholes and uneven road surface at junction. Hard to avoid. Please repair.
Location: at junct with Dalry Road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50183375 **Defect Number:** 42188099

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1988013 **Logged by:** Verint CRM Connector **on:** 31/07/2025 08:46
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Pavement.
Type:Foliage / Bush
Location: There is a tree which is obstructing the pathway on the bridge leading from Lift Gym heading towards the pedestrian crossing at the old Arnold Clark building at 555 Gorgie Road. This foliage is so bad you actually have to duck . I know there are road works along this stretch of the road at the moment but if this could be looked at asap that would be great. Thank you **Contact:**

Enquiry No.: 1986580 **Logged by:** Verint CRM Connector **on:** 28/07/2025 17:30
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Footpath.
Type:Foliage / Bush
Location: Overhanging tree over footpath along John Muir walkway coming from the pedestrian crossing at 555 Gorgie Road heading towards Buyrite and it's to the right of there. You have to duck under the overhanging foliage and the tree it comes from looks like it's about to fall onto the path. **Contact:**

Enquiry No.: 1984180 **Logged by:** Verint CRM Connector **on:** 23/07/2025 19:29
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Sunken ironwork at pedestrian crossing near to Inkaholics on Gorgie Road. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1984172 **Logged by:** Verint CRM Connector **on:** 23/07/2025 19:18
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Cracked Pavement slabs. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Job Number: 50153745 **Defect Number:** 42187668

Enquiry No.: 1979922 **Logged by:** Verint CRM Connector **on:** 17/07/2025 05:39
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large potholes on the approach to the bus stop heading eastbound. Previous 'repair' has dislodged from heavy vehicles.... likely buses. Remains of previous is now scattered over the pavement. The potholes will cause damage to vehicles and pose a danger to cyclists **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Job Number: 50182876 **Defect Number:** 42187368

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1973606 **Logged by:** Verint CRM Connector **on:** 04/07/2025 19:37
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: There is a tree overhanging the path . You cross over the main road from Buyrite across Gorgie Road to the old Arnold Clark building behind the student flats heading along the John Muir Walkway . **Contact:**

Enquiry No.: 1969615 **Logged by:** Verint CRM Connector **on:** 26/06/2025 19:14
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Sunken manhole on Gorgie Road going westbound, near junction with Newton Road (opposite the laundrette). **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50182085 **Defect Number:** 42186230

Enquiry No.: 1969612 **Logged by:** Verint CRM Connector **on:** 26/06/2025 19:10
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Broken and uneven road surface on Gorgie Road going westbound, just after the traffic lights near the intersection with McLeod Street, but before Newton Street **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1969609 **Logged by:** Verint CRM Connector **on:** 26/06/2025 19:07
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Broken tarmac on Gorgie Road at junction with McLeod Street. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50182087 **Defect Number:** 42186232

Enquiry No.: 1969602 **Logged by:** Verint CRM Connector **on:** 26/06/2025 18:52
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Serverly bumpy road caused by sunken surfaces and potholes at the end of Gorgie Road at the junction with Ardmillan Terrace, going westbound. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1967326 **Logged by:** Verint CRM Connector **on:** 23/06/2025 12:43
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road surface is dangerous for a bicycle **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1964851 **Logged by:** Verint CRM Connector **on:** 17/06/2025 14:48
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: Overhanging foliage from a tree that looks like it's also about to fall onto the path. **Contact:**
The overhanging foliage is along over the crossing from 555 Gorgie Road along the John Weir walkway towards Buyrite. You have to duck to get past it which is certainly not good if you are blind.

Enquiry No.: 1963639 **Logged by:** Verint CRM Connector **on:** 14/06/2025 18:48
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Two of the hatches built into the sidewalk are collapsing into the sidewalk and are a massive trip hazard. There was a yellow cover over them for a few months which was helpful, but someone must have taken it. This is right outside the Salvation Army Charity Shop next to the bus stop. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50181497 **Defect Number:** 42185625

Enquiry No.: 1961757 **Logged by:** Verint CRM Connector **on:** 11/06/2025 14:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole in side of road heading into town between Fords road and the bus stop for Saughton park **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1961275 **Logged by:** Verint CRM Connector **on:** 10/06/2025 15:44
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: On the area marked is the main area where the road is lowering in on the left side especially where buses go towards the bus stop as well as the pavement being in need of repiar, from the chart it looks like a category 3 but I'm not certain. Headed outward towards the petrol garage. Just past the junction at the lights toward the garage on the left the road has multiple issues on the left, where the road may need resurfacing. The turn left of petrol station just before has serious issues too. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50181295 **Defect Number:** 42185509

Enquiry No.: 1959571 **Logged by:** Verint CRM Connector **on:** 06/06/2025 12:41
Service: Roads General **Subject:** Road: General Enquiry **Classification:** Request for service
Desc.:
Location: Traffic management directs busses and HGVs over a series of large pot holes. This causes excessive vibrations in surrounding buildings at ALL TIMES OF DAY. Furniture is rattling. Cracks have started to appear in plasterboard walls. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50182160 **Defect Number:** 42186312

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1954414 Service: Roads General Desc.: Location: Kerbstone coming loose	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 27/05/2025 22:52 Classification: Request for service	Contact:
Plot Number: 1.00 Job Number: 50180530	Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive Defect Number: 42184529	Feature Type: Road Asset	
Enquiry No.: 1953337 Service: Roads General Desc.: Fence down by skip at 458 Gorgie road. It blocks pedestrians path. I'm assuming the wind knocked it down and couldn't lift it myself and with nothing to secure it. Tried to find out who the skip belonged to but no answer. Can someone help/advise please? Thanks Location: 458 Gorgie road	Logged by: [REDACTED] Subject: Fence: Damaged / Defective	on: 26/05/2025 09:29 Classification: Request for service	Contact:
Enquiry No.: 1951135 Service: Roads General Desc.: Location: Heading direction toward Dalry along gorgie there is a large section of rough road the width of the lane with numerous defects and potholes. Totally unavoidable unless driving on opposite side. Not too far before the hearts pub. Make the car shake having to go over this every day.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 21/05/2025 09:47 Classification: Request for service	Contact:
Plot Number: 1.00 Job Number: 50180182	Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive Defect Number: 42183956	Feature Type: Road Asset	
Enquiry No.: 1948289 Service: Roads General Desc.: Location: Uneven damaged pavement with various slabs broken. I tripped and broke my elbow and sprained my other wrist.	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 15/05/2025 09:40 Classification: Request for service	Contact:
Plot Number: 1.00 Job Number: 50180188	Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive Defect Number: 42183964	Feature Type: Road Asset	
Enquiry No.: 1946963 Service: Roads General Desc.: What type of sign is it? Road sign problem, type unlit 20mph zone sign and pole damaged by stickers. The pole is also leaning. This is outside A One Africa Shop. Location: 20mph zone sign and pole damaged by stickers. The pole is also leaning. This is outside A One Africa Shop.	Logged by: Verint CRM Connector Subject: Traffic Sign:Defective/Damaged	on: 12/05/2025 20:13 Classification: Request for service	Contact:
Enquiry No.: 1946942 Service: Roads General Desc.: What type of sign is it? Road sign problem, type unlit Gorgie Farm Sign on Lampost has sticker damage on it. There are 2 at this location. As Gorgie Farm is now closed are these still required. Location: On Gorgie Road on Lampost near to Gorgie Farm.	Logged by: Verint CRM Connector Subject: Traffic Sign:Defective/Damaged	on: 12/05/2025 19:31 Classification: Request for service	Contact:
Plot Number: 1.00 Job Number: 50180079	Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive Defect Number: 42183796	Feature Type: Road Asset	

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1940751 **Logged by:** Verint CRM Connector **on:** 30/04/2025 07:23
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Metal manhole on road is making an extremely loud noise with every bus and car that goes over it. This happens all the time. It is waking myself and children up at night. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50179400 **Defect Number:** 42182686

Enquiry No.: 1939531 **Logged by:** Verint CRM Connector **on:** 27/04/2025 23:15
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type unlit Pole with 20mph speed limit sign on it is leaning. Also damage to the sign face of the 20mph sign as well.
Location: Pole leaning on Gorgie Road near to no 12. The 20mph sign is also damaged. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50179939 **Defect Number:** 42183548

Enquiry No.: 1939518 **Logged by:** Verint CRM Connector **on:** 27/04/2025 22:07
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Damage to Paving Stone on Gorgie Road. Near to junction with Murieston Road. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1933968 **Logged by:** Verint CRM Connector **on:** 15/04/2025 13:43
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: sunken manhole cover with loss of anti skid surfacing. very dangerous for cyclists and motorcyclists, esp when wet. Cover is marked as belonging to NORWEB Telecom. If this is not CEC responsibility, can you please advise as to the current owner as NORWEB Telecom, no longer exists and has been taken over several times **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50178623 **Defect Number:** 42181470

Enquiry No.: 1926746 **Logged by:** [REDACTED] **on:** 01/04/2025 11:48
Service: Roads General **Subject:** Roadworks: General Enquiry **Classification:** Request for service
Desc.: Works started linked to providing a pelican crossing in front of 505 – 503 recently and made a great job of the crossing . Huge problem is the pavements. The men also removed safety island and dropped kerb. They have now been on site since last Thursday. At lot of the residents including lady on phone either have mobility scooters or zimmers. They cannot cross at this point and having difficulty walking to the bus stop at chesser cottages. When they get off the bus at other side of road there is no place to easily cross road safely. Can you please investigate and resolve this matter as an urgent one please. The area is normally tarmacked however it is in a mess with sand and you cannot walk on this safely.
Location: Directly in front building 505 **Contact:**

Enquiry No.: 1925175 **Logged by:** Verint CRM Connector **on:** 28/03/2025 15:22
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Noisy cover in junction. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Site History Report

Effective: 27/09/2024 to 27/09/2025
Service: Roads General
Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1918970 **Logged by:** Verint CRM Connector **on:** 16/03/2025 21:25
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: At Traffic lights at VPZ shop on Gorgie road near to wardlaw place junction. **Contact:**

Utility cover is moving when traffic goes over. Looks like beginning to fail.

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50177089 **Defect Number:** 42178917

Enquiry No.: 1915758 **Logged by:** [REDACTED] **on:** 10/03/2025 10:49
Service: Roads General **Subject:** Roadworks: General Enquiry **Classification:** General Enquiry
Desc.: Putting a new crossing in this area near the bus stop. As this is sheltered housing area Residents says this is now too far away for the locals who are elderly and use mobility items. Resident is request that the bus stop be moved to the cut in in the area where people are always illegally parked.
Location: 511 Gorgie Road **Contact:**

Enquiry No.: 1914594 **Logged by:** Verint CRM Connector **on:** 07/03/2025 11:25
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Several loose and rocking slabs on this section outside Gorgie Dental **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1911274 **Logged by:** Verint CRM Connector **on:** 28/02/2025 14:41
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: There is a loose drain cover in the middle of the junction of Dalry Road and Gorgie Road. It is very noisy every time a vehicle drives over it. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1905928 **Logged by:** Verint CRM Connector **on:** 19/02/2025 12:15
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Numerous potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1904386 **Logged by:** Verint CRM Connector **on:** 16/02/2025 16:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: gorgie road, the narrow street between gorgie road and fords road, next to the Puregym edinburgh west. you would take this road to get to buyrite bathrooms. The worst part of the road is next to the Puregym. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1903897 **Logged by:** Verint CRM Connector **on:** 15/02/2025 08:04
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: Ongoing pavement issue. Problem was covered by yellow board and tarmac round the edges. This has failed. Due to heavy footfall the boards have moved. There is football tomorrow so this is unsafe. Problem is at the road crossing outside Stratfords Bar. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50175363 **Defect Number:** 42176338

Enquiry No.: 1897556 **Logged by:** Verint CRM Connector **on:** 03/02/2025 09:58
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Broken and rocking slab on section of pavement in front of Gorgie White Park **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50174095 **Defect Number:** 42174701

Enquiry No.: 1893564 **Logged by:** Verint CRM Connector **on:** 27/01/2025 15:04
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The pigeon mesh underneath the deck of the railway bridge on Gorgie road is hanging down and striking double decker buses. This has been called in to Network Rail by bus company employee (wrong number given). Pigeon mesh is responsibility of local authority. I believe this should go to Structures / Bridges within CEC. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1893541 **Logged by:** [REDACTED] **on:** 27/01/2025 14:29
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: netting hanging low and catching the buses. buses have had to be pulled off-road to get this netting taken away ASAP
Location: railway bridge at Dalry road/mcleod street **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1892414 **Logged by:** Verint CRM Connector **on:** 25/01/2025 18:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Crumbling surface around utility cover. Opposite side of the road to Krishna at entrance to Gorgie Stand. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1892406 **Logged by:** Verint CRM Connector **on:** 25/01/2025 17:41
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road Crumbling around train. This is on Gorgie Road directly opposite the Gorgie Laundrette near to Tynecastle. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50173639 **Defect Number:** 42174101

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1892364 **Logged by:** Verint CRM Connector **on:** 25/01/2025 16:16
Service: Roads General **Subject:** Fence: Damaged / Defective **Classification:** Request for service
Desc.:

Location: Between the railway bridge and the private road which is used by the railway maintenance men, there is a high wall. Stop the wall is a wooden fence. Storm damage has broken the fence, a section of which is flipped over and is precariously balanced only just still connected to the fence. Several nails are sticking out of it When it gives way, it may cause someone serious injury. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1889829 **Logged by:** Verint CRM Connector **on:** 20/01/2025 17:27
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.

Location:Footpath.
Type:Foliage / Bush
Location: Very thorny bush at head height on pavement **Contact:**

Enquiry No.: 1886217 **Logged by:** Verint CRM Connector **on:** 14/01/2025 09:10
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: drain cover sticking up in the middle of the road - east bound in the bus lane between elfin square and fords road - opposite The Laich **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Job Number: 50172783 **Defect Number:** 42172944

Enquiry No.: 1884983 **Logged by:** Verint CRM Connector **on:** 11/01/2025 19:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Uneven and crack surfaces on road Gorgie Road eastbound, just before junction with Newton Street. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1884467 **Logged by:** Verint CRM Connector **on:** 10/01/2025 15:28
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow Box lying on pavement

Location: Box and pole lying on pavement **Contact:**

Enquiry No.: 1884229 **Logged by:** Verint CRM Connector **on:** 10/01/2025 11:32
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: Stratfords Pub, Edinburgh EH11 1TU Pavement defect directly outside the pub, this is very dangerous and is a H&S Hazzard **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Site History Report

Effective: 27/09/2024 to 27/09/2025
Service: Roads General
Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1883509 **Logged by:** Verint CRM Connector **on:** 09/01/2025 11:33
Service: Roads General **Subject:** Pavement: Missing Slab / Kerb **Classification:** Customer Emergency
Desc.:
Location: Pavement collapsing outside Stratfords Bar at the crossing **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50172546 **Defect Number:** 42172602

Enquiry No.: 1882182 **Logged by:** Verint CRM Connector **on:** 07/01/2025 15:45
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Other.
Location: Road.
Type: Foliage / Bush
Location: Tree encroaching on wall for car park in Scotmid Gorgie - causing structural issues with wall and likely to cause collapse. **Contact:**

Enquiry No.: 1881131 **Logged by:** Verint CRM Connector **on:** 06/01/2025 15:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge pothole has appeared at the cross section between the sainsburys car park and the main road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1880860 **Logged by:** Verint CRM Connector **on:** 06/01/2025 11:54
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Massive pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1879740 **Logged by:** Verint CRM Connector **on:** 04/01/2025 18:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Three potholes at the entrance towards Gorgie Road at the junction. Two of the three potholes are caused by poor 'repairs' of previous potholes ('repaired' twice already) **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1879234 **Logged by:** Verint CRM Connector **on:** 04/01/2025 08:45
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Citybound bus stop multiple large potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1878505 **Logged by:** [REDACTED] **on:** 03/01/2025 09:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Potholed surface
Location: at junct with White Park **Contact:**

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1878468 Service: Roads General Desc.: Location: large pot hole around here heading into town near the curb	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 03/01/2025 09:08 Classification: Request for service	Contact:
Plot Number: 1.00 Job Number: 50172055	Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive Defect Number: 42172010	Feature Type: Road Asset	
Enquiry No.: 1873660 Service: Roads General Desc.: Location: Large bumps and undulations in westbound lane (full width, 20+m length). Passing of HGV's and busses causes excessive noise and vibrations, which are a nuisance to adjacent roadside properties. See attached photos. Submitted by resident at 572 Gorgie Road.	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 20/12/2024 11:31 Classification: Request for service	Contact:
Plot Number: 1.00 Job Number: 50171741	Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive Defect Number: 42171645	Feature Type: Road Asset	
Enquiry No.: 1873370 Service: Roads General Desc.: Location: Can I report a wonky pavement slab outside the coffee pot cafe in Gorgie road Edinburgh. Near Robertson avenue. The paving slab is moving up and down and is a trip hazard.. I would be grateful if you could look into this.	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 19/12/2024 15:34 Classification: Request for service	Contact:
Plot Number: 1.00 Job Number: 50171741	Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive Defect Number: 42171645	Feature Type: Road Asset	
Enquiry No.: 1869056 Service: Roads General Desc.: sunken/noisy manhole cover Location: At Ardmillan Terrace, Gorgie Road & Henderson Terrace junction - caller lives halfway up Henderson Terrace, but can hear it clearly	Logged by: [REDACTED] Subject: Public Utilities: General	on: 09/12/2024 15:30 Classification: General Enquiry	Contact:
Enquiry No.: 1863904 Service: Roads General Desc.: Location: Loose and sunken manhole cover, Gorgie Road westbound just at the Robertson Avenue bridge, looks like it could give way completely soon.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 26/11/2024 18:31 Classification: Request for service	Contact:
Plot Number: 1.00 Job Number: 50170442	Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive Defect Number: 42169950	Feature Type: Road Asset	
Enquiry No.: 1863319 Service: Roads General Desc.: temporary bus stop to be install before and after the roadworks - for at least 20 weeks Location: at top of Smithfield street - (Stewart Terrace)	Logged by: [REDACTED] Subject: Roadworks: General Enquiry	on: 25/11/2024 16:20 Classification: General Enquiry	Contact:

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Customer Services

Enquiry No.: 1862891 Logged by: Verint CRM Connector on: 25/11/2024 01:10

Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:

Location: I was walking home from Sainsbury's last week when I took a tumble and fell due to uneven pavement slabs and poor lighting. I landed on my left knee and right foot with both hands in front of me feeling the full force.

I was helped up by a younger couple and hobbled to the bus stop, I went to minor injuries the following day, where I got xrays of left knee and of my wrist none broken however I have fluid on the knee and suffered lots of pain in my right wrist and foot

Contact:

Plot Number: 1.00 Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive Feature Type: Road Asset

Enquiry No.: 1858527 Logged by: [REDACTED] on: 14/11/2024 11:32

Service: Roads General Subject: Road Safety: General Enquiry Classification: General Enquiry

Desc.: As there are road works in the area at present said this would be a good time to install the crossing whilst the road is up. There are a lot of elderly people living at the area. [REDACTED] has mobility scooter and finds it difficult to cross the road with new housing being installed. also the pavement has been narrowed due to installatoin of housing opposite number 505

Location: at the safety island slightly to the side of 511 can a pedestrian crossing possibly be installed. Contact:

Enquiry No.: 1857313 Logged by: [REDACTED] on: 11/11/2024 17:03

Service: Roads General Subject: Roadworks: Defect Classification: Request for service

Desc.: @edinhelp hi, guys. Ridiculous amount of road signs placed on pavements along busy Gorgie Road, from around the Scotmid store onwards, on both sides of the road, 8 signs alone on this two block stretch in a very busy area.

Location: from around the Scotmid store onwards, on both sides of the road Contact:

Enquiry No.: 1853595 Logged by: Verint CRM Connector on: 04/11/2024 10:03

Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:

Location: Loose and cracked slab Contact:

Plot Number: 1.00 Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive Feature Type: Road Asset

Enquiry No.: 1853592 Logged by: Verint CRM Connector on: 04/11/2024 10:02

Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service

Desc.:

Location: Loose slab outside Gorgie Road Barbers Contact:

Plot Number: 1.00 Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive Feature Type: Road Asset

Enquiry No.: 1853001 Logged by: Verint CRM Connector on: 02/11/2024 11:58

Service: Roads General Subject: Traffic Sign:Defective/Damaged Classification: Request for service

Desc.: What type of sign is it? Road sign problem, type lit. Issue : SL28.

Location: No right turn sign before bridge. Sign has been completely defaced and is unreadable. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 7 - Ardmillan Terrace to Stenhouse Drive Feature Type: Road Asset

Job Number: 50170874 Defect Number: 42170561

Enquiry No.: 1851544 Logged by: [REDACTED] on: 30/10/2024 11:26

Service: Roads General Subject: Covers: Damaged / Defective Classification: Request for service

Desc.: part of manhole cover missing and very dangerous

Location: cycle lane front of number 580 on road Contact:

Site History Report

Effective: 27/09/2024 to 27/09/2025
Service: Roads General
Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1851531 **Logged by:** Verint CRM Connector **on:** 30/10/2024 11:17
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Man hole broke. It's wide open. At the cycle lane. Extremely dangerous **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50169075 **Defect Number:** 42168215

Enquiry No.: 1850249 **Logged by:** Verint CRM Connector **on:** 28/10/2024 08:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Exposed manhole cover **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1845565 **Logged by:** Verint CRM Connector **on:** 17/10/2024 04:48
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: broken manhole, rocks and sinks when stepped on, feels like it's about to break **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50168196 **Defect Number:** 42166945

Enquiry No.: 1841273 **Logged by:** [REDACTED] **on:** 07/10/2024 10:05
Service: Roads General **Subject:** Road Safety: General Enquiry **Classification:** Request for service
Desc.: Please see attached
Location: Flat 6, 7 Gorgie Road, Gorgie, Edinburgh, City of Edinburgh, EH11 2FA **Contact:** [REDACTED]

Enquiry No.: 1839733 **Logged by:** Verint CRM Connector **on:** 03/10/2024 10:23
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: pothole around small iron work cover heading into town **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset

Enquiry No.: 1837828 **Logged by:** Verint CRM Connector **on:** 29/09/2024 10:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: A new small but deep pothole has formed next to a patch of previously patched pothole. It is located at the west bound carriageway just next to the dropped curb at the pedestrian crossing. It is capable of causing a fall, particularly at night **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 7 - Ardmillan Terrace to Stenhouse Drive **Feature Type:** Road Asset
Job Number: 50167659 **Defect Number:** 42166110

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 7 - Ardmillan Terrace to Stenhouse Drive		Feature Type: Road Asset		Area: South West Locality	
50167659	Cw x1 pothole Road: Defective / Damaged (Enquiry 1837828) (RD: CW Pothole)	Pedestrian crossing at the junction with Ardmillan Terrace	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/10/2024	07/10/2024	Act. ROAD/82097009

Site History Report

Effective: 27/09/2024 to 27/09/2025
Service: Roads General
Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 7 - Ardmillan Terrace to Stenhouse Drive		Feature Type: Road Asset		Area: South West Locality	
50169075	New frame and brander required (RD: Gully Damaged/Sunken)	Outside 580	RD: Cat 3 - 60 Day	Job Complete	01/11/2024	04/11/2024	Act. ROAD/82097953
50169580	2no potholes (RD: CW Pothole)	At the bus stop opposite no451	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/11/2024	11/11/2024	Act. ROAD/82098270
50170144	Sunken gully (RD: Gully Damaged/Sunken)	Opposite 501	RD: Cat 3 - 60 Day	Job Complete	21/11/2024	13/12/2024	Act. ROAD/82098681
50170334	3 Broken and missing slabs also concrete needs redone around other manhole (RD: FW Slabs Broken/Missing)	See pin location around catv box	RD: Cat 3 - 60 Day	Job Complete	25/11/2024	29/11/2024	Act. ROAD/82098780
50170549	Pothole around gully frame (RD: CW Pothole)	Outside 475	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/11/2024	28/11/2024	Act. ROAD/82098939
50170874	Traffic Sign:Defective/Damaged - What type of sign is it? Road sign problem, type lit. Issue : SL28. (Enquiry 1853001) (RD: Unlit Sign Damaged/Missing)	At the junction with Robertson avenue. Please remove no right turn sign and supplemental plate and replace with new. Signs ordered and ready to collect from stores. Mounting height 2300mm	RD: Cat 3 - 60 Day	Job Complete	05/12/2024	21/12/2024	Act. ROAD/82099165
50170893	Brander damaged (RD: Gully Damaged/Sunken)	Gorgie road @ped crossing	RG: Gully - Standard Priority	Job Complete	05/12/2024	13/12/2024	Act. ROAD/82099184
50170894	RD: Gully Damaged/Sunken	Outsides Stevensons	RG: Gully - Standard Priority	Job Complete	05/12/2024	13/12/2024	Act. ROAD/82099185
50170895	RD: Gully Damaged/Sunken	Outside 498	RG: Gully - Standard Priority	Job Complete	05/12/2024	13/12/2024	Act. ROAD/82099186
50170899	RD: Gully Damaged/Sunken	Outside 501	RG: Gully - Standard Priority	Job Complete	05/12/2024	13/12/2024	Act. ROAD/82099189
50171126	1no pothole (RD: CW Pothole)	At the bus stop opposite the Salvation Army	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/12/2024	11/12/2024	Act. ROAD/82099340
50171128	2no potholes (RD: CW Pothole)	At the bus stop at Smithfield Street	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/12/2024	11/12/2024	Act. ROAD/82099342
50171741	Renew broken and rocking 600x900 pic flag (RD: FW Slabs Broken/Missing)	Outside the koffee pot cafe	RD: Cat 3 - 60 Day	Job Complete	20/12/2024	23/12/2024	Act. ROAD/82099858
50172055	Pothole (RD: CW Pothole)	City bound lane before bridge	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/01/2025	06/01/2025	Act. ROAD/82100104
50172056	Pothole (RD: CW Pothole)	City bound lane at McDonald's traffic lights	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/01/2025	06/01/2025	Act. ROAD/82100105
50172071	Potholes (RD: CW Pothole)	In bus stop city bound lane	RD: Cat 2 - 5 Day	Job Complete	03/01/2025	07/01/2025	Act. ROAD/82100120
50172189	Renew broken 600x900 occ flag (RD: FW Slabs Broken/Missing)	Behind bins at pin location	RD: Cat 3 - 60 Day	Job Complete	06/01/2025	07/01/2025	Act. ROAD/82100212
50172346	Pothole x 2 (RD: CW Pothole)	At bus stop opposite 451	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/01/2025	09/01/2025	Act. ROAD/82100344
50172418	2no potholes (RD: CW Pothole)	At the junction with Fords Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/01/2025	13/01/2025	Act. ROAD/82100399

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 7 - Ardmillan Terrace to Stenhouse Drive		Feature Type: Road Asset		Area: South West Locality	
50172420	1no pothole (RD: CW Pothole)	At the bus stop at Smithfield Street	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/01/2025	13/01/2025	Act. ROAD/82100400
50173024	Sunken slabs round manhole cover on footway excavate investigate and reinstate (RD: FW Slabs Broken/Missing)	Outside stratford pub	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/01/2025	06/02/2025	Act. ROAD/82100880
50173427	Bollard reversed into and pushing up the slabs and tactiles around it, bollard and tactiles, slabs need reset, bollard not removed from site as is reusable (RD: Bollard Damage/Missing/New)	On footway outside Costa coffee	RD: Cat 3 - 60 Day	Job Complete	22/01/2025	23/01/2025	Act. ROAD/82101165
50173639	Renew frame and brander, rocking Sunken gully (RD: Gully Damaged/Sunken)	Outside bite & go	RD: Cat 3 - 60 Day	Job Complete	27/01/2025	25/03/2025	Act. ROAD/82101299
50173945	1no pothole (RD: CW Pothole)	At the junction with Chesser Avenue	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/01/2025	31/01/2025	Act. ROAD/82101537
50174095	Renew Broken 600x 900 pcc flag (RD: FW Slabs Broken/Missing)	Opposite 158 gorgie road on footway	RD: Cat 3 - 60 Day	Job Complete	03/02/2025	10/02/2025	Act. ROAD/82101665
50174172	Damaged weebol (RD: Weebol Damage/Missing/New)	Outside 355	RD: Cat 3 - 60 Day	Job Complete	04/02/2025	11/02/2025	Act. ROAD/82101728
50174173	Pothole (RD: CW Pothole)	Outside mcdonalds	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/02/2025	09/02/2025	Act. ROAD/82101729
50174417	Keep left weebol damaged	Outside 355	RD: Cat 3 - 60 Day	Job Complete	06/02/2025	11/02/2025	Act. ROAD/82101915
50174423	Renew keep left weebol (RD: Weebol Damage/Missing/New) 2 potholes (RD: CW Pothole)	Outside flowers by McDowell	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2025	11/02/2025	Act. ROAD/82101920
50174428	Missing kerb renew kerb cut to size (RD: FW Kerbs Damaged/Missing)	At speed camera	RD: Cat 3 - 60 Day	Job Complete	06/02/2025	21/02/2025	Act. ROAD/82101925
50175451	RD: CW Pothole	On Gorgie road city bound at the junction with stenhouse drive	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/02/2025	20/02/2025	Act. ROAD/82102801
50175753	Pothole (RD: CW Pothole)	On crossing outside McDonald's	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	24/02/2025	25/02/2025	Act. ROAD/82103059
50175754	Pothole (RD: CW Pothole)	Just before the crossroads pothole on city bound lane	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/02/2025	05/03/2025	Act. ROAD/82103060
50176037	Potholes around manhole (RD: CW Pothole)	At bus stop outside Salvation Army shop	RD: Cat 3 - 60 Day	Job Complete	27/02/2025	06/03/2025	Act. ROAD/82103291
50176042	1no pothole (RD: CW Pothole)	At the junction with Chesser Avenue	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/02/2025	05/03/2025	Act. ROAD/82103296
50176064	3no potholes (RD: CW Pothole)	At the bus stop opposite no451	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/02/2025	05/03/2025	Act. ROAD/82103313

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 7 - Ardmillan Terrace to Stenhouse Drive		Feature Type: Road Asset		Area: South West Locality	
50176067	2no potholes at manhole (RD: CW Pothole)	At the bus stop at Smithfield Street	RD: Cat 3 - 60 Day	Job Complete	27/02/2025	06/03/2025	Act. ROAD/82103315
50176093	4no potholes (RD: CW Pothole)	On the pedestrian crossing at the corner of Ardmillan Terrace	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/02/2025	05/03/2025	Act. ROAD/82103339
50176322	Pothole (RD: CW Pothole)	At junction with chesser avenue	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/03/2025	05/03/2025	Act. ROAD/82103526
50176323	Pothole (RD: CW Pothole)	Opposite 451 at bus stop	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/03/2025	04/03/2025	Act. ROAD/82103527
50177095	Pothole (RD: CW Pothole)	At junction with Westfield street	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/03/2025	21/03/2025	Act. ROAD/82104106
50177096	Pothole (RD: CW Pothole)	Just after junction of westfield road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/03/2025	21/03/2025	Act. ROAD/82104107
50178137	Pothole (RD: CW Pothole)	Outside els house	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/04/2025	03/04/2025	Act. ROAD/82104827
50178138	Pothole (RD: CW Pothole)	Opposite 572 gorgie road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/04/2025	03/04/2025	Act. ROAD/82104828
50179939	Traffic Sign:Defective/Damaged - What type of sign is it? Road sign problem, type unlit Pole with 20mph speed limit sign on it is leaning. Also damage to the sign face of the 20mph sign as well. (Enquiry 1939531) (RD: Unlit Sign Damaged/Missing)	Please remove existing 20mph sign and pole and replace with new as per attached sign design detail documents.	RD: Cat 3 - 60 Day	Job Complete	15/05/2025	26/03/2026	Act. ROAD/82106062
50180072	Turn 20mph & 30mph speed limit signs to face oncoming vehicles (RD: Unlit Sign Damaged/Missing)	On footway outside Kaspas' desert shop	RD: Cat 3 - 60 Day	Job Complete	19/05/2025	13/06/2025	Act. ROAD/82106138
50180075	Turn 20mph speed limit roundal sign to face oncoming vehicle (RD: Unlit Sign Damaged/Missing)	On footway outside Patisserie Adlai	RD: Cat 3 - 60 Day	Job Complete	19/05/2025	14/06/2025	Act. ROAD/82106140
50180079	Remove two Gorgie city farm signs from lamppost as no longer required (RD: Unlit Sign Damaged/Missing)	On lamppost at Gorgie road outside Tynecastle school	RD: Cat 3 - 60 Day	Job Complete	19/05/2025	13/06/2025	Act. ROAD/82106142
50180080	Remove Gorgie city farm signs from from signs pole as no longer required (RD: Unlit Sign Damaged/Missing)	On footway outside old Gorgie city farm on signs pole	RD: Cat 3 - 60 Day	Job Complete	19/05/2025	13/06/2025	Act. ROAD/82106143
50180188	At gas Toby on fw (RD: FW Grano Pothole)	.outside 12	RD: Cat 2 - 5 Day	Job Complete	21/05/2025	26/05/2025	Act. ROAD/82106208
50180296	Road island damaged in accident Renew 3xrail/safety barriers (RD: Railing Damage/Missing/New)	Outside pure gym on Gorgie road	RD: Cat 3 - 60 Day	Job Complete	23/05/2025	02/09/2025	Act. ROAD/82106301

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 7 - Ardmillan Terrace to Stenhouse Drive		Feature Type: Road Asset		Area: South West Locality	
50180530	Reinstate loose Radius kerb and infill behind with hra. (RD: FW Kerb Dislodged/Rocking)	At the junction of Gorgie road and Robertson avenue	RD: Cat 3 - 60 Day	Job Complete	28/05/2025	16/06/2025	Act. ROAD/82106463
50181390	1no f/w pothole (RD: FW HRA Pothole)	Outside Four Square	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/06/2025	17/06/2025	Act. ROAD/82106981
50181392	2no rocking cut slabs (RD: FW Slabs Rocking)	Outside Brass	RD: Cat 3 - 60 Day	Job Complete	13/06/2025	17/06/2025	Act. ROAD/82106983
50181394	Replace broken grano approx 0.2x0.4 1no broken 600x900 pcc slab 1no rocking 600x600 pcc slab (RD: FW Grano Cracked/Broken)	Outside 320	RD: Cat 3 - 60 Day	Job Complete	13/06/2025	17/06/2025	Act. ROAD/82106985
50181396	7no rocking slabs (RD: FW Slabs Rocking)	Outside 296	RD: Cat 3 - 60 Day	Job Complete	13/06/2025	18/06/2025	Act. ROAD/82106986
50181397	3no rocking 600x900 slabs 1no broken 600x900 slab (RD: FW Slabs Rocking)	Outside 266	RD: Cat 3 - 60 Day	Job Complete	13/06/2025	19/06/2025	Act. ROAD/82106987
50181399	1no broken 600x900 pcc slab (RD: FW Slabs Broken/Missing)	Outside Hospices of hope	RD: Cat 3 - 60 Day	Job Complete	13/06/2025	19/06/2025	Act. ROAD/82106988
50181400	1no rocking slab (RD: FW Slabs Rocking)	Behind bus stop at Smithfield st	RD: Cat 3 - 60 Day	Job Complete	13/06/2025	19/06/2025	Act. ROAD/82106989
50181402	1no rocking slab (RD: FW Slabs Rocking)	Approx 10m east of Murieston crescent lane	RD: Cat 3 - 60 Day	Job Annulled	13/06/2025	13/06/2025	Act. ROAD/82106991
50181403	2no broken 400x400 tactile slabs 3no rocking 400x400 tactile slabs (RD: FW Slabs Broken/Missing)	At Cathcart place	RD: Cat 3 - 60 Day	Job Annulled	13/06/2025	13/06/2025	Act. ROAD/82106992
50181404	Renew grano surround (RD: FW Grano Cracked/Broken)	Outside co-op	RD: Cat 2 - 5 Day	Job Annulled	13/06/2025	13/06/2025	Act. ROAD/82106993
50181405	3no rocking slabs (RD: FW Slabs Rocking)	Opposite Orwell Terrace	RD: Cat 3 - 60 Day	Job Annulled	13/06/2025	13/06/2025	Act. ROAD/82106994
50181406	Renew grano surround approx 1m (RD: FW Grano Cracked/Broken)	At side of bus stop next to British heart foundation	RD: Cat 3 - 60 Day	Job Annulled	13/06/2025	13/06/2025	Act. ROAD/82106995
50181407	Renew grano surround (RD: FW Grano Cracked/Broken)	Outside Locanda de gusti	RD: Cat 3 - 60 Day	Job Annulled	13/06/2025	13/06/2025	Act. ROAD/82106996
50181408	9no rocking tactile slabs (RD: FW Slabs Rocking)	At Dalry gait	RD: Cat 3 - 60 Day	Job Annulled	13/06/2025	13/06/2025	Act. ROAD/82106997
50181417	3no rocking slabs (RD: FW Slabs Rocking)	Opposite Orwell Terrace	RD: Cat 3 - 60 Day	Job Annulled	13/06/2025	13/06/2025	Act. ROAD/82107005
50181512	Grano pothole repair needed at manhole on footway (existing grano still in pothole) (RD: FW Grano Pothole)	Outside 320 just before rail bridge	RD: Cat 2 - 5 Day	Job Complete	16/06/2025	17/06/2025	Act. ROAD/82107026
50181517	Pothole (RD: CW Pothole)	Outside 109 on crossing	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/06/2025	17/06/2025	Act. ROAD/82107031

Site History Report

Effective: 27/09/2024 to 27/09/2025

Service: Roads General

Site: Gorgie Road (7902864)

Asset Number: 1.00 to 1.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 7 - Ardmillan Terrace to Stenhouse Drive		Feature Type: Road Asset		Area: South West Locality	
50181788	Replace and cut to size 4x 600x900 Reset 1 x rocking slab (RD: FW Slabs Broken/Missing)	Outside 106 Gorgie Road hair art by Eva	RD: Cat 2 - 5 Day	Job Complete	23/06/2025	26/06/2025	Act. ROAD/82107189
50181966	Bollard loose Reset bollard 1x (no damage to bollard) reuse Reset small granite blocks around bollard 10 or 11 (RD: Bollard Damage/Missing/New)	On wardlaw street ar corner of Gorgie Road	RD: Cat 3 - 60 Day	Job Complete	25/06/2025	11/07/2025	Act. ROAD/82107289
50182160	Large patch needing overlayed in areas (RD: CW Pothole)	Outside the flats next to gym	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/07/2025	07/07/2025	Act. ROAD/82107428
50182596	Pothole over over utility defect as it's not been picked up yet as it's on the crossing. (RD: CW Pothole)	At crossing at rail bridge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/07/2025	15/07/2025	Act. ROAD/82107744
50182876	Pothole (RD: CW Pothole)	at bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/07/2025	21/07/2025	Act. ROAD/82107934
50183681	Relay x3 marked slabs Replace broken 400x400 Renew grano around manhole (RD: FW Slabs Broken/Missing)	Outside pepes	RD: Cat 3 - 60 Day	Job Complete	18/08/2025	04/09/2025	Act. ROAD/82108406
50183682	Renew grano at catv box (RD: FW Grano Cracked/Broken)	Outside christines	RD: Cat 3 - 60 Day	Job Complete	18/08/2025	20/08/2025	Act. ROAD/82108407
50183690	x2 rocking slabs Renew grano around double manhole (RD: FW Slabs Rocking)	Outside good food	RD: Cat 2 - 5 Day	Job Complete	18/08/2025	19/08/2025	Act. ROAD/82108414
50183691	1 rocking slab (RD: FW Slabs Rocking)	Outside baguette express	RD: Cat 3 - 60 Day	Job Complete	18/08/2025	20/08/2025	Act. ROAD/82108415
50183694	Remove marked cut slabs and replace with grano Relay marked 900 slab with cross cut as marked to suit existing height (RD: FW Slabs Rocking)	Outside aquatic shop	RD: Cat 3 - 60 Day	Job Complete	18/08/2025	20/08/2025	Act. ROAD/82108418
50184326	Loose pole and damaged 20mph sign with stickers (TS: Sign Pole Loose)	Outside 18	RD: Cat 2 - 5 Day	Job Complete	01/09/2025	03/09/2025	Act. ROAD/82108756
50184832	Relay 4 sunken slabs (RD: FW Slabs Rocking)	Outside murshid & co accountants	RD: Cat 3 - 60 Day	Job Complete	16/09/2025	17/09/2025	Act. ROAD/82109078