


61827

The date the playpark next to Oxgangs Primary school (circled on the attached map) was constructed; Late 2018 but school could confirm exact date.

There is no available paperwork confirming the supplier or installation date. There is no CCR or caveat letter available.

See picture below - Google map photos of Oxgangs Primary School during construction. The Adventure Playground was being constructed in the first photo taken in 2005. This aligns with the handover of Phase 2 of PPP1. The second photo shows it more clearly in 2012.



The details of who constructed the playpark next to Oxgangs Primary School (circled on the attached map; School to confirm supplier / installer.

As above.

The dates of any work carried out to the playpark next to Oxfangs Primary School (circled on the attached map);

Due to maintenance issues, it was decided at the school's Health and Safety Meeting that the Trim Trail should be removed – this was completed during summer holidays.

Inspection records relating to the playpark next to Oxfangs Primary School (circled on the attached map) from 21 April 2023;

Please see the attached.

Maintenance records relating to the playpark next to Oxfangs Primary School (circled on the attached map) from 21 April 2023;

We hold no maintenance records from the school or Amey.

Any complaints made in relation to the playpark next to Oxfangs Primary School (circled on the attached map) from 21 April 2023; For school to answer,

We hold no records of complaints made to Amey or received by the school.

Grass cutting records of the area beside the playpark next to Oxfangs Primary School (circled on the attached map) from 21 April 2023;

Please refer to the grass cutting PPM records attached.

Your policy relating to defect categorisations.

We do not hold a policy. All defects would be reported to installer to rectify. If possible, the school follows advice recorded in the ROSPA reports.