

Effective: 04/03/2026 to 04/03/2026

Asset Number: 1.00 to 1.00

Display Action Officer: No

Site: Craiglockhart Avenue (7902734)

Site: Craiglockhart Avenue (7902734)

Locality: Wester Craiglockhart, Edinburgh, City of Edinburgh

Area: South West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South West Locality	
Batch: 41256431 - Inspection Batch				Route: South Mobile Inspection Route			Date: 04/03/2026	
42200958	1no pothole	03/03/2026	Outside 34a	RD: CW Pothole	Internal		Committed	50193089