

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Site: C157 - Kirkliston To Burnshot (7906080)

Locality: Craigiehall, Edinburgh, City of Edinburgh

Area: North West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c			Feature Type: Road Asset			Area: North West Locality	
Batch: 41262267 - Inspection Batch	No actionable defects found			Route: NW_CW1_West1			Date: 05/05/2026	
Batch: 41260996 - Inspection Batch				Route: Ad hoc Route			Date: 15/04/2026	
42204200	1 number pothole on slip road from Burnshot to Miller and Carter	15/04/2026	Go to pin placement as no location	RD: CW Pothole	Internal		Committed	50195408
Batch: 41259689 - Inspection Batch				Route: Ad hoc Route			Date: 30/03/2026	
42203260	Various potholes require HRA overlay	30/03/2026	From under the rail bridge to just before the bend both lanes	RD: CW Pothole	Internal		Committed	50193440
Batch: 41259391 - Inspection Batch				Route: Ad hoc Route			Date: 26/03/2026	
42203089	1 number pothole	26/03/2026	No exact location, go to pin placement just before bridge heading towards Kirkliston	RD: CW Pothole	Internal		Committed	50194595
Batch: 41257055 - Inspection Batch				Route: Ad hoc Route			Date: 06/03/2026	
42201440	Various potholes require HRA overlay	06/03/2026	From under the rail bridge to just before the bend both lanes	RD: CW Pothole	Internal		No Action Required	
Batch: 41255960 - Inspection Batch				Route: Ad hoc Route			Date: 28/02/2026	
42200819	Cracked broken surface along middle of lanes	28/02/2026	On the straight Between the Bends	RD: CW Cracked/Broken	Internal		Uncommitted	50192976
Batch: 41255959 - Inspection Batch				Route: Ad hoc Route			Date: 28/02/2026	
42200818	After clearing up fw old concrete post stump uncovered and needs took away and infilling with tar	28/02/2026	On fw at pin location	RD: FW HRA Cracked/Broken	Internal		Committed	50192975
Batch: 41255950 - Inspection Batch				Route: Ad hoc Route			Date: 28/02/2026	
42200808	Pothole at gully	28/02/2026	First gully 15041 just past hillside road junction west bound lane	RD: CW Pothole	Internal		Committed	50192966
Batch: 41251305 - Inspection Batch				Route: Ad hoc Route			Date: 31/01/2026	
42198150	Cracked broken surface	31/01/2026	Section after new surface	RD: CW Cracked/Broken	Internal		Uncommitted	50190842
Batch: 41249629 - Inspection Batch				Route: Ad hoc Route			Date: 22/01/2026	
42197378	3 potholes area in need of hra overlay	22/01/2026	Heading west on burnshot just before bend	RD: CW Pothole	Internal		Committed	50190224
Batch: 41249457 - Inspection Batch				Route: NW_CW1_West1			Date: 23/01/2026	
42197314	1 cw pothole	22/01/2026	Top of slip road from a90 northbound	RD: CW Pothole	Internal		Committed	50190172
Batch: 41248814 - Inspection Batch				Route: Ad hoc Route			Date: 17/01/2026	
42196790	Pothole	17/01/2026	just before the bridge west bound	RD: CW Pothole	Internal		Committed	50189795
Batch: 41247349 - Inspection Batch				Route: Ad hoc Route			Date: 08/01/2026	
42196253	Pothole	08/01/2026	At top of slip heading to kirkliston	RD: CW Pothole	Internal		Committed	50189372

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41244992 - Inspection Batch			Route:	Ad hoc Route			Date: 17/12/2025
42195411	Pothole at gully	17/12/2025	At junction of cragiehall camp junction	RD: CW Pothole	Internal		Committed	50188620
Batch:	41244446 - Inspection Batch			Route:	Ad hoc Route			Date: 12/12/2025
42195157	Pothole	12/12/2025	As soon as you exit the bend heading for crammond	RD: CW Pothole	Internal		Committed	50188426
Batch:	41244445 - Inspection Batch			Route:	Ad hoc Route			Date: 12/12/2025
42195156	Cracked broken road surface	12/12/2025	At pin location between bends	RD: CW Cracked/Broken	Internal		Uncommitted	50188425
Batch:	41243516 - Inspection Batch			Route:	NW_CW1_West1			Date: 02/12/2025
	No actionable defects found							
Batch:	41242016 - Inspection Batch			Route:	Ad hoc Route			Date: 19/11/2025
42193555	Cracked and broken carriageway	19/11/2025	Just before after/bend at pin area	RD: CW Cracked/Broken	Internal		Uncommitted	50187189
Batch:	41236332 - Inspection Batch			Route:	NW_CW1_West1			Date: 10/09/2025
	No actionable defects found							
Batch:	41235230 - Inspection Batch			Route:	Ad hoc Route			Date: 21/08/2025
42188854	Keep Clear markings required	21/08/2025	Outside entrance to Dalmeny Estate	RD: Markings New	Internal		Committed	50183931
Batch:	41233532 - Inspection Batch			Route:	Ad hoc Route			Date: 22/07/2025
42187455	Pothole on carriageway	22/07/2025	Heading west before railway bridge	RD: CW Pothole	Internal		Committed	50182936
Batch:	41232944 - Inspection Batch			Route:	Ad hoc Route			Date: 14/07/2025
42186992	Replace gully frame	14/07/2025	Junction Hillside Road	RD: Gully Damaged/Sunken	Internal		Committed	50182630
Batch:	41231791 - Inspection Batch			Route:	NW_CF1_BurnshotRd1			Date: 26/06/2025
	No actionable defects found							
Batch:	41231354 - Inspection Batch			Route:	Ad hoc Route			Date: 19/06/2025
42185817	Pothole on carriageway	19/06/2025	At Burnshot /Edinburgh junction	RD: CW Pothole	Internal		Committed	50181686
Batch:	41230620 - Inspection Batch			Route:	NW_CW1_West1			Date: 11/06/2025
42185413	2no potholes	11/06/2025	At the bus stop at Burnshot Lodge	RD: CW Pothole	Internal		Committed	50181215
Batch:	41227635 - Inspection Batch			Route:	Ad hoc Route			Date: 06/05/2025
42182994	Pothole on carriageway	06/05/2025	Heading west before railway bridge	RD: CW Pothole	Internal		Committed	50179595
Batch:	41227009 - Inspection Batch			Route:	Ad hoc Route			Date: 29/04/2025
42182406	Pothole on carriageway	29/04/2025	Heading west after West Craigleith Farm Road	RD: CW Pothole	Internal		Committed	50179227
Batch:	41225817 - Inspection Batch			Route:	Ad hoc Route			Date: 10/04/2025
42181093	Pothole on carriageway	10/04/2025	Heading west before railway bridge	RD: CW Pothole	Internal		Committed	50178416
Batch:	41223068 - Inspection Batch			Route:	Ad hoc Route			Date: 17/03/2025
42178836	Pothole on carriageway	17/03/2025	Heading west to Kirkliston before railway bridge	RD: CW Pothole	Internal		Committed	50177046

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41222447 - Inspection Batch			Route:	Ad hoc Route			Date: 12/03/2025
42178502	Pothole on carriageway	12/03/2025	Heading west at army houses	RD: CW Pothole	Internal		Committed	50176846
Batch:	41221924 - Inspection Batch			Route:	NW_CW1_West1			Date: 10/03/2025
42178128	2no potholes	10/03/2025	At the Burnshot Lodge bus stop	RD: CW Pothole	Internal		Committed	50176613
Batch:	41220694 - Inspection Batch			Route:	Ad hoc Route			Date: 26/02/2025
42177141	Potholes	26/02/2025	Coming down hill at beside bus lane	RD: CW Pothole	Internal		Committed	50175950
Batch:	41218244 - Inspection Batch			Route:	Ad hoc Route			Date: 10/02/2025
42175492	Pothole on carriageway	10/02/2025	Slip road from A90 at Burnshot Road	RD: CW Pothole	Internal		Committed	50174682
Batch:	41217213 - Inspection Batch			Route:	Ad hoc Route			Date: 03/02/2025
42174636	Pothole on carriageway	03/02/2025	Bus stop at bridge	RD: CW Pothole	Internal		Committed	50174050
Batch:	41216912 - Inspection Batch			Route:	Ad hoc Route			Date: 30/01/2025
42174449	Pothole on carriageway	30/01/2025	Heading west before railway bridge	RD: CW Pothole	Internal		Committed	50173913
Batch:	41213005 - Inspection Batch			Route:	NW_CW1_West1			Date: 07/01/2025
42172176	6no potholes	07/01/2025	No reference point please use pin location	RD: CW Pothole	Internal		Committed	50172217
42172174	2no potholes	07/01/2025	At the Burnshot Lodge bus stop	RD: CW Pothole	Internal		Committed	50172215
42172177	3no potholes	07/01/2025	No reference point please use pin location	RD: CW Pothole	Internal		Committed	50172218
42172178	1no pothole	07/01/2025	No reference point please use pin location	RD: CW Pothole	Internal		Committed	50172219
Batch:	41210894 - Inspection Batch			Route:	Ad hoc Route			Date: 13/12/2024
42171173	Permanent carriageway repair required	13/12/2024	From West Craigie Farm road to Carlowrie Farm	RD: CW Rutting	Internal		Archived	50171397
Batch:	41210088 - Inspection Batch			Route:	Ad hoc Route			Date: 09/12/2024
42170766	Pothole on carriageway	09/12/2024	Bus stop at end of slip road junction Burnshot Road	RD: CW Pothole	Internal		Committed	50171056
Batch:	41205814 - Inspection Batch			Route:	Ad hoc Route			Date: 30/10/2024
42167938	1no pothole	30/10/2024	At the Burnshot Lodge bus stop	RD: CW Pothole	Internal		Committed	50168917
Batch:	41204029 - Inspection Batch			Route:	Ad hoc Route			Date: 18/10/2024
42167043	Pothole on carriageway	18/10/2024	After West Craigie farm road heading west	RD: CW Pothole	Internal		Committed	50168263
Batch:	41202247 - Inspection Batch			Route:	NW_CW1_West1			Date: 03/10/2024
	No actionable defects found							
Batch:	41199790 - Inspection Batch			Route:	Ad hoc Route			Date: 03/09/2024
42164504	1no pothole	03/09/2024	At the Burnshot Lodge bus stop	RD: CW Pothole	Internal		Committed	50166054
Batch:	41197175 - Inspection Batch			Route:	Ad hoc Route			Date: 22/07/2024
42162182	Pothole on carriageway	22/07/2024	Slip road to A90 east from Burnshot Road	RD: CW Pothole	Internal		Committed	50164229

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41197171 - Inspection Batch			Route:	Ad hoc Route			Date: 22/07/2024
42162176	Pothole on carriageway	22/07/2024	Bus stop at Burnshot Road	RD: CW Pothole	Internal		Committed	50164225
Batch:	41196454 - Inspection Batch			Route:	Ad hoc Route			Date: 11/07/2024
42161497	4no potholes	11/07/2024	Slip rd from Burnshot rd heading northbound onto A90	RD: CW Pothole	Internal		Committed	50163740
Batch:	41195261 - Inspection Batch			Route:	NW_CW1_West1			Date: 24/06/2024
	No actionable defects found							
Batch:	41194926 - Inspection Batch			Route:	NW_CF1_BurnshotRd1			Date: 19/06/2024
	No actionable defects found							
Batch:	41194477 - Inspection Batch			Route:	Ad hoc Route			Date: 17/06/2024
42159889	Reset carriageway gully	17/06/2024	Heading west after A90 slip road	RD: Gully Damaged/Sunken	Internal		Committed	50162487
Batch:	41194476 - Inspection Batch			Route:	Ad hoc Route			Date: 17/06/2024
42159888	Pothole on carriageway	17/06/2024	Heading west after A90 slip road	RD: CW Pothole	Internal		Committed	50162486
Batch:	41194259 - Inspection Batch			Route:	Ad hoc Route			Date: 13/06/2024
42159697	Pothole on carriageway	13/06/2024	Bus stop at Burnshot flyover	RD: CW Pothole	Internal		Committed	50162298
Batch:	41188197 - Inspection Batch			Route:	Ad hoc Route			Date: 03/04/2024
42153536	1 pothole	03/04/2024	At the bus stop	RD: CW Pothole	Internal		Committed	50157271
Batch:	41187022 - Inspection Batch			Route:	NW_CW1_West1			Date: 20/03/2024
	No actionable defects found							
Batch:	41182345 - Inspection Batch			Route:	Ad hoc Route			Date: 13/02/2024
42147423	2no potholes	13/02/2024	At bus stop on slip rd	RD: CW Pothole	Internal		Committed	50152852
Batch:	41182087 - Inspection Batch			Route:	Ad hoc Route			Date: 09/02/2024
42147105	1no pothole	09/02/2024	Slip rd to A90 city bound	RD: CW Pothole	Internal		Committed	50152614
Batch:	41180815 - Inspection Batch			Route:	Ad hoc Route			Date: 31/01/2024
42145874	Pothole on carriageway	31/01/2024	In bus lane	RD: CW Pothole	Internal		Committed	50151817
Batch:	41178223 - Inspection Batch			Route:	Ad hoc Route			Date: 11/01/2024
42143794	Pothole on carriageway,overlay with hra	11/01/2024	Heading west before railway bridge	RD: CW Pothole	Internal		Committed	50149938
Batch:	41178222 - Inspection Batch			Route:	Ad hoc Route			Date: 11/01/2024
42143793	Pothole on carriageway,overlay with hra	11/01/2024	Heading east after railway bridge	RD: CW Pothole	Internal		Committed	50149937
Batch:	41174395 - Inspection Batch			Route:	Ad hoc Route			Date: 14/12/2023
42141908	Road: Defective / Damaged (Enquiry 1658230) pothole on carriageway	14/12/2023	Heading to Kirkliston	RD: CW Pothole	Internal		Committed	50148021
Batch:	41174255 - Inspection Batch			Route:	NW_CW1_West1			Date: 13/12/2023
42141739	3no potholes	13/12/2023	At the Burnshot Lodge bus stop	RD: CW Pothole	Internal		Committed	50147847

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c			Feature Type: Road Asset			Area: North West Locality	
Batch: 41170461 - Inspection Batch				Route: Ad hoc Route				Date: 30/10/2023
42138304	Pothole on carriageway	30/10/2023	Heading south to A90 from Burnshot Road	RD: CW Pothole	Internal		Committed	50144678
Batch: 41170269 - Inspection Batch				Route: Ad hoc Route				Date: 27/10/2023
42138105	Road: Defective / Damaged (Enquiry 1633921) pothole on carriageway	27/10/2023	Heading east to West Craigie Farm Road	RD: CW Pothole	Internal		Committed	50144563
Batch: 41170266 - Inspection Batch				Route: Ad hoc Route				Date: 27/10/2023
42138102	Road: Defective / Damaged (Enquiry 1633921) pothole on carriageway	27/10/2023	At railway bridge	RD: CW Pothole	Internal		Committed	50144560
Batch: 41168251 - Inspection Batch				Route: Ad hoc Route				Date: 10/10/2023
42137345	Pothole on carriageway	10/10/2023	Heading to Kirkliston from Burnshot slip road	RD: CW Pothole	Internal		Committed	50143832
Batch: 41167393 - Inspection Batch				Route: Ad hoc Route				Date: 02/10/2023
42136879	2no potholes	02/10/2023	Just before and at the Burnshot Lodge bus stop	RD: CW Pothole	Internal		Committed	50143394
Batch: 41164855 - Inspection Batch				Route: Ad hoc Route				Date: 13/09/2023
42136094	Carriageway edge broken approximately 0.5x6m	13/09/2023	See pin location	RD: CW Edge Deterioration	Internal		Committed	50142511
Batch: 41164225 - Inspection Batch				Route: NW_CW1_West1				Date: 05/09/2023
	No actionable defects found							
Batch: 41162247 - Inspection Batch				Route: Ad hoc Route				Date: 01/08/2023
42133082	Road: Defective / Damaged (Enquiry 1590289) permanent repair required to carriageway	01/08/2023	Heading to A90	RD: CW Rutting	Internal		Uncommitted	50140215
Batch: 41161973 - Inspection Batch				Route: Ad hoc Route				Date: 28/07/2023
42132944	1no pothole	28/07/2023	At the bus stop at Burnshot Lodge	RD: CW Pothole	Internal		Committed	50140069
Batch: 41159853 - Inspection Batch				Route: NW_CF1_BurnshotRd1				Date: 22/06/2023
	No actionable defects found							
Batch: 41158827 - Inspection Batch				Route: NW_CW1_West1				Date: 07/06/2023
	No actionable defects found							
Batch: 41151846 - Inspection Batch				Route: NW_CW1_West1				Date: 10/03/2023
42121927	1 cw pothole	10/03/2023	At bus stop on off slip for burnshot bridge	RD: CW Pothole	Internal		Committed	50131617
Batch: 41148206 - Inspection Batch				Route: Ad hoc Route				Date: 07/02/2023
42117682	Pothole on carriageway	07/02/2023	Heading east from Carlowrie farm	RD: CW Pothole	Internal		Committed	50128573
Batch: 41148121 - Inspection Batch				Route: Ad hoc Route				Date: 06/02/2023
42117576	Road: Defective / Damaged (Enquiry 1504186) pothole on carriageway	06/02/2023	Entrance to Kirkliston at 30 mph sign	RD: CW Pothole	Internal		Committed	50128494

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41148120 - Inspection Batch			Route:	Ad hoc Route			Date: 06/02/2023
42117575	Road: Defective / Damaged (Enquiry 1504186) pothole on carriageway	06/02/2023	Heading east from railway bridge at top of hill	RD: CW Pothole	Internal		Committed	50128493
Batch:	41146726 - Inspection Batch			Route:	Ad hoc Route			Date: 26/01/2023
42116558	Road: Defective / Damaged (Enquiry 1488080) pothole on carriageway	26/01/2023	Heading east after railway bridge	RD: CW Pothole	Internal		Committed	50127606
Batch:	41142521 - Inspection Batch			Route:	Ad hoc Route			Date: 06/01/2023
42114361	Road: Defective / Damaged (Enquiry 1481336) pothole on carriageway	06/01/2023	Heading west from A90	RD: CW Pothole	Internal		Committed	50125524

Customer Services**Enquiry No.:** 2131427**Logged by:** Verint CRM Connector**on:** 15/04/2026 21:35**Service:** Roads General**Subject:** Road: Defective / Damaged**Classification:** Request for service**Desc.:****Location:** Massive potholes over hundreds of yards**Contact:****Plot Number:** 1.00**Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c**Feature Type:** Road Asset**Enquiry No.:** 2130677**Logged by:** Verint CRM Connector**on:** 14/04/2026 17:48**Service:** Roads General**Subject:** Road: Defective / Damaged**Classification:** Request for service**Desc.:****Location:** Large pothole on the bend**Contact:****Plot Number:** 1.00**Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c**Feature Type:** Road Asset**Job Number:** 50195408**Defect Number:** 42204200**Enquiry No.:** 2125926**Logged by:** Verint CRM Connector**on:** 06/04/2026 12:51**Service:** Roads General**Subject:** Road: Defective / Damaged**Classification:** Request for service**Desc.:****Location:** Pothole in left lane heading into Edinburgh**Contact:****Plot Number:** 1.00**Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c**Feature Type:** Road Asset**Enquiry No.:** 2124266**Logged by:** Verint CRM Connector**on:** 02/04/2026 12:33**Service:** Roads General**Subject:** Road: Defective / Damaged**Classification:** Request for service**Desc.:****Location:** The whole stretch of road from the cottage's to the Craigs farm turn off is riddles with

pot holes . Cars frequently drive in the middle

Of the road to avoid them and it's very dry unsafe for cyclists because of this too.

Past pothole repairs hav failed following just one bad wet winter. The stretch of road

needs resurfaced.

Contact:**Plot Number:** 1.00**Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c**Feature Type:** Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 2123332	Logged by: Verint CRM Connector	on: 01/04/2026 08:02
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Huge pothole, damaged my tyre. This is the largest but there are others in this area almost as big. It is genuine dangerous as causing people to swerve		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2121885	Logged by: Verint CRM Connector	on: 30/03/2026 00:11
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Road is in a mess and almost causing accidents with trying to avoid damage to cars due to the state of the road.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2121580	Logged by: Verint CRM Connector	on: 29/03/2026 12:25
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Slalom driving on this road		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2121578	Logged by: Verint CRM Connector	on: 29/03/2026 12:23
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: More potholes that are becoming worse		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2121299	Logged by: Verint CRM Connector	on: 28/03/2026 13:56
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Dangerous, probably over 50 pot holes		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2121297	Logged by: Verint CRM Connector	on: 28/03/2026 13:52
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Between the s bend and the end of burnshot road, its a disgrace, pot holes everywhere. Its very dangerous.		
Contact:		
Sadly due to the area, its difficult and dangerous to get photos of them all		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2120753	Logged by: Verint CRM Connector	on: 27/03/2026 10:47
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Multiple large, deep potholes on the westbound side of the road. I've witnessed cars going onto the other side of the road to avoid them.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 2120743	Logged by: Verint CRM Connector	on: 27/03/2026 10:40
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Multiple large and deep potholes in the same area. Almost impossible to miss them as they are spread out across the road.		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50193440	Defect Number: 42203260	
Enquiry No.: 2119773	Logged by: Verint CRM Connector	on: 25/03/2026 16:14
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Pavement narrow due to years of undergrowth. One side of pavement has been cleared in recent weeks. However the main path used by resident to bus stop is still narrow in places. Not suitable for prams or buggies or with small children.		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2119400	Logged by: Verint CRM Connector	on: 25/03/2026 08:02
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Several large potholes on this road (both sides) that are causing cars to swerve and add high risk of incident. Location selected on the map and corner before are in severe need of repair		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2117280	Logged by: Verint CRM Connector	on: 21/03/2026 17:59
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Several potholes on both sides of road		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2117278	Logged by: Verint CRM Connector	on: 21/03/2026 17:58
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Huge potholes		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50194595	Defect Number: 42203089	
Enquiry No.: 2117254	Logged by: Verint CRM Connector	on: 21/03/2026 17:12
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Several potholes after the cutting as you head towards Cramond		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 2116461	Logged by: Verint CRM Connector	on: 20/03/2026 08:52
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a large hole in the road. It seems to be a rectangle so metal cover may have been past the junction approximately 100m down the road on the Edinburgh bound side, inside lane.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2116285	Logged by: Verint CRM Connector	on: 19/03/2026 19:05
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There are extremely deep potholes on the eastbound carriageway along this section of road, particularly from the rail bridge as indicated on the map all the way up until the bend at the forestry. They are going to cause significant damage to travelling vehicles.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2113905	Logged by: Verint CRM Connector	on: 16/03/2026 18:07
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Prior to the bus lane. As the traffic from Kirkliston merges with A90		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2112440	Logged by: Verint CRM Connector	on: 14/03/2026 08:37
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole under bridge and another just a little on from it		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2112430	Logged by: Verint CRM Connector	on: 14/03/2026 07:37
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Potholes all along this road		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2109690	Logged by: Verint CRM Connector	on: 10/03/2026 09:08
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole on east bound lane		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2103864	Logged by: Verint CRM Connector	on: 27/02/2026 21:33
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Nearly this whole road has severe potholes and/or a crumbling road surface. It is quite dangerous to drive on.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 2103355	Logged by: Verint CRM Connector	on: 27/02/2026 09:23
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Worst of the potholes as you approach up the hill from the kirkliston side towards craigies.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2102432	Logged by: Verint CRM Connector	on: 25/02/2026 20:20
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The whole stretch from craigies farm turnoff to the narrow road to kirliston is terrible. So many potholes!!!!		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2101735	Logged by: Verint CRM Connector	on: 25/02/2026 06:04
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large potholes in middle of road.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50192976	Defect Number: 42200819	
Enquiry No.: 2101734	Logged by: Verint CRM Connector	on: 25/02/2026 06:02
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2100957	Logged by: Verint CRM Connector	on: 23/02/2026 21:52
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Sunken drain 3. Pothole		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2100955	Logged by: Verint CRM Connector	on: 23/02/2026 21:50
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Sunken drain pothole 1		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50192966	Defect Number: 42200808	

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 2100543 Logged by: Verint CRM Connector on: 23/02/2026 12:45
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:
 Location: Almost the entire section of Burnshot road from Craighall to the railway bridge is cratered with potholes. People are swerving into opposite lanes to avoid potholes and clearly driving just looking at the road immediately ahead of them. There are way too many serious potholes to begin to report each individually. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c Feature Type: Road Asset

Enquiry No.: 2098166 Logged by: Verint CRM Connector on: 19/02/2026 07:48
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:
 Location: Broken road Contact:
 Report ID: 8950064

Category: Potholes
 Months of hell here

Location:
 Easting/Northing: 315496/675683 (55.966692, -3.35535)
 Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): City of Edinburgh, Alba / Scotland, EH30 9AR, United Kingdom
 Nearest postcode to the pin placed on the map (automatically generated): EH30 9AR (794m away)

Plot Number: 1.00 Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c Feature Type: Road Asset

Enquiry No.: 2095857 Logged by: Verint CRM Connector on: 16/02/2026 08:37
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:
 Location: I raised a problem yesterday at 06:40 I have now added photos for reference Contact:

Plot Number: 1.00 Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c Feature Type: Road Asset

Enquiry No.: 2094803 Logged by: Verint CRM Connector on: 13/02/2026 20:01
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:
 Location: Pot holes across a lot of the road, before and after the bend. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c Feature Type: Road Asset

Enquiry No.: 2094450 Logged by: Verint CRM Connector on: 13/02/2026 12:21
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service

Desc.:
 Location: Broken surface Contact:

Plot Number: 1.00 Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 2093070	Logged by: Verint CRM Connector	on: 11/02/2026 19:23
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The westbound carriage way on the Butnshot road going downhill round the bend just after Craigie Farm is full of potholes. Some are central but two on the bend are really dangerous and completely unavoidable. The burnshot road after Craigie Farm is a disgrace but that bend and the road leading up to the cottages is simply unacceptable.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2092957	Logged by: Verint CRM Connector	on: 11/02/2026 16:23
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Destroyed road. Potholes on top of potholes. Don't patch it again. Resurface it		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2092953	Logged by: Verint CRM Connector	on: 11/02/2026 16:20
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The entire road section needs resurfaced. Absolutely destroying my car to get to work. Dont just patch it again. Completely resurface		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2092228	Logged by: Verint CRM Connector	on: 10/02/2026 17:52
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Multiple potholes		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2091829	Logged by: Verint CRM Connector	on: 10/02/2026 09:42
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pot hole where just after Burnshott slip road where you join A90		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2091501	Logged by: Verint CRM Connector	on: 09/02/2026 16:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pot hole		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2090720	Logged by: Verint CRM Connector	on: 08/02/2026 12:03
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Come and have a look, this road is in pieces and not safe to cycle on.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 2089554	Logged by: Verint CRM Connector	on: 05/02/2026 18:50
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Travelling west bound	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2089552	Logged by: Verint CRM Connector	on: 05/02/2026 18:47
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Travelling west bound	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2089549	Logged by: Verint CRM Connector	on: 05/02/2026 18:45
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Travelling west bound	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2089548	Logged by: Verint CRM Connector	on: 05/02/2026 18:44
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Travelling west bound	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2088775	Logged by: Verint CRM Connector	on: 04/02/2026 15:33
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Very poor road condition with several deep potholes. The worst potholes on Burnshot Road are the ones just after Craigies Farm junction when heading from Edinburgh towards Kirkliston. The potholes caused damage to my car and broke a springcoil which I'm looking to claim compensation for.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2088293	Logged by: Verint CRM Connector	on: 03/02/2026 21:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Multiple potholes	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2088188	Logged by: Verint CRM Connector	on: 03/02/2026 17:23
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Several unavoidable holes on this section and to be honest the entire road is embarrassing and a serious health and safety hazard.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 2088111 **Logged by:** Verint CRM Connector **on:** 03/02/2026 15:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Horrendous potholes cover approx 50 metres heading west **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Enquiry No.: 2088022 **Logged by:** Verint CRM Connector **on:** 03/02/2026 13:48
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Multiple pot holes along this road, particularly this location. Cars are going a minimum of 40mph so this is causing damage and also is dangerous to slow down right before a bend with cars behind. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Enquiry No.: 2087652 **Logged by:** Verint CRM Connector **on:** 02/02/2026 21:54
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Horrific deep pot holes unavoidable as there is so many next to each other. Massive accusations waiting to happen **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Enquiry No.: 2087575 **Logged by:** Verint CRM Connector **on:** 02/02/2026 19:19
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Multiple potholes and extremely dangerous at present. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Enquiry No.: 2086968 **Logged by:** Verint CRM Connector **on:** 01/02/2026 20:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There is a series of large potholes stretching some 30 meters on Burnshot road heading from Craigiehall Camp to Kirkliston, approx 2/3 of mile from Craigiehall before a right hand bend through woodland. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Enquiry No.: 2086728 **Logged by:** Verint CRM Connector **on:** 01/02/2026 12:12
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Several large potholes in the road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Enquiry No.: 2086634 **Logged by:** Verint CRM Connector **on:** 01/02/2026 08:44
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole in middle of road. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 2086627	Logged by: Verint CRM Connector	on: 01/02/2026 08:40
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: A number of very large potholes. This side of the road is almost impassable without damage and cars are now driving on the opposite side of the road to avoid these, which is already dangerous, however this corner is a blind corner and oncoming vehicles can't be seen coming round the corner - very dangerous.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2086429	Logged by: Verint CRM Connector	on: 31/01/2026 14:17
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Road badly breaking up with significant number of large deep potholes.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2086082	Logged by: Verint CRM Connector	on: 30/01/2026 17:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The road surface is terrible along that road. Can't avoid it due to being across most of the road.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50190842	Defect Number: 42198150	
Enquiry No.: 2084037	Logged by: Verint CRM Connector	on: 27/01/2026 18:47
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Severe damage to this section of the road which has lead to £840 plus on car repairs. Please make this section on the burnshot road a priority. Car's are swerving pot holes this could clearly lead to road accidents.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2082851	Logged by: Verint CRM Connector	on: 26/01/2026 08:05
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: significant pothole on left hand soide of the carriageway heading towards kirkliston. I have reported this before and it hasnt been actioned, if my car gets damaged as a result of this pothole, and the others I have reported in the area, then I will take action to recover any costs. I appreciate budgets are tight but this is dangerous.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2082253	Logged by: Verint CRM Connector	on: 24/01/2026 15:32
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Multiple potholes, drivers swerving to avoid, many sections of this road requiring attention		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 2080855	Logged by: Verint CRM Connector	on: 21/01/2026 22:06
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Multiple potholes along road between (55.9660759, -3.3614520) and (55.9670810, -3.3527596) - EH309TN		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2078970	Logged by: Verint CRM Connector	on: 19/01/2026 10:42
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: multiple pothole which dangerously unsettle your car even at low speed going into a reverse camber bend. Please have a look at this as soon as you can, I know money is tight but this is a busy wee road and it is in a very poor state of repair.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2078861	Logged by: Verint CRM Connector	on: 19/01/2026 08:41
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole on the inside of the east bound lane. The whole area is littered with potholes and needs urgent attention because at night vehicles are swerving at the last minute to avoid them!		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2078489	Logged by: Verint CRM Connector	on: 18/01/2026 11:18
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Heading west on Burnshot road towards Kirkliston after the turning for Craigies farm, several potholes just before bend		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50190224	Defect Number: 42197378	
Enquiry No.: 2076626	Logged by: Verint CRM Connector	on: 15/01/2026 08:11
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: multiple potholes		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2076625	Logged by: Verint CRM Connector	on: 15/01/2026 08:09
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: just round the bend heading to Kirkliston		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 2076623	Logged by: Verint CRM Connector	on: 15/01/2026 08:08
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: pothole just before the bridge	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50189795	Defect Number: 42196790	
Enquiry No.: 2075404	Logged by: Verint CRM Connector	on: 13/01/2026 12:42
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Somewhere along this road, heading southbound, is the worst pothole known to mankind. In the dark, it's impossible to avoid, right in the path of the offside wheels, hit at speed it felt like it could destroy a car's suspension or steering rack, or someones spine...	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2073991	Logged by: Verint CRM Connector	on: 11/01/2026 12:34
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Both sides of the road are breaking up and pothole repairs have made the surface very uneven	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2071181	Logged by: Verint CRM Connector	on: 06/01/2026 16:26
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: The complete pavement from entrance of hillside road to the burn shot flyover is inaccessible for walking . This was also reported on tve 5th august	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2062313	Logged by: Verint CRM Connector	on: 22/12/2025 15:46
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: south side of the carriageway near the middle.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2058919	Logged by: Verint CRM Connector	on: 15/12/2025 15:47
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large, suspension breaking potholes along this section of road on both sides.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2058479	Logged by: Verint CRM Connector	on: 14/12/2025 22:23
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There's a pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 2056231	Logged by: Verint CRM Connector	on: 10/12/2025 15:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Burn-shot road heading east pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2054777	Logged by: Verint CRM Connector	on: 08/12/2025 11:24
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: As soon as you exit the bend heading for Edinburgh there is a large hole on the n/s of the surface that is filling with water and is hard to see in the dark. Will take a cyclist off a bike, puncture a car tyre and case wheel damage.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50188426	Defect Number: 42195157	
Enquiry No.: 2053676	Logged by: Verint CRM Connector	on: 05/12/2025 08:12
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The surface is breaking up and is very uneven which unsettles the car when going into the corner driving towards Kirkliston.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2053673	Logged by: Verint CRM Connector	on: 05/12/2025 08:07
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole just as you come around the corner heading towards Barnton. Itr unsettles the car, very dangerous	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 2043948	Logged by: Verint CRM Connector	on: 16/11/2025 14:18
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large deep pothole on the side of the road traveling east (side furthest away from the airport). Could catch a cyclist/driver by surprise after coming round the corner.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50187189	Defect Number: 42193555	

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 2043899 **Logged by:** Verint CRM Connector **on:** 16/11/2025 12:54
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: Section of pavement from turn off to Hillside Road along Burnshot Road towards Burnshot Bridge. **Contact:**

Yes, I know this has been reported already but nothing has been done yet, despite there being a crew within a mile two weeks ago. This pavement is so overgrown IT IS DANGEROUS. Please do something about it.

It's now dark when people go to the bus stop for work AND when they return, and cars drive dangerously fast along this road. Does someone have to be clipped by a vehicle before anything is done?

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Enquiry No.: 2003485 **Logged by:** Verint CRM Connector **on:** 26/08/2025 12:09
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: The road and pavement behind these houses are an absolute disgrace leaves taking up half the pavement and overhanging trees from the land belonging to Millar developments are dangerously overhanging **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Enquiry No.: 2000240 **Logged by:** Verint CRM Connector **on:** 20/08/2025 16:19
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: Thank you for your help. The pavement along this stretch of Burnshot road is extremely overgrown. In some parts there is barely enough pavement to walk on and the cars come frighteningly close. There is no space for wheeling luggage so you have to do it on the road, jumping back on the kerb each time a car comes. There is also no street lighting here on the way to the Burnshot flyover bus stop, so nothing for quite a long way, so it requires a torch. I have a video but it won't upload. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Enquiry No.: 1999341 **Logged by:** Verint CRM Connector **on:** 19/08/2025 13:21
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Could we please have a "Keep Clear" here so that we can exit the Dalmeny Estate safely over the Burnshot flyover. Traffic regularly gets backed up along the A90 heading into Edinburgh. Edin bound A90 traffic trying to leapfrog persistently come up the Burnshot slip only to go back down again causing gridlock at the Dalmeny estate exit. If queuing traffic left a small gap then we could get out. "Keep Clear" road markings would allowing a safe path out and over the bridge towards Kirkliston. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Job Number: 50183931 **Defect Number:** 42188854

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 1997728 **Logged by:** Verint CRM Connector **on:** 16/08/2025 16:55
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: These potholes have since been filled. However, when driving on this road on 31 May 2025, these potholes damaged my car, so I am reporting it here to get a reference number to make a claim. **Contact:**

They were on the southbound slip from the A90 to Burnshot Bridge, just before the junction.

I will not provide a photo here as they have since been filled and do not have jpeg photos on my phone.

Will provide evidence in my claim form email.

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Enquiry No.: 1994078 **Logged by:** Verint CRM Connector **on:** 11/08/2025 13:30
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: This pavement is very badly overgrown, and tree branches are hanging low above it. Residents from Hillside Road must use this pavement to get to and from bus stops. Cars are driven very fast along that road (NOT at 40, I can assure you) and it's becoming increasingly uncomfortable/dangerous walking beside it. Please do something about this before winter. The road is not lit so any pedestrians are going to be in an even more precarious situation. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Enquiry No.: 1977364 **Logged by:** Verint CRM Connector **on:** 13/07/2025 11:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Drain has dropped at entrance of hillside road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Job Number: 50182630 **Defect Number:** 42186992

Enquiry No.: 1972073 **Logged by:** Verint CRM Connector **on:** 02/07/2025 09:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: This whole strip of road is dangerous with holes!! **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Enquiry No.: 1967278 **Logged by:** Verint CRM Connector **on:** 23/06/2025 12:38
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Obscuring sight line.

Location:Road.
Type:Foliage / Bush

Location: Overgrown foliage substantially blocking junction line of sight for joining traffic even when at complete stop. Risk of high speed collision as result **Contact:**

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 1965673	Logged by: Verint CRM Connector	on: 18/06/2025 18:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: two potholes, one big enough to cause the glass to fall out of my wing mirror!	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50181686	Defect Number: 42185817	
Enquiry No.: 1945901	Logged by: Verint CRM Connector	on: 10/05/2025 00:53
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: I want to report pavement problem. This is a road towards kirkliston & Craigiehall. There are now people living at Craigiehall. To get to the estate from a bus stop it is very hard as the pavements are over grown with trees, wild gras, bushes etc which is making dangerous to walk and cars on that road drive quite fast. I would like to report this and ask Council to cut the trees and clear the pavements to make them wider and safer for the community there. I have but image to large to upload	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1940070	Logged by: Verint CRM Connector	on: 28/04/2025 19:34
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: several potholes, westbound carriageway, been there for six months at least	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50179227	Defect Number: 42182406	
Enquiry No.: 1930361	Logged by: Verint CRM Connector	on: 08/04/2025 11:08
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: The path on the main road along from Burnshot Bridge is really over grown and makes it dangerous to walk along with my dog as we are very close to the road. I have recently moved into 5 Hillside Road on the other side as the street is under development. I understand that these houses have been left empty for a long time however more people are moving in now and need to use this pavement to access the bus stop and road into Barnton/Cramond. Please can this be dealt with and maintained? Thanks.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1929401	Logged by: Verint CRM Connector	on: 06/04/2025 17:35
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There are numerous potholes on Burnshot Road well beyond Cragies Farm Road which require repairing. This stretch covers the length of Burnshot past the first farm close to the rail bridge and up to within a 100 metres to Kirkliston.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50178416	Defect Number: 42181093	

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 1928253	Logged by: Verint CRM Connector	on: 03/04/2025 18:53
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The road is covered in potholes. I have previously reported this and received an email that it had been dealt with but this was incorrect. This area is dangerous as it's causing cars to avoid the holes by driving on the wrong side of the road.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50179595	Defect Number: 42182994	
Enquiry No.: 1927175	Logged by: Verint CRM Connector	on: 02/04/2025 07:20
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Multiple potholes. Surface disintegrating.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1924369	Logged by: Verint CRM Connector	on: 27/03/2025 10:46
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Category 1 – critical risk, repaired within 24 hours		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1921175	Logged by: Verint CRM Connector	on: 20/03/2025 16:00
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.:		
Location: Pavement leading towards burnshot flyover at lowood entrance is a terrible mess with overhanging trees and roots growing through the pavement which makes it hard for pedestrians and cyclists to use the pavements, also the pavements along the back off hillside road is in a terrible mess assuming due to the houses there not being lived in ove the last few years		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1918482	Logged by: Verint CRM Connector	on: 15/03/2025 11:55
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: After the bend past Craigie Hill		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50177046	Defect Number: 42178836	
Enquiry No.: 1915158	Logged by: Verint CRM Connector	on: 08/03/2025 16:27
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Surface is crumbling. Lots of potholes. Traffic wide on road to avoid. Becomes a hazard to oncoming vehicles. Over approx. 40m.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026
 Service: Roads General
 Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00
 Display Action Officer: No

Customer Services

Enquiry No.: 1915154 **Logged by:** Verint CRM Connector **on:** 08/03/2025 16:20
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole. Beside drain. Deep and getting wider. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset
Job Number: 50176846 **Defect Number:** 42178502

Enquiry No.: 1899402 **Logged by:** Verint CRM Connector **on:** 05/02/2025 21:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Hi I reported this the other day (reference number 101002934935.). I received an email stating the job has been completed. It hasn't. Please confirm status. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Enquiry No.: 1896699 **Logged by:** Verint CRM Connector **on:** 01/02/2025 10:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Massive pothole opposite bus stop at Burnshot Lodge **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset
Job Number: 50174050 **Defect Number:** 42174636

Enquiry No.: 1895380 **Logged by:** Verint CRM Connector **on:** 29/01/2025 19:41
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Massive potholes you cannot miss them. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Enquiry No.: 1894853 **Logged by:** Verint CRM Connector **on:** 29/01/2025 08:29
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Multiple potholes on the westbound side of the road causing traffic to move to the oncoming lane. Dangerous **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset
Job Number: 50173913 **Defect Number:** 42174449

Enquiry No.: 1889380 **Logged by:** Verint CRM Connector **on:** 20/01/2025 09:14
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Hi All **Contact:**

I wish to report a pothole along the A90 Edinburgh Dunfermline road . I happen to have hit the pothole and it damaged the rear right passenger tyre of my Tesla model 3 Si69xan .I was driving from Edinburgh to Dunfermline on Wednesday 16 January2025 between 6pm and 7pm . I hit the pothole with the right wheels and there was a loud noise . In the morning I realised the tyre pressure for the rear right passenger tyre had dropped from 41psi to 35psi I then noticed a buldge on the tyre . Please confirm how I report this issue

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 1887936	Logged by: Verint CRM Connector	on: 16/01/2025 18:25
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Take your pick multiple potholes here	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1887680	Logged by: Verint CRM Connector	on: 16/01/2025 12:28
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pot holes are shocking on this road and causing so many burst tyres and people have to drive on opposite side of road which is a danger to on coming traffic	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1887421	Logged by: Verint CRM Connector	on: 16/01/2025 06:59
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Potholes are dangerous. I hit them on my bike again after reporting them months ago.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1870054	Logged by: Verint CRM Connector	on: 11/12/2024 16:38
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Heading from Edinburgh towards Kirkliston just past the Craigie farm turn off, the road goes from good to crap. There is now a huge pothole. Then further down under the bridge outside a dilapidated farm there are numerous lumps, bumps and holes.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50171397	Defect Number: 42171173	
Enquiry No.: 1868335	Logged by: Verint CRM Connector	on: 07/12/2024 16:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Approx. 10m short of the junction between the A90 sliproad and Burnshot bridge. By the bus stop. There are two separate potholes at least 15cm deep, with steep edges, and infilled with water. There is evidence of prior repair work that is either failed or incomplete, and no signage or warnings to oncoming traffic.	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50171056	Defect Number: 42170766	
Enquiry No.: 1851308	Logged by: Verint CRM Connector	on: 29/10/2024 19:43
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Destroyed road on approach to Kirkliston/SQ. Before bend. Massive potholes cause massive puddles to collect and you don't see potholes and go right into them. Needs resurfacing asap	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 1845932	Logged by: Verint CRM Connector	on: 17/10/2024 15:57
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Huge potholes in this area with one really bad one that is unavoidable. Don't know why the resurfacing wasn't extended to the end of this stretch of road when it was done.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50168263	Defect Number: 42167043	
Enquiry No.: 1832428	Logged by: Verint CRM Connector	on: 16/09/2024 12:55
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: All the back road,across from the Airport,has large broken areas/potholes,all the way,from where,the army barracks were,to Kirkliston.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1831314	Logged by: Verint CRM Connector	on: 13/09/2024 09:13
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The road from burnshot bridge to carlowrie cottages is terrible. Cars are now driving on the wrong side of the road to avoid the pot holes and uneven road, which is eventually going to cause accidents as they are near 2 bends.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1827864	Logged by: Verint CRM Connector	on: 05/09/2024 17:47
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: pothole on road going west after craigies farm turnoff		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1801372	Logged by: Verint CRM Connector	on: 19/07/2024 11:20
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Could you please check road surface on this slip road please. It's between Burnshot Farmhouse all the way to where the slip road joins A90. Small potholes in various locations		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50164229	Defect Number: 42162182	
Enquiry No.: 1801368	Logged by: Verint CRM Connector	on: 19/07/2024 11:17
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: pothole on bus stop at the top of the slip road		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50164225	Defect Number: 42162176	

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 1780311	Logged by: Verint CRM Connector	on: 13/06/2024 17:04
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Issue is the terrible condition of the road and cars have to veer out of lane to not damage their cars. The road had been resurfaced up to this point and as you hit the start of the section that wasn't resurfaced, there are potholes and crumbling tarmac		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1779635	Logged by: Verint CRM Connector	on: 13/06/2024 05:02
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Burnshot flyover bus stop,		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50162298	Defect Number: 42159697	
Enquiry No.: 1772694	Logged by: Verint CRM Connector	on: 05/06/2024 08:47
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The road from burnshot bridge(burnshot road) west bound in particular near carlowrie farm is full of potholes, gouges in the road. It is almost undriveable at one bend. This is a very busy commuting road.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1768820	Logged by: Verint CRM Connector	on: 31/05/2024 14:35
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: This road from the entrance to Craigies Farm shop road, exhibits pot holes which continue for about 1.5 miles towards Kirkliston		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1732995	Logged by: Verint CRM Connector	on: 08/04/2024 19:44
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: West bound carriageway		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1695893	Logged by: Verint CRM Connector	on: 08/02/2024 18:33
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Big pot hole on way into town before Cramond Brig. Inside lane. Thought I had jiggered my tyre seems okay not good for wheel alignment.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1695550	Logged by: Verint CRM Connector	on: 08/02/2024 11:44
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large potholes just where the slip road joins the A90 city bound		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 1695200	Logged by: Verint CRM Connector	on: 07/02/2024 19:52
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Big pothole on A90 in between slip and bus lane on A90		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1694953	Logged by: Verint CRM Connector	on: 07/02/2024 14:33
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole in the carriageway which is unavoidable for large vehicles.		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1688822	Logged by: Verint CRM Connector	on: 30/01/2024 10:29
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large potholes within the bus lane citybound.		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50151817	Defect Number: 42145874	
Enquiry No.: 1688344	Logged by: Verint CRM Connector	on: 29/01/2024 15:07
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Left hand side of road going towards Edinburgh. Giant pothole often in puddle after rail bridge.		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1685291	Logged by: Verint CRM Connector	on: 25/01/2024 09:18
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pot hole		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1684550	Logged by: Verint CRM Connector	on: 24/01/2024 11:57
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Just after you merge onto the A90 from the Burnshot Road, this pothole was filled last year and has now opened up again		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1678655	Logged by: Verint CRM Connector	on: 15/01/2024 16:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Burnshot road is in general disrepair and several potholes are growing daily due to the lack of maintenance and improper previous repairs. The road markings (white lines) need to be repainted to indicate to larger vehicles that they can't take up the whole road.		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 1678479	Logged by: Verint CRM Connector	on: 15/01/2024 13:40
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Road has eroded just after Craigies Farm heading West towards Kirkliston. further deep potholes have opened up between the erosion point and the live railway bridge		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1678086	Logged by: Verint CRM Connector	on: 15/01/2024 08:15
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Broken manhole grille cover on southerly aspect of road		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1677966	Logged by: Verint CRM Connector	on: 14/01/2024 20:05
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: A series of severe potholes. Nearly crashed trying to avoid them.		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1677853	Logged by: Verint CRM Connector	on: 14/01/2024 16:46
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: large potholes and broken road		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1677394	Logged by: Verint CRM Connector	on: 13/01/2024 14:49
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The road from just beyond the entrance to Craigies Farm shop has multiple dangerous pot holes, these continue to more random pop holes after the rail bridge in the direction of Kirkliston		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1677389	Logged by: Verint CRM Connector	on: 13/01/2024 14:34
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Horrendous gigantic potholes. Absolutely dangerous and cars will end up having flat tyres through this section. It's hard to avoid them as the whole section has potholes.		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1677387	Logged by: Verint CRM Connector	on: 13/01/2024 14:33
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: All this stretch from Craigie's needs to be replaced as uneven and huge potholes. You have zigzag along the road avoiding the potholes. It's ridiculous.		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 1677185	Logged by: Verint CRM Connector	on: 13/01/2024 01:47
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: This whole road is absolutely filled of potholes I hit one tonight and have burst my tyre not happy at all I'll be putting in a claim for the damages to my car the whole road needs checked in to Edinburgh and kirkliston it's an absolute joke the amount of potholes on this road		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1676498	Logged by: Verint CRM Connector	on: 11/01/2024 20:24
Service: Roads General	Subject: Road: Missing Setts / Blocks	Classification: Customer Emergency
Desc.:		
Location: This section of road is a disgrace.. the company that cover the holes doesn't so it properly.. 2 weeks after the holes are open again.		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1676457	Logged by: Verint CRM Connector	on: 11/01/2024 19:26
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Numerous potholes and crumbling road		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1669372	Logged by: Verint CRM Connector	on: 01/01/2024 16:18
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Really bad uneven surface and a ridiculous amount of pot holes		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1667324	Logged by: Verint CRM Connector	on: 28/12/2023 09:20
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Wheel wrecking pot holes appearing - a new one every day!		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1664354	Logged by: Verint CRM Connector	on: 19/12/2023 23:04
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: numerous potholes		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1662474	Logged by: Verint CRM Connector	on: 15/12/2023 18:45
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Potholes		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 1660235	Logged by: Verint CRM Connector	on: 12/12/2023 12:55
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Along the road leading from Queensferry Road towards Craigies Farm turn off there's a massive pothole that needs addressing as I found out to my cost. It was either just before or just after the Craigies turn off. I had to spend £300 on a new tire because of this!! Queensferry Road also has intermittent issues with potholes. The worst are around grids. There's no chance of avoiding them without suddenly veering into the next lane, which is obviously incredibly dangerous.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1658230	Logged by: Verint CRM Connector	on: 08/12/2023 19:11
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Two potholes, on on the left one close to the middle of the road so difficult to avoid them both (travelling from Edinburgh)		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50148021	Defect Number: 42141908	
Enquiry No.: 1639013	Logged by: Verint CRM Connector	on: 05/11/2023 14:56
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole before the road forks heading towards Edinburgh.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1633921	Logged by: Verint CRM Connector	on: 26/10/2023 20:09
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Burnshot road heading to Kirkliston from the a90 the stretch of road from Craigie farm all the way to the cottages at carlowrie have pot holes galore and getting deeper by the day. A large section of the road many are central road		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50144560	Defect Number: 42138102	
Enquiry No.: 1627068	Logged by: Verint CRM Connector	on: 12/10/2023 11:01
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Junction from queensferry Road to kirkliston. Burnshot Bridge/Road large pot hole.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1626996	Logged by: Verint CRM Connector	on: 12/10/2023 09:30
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Slip road coming from A90 towards Burnshot going towards Kirkliston. Must be muddle if the road as hot front right tyre - drivers side.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 1626454	Logged by: Verint CRM Connector	on: 11/10/2023 07:06
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: When you enter burnshot road exit from Queensferry, right on the junction there is a big and deep pothole. Day time cars do a aid if but at night and in rain it's difficult to see		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1625848	Logged by: Verint CRM Connector	on: 09/10/2023 22:51
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a huge pothole on the A90 northbound slip road towards Craigiehall, just as you approach the Burnshot Bridge. This is particularly dangerous as I found out myself in the dark and is an accident waiting to happen.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1625392	Logged by: Verint CRM Connector	on: 09/10/2023 10:37
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a pothole on the slip near the top		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1624892	Logged by: Verint CRM Connector	on: 07/10/2023 23:14
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Deep hole could cause accident, especially if motorcycle were to hit it. No street lighting so not able to see the hole.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1624282	Logged by: Verint CRM Connector	on: 06/10/2023 11:45
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Two potholes close to middle of road		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1623971	Logged by: Verint CRM Connector	on: 05/10/2023 19:09
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Two potholes quite close together		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1620185	Logged by: Verint CRM Connector	on: 28/09/2023 09:42
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: This pothole is getting bigger and bigger.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 1615955	Logged by: Verint CRM Connector	on: 18/09/2023 20:05
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole, it's possible to avoid it if you know where it is but if you don't ignore the stripy lines you painted a few weeks ago you'll hit the pothole. It's a joke, how can you spend all that money on painting lines and not fill the potholes?		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1584880	Logged by: Verint CRM Connector	on: 20/07/2023 19:58
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole on off ramp		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1515178	Logged by: Verint CRM Connector	on: 24/02/2023 19:18
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Multiple holes were patched. Patching has since worn leaving road very bumpy with more holes		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1509421	Logged by: Verint CRM Connector	on: 13/02/2023 21:11
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole in the middle of the road which I hit skidded spun round and hit a tree. I can't provide a photo as the pot hole has been filled in badly. This is my car.		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1506489	Logged by: Verint CRM Connector	on: 07/02/2023 18:36
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Several potholes		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1505120	Logged by: Verint CRM Connector	on: 05/02/2023 11:57
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: road is breaking up, very dangerous as the road is VERY narrow		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1504186	Logged by: Verint CRM Connector	on: 03/02/2023 07:34
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Gigantic pothole which is unavoidable due to size and it's deep. Needs to be repaired asap.		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Job Number: 50128493	Defect Number: 42117575	

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 1503438	Logged by: Verint CRM Connector	on: 01/02/2023 19:28
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Multiple deep and long potholes on eastbound section of road between railway bridge and straight section. High risk of cars or cyclists being thrown into the path of oncoming westbound vehicles. Long deep pothole caught the tyre of my Mini tonight and threw me off course.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1499928	Logged by: Verint CRM Connector	on: 26/01/2023 15:32
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Utterly awful road surface all along this section of road. Will be astonished if my wheel isn't damaged.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1497560	Logged by: Verint CRM Connector	on: 23/01/2023 10:40
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Many pot holes, about ten perhaps, some in the middle of the road, some on the left hand carriageway (going to Edinburgh)		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1495288	Logged by: Verint CRM Connector	on: 18/01/2023 18:50
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pot hole in middle of road. Un-avoidable and causing significant impact on wheels when hitting it.		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset
Enquiry No.: 1488904	Logged by: Verint CRM Connector	on: 10/01/2023 10:05
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large hole in middle of road on approach to Burnshot rd - right front wheel hit hole causing immediate puncture requiring roadside assistance at 22.30hrs 25th December		
Contact:		
Plot Number: 1.00	Feature Id - Location: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c	Feature Type: Road Asset

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Customer Services

Enquiry No.: 1488080 **Logged by:** Verint CRM Connector **on:** 09/01/2023 11:22
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: I already reported this pothole, my reference number is 101001640295, I just wanted to add a photograph, but it says "the file you tried to upload failed security checking, it will not be uploaded". Beyond the pothole that I hit there are dozens more, the road should be declared unsafe. I've taken my wheel to a garage, they think the tyre is burst and will require replacing and the wheel is damaged and will require repairing, I will let you know **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset
Job Number: 50127606 **Defect Number:** 42116558

Enquiry No.: 1486380 **Logged by:** Verint CRM Connector **on:** 06/01/2023 19:10
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Potholes, where I dropped the pin and numerous others over the next quarter of a mile, sitting in my car with a flat tyre, it's a disgrace! **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Enquiry No.: 1483079 **Logged by:** Verint CRM Connector **on:** 02/01/2023 18:41
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Burnshot road from the end of the newer resurfacing close to Craigies entrance, there are now multiple pot holes and broken surfaces up to the road up to Dalmeny. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 01 From A90 west to Carlowrie Railway Bridge (just east c **Feature Type:** Road Asset

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c		Feature Type: Road Asset		Area: North West Locality	
50125524	Road: Defective / Damaged (Enquiry 1481336) pothole on carriageway (RD: CW Pothole)	Heading west from A90	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/01/2023	13/01/2023	Act. ROAD/82070373
50127606	Road: Defective / Damaged (Enquiry 1488080) pothole on carriageway (RD: CW Pothole)	Heading east after railway bridge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/01/2023	06/02/2023	Act. ROAD/82071800
50128493	Road: Defective / Damaged (Enquiry 1504186) pothole on carriageway (RD: CW Pothole)	Heading east from railway bridge at top of hill	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2023	07/02/2023	Act. ROAD/82072372
50128494	Road: Defective / Damaged (Enquiry 1504186) pothole on carriageway (RD: CW Pothole)	Entrance to Kirkliston at 30 mph sign	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2023	07/02/2023	Act. ROAD/82072373
50128573	Pothole on carriageway (RD: CW Pothole)	Heading east from Carlowrie farm	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/02/2023	12/02/2023	Act. ROAD/82072421
50131617	1 cw pothole (RD: CW Pothole)	At bus stop on off slip for burnshot bridge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/03/2023	13/03/2023	Act. ROAD/82074107
50140069	1 no pothole (RD: CW Pothole)	At the bus stop at Burnshot Lodge	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	28/07/2023	31/07/2023	Act. ROAD/82079531

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c		Feature Type: Road Asset		Area: North West Locality	
50142511	Carriageway edge broken approximately 0.5x6m (RD: CW Edge Deterioration)	See pin location	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/09/2023	27/09/2023	Act. ROAD/82080652
50143394	2no potholes (RD: CW Pothole)	Just before and at the Burnshot Lodge bus stop	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/10/2023	02/10/2023	Act. ROAD/82081170
50143832	Pothole on carriageway (RD: CW Pothole)	Heading to Kirkliston from Burnshot slip road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/10/2023	11/10/2023	Act. ROAD/82081503
50144560	Road: Defective / Damaged (Enquiry 1633921) pothole on carriageway (RD: CW Pothole)	At railway bridge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/10/2023	31/10/2023	Act. ROAD/82081997
50144563	Road: Defective / Damaged (Enquiry 1633921) pothole on carriageway (RD: CW Pothole)	Heading east to West Craigie Farm Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/10/2023	31/10/2023	Act. ROAD/82082002
50144678	Pothole on carriageway (RD: CW Pothole)	Heading south to A90 from Burnshot Road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/10/2023	31/10/2023	Act. ROAD/82082077
50147847	3no potholes (RD: CW Pothole)	At the Burnshot Lodge bus stop	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	13/12/2023	13/12/2023	Act. ROAD/82083904
50148021	Road: Defective / Damaged (Enquiry 1658230) pothole on carriageway (RD: CW Pothole)	Heading to Kirkliston	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/12/2023	15/12/2023	Act. ROAD/82084017
50149937	Pothole on carriageway, overlay with hra (RD: CW Pothole)	Heading east after railway bridge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/01/2024	21/01/2024	Act. ROAD/82085274
50149938	Pothole on carriageway, overlay with hra (RD: CW Pothole)	Heading west before railway bridge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/01/2024	21/01/2024	Act. ROAD/82085275
50151817	Pothole on carriageway (RD: CW Pothole)	In bus lane	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/01/2024	01/02/2024	Act. ROAD/82086577
50152614	1no pothole (RD: CW Pothole)	Slip rd to A90 city bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/02/2024	14/02/2024	Act. ROAD/82087157
50152852	2no potholes (RD: CW Pothole)	At bus stop on slip rd	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/02/2024	22/02/2024	Act. ROAD/82087323
50157271	1 pothole (RD: CW Pothole)	At the bus stop	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/04/2024	03/04/2024	Act. ROAD/82090427
50162298	Pothole on carriageway (RD: CW Pothole)	Bus stop at Burnshot flyover	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	13/06/2024	13/06/2024	Act. ROAD/82093794
50162486	Pothole on carriageway (RD: CW Pothole)	Heading west after A90 slip road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/06/2024	17/06/2024	Act. ROAD/82093875
50162487	Reset carriageway gully (RD: Gully Damaged/Sunken)	Heading west after A90 slip road	RD: Cat 3 - 60 Day	Job Complete	17/06/2024	21/06/2024	Act. ROAD/82093876
50163740	4no potholes (RD: CW Pothole)	Slip rd from Burnshot rd heading northbound onto A90	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/07/2024	11/07/2024	Act. ROAD/82094657
50164225	Pothole on carriageway (RD: CW Pothole)	Bus stop at Burnshot Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/07/2024	22/07/2024	Act. ROAD/82094880
50164229	Pothole on carriageway (RD: CW Pothole)	Slip road to A90 east from Burnshot Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/07/2024	22/07/2024	Act. ROAD/82094884

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c		Feature Type: Road Asset		Area: North West Locality	
50166054	1no pothole (RD: CW Pothole)	At the Burnshot Lodge bus stop	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/09/2024	03/09/2024	Act. ROAD/82096019
50168263	Pothole on carriageway (RD: CW Pothole)	After West Craigie farm road heading west	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/10/2024	18/10/2024	Act. ROAD/82097421
50168917	1no pothole (RD: CW Pothole)	At the Burnshot Lodge bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/10/2024	30/10/2024	Act. ROAD/82097856
50171056	Pothole on carriageway (RD: CW Pothole)	Bus stop at end of slip road junction Burnshot Road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/12/2024	10/12/2024	Act. ROAD/82099310
50172215	2no potholes (RD: CW Pothole)	At the Burnshot Lodge bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/01/2025	08/01/2025	Act. ROAD/82100238
50172217	6no potholes (RD: CW Pothole)	No reference point please use pin location	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/01/2025	08/01/2025	Act. ROAD/82100239
50172218	3no potholes (RD: CW Pothole)	No reference point please use pin location	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/01/2025	08/01/2025	Act. ROAD/82100240
50172219	1no pothole (RD: CW Pothole)	No reference point please use pin location	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/01/2025	08/01/2025	Act. ROAD/82100241
50173913	Pothole on carriageway (RD: CW Pothole)	Heading west before railway bridge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/01/2025	03/02/2025	Act. ROAD/82101515
50174050	Pothole on carriageway (RD: CW Pothole)	Bus stop at bridge	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/02/2025	03/02/2025	Act. ROAD/82101636
50174682	Pothole on carriageway (RD: CW Pothole)	Slip road from A90 at Burnshot Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/02/2025	16/02/2025	Act. ROAD/82102152
50175950	Potholes (RD: CW Pothole)	Coming down hill at beside bus lane	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/02/2025	27/02/2025	Act. ROAD/82103221
50176613	2no potholes (RD: CW Pothole)	At the Burnshot Lodge bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/03/2025	13/03/2025	Act. ROAD/82103753
50176846	Pothole on carriageway (RD: CW Pothole)	Heading west at army houses	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/03/2025	13/03/2025	Act. ROAD/82103948
50177046	Pothole on carriageway (RD: CW Pothole)	Heading west to Kirkliston before railway bridge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/03/2025	18/03/2025	Act. ROAD/82104074
50178416	Pothole on carriageway (RD: CW Pothole)	Heading west before railway bridge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/04/2025	10/04/2025	Act. ROAD/82105008
50179227	Pothole on carriageway (RD: CW Pothole)	Heading west after West Craigleith Farm Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/04/2025	30/04/2025	Act. ROAD/82105537
50179595	Pothole on carriageway (RD: CW Pothole)	Heading west before railway bridge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/05/2025	10/05/2025	Act. ROAD/82105804
50181215	2no potholes (RD: CW Pothole)	At the bus stop at Burnshot Lodge	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	11/06/2025	11/06/2025	Act. ROAD/82106873
50181686	Pothole on carriageway (RD: CW Pothole)	At Burnshot /Edinburgh junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/06/2025	23/06/2025	Act. ROAD/82107138
50182630	Replace gully frame (RD: Gully Damaged/Sunken)	Junction Hillside Road	RD: Cat 3 - 60 Day	RD: Reinstatement Required	14/07/2025	06/10/2025	Est. RDGC14/82007250
50182936	Pothole on carriageway (RD: CW Pothole)	Heading west before railway bridge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/07/2025	23/07/2025	Act. ROAD/82107971

Effective: 01/01/2023 to 11/06/2026

Service: Roads General

Site: C157 - Kirkliston To Burnshot (7906080)

Asset Number: 1.00 to 3.00

Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 01 From A90 west to Carlowrie Railway Bridge (just east c		Feature Type: Road Asset		Area: North West Locality	
50183931	Keep Clear markings required (RD: Markings New)	Outside entrance to Dalmeny Estate	RD: Cat 4 - Programmed	Job Cancelled	21/08/2025		ROAD/82110068
50188426	Pothole (RD: CW Pothole)	As soon as you exit the bend heading for crammond	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/12/2025	15/12/2025 Act.	ROAD/82111612
50188620	Pothole at gully (RD: CW Pothole)	At junction of cragiehall camp junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/12/2025	21/12/2025 Act.	ROAD/82111752
50189372	Pothole (RD: CW Pothole)	At top of slip heading to kirkliston	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/01/2026	09/01/2026 Act.	ROAD/82112366
50189795	Pothole (RD: CW Pothole)	just before the bridge west bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/01/2026	20/01/2026 Act.	ROAD/82112721
50190172	1 cw pothole (RD: CW Pothole)	Top of slip road from a90 northbound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/01/2026	23/01/2026 Act.	ROAD/82113011
50190224	3 potholes area in need of hra overlay (RD: CW Pothole)	Heading west on burnshot just before bend	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/01/2026	02/02/2026 Act.	ROAD/82113054
50192966	Pothole at gully (RD: CW Pothole)	First gully 15041 just past hillside road junction west bound lane	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/02/2026	04/03/2026 Act.	ROAD/82115369
50192975	After clearing up fw old concrete post stump uncovered and needs took away and infilling with tar (RD: FW HRA Cracked/Broken)	On fw at pin location	RD: Cat 3 - 60 Day	Job Committed	28/02/2026	25/05/2026 Est.	ROAD/82115374
50193440	Various potholes require HRA overlay (RD: CW Pothole)	From under the rail bridge to just before the bend both lanes	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/03/2026	02/04/2026 Act.	ROAD/82115726
50194595	1 number pothole (RD: CW Pothole)	No exact location, go to pin placement just before bridge heading towards Kirkliston	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/03/2026	27/03/2026 Act.	ROAD/82116623
50195408	1 number pothole on slip road from Burnshot to Miller and Carter (RD: CW Pothole)	Go to pin placement as no location	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/04/2026	16/04/2026 Act.	ROAD/82117275