

Effective: 01/01/2021 to 09/06/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Clifton Terrace (7904047)

Site: Clifton Terrace (7904047)

Locality: New Town, Edinburgh, City of Edinburgh

Area: South East Locality

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> South East Locality	
50073285	1n (RD: CW Pothole)	On the pedestrian crossing outside no14	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/01/2021	29/01/2021	Act. ROAD/82043957
50079377	1no pothole (RD: CW Pothole)	Opposite no11	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/03/2021	30/03/2021	Act. ROAD/82047527
50085131	Signs facing the wrong direction. Turn the signs so the face the oncoming traffic. (RD: Unlit Sign Damaged/Missing)	Clifton Terrace opposite Haymarket Station	RD: Cat 3 - 60 Day	Job Complete	11/06/2021	26/06/2021	Act. ROAD/82050869
50107154	1no pothole (RD: CW Pothole)	Opposite no12	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	22/02/2022	25/02/2022	Act. ROAD/82060745
50109442	1no pothole (RD: CW Pothole)	Outside Platform 5	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/03/2022	18/03/2022	Act. ROAD/82061913
50109443	1no pothole (RD: CW Pothole)	Outside no12	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/03/2022	18/03/2022	Act. ROAD/82061914
50109959	CW cracking at 3 areas within and just out with road studs at pedestrian crossing.	Outside la bruschetta.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/03/2022	11/04/2022	Act. ROAD/82062157
	Assess and make safe. (RD: CW Cracked/Broken)						
50117776	Sunken gas Toby (RU: Utility Apparatus)	Outside 11	RU: Fail Low Risk	Job Complete	23/08/2022	23/08/2022	Act.
50119424	5 no broken 900x600 1 no broken 600x600 3 no low 900x 600 Reset 2 Toby's to original level (RD: FW Slabs Broken/Missing)	Outside club sandwich cafe	RD: Cat 3 - 60 Day	Job Complete	04/10/2022	31/10/2022	Act. ROAD/82067196
50119425	Replace Broken grano at box (RD: FW Grano Cracked/Broken)	Outside hub hotel	RD: Cat 3 - 60 Day	Job Complete	04/10/2022	18/10/2022	Act. ROAD/82067197
50119498	Carriageway cracked broken and heaving please relay hra approx 9mx2.5m (RD: CW Cracked/Broken)	On the pedestrian crossing at no13	RD: Cat 3 - 60 Day	Job Complete	05/10/2022	09/10/2022	Act. ROAD/82067231
50119737	Please refresh all markings and zigzags on crossing (RD: Markings Refresh)	On the pedestrian crossing outside La Bruschetta	RD: Cat 4 - Programmed	Job Complete	10/10/2022	15/10/2022	Act. ROAD/82067357
50125194	1 rocking 600x900 (RD: FW Slabs Rocking)	Outside platform 5	RD: Cat 3 - 60 Day	Job Complete	04/01/2023	06/02/2023	Act. ROAD/82070136
50130124	1 rocking 600x900 (RD: FW Slabs Rocking)	At phone box outside platform 5	RD: Cat 3 - 60 Day	Job Complete	24/02/2023	20/03/2023	Act. ROAD/82073294
50130125	1 rocking 600x900 (RD: FW Slabs Rocking)	Outside 12	RD: Cat 3 - 60 Day	Job Complete	24/02/2023	20/03/2023	Act. ROAD/82073295
50130126	1 rocking cut tactile (RD: FW Slabs Rocking)	Outside 13	RD: Cat 3 - 60 Day	Job Complete	24/02/2023	28/02/2023	Act. ROAD/82073296

Effective: 01/01/2021 to 09/06/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Clifton Terrace (7904047)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> South East Locality	
50132136	4 carriageway potholes (RD: CW Pothole)	Outside platform 5	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	16/03/2023	23/03/2023	Act. ROAD/82074388
50134260	1 rocking slab (RD: FW Slabs Rocking)	Outside Ross & liddell	RD: Cat 3 - 60 Day	Job Complete	14/04/2023	27/04/2023	Act. ROAD/82075790
50134783	1no pothole (RD: CW Pothole)	Opposite no11	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	21/04/2023	23/04/2023	Act. ROAD/82076184
50135955	Relay 900 x 600 slab Renew missing granite at box (RD: FW Slabs Rocking)	Outside platform 5	RD: Cat 3 - 60 Day	Job Complete	12/05/2023	16/05/2023	Act. ROAD/82077085
50144680	1 broken cut 600x900 1 broken cut 600x600 (RD: FW Slabs Broken/Missing)	Outside station express	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/10/2023	18/12/2023	Act. ROAD/82082079
50148500	1no Broken 900x600 (RD: FW Slabs Broken/Missing)	Haymarket outside innis and gunn	RD: Cat 4 - Programmed	Job Annulled	19/12/2023	19/12/2023	Act.
50151502	1no rocking cut 900x600 pcc slab at box (RD: FW Slabs Rocking)	Outside fish haymarket	RD: Cat 3 - 60 Day	Job Complete	29/01/2024	14/03/2024	Act. ROAD/82086347
50151505	1no broken 900 x 600 pcc slab (RD: FW Slabs Broken/Missing)	Outside platform 5	RD: Cat 3 - 60 Day	Job Complete	29/01/2024	21/05/2024	Act. ROAD/82086350
50151570	1no cut 900x600 pcc slab (RD: FW Slabs Broken/Missing)	Opposite Clifton terrace at box between ryries and Starbucks	RD: Cat 3 - 60 Day	Job Complete	29/01/2024	18/04/2024	Act. ROAD/82086401
50153577	1no 600x500 pcc slab 1no 600 cut pcc slab (RD: FW Slabs Rocking)	Outside haymarket hub hotel	RD: Cat 3 - 60 Day	Job Complete	21/02/2024	15/05/2024	Act. ROAD/82087849
50157410	1no rocking cut 400 x 400 pcc slab (RD: FW Slabs Rocking)	At taxi rank outside train station	RD: Cat 2 - 5 Day	Job Complete	04/04/2024	10/04/2024	Act. ROAD/82090533
50159719	Tram tracks warning sign facing away from traffic and not being lit by the lamp.  Please turn to face correct way and tighten - cheers (RD: Unlit Sign Damaged/Missing)	Outside 9 Clifton Terrace	RD: Cat 3 - 60 Day	Job Complete	02/05/2024	06/05/2024	Act. ROAD/82092164
50160141	Sunken and noisy manhole (RU: Utility Apparatus)	Westbound lane opposite Platform 5	RU: Fail Med.Risk (Apparatus)	Job Complete	10/05/2024	13/05/2024	Act.
50162061	1no rocking 600 x 600 pcc slab 1no section of grano at box (RD: FW Slabs Rocking)	Outside platform 5 on fw next to nal signal box	RD: Cat 3 - 60 Day	Job Complete	10/06/2024	19/06/2024	Act. ROAD/82093656
50165724	2no broken 900 x 600 pcc slabs 1no rocking 600 x 600 pcc slab (RD: FW Slabs Broken/Missing)	Outside Starbucks near taxi rank	RD: Cat 3 - 60 Day	Job Complete	23/08/2024	26/08/2024	Act. ROAD/82095835
50167802	1no broken 900 x 600 pcc slab 1no missing grano around box (RD: FW Slabs Broken/Missing)	Outside no6 Ross and middle property opposite Starbucks	RD: Cat 3 - 60 Day	Job Complete	09/10/2024	10/10/2024	Act. ROAD/82097106

Effective: 01/01/2021 to 09/06/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Clifton Terrace (7904047)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> South East Locality	
50171582	2no broken 900 x 600 pcc slabs 1no broken cut pcc slab 2no rocking pcc slabs next to poly channel (RD: FW Slabs Broken/Missing)	Outside Starbucks next to taxi rank	RD: Cat 2 - 5 Day	Job Complete	17/12/2024	04/04/2025	Act. ROAD/82099757
50174005	Missing Scottish Water manhole cover on carriageway in the middle of the road Photos attached (RU: Utility Apparatus)	Outside number 11	RU: Fail High Risk	Job Complete	31/01/2025	31/01/2025	Act.
50177708	3no rocking /low cut pcc slabs at box 1no grano surrounding metal pole base needs renewed (RD: FW Slabs Rocking)	Outside platform 5 bar	RD: Cat 3 - 60 Day	Job Complete	27/03/2025	28/03/2025	Act. ROAD/82104524
50177725	1no broken cut 900 x 600 pcc slat 1no broken cut pcc slab (RD: FW on Fw next to manhole Slabs Broken/Missing)	At Taxi rank outside Starbucks	RD: Cat 3 - 60 Day	Job Complete	27/03/2025	04/04/2025	Act. ROAD/82104535
50177761	Sunken , loose and noisy Verizon manhole (RU: Utility Apparatus)	On the carriageway outside no8	RU: Fail Med.Risk (Apparatus)	Job Complete	28/03/2025	28/03/2025	Act.
50179128	1no small piece of slab Remove and infill with grano (RD: FW Slabs Broken/Missing)	Outside no6 On fw at entrance into Ross & Liddell property office	RD: Cat 3 - 60 Day	Job Complete	28/04/2025	29/04/2025	Act. ROAD/82105471
50180001	please turn tram track warning sign so it's under the lamp and facing traffic heading into town - cheers (RD: Unlit Sign Damaged/Missing)	Outside Bubba, 9 Clifton Terrace	RD: Cat 3 - 60 Day	Job Complete	16/05/2025	14/06/2025	Act. ROAD/82106102
50180294	Fw Double box grano surround needs renewed (RD: FW Grano Open Joint)	Opposite Starbucks	RD: Cat 3 - 60 Day	Job Complete	23/05/2025	10/06/2025	Act. ROAD/82106299
50180306	1no rocking cut 900 x 600 pcc slab (RD: FW Slabs Rocking)	Outside Starbucks at taxi rank	RD: Cat 3 - 60 Day	Job Complete	23/05/2025	09/06/2025	Act. ROAD/82106311
50183630	1no grano pothole at box (RD: FW Grano Pothole)	Outside platform 5 next to bus stop	RD: Cat 2 - 5 Day	Job Complete	14/08/2025	15/08/2025	Act. ROAD/82108365
50184631	Noisy, sinking and loose Scottish Water manhole after recent reinstatement (RU: Utility Reinstatement)	On the carriageway opposite no11	RU: Fail Med.Risk (Apparatus)	Job Complete	09/09/2025	09/09/2025	Act.
50184848	Please make safe defective sw cover until permanent repair (RD: CW Pothole)	Haymarket terrace at 12	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/09/2025	17/09/2025	Act. ROAD/82109086
50185986	1no rocking 900 x 600 pcc slab (RD: FW Slabs Rocking)	On Fw outside no6 Ross + Liddell	RD: Cat 2 - 5 Day	Job Complete	23/10/2025	24/10/2025	Act. ROAD/82109912
50187330	1no rocking cut pcc slab at box on fw (RD: FW Slabs Rocking)	Outside platform 5	RD: Cat 3 - 60 Day	Job Complete	24/11/2025	17/12/2025	Act. ROAD/82110778

Effective: 01/01/2021 to 09/06/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Clifton Terrace (7904047)

**Maintenance Management**

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> South East Locality	
50188829	1no broken 750 x 600 pcc slab (RD: FW Slabs Broken/Missing)	Opposite Starbucks	RD: Cat 3 - 60 Day	Job Complete	23/12/2025	27/01/2026	Act. ROAD/82111918
50190189	1no broken cut 750 x 600 pcc slab (RD: FW Slabs Broken/Missing)	Next to Garner by IHG at double box	RD: Cat 3 - 60 Day	Job Complete	22/01/2026	29/01/2026	Act. ROAD/82113025
50192656	1no broken 400 x 400 pcc slab (RD: FW Slabs Broken/Missing)	At Taxi rank outside Haymarket train station	RD: Cat 3 - 60 Day	Job Complete	24/02/2026	28/02/2026	Act. ROAD/82115098
50194409	1no rocking 600 x 600 pcc slab (RD: FW Slabs Rocking)	Outside platform 5	RD: Cat 2 - 5 Day	Job Complete	24/03/2026	26/03/2026	Act. ROAD/82116477
50194434	1no broken 900 x 600 pcc slab (RD: FW Slabs Broken/Missing)	Outside Starbucks next to taxi rank	RD: Cat 3 - 60 Day	Job Scheduled	24/03/2026	03/06/2026	Est. ROAD/82116498
50197610	1no broken cut 400 x 400 pcc slab (RD: FW Slabs Broken/Missing)	At Taxi rank outside Haymarket train station	RD: Cat 3 - 60 Day	Job Scheduled	28/05/2026	03/06/2026	Est. ROAD/82118986
50197611	3no broken 900 x 600 pcc slabs (RD: FW Slabs Broken/Missing)	Outside Starbucks next to Taxi rank	RD: Cat 3 - 60 Day	Job Committed	28/05/2026	20/08/2026	Est. ROAD/82118987