

Effective: 01/01/2021 to 09/06/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Haymarket Terrace (7902909)

Site: Haymarket Terrace (7902909)

Locality: New Town, Edinburgh, City of Edinburgh

Area: South East Locality

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50070326	x3 rocking PCC cut slabs around service cover. Lift and relay. (RD: FW Slabs Rocking)	Outside plant bae.	RD: Cat 3 - 60 Day	Job Complete	16/12/2020	03/03/2021	Act. ROAD/82042648
50072787	1no pothole (RD: CW Pothole)	At the bus stop opposite Vietnam House	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/01/2021	27/01/2021	Act. ROAD/82043673
50073286	1no pothole (RD: CW Pothole)	Outside no6	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/01/2021	29/01/2021	Act. ROAD/82043958
50074288	Grano pothole outside Drummond.	Outside Drummond.	RD: Cat 3 - 60 Day	Job Complete	05/02/2021	16/03/2021	Act. ROAD/82044511
	Remove silt and reinstate with fresh grano. (RD: FW Grano Pothole)						
50075123	1 number pothole (RD: CW Pothole)	At bus stop opposite number 18	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	16/02/2021	17/02/2021	Act. ROAD/82044937
50079120	Collapsed gully frame pot and brander needs replaced (RD: Gully Sunken/Damaged Frame)	At the bus stop opposite no22	RD: Cat 1 - 24 Hours	RD: Made Safe Job Complete	22/03/2021	23/03/2021	Act. ROAD/82047361
50079124	Collapsed gully frame and brander needs replaced (RD: Gully Sunken/Damaged Frame)	At the bus stop opposite no22	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	22/03/2021	23/03/2021	Act. ROAD/82047362
50080556	Loose rocking slab please reset (RD: FW Slabs Rocking)	O/S no 14	RD: Cat 2 - 5 Day	Job Complete	06/04/2021	09/04/2021	Act. ROAD/82048282
50081722	1no pothole (RD: CW Pothole)	Outside no10	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/04/2021	27/04/2021	Act. ROAD/82048967
50082487	x10 900x600 pcc slabs, lift and relay with 900x600 pcc grey slabs.	Outside Tesco.	RD: Cat 3 - 60 Day	Job Complete	06/05/2021	28/07/2021	Act. ROAD/82049392
	x7 600x600 broken pcc slabs, lift and relay with 600x600 pcc grey slabs.						
	Cuts adjacent to kerb are approx 400-450mm length, use 900x600 slabs for cuts if easier. (RD: FW Slabs Broken/Missing)						
50084240	1no pothole (RD: CW Pothole)	Outside no12	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/05/2021	02/06/2021	Act. ROAD/82050351
50089881	2no potholes (RD: CW Pothole)	Outside no50	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/08/2021	19/08/2021	Act. ROAD/82053320
50089883	1no pothole (RD: CW Pothole)	Outside no44	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/08/2021	19/08/2021	Act. ROAD/82053322
50089885	1no pothole (RD: CW Pothole)	Outside no38	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/08/2021	19/08/2021	Act. ROAD/82053323

Effective: 01/01/2021 to 09/06/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Haymarket Terrace (7902909)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50090984	Numerous potholes within middle running lane. (RD: CW Pothole)	Outside Kung fu tea.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2021	03/09/2021	Act. ROAD/82054001
50094495	x2 CW potholes, make safe. (RD: CW Pothole)	Outside easy coffee at junction of rose berry crescent.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/10/2021	24/10/2021	Act. ROAD/82055234
50096454	Grano is breaking up, exposing open joint. Remove loose/old and reinstate new patch of grano. (RD: FW Grano Cracked/Broken)	Outside Coates cafe.	RD: Cat 3 - 60 Day	Job Complete	09/11/2021	15/11/2021	Act. ROAD/82056017
50100088	Cracked asphalt surface within road studs, make safe with overlay or a patch. (RD: CW Cracked/Broken)	Outside conneta & co at ped crossing.	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/12/2021	07/03/2022	Act. ROAD/82057527
50103748	1no pothole (RD: CW Pothole)	Outside no52	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/01/2022	24/01/2022	Act. ROAD/82059122
50107268	2no potholes (RD: CW Pothole)	Outside no4	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/02/2022	02/03/2022	Act. ROAD/82060808
50109440	1no pothole (RD: CW Pothole)	Outside no10	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/03/2022	22/03/2022	Act. ROAD/82061911
50112272	Rocking cut slab - lift and relay (RD: FW Slabs Rocking)	O/S no 84	RD: Cat 3 - 60 Day	Job Complete	25/04/2022	26/04/2022	Act. ROAD/82063369
50112273	Low slab - lift and relay (RD: FW Slabs Rocking)	O/S Kung Fu Tea	RD: Cat 3 - 60 Day	Job Complete	25/04/2022	26/04/2022	Act. ROAD/82063370
50115426	Utility cover damaged (RU: Utility Apparatus)	Outside fine fellas	RU: Fail Med.Risk (Apparatus)	Job Complete	16/06/2022	16/06/2022	Act.
50116908	Noisy vodaphone manhole cover in carriageway (RU: Utility Apparatus)	Opposite Nomad	RU: Fail Med.Risk (Apparatus)	Job Complete	27/07/2022	27/07/2022	Act.
50119435	Low Scottish power box (RU: Utility Apparatus)	Outside 83	RU: Fail Med.Risk (Apparatus)	Job Complete	04/10/2022	04/10/2022	Act.
50122881	1no pothole (RD: CW Pothole)	Outside no12	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/11/2022	24/11/2022	Act. ROAD/82068798
50125196	1 broken 600x900 (RD: FW Slabs Broken/Missing)	Outside TH bike shop	RD: Cat 3 - 60 Day	Job Complete	04/01/2023	30/01/2023	Act. ROAD/82070138
50125206	1 rocking 600x900 Adjust x3 marked 600x900s to suit new height (RD: FW Slabs Rocking)	Opposite Apex3	RD: Cat 3 - 60 Day	Job Complete	04/01/2023	30/01/2023	Act. ROAD/82070144
50125639	Damaged Scottish Power no2 box cover Called through to Lorraine Jones (RU: Utility Apparatus)	On the footway outside no24	RU: Fail High Risk	Job Complete	09/01/2023	09/01/2023	Act.
50130127	1 rocking 600x900 (RD: FW Slabs Rocking)	Outside caldows	RD: Cat 3 - 60 Day	Job Complete	24/02/2023	28/02/2023	Act. ROAD/82073297

Effective: 01/01/2021 to 09/06/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Haymarket Terrace (7902909)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: South East Locality		
50130609	1no section of missing polychannel cover needs replacing (RD: Polychannel Missing)	Outside no87	RD: Cat 3 - 60 Day	Job Complete	27/02/2023	02/03/2023	Act. ROAD/82073549
50131234	2no potholes (RD: CW Pothole)	Outside no12	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/03/2023	08/03/2023	Act. ROAD/82073892
50133387	1no pothole (RD: CW Pothole)	Outside Apex2	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/03/2023	04/04/2023	Act. ROAD/82075121
50134622	1no pothole (RD: CW Pothole)	Opposite no28	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/04/2023	20/04/2023	Act. ROAD/82076054
50134624	Rocking Mercury manhole (RU: Utility Apparatus)	On the carriageway at bus stop HJ	RU: Fail Med.Risk (Apparatus)	Job Complete	19/04/2023	21/04/2023	Act.
50140148	1no pothole (RD: CW Pothole)	Outside Apex3	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/07/2023	31/07/2023	Act. ROAD/82079568
50142663	1no pothole (RD: CW Pothole)	Outside Apex3	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	18/09/2023	18/09/2023	Act. ROAD/82080743
50143716	1no pothole (RD: CW Pothole)	Outside Apex3	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/10/2023	09/10/2023	Act. ROAD/82081424
50147833	Old sign pole has been cut away leaving a hole and trip hazard within the slabs. Please make safe / cut further down and fill hole (RD: Unlit Sign Damaged/Missing)	On footway in between Deluxe Dry Cleaning & David Drummond shop	RD: Cat 3 - 60 Day	Job Complete	13/12/2023	22/12/2023	Act. ROAD/82083894
50147843	Obscured 20mph repeater needing moved further up the pole please above bus tracker. (RD: Unlit Sign Damaged/Missing)	Magdala / Osborne Terrace - 10m from Devon place exit	RD: Cat 3 - 60 Day	Job Complete	13/12/2023	20/12/2023	Act. ROAD/82083900
50153488	Collapsed Scottish Power manhole (RU: Utility Apparatus)	On the footway outside Apex1	RU: Fail Med.Risk (Apparatus)	Job Complete	20/02/2024	21/02/2024	Act.
50161673	Really noisy triple Vodafone manhole with lids bouncing (RU: Utility Apparatus)	Westbound carriageway at bus stop HJ	RU: Fail Med.Risk (Apparatus)	Job Complete	03/06/2024	03/06/2024	Act.
50168534	Sunken damaged and noisy triple manhole (RU: Utility Apparatus)	On the carriageway at the bus stop HJ	RU: Fail Med.Risk (Apparatus)	Job Complete	23/10/2024	23/10/2024	Act.
50170345	1no box surround needs renewed (RD: FW Grano Open Joint)	Opposite eight yards shop	RD: Cat 3 - 60 Day	Job Complete	26/11/2024	28/11/2024	Act. ROAD/82098791
50172584	1no fw traffic signal box has sunk please reset to correct height and re grano surround (RD: FW Cover Make Safe)	Opposite eight yards shop	RD: Cat 3 - 60 Day	Job Complete	10/01/2025	26/02/2025	Act. ROAD/82100547

Effective: 01/01/2021 to 09/06/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Haymarket Terrace (7902909)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50176571	Triple manhole cover causing noise for local residents when struck by traffic (RU: Utility Apparatus)	Outside no91 thistle house	RU: Fail Med.Risk (Apparatus)	Job Complete	07/03/2025	07/03/2025	Act.
50180307	Grano strip across Fw needs renewed (RD: FW Grano Open Joint)	Outside no79-81 opposite Coates gardens	RD: Cat 3 - 60 Day	Job Complete	23/05/2025	06/06/2025	Act. ROAD/82106312
50183343	Recent manhole replacement has failed It is loose , noisy and asphalt is breaking up (RU: Utility Reinstatement)	On the carriageway opposite no44	RU: Fail Med.Risk (Apparatus)	Job Complete	04/08/2025	04/08/2025	Act.
50183344	Failed manhole reinstatement Loose manhole with asphalt surround breaking up (RU: Utility Reinstatement)	On the carriageway opposite no28	RU: Fail Med.Risk (Apparatus)	Job Complete	04/08/2025	04/08/2025	Act.
50183629	1no damaged bollard (RD: Bollard Damage/Missing/New)	At junction with Coates gardens	RD: Cat 3 - 60 Day	Job Complete	14/08/2025	20/08/2025	Act. ROAD/82108364
50184372	1no pothole (RD: CW Pothole)	Opposite no44	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/09/2025	03/09/2025	Act. ROAD/82108787
50184834	Damaged drain cover (RU: Utility Apparatus)	On the footway outside Tesco Express	RU: Fail Med.Risk (Apparatus)	Job Complete	16/09/2025	17/09/2025	Act.
50185137	1no damaged Edinburgh bollard needs replaced (RD: Bollard Damage/Missing/New)	Outside Arboosh	RD: Cat 4 - Programmed	No code allocated	03/10/2025		
50185983	1no sunken / loose double Vodafone utility box on Fw Photos attached (RU: Utility Apparatus)	Haymarket terrace at junction with Magdala crescent on Footway outside four points hotel	RU: Fail Med.Risk (Apparatus)	Job Complete	23/10/2025	23/10/2025	Act.
50185985	1no broken utility box cover on Fw Photos attached (RU: Utility Apparatus)	Haymarket terrace on Footway outside Tesco express	RU: Fail Med.Risk (Apparatus)	Job Complete	23/10/2025	23/10/2025	Act.
50187326	Double Vodafone utility box loose / sunken Defect has been raised before Ref no 03923819 but no action has been taken (RU: Utility Apparatus)	Haymarket terrace at junction with Magdala crescent, On Footway outside four points by Sheraton hotel	RU: Fail Med.Risk (Apparatus)	Job Complete	24/11/2025	24/11/2025	Act.
50187361	Collapsed Scottish Power no2 box lid (RU: Utility Apparatus)	On the footway outside Apex2	RU: Fail Med.Risk (Apparatus)	Job Complete	24/11/2025	24/11/2025	Act.
50190201	1no Fw pothole (RD: FW HRA Pothole)	Outside Apex 2 no97	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/01/2026	23/01/2026	Act. ROAD/82113037
50192635	1no damaged pole and sign need replaced (TS: Sign Replace Sign and Pole)	Outside Tesco	RD: Cat 3 - 60 Day	Job Committed	24/02/2026	19/05/2026	Est. ROAD/82115079

Effective: 01/01/2021 to 09/06/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Haymarket Terrace (7902909)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50192701	Loose and noisy Verizon triple manhole cover on carriageway (RU: Utility Apparatus)	at junction of Coates Gardens	RU: Fail Med.Risk (Apparatus)	Job Complete	25/02/2026	25/02/2026	Act.
50192704	Sunken loose and noisy Scottish water manhole cover on carriageway photos attached (RU: Utility Apparatus)	Outside number 69	RU: Fail Med.Risk (Apparatus)	Job Complete	25/02/2026	25/02/2026	Act.
50192706	1 number pothole (RD: CW Pothole)	outside number 91	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/02/2026	04/03/2026	Act. ROAD/82115140
50194447	Sunken / loose Vodafone box on Fw that belongs to virgin media. Been reported before and still not repaired. Ref no 3923819 Photos attached (RU: Utility Apparatus)	Haymarket terrace at junction with Magdala crescent, outside the four points hotel	RU: Fail Med.Risk (Apparatus)	Job Complete	24/03/2026	24/03/2026	Act.
50195682	Failed Loose and noisy Verizon triple manhole cover on carriageway previous repaired under LA ref 4027523 photos attached (RU: Utility Apparatus)	At junction of Coates Gardens	RU: Fail Med.Risk (Apparatus)	Job Complete	22/04/2026	22/04/2026	Act.
50195889	Sunken / loose Double frame and covers telecommunications utility box , been raised before as Vodafone but was rejected (RU: Utility Apparatus)	Haymarket terrace on Fw at junction with Magdala crescent outside Four points Sheraton hotel	RU: Fail Med.Risk (Apparatus)	Job Complete	24/04/2026	24/04/2026	Act.
50197608	1no open joint needs infilled (RD: FW Grano Open Joint)	Outside Global food at manhole on Fw	RD: Cat 3 - 60 Day	Job Scheduled	28/05/2026	17/06/2026	Est. ROAD/82118984
50197609	1no cw pothole (RD: CW Pothole)	Outside no58 Nail & beauty	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/05/2026	29/05/2026	Act. ROAD/82118985
50198168	1no Cw pothole (RD: CW Pothole)	Outside Thistle house no91 Haymarket Terrace	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/06/2026	09/06/2026	Act. ROAD/82119379
	Asset: 2.00	Asset - Locn.: Ward 11 - Footway on south side of Haymarket Tram stop Note:		Feature Type: Road Asset		Area: South East Locality	
50168532	1no rocking 750x600 pcc flag (RD: FW Slabs Rocking)	Outside Rosebery House at the corner of Haymarket Yards	RD: Cat 2 - 5 Day	Job Complete	23/10/2024	24/10/2024	Act. ROAD/82097631
50180625	1no rocking cut 400 x 400 pcc slab (RD: FW Slabs Rocking)	At tram stop west bound opposite no10 haymarket terrace	RD: Cat 3 - 60 Day	Job Complete	29/05/2025	09/06/2025	Act. ROAD/82106514