

# Site History Report

Effective: 01/01/2010 to 01/06/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Clerwood Terrace (7902657)

Site: Clerwood Terrace (7902657)

Locality: Clerwood, Edinburgh, City of Edinburgh

Area: North West Locality

## Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> North West Locality	
50001415	Road: Defective / Damaged (Enquiry 596770) pothole (RD: CW Pothole)	At first speed bump 20m in from clermiston road	RD: Cat 2 - 5 Day	Job Complete	17/01/2018	18/01/2018	Act. ROAD/82001072
50002648	Road: Defective / Damaged (Enquiry 614476) (RD: CW Pothole)	There are two potholes in the road the first just after the first speed bump into Clerwood Terrace and the second a few metres down the road opposite the junction to Clerwood Grove	RD: Cat 3 - 60 Day	Job Complete	08/02/2018	20/02/2018	Act. ROAD/82002123
50003205	Road: Defective / Damaged (Enquiry 617182) (RD: CW Pothole)	30m from jct with roundabout, after speed bump (car parked over pothole during inspection)	RD: Cat 3 - 60 Day	Job Complete	15/02/2018	20/02/2018	Act. ROAD/82002518
50006590	RD: CW Pothole	Opothooe os no.28	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/04/2018	14/04/2018	Act. ROAD/82005372
50008541	Hot temp make safe (RD: CW Pothole)	Potholes on carriageway outside no 6	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/05/2018	04/05/2018	Act. ROAD/82007084
50009166	Hot temp make safe (RD: CW Pothole)	Pothole on carriageway outside no 12	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/05/2018	10/05/2018	Act. ROAD/82007597
50009167	Hot temp make safe (RD: CW Pothole)	Pothole & depression on carriageway outside no 30	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/05/2018	11/05/2018	Act. ROAD/82007598
50012477	Hot temp make safe (RD: CW Pothole)	Potholes & depressions on carriageway outside no 16	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/07/2018	03/07/2018	Act. ROAD/82009935
50013565	Hot temp make safe (RD: CW Pothole)	Pothole on carriageway outside no 10	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	26/07/2018	27/07/2018	Act. ROAD/82010783
50014812	Hot temp make safe (RD: FW HRA Pothole)	Pothole on footway / carriageway at driveway entrance to no 4	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	24/08/2018	28/08/2018	Act. ROAD/82011685
50016721	Hot temp make safe (RD: CW Pothole)	Potholes on carriageway at junction to school	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	29/09/2018	01/10/2018	Act. ROAD/82012995
50016722	Clean out blocked gully (Gully: Blocked / Flooding)	Blocked gully on carriageway at I / p 7	RD: Cat 3 - 60 Day	Job Complete	29/09/2018	21/09/2020	Act. ROAD/82012996
50018414	Road: Defective / Damaged (Enquiry 739876)	Potholes on carriageway at junction with clerwood Grove	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/11/2018	06/11/2018	Act. ROAD/82014234
	Hot temp make safe (RD: CW Pothole)						
50026469	Road: Defective / Damaged (Enquiry 798805)	Pothole on carriageway outside no 8	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	19/02/2019	20/02/2019	Act. ROAD/82017862
	Hot temp make safe (RD: CW Pothole)						
50029323	Hot temp make safe (RD: CW Pothole)	Pothole in middle of carriageway approximately 5m before junction with clermiston road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	25/03/2019	26/03/2019	Act. ROAD/82019168

## Site History Report

Effective: 01/01/2010 to 01/06/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Clerwood Terrace (7902657)

### Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> North West Locality	
50041832	Road: Defective / Damaged (Enquiry 883079)  Hot temp make safe (RD: CW Pothole)	Potholes on both sides of carriageway at speed hump next to l/p no 2	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/09/2019	10/09/2019	Act. ROAD/82026081
50041833	Hot temp make safe (RD: CW Pothole)	Potholes on carriageway outside no 2	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/09/2019	10/09/2019	Act. ROAD/82026082
50041834	Road: Defective / Damaged (Enquiry 883077)  Hot temp make safe (RD: CW Pothole)	Potholes on carriageway with junction at school	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/09/2019	10/09/2019	Act. ROAD/82026083
50041835	Hot temp make safe (RD: CW Pothole)	Pothole on carriageway outside no 8	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/09/2019	10/09/2019	Act. ROAD/82026084
50046286	Road: Defective / Damaged (Enquiry 907853)  Hot temp make safe (RD: CW Pothole)	Pothole & depression on carriageway next to speed hump at l/p no 2	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	21/11/2019	22/11/2019	Act. ROAD/82028445
50046491	Road: Defective / Damaged (Enquiry 910994)  Hot temp make safe (RD: CW Pothole)	Potholes on north bound carriageway approximately 5m north of junction with clerwood terrace	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	26/11/2019	27/11/2019	Act. ROAD/82028573
50046903	Road: Defective / Damaged (Enquiry 911205)  Hot temp make safe (RD: CW Pothole)	Potholes on carriageway between no 6 & no 10	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/12/2019	05/12/2019	Act. ROAD/82028866
50050289	Road: Defective / Damaged (Enquiry 946280)  Hot temp make safe (RD: CW Pothole)	Pothole on carriageway at junction with Clerwood terrace	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/01/2020	23/01/2020	Act. ROAD/82031200
50050290	Road: Defective / Damaged (Enquiry 946273)  Hot temp make safe (RD: CW Pothole)	Pothole on carriageway outside no 2	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/01/2020	23/01/2020	Act. ROAD/82031201
50051571	Road: Defective / Damaged (Enquiry 953681)  Hot temp make safe (RD: CW Pothole)	Potholes on carriageway outside no 8	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/02/2020	11/02/2020	Act. ROAD/82032289
50051573	Hot (RD: CW Pothole)	Potholes on carriageway outside no 12	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/02/2020	11/02/2020	Act. ROAD/82032291

## Site History Report

Effective: 01/01/2010 to 01/06/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Clerwood Terrace (7902657)

### Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> North West Locality	
50055665	Road: Defective / Damaged (Enquiry 980066) (RD: CW Pothole)	2 potholes outside 8 and 10 Clerwood Terrace	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	14/04/2020	15/04/2020	Act. ROAD/82035836
50056082	RD: FW HRA Cracked/Broken	Surrounded at iron work is broken up. Resident tripped, please can you make safe and remove debris	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	07/05/2020	08/05/2020	Act. ROAD/82036168
50057654	Gully: Vegetation in Gully - What is the problem with the gully : vegetation in gully. What surface is the gully on : road (Enquiry 997145)	Gully is on road leading up to Clerwood house, water running downhill on this road not being caught by blocked gully and runs across Clermiston road causing a potential skid risk.	RG: Gully - High Priority	Job Complete	02/07/2020	13/07/2020	Act. RDGC14/82000973
50058075	Road: Defective / Damaged (Enquiry 999850) (RD: CW Pothole)	Two potholes outside house number 8	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/07/2020	08/07/2020	Act. ROAD/82037502
50059683	Road: Defective / Damaged (Enquiry 1016874) pothole on carriageway (RD: CW Pothole)	Outside 1	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	05/08/2020	06/08/2020	Act. ROAD/82038410
50064058	Road: Defective / Damaged (Enquiry 1048760) Pothole on carriageway (RD: CW Pothole)	Potholes forming in the road again, outside 16+8	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	05/10/2020	06/10/2020	Act. ROAD/82039991
50064629	Road: Defective / Damaged (Enquiry 1051811) Pothole on carriageway (RD: CW Pothole)	Junction of Clerwood Terrace and Clerwood Place.	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	12/10/2020	13/10/2020	Act. ROAD/82040211
50066794	Road: Defective / Damaged (Enquiry 1065571) Pothole on carriageway (RD: CW Pothole)	outside 10	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/11/2020	11/11/2020	Act. ROAD/82041142
50071751	Road: Defective / Damaged (Enquiry 1098303) carriageway patching required (RD: CW Cracked/Broken)	east and west bound	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/01/2021	20/04/2021	Act. ROAD/82043197
50075174	Road: Defective / Damaged (Enquiry 1120569) Pothole on carriageway (RD: CW Pothole)	From 6-10	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	16/02/2021	17/02/2021	Act. ROAD/82044972
50082182	Sign and pole not required (RD: Unlit Sign Damaged/Missing)	Remove Give Way sign and pole from footway outside no 6 Clerwood Terrace	RD: Cat 3 - 60 Day	Job Complete	03/05/2021	04/05/2021	Act. ROAD/82049195
50090996	Road: Defective / Damaged (Enquiry 1237784) Pothole on carriageway (RD: CW Pothole)	Outside 10-12	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/09/2021	02/09/2021	Act. ROAD/82054010
50093639	Road: Defective / Damaged (Enquiry 1258899) Pothole on carriageway (RD: CW Pothole)	Outside 8	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	13/10/2021	14/10/2021	Act. ROAD/82054964
50101727	Road: Defective / Damaged (Enquiry 1298779) pothole on carriageway (RD: CW Pothole)	Outside 2,	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/01/2022	06/01/2022	Act. ROAD/82058160

# Site History Report

Effective: 01/01/2010 to 01/06/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Clerwood Terrace (7902657)

## Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> North West Locality	
50103378	Road: Defective / Damaged (Enquiry 1309625) pothole on carriageway (RD: CW Pothole)	Outside 22	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/01/2022	19/01/2022	Act. ROAD/82058938
50108036	Road: Defective / Damaged (Enquiry 1338085) pothole on carriageway (RD: CW Pothole)	Outside 2	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/03/2022	04/03/2022	Act. ROAD/82061239
50111681	Road: Defective / Damaged (Enquiry 1359650) permanent repair required to carriageway in hra (RD: CW Pothole)	Outside 18	RD: Cat 4 - Programmed	RD: Made Safe Job Complete	11/04/2022	11/05/2022	Act. ROAD/82063910
50116525	Road: Defective / Damaged (Enquiry 1406366) pothole on carriageway (RD: CW Pothole)	Outside 2 at speed ramp	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/07/2022	15/07/2022	Act. ROAD/82065579
50117023	Pothole (RD: CW Pothole)	Outside number 12	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/08/2022	02/08/2022	Act. ROAD/82065892
50119055	Pavement: Damaged / Defective (Enquiry 1427250) (RD: FW HRA Pothole)	Clerwood terrace os 9	RD: Cat 2 - 5 Day	Job Complete	22/09/2022	23/09/2022	Act. ROAD/82067014
50123170	Pothole on carriageway (RD: CW Pothole)	Outside 10,8	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	28/11/2022	29/11/2022	Act. ROAD/82068921
50123582	Road: Defective / Damaged (Enquiry 1470656) pothole on carriageway (RD: CW Pothole)	Outside 2,6,10	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/12/2022	06/12/2022	Act. ROAD/82069121
50123874	Road: Defective / Damaged (Enquiry 1473046) pothole on carriageway (RD: CW Pothole)	Outside 3,6,10 and entrance to school	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/12/2022	12/12/2022	Act. ROAD/82069294
50124110	Road: Defective / Damaged (Enquiry 1474809) pothole on carriageway (RD: CW Pothole)	Outside 6	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	13/12/2022	13/12/2022	Act. ROAD/82069446
50130187	Road: Defective / Damaged (Enquiry 1514490) pothole on carriageway (RD: CW Pothole)	Entrance to school	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/02/2023	02/03/2023	Act. ROAD/82073338
50130647	Pothole on carriageway (RD: CW Pothole)	Outside 6,10ams School entrance	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	28/02/2023	01/03/2023	Act. ROAD/82073572
50134022	Road: Defective / Damaged (Enquiry 1535086) pothole on carriageway (RD: CW Pothole)	Carriageway leading to primary school ,outside 10	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/04/2023	12/04/2023	Act. ROAD/82075600
50136215	Road: Defective / Damaged (Enquiry 1551940) pothole on carriageway (RD: CW Pothole)	Outside 8,2	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/05/2023	17/05/2023	Act. ROAD/82077262
50138461	Road: Defective / Damaged (Enquiry 1572477) pothole on carriageway (RD: CW Pothole)	Outside 10	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/06/2023	28/06/2023	Act. ROAD/82078608
50140688	1 cw pothole (RD: CW Pothole)	Outside 22	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/08/2023	09/08/2023	Act. ROAD/82079859

## Site History Report

Effective: 01/01/2010 to 01/06/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Clerwood Terrace (7902657)

### Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> North West Locality	
50143168	Fox covert primary school direction sign no longer required. Remove sign face and pole for disposal. Permanently reinstate HRA footway with white chip. (RD: Unlit Sign Damaged/Missing)	At ped crossing.	RD: Cat 3 - 60 Day	Job Complete	26/09/2023	27/09/2023	Act. ROAD/82081007
50143172	TSSE9-2c. Install new "Fox Covert Campus" direction flag sign onto LP so the bottom of the sign is 2300mm above the FW. New sign in stock. (RD: Unlit Sign Damaged/Missing)	On LP CKV06.	RD: Cat 3 - 60 Day	Job Complete	26/09/2023	27/09/2023	Act. ROAD/82081008
50144197	Pothole on carriageway (RD: CW Pothole)	Outside 10	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/10/2023	18/10/2023	Act. ROAD/82081741
50145417	Road: Defective / Damaged (Enquiry 1641403) pothole on carriageway (RD: CW Pothole)	Outside 6	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/11/2023	09/11/2023	Act. ROAD/82082545
50147853	Road: Defective / Damaged (Enquiry 1659957) pothole on carriageway (RD: CW Pothole)	Outside 6,10	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/12/2023	15/12/2023	Act. ROAD/82083909
50149014	Road: Defective / Damaged (Enquiry 1668006) pothole on carriageway (RD: CW Pothole)	Outside 2	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/12/2023	08/01/2024	Act. ROAD/82084673
50149015	Road: Defective / Damaged (Enquiry 1668007) pothole on carriageway (RD: CW Pothole)	Outside 10,12	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/12/2023	08/01/2024	Act. ROAD/82084674
50151203	Pothole on carriageway (RD: CW Pothole)	Outside 10,8	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/01/2024	02/02/2024	Act. ROAD/82086114
50157339	Pothole on carriageway (RD: CW Pothole)	Outside 2,6,10	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/04/2024	10/04/2024	Act. ROAD/82090488
50157340	Pothole on carriageway (RD: CW Pothole)	Outside 16	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/04/2024	09/04/2024	Act. ROAD/82090489
50158568	Cw x1 pothole Road: Defective / Damaged (Enquiry 1736532) (RD: CW Pothole)	At the junction Comiston Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/04/2024	22/04/2024	Act. ROAD/82091423
50159139	Pothole on carriageway (RD: CW Pothole)	Opposite 2	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/04/2024	26/04/2024	Act. ROAD/82091787
50160719	Pothole on carriageway (RD: CW Pothole)	Outside 6,10,12	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/05/2024	30/05/2024	Act. ROAD/82092731
50162843	Pothole on carriageway (RD: CW Pothole)	Outside 16,22	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/06/2024	24/06/2024	Act. ROAD/82094108
50167314	Pothole on carriageway (RD: CW Pothole)	Outside 8	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/10/2024	02/10/2024	Act. ROAD/82096804
50172690	Pothole on carriageway (RD: CW Pothole)	From 6-12	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/01/2025	16/01/2025	Act. ROAD/82100625

## Site History Report

Effective: 01/01/2010 to 01/06/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Clerwood Terrace (7902657)

### Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	<b>Asset:</b> 1.00	<b>Asset - Locn.:</b> Whole Street		<b>Feature Type:</b> Road Asset		<b>Area:</b> North West Locality	
50172883	Pothole on carriageway (RD: CW Outside 12 Pothole)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/01/2025	16/01/2025	Act. ROAD/82100789
50178937	Pothole on carriageway (RD: CW Outside 10,8,4 Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/04/2025	24/04/2025	Act. ROAD/82105329
50181846	Pothole on carriageway (RD: CW Outside 6 Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/06/2025	27/06/2025	Act. ROAD/82107217
50182885	Relay 1 dislodged whin kerb (RD: Opposite 5 FW Kerb Dislodged/Rocking)	At opening to fox covert primary	RD: Cat 3 - 60 Day	Job Complete	18/07/2025	24/07/2025	Act. ROAD/82107938
50182886	1 cw pothole (RD: CW Pothole)	Opposite 5	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/07/2025	21/07/2025	Act. ROAD/82107939
50186776	No 1 pothole (RD: CW Pothole)	Outside no 4	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/11/2025	12/11/2025	Act. ROAD/82110385
50189446	4 potholes (RD: CW Pothole)	From 6-12	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/01/2026	12/01/2026	Act. ROAD/82112451
50192896	2no potholes (RD: CW Pothole)	10m west of roundabout	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/02/2026	05/03/2026	Act. ROAD/82115303
50192902	6 potholes (RD: CW Pothole)	outside 12/entrance to primary school	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/02/2026	05/03/2026	Act. ROAD/82115306
50194894	Pothole (RD: CW Pothole)	Outside 18	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/04/2026	03/04/2026	Act. ROAD/82116853
50194895	Pothole (RD: CW Pothole)	Outside 8	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	02/04/2026	03/04/2026	Act. ROAD/82116854
50194896	Potholes (RD: CW Pothole)	Outside 10	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/04/2026	03/04/2026	Act. ROAD/82116855