

62252 A6095 Road Repair and Inspection History

The road in question is the A6095 Newcraighall Road, with particular focus on the section between Newhailes Road and Benhar Road.

Please can you provide the full road repair history for that aforementioned road for the past year. Specifically, please supply the complete repair and inspection history for 2025, including:

The dates of all safety inspections carried out between August and October 2025.

Details of how each safety inspection was undertaken (e.g., walked or driven inspection, speed of inspection vehicle, and any other relevant methodology).

Details of all carriageway defects identified, including descriptions, dates, and times.

Details of how each defect was handled by the authority, the nature of the repairs undertaken, and the time elapsed between identification and completion of the repair.

The attached [Site History Report](#) provides the dates of all inspections, details of identified defects, and the time elapsed between identification and repair. Please also note that the [South Mobile Inspection Route](#) is a driven inspection, and [Newcraighall Road](#) is a walked inspection.

We are unable to provide you with details of how each defect was handled and the nature of the repairs undertaken as it is not held by the Council.