

Effective: 01/06/2025 to 30/06/2025

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Newcraighall Drive (7902416)

Site: Newcraighall Drive (7902416)

Locality: Newcraighall, Edinburgh, City of Edinburgh

Area: North East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North East Locality		
Batch: 41231352 - Inspection Batch			Route: NE_CF2_Newcraighall1			Date: 19/06/2025		
42185814	1 rocking kerb	19/06/2025	Outside 16	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42185815	Tree root push up	19/06/2025	20m east of bend	RD: FW Tree Root Tar	Internal		Action Required	
42185819	Refresh all markings at junction	19/06/2025	At junction of Newcraighall Road	RD: Markings Refresh	Internal		Committed	50131158
42185813	Broken 6x5" kerb	19/06/2025	Outside 12	RD: FW Kerbs Damaged/Missing	Internal		No Action Required	