

Effective: 01/06/2025 to 30/06/2025

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Park View (7902432)

Site: Park View (7902432)

Locality: Newcraighall, Edinburgh, City of Edinburgh

Area: North East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Ward 17 - From Newcraighall Drive south then east			Feature Type: Road Asset			Area: North East Locality	
Batch: 41231381 - Inspection Batch				Route: NE_CF2_Newcraighall1			Date: 19/06/2025	
No actionable defects found								