

## 62300 Walking Route Used by Children in the Redford Road and Dreghorn Link Area

A review of the safety of the walking route for children travelling to school.

Clarification as to whether the route is currently considered an “available safe walking route” under relevant council and Scottish Government guidance.

Consideration of additional safety measures where appropriate.

[No route has been identified, nor school.](#)

Copies of any Road Safety Audits, pedestrian assessments, Safe Routes to School evaluations, or collision data relating to:

Redford Road

Dreghorn Link

Dreghorn Junction

[Please see the Road Safety Audit and pedestrian crossing assessments attached. No collisions have been reported at these locations in the requested timeframe.](#)

[No Safe Routes to School evaluations are available, as this applies solely to schools and not to transport routes.](#)