

Site History Report

Effective: 30/05/2025 to 29/05/2026
Service: Roads General
Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00
Display Action Officer: Yes

Site: Leith Walk (7900015)

Locality: Edinburgh, City of Edinburgh

Area: North East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset: 1.00	Asset - Locn.: Ward 11 - in 2 sections -From Greenside Place to Broughton Str			Feature Type: Road Asset			Area: South East Locality	
Batch: 41263502	- Inspection Batch No actionable defects found			Route: NE_FW1_LeithWalk1	Officer:			Date: 19/05/2026
Batch: 41262870	- Inspection Batch No actionable defects found			Route: South Mobile Inspection Route	Officer:			Date: 11/05/2026
Batch: 41261197	- Inspection Batch No actionable defects found			Route: NE_FW1_LeithWalk1	Officer:			Date: 17/04/2026
Batch: 41260063	- Inspection Batch No actionable defects found			Route: South Mobile Inspection Route	Officer:			Date: 01/04/2026
Batch: 41259577	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic	Officer:			Date: 29/03/2026
Batch: 41258825	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic	Officer:			Date: 22/03/2026
Batch: 41258243	- Inspection Batch No actionable defects found			Route: NE_FW1_LeithWalk1	Officer:			Date: 16/03/2026
Batch: 41258021	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic	Officer:			Date: 15/03/2026
Batch: 41257140	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic	Officer:			Date: 08/03/2026
Batch: 41256381	- Inspection Batch No actionable defects found			Route: South Mobile Inspection Route	Officer:			Date: 02/03/2026
Batch: 41256169	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic	Officer:			Date: 02/03/2026
Batch: 41254982	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic	Officer:			Date: 23/02/2026
Batch: 41253942	- Inspection Batch No actionable defects found			Route: NE_FW1_LeithWalk1	Officer:			Date: 17/02/2026
Batch: 41253361	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic	Officer:			Date: 14/02/2026
Batch: 41252165	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic	Officer:			Date: 07/02/2026
Batch: 41251249	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic	Officer:			Date: 31/01/2026
Batch: 41250639	- Inspection Batch No actionable defects found			Route: South Mobile Inspection Route	Officer:			Date: 27/01/2026

Site History Report

Effective: 30/05/2025 to 29/05/2026

Service: Roads General

Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 11 - in 2 sections -From Greenside Place to Broughton Str	Feature Type:	Road Asset		Area:	South East Locality
Batch:	41250360 - Inspection Batch			Route:	Mobile Inspection Strategic	Officer:		Date: 26/01/2026
	No actionable defects found							
Batch:	41249012 - Inspection Batch			Route:	Mobile Inspection Strategic	Officer:		Date: 19/01/2026
	No actionable defects found							
Batch:	41248618 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 14/01/2026
	No actionable defects found							
Batch:	41247536 - Inspection Batch			Route:	Mobile Inspection Strategic	Officer:		Date: 10/01/2026
	No actionable defects found							
Batch:	41245828 - Inspection Batch			Route:	Mobile Inspection Strategic	Officer:		Date: 22/12/2025
	No actionable defects found							
Batch:	41245265 - Inspection Batch			Route:	South Mobile Inspection Route	Officer:		Date: 18/12/2025
	No actionable defects found							
Batch:	41245111 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 17/12/2025
	No actionable defects found							
Batch:	41244180 - Inspection Batch			Route:	Mobile Inspection Strategic	Officer:		Date: 11/12/2025
	No actionable defects found							
Batch:	41242263 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 20/11/2025
	No actionable defects found							
Batch:	41241885 - Inspection Batch			Route:	South Mobile Inspection Route	Officer:		Date: 18/11/2025
	No actionable defects found							
Batch:	41239608 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 22/10/2025
	No actionable defects found							
Batch:	41238669 - Inspection Batch			Route:	South Mobile Inspection Route	Officer:		Date: 14/10/2025
	No actionable defects found							
Batch:	41237393 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 25/09/2025
	No actionable defects found							
Batch:	41236732 - Inspection Batch			Route:	South Mobile Inspection Route	Officer:		Date: 12/09/2025
	No actionable defects found							
Batch:	41235256 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 21/08/2025
	No actionable defects found							
Batch:	41234590 - Inspection Batch			Route:	South Mobile Inspection Route	Officer:		Date: 12/08/2025
	No actionable defects found							
Batch:	41233513 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 21/07/2025
	No actionable defects found							
Batch:	41232914 - Inspection Batch			Route:	South Mobile Inspection Route	Officer:		Date: 14/07/2025
	No actionable defects found							

Site History Report

Effective: 30/05/2025 to 29/05/2026

Service: Roads General

Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 11 - in 2 sections -From Greenside Place to Broughton Str		Feature Type: Road Asset			Area: South East Locality	
Batch:	41231674 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 24/06/2025
	No actionable defects found							
Batch:	41230421 - Inspection Batch			Route:	South Mobile Inspection Route	Officer:		Date: 09/06/2025
	No actionable defects found							
Asset:	2.00	Asset - Locn.: Ward 12 - From Manderston Street to Pilrig Street both sides &		Feature Type: Road Asset			Area: North East Locality	
Batch:	41263796 - Inspection Batch			Route:	North Mobile Inspection Route	Officer:		Date: 21/05/2026
	No actionable defects found							
Batch:	41263414 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 19/05/2026
42206619	Lift and relay x13 rocking slabs Replace broken cut 450x600 and 1 broken rumble strip	19/05/2026	Outside bee tech/epoca	RD: FW Slabs Broken/Missing	Internal		Committed	50197028
42206639	replace x29 450x600s as marked Replace full section of rumble strip (21 slabs)	19/05/2026	At dalmeny street	RD: FW Slabs Broken/Missing	Internal		No Action Required	
Batch:	41263137 - Inspection Batch			Route:	Ad hoc Route	Officer:	Graeme Shanley	Date: 14/05/2026
42206365	Triple manhole cover making noise	14/05/2026	Outside no 285	RU: Utility Apparatus	Internal		Uncommitted	50196843
Batch:	41261198 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 17/04/2026
	No actionable defects found							
Batch:	41260966 - Inspection Batch			Route:	North Mobile Inspection Route	Officer:		Date: 14/04/2026
	No actionable defects found							
Batch:	41258171 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 16/03/2026
42202115	Remove x4 marked slabs and infill with cold tar	16/03/2026	Junction with dalmeny street	RD: FW Slabs Broken/Missing	Internal		Committed	50193931
	Area is scheduled for permanent repair but needs made safe immediately							
Batch:	41257530 - Inspection Batch			Route:	North Mobile Inspection Route	Officer:		Date: 10/03/2026
42201727	1no pothole	10/03/2026	Outside 267	RD: CW Pothole	Internal		Committed	50193643
Batch:	41255889 - Inspection Batch			Route:	Ad hoc Route	Officer:		Date: 27/02/2026
42200754	1 number pothole	27/02/2026	Outside number 282	RD: CW Pothole	Internal		Committed	50192919
Batch:	41253813 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 17/02/2026
42199671	5no rocking pcc slabs	17/02/2026	Outside Domino's pizza	RD: FW Slabs Rocking	Internal		Committed	50192043
42199677	1no loose Gas Toby	17/02/2026	Fw on Leith walk outside no 253	RU: Utility Apparatus	Internal		Uncommitted	50192049
42199672	1no sunken utility manhole	17/02/2026	On Leith walk outside no 129 on Footway	RU: Utility Apparatus	Internal		Uncommitted	50192044
42199678	1no Cw pothole	17/02/2026	Outside no 267	RD: CW Pothole	Internal		Committed	50192050
42199679	replace x29 450x600s as marked Replace full section of rumble strip (21 slabs)	17/02/2026	At dalmeny street	RD: FW Slabs Broken/Missing	Internal		No Action Required	

Site History Report

Effective: 30/05/2025 to 29/05/2026
 Service: Roads General
 Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00
 Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 12 - From Manderston Street to Pilrig Street both sides & i		Feature Type: Road Asset		Area: North East Locality		
Batch:	41253273 - Inspection Batch		Route: Ad hoc Route		Officer:		Date: 13/02/2026	
42199358	1no blocked gully	13/02/2026	Outside st Columbus hospice care	Gully: Blocked - Hand Clear	Internal		Committed	50191789
Batch:	41251966 - Inspection Batch		Route: North Mobile Inspection Route		Officer:		Date: 05/02/2026	
No actionable defects found								
Batch:	41248268 - Inspection Batch		Route: NE_FW1_LeithWalk1		Officer:		Date: 14/01/2026	
42196526	1 rocking 450 and 1 rocking cut 450	14/01/2026	Outside jewellers	RD: FW Slabs Rocking	Internal		Committed	50189587
42196544	1 broken cut 450x600	14/01/2026	Outside 346	RD: FW Slabs Broken/Missing	Internal		Committed	50188625
42196530	x2 rocking 450x600s	14/01/2026	Outside 20-21	RD: FW Slabs Rocking	Internal		Committed	50181839
42196525	replace x29 450x600s as marked Replace full section of rumble strip (21 slabs)	14/01/2026	At dalmeny street	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42196523	x8 rocking slabs	14/01/2026	Outside magikats	RD: FW Slabs Rocking	Internal		Committed	50185001
42196529	1 low cut 450x600	14/01/2026	Outside querencia	RD: FW Slabs Broken/Missing	Internal		Committed	50189589
42196524	x2 rocking 450x600s	14/01/2026	Outside qupi coffee shop	RD: FW Slabs Rocking	Internal		Committed	50189585
Batch:	41246578 - Inspection Batch		Route: North Mobile Inspection Route		Officer:		Date: 30/12/2025	
No actionable defects found								
Batch:	41244979 - Inspection Batch		Route: NE_FW1_LeithWalk1		Officer:		Date: 17/12/2025	
42195405	x8 broken 450x600s x1 rocking 450x600 Replace damaged PCC kerb	17/12/2025	At lorne street	RD: FW Slabs Broken/Missing	Internal		Committed	50188616
42195408	x2 rocking 450x600s	17/12/2025	Outside 20-21	RD: FW Slabs Rocking	Internal		No Action Required	
42195416	1 broken cut 450x600	17/12/2025	Outside 346	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42195407	replace x29 450x600s as marked Replace full section of rumble strip (21 slabs)	17/12/2025	At dalmeny street	RD: FW Slabs Broken/Missing	Internal		No Action Required	
Batch:	41242863 - Inspection Batch		Route: North Mobile Inspection Route		Officer:		Date: 26/11/2025	
42194011	1no pothole	26/11/2025	Outside no297	RD: CW Pothole	Internal		Committed	50187545
Batch:	41242144 - Inspection Batch		Route: NE_FW1_LeithWalk1		Officer:		Date: 20/11/2025	
42193587	x7 rocking slabs	20/11/2025	Outside Victoria	RD: FW Slabs Rocking	Internal		Committed	50181835
42193584	Relay x3 marked slabs	20/11/2025	Outside toast	RD: FW Slabs Rocking	Internal		Committed	50187219
42193583	Relay rocking 450x600	20/11/2025	Outside inchkeith house	RD: FW Slabs Rocking	Internal		Committed	50187218
42193582	x8 rocking slabs	20/11/2025	Outside magikats	RD: FW Slabs Rocking	Internal		No Action Required	
42193588	replace x29 450x600s as marked Replace full section of rumble strip (21 slabs)	20/11/2025	At dalmeny street	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42193602	x2 rocking slabs at manhole	20/11/2025	Outside easy tan	RD: FW Slabs Rocking	Internal		Committed	50185912
Batch:	41239702 - Inspection Batch		Route: North Mobile Inspection Route		Officer:		Date: 23/10/2025	
No actionable defects found								
Batch:	41239426 - Inspection Batch		Route: NE_FW1_LeithWalk1		Officer:		Date: 22/10/2025	
42191595	x8 rocking slabs	22/10/2025	Outside magikats	RD: FW Slabs Rocking	Internal		No Action Required	

Site History Report

Effective: 30/05/2025 to 29/05/2026

Service: Roads General

Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	2.00	Asset - Locn.: Ward 12 - From Manderston Street to Pilrig Street both sides & i			Feature Type: Road Asset		Area: North East Locality	
Batch: 41239426 - Inspection Batch			Route: NE_FW1_LeithWalk1		Officer:		Date: 22/10/2025	
42191631	x2 rocking slabs at manhole	22/10/2025	Outside easy tan	RD: FW Slabs Rocking	Internal		No Action Required	
42191597	replace x29 450x600s as marked	22/10/2025	At dalmeny street	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42191596	x7 rocking slabs	22/10/2025	Outside Victoria	RD: FW Slabs Rocking	Internal		No Action Required	
42191599	x2 rocking 450x600s	22/10/2025	Outside 20-21	RD: FW Slabs Rocking	Internal		No Action Required	
42191598	replace x29 450x600s as marked Replace full section of rumble strip (21 slabs)	22/10/2025	At dalmeny street	RD: FW Slabs Broken/Missing	Internal		No Action Required	
Batch: 41237357 - Inspection Batch			Route: NE_FW1_LeithWalk1		Officer:		Date: 25/09/2025	
42190287	x2 rocking slabs as marked	25/09/2025	Outside shwarma	RD: FW Slabs Rocking	Internal		Committed	50182912
42190283	x8 rocking slabs	25/09/2025	Outside magikats	RD: FW Slabs Rocking	Internal		No Action Required	
42190284	x7 rocking slabs	25/09/2025	Outside Victoria	RD: FW Slabs Rocking	Internal		No Action Required	
Batch: 41237082 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route		Officer:		Date: 22/09/2025	
Batch: 41235216 - Inspection Batch			Route: NE_FW1_LeithWalk1		Officer:		Date: 21/08/2025	
42188830	x7 rocking slabs	21/08/2025	Outside Victoria	RD: FW Slabs Rocking	Internal		No Action Required	
42188836	x2 rocking 450x600s	21/08/2025	Outside 20-21	RD: FW Slabs Rocking	Internal		No Action Required	
Batch: 41235013 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route		Officer:		Date: 19/08/2025	
Batch: 41233433 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route		Officer:		Date: 21/07/2025	
Batch: 41233407 - Inspection Batch			Route: NE_FW1_LeithWalk1		Officer:		Date: 21/07/2025	
42187405	x7 rocking slabs	21/07/2025	Outside Victoria	RD: FW Slabs Rocking	Internal		No Action Required	
42187421	x2 rocking slabs as marked	21/07/2025	Outside shwarma	RD: FW Slabs Rocking	Internal		No Action Required	
42187407	x2 rocking 450x600s	21/07/2025	Outside 20-21	RD: FW Slabs Rocking	Internal		No Action Required	
42187406	x7 rocking slabs as marked	21/07/2025	Outside boundary bar	RD: FW Slabs Rocking	Internal		Committed	50182899
42187403	1 broken cut 450x600 at manhole	21/07/2025	Outside 113	RD: FW Slabs Broken/Missing	Internal		Committed	50182898
Batch: 41231607 - Inspection Batch			Route: NE_FW1_LeithWalk1		Officer:		Date: 24/06/2025	
42186007	1 rocking 450x600	24/06/2025	Outside 20-21	RD: FW Slabs Rocking	Internal		No Action Required	
42186004	1 broken cut 450x600	24/06/2025	Outside epoca	RD: FW Slabs Broken/Missing	Internal		Committed	50181836
42186003	x7 rocking slabs	24/06/2025	Outside Victoria	RD: FW Slabs Rocking	Internal		No Action Required	
Batch: 41231176 - Inspection Batch No actionable defects found			Route: North Mobile Inspection Route		Officer:		Date: 17/06/2025	
Batch: 41230409 - Inspection Batch			Route: Ad hoc Route		Officer:		Date: 09/06/2025	
42185235	Sunken loose and noisy manhole cover on carriageway photos attached	09/06/2025	Outside Chinese Supermarket.	RU: Utility Apparatus	Internal		Uncommitted	50181088

Site History Report

Effective: 30/05/2025 to 29/05/2026

Service: Roads General

Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00

Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Ward 13 - Manderston Street to Great Junction Street		Feature Type: Road Asset		Area: North East Locality		
Batch:	41263797 - Inspection Batch			Route:	North Mobile Inspection Route	Officer:		Date: 21/05/2026
	No actionable defects found							
Batch:	41263504 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 19/05/2026
	No actionable defects found							
Batch:	41262642 - Inspection Batch			Route:	Ad hoc Route	Officer:		Date: 11/05/2026
42205859	1 pothole	11/05/2026	Outside barbers at foot of the walk	RD: CW Pothole	Internal		Committed	50196523
Batch:	41261151 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 17/04/2026
42204338	Lift and relay x10 marked slabs	17/04/2026	Behind foot of the walk bus stop	RD: FW Slabs Rocking	Internal		Committed	50195519
Batch:	41260967 - Inspection Batch			Route:	North Mobile Inspection Route	Officer:		Date: 14/04/2026
	No actionable defects found							
Batch:	41258244 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 16/03/2026
	No actionable defects found							
Batch:	41257624 - Inspection Batch			Route:	North Mobile Inspection Route	Officer:		Date: 10/03/2026
	No actionable defects found							
Batch:	41253943 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 17/02/2026
	No actionable defects found							
Batch:	41251967 - Inspection Batch			Route:	North Mobile Inspection Route	Officer:		Date: 05/02/2026
	No actionable defects found							
Batch:	41248264 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 14/01/2026
42196520	Relay x3 marked slabs	14/01/2026	Outside antient robot games	RD: FW Slabs Rocking	Internal		Committed	50187217
Batch:	41246577 - Inspection Batch			Route:	North Mobile Inspection Route	Officer:		Date: 30/12/2025
	No actionable defects found							
Batch:	41245108 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 17/12/2025
	No actionable defects found							
Batch:	41242862 - Inspection Batch			Route:	North Mobile Inspection Route	Officer:		Date: 26/11/2025
	No actionable defects found							
Batch:	41242143 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 20/11/2025
42193580	Relay x3 marked slabs	20/11/2025	Outside antient robot games	RD: FW Slabs Rocking	Internal		No Action Required	
42193581	X13 rocking slabs	20/11/2025	Opposite 52	RD: FW Slabs Rocking	Internal		Committed	50183915
Batch:	41239700 - Inspection Batch			Route:	North Mobile Inspection Route	Officer:		Date: 23/10/2025
	No actionable defects found							
Batch:	41239610 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 22/10/2025
	No actionable defects found							
Batch:	41237391 - Inspection Batch			Route:	NE_FW1_LeithWalk1	Officer:		Date: 25/09/2025
	No actionable defects found							

Site History Report

Effective: 30/05/2025 to 29/05/2026
Service: Roads General
Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00
Display Action Officer: Yes

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	3.00	Asset - Locn.: Ward 13 - Manderston Street to Great Junction Street		Feature Type: Road Asset		Area: North East Locality		
Batch:	41237083 - Inspection Batch			Route: North Mobile Inspection Route	Officer:			Date: 22/09/2025
	No actionable defects found							
Batch:	41235215 - Inspection Batch			Route: NE_FW1_LeithWalk1	Officer:			Date: 21/08/2025
42188827	X13 rocking slabs	21/08/2025	Opposite 52	RD: FW Slabs Rocking	Internal		No Action Required	
Batch:	41235169 - Inspection Batch			Route: Ad hoc Route	Officer:			Date: 20/08/2025
42188782	Missing Scottish water cover on footpath	20/08/2025	Outside Argonaut books	RU: Utility Apparatus	Internal		Uncommitted	50183887
Batch:	41235012 - Inspection Batch			Route: North Mobile Inspection Route	Officer:			Date: 19/08/2025
	No actionable defects found							
Batch:	41233514 - Inspection Batch			Route: NE_FW1_LeithWalk1	Officer:			Date: 21/07/2025
	No actionable defects found							
Batch:	41233432 - Inspection Batch			Route: North Mobile Inspection Route	Officer:			Date: 21/07/2025
	No actionable defects found							
Batch:	41231671 - Inspection Batch			Route: NE_FW1_LeithWalk1	Officer:			Date: 24/06/2025
	No actionable defects found							
Batch:	41231175 - Inspection Batch			Route: North Mobile Inspection Route	Officer:			Date: 17/06/2025
	No actionable defects found							

Customer Services

Enquiry No.: 31604024 **Logged by:** [Redacted] **on:** 16/03/2026 18:45 **Officer:** [Redacted]
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: Please logon [Redacted] for an inspector to visit site, to take an updated photo of the existing west bound ADS sign on Leith Walk in advance of London Road junction. Please take photos of existing junction lane road markings , road marking text and traffic signage at Leith Walk/ London Road junction. And also take photos of 'any amendments made to the kerb alignment/ junction layout' to allow left turning traffic into London Road from Leith Walk. Note to inspector, please contact/ email [Redacted] on outcome of site visit thanks.

Location: _____ **Contact:** _____

Enquiry No.: 2154079 **Logged by:** Verint CRM Connector **on:** 27/05/2026 22:44 **Officer:** [Redacted]
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.: Raised paving slab on edge of cycle lane. Watched two people trip over it in five minute window whilst waiting for a bus.

Location: _____ **Contact:** _____

Plot Number: 2.00 **Feature Id - Location:** Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset

Site History Report

Effective: 30/05/2025 to 29/05/2026

Service: Roads General

Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00

Display Action Officer: Yes

Customer Services

Enquiry No.: 2149689 **Logged by:** Verint CRM Connector **on:** 19/05/2026 20:32 **Officer:** Follow-up Officer

Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: The tram tracks on leith road outside papa johns. It's very slippery and dangerous. I came off my motorbike around 8:15am on 18th May and went to a&e

My bike is damaged and I will need to replace my helmet from the impact of falling. Passers by carried me off the road and my bike, one said the same thing happened to her there. The hospital also said they've had quite a few people coming in from being injured there too in the same way.

Plot Number: 3.00 **Feature Id - Location:** Ward 13 - Manderston Street to Great Junction Street **Feature Type:** Road Asset

Enquiry No.: 2145997 **Logged by:** Verint CRM Connector **on:** 12/05/2026 13:17 **Officer:** [REDACTED]

Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service

Desc.:

Location: The glass bricks on the pavement outside the both windows at St Columbas shop 352 Leith walk are broken/missing. The void below is full of rubbish and its causing a really bad odour within our shop basement area which then leads into our main shop, especially when it is raining. The damage also poses a possible trip hazard as well as a fire hazard as there are discarded cigarette ends. Can this void be cleaned out and the glass bricks repaired /replaced to prevent re-occurrence please

Plot Number: 2.00 **Feature Id - Location:** Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset

Enquiry No.: 2145983 **Logged by:** Verint CRM Connector **on:** 12/05/2026 12:58 **Officer:** [REDACTED]

Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: Repair in road has failed and causing loud noises every time a car drives over it. Especially loud when trucks or large vehicles pass by.

Plot Number: 2.00 **Feature Id - Location:** Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset

Job Number: 50196843 **Defect Number:** 42206365

Enquiry No.: 2144092 **Logged by:** Verint CRM Connector **on:** 08/05/2026 12:44 **Officer:** Road Ops Live Enquiries

Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: Deep pothole with two sunken drain covers **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 13 - Manderston Street to Great Junction Street **Feature Type:** Road Asset

Job Number: 50196523 **Defect Number:** 42205859

Site History Report

Effective: 30/05/2025 to 29/05/2026

Service: Roads General

Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00

Display Action Officer: Yes

Customer Services

Enquiry No.: 2133533 **Logged by:** [REDACTED] **on:** 20/04/2026 11:03 **Officer:** [REDACTED]
Service: Roads General **Subject:** Street Furniture: General Enq **Classification:** General Enquiry
Desc.: First name : [REDACTED]
Last name : [REDACTED]
email : [REDACTED]
telephone number : [REDACTED]
Full address : [REDACTED]
What area does your complaint relate to ? : road_travel_parking
If your comments relate to a council service for which you have an account then please provide an account number :
Short description of complaint : There are no currently no bike racks or any forms of cycle parking in or around Leith Walk, even though we have a newly installed off road cycle path
Please provide the details of the complaint : Bike lanes are being extended across North Edinburgh and yet at the very places by shops and supermarkets in Leith there are no bike parking racks whatsoever
How would you like us to deal with this? : Please install bike parking at busy places - Leith Depot, Tesco, Leith Library. There is some at Sainsbury's but not enough
Location: Leith Walk and surrounding area **Contact:**

Enquiry No.: 2132476 **Logged by:** Verint CRM Connector **on:** 17/04/2026 15:15 **Officer:** [REDACTED]
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Unsafe crossing at traffic lights. 3 cars went through a red light and green man signal turning from dalmeny street onto leith walk. This happens regularly and unsafe crossing road with toddler as cars do not stop and think it is ok to go through red light, cars are not paying attention to the traffic lights and watching for pedestrians.
Contact:

Plot Number: 2.00 **Feature Id - Location:** Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset

Enquiry No.: 2129637 **Logged by:** [REDACTED] **on:** 13/04/2026 09:13 **Officer:** Follow-up Officer
Service: Roads General **Subject:** Road: General Enquiry **Classification:** General Enquiry
Desc.: First name : [REDACTED] Last name : [REDACTED]
email : [REDACTED]
telephone number : [REDACTED]
Full address : [REDACTED]
Short description of complaint : Shared pavement/roads on Leith walk almost cost the life of my [REDACTED] year old son - please can they be altered before a serious accident occurs
Please provide the details of the complaint : Good afternoon, I have always been slightly dubious about the pavements on Leith Walk that cross the adjoining roads with no clear distinction between road and pavement. However, yesterday I had a truly scary experience and I really feel that a bad accident will happen soon if changes aren't made. My [REDACTED] year old was riding his pedal bike approximately 1-2 metres in front of me. He's aware of road safety and always knows to stop at road crossings, and we have also discussed how it's very difficult to tell where the road starts and stops along Leith Walk (a regular walk for us). However yesterday a van came hurtling along at 20mph from an adjoining road, straight across the 'pavement'. As there was no clear markings to tell the van to STOP, and no clear markings to tell my [REDACTED] year old it's a 'road' (despite looking exactly like a pavement!), there was very nearly a fatal collision. The van driver was shaken as he could not see any clear warning of the fact it was a 'pavement' he was driving over. If there are going to be shared pedestrian/car areas such as this, there must be far clearer markings and signposts warning cars (and toddlers) of this fact. I truly believe it's only a matter of time before a terrible accident happens on one of these junctions.
How would you like us to deal with this? : See above - clearer markings warning cars they are about to cross a 'shared pavement', and clearer markings warning pedestrians they are about to cross a 'road' (despite it looking exactly like a pavement)
Location: Leith Walk **Contact:**

Site History Report

Effective: 30/05/2025 to 29/05/2026

Service: Roads General

Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00

Display Action Officer: Yes

Customer Services

Enquiry No.: 2120214

Logged by: Verint CRM Connector

on: 26/03/2026 12:56

Officer: [REDACTED]

Service: Roads General

Subject: Pavement: Damaged / Defective

Classification: Request for service

Desc.:

Location: 233 to 239 Leith Walk paving have many paving slabs moving and flipping up in this zone. They require re setting asap before further movements result in accidents. Not re sealing the slabs will allow further rainwater wash to erode below. Please see this as a stitch in time. Pedestrian accidents have already occurred.

Contact:

Plot Number: 2.00

Feature Id - Location: Ward 12 - From Manderston Street to Pilrig Street both sides &

Feature Type: Road Asset

Enquiry No.: 2117364

Logged by: Verint CRM Connector

on: 22/03/2026 00:05

Officer: [REDACTED]

Service: Roads General

Subject: Public Utilities: General

Classification: Request for service

Desc.:

Location: Hey there.

Just outside the Scotmid by the pin. Is the metal cover in the road, has been worn down and metallic thumps Tun-Tun, Tun-Tun as cars drove over it for a couple weeks now.

Is getting alot louder and worse, can see it seesaw when things drive over it.

No idea who to send this to, but it's getting loud and looks like it'll catch a wheel somepoint.

Contact:

Plot Number: 2.00

Feature Id - Location: Ward 12 - From Manderston Street to Pilrig Street both sides &

Feature Type: Road Asset

Enquiry No.: 2109347

Logged by: [REDACTED]

on: 09/03/2026 15:57

Officer: [REDACTED]

Service: Roads General

Subject: Road: Defective / Damaged

Classification: Request for service

Desc.: Pothole right at the pedestrian crossing opposite mcd road library

Report ID: 9073125

Category: Potholes

Pothole right in front of the pelican crossing, looks like a patch job has worn away. Danger for people crossing here particularly if visually impaired.

Location:

Easting/Northing: 326389/674870 (55.961178, -3.18067)

Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 2, Leith Walk, Shaw's Colonies, Leith, City of Edinburgh, Alba / Scotland, EH7 5HP, United Kingdom

Nearest postcode to the pin placed on the map (automatically generated): EH7 5HP (6m away)

Location: Pothole right at the pedestrian crossing opposite mcd road library

Contact:

Report ID: 9073125

Category: Potholes

Pothole right in front of the pelican crossing, looks like a patch job has worn away.

Danger for people crossing here particularly if visually impaired.

Location:

Easting/Northing: 326389/674870 (55.961178, -3.18067)

Nearest road to the pin placed on the map (automatically generated by

OpenStreetMap): 2, Leith Walk, Shaw's Colonies, Leith, City of Edinburgh, Alba /

Scotland, EH7 5HP, United Kingdom

Nearest postcode to the pin placed on the map (automatically generated): EH7 5HP

(6m away)

Site History Report

Effective: 30/05/2025 to 29/05/2026

Service: Roads General

Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00

Display Action Officer: Yes

Customer Services

Enquiry No.: 2109109 **Logged by:** Verint CRM Connector **on:** 09/03/2026 12:38 **Officer:** [REDACTED]
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole category 1 and sunken surroundings opposite tram stop at Balfour Street heading down Leith Walk towards the walk **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset

Enquiry No.: 2109106 **Logged by:** Verint CRM Connector **on:** 09/03/2026 12:36 **Officer:** [REDACTED]
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Category 1 pothole just before Balfour Street tram stop next to the pavement heading up Leith Walk to town **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset

Enquiry No.: 2107656 **Logged by:** Verint CRM Connector **on:** 06/03/2026 10:48 **Officer:** [REDACTED]
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset

Enquiry No.: 2105193 **Logged by:** [REDACTED] **on:** 02/03/2026 14:16 **Officer:** Follow-up Officer
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: this request is attached to the Leith Walk portion of the request within paper attached
Location: this request is attached to the Leith Walk portion of the request within paper attached **Contact:**

Enquiry No.: 2100304 **Logged by:** [REDACTED] **on:** 23/02/2026 08:58 **Officer:** Follow-up Officer
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Uneven ground at street/tram crossing
Report ID: 8968042
Category: Other
Uneven ground, with sunken tarmac and concrete slab for the tramline c. 1 inch higher. Not quite a pothole but easily trippable
Location:
Easting/Northing: 326505/675042 (55.962747, -3.178848)
Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 4-5, Leith Walk, Shaw's Colonies, Leith, City of Edinburgh, Alba / Scotland, EH7 4NZ, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH7 4NZ (32m away)
Location: Uneven ground at street/tram crossing **Contact:**
Report ID: 8968042
Category: Other
Uneven ground, with sunken tarmac and concrete slab for the tramline c. 1 inch higher. Not quite a pothole but easily trippable
Location:
Easting/Northing: 326505/675042 (55.962747, -3.178848)
Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 4-5, Leith Walk, Shaw's Colonies, Leith, City of Edinburgh, Alba / Scotland, EH7 4NZ, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH7 4NZ (32m away)

Site History Report

Effective: 30/05/2025 to 29/05/2026

Service: Roads General

Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00

Display Action Officer: Yes

Customer Services

Enquiry No.: 2099486 **Logged by:** Verint CRM Connector **on:** 21/02/2026 09:53 **Officer:** [REDACTED]
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole beside pedestrian crossing **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset

Enquiry No.: 2099414 **Logged by:** Verint CRM Connector **on:** 20/02/2026 23:12 **Officer:** Road Ops Live Enquiries
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: At side of carriageway next to the tram stop heading north **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset

Job Number: 50192919 **Defect Number:** 42200754

Enquiry No.: 2097962 **Logged by:** Verint CRM Connector **on:** 18/02/2026 16:24 **Officer:** [REDACTED]
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: I was getting out my car and was walking over cycle lane and tripped on the ridge that goes down the side. [REDACTED]
[REDACTED] The picture was taken a week ago on the 9th of February. It is really dangerous
On the 9th February at 6.30 pm on leith walk had got out my car and was walking over bike lane and tripped and fell [REDACTED]
[REDACTED] Luckily my [REDACTED] helped me. Have doctor today **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset

Enquiry No.: 2097384 **Logged by:** Verint CRM Connector **on:** 17/02/2026 23:24 **Officer:** [REDACTED]
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Outside beside la casa restaurant beside best kebab takeaway **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset

Enquiry No.: 2096724 **Logged by:** Verint CRM Connector **on:** 17/02/2026 09:35 **Officer:** [REDACTED]
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep pothole spraying road matter when cars drive over just by pedestrian crossing **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset

Enquiry No.: 2095944 **Logged by:** [REDACTED] **on:** 16/02/2026 09:45 **Officer:** [REDACTED]
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Pothole forming around manhole cover
Location: **Contact:**

Enquiry No.: 2088651 **Logged by:** [REDACTED] **on:** 04/02/2026 13:31 **Officer:** [REDACTED]
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.: Pavement badly damaged due to cars driving over the surface
Location: at junct with Dalmeny Street **Contact:**

Site History Report

Effective: 30/05/2025 to 29/05/2026
Service: Roads General
Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00
Display Action Officer: Yes

Customer Services

Enquiry No.: 2087251 **Logged by:** Verint CRM Connector **on:** 02/02/2026 12:03 **Officer:** [REDACTED]
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole at pedestrian crossing **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset

Enquiry No.: 2069486 **Logged by:** [REDACTED] **on:** 05/01/2026 09:29 **Officer:** [REDACTED]
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.: Multiple cracked paving slabs at junction
Report ID: 8621024
Category: Pavements/footpaths
Multiple cracked paving slabs at junction with Leith Walk. Please repair to ensure the crossing is not a trip hazard for pedestrians, especially those who are visually impaired.
Location:
Easting/Northing: 326676/675306 (55.965144, -3.176181)
Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): Dalmeny Street, Lorne, Leith, City of Edinburgh, Alba / Scotland, EH6 8RA, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH6 8PF (34m away)
Location: Multiple cracked paving slabs at junction **Contact:**
Report ID: 8621024
Category: Pavements/footpaths
Multiple cracked paving slabs at junction with Leith Walk. Please repair to ensure the crossing is not a trip hazard for pedestrians, especially those who are visually impaired.
Location:
Easting/Northing: 326676/675306 (55.965144, -3.176181)
Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): Dalmeny Street, Lorne, Leith, City of Edinburgh, Alba / Scotland, EH6 8RA, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH6 8PF (34m away)

Enquiry No.: 2061231 **Logged by:** Verint CRM Connector **on:** 19/12/2025 15:34 **Officer:** [REDACTED]
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: The road has sunken down around these manhole / inspection hatches and when heavy vehicles like buses or lorries (which are frequent on Leith Walk) drive over it it creates so much vibration it literally shakes my 2nd floor flat, and my flat is across the street. I feel this cannot be good for the fabric of the nearby buildings which are mostly 100+ years old. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset

Enquiry No.: 2058123 **Logged by:** Verint CRM Connector **on:** 13/12/2025 21:30 **Officer:** Traffic Signs Live Enquiries
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type unlit No entry sign is facing the wrong way
Location: No entry sign (right side of picture) should be facing Leith Walk; may have got loose and facing other direction **Contact:**

Site History Report

Effective: 30/05/2025 to 29/05/2026
Service: Roads General
Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00
Display Action Officer: Yes

Customer Services

Enquiry No.: 2042774 **Logged by:** Verint CRM Connector **on:** 13/11/2025 16:55 **Officer:** Customer Contact Centre
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Between Balfour Street and the foot of the Walk. **Contact:**
I suspect the pavements on the whole of Leith Walk suffer the same.

Enquiry No.: 2025279 **Logged by:** [REDACTED] **on:** 08/10/2025 09:17 **Officer:** Customer Contact Centre
Service: Roads General **Subject:** Pavement: General Enquiry **Classification:** General Enquiry
Desc.: Summary
First name : [REDACTED]
Last name : [REDACTED]
email : [REDACTED]
telephone number : [REDACTED]
Street number : [REDACTED]
Street address : [REDACTED]
Town : [REDACTED]
Postcode : [REDACTED]

If your comments relate to a council service for which you have an account then please provide an account number :

Short description of complaint : The pavements in leith walk in a terrible condition, post tram & cycle way. The slabs are broken, misplaced, loose and in a number locations trip haz.

Please provide the details of the complaint : The pavements in leith walk in a terrible condition, post tram & cycle way. The slabs are broken, misplaced, loose and in a number locations trip hazArds. This has to be due to poor spec. Installation or material, these should be fully repaired as a matter of urgency.

How would you like us to deal with this? : Review contract and have responsible party repair in full. Without cost to council tax payer. If it falls to Edin council for mid management - a person should be held responsible

Please upload additional documents that may assist us :

Submit

Location: Leith Walk

Contact:

Enquiry No.: 2021364 **Logged by:** Verint CRM Connector **on:** 30/09/2025 11:14 **Officer:** [REDACTED]
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Manhole cover has hole and broken tar which has fallen inwards creating an uneven **Contact:**
surface.

Plot Number: 2.00

Feature Id - Location: Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset

Site History Report

Effective: 30/05/2025 to 29/05/2026

Service: Roads General
Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00

Display Action Officer: Yes

Customer Services

Enquiry No.: 2002051 Logged by: Verint CRM Connector on: 24/08/2025 00:05 Officer: [REDACTED]
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.:
 Location: Chipped away edge of paving stone next to utility cover, possible trip hazard Contact:

Plot Number: 2.00 Feature Id - Location: Ward 12 - From Manderston Street to Pilrig Street both sides & Feature Type: Road Asset

Enquiry No.: 2002050 Logged by: Verint CRM Connector on: 24/08/2025 00:04 Officer: [REDACTED]
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.:
 Location: 1x Cracked paving stone (small) Contact:

Plot Number: 2.00 Feature Id - Location: Ward 12 - From Manderston Street to Pilrig Street both sides & Feature Type: Road Asset

Enquiry No.: 1999617 Logged by: Verint CRM Connector on: 19/08/2025 19:01 Officer: [REDACTED]
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.:
 Location: The pavement area between 15 to 19 Leith Walk. The area bordering and space between the cycle lane and pedestrian lane is broken.. I went over on my ankle because of this and also because of the limited space on the pedestrian lane. This pedestrian space is also taken up by an advertising board and table and chairs from a cake shop This is also very near a bus stop There is also an uncovered pothole already there. This is a very congested area The bicycle lae should have a speed limit Contact:

Enquiry No.: 1998778 Logged by: Verint CRM Connector on: 18/08/2025 16:02 Officer: [REDACTED]
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.:

Location: My [REDACTED] just tripped and fell on a broken pavement on the bike lane, outside ancient robot games. Vehicles keep parking on the cycle lane and breaking the paving stones. Please improve enforcement of not parking on the cycle lane, and replace this serious trip hazard. [REDACTED] Contact:

Plot Number: 3.00 Feature Id - Location: Ward 13 - Manderston Street to Great Junction Street Feature Type: Road Asset

Enquiry No.: 1998515 Logged by: Verint CRM Connector on: 18/08/2025 11:41 Officer: [REDACTED]
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.:
 Location: Pavement outside TSB has uneven slabs Contact:
 3 tenants of Manderston Court (Sheltered Housing) has fallen or tripped over these in the past month or so.... tenant fell on Sunday 17th August ([REDACTED]) please repair this section of pavement ASAP

Plot Number: 3.00 Feature Id - Location: Ward 13 - Manderston Street to Great Junction Street Feature Type: Road Asset

Enquiry No.: 1997468 Logged by: Verint CRM Connector on: 16/08/2025 09:56 Officer: [REDACTED]
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.:
 Location: Shattered and raised paving slab some 2.5m out from Leith Depot frontage. Multiple trips observed during 1.5 hour presence at location. Contact:

Plot Number: 2.00 Feature Id - Location: Ward 12 - From Manderston Street to Pilrig Street both sides & Feature Type: Road Asset

Site History Report

Effective: 30/05/2025 to 29/05/2026

Service: Roads General

Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00

Display Action Officer: Yes

Customer Services

Enquiry No.: 1992300 **Logged by:** Verint CRM Connector **on:** 07/08/2025 16:44 **Officer:** [REDACTED]
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
Location:Footpath.
Type:Foliage / Bush
Location: Tree branches overhanging the path **Contact:**

Enquiry No.: 1982607 **Logged by:** Verint CRM Connector **on:** 21/07/2025 15:33 **Officer:** [REDACTED]
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Between the door of 13 Leith Walk and the cycle path, there is a loose pavement slab that is getting worse. There are other loose slabs that were not fixed in place when installed as part of the tram works on the same strip. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 13 - Manderston Street to Great Junction Street **Feature Type:** Road Asset

Enquiry No.: 1969795 **Logged by:** [REDACTED] **on:** 27/06/2025 08:12 **Officer:** Roads Safety Email
Service: Roads General **Subject:** Traffic Sign: General Enquiry **Classification:** General Enquiry
Desc.: First name : [REDACTED]
Last name : [REDACTED]
email : [REDACTED]
Street number : [REDACTED]
Street address : [REDACTED]
Town : [REDACTED]
Postcode : [REDACTED]
Short description of complaint : Unsuitable road signage in relation to cycle lanes at the Foot of the Walk junction.
Please provide the details of the complaint : The design and layout of cycle lanes at the Foot of the Walk are not clear and I fear may lead to a serious accident. On the approach to the left turn on to Great Junction Street from Leith Walk the cycle lane appears to just end, which leads cyclists to mounting the pavement while still cycling at full speed. I work on Great Junction Street and have lost count of the amount of times a cyclist has almost smashed into myself or another pedestrian when turning that corner. I can think of no logical reason why the cycle lane suddenly ends, and while the onus is on the cyclist to take better care and pay more attention, they're also not really at fault as they appear to have no other option. Far more concerning than that corner, however, is the cycle lane which crosses Duke Street at the opposite side of the junction, which leads south onto Leith Walk. This evening at approximately 18:05, for what I believe might be the tenth time in the last three months, a cyclist attempted to cycle through the pedestrian green light and very nearly crashed into me. I'm not a cyclist myself, and I don't want to believe that all cyclist are so ignorant, so I can only assume that when the green light appears for pedestrians to cross at the Foot of the Walk from the island towards Duke Street, cyclists coming from the side of the road which now houses the Angel bar seem to think the light is green for them as well. I know that this isn't the case, so why do they keep doing it? I have, on more than one occasion, attempted to cross when the green light appears only to have a cyclist start ringing their bell or shouting at me to get out of the way, when I clearly have right of way as the green light is on. I've even witnessed a woman with a baby in a pram attempt to cross and quickly have to jump backwards back onto the path to avoid an oncoming cyclist (when crossing the Foot of the Walk from the direction of Duke Street towards Great Junction Street). At this point I'm just flabbergasted that with all the money spent on that junction, no one seemed to consider just how unclear the signals are for cyclists. Again I want to stress that cyclists are responsible for their own behaviour when cycling on public roads, but because I've witnessed this exact same behaviour more times than I can count I can't help but come to the conclusion that better signage is needed so that cyclists are aware they cannot cycle through the pedestrian green light.
How would you like us to deal with this? : Ideally I think someone from the council needs to spend a few hours observing that junction to witness the amount of cutting through the lights that takes place every single day by cyclists as well as motorists. At the very least, something needs to be done to address the issue of the cycle lanes. I don't know if that's improved signage or redesigning the cycle lanes altogether, or having a dedicated set of lights which signal cyclists.
Location: Foot of Leith Walk **Contact:**

Site History Report

Effective: 30/05/2025 to 29/05/2026
Service: Roads General
Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00
Display Action Officer: Yes

Customer Services

Enquiry No.: 1961750 **Logged by:** Verint CRM Connector **on:** 11/06/2025 14:02 **Officer:** [REDACTED]
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: There is a metal manhole (or drainage) cover on the road which must be loose as it makes a noise every time a vehicle goes over it. It is very noisy and annoyingly can be heard 2 flights up even when the windows are closed. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset

Enquiry No.: 1958819 **Logged by:** Verint CRM Connector **on:** 05/06/2025 08:22 **Officer:** [REDACTED]
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: A whole stretch of pavement and ridged slabs and work associated with the cycle path and bus stops is an absolute mess here. Broken and dangerous surfaces everywhere. Please get this sorted. **Contact:**

Plot Number: 3.00 **Feature Id - Location:** Ward 13 - Manderston Street to Great Junction Street **Feature Type:** Road Asset

Enquiry No.: 1958482 **Logged by:** Verint CRM Connector **on:** 04/06/2025 13:30 **Officer:** [REDACTED]
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Drain cover dropping as tarmac is cracking and breaking off around it on nearside of Nothbound carriageway. **Contact:**

Plot Number: 2.00 **Feature Id - Location:** Ward 12 - From Manderston Street to Pilrig Street both sides & **Feature Type:** Road Asset
Job Number: 50181088 **Defect Number:** 42185235

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
	Asset: 2.00	Asset - Locn.: Ward 12 - From Manderston Street to Pilrig Street both sides &			Feature Type: Road Asset		Area: North East Locality	
50168583	Replace all broken 450x600s and reset rockers as discussed on site with Jamie Boyle (RD: FW Slabs Broken/Missing)	From Dofos to tattoo studio	[REDACTED]	RD: Cat 3 - 60 Day	Job Committed	24/10/2024	22/01/2025	Est. ROAD/82097672
50181835	x7 rocking slabs (RD: FW Slabs Rocking)	Outside Victoria	[REDACTED]	RD: Cat 3 - 60 Day	Job Complete	24/06/2025	05/02/2026	Act. ROAD/82107207
50181836	1 broken cut 450x600 (RD: FW Slabs Broken/Missing)	Outside epoca	[REDACTED]	RD: Cat 3 - 60 Day	Job Complete	24/06/2025	03/02/2026	Act. ROAD/82107208
50181839	1 rocking 450x600 (RD: FW Slabs Rocking)	Outside 20-21	[REDACTED]	RD: Cat 3 - 60 Day	Job Complete	24/06/2025	28/01/2026	Act. ROAD/82107210
50182898	1 broken cut 450x600 at manhole (RD: FW Slabs Broken/Missing)	Outside 113	[REDACTED]	RD: Cat 3 - 60 Day	Job Complete	21/07/2025	23/09/2025	Act. ROAD/82107947
50182899	x7 rocking slabs as marked (RD: FW Slabs Rocking)	Outside boundary bar	[REDACTED]	RD: Cat 3 - 60 Day	Job Complete	21/07/2025	31/01/2026	Act. ROAD/82107948
50182912	x2 rocking slabs as marked (RD: FW Slabs Rocking)	Outside shwarma	[REDACTED]	RD: Cat 3 - 60 Day	Job Complete	21/07/2025	03/02/2026	Act. ROAD/82107956
50185001	x8 rocking slabs (RD: FW Slabs Rocking)	Outside magikats	[REDACTED]	RD: Cat 3 - 60 Day	Job Complete	25/09/2025	31/01/2026	Act. ROAD/82109252
50185899	replace x29 450x600s as marked (RD: FW Slabs Broken/Missing)	At dalmeny street	[REDACTED]	RD: Cat 3 - 60 Day	Job Committed	22/10/2025	20/01/2026	Est. ROAD/82109848

Site History Report

Effective: 30/05/2025 to 29/05/2026

Service: Roads General

Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00

Display Action Officer: Yes

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order
Asset: 2.00		Asset - Locn.: Ward 12 - From Manderston Street to Pilrig Street both sides &			Feature Type: Road Asset		Area: North East Locality	
50185912	x2 rocking slabs at manhole (RD: FW Slabs Rocking)	Outside easy tan		RD: Cat 3 - 60 Day	Job Complete	22/10/2025	03/02/2026	Act. ROAD/82109857
50187218	Relay rocking 450x600 (RD: FW Slabs Rocking)	Outside inchkeith house		RD: Cat 3 - 60 Day	Job Complete	20/11/2025	22/12/2025	Act. ROAD/82110692
50187219	Relay x3 marked slabs (RD: FW Slabs Rocking)	Outside toast		RD: Cat 3 - 60 Day	Job Complete	20/11/2025	22/12/2025	Act. ROAD/82110693
50187545	1no pothole (RD: CW Pothole)	Outside no297		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/11/2025	27/11/2025	Act. ROAD/82110929
50188616	x8 broken 450x600s x1 rocking 450x600 Replace damaged PCC kerb (RD: FW Slabs Broken/Missing)	At lorne street		RD: Cat 3 - 60 Day	Job Complete	17/12/2025	18/12/2025	Act. ROAD/82111748
50188625	1 broken cut 450x600 (RD: FW Slabs Broken/Missing)	Outside 346		RD: Cat 3 - 60 Day	Job Complete	17/12/2025	03/02/2026	Act. ROAD/82111755
50189585	x2 rocking 450x600s (RD: FW Slabs Rocking)	Outside qupi coffee shop		RD: Cat 3 - 60 Day	Job Complete	14/01/2026	27/01/2026	Act. ROAD/82112557
50189587	1 rocking 450 and 1 rocking cut 450 (RD: FW Slabs Rocking)	Outside jewellers		RD: Cat 3 - 60 Day	Job Complete	14/01/2026	20/01/2026	Act. ROAD/82112558
50189589	1 low cut 450x600 (RD: FW Slabs Broken/Missing)	Outside querencia		RD: Cat 3 - 60 Day	Job Complete	14/01/2026	20/01/2026	Act. ROAD/82112560
50191789	1no blocked gully (Gully: Blocked - Hand Clear)	Outside st Columbus hospice care		RG: Gully - Standard Priority	Job Committed	13/02/2026	13/05/2026	Est. RDGC14/82007596
50192043	5no rocking pcc slabs (RD: FW Slabs Rocking)	Outside Domino's pizza		RD: Cat 3 - 60 Day	Job Complete	17/02/2026	18/02/2026	Act. ROAD/82114560
50192050	1no Cw pothole (RD: CW Pothole)	Outside no 267		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	17/02/2026	17/02/2026	Act. ROAD/82114565
50192919	1 number pothole (RD: CW Pothole)	Outside number 282		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/02/2026	10/03/2026	Act. ROAD/82115320
50193643	1no pothole (RD: CW Pothole)	Outside 267		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/03/2026	10/03/2026	Act. ROAD/82115907
50193931	Remove x4 marked slabs and infill with cold tar	Junction with dalmeny street		RD: Cat 1 - 24 Hours	Job Complete	16/03/2026	17/03/2026	Act. ROAD/82116124
	Area is scheduled for permanent repair but needs made safe immediately (RD: FW Slabs Broken/Missing)							
50197028	Lift and relay x13 rocking slabs Replace broken cut 450x600 and 1 broken rumble strip (RD: FW Slabs Broken/Missing)	Outside bee tech/epoca		RD: Cat 3 - 60 Day	Job Complete	19/05/2026	17/06/2026	Act. ROAD/82118514
Asset: 3.00		Asset - Locn.: Ward 13 - Manderston Street to Great Junction Street			Feature Type: Road Asset		Area: North East Locality	
50183915	X13 rocking slabs (RD: FW Slabs Rocking)	Opposite 52		RD: Cat 3 - 60 Day	Job Complete	21/08/2025	31/01/2026	Act. ROAD/82108516

Site History Report

Effective: 30/05/2025 to 29/05/2026

Service: Roads General

Site: Leith Walk (7900015)

Asset Number: 1.00 to 9.00

Display Action Officer: Yes

Maintenance Management

Job No.	Description	Location	Officer	Priority	Job Status	Entered	Completion	Works Order	
Asset: 3.00		Asset - Locn.: Ward 13 - Manderston Street to Great Junction Street			Feature Type: Road Asset		Area: North East Locality		
50187217	Relay x3 marked slabs (RD: FW Slabs Rocking)	Outside antient robot games		RD: Cat 3 - 60 Day	Job Complete	20/11/2025	03/02/2026	Act. ROAD/82110691	
50195519	Lift and relay x10 marked slabs (RD: FW Slabs Rocking)	Behind foot of the walk bus stop		RD: Cat 3 - 60 Day	Job Complete	17/04/2026	22/04/2026	Act. ROAD/82117368	
50196523	1 pothole (RD: CW Pothole)	Outside barbers at foot of the walk		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/05/2026	13/05/2026	Act. ROAD/82118147	