

25/06/2026

Enquiry Trace Form - Preview

Enquiry: 2083887	Logged by: [REDACTED]	on 27/01/2026 14:50
Service: Roads General Classification: Request for service		
Subject: Street Furniture: Defective		
Desc.: Loose steps at Murrayfield tram stop Report ID: 8778838 Category: Pavements/footpaths The bottom steps on the left are dangerously loose and rocking. Location: Easting/Northing: 322801/672864 (55.942598, -3.237548) Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 74, Roseburn Street, Murrayfield, City of Edinburgh, Alba / Scotland, EH12 5PA, United Kingdom Nearest postcode to the pin placed on the map (automatically generated): EH12 5PL (39m away)		
Site: Roseburn Street (7903203), Roseburn, Edinburgh, City of Edinburgh		
Site Address: Roseburn Street	Area: North West Locality	
Location: Loose steps at Murrayfield tram stop Report ID: 8778838 Category: Pavements/footpaths The bottom steps on the left are dangerously loose and rocking. Location: Easting/Northing: 322801/672864 (55.942598, -3.237548) Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 74, Roseburn Street, Murrayfield, City of Edinburgh, Alba / Scotland, EH12 5PA, United Kingdom Nearest postcode to the pin placed on the map (automatically generated): EH12 5PL (39m away)	Ward: 06-Corstorphine/Murrayfield	
Email: [REDACTED]		
Customer: [REDACTED]	Time: 27/01/2026 14:50	Method: Email
Name: [REDACTED]	Email: [REDACTED]	
Address:		
Current Status:		
No. Effective	Status	Officer
3 10/02/2026 10:25:27	No Actionable Issue	[REDACTED]
Notes: No actionable issues seen when inspected. Half the steps barricaded off when inspected		
Status history:		
No. Effective	Status	Officer
2 28/01/2026 22:35	Enquiry Raised	[REDACTED]
1 27/01/2026 14:50	Enquiry Raised	[REDACTED]
Revised Status:		

Name : Signed : Date : Time :