

Effective: 01/11/2025 to 19/02/2026

Service: Roads General

Site: West Savile Road (7902285)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: West Savile Road (7902285)

Locality: Mayfield, Edinburgh, City of Edinburgh

Area: South East Locality

Customer Services

Enquiry No.: 2086796

Service: Roads General

Desc.: Problem: Other.
Location:Pavement.
Type:Foliage / Bush

Logged by: Verint CRM Connector

Subject: Trees & Foliage: Defect

on: 01/02/2026 14:35

Classification: Request for service

Location: On the northern side of West Savile Road there is old leaf mould following fallen leaves from the trees in the Cala Development at James Gall Whnd not being cleared in the autumn.

Contact: