

Effective: 01/11/2025 to 19/02/2026

Service: Roads General

Site: West Savile Terrace (7902286)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: West Savile Terrace (7902286)	Locality: Blackford , Edinburgh, City of Edinburgh	Area: South East Locality
-------------------------------------	--	---------------------------

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South East Locality	
Batch:	41254180 - Inspection Batch			Route: Ad hoc Route			Date:	19/02/2026
42199882	No 1 pothole	19/02/2026	Outside no 11	RD: CW Pothole	Internal		Committed	50192248
Batch:	41251681 - Inspection Batch			Route: Ad hoc Route			Date:	03/02/2026
42198417	No 1 pothole	03/02/2026	At crossing point at traffic lights heading east opposite lampost WJL26	RD: CW Pothole	Internal		Committed	50191047
Batch:	41250511 - Inspection Batch			Route: Ad hoc Route			Date:	27/01/2026
42197629	No 1 pothole	27/01/2026	On crossing point at no entry sign outside no 39 blackford avenue sunken track	RD: FW HRA Pothole	Internal		Committed	50190455
Batch:	41247200 - Inspection Batch			Route: SE_CW1_North1			Date:	07/01/2026
	No actionable defects found							
Batch:	41247169 - Inspection Batch			Route: Ad hoc Route			Date:	07/01/2026
42196189	No1 pothole	07/01/2026	Opposite no 13	RD: CW Pothole	Internal		Committed	50189308
Batch:	41247163 - Inspection Batch			Route: Ad hoc Route			Date:	07/01/2026
42196188	No 1 pothole	07/01/2026	Outside no 19	RD: CW Pothole	Internal		Committed	50189307

Customer Services

Enquiry No.:	34010714	Logged by:		on:	09/01/2026 10:57
Service:	Roads General	Subject:	Pavement: Damaged / Defective	Classification:	Request for service
Desc.:	west saville terrace at Blackford Avenue, near number 39 The pavement is right beside a retirement complex so elderly people are concerned The pavements are also very cracked with holes, so wheelchair access is difficult.				
Location:	West Savile Terrace	Contact:			
Plot Number:	1.00	Feature Id - Location:	Whole Street	Feature Type:	Road Asset
Job Number:	50190455	Defect Number:	42197629		
Enquiry No.:	2097224	Logged by:	Verint CRM Connector	on:	17/02/2026 18:42
Service:	Roads General	Subject:	Road: Defective / Damaged	Classification:	Request for service
Desc.:					
Location:	the run up to and the traffic light junction is all breaking up with numerous potholes		Contact:		
Plot Number:	1.00	Feature Id - Location:	Whole Street	Feature Type:	Road Asset
Enquiry No.:	2095117	Logged by:	Verint CRM Connector	on:	14/02/2026 15:46
Service:	Roads General	Subject:	Road: Defective / Damaged	Classification:	Request for service
Desc.:					
Location:	The whole road is terribly cracked and crumbling at this junction including drains sticking up out of the ground. Needs total replacement.		Contact:		
Plot Number:	1.00	Feature Id - Location:	Whole Street	Feature Type:	Road Asset

Effective: 01/11/2025 to 19/02/2026
Service: Roads General
Site: West Savile Terrace (7902286)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2094771	Logged by: Verint CRM Connector	on: 13/02/2026 19:06
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Very deep pothole, think our car may be damaged so will be doing an assessment	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2094770	Logged by: Verint CRM Connector	on: 13/02/2026 19:04
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: One of the stain covers has collapsed in the pavement and very dangerous for pedestrians, someone could fall an hurt themselves very badly at break a limb	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2094636	Logged by: Verint CRM Connector	on: 13/02/2026 16:02
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Outside Margiotas Shop on West Savile Terrace. You need to repair this quickly before someone injures themselves!	Contact:	
Enquiry No.: 2094374	Logged by:	on: 13/02/2026 11:11
Service: Roads General	Subject: Covers: Damaged / Defective	Classification: Request for service
Desc.: Loud Noise everytime someone goes over it		
Location: Between Mayfield Road and West Savile Terrace near Margiotta store	Contact:	
Enquiry No.: 2092615	Logged by: Verint CRM Connector	on: 11/02/2026 11:22
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2092610	Logged by: Verint CRM Connector	on: 11/02/2026 11:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50192248	Defect Number: 42199882	
Enquiry No.: 2090392	Logged by: Verint CRM Connector	on: 07/02/2026 13:05
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Deep pothole near centre of road outside 7 West Savile Terrace	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Effective: 01/11/2025 to 19/02/2026
Service: Roads General
Site: West Savile Terrace (7902286)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2087617	Logged by: Verint CRM Connector	on: 02/02/2026 20:37
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50191047	Defect Number: 42198417	
Enquiry No.: 2083963	Logged by: Verint CRM Connector	on: 27/01/2026 16:26
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: In the middle of the road - right by the bus stop - Massive depression in the road. Getting much worse! Particularly because buses drive here.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2079641	Logged by: Verint CRM Connector	on: 20/01/2026 09:37
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2079639	Logged by: Verint CRM Connector	on: 20/01/2026 09:36
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Road	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2079638	Logged by: Verint CRM Connector	on: 20/01/2026 09:35
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The road is crumbling	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2079634	Logged by: Verint CRM Connector	on: 20/01/2026 09:34
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2069273	Logged by: Verint CRM Connector	on: 04/01/2026 21:22
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: West Savile Terrace, north (westbound) side, immediately outside no 19. Large and deep pothole, with several very large stones in base being dislodged and thrown to side of carriageway - possible risk of injury to persons/vehicles.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50189307	Defect Number: 42196188	

Effective: 01/11/2025 to 19/02/2026
 Service: Roads General
 Site: West Savile Terrace (7902286)

Asset Number: 1.00 to 9.00
 Display Action Officer: No

Customer Services

Enquiry No.: 2061528 Logged by: Verint CRM Connector on: 20/12/2025 12:06
 Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
 Desc.: This is a problem with the use of this area of tarmac for Voi Bikes. I have already reported the issue to them but as the council licences the location it is your responsibility. The location of the bikes entirely blocks the pedestrian route between the lights from the Reid Memorial Church and the other two. Difficult enough if able, if less able or sight impaired then practically impossible. It is also a very windy corner and a few days ago in the high winds most of the bikes had fallen over,

Location: Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 2048144 Logged by: Verint CRM Connector on: 24/11/2025 16:47
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:

Location: Junction/Pedestrian crossing between West Savile Terrace with Mayfield Road (outside Margiotta supermarket). Extremely poor condition of tarmac - extensive potholing, broken tarmac, uneven surface. Condition has deteriorated over the last year - reported previously and no repairs undertaken. Road surface is extremely dangerous for cyclists and pedestrians (especially those with poor mobility). Needs urgent repair Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 2042064 Logged by: Verint CRM Connector on: 12/11/2025 14:46
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:

Location: The road condition at the junction of West Savile Terrace and Mayfield Road is in an abysmal condition on both roads. It has been pothole filled many times but the time has come to do a proper repair. It causes severe jolting to cars and passengers. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50189307	No 1 pothole (RD: CW Pothole)	Outside no 19	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/01/2026	08/01/2026	Act. ROAD/82112329
50189308	No1 pothole (RD: CW Pothole)	Opposite no 13	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/01/2026	08/01/2026	Act. ROAD/82112330
50190455	No 1 pothole (RD: FW HRA Pothole)	On crossing point at no entry sign outside no 39 blackford avenue sunken track	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/01/2026	30/01/2026	Act. ROAD/82113258
50191047	No 1 pothole (RD: CW Pothole)	At crossing point at traffic lights heading east opposite lamppost WJL26	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/02/2026	04/02/2026	Act. ROAD/82113719
50192248	No 1 pothole (RD: CW Pothole)	Outside no 11	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/02/2026	11/03/2026	Act. ROAD/82114756