

Effective: 01/01/2018 to 19/06/2026
Service: Roads General
Site: Bellevue Road (7903857)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Site: Bellevue Road (7903857)

Locality: Broughton, Edinburgh, City of Edinburgh

Area: North East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	North East Locality
Batch:	41260610 - Inspection Batch			Route:	NE_CF2_BellevueEast1		Date:	13/04/2026
42203975	Sunken manhole at crossing point	13/04/2026	On footway opposite 65 outside Bellevue express	RU: Utility Apparatus	Internal		Uncommitted	50195218
42203968	Carriageway breaking up approx 3x7m	13/04/2026	Opposite 11	RD: CW Cracked/Broken	Internal		Uncommitted	50156112
Batch:	41258732 - Inspection Batch			Route:	Ad hoc Route		Date:	20/03/2026
42202627	Controlled Parking Zone remove pole/sign/bay and install syl	20/03/2026	OS 70 bellevue road	NSL: Marking Removal Defect	Internal		Committed	50194271
Batch:	41257301 - Inspection Batch			Route:	Ad hoc Route		Date:	09/03/2026
42201548	1. Pothole	09/03/2026	Opposite no 11	RD: CW Pothole	Internal		Committed	50193518
Batch:	41237916 - Inspection Batch			Route:	Ad hoc Route		Date:	06/10/2025
42190511	2 number potholes	06/10/2025	Outside number 13	RD: CW Pothole	Internal		Committed	50185161
Batch:	41224783 - Inspection Batch			Route:	NE_CF2_BellevueEast1		Date:	01/04/2025
42180376	Carriageway breaking up approx 3x7m	01/04/2025	Opposite 11	RD: CW Cracked/Broken	Internal		No Action Required	
42180377	Carriageway breaking up approx 1x1m	01/04/2025	Outside 15	RD: CW Cracked/Broken	Internal		Uncommitted	50156114
Batch:	41215990 - Inspection Batch			Route:	Ad hoc Route		Date:	22/01/2025
42173773	Uplift abandoned sign	22/01/2025	Bellevue road os 56	RD: Uplift Abandoned TM	Internal		Committed	50173406
Batch:	41186662 - Inspection Batch			Route:	NE_CF2_BellevueEast1		Date:	18/03/2024
42151972	Uneven section of footway	18/03/2024	O/S driveway to no 96	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50100071
42151955	.5x.5m patch	18/03/2024	Opposite 11	RD: CW Cracked/Broken	Internal		Uncommitted	50132773
42151956	Carriageway breaking up approx 3x7m	18/03/2024	Opposite 11	RD: CW Cracked/Broken	Internal		No Action Required	
42151958	Carriageway breaking up approx 1x1m	18/03/2024	Outside 15	RD: CW Cracked/Broken	Internal		No Action Required	
Batch:	41171302 - Inspection Batch			Route:	Ad hoc Route		Date:	06/11/2023
42138811	1 number pothole	06/11/2023	Opposite number 11	RD: CW Pothole	Internal		Committed	50145169
Batch:	41153143 - Inspection Batch			Route:	NE_CF2_BellevueEast1		Date:	24/03/2023
42123516	Uneven section of footway	24/03/2023	O/S driveway to no 96	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42123520	.5x.5m patch	24/03/2023	Opposite 11	RD: CW Cracked/Broken	Internal		No Action Required	
Batch:	41110289 - Inspection Batch			Route:	NE_CF2_BellevueEast1		Date:	13/12/2021
42086808	Pothole at ramp	13/12/2021	Opp no 11	RD: CW Pothole	Internal		Committed	50100034
42086823	Pothole	13/12/2021	O/S school at L of School marking	RD: CW Pothole	Internal		Committed	50100046
42086849	Uneven section of footway	13/12/2021	O/S driveway to no 96	RD: FW HRA Cracked/Broken	Internal		No Action Required	
Batch:	41089737 - Inspection Batch			Route:	Ad hoc Route		Date:	06/04/2021
42066503		06/04/2021	Whole street	RD: CW Rutting	Internal		Committed	50080509
Batch:	41089722 - Inspection Batch			Route:	Ad hoc Route		Date:	06/04/2021
42066491	C/W pTching	06/04/2021	Whole street	RD: CW Rutting	Internal		Committed	50080500
Batch:	41061774 - Inspection Batch			Route:	NE_CF2_BellevueEast1		Date:	18/08/2020
42052601	Cw pothole as marked	18/08/2020	At junction with Green St	RD: CW Pothole	Internal		Committed	50060563

Effective: 01/01/2018 to 19/06/2026
 Service: Roads General
 Site: Bellevue Road (7903857)

Asset Number: 1.00 to 9.00
 Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North East Locality		
Batch: 41061774 - Inspection Batch				Route: NE_CF2_BellevueEast1		Date: 18/08/2020		
42052607	Cw pothole as marked	18/08/2020	O/S no 92	RD: CW Pothole	Internal		Committed	50060578
42052599	3 x Cw potholes as marked	18/08/2020	O/S no 15	RD: CW Pothole	Internal		Committed	50060560
Batch: 41058266 - Inspection Batch				Route: Ad hoc Route		Date: 27/05/2020		
42050438	Skip on carriageway	27/05/2020	Outside 54	RU: Fixed Penalty Notice	Internal		Committed	50056312
Batch: 41050437 - Inspection Batch				Route: Ad hoc Route		Date: 23/01/2020		
42044658	Cw pothole	23/01/2020	Opp 84	RD: CW Pothole	Internal		Committed	50050346
Batch: 41042717 - Inspection Batch				Route: Ad hoc Route		Date: 11/10/2019		
No actionable defects found								
Batch: 41031527 - Inspection Batch				Route: Ad hoc Route		Date: 24/04/2019		
42029846	Gully blocked please clean and flush	24/04/2019	O/s 76	Gully: Blocked / Flooding	Internal		Committed	50031664
Batch: 41022730 - Inspection Batch				Route: NE_CF2_BellevueEast1		Date: 23/11/2018		
No actionable defects found								

Customer Services

Enquiry No.: 34008617	Logged by: [REDACTED]	on: 05/06/2024 14:01
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: The B901 Belle Vue just beyond the London Street roundabout please inspect road surface.		
Location: Bellevue Road		
Contact:		
Enquiry No.: 34008472	Logged by: [REDACTED]	on: 29/04/2024 11:00
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Bellevue Road the stretch between the two traffic islands on Bellevue B901 (outside 3 Bellevue and the Bellevue Dental Practice) please see pics attached.		
Location: Bellevue Road		
Contact:		
Enquiry No.: 34008123	Logged by: [REDACTED]	on: 15/02/2024 09:21
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Bellevue Road please inspect road surface		
Location: Bellevue Road		
Contact:		
Enquiry No.: 34006381	Logged by: [REDACTED]	on: 06/02/2023 11:58
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Bellevue Road please inspect road surface .		
Location: Bellevue Road		
Contact: Liam McCabe		
Enquiry No.: 30703279	Logged by: [REDACTED]	on: 08/03/2018 16:42
Service: Roads General	Subject: Roadworks: General Enquiry	Classification: Frontline Resolution (Stage1)
Desc.: Customer has called today as she is concerned about her house. There are road works going on at Bellevue Road right outside her house. Her house is shaking and as the vibrations are coming through the ground and stuff is actually moving in her house. She worried that there could be foundation damage due to this.		
Location: Bellevue Road		
Contact:		
Enquiry Ref: 1007392		

Effective: 01/01/2018 to 19/06/2026

Service: Roads General

Site: Bellevue Road (7903857)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 2105869

Service: Roads General

Desc.:

Location: pothole near edge of road on the southside next to the school at the top end of the lower zig-zags. Risk to cycling.

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 03/03/2026 16:10

Classification: Request for service

Contact:

Plot Number: 1.00

Job Number: 50193518

Feature Id - Location: Whole Street

Defect Number: 42201548

Feature Type: Road Asset

Enquiry No.: 2065821

Service: Roads General

Desc.:

Location: The stump of a plant or tree is bulging from the pavement, preventing the gate to the school path from opening fully. This creates an impediment and is potentially unsafe.

Logged by: Verint CRM Connector

Subject: Pavement: Damaged / Defective

on: 29/12/2025 17:58

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street

Feature Type: Road Asset

Enquiry No.: 2022840

Service: Roads General

Desc.:

Location: Deep pothole, can see cobblestone underneath

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 02/10/2025 20:29

Classification: Request for service

Contact:

Plot Number: 1.00

Job Number: 50185161

Feature Id - Location: Whole Street

Defect Number: 42190511

Feature Type: Road Asset

Effective: 01/01/2018 to 19/06/2026
Service: Roads General
Site: Bellevue Road (7903857)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1887168
Service: Roads General
Desc.: What type of sign is it? Road sign problem, type unlit Folding temporary roadworks sign (triangular sign mounted on s folding steel frame).
This sign has been left unused, folded up and propped against a streetside hedge for the last year.
Location: Unused folding temporary road sign left abandoned and propped against roadside hedge for the last year, outside 54/56 Bellevue Road EH7 4DE beside Ringo ticket machine. This causes a potential hazard to pedestrians/ wheelchair users/ children playing in the street.

Logged by: Verint CRM Connector
Subject: Public Utilities: General

on: 15/01/2025 15:24
Classification: Request for service
Contact:

Plot Number: 1.00
Job Number: 50173406

Feature Id - Location: Whole Street
Defect Number: 42173773

Feature Type: Road Asset

Enquiry No.: 1805888
Service: Roads General
Desc.:
Location: Hi,

Logged by: Verint CRM Connector
Subject: Pavement: Damaged / Defective

on: 26/07/2024 14:24
Classification: Request for service
Contact:

There is a very loose paving slab at the entrance to 17 Bellevue Road. It is unsteady so may cause injury, may completely break and is allowing water ingress under the entrance to the building.

Plot Number: 1.00

Feature Id - Location: Whole Street

Feature Type: Road Asset

Effective: 01/01/2018 to 19/06/2026

Service: Roads General

Site: Bellevue Road (7903857)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1772134

Service: Roads General

Desc.: roadworks outside Bellevue Express red placstic barriers have blown on to Road can someone check and remedy

Location: Bellevue Road/Anningdale Street

Logged by: Stewart McGregor

Subject: Roadworks: Defect

on: 04/06/2024 16:43

Classification: Request for service

Contact:



Enquiry No.: 1756503

Service: Roads General

Desc.:

Location: Two potholes on either side of the speed bump

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 19/05/2024 13:14

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street

Feature Type: Road Asset



Effective: 01/01/2018 to 19/06/2026

Service: Roads General

Site: Bellevue Road (7903857)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1638675

Service: Roads General

Desc.:

Location: Two large potholes near the speed bumps

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 04/11/2023 13:23

Classification: Request for service

Contact:

Plot Number: 1.00

Job Number: 50145169

Feature Id - Location: Whole Street

Defect Number: 42138811

Feature Type: Road Asset

Enquiry No.: 1619088

Service: Roads General

Desc.:

Location: Since the electric works were carried out last year by a contractor the slab in front of the main door is unsafe. The slab was removed and the cement broken so now it moves when standing and a large hole is now present that will gather water and could potentially cause subsidence going forward. It was discussed I believe with the contractor or a call was made (by another resident)but it must have ignored. I'm concerned with winter approaching it could get worse. I appreciate any advice.

Logged by: Verint CRM Connector

Subject: Pavement: Damaged / Defective

on: 25/09/2023 19:13

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street

Feature Type: Road Asset

Enquiry No.: 1344817

Service: Roads General

Desc.:

Location: Busses diverted down Bellevue Road due to works on Leith Walk are causing vibrations of increasing magnitude to properties on the street. There is a concern for damage to properties from these repeated vibrations

Logged by: Verint CRM Connector

Subject: Road: Defective / Damaged

on: 14/03/2022 11:52

Classification: Request for service

Contact:

Plot Number: 1.00

Feature Id - Location: Whole Street

Feature Type: Road Asset

Effective: 01/01/2018 to 19/06/2026

Service: Roads General

Site: Bellevue Road (7903857)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services



Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1145544	Logged by: Verint CRM Connector	on: 22/03/2021 12:00
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Re: 101000589095, 101000596403, 101000600278	Contact:	
My concerns are repeatedly being dismissed. It is the opinion of myself and all neighbours, within the tenement 89 Bellevue Road, that the severity of building shake we all experience from busses hitting the pothole is detrimental to the structural integrity of this Victorian tenement building. The damage to the road outside, which extends along most of Bellevue Road, continues to deteriorate on a daily basis with the number of busses passing by.		
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1144255	Logged by: Verint CRM Connector	on: 19/03/2021 16:06
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: 101000595457, 101000596403	Contact:	
The pothole in the road in Bellevue Road is worsening and with it the potentially detrimental effects to the building 89 Bellevue Road. Your previous replies have failed to acknowledge the severity of the situation. This has now been raised with the office of the local MSP Ben MacPherson and local councillor Rob Munn. Complacency will not solve this critical situation. Please take this seriously.		
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1141427	Logged by: Verint CRM Connector	on: 16/03/2021 12:50
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Location: Ref - 101000595457	Contact:	
There's a pothole on the road caused by the bus traffic. Every time a bus hits the pothole the entire tenement building shudders. Nobody had 'inspected' this as you have falsely claimed. This is critical to the structural integrity of the affected buildings.		
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Effective: 01/01/2018 to 19/06/2026

Service: Roads General

Site: Bellevue Road (7903857)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1140783 Logged by: Verint CRM Connector on: 15/03/2021 14:00
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:

Location: Pothole on road caused by double decker busses. When the busses drive over the pothole the building shakes and can be felt on the top floor. The shake is so severe it wakes up members of my household, including me. My neighbours are also experiencing this. [REDACTED]

The recent removal of speed bumps from the road now allows the busses to drive at greater speeds.

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1138062 Logged by: Verint CRM Connector on: 10/03/2021 14:25
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:

Location: Potholes, cracks in tarmac, sinking in tarmac, road surface uneven Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1136466 Logged by: Verint CRM Connector on: 08/03/2021 11:15
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:

Location: Deep potholes and cracks Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1136442 Logged by: Verint CRM Connector on: 08/03/2021 10:49
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:

Location: 2 large Pot holes in road. Buses travelling along road hitting these pot holes and causing vibration to the tenements and building at 113. I myself hit the pot hole before I realised it was there and clinked my car. I was travelling very slow and drive a small car. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1111760 Logged by: Verint CRM Connector on: 02/02/2021 23:46
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:

Location: 2 small potholes + one large on NE bound side, adjacent to recycling bins. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 1056530 Logged by: Verint CRM Connector on: 20/10/2020 15:51
 Service: Roads General Subject: Traffic Sign:Defective/Damaged Classification: Request for service
 Desc.:

What type of sign is it? Road sign problem, type unlit
 Location: Temporary traffic lights and 'Keep Right' sign are completely blocking driveway at 56 Bellevue Road EH7 4DE. Impossible to get car out of driveway (or in again). Contact:

Effective: 01/01/2018 to 19/06/2026

Service: Roads General

Site: Bellevue Road (7903857)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services



Enquiry No.: 1037384

Service: Roads General

Desc.: From: [redacted]

Logged by: [redacted]

Subject: Road Safety: General Enquiry

on: 10/09/2020 08:06

Classification: General Enquiry

Sent: 08 September 2020 10:53

To: Clarence <Clarence@edinburgh.gov.uk>

Subject: Speed Bumps Removal Bellevue Road

Good Morning,

I have been passed on your contact information from Edinburgh City Council. I am a resident on Bellevue road, due to the ongoing traffic reroute with HGVs and busses causing vibration of the adjacent building edinburgh council have advised us that the speed bumps are to be removed on the street. Can you confirm when this work has been programmed for? As the vibration is currently causing damage to all the surrounding properties.

Best regards,

Location: [redacted]

Contact: [redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

[redacted]

Effective: 01/01/2018 to 19/06/2026
Service: Roads General
Site: Bellevue Road (7903857)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1034813 **Logged by:** Verint CRM Connector **on:** 05/09/2020 17:04
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: 33 Bellevue Road, by far the worst on the street. Something needs to be done! **Contact:**

Enquiry No.: 1023498 **Logged by:** Verint CRM Connector **on:** 17/08/2020 11:17
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: bellevue road at green street.
potholes on road. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1018817 **Logged by:** Verint CRM Connector **on:** 07/08/2020 13:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Diverted traffic along Bellevue Road is flying over the speed bump outside number 113, causing our block of 13 flats to shake. Plaster is falling and we are being woken up by the first buses of the day shaking our building. The speed bump/sleeping policeman needs removed. **Contact:**

Enquiry No.: 1012322 **Logged by:** Verint CRM Connector **on:** 24/07/2020 13:11
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The traffic has been diverted from Leith Walk down Bellevue Road. This normally quiet residential street now has a constant stream of cars, buses and lorries. We have had issues with lorries and buses speeding but the main issue that large vehicles going over the speed bumps is causing the whole building to shake. We have already noticed cracking to plaster since the traffic was diverted. Is it possible to have the speed bumps removed or reduced, and for a speed camera to be put in? **Contact:**

Enquiry No.: 1011469 **Logged by:** Verint CRM Connector **on:** 22/07/2020 18:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Due to the closure of Leith walk, our road is now being used as a through road. There is a speed bump right outside our house and whenever buses or lorry's go over it our entire house shakes. This is now happening on average once every ten minutes. I suspect that most vehicles are speeding over the bump. Neighbours have also filed a complaint about this issue. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Effective: 01/01/2018 to 19/06/2026
Service: Roads General
Site: Bellevue Road (7903857)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1010369 **Logged by:** Verint CRM Connector **on:** 20/07/2020 15:34
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Hi there, **Contact:**

With the current works from the trams on Leith walk buses and heavy traffic travelling along Bellevue road is causing the houses and tenement building to shake. I have spoken to several residences and we are concerned damage might be being done to the building with some noting cracks around there windows have started to form.

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1008537 **Logged by:** Verint CRM Connector **on:** 16/07/2020 09:04
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Following recent traffic diversions from Leith Walk to Bellevue Road there is persistent heavy vehicle traffic buses as well as HGVs. This has resulted in vibrations within residential properties on Bellevue Road as each vehicle passes. This route does not appear suitable for increased traffic flow. [REDACTED] r. Please confirm when this can be checked and provide details on the impact of the change in loading during your planning . **Contact:**

Enquiry No.: 965884 **Logged by:** Verint CRM Connector **on:** 24/02/2020 23:22
Service: Roads General **Subject:** Traffic Sign: Defective/Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow
Location: School Patrol sign was damaged when a vehicle reversed into it around 0950 hours on Monday 24 February 2020. The driver reported this incident to police in Glasgow. Police Scotland [REDACTED] . **Contact:**

Enquiry No.: 947708 **Logged by:** Verint CRM Connector **on:** 22/01/2020 18:46
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Asphalt, tar missing, type 1 broken up creating 1 or two holes in the road. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 910913 **Logged by:** Verint CRM Connector **on:** 04/11/2019 18:54
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: huge puddle appears when it rains **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Effective: 01/01/2018 to 19/06/2026
 Service: Roads General
 Site: Bellevue Road (7903857)

Asset Number: 1.00 to 9.00
 Display Action Officer: No

Customer Services

Enquiry No.: 780898	Logged by: [REDACTED]	on: 11/01/2019 11:45
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Dropped kerb o/s property requires lowering as catching bottom of car		
Location: o/s no 70	Contact:	
Enquiry No.: 644779	Logged by: CEC Enterprise Service Bus	on: 09/04/2018 15:40
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Pavement dug up by the gas oard. They informed customer we would re do pavement. Can this be done. Yellow plastic safety boards have become loose.	Contact:	
Enquiry No.: 635630	Logged by: [REDACTED]	on: 19/03/2018 16:10
Service: Roads General	Subject: Road Markings: Defective	Classification: Request for service
Desc.: There have been marking placed o/s 55 Bellevue Road, original markings were o/s 53 but road got resurfaced and markings got put accidently o/s 55. Is there anything we can do to resolve this to put markins back o/s 53. Already spoken to waste and they have advised to contact roads.		
Location: O/s 55	Contact:	
Enquiry No.: 616568	Logged by: CEC Enterprise Service Bus	on: 08/02/2018 10:35
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Resurfacing road but not cul de sac. Can this be done with the road	Contact:	
Enquiry No.: 616552	Logged by: CEC Enterprise Service Bus	on: 08/02/2018 10:25
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Bellevue Road is currently getting refurbished however the worst part of it is where 76 Bellevue Road is- the cul-de-sac off the main road. Please could this be looked at as a matter of urgency- whilst all the equipment and manpower is resurfacing the main Bellevue road it would make the most sense to do this at the same time and will save resources too. Please let us know. Many thanks, Naom [REDACTED]	Contact:	

Plot Number: 1.00

Feature Id - Location: Whole Street

Feature Type: Road Asset

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North East Locality	
50031664	Gully blocked please clean and flush (Gully: Blocked / Flooding)	O/s 76	RG: Gully - Standard Priority	Job Complete	24/04/2019	13/08/2020	Act. ROAD/82020483
50050346	Cw pothole (RD: CW Pothole)	Opp 84	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/01/2020	28/01/2020	Act. ROAD/82031239
50056312	Skip on carriageway (RU: Fixed Penalty Notice)	Outside 54	Non Routine (One Off Works)	Job Complete	27/05/2020	11/06/2020	Act. ROAD/82036340

Effective: 01/01/2018 to 19/06/2026
 Service: Roads General
 Site: Bellevue Road (7903857)

Asset Number: 1.00 to 9.00
 Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: North East Locality		
50060560	3 x Cw potholes as marked (RD: CW Pothole)	O/S no 15	RD: Cat 3 - 60 Day	Job Complete	18/08/2020	19/08/2020	Act. ROAD/82038723
50060563	Cw pothole as marked (RD: CW Pothole)	At junction with Green St	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/08/2020	19/08/2020	Act. ROAD/82038724
50060578	Cw pothole as marked (RD: CW Pothole)	O/S no 92	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/08/2020	19/08/2020	Act. ROAD/82038727
50080500	C/W pTching (RD: CW Rutting)	Whole street	RD: Cat 2 - 5 Day	Job Cancelled	06/04/2021	13/04/2021	Est. ROAD/82048247
50080509	RD: CW Rutting	Whole street	RD: Cat 2 - 5 Day	Job Cancelled	06/04/2021	13/04/2021	Est. ROAD/82048254
50100034	Pothole at ramp (RD: CW Pothole)	Opp no 11	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/12/2021	14/12/2021	Act. ROAD/82057498
50100046	Pothole (RD: CW Pothole)	O/S school at L of School marking	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/12/2021	14/12/2021	Act. ROAD/82057507
50145169	1 number pothole (RD: CW Pothole)	Opposite number 11	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/11/2023	08/11/2023	Act. ROAD/82082411
50173406	Uplift abandoned sign (RD: Uplift Abandoned TM)	Bellevue road os 56	RD: Cat 4 - Programmed	Job Complete	22/01/2025	26/01/2025	Act. ROAD/82101189
50185161	2 number potholes (RD: CW Pothole)	Outside number 13	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/10/2025	06/10/2025	Act. ROAD/82109364
50193518	1. Pothole (RD: CW Pothole)	Opposite no 11	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/03/2026	13/03/2026	Act. ROAD/82115798
50194271	Controlled Parking Zone remove pole/sign/bay and install syl (NSL: Marking Removal Defect)	OS 70 bellevue road	Parking Operations	NSL Job Complete	20/03/2026	08/04/2026	Act. NSL/40144