

62795 Snip 1 and Snip 2

Snip 1

SBFCINSDTL10.7 Inspection details



Plot	1	Plot 1					
Inspection type	NOTE - Inspectors notes	Date	10.01.2014	Time		Inspecting Officer	
Status	O	Hours taken		Miles Travelled			
Notes Category							
Inspection Notes							
Inspected 113 Bellevue Road following a complaint from a [REDACTED] about cracking. There was a number of flats who have cracking in their flats, see list as follows :- Flat [REDACTED] has cracking in hall, kitchen and lounge. Flat [REDACTED] has cracking in hall, kitchen, lounge and bedroom, also door to lounge is not closing. There is also cracking in a cupboard on the first floor level. Also there are signs of cracking externally. A structural report to check that the building is safe i=will be required							
Event/Task/Activity						Close	

Snip 2

SBFCINSDTL10.7 Inspection details



Plot	1	Plot 1					
Inspection type	NOTE - Inspectors notes	Date	20.03.2014	Time		Inspecting Officer	
Status	O	Hours taken		Miles Travelled			
Notes Category							
Inspection Notes							
letter in file stating that building is safe from [REDACTED] of Quattro Consult Ltd.(following complaint re cracking). E-mailed [REDACTED] spokesman for complainers asking for copy of report that complainers commissioned).							
Event/Task/Activity						Close	