

Site History Report

Effective: 25/06/2024 to 25/06/2026
Service: Roads General
Site: Nether Currie Road (7900143)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Site: Nether Currie Road (7900143)

Locality: Currie, Edinburgh, City of Edinburgh

Area: South West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type: Road Asset			Area: South West Locality	
Batch:	41259440 - Inspection Batch			Route:	Ad hoc Route		Date:	27/03/2026
42203120	Pole is loose and leaning please reset	27/03/2026	Opposite no 2	TS: Sign Pole Loose	Internal		Committed	50194610
Batch:	41259439 - Inspection Batch			Route:	Ad hoc Route		Date:	27/03/2026
42203119	Pothole	27/03/2026	Opposite no 2	RD: CW Pothole	Internal		Committed	50194609
Batch:	41256973 - Inspection Batch			Route:	Ad hoc Route		Date:	06/03/2026
42201389	Pothole near junction	06/03/2026	Opposite 37	RD: CW Pothole	Internal		Committed	50193391
Batch:	41251900 - Inspection Batch			Route:	Ad hoc Route		Date:	05/02/2026
42198562	Pothole	05/02/2026	Opposite 37 at gully	RD: CW Pothole	Internal		Committed	50191158
Batch:	41250269 - Inspection Batch			Route:	Ad hoc Route		Date:	26/01/2026
42197531	Pothole	26/01/2026	At the junction with muirwood crescent	RD: CW Pothole	Internal		Committed	50190365
Batch:	41249839 - Inspection Batch			Route:	Ad hoc Route		Date:	23/01/2026
42197410	Potholes	23/01/2026	Outside 32	RD: CW Pothole	Internal		Committed	50190254
Batch:	41246635 - Inspection Batch			Route:	Ad hoc Route		Date:	30/12/2025
42195934	Pothole	30/12/2025	Opposite 37	RD: CW Pothole	Internal		Committed	50189080
Batch:	41241515 - Inspection Batch			Route:	Ad hoc Route		Date:	17/11/2025
42193330	pothole at gully	17/11/2025	Opposite 43	RD: CW Pothole	Internal		Committed	50186999
Batch:	41241512 - Inspection Batch			Route:	Ad hoc Route		Date:	17/11/2025
42193329	Pothole	17/11/2025	outside 28	RD: CW Pothole	Internal		Committed	50186998
Batch:	41240043 - Inspection Batch			Route:	SW_CF2_NetherCurrie1		Date:	28/10/2025
42192055	.5x7m patch at kerb	28/10/2025	Outside 34	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50152446
42192060	S	28/10/2025	Outside number 19	RD: Gully Damaged/Sunken	Internal		Uncommitted	50095177
42192054	2x2m patch	28/10/2025	Adjacent to junction with thomson drive	RD: CW Cracked/Broken	Internal		Uncommitted	50126684
	.5x.5m patch							
	.5m patch around manhole							
42192062	Cracked broken cw	28/10/2025	Outside 8	RD: CW Cracked/Broken	Internal		Uncommitted	50152440
42192057	Refresh markings	28/10/2025	Entire cw including all junctions	RD: Markings Refresh	Internal		Uncommitted	50095180
42192053	Roots breaking surface	28/10/2025	Outside number 51	RD: FW Tree Root Tar	Internal		Uncommitted	50126676
42192058	Roots breaking surface	28/10/2025	At junction with Thomson grove	RD: FW Tree Root Tar	Internal		Uncommitted	50126673
42192061	Cracked broken cw	28/10/2025	Outside 17	RD: CW Cracked/Broken	Internal		Uncommitted	50152442
42192056	Cracked broken cw	28/10/2025	Outside 30	RD: CW Cracked/Broken	Internal		Uncommitted	50152444
Batch:	41233615 - Inspection Batch			Route:	Ad hoc Route		Date:	23/07/2025
42187532	Footway cracked and broken	23/07/2025	On corner of footway at 21	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50182986
Batch:	41231836 - Inspection Batch			Route:	Ad hoc Route		Date:	26/06/2025
42186199	Pothole at gully	26/06/2025	Opposite 27	RD: CW Pothole	Internal		Committed	50182054
Batch:	41231835 - Inspection Batch			Route:	Ad hoc Route		Date:	26/06/2025
42186198	Pothole at gully	26/06/2025	Opposite 37	RD: CW Pothole	Internal		Committed	50182053

Site History Report

Effective: 25/06/2024 to 25/06/2026
Service: Roads General
Site: Nether Currie Road (7900143)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street			Feature Type: Road Asset		Area: South West Locality	
Batch: 41231833 - Inspection Batch			Route: Ad hoc Route			Date: 26/06/2025		
42186196	Pothole around the manhole	26/06/2025	At junction with Thomson drive	RD: CW Pothole	Internal		Committed	50182051
Batch: 41219842 - Inspection Batch			Route: Ad hoc Route			Date: 20/02/2025		
42176534	3 potholes	20/02/2025	At junction with muir wood crescent	RD: CW Pothole	Internal		Committed	50175495
Batch: 41217052 - Inspection Batch			Route: SW_CF2_NetherCurrie1			Date: 31/01/2025		
42174561	.5x7m patch at kerb	31/01/2025	Outside 34	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42174559	2x2m patch	31/01/2025	Adjacent to junction with thomson drive	RD: CW Cracked/Broken	Internal		No Action Required	
	.5x.5m patch							
	.5m patch around manhole							
42174560	Roots breaking surface	31/01/2025	Outside number 51	RD: FW Tree Root Tar	Internal		No Action Required	

Customer Services

Enquiry No.: 2161173		Logged by: Verint CRM Connector		on: 10/06/2026 16:09	
Service: Roads General		Subject: Pavement: Damaged / Defective		Classification: Request for service	
Desc.:					
Location: The kerbs on nether currie road have been lowered in preparation for the resurfacing of the road but the pavements have been left in a dreadful state. Loads of trips, holes and edges that are dangerous. The letter I have recieved mentions only the road surface. Please can the residents be assured the pavements will also be resurfaced.		Contact:			
Plot Number: 1.00		Feature Id - Location: Whole Street		Feature Type: Road Asset	
Enquiry No.: 2138613		Logged by: Verint CRM Connector		on: 29/04/2026 11:15	
Service: Roads General		Subject: Pavement: Damaged / Defective		Classification: Request for service	
Desc.:					
Location: Works to the pavement/road way on the entirety of Nether Currie Road for the entirety of April.		Contact:			
I really hope that these works either aren't finished or are a temporary measure because as I'm sure you'll agree the quality of the repair is beyond shocking- one winter and they'll need to be done again. This is in an area where many vulnerable persons use the pavement (also near a school) and it's a complete hazard for these people - putting them at risk of falling/injury!					
Plot Number: 1.00		Feature Id - Location: Whole Street		Feature Type: Road Asset	
Enquiry No.: 2120201		Logged by: Verint CRM Connector		on: 26/03/2026 12:34	
Service: Roads General		Subject: Road: Defective / Damaged		Classification: Request for service	
Desc.:					
Location: Pothole		Contact:			
Plot Number: 1.00		Feature Id - Location: Whole Street		Feature Type: Road Asset	
Job Number: 50194609		Defect Number: 42203119			

Site History Report

Effective: 25/06/2024 to 25/06/2026
Service: Roads General
Site: Nether Currie Road (7900143)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2116144 Service: Roads General Desc.: Location: Large pot hole	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 19/03/2026 15:57 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2107382 Service: Roads General Desc.: Location: 3 x Large Pot holes near junction. Multiple holes	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 05/03/2026 19:20 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50193391	Feature Id - Location: Whole Street Defect Number: 42201389	Feature Type: Road Asset
Enquiry No.: 2092978 Service: Roads General Desc.: Location: outside 17 nethercurrie Rd. Speed Hump potholed on both leading edges.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 11/02/2026 16:45 Classification: Request for service Contact:
Enquiry No.: 2092965 Service: Roads General Desc.: Location: Pothole!	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 11/02/2026 16:31 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2089704 Service: Roads General Desc.: Location: Big Pothole	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 06/02/2026 08:49 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2088897 Service: Roads General Desc.: Location: Pothole, please note that was filled in two and a half weeks ago and has reopened.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 04/02/2026 18:15 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50191158	Feature Id - Location: Whole Street Defect Number: 42198562	Feature Type: Road Asset
Enquiry No.: 2084289 Service: Roads General Desc.: Location: Large, deep pothole on corner of Nether Currie Road and Muir Wood Crescent. The surface of Nether Currie Road is failing right across the mouth of the junction, adjacent to the recently resurfaced road in Muir Wood Crescent. This pot hole is really deep and is going to cause damage to vehicles or an injury to pedestrian if not fixed soon.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 28/01/2026 09:30 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Site History Report

Effective: 25/06/2024 to 25/06/2026
Service: Roads General
Site: Nether Currie Road (7900143)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2082430 Service: Roads General Desc.: Location: Massive pothole	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 25/01/2026 08:26 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50190365	Feature Id - Location: Whole Street Defect Number: 42197531	Feature Type: Road Asset
Enquiry No.: 2081214 Service: Roads General Desc.: Location: 4 potholes in same 10 metres of road. Nether Currie Road	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 22/01/2026 14:03 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50190254	Feature Id - Location: Whole Street Defect Number: 42197410	Feature Type: Road Asset
Enquiry No.: 2066111 Service: Roads General Desc.: Location: Large Pothole on left hand side of road, near corner as you go down the street	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 30/12/2025 09:46 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50189080	Feature Id - Location: Whole Street Defect Number: 42195934	Feature Type: Road Asset
Enquiry No.: 2050900 Service: Roads General Desc.: Location: Road surface breaking up.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 29/11/2025 12:31 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2043648 Service: Roads General Desc.: Location: Massive pothole outside 28 Nether Currie Road	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 15/11/2025 15:04 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50186998	Feature Id - Location: Whole Street Defect Number: 42193329	Feature Type: Road Asset
Enquiry No.: 2000936 Service: Roads General Desc.: Location: Significant degradation to the pavement surrounding the driveway curb stones meaning the block is protruding by 3-4 cm. I had a nasty fall there after tripping over the block which is quite far into the middle of the passageway.	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 21/08/2025 16:35 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Site History Report

Effective: 25/06/2024 to 25/06/2026
Service: Roads General
Site: Nether Currie Road (7900143)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1983407
Service: Roads General
Desc.:
Location: Name is [REDACTED] Address is [REDACTED] On a corner site. Currently telecomms works has excavated a channel to install upgraded cables. Remainder of the pavement is in an awful condition. The surface has completely disintegrated with weeds growing through loose chips. I treat them with weedkiller but it is unsafe. Telecoms has further eroded surface but no sign that repairs will go beyond simply covering their excavation channel. My number is [REDACTED]

Logged by: Verint CRM Connector
Subject: Pavement: Damaged / Defective
Contact:

on: 22/07/2025 17:10
Classification: Request for service

Plot Number: 1.00
Job Number: 50182986

Feature Id - Location: Whole Street
Defect Number: 42187532

Feature Type: Road Asset

Enquiry No.: 1829720
Service: Roads General
Desc.:
Location: I took ill last Friday 30/8/2024, resulting in an ambulance having to be called. They put me on a chair to get me in ambulance and which was going to be blue lighted to Royal Infirmary as they couldnt get a blood pressure, when taking me from the path of my house the chair wheels got stuck on the pavement outside our gate, due to the wholes in the pavement. It was vital they got me into the ambulance quickly and this hazzard delayed this. Could you please get someone to look at this.

Logged by: Verint CRM Connector
Subject: Pavement: Damaged / Defective
Contact:

on: 10/09/2024 11:04
Classification: Request for service

Plot Number: 1.00
Feature Id - Location: Whole Street

Feature Type: Road Asset

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset:	1.00	Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: South West Locality		
50175495	3 potholes (RD: CW Pothole)	At junction with muir wood crescent	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/02/2025	27/02/2025	Act. ROAD/82102821
50182051	Pothole around the manhole (RD: CW Pothole)	At junction with Thomson drive	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/06/2025	27/06/2025	Act. ROAD/82107356
50182053	Pothole at gully (RD: CW Pothole)	Opposite 37	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/06/2025	27/06/2025	Act. ROAD/82107358
50182054	Pothole at gully (RD: CW Pothole)	Opposite 27	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/06/2025	27/06/2025	Act. ROAD/82107359
50186998	Pothole (RD: CW Pothole)	outside 28	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/11/2025	17/11/2025	Act. ROAD/82110530
50186999	pothole at gully (RD: CW Pothole)	Opposite 43	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/11/2025	17/11/2025	Act. ROAD/82110531
50189080	Pothole (RD: CW Pothole)	Opposite 37	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/12/2025	31/12/2025	Act. ROAD/82112142
50190254	Potholes (RD: CW Pothole)	Outside 32	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/01/2026	26/01/2026	Act. ROAD/82113088
50190365	Pothole (RD: CW Pothole)	At the junction with muirwood crescent	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/01/2026	28/01/2026	Act. ROAD/82113180
50191158	Pothole (RD: CW Pothole)	Opposite 37 at gully	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/02/2026	05/02/2026	Act. ROAD/82113812

Site History Report

Effective: 25/06/2024 to 25/06/2026
Service: Roads General
Site: Nether Currie Road (7900143)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South West Locality	
50193391	Pothole near junction (RD: CW Pothole)	Opposite 37	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/03/2026	24/03/2026	Act. ROAD/82115685
50194609	Pothole (RD: CW Pothole)	Opposite no 2	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	27/03/2026	27/03/2026	Act. ROAD/82116638
50194610	Pole is loose and leaning please reset (TS: Sign Pole Loose)	Opposite no 2	RD: Cat 3 - 60 Day	Job Complete	27/03/2026	01/04/2026	Act. ROAD/82116639