

Site History Report

Effective: 01/03/2026 to 30/06/2026
Service: Roads General
Site: Bankhead Road (7903505)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Site: Bankhead Road (7903505)

Locality: Dalmeny, Edinburgh, City of Edinburgh

Area: North West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41266268 - Inspection Batch			Route:	Ad hoc Route		Date:	30/06/2026
42210034	2 number potholes	30/06/2026	Opposite Bankhead Farmhouse	RD: CW Pothole	Internal		Committed	50199250
Batch:	41262283 - Inspection Batch			Route:	NW_CW1_West1		Date:	05/05/2026
	No actionable defects found							
Batch:	41261229 - Inspection Batch			Route:	NW_CF1_Dalmeny1		Date:	20/04/2026
42204397	Patching required Approx 8m x 1m & 3m x 1m	20/04/2026	At Ip56	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50177709
42204389	1.5x3m patch	20/04/2026	Opposite lamppost 62	RD: CW Cracked/Broken	Internal		Uncommitted	50109042
42204398	2 potholes	20/04/2026	At Ip56	RD: FW HRA Pothole	Internal		Committed	50195568
42204400	1 pothole	20/04/2026	Outside dalmeny Kirk cafe	RD: CW Pothole	Internal		Committed	50195570
42204390	Patching required Approx 2m x 1m & 2m x 1m	20/04/2026	At entrance to dalmeny church car park	RD: CW Cracked/Broken	Internal		Uncommitted	50157397
42204394	Road markings refresh	20/04/2026	Junction of Bankhead road	RD: Markings Refresh	Internal		Uncommitted	50175815
Batch:	41260990 - Inspection Batch			Route:	Ad hoc Route		Date:	15/04/2026
42204186	1 number pothole	15/04/2026	At entrance to Bankhead Steading	RD: CW Pothole	Internal		Committed	50195399
Batch:	41258480 - Inspection Batch			Route:	Ad hoc Route		Date:	18/03/2026
42202378	Pothole	18/03/2026	Just before the giveaway sign at junction	RD: CW Pothole	Internal		Committed	50194113
Batch:	41257547 - Inspection Batch			Route:	Ad hoc Route		Date:	10/03/2026
42201752	Various areas in need of HRA overlay	10/03/2026	At the entrance to church parking	RD: CW Pothole	Internal		Committed	50193665
Batch:	41257546 - Inspection Batch			Route:	Ad hoc Route		Date:	10/03/2026
42201751	Various areas requiring HRA overlay	10/03/2026	At speed bump	RD: CW Pothole	Internal		Committed	50193664
Batch:	41257545 - Inspection Batch			Route:	Ad hoc Route		Date:	10/03/2026
42201750	Pothole	10/03/2026	At the entrance to new garden house	RD: CW Pothole	Internal		Committed	50193663

Customer Services

Enquiry No.: 2171267	Logged by: Verint CRM Connector	on: 29/06/2026 17:34
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Southbound carriage next to kerb, between turnoff from B924 and Bankhead Steading	Contact:	
Enquiry No.: 2170814	Logged by: Verint CRM Connector	on: 29/06/2026 08:49
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: There is a very large pot hole which has damaged my car. It is on the left by the kerb when travelling south along Bankhead Road.	Contact:	

Plot Number: 1.00

Feature Id - Location: Whole Street

Feature Type: Road Asset

Site History Report

Effective: 01/03/2026 to 30/06/2026
Service: Roads General
Site: Bankhead Road (7903505)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2169963	Logged by: Verint CRM Connector	on: 26/06/2026 18:39
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Sunken drains and pot holes	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50199250	Defect Number: 42210034	
Enquiry No.: 2141147	Logged by: Verint CRM Connector	on: 03/05/2026 18:06
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Failure of pavement structure in north bound near side wheel location (canalisation) circa 10m in length - extensive failure of road structure. 2nd area reported.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2141146	Logged by: Verint CRM Connector	on: 03/05/2026 18:04
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Failure of pavement structure in north bound near side wheel location (canalisation) circa 10m in length - extensive failure of road structure	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2130183	Logged by: Verint CRM Connector	on: 14/04/2026 07:37
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: I hit this pothole just near the entrance to the farm on Bankhead Road heading towards Hawes Brae. The near side tyre burst immediately [REDACTED].	Contact:	
I am looking to claim the cost of a new tyre which is £[REDACTED].		
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50195399	Defect Number: 42204186	
Enquiry No.: 2126587	Logged by: Verint CRM Connector	on: 07/04/2026 13:41
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: entire junction is scattered with pot holes and sunken	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2119708	Logged by: Verint CRM Connector	on: 25/03/2026 15:03
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: The pot hole is located about a cars length into the road marked. It is quite deep and unsuspecting.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Site History Report

Effective: 01/03/2026 to 30/06/2026
Service: Roads General
Site: Bankhead Road (7903505)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2114812 Service: Roads General Desc.: Location: Not been repaired in years multiply pot holes and one massive hole	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 17/03/2026 21:57 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2113200 Service: Roads General Desc.: Location: Potholes on both sides of the speed bump	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 16/03/2026 02:07 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2110778 Service: Roads General Desc.: Location: Road structure failed, surface completely broken with deep pothole.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 11/03/2026 17:53 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2110771 Service: Roads General Desc.: Location: Road structure completely failed. Location o/s entrance to church hall car park.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 11/03/2026 17:49 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2110463 Service: Roads General Desc.: Location: Pot hole over bumps	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 11/03/2026 11:41 Classification: Request for service Contact:
Enquiry No.: 2109255 Service: Roads General Desc.: Location: Shocking potholes	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 09/03/2026 14:49 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50193664	Feature Id - Location: Whole Street Defect Number: 42201751	Feature Type: Road Asset
Enquiry No.: 2108088 Service: Roads General Desc.: Location: At least 3 large potholes heading south up Bankhead Road towards Dalmeny Main Street. Near brow of hill.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 06/03/2026 21:45 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50193665	Feature Id - Location: Whole Street Defect Number: 42201752	Feature Type: Road Asset

Site History Report

Effective: 01/03/2026 to 30/06/2026
Service: Roads General
Site: Bankhead Road (7903505)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2108084	Logged by: Verint CRM Connector	on: 06/03/2026 21:43
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole northbound toward Hawes Brae	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50193663	Defect Number: 42201750	
Enquiry No.: 2107000	Logged by: Verint CRM Connector	on: 05/03/2026 11:05
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Bus Stop at bankhead road. Couple feet wide	Contact:	
Enquiry No.: 2106602	Logged by: Verint CRM Connector	on: 04/03/2026 17:42
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: You claim to have fixed these potholes surrounding the speed bump and effectively putting it well above prescribed size, but they have not been touched.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2104566	Logged by: Verint CRM Connector	on: 01/03/2026 17:28
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Potholes along this road	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2104563	Logged by: Verint CRM Connector	on: 01/03/2026 17:23
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large potholes. A car nearly took the side of its car off. Serious damage going to happen to a vehicle in this road	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2104455	Logged by: Verint CRM Connector	on: 01/03/2026 14:15
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Giant pothole. A car is going get stuck in it and cause serious damage to their car.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality	
50187187	All Markings refresh (RD: Markings Refresh)	At the junction of hawes brae and Bankhead road	RD: Cat 4 - Programmed	Job Complete	19/11/2025	28/04/2026	Act. ROAD/82117674
50191922	Pothole (RD: CW Pothole)	At the 20 mph sign	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2026	03/03/2026	Act. ROAD/82114454

Site History Report

Effective: 01/03/2026 to 30/06/2026
Service: Roads General
Site: Bankhead Road (7903505)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: North West Locality		
50191923	Pothole (RD: CW Pothole)	Opposite gospatric gardens junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/02/2026	03/03/2026	Act. ROAD/82114455
50192957	Outside Bankhead farm house at bend south bound (RD: CW Pothole)	Pothole	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/02/2026	03/03/2026	Act. ROAD/82115360
50193663	Pothole (RD: CW Pothole)	At the entrance to new garden house	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/03/2026	18/03/2026	Act. ROAD/82115921
50193664	Various areas requiring HRA overlay (RD: CW Pothole)	At speed bump	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/03/2026	18/03/2026	Act. ROAD/82115922
50193665	Various areas in need of HRA overlay (RD: CW Pothole)	At the entrance to church parking	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/03/2026	18/03/2026	Act. ROAD/82115923
50194113	Pothole (RD: CW Pothole)	Just before the giveaway sign at junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/03/2026	25/03/2026	Act. ROAD/82116267
50195399	1 number pothole (RD: CW Pothole)	At entrance to Bankhead Steading	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/04/2026	16/04/2026	Act. ROAD/82117269
50195568	2 potholes (RD: FW HRA Pothole)	At lp56	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/04/2026	21/04/2026	Act. ROAD/82117409
50195570	1 pothole (RD: CW Pothole)	Outside dalmeny Kirk cafe	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/04/2026	21/04/2026	Act. ROAD/82117411
50199250	2 number potholes (RD: CW Pothole)	Opposite Bankhead Farmhouse	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/06/2026	01/07/2026	Act. ROAD/82120297