

Site History Report

Effective: 27/07/2021 to 27/07/2026

Display Action Officer: No

Asset Number: 1.00 to 9.00

Site: Kirk Brae (7902516)

Site: Kirk Brae (7902516)

Locality: Liberton, Edinburgh, City of Edinburgh

Area: South East Locality

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 16 - From Liberton Brae to Kirkgate		Feature Type: Road Asset		Area: South East Locality	
50085822	Rocking small slab please reset and uplift loose tar (RD: FW Slabs Rocking)	At Kirkgate	RD: Cat 3 - 60 Day	Job Complete	24/06/2021	10/08/2021	Act. ROAD/82051256
50113921	Cw breaking up hot overlays required (RD: CW Cracked/Broken)	Kirk brae city bound at 80	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/05/2022	31/05/2022	Act. ROAD/82064262
50123206	Cw pothole marked on site (RD: CW Pothole)	Liberton brae 76	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	28/11/2022	29/11/2022	Act. ROAD/82068946
50123208	Cw pothole marked on site (RD: CW Pothole)	Kirk brae 64 as per map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/11/2022	29/11/2022	Act. ROAD/82068948
50123478	Cw pothole x2 marked on site please clear debris and make safe. Road: Defective / Damaged (Enquiry 1469775) (RD: CW Pothole)	Kirk Brae junction with Wolrige Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/12/2022	04/12/2022	Act. ROAD/82069091
50125283	Cw pothole marked on site (RD: CW Pothole)	Kirk Brae 76	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	04/01/2023	05/01/2023	Act. ROAD/82070208
50130469	Cwx1 Road: Defective / Damaged (Enquiry 1515338) (RD: CW Pothole)	At the junction with Kirk park	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/02/2023	01/03/2023	Act. ROAD/82073460
50134876	Cw x2 potholes Road: Defective / Damaged (Enquiry 1541427) (RD: CW Pothole)	Outside of numbers 74 and 80	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/04/2023	26/04/2023	Act. ROAD/82076250
50134877	Cw x1 pothole (RD: CW Pothole)	Outside of number 71	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/04/2023	26/04/2023	Act. ROAD/82076251
50135736	Remove damaged/dent sign pole make safe footway and place signs at Bankhead depot stores. (RD: Unlit Sign Damaged/Missing)	Opposite house no 4	RD: Cat 2 - 5 Day	Job Complete	09/05/2023	12/05/2023	Act. ROAD/82076905
50136487	Remove Large Advanced Directional Sign & Sign Poles from South footway approximately 50yds East of junction with Liberton Brae, Make Safe Footway , skip sign and poles. (RD: Unlit Sign Damaged/Missing)	On South footway approximately 50yds East of junction with Liberton Brae	RD: Cat 2 - 5 Day	Job Complete	22/05/2023	23/05/2023	Act. ROAD/82077417
50141565	1 carriageway pothole at manhole (RD: CW Pothole)	At junction with wolrige road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/08/2023	28/08/2023	Act. ROAD/82080231
50143261	Signs: Defective / Damaged - Damaged Sign Pole (Enquiry 31602878) (RD: SFP Damaged Signage)	Please install new pole with 2 existing signs which are being kept at stores. Location- Outside house no 2	RD: Cat 3 - 60 Day	Job Complete	27/09/2023	18/10/2023	Act. ROAD/82081073

Site History Report

Effective: 27/07/2021 to 27/07/2026
Display Action Officer: No

Asset Number: 1.00 to 9.00
Site: Kirk Brae (7902516)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 16 - From Liberton Brae to Kirkgate		Feature Type: Road Asset		Area: South East Locality	
50147422	Cw x1 pothole (RD: CW Pothole)	Outside of number 74	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/12/2023	08/12/2023	Act. ROAD/82083650
50147914	1no pothole (RD: CW Pothole)	At wolrige rd	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/12/2023	15/12/2023	Act. ROAD/82083950
50152005	Cw x2 potholes Road: Defective / Damaged (Enquiry 1690968) (RD: CW Pothole)	Outside of 62	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/02/2024	06/02/2024	Act. ROAD/82086704
50152361	Cw x1 pothole Road: Defective / Damaged (Enquiry 1693499) (RD: CW Pothole)	Outside of 83	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2024	07/02/2024	Act. ROAD/82086963
50152477	Cw x3 potholes Road: Defective / Damaged (Enquiry 1695294) (RD: CW Pothole)	Outside of 71 southbound bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/02/2024	09/02/2024	Act. ROAD/82087051
50152478	Cw x2 potholes (RD: CW Pothole)	At the junction with Wolrige road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/02/2024	09/02/2024	Act. ROAD/82087052
50152771	New signs pole 400mm from kirb line, approximately 45m before junction with Liberton Brae New signs placed as per the installation details. (RD: Unlit Sign Damaged/Missing)	Place new signs pole on south footway 400mm from kirb line approximately 45m before junction with Liberton Brae	RD: Cat 3 - 60 Day	Job Complete	13/02/2024	27/02/2024	Act. ROAD/82087268
50156147	Cw x2 potholes Road: Defective / Damaged (Enquiry 1718767) (RD: CW Pothole)	Outside of 73 (Caledon House)	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	18/03/2024	19/03/2024	Act. ROAD/82089608
50158605	Cw x 3 potholes (RD: CW Pothole)	Outside of 76	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/04/2024	21/04/2024	Act. ROAD/82091454
50159099	Cw x 1 pothole Road: Defective / Damaged (Enquiry 1741899) (RD: FW Grano Pothole)	Outside of 71	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/04/2024	03/06/2024	Act. ROAD/82091752
50161044	Cw x1 pothole Road: Defective / Damaged (Enquiry 1762760) (RD: CW Pothole)	At the junction with Wolrige Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/05/2024	28/05/2024	Act. ROAD/82092896
50166941	Traffic Sign:Defective/Damaged - What type of sign is it? Road sign problem, type unlit (Enquiry 1792743) (RD: Unlit Sign Damaged/Missing)	Please install new city centre sign onto existing pole with no left turn. Mounting height 2300mm. Pole located outside no.2 just prior to traffic lights. Sign ready for collection from stores.	RD: Cat 3 - 60 Day	Job Complete	24/09/2024	30/09/2024	Act. ROAD/82096497
50176335	No 1 pothole (RD: CW Pothole)	Opposite number 12	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/03/2025	05/03/2025	Act. ROAD/82103537
50176336	No1 pothole (RD: CW Pothole)	In yellow box at firestation	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/03/2025	05/03/2025	Act. ROAD/82103538
50177090	No 1 pothole) (RD: CW Pothole)	At junction opposite blackford glen road heading up Kirk brae	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/03/2025	18/03/2025	Act. ROAD/82104103
50183232	1no Fw pothole (RD: FW HRA Pothole)	At junction with double hedges road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/07/2025	31/07/2025	Act. ROAD/82108120

Site History Report

Effective: 27/07/2021 to 27/07/2026

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Kirk Brae (7902516)

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 16 - From Liberton Brae to Kirkgate		Feature Type: Road Asset		Area: South East Locality	
50187818	Turn city centre sign to face oncoming vehicles (RD: Unlit Sign Damaged/Missing)	On south footway at side of dental practice	RD: Cat 2 - 5 Day	Job Complete	01/12/2025	02/12/2025	Act. ROAD/82111130
50197891	Disabled Bay new - install as per drawing (NSL: Markings New Defect)	16, KIRK BRAE, EDINBURGH, EH16 6HH	Parking Operations	NSL Job Complete	03/06/2026	17/06/2026	Act. NSL/40206
Asset: 2.00		Asset - Locn.: Ward 16 - Branch off east side at No.73-75		Feature Type: Road Asset		Area: South East Locality	
50090342	Cw potholes marked on site x5 (RD: CW Pothole)	Kirk brae city bound past wolrige rd Tour or Britain cycle route	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/08/2021	25/08/2021	Act. ROAD/82053602