

Site History Report

Page 1 of 5

Effective: 06/04/2025 to 02/07/2026
Service: Roads General
Site: Clermiston Avenue (7900369)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Site: Clermiston Avenue (7900369)

Locality: Barnton, Edinburgh, City of Edinburgh

Area: North West Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	North West Locality
Batch:	41266360 - Inspection Batch			Route:	Ad hoc Route		Date:	01/07/2026
42210140	1 number pothole	01/07/2026	Outside number 23	RD: CW Pothole	Internal		Committed	50199328
Batch:	41266199 - Inspection Batch			Route:	Ad hoc Route		Date:	29/06/2026
42209997	Cracked and broken footpath needs resurfaced	29/06/2026	Outside number 36	RD: FW HRA Cracked/Broken	Internal		Uncommitted	50199214
Batch:	41262921 - Inspection Batch			Route:	Ad hoc Route		Date:	12/05/2026
42206009	1 number pothole	12/05/2026	Outside number 10	RD: CW Pothole	Internal		Committed	50196613
Batch:	41261476 - Inspection Batch			Route:	Ad hoc Route		Date:	22/04/2026
42204614	1 number pothole	22/04/2026	Outside number 13	RD: CW Pothole	Internal		Committed	50195716
Batch:	41261474 - Inspection Batch			Route:	Ad hoc Route		Date:	22/04/2026
42204612	2 number potholes	22/04/2026	outside number 43	RD: CW Pothole	Internal		Committed	50195714
Batch:	41260872 - Inspection Batch			Route:	Ad hoc Route		Date:	14/04/2026
42204150	1 number pothole	14/04/2026	Outside number 29	RD: CW Pothole	Internal		Committed	50195359
Batch:	41255869 - Inspection Batch			Route:	Ad hoc Route		Date:	27/02/2026
42200719	1no pothole	27/02/2026	Outside 37	RD: CW Pothole	Internal		Committed	50192894
Batch:	41247763 - Inspection Batch			Route:	Ad hoc Route		Date:	11/01/2026
42196306	1 pothole	11/01/2026	Outside 35	RD: CW Pothole	Internal		Committed	50189420
Batch:	41235793 - Inspection Batch			Route:	Ad hoc Route		Date:	01/09/2025
42189359	Pothole on carriageway	01/09/2025	Outside 39	RD: CW Pothole	Internal		Committed	50184338
Batch:	41235289 - Inspection Batch			Route:	NW_CF2_ClermistonWest1		Date:	22/08/2025
42188910	Pavement: Damaged / Defective (Enquiry 719502) Dig out damaged footway & resurface in HRA	22/08/2025	Footway breaking up leaving uneven surface between no 36 & 38	RD: FW HRA Cracked/Broken	Internal		Action Required	
42188909	1 cw pothole	22/08/2025	Outside 41	RD: CW Pothole	Internal		Committed	50183968
Batch:	41230191 - Inspection Batch			Route:	Ad hoc Route		Date:	05/06/2025
42185092	Pothole on carriageway	05/06/2025	Outside 25,29	RD: CW Pothole	Internal		Committed	50180998

Customer Services

Enquiry No.: 2171760

Service: Roads General

Desc.: Problem: Overgrown.
Location:Verge / Grass area .
Type:Foliage / Bush

Location: This is the tree outside my house. It is overhangin into our garden and blocking light. **Contact:**

Logged by: Verint CRM Connector

Subject: Trees & Foliage: Defect

on: 30/06/2026 14:44

Classification: Request for service

Site History Report

Page 2 of 5

Effective: 06/04/2025 to 02/07/2026
Service: Roads General
Site: Clermiston Avenue (7900369)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2171688	Logged by: Verint CRM Connector	on: 30/06/2026 13:22
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: ref number 102000417440	Contact:	
As i had fallen before i reported the pavement i wasnt able to give u the exact number. Its between 36cm and 38 clermiston ave.		
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2170457	Logged by: Verint CRM Connector	on: 28/06/2026 11:31
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Customer Emergency
Desc.:		
Location: As i fell and hurt my foot i cannot give u the exact number but i was walking down the avenue with my grandson and fell. It is the pavement beside the old age pensioner cottages.the slabs are not missing but very uneven	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2144187	Logged by: [REDACTED]	on: 08/05/2026 13:24
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: Customer says potholes over the entire street, really big one near number 10. Also says the speed bumps on the street are breaking up and causing problems for car tires	Contact:	
Location: Clermiston avenue		
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50196613	Defect Number: 42206009	
Enquiry No.: 2132966	Logged by: Verint CRM Connector	on: 18/04/2026 21:52
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Potholes on road	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50195716	Defect Number: 42204614	
Enquiry No.: 2132965	Logged by: Verint CRM Connector	on: 18/04/2026 21:52
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: 2 large potholes on road	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50195714	Defect Number: 42204612	
Enquiry No.: 2129173	Logged by: Verint CRM Connector	on: 11/04/2026 21:57
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Large pothole in the road in-between number 29 and 31 Clermiston Avenue.	Contact:	
As cars park on the opposite side of the road then cars are consistently having to go into the hole to get down the road.		
More and more Stones breaking off and laying at the side of the road which are also being driven over and flicking onto the pavement. Being a busy road during school pick up and drop off times this may become dangerous		
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50195359	Defect Number: 42204150	

Site History Report

Page 3 of 5

Effective: 06/04/2025 to 02/07/2026
Service: Roads General
Site: Clermiston Avenue (7900369)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2122639	Logged by: Verint CRM Connector	on: 31/03/2026 07:07
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2122638	Logged by: Verint CRM Connector	on: 31/03/2026 07:06
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole either side of drain So 2	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2122637	Logged by: Verint CRM Connector	on: 31/03/2026 07:05
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Spead bump is to high You can see by the deep gouges from cars scraping over it in photo	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2122635	Logged by: Verint CRM Connector	on: 31/03/2026 07:03
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Two potholes	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2120923	Logged by: Verint CRM Connector	on: 27/03/2026 14:13
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Two potholes	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2098727	Logged by: Verint CRM Connector	on: 19/02/2026 18:36
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Speedbump crumbling	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50192894	Defect Number: 42200719	
Enquiry No.: 2057690	Logged by: Verint CRM Connector	on: 12/12/2025 16:48
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole in road	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Site History Report

Effective: 06/04/2025 to 02/07/2026
Service: Roads General
Site: Clermiston Avenue (7900369)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2006627 **Logged by:** Verint CRM Connector **on:** 31/08/2025 17:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Broken speed hump
 It is to high it has always been to high
 Cars scrape across it please see photos

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50184338 **Defect Number:** 42189359

Enquiry No.: 1964451 **Logged by:** Verint CRM Connector **on:** 16/06/2025 15:38
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Overgrown.
 Location:Verge / Grass area .
 Type:Foliage / Bush
Location: Tree outside 17 Clermiston Avenue, overhanging garden and also obscuring street light.

Contact:

Enquiry No.: 1959618 **Logged by:** Verint CRM Connector **on:** 06/06/2025 14:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Job number 101003135071 shown as completed 6/6/25. Enterprise truck arrived today 11.30. Man filled hole with tar and hit down with back of shovel. Then shovelled up tar not used and threw back in flatbed of truck. Drove away. No use of proper equipment to flatten tar and secure. Did not sweep up any loose tar spread on road from hole to truck. Likely hole will need done again soon when it all breaks up. Job well done !!

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1959322 **Logged by:** Verint CRM Connector **on:** 05/06/2025 20:37
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole that was previously filled but has broken down again. It is right outside my driveway at 29 Clermiston Avenue and is causing issues as when I reverse into my drive the front of my car scrapes the edge of it. There is also lots of loose stones now due to the breakdown of previously filling that are risking being thrown up olamd chipping my car when vans drive past.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1958928 **Logged by:** Verint CRM Connector **on:** 05/06/2025 11:23
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Area of road against the kerb broken and loose rubble . Hole fills up with water when raining and also it's the road access to house run in for number 25.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50180998 **Defect Number:** 42185092

Site History Report

Effective: 06/04/2025 to 02/07/2026
Service: Roads General
Site: Clermiston Avenue (7900369)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: North West Locality	
50135773	Gully: Blocked/Needs Clean - What is the problem with the gully : blocked. What surface is the gully on : road (Enquiry 1548162) gully chocked (Gully: Blocked / Flooding)	Outside 52	RG: Gully - Standard Priority	Job Complete	10/05/2023	30/03/2026 Act.	RDGC14/82005493
50180998	Pothole on carriageway (RD: CW Pothole)	Outside 25,29	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/06/2025	06/06/2025 Act.	ROAD/82106710
50183968	1 cw pothole (RD: CW Pothole)	Outside 41	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/08/2025	25/08/2025 Act.	ROAD/82108549
50184338	Pothole on carriageway (RD: CW Pothole)	Outside 39	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/09/2025	02/09/2025 Act.	ROAD/82108765
50189420	1 pothole (RD: CW Pothole)	Outside 35	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/01/2026	12/01/2026 Act.	ROAD/82112426
50192894	1no pothole (RD: CW Pothole)	Outside 37	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/02/2026	05/03/2026 Act.	ROAD/82115301
50195359	1 number pothole (RD: CW Pothole)	Outside number 29	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/04/2026	15/04/2026 Act.	ROAD/82117239
50195714	2 number potholes (RD: CW Pothole)	outside number 43	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/04/2026	23/04/2026 Act.	ROAD/82117529
50195716	1 number pothole (RD: CW Pothole)	Outside number 13	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/04/2026	23/04/2026 Act.	ROAD/82117531
50196613	1 number pothole (RD: CW Pothole)	Outside number 10	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/05/2026	12/05/2026 Act.	ROAD/82118208
50199328	1 number pothole (RD: CW Pothole)	Outside number 23	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/07/2026	02/07/2026 Act.	ROAD/82120364