

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Site: Morningside Road (7903068)

Locality: Morningside, Edinburgh, City of Edinburgh

Area: South East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road		Feature Type: Road Asset		Area: South East Locality		
Batch:	41267388 - Inspection Batch			Route:	Ad hoc Route		Date:	15/07/2026
42211165	Sunken cut off a slab	15/07/2026	Outside no 2	RD: FW Slabs Rocking	Internal		No Action Required	
Batch:	41267254 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	14/07/2026
42211131	1no Cw pothole	14/07/2026	Opposite Elim church	RD: CW Pothole	Internal		Committed	50199928
Batch:	41266764 - Inspection Batch			Route:	Ad hoc Route		Date:	08/07/2026
42210736	Broken slab around gas Toby	08/07/2026	Outside no 388 .	RD: FW Slabs Broken/Missing	Internal		No Action Required	
Batch:	41265908 - Inspection Batch			Route:	Ad hoc Route		Date:	23/06/2026
42209573	No 1 pothole	23/06/2026	At Morningside place bus stop outside morningside medical practice	RD: CW Pothole	Internal		Committed	50198931
Batch:	41265205 - Inspection Batch			Route:	Ad hoc Route		Date:	09/06/2026
42208597	No 2 potholes	09/06/2026	Outside. Costa coffee at crossing point	RD: CW Pothole	Internal		Committed	50198250
Batch:	41265033 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	08/06/2026
	No actionable defects found							
Batch:	41264844 - Inspection Batch			Route:	SfP_SouthEast		Date:	04/06/2026
	No actionable defects found							
Batch:	41263475 - Inspection Batch			Route:	SfP_SouthEast		Date:	19/05/2026
	No actionable defects found							
Batch:	41263425 - Inspection Batch			Route:	Ad hoc Route		Date:	19/05/2026
42206631	No 1 pothole around iron work	19/05/2026	Outside Eric Liddell heading south	RD: CW Pothole	Internal		Committed	50197040
Batch:	41262826 - Inspection Batch			Route:	South Mobile Inspection Route		Date:	11/05/2026
	No actionable defects found							
Batch:	41262271 - Inspection Batch			Route:	Ad hoc Route		Date:	05/05/2026
42205507	No 1 pothole	05/05/2026	At crossing point outside gratitude Thai lounge bar opposite no 90	RD: CW Pothole	Internal		Committed	50196279
Batch:	41262148 - Inspection Batch			Route:	Ad hoc Route		Date:	01/05/2026
42205342	Cw x1 pothole	01/05/2026	Pedestrian crossing outside of Techfixd , please uplift loose debris	RD: CW Pothole	Internal		Committed	50196177
Batch:	41261674 - Inspection Batch			Route:	SfP_SouthEast		Date:	23/04/2026
	No actionable defects found							
Batch:	41261565 - Inspection Batch			Route:	SE_Morningside_3Month		Date:	23/04/2026
42204723	5no broken 750 x 600 pcc slabs 3no broken 600 x 600 pcc slabs 1no broken 450 x 600 pcc slab	23/04/2026	Outside no33 opposite mail boxes etc	RD: FW Slabs Broken/Missing	Internal		Committed	50195793
42204738	2no cw potholes	23/04/2026	Between studded area of pedestrian crossing outside Bodysmart physios	RD: CW Pothole	Internal		Committed	50195802
42204696	Yellow box road markings need refreshed	23/04/2026	At junction with Falcon road west	RD: Markings Refresh	Internal		No Action Required	

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road		Feature Type: Road Asset		Area: South East Locality		
Batch: 41261565 - Inspection Batch		Route: SE_Morningside_3Month				Date: 23/04/2026		
42204744	1no rocking cut pcc slab	23/04/2026	Outside the Gurkha takeaway	RD: FW Slabs Rocking	Internal		Committed	50195804
42204725	4no broken 900 x 600 pcc slabs 1no broken 750 x 600 pcc slab 3no rocking pcc slabs	23/04/2026	Outside no31	RD: FW Slabs Rocking	Internal		No Action Required	
42204737	2no cw potholes	23/04/2026	At junction with church hill place Outside	RD: CW Pothole	Internal		Committed	50195801
42204682	1no broken 350 x 450 pcc slab Remove and infill with cold tar	23/04/2026	Outside no 263 vets / building site	RD: FW Slabs Broken/Missing	Internal		Committed	50195778
42204675	Faded yellow box grid needs refreshed	23/04/2026	Morningside Road	RD: Markings Refresh	Internal		No Action Required	
42204732	2 x 4 patching required at bus stop	23/04/2026	Bus stop outside of 66	RD: CW Cracked/Broken	Internal		No Action Required	
42204712	Cw breaking up approximately 20m x 5m	23/04/2026	Outside no51 at Orenda shop near junction with churchill place	RD: CW Cracked/Broken	Internal		No Action Required	
42204689	1no yellow box road markings need refreshed	23/04/2026	At junction with Morningside park	RD: Markings Refresh	Internal		No Action Required	
42204704	low grano area at kerb / make safe	23/04/2026	Outside home hardware shop	RD: FW HRA Pothole	Internal		Committed	50195788
42204768	Uneven slabs	23/04/2026	Outside no 368	RD: FW Slabs Rocking	Internal		No Action Required	
42204684	Yellow box road markings need refreshed	23/04/2026	At junction with Jordan lane / millar cres	RD: Markings Refresh	Internal		No Action Required	
42204698	2 Whin kerb needs lifted and grano patch taken out and re slabbed 6 /7 roughly as cuts will be needed 450x 600 grey slabs	23/04/2026	Outside home hardware 169 Morningside Road.	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42204683	1no sunken water Toby also causing surrounding broken / sunken slabs	23/04/2026	Morningside road on Fw outside no261 west end vets	RU: Utility Apparatus	Internal		Uncommitted	50195779
42204731	low grano area at utility box / make safe	23/04/2026	Outside Luca ice cream	RD: FW HRA Pothole	Internal		Committed	50195798
42204727	Broken grano surrounding double manhole	23/04/2026	Outside Eric Liddell community centre	RD: FW Grano Cracked/Broken	Internal		Committed	50195795
42204710	Patch required at bus stop approx 3x10m	23/04/2026	Outside 59	RD: CW Cracked/Broken	Internal		No Action Required	
42204748	Grano open joint at Gas Toby	23/04/2026	Outside no160	RD: FW Grano Open Joint	Internal		Committed	50195806
42204766	1 broken 600x 750 slab and loose 200x200 slab	23/04/2026	Outside Sainsbury's door / near atm machine	RD: FW Slabs Rocking	Internal		No Action Required	
42204734	Cw patch approx 6m x 2m	23/04/2026	At junction with church hill place	RD: CW Cracked/Broken	Internal		No Action Required	
42204709	1no missing 6 x 12 whin kerb	23/04/2026	Next to parking machine no12246	RD: FW Kerbs Damaged/Missing	Internal		No Action Required	
42204745	1 m x1 m patch required for recurring pothole)	23/04/2026	Morningside Road opposite no 93 Bethany shop in bustop	RD: CW Cracked/Broken	Internal		No Action Required	
42204686	5no broken 450 x 600 pcc slabs	23/04/2026	At junction with Jordan lane	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42204765	3no rocking / sunken 900 x 600 pcc slabs	23/04/2026	At junction with millar cres outside Marie curie charity shop	RD: FW Slabs Rocking	Internal		Committed	50195811
42204717	Stop line and bicycle road markings need refreshed	23/04/2026	At approach to traffic lights north bound at junction with Churchill place	RD: Markings Refresh	Internal		No Action Required	
42204714	1no Cw patch approx 2m x 2m	23/04/2026	At junction with church hill place pedestrian crossing	RD: CW Cracked/Broken	Internal		No Action Required	
42204678	12 broken 600x450 pcc slabs , please uplift and replace with new	23/04/2026	Outside West End Veterinary Clinic	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42204692	Cracked broken cw approx 0.5m x 0.5m	23/04/2026	Outside no217 cafe blush	RD: CW Cracked/Broken	Internal		No Action Required	

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road			Feature Type: Road Asset		Area: South East Locality	
Batch: 41261565 - Inspection Batch		Route: SE_Morningside_3Month			Date: 23/04/2026			
42204707	Yellow box road markings need refreshed	23/04/2026	At junction with falcon avenue	RD: Markings Refresh	Internal		No Action Required	
42204708	1no yellow box road markings need refreshed	23/04/2026	At junction with Newbattle terrace	RD: Markings Refresh	Internal		No Action Required	
42204688	1no raised utility box on tactile slabs at pedestrian crossing	23/04/2026	Morningside road outside no235 at junction with canaan lane	RU: Utility Apparatus	Internal		Uncommitted	50195782
Batch: 41261310 - Inspection Batch		Route: Ad hoc Route			Date: 21/04/2026			
42204473	No 2 potholes	21/04/2026	At junction of falcon avenue and morningside road at crossing point	RD: CW Pothole	Internal		Committed	50195622
Batch: 41261162 - Inspection Batch		Route: Ad hoc Route			Date: 17/04/2026			
42204349	No 1 pothole	17/04/2026	Outside no 271 heading to comiston road in red cyclist box opposite the bank of Scotland	RD: CW Pothole	Internal		Committed	50195531
Batch: 41260080 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 01/04/2026			
Batch: 41259728 - Inspection Batch No actionable defects found		Route: Mobile Inspection Strategic			Date: 30/03/2026			
Batch: 41259344 - Inspection Batch		Route: Ad hoc Route			Date: 26/03/2026			
42202999	No 2 potholes	26/03/2026	Outside no 15 the Eric Liddell centre at crossing point	RD: CW Pothole	Internal		Committed	50194552
Batch: 41258963 - Inspection Batch No actionable defects found		Route: Mobile Inspection Strategic			Date: 23/03/2026			
Batch: 41258598 - Inspection Batch		Route: Ad hoc Route			Date: 19/03/2026			
42202448	Gully blocked not running 100% when raining flooding footpath	19/03/2026	outside 386 Morningside	Gully: Blocked - HP Jet Req'd	Internal		Committed	50194169
Batch: 41258528 - Inspection Batch No actionable defects found		Route: SfP_SouthEast			Date: 18/03/2026			
Batch: 41258183 - Inspection Batch No actionable defects found		Route: Mobile Inspection Strategic			Date: 16/03/2026			
Batch: 41257807 - Inspection Batch		Route: Ad hoc Route			Date: 12/03/2026			
42201858	No 1 pothole	12/03/2026	Outside no 19!	RD: CW Pothole	Internal		Committed	50193766
Batch: 41257358 - Inspection Batch		Route: Mobile Inspection Strategic			Date: 09/03/2026			
42201575	1no pothole	09/03/2026	At the bus stop opposite no408	RD: CW Pothole	Internal		Committed	50193535
42201578	1no pothole	09/03/2026	Opposite no420	RD: CW Pothole	Internal		Committed	50193538
Batch: 41256517 - Inspection Batch		Route: Ad hoc Route			Date: 03/03/2026			
42201016	No 1 pothole	03/03/2026	At bustop at no 2 morningside medical practice	RD: CW Pothole	Internal		Committed	50193129

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road		Feature Type: Road Asset		Area: South East Locality		
Batch: 41256301 - Inspection Batch			Route: South Mobile Inspection Route					Date: 02/03/2026
No actionable defects found								
Batch: 41256194 - Inspection Batch			Route: Mobile Inspection Strategic					Date: 02/03/2026
No actionable defects found								
Batch: 41254930 - Inspection Batch			Route: Mobile Inspection Strategic					Date: 23/02/2026
No actionable defects found								
Batch: 41254499 - Inspection Batch			Route: Ad hoc Route					Date: 20/02/2026
42200109	Rocking 900x600 slab at entrance to shop	20/02/2026	Outside pop cafe	RD: FW Slabs Rocking	Internal		Committed	50192442
Batch: 41254458 - Inspection Batch			Route: Ad hoc Route					Date: 20/02/2026
42200064	No 2 potholes	20/02/2026	Outside no 86 masti Indian street food in yellow grid box	RD: CW Pothole	Internal		Committed	50192398
Batch: 41253645 - Inspection Batch			Route: Mobile Inspection Strategic					Date: 15/02/2026
No actionable defects found								
Batch: 41252973 - Inspection Batch			Route: SfP_SouthEast					Date: 12/02/2026
No actionable defects found								
Batch: 41252417 - Inspection Batch			Route: Mobile Inspection Strategic					Date: 08/02/2026
42198786	1no pothole	08/02/2026	At the bus stop outside no59	RD: CW Pothole	Internal		Committed	50191336
Batch: 41251486 - Inspection Batch			Route: Mobile Inspection Strategic					Date: 01/02/2026
No actionable defects found								
Batch: 41250678 - Inspection Batch			Route: South Mobile Inspection Route					Date: 27/01/2026
No actionable defects found								
Batch: 41249958 - Inspection Batch			Route: Mobile Inspection Strategic					Date: 25/01/2026
No actionable defects found								
Batch: 41248989 - Inspection Batch			Route: SE_Morningside_3Month					Date: 19/01/2026
42196913	Yellow box road markings need refreshed	19/01/2026	At junction with falcon avenue	RD: Markings Refresh	Internal		No Action Required	
42196921	Yellow box road markings need refreshed	19/01/2026	At junction with Jordan lane / millar cres	RD: Markings Refresh	Internal		No Action Required	
42196933	1no missing 6 x 12 whin kerb	19/01/2026	Next to parking machine no12246	RD: FW Kerbs Damaged/Missing	Internal		No Action Required	
42196938	1no Cw patch approx 2m x 2m	19/01/2026	At junction with church hill place pedestrian crossing	RD: CW Cracked/Broken	Internal		No Action Required	
42196916	Bus stop road markings need refreshed	19/01/2026	Outside no181	RD: Markings Refresh	Internal		Uncommitted	50177994
42196935	Bus stop road markings need refreshed	19/01/2026	Outside no59	RD: Markings Refresh	Internal		Uncommitted	50185926
42196903	4no broken 900 x 600 pcc slabs 1no broken 750 x 600 pcc slab 3no rocking pcc slabs	19/01/2026	Outside no31	RD: FW Slabs Rocking	Internal		No Action Required	
42196937	Cw breaking up approximately 20m x 5m	19/01/2026	Outside no51 at Orenda shop near junction with churchill place	RD: CW Cracked/Broken	Internal		No Action Required	
42196941	1no Cw pothole	19/01/2026	At pedestrian crossing opposite bodysmart physio	RD: CW Pothole	Internal		Committed	50189896
42196906	2 x 4 patching required at bus stop	19/01/2026	Bus stop outside of 66	RD: CW Cracked/Broken	Internal		No Action Required	

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road			Feature Type: Road Asset		Area: South East Locality	
Batch: 41248989 - Inspection Batch		Route: SE_Morningside_3Month				Date: 19/01/2026		
42196932	2 Whin kerb needs lifted and grano patch taken out and re slabbed 6 /7 roughly as cuts will be needed 450x 600 grey slabs	19/01/2026	Outside home hardware 169 Morningside Road.	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42196942	Stop line and bicycle road markings need refreshed	19/01/2026	At approach to traffic lights north bound at junction with Churchill place	RD: Markings Refresh	Internal		No Action Required	
42196912	1 m x1 m patch required for recurring pothole)	19/01/2026	Morningside Road opposite no 93 Bethany shop in bustop	RD: CW Cracked/Broken	Internal		No Action Required	
42196920	1no yellow box road markings need refreshed	19/01/2026	At junction with Morningside park	RD: Markings Refresh	Internal		No Action Required	
42196908	1no yellow box road markings need refreshed	19/01/2026	At junction with Newbattle terrace	RD: Markings Refresh	Internal		No Action Required	
42196936	Patch required at bus stop approx 3x10m	19/01/2026	Outside 59	RD: CW Cracked/Broken	Internal		No Action Required	
42196925	Faded yellow box grid needs refreshed	19/01/2026	Morningside Road	RD: Markings Refresh	Internal		No Action Required	
42196910	Bus stop road markings need refreshed	19/01/2026	Outside morningside medical practice	RD: Markings Refresh	Internal		Uncommitted	50173013
42196923	1 broken 600x 750 slab and loose 200x200 slab	19/01/2026	Outside Sainsbury's door / near atm machine	RD: FW Slabs Rocking	Internal		No Action Required	
42196928	12 broken 600x450 pcc slabs , please uplift and replace with new	19/01/2026	Outside West End Veterinary Clinic	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42196915	Yellow box road markings need refreshed	19/01/2026	At junction with Falcon road west	RD: Markings Refresh	Internal		No Action Required	
42196904	Bus stop road markings need refreshed	19/01/2026	Outside no64 opposite Churchill theatre	RD: Markings Refresh	Internal		Uncommitted	50178000
Batch: 41248960 - Inspection Batch		Route: Mobile Inspection Strategic				Date: 18/01/2026		
No actionable defects found								
Batch: 41248010 - Inspection Batch		Route: SfP_SouthEast				Date: 12/01/2026		
No actionable defects found								
Batch: 41247686 - Inspection Batch		Route: Mobile Inspection Strategic				Date: 10/01/2026		
42196298	1no pothole	10/01/2026	At the bus stop opposite no408	RD: CW Pothole	Internal		Committed	50189413
Batch: 41246817 - Inspection Batch		Route: Ad hoc Route				Date: 05/01/2026		
42196031	Centre lines need refresh full length of morningside road	05/01/2026	Morningside Road	RD: Markings Refresh	Internal		No Action Required	
Batch: 41246813 - Inspection Batch		Route: Ad hoc Route				Date: 05/01/2026		
42196027	Uneven slabs	05/01/2026	Outside no 368	RD: FW Slabs Rocking	Internal		No Action Required	
Batch: 41245799 - Inspection Batch		Route: Mobile Inspection Strategic				Date: 22/12/2025		
No actionable defects found								
Batch: 41245500 - Inspection Batch		Route: South Mobile Inspection Route				Date: 19/12/2025		
42195558	1no pothole	19/12/2025	At the bus stop outside Morningside Medical Practice	RD: CW Pothole	Internal		Committed	50188735
Batch: 41245289 - Inspection Batch		Route: Ad hoc Route				Date: 18/12/2025		
42195512	No 1 pothole	18/12/2025	at South west corner of the yellow grid box junction at Holy corner heading north into town	RD: CW Pothole	Internal		Committed	50188690

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road			Feature Type: Road Asset		Area: South East Locality	
Batch: 41244429 - Inspection Batch		Route: Ad hoc Route			Date: 12/12/2025			
42195144	1 m x1 m patch required for recurring pothole)	12/12/2025	Morningside Road opposite no 93 Bethany shop in bustop	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41244300 - Inspection Batch		Route: Ad hoc Route			Date: 11/12/2025			
42195046	1no pothole	11/12/2025	Outside no20	RD: CW Pothole	Internal		Committed	50188331
Batch: 41244292 - Inspection Batch No actionable defects found		Route: Mobile Inspection Strategic			Date: 11/12/2025			
Batch: 41243348 - Inspection Batch No actionable defects found		Route: SfP_SouthEast			Date: 01/12/2025			
Batch: 41242189 - Inspection Batch		Route: Ad hoc Route			Date: 20/11/2025			
42193619	Rocking 2x 2 slab	20/11/2025	outside 77 Morningside Road'Six Acres'	RD: FW Slabs Rocking	Internal		Committed	50187249
Batch: 41241798 - Inspection Batch		Route: Ad hoc Route			Date: 18/11/2025			
42193453	Hole in the granite around utility cover possible subsidence under slabs nxt to the hole	18/11/2025	Just outside front door of 398,nxt to Greggs	RD: FW Grano Depression/Sunk	Internal		Committed	50187103
Batch: 41241778 - Inspection Batch		Route: Ad hoc Route			Date: 18/11/2025			
42193439	No 1 pothole	18/11/2025	At bustop at morningside medical practice	RD: CW Pothole	Internal		Committed	50187096
Batch: 41241771 - Inspection Batch		Route: Ad hoc Route			Date: 18/11/2025			
42193433		18/11/2025	At bustop at no 64 morningside road	RD: CW Pothole	Internal		Committed	50187095
Batch: 41241610 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 17/11/2025			
Batch: 41240483 - Inspection Batch No actionable defects found		Route: SfP_SouthEast			Date: 02/11/2025			
Batch: 41239448 - Inspection Batch		Route: SE_Morningside_3Month			Date: 22/10/2025			
42191618	Yellow box road markings need refreshed	22/10/2025	At junction with falcon avenue	RD: Markings Refresh	Internal		No Action Required	
42191677	3no rocking pcc slabs	22/10/2025	Opposite la matinee shop	RD: FW Slabs Rocking	Internal		Committed	50185931
42191620	1no yellow box road markings need refreshed	22/10/2025	At junction with Newbattle terrace	RD: Markings Refresh	Internal		No Action Required	
42191669	2no rocking pcc slabs	22/10/2025	Outside specsavers	RD: FW Slabs Rocking	Internal		Committed	50185928
42191625	2 x 4 patching required at bus stop	22/10/2025	Bus stop outside of 66	RD: CW Cracked/Broken	Internal		No Action Required	
42191611	1no yellow box road markings need refreshed	22/10/2025	At junction with Morningside park	RD: Markings Refresh	Internal		No Action Required	
42191606	1no sunken utility box on Fw	22/10/2025	Morningside road on Footway outside MATTO pizza next to no 368 Photos attached	RU: Utility Apparatus	Internal		Uncommitted	50185904
42191617	1no open joint surrounding water Toby	22/10/2025	Outside no144	RD: FW Grano Open Joint	Internal		Committed	50185906

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Ward 10 - From Colinton Road to Comiston Road	Feature Type: Road Asset			Area: South East Locality	
Batch: 41239448 - Inspection Batch		Route: SE_Morningside_3Month				Date: 22/10/2025		
42191670	1no sunken electricity utility box on Fw	22/10/2025	Morningside Road outside no161 Hospice for hope charity shop opposite the Merlin bar Photos attached	RU: Utility Apparatus	Internal		Uncommitted	50185929
42191666	Bus stop road markings need refreshed	22/10/2025	Outside no59	RD: Markings Refresh	Internal		No Action Required	50185909
42191626	1no Cw pothole	22/10/2025	Outside church Next to Lucas ice cream shop in Loading bay	RD: CW Pothole	Internal		Committed	
42191621	Cracked and broken asphalt surface approx 6mx2m	22/10/2025	Opposite no126	RD: CW Cracked/Broken	Internal		Uncommitted	50081549
42191664	1no Cw patch approx 2m x 2m	22/10/2025	At junction with church hill place pedestrian crossing	RD: CW Cracked/Broken	Internal		No Action Required	
42191663	Cw breaking up approximately 20m x 5m	22/10/2025	Outside no51 at Orenda shop near junction with churchill place	RD: CW Cracked/Broken	Internal		No Action Required	
42191619	Bus stop road markings need refreshed	22/10/2025	Outside morningside medical practice	RD: Markings Refresh	Internal		No Action Required	
42191679	1no broken 450 x 300 pcc slab 1no rocking 450 x 300 pcc slab	22/10/2025	Opposite bus stop at no 378	RD: FW Slabs Broken/Missing	Internal		Committed	50185933
42191653	Stop line and bicycle road markings need refreshed	22/10/2025	At approach to traffic lights north bound at junction with Churchill place	RD: Markings Refresh	Internal		No Action Required	
42191671	3no uneven kerb 8no 450x600 pcc slabs	22/10/2025	Outside Home hardware	RD: FW Kerb Dislodged/Rocking	Internal		Uncommitted	50143986
42191665	Patch required at bus stop approx 3x10m	22/10/2025	Outside 59	RD: CW Cracked/Broken	Internal		No Action Required	
42191608	Yellow box road markings need refreshed	22/10/2025	At junction with Jordan lane / millar cres	RD: Markings Refresh	Internal		No Action Required	
42191672	2 Whin kerb needs lifted and grano patch taken out and re slabbed 6 /7 roughly as cuts will be needed 450x 600 grey slabs	22/10/2025	Outside home hardware 169 Morningside Road.	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42191667	1no missing 6 x 12 whin kerb	22/10/2025	Next to parking machine no12246	RD: FW Kerbs Damaged/Missing	Internal		No Action Required	
42191676	12 broken 600x450 pcc slabs , please uplift and replace with new	22/10/2025	Outside West End Veterinary Clinic	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42191673	Yellow box road markings need refreshed	22/10/2025	At junction with Falcon road west	RD: Markings Refresh	Internal		No Action Required	
42191675	Bus stop road markings need refreshed	22/10/2025	Outside no181	RD: Markings Refresh	Internal		No Action Required	
42191623	1no broken cut pcc slab at catv box Remove and infill with grano	22/10/2025	At junction with Abbotsford park Outside shelter Scotland charity shop	RD: FW Slabs Broken/Missing	Internal		Committed	50185908
42191624	Bus stop road markings need refreshed	22/10/2025	Outside no64 opposite Churchill theatre	RD: Markings Refresh	Internal		No Action Required	
42191607	1 broken 600x 750 slab and loose 200x200 slab	22/10/2025	Outside Sainsbury's door / near atm machine	RD: FW Slabs Rocking	Internal		No Action Required	
Batch: 41238880 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route				Date: 15/10/2025		
Batch: 41238459 - Inspection Batch		Route: Ad hoc Route				Date: 10/10/2025		
42190979	Yellow grid box needs refresh	10/10/2025	Comiston Road at junction with morningside drive	RD: Markings Refresh	Internal		Uncommitted	50185461
Batch: 41238454 - Inspection Batch		Route: Ad hoc Route				Date: 10/10/2025		
42190974	Faded yellow box grid needs refreshed	10/10/2025	Morningside Road	RD: Markings Refresh	Internal		No Action Required	

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road			Feature Type: Road Asset		Area: South East Locality	
Batch: 41238029 - Inspection Batch		Route: Ad hoc Route			Date: 07/10/2025			
42190599	No 1 pothole	07/10/2025	outside The Morningside Medical Centre.on CW at bustop	RD: CW Pothole	Internal		Committed	50185213
Batch: 41237836 - Inspection Batch No actionable defects found		Route: SfP_SouthEast			Date: 02/10/2025			
Batch: 41237806 - Inspection Batch		Route: Ad hoc Route			Date: 02/10/2025			
42190453	No 1 pothole	02/10/2025	Opposite Churchill theatre at bustop	RD: CW Pothole	Internal		Committed	50185110
Batch: 41236576 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 11/09/2025			
Batch: 41235544 - Inspection Batch No actionable defects found		Route: SfP_SouthEast			Date: 27/08/2025			
Batch: 41234440 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 11/08/2025			
Batch: 41233823 - Inspection Batch		Route: Ad hoc Route			Date: 29/07/2025			
42187805	1 broken 600x 750 slab and loose 200x200 slab	29/07/2025	Outside door / near atm machine	RD: FW Slabs Rocking	Internal		No Action Required	
Batch: 41233121 - Inspection Batch No actionable defects found		Route: SfP_SouthEast			Date: 17/07/2025			
Batch: 41232779 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 11/07/2025			
Batch: 41232258 - Inspection Batch		Route: SE_Morningside_3Month			Date: 04/07/2025			
42186545	1no missing 6 x 12 whin kerb	04/07/2025	Next to parking machine no12246	RD: FW Kerbs Damaged/Missing	Internal		No Action Required	
42186531	12 broken 600x450 pcc slabs , please uplift and replace with new	04/07/2025	Outside West End Veterinary Clinic	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42186538	1no sunken plastic water Toby / cover Photos attached	04/07/2025	Morningside road on Footway outside no 263 west end vets shop	RU: Utility Apparatus	Internal		Uncommitted	50182346
42186524	Bus stop road markings need refreshed	04/07/2025	Outside mirningside medical practice	RD: Markings Refresh	Internal		No Action Required	
42186514	1no broken 450 x 600 pcc slab	04/07/2025	Outside no20 the source clinic	RD: FW Slabs Broken/Missing	Internal		Committed	50178002
42186540	Yellow box road markings need refreshed	04/07/2025	At junction with Falcon road west	RD: Markings Refresh	Internal		No Action Required	
42186526	Straighen signs and replace signs brackets	04/07/2025	Royal Edinburgh Direction Sign on Morningside Road at junction with Morningside park	RD: Unlit Sign Damaged/Missing	Internal		Committed	50180382
42186549	Broken Grano track on crossing approx 1m x 0.2m	04/07/2025	At vehicle entrance into church hill theatre	RD: FW Grano Cracked/Broken	Internal		Committed	50182350
42186516	Bus stop road markings need refreshed	04/07/2025	Outside no64 opposite Churchill theatre	RD: Markings Refresh	Internal		No Action Required	
42186541	Bus stop road markings need refreshed	04/07/2025	Outside no181	RD: Markings Refresh	Internal		No Action Required	
42186513	1no missing Grano area at box	04/07/2025	Outside Luca ice cream shop	RD: FW Grano Open Joint	Internal		Committed	50182332
42186529	Broken Grano at box on fw	04/07/2025	Outside no408	RD: FW Grano Cracked/Broken	Internal		Committed	50182339
42186527	Yellow box road markings need refreshed	04/07/2025	At junction with Jordan lane / millar cres	RD: Markings Refresh	Internal		No Action Required	

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road		Feature Type: Road Asset		Area: South East Locality		
Batch: 41232258 - Inspection Batch		Route: SE_Morningside_3Month				Date: 04/07/2025		
42186519	1no missing Grano area at box 1no rocking 300 x 300 pcc slab	04/07/2025	Outside old school house next to cuddy lane	RD: FW Grano Open Joint	Internal		Committed	50182334
42186515	2 x 4 patching required at bus stop	04/07/2025	Bus stop outside of 66	RD: CW Cracked/Broken	Internal		No Action Required	
42186548	1no Fw pothole	04/07/2025	At vehicle exit at church hill theatre	RD: FW HRA Pothole	Internal		Committed	50182349
42186544	Cracked and broken asphalt surface approx 6mx2m	04/07/2025	Opposite no126	RD: CW Cracked/Broken	Internal		No Action Required	
42186543	1no sunken electricity box Photos attached	04/07/2025	Morningside road on Footway outside no 159 hospices of hope charity shop	RU: Utility Apparatus	Internal		Uncommitted	50182348
42186542	2 Whin kerb needs lifted and grano patch taken out and re slabbed 6 /7 roughly as cuts will be needed 450x 600 grey slabs	04/07/2025	Outside home hardware 169 Morningside Road.	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42186520	Yellow box road markings need refreshed	04/07/2025	At junction with falcon avenue	RD: Markings Refresh	Internal		No Action Required	
42186518	Stop line and bicycle road markings need refreshed	04/07/2025	At approach to traffic lights north bound at junction with Churchill place	RD: Markings Refresh	Internal		No Action Required	
42186539	1no broken 450 x 600 pcc slab	04/07/2025	Outside food for u shop	RD: FW Slabs Broken/Missing	Internal		Committed	50182347
42186547	Cw breaking up approximately 20m x 5m	04/07/2025	Outside no51 at Orenda shop near junction with churchill place	RD: CW Cracked/Broken	Internal		No Action Required	
42186546	Patch required at bus stop approx 3x10m	04/07/2025	Outside 59	RD: CW Cracked/Broken	Internal		No Action Required	
42186528	Place No Through road sign on signs pole , signs diagram no 816, sign size 400mm x 400mm Pickup sign from Bankhead depot stores	04/07/2025	Missing No through road sign On east footway at junction with Maxwell street	RD: Unlit Sign Damaged/Missing	Internal		Committed	50180388
42186525	1no missing Grano area at gas Toby	04/07/2025	Outside no160	RD: FW Grano Open Joint	Internal		Committed	50182338
Batch: 41231504 - Inspection Batch		Route: SfP_SouthEast				Date: 23/06/2025		
No actionable defects found								
Batch: 41230163 - Inspection Batch		Route: South Mobile Inspection Route				Date: 05/06/2025		
No actionable defects found								
Batch: 41229316 - Inspection Batch		Route: Ad hoc Route				Date: 27/05/2025		
42184412	No1 pothole around fire hydrant)	27/05/2025	Outside entrance to Eric Liddell Centre. At traffic lights	RD: CW Pothole	Internal		Committed	50180461
Batch: 41229293 - Inspection Batch		Route: Ad hoc Route				Date: 27/05/2025		
42184372	2 Whin kerb needs lifted and grano patch taken out and re slabbed 6 /7 roughly as cuts will be needed 450x 600 grey slabs	27/05/2025	Outside home hardware 169 Morningside Road.	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
Batch: 41229220 - Inspection Batch		Route: Ad hoc Route				Date: 27/05/2025		
42184288	Place No Through road sign on signs pole , signs diagram no 816, sign size 400mm x 400mm Pickup sign from Bankhead depot stores	27/05/2025	Missing No through road sign On east footway at junction with Maxwell street	RD: Unlit Sign Damaged/Missing	Internal		No Action Required	

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road			Feature Type: Road Asset		Area: South East Locality	
Batch: 41229211 - Inspection Batch			Route: Ad hoc Route				Date: 27/05/2025	
42184281	Straighten signs and replace signs brackets	27/05/2025	Royal Edinburgh Direction Sign on Morningside Road at junction with Morningside park	RD: Unlit Sign Damaged/Missing	Internal		No Action Required	
Batch: 41228263 - Inspection Batch No actionable defects found			Route: SfP_SouthEast				Date: 14/05/2025	
Batch: 41227649 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route				Date: 06/05/2025	
Batch: 41226152 - Inspection Batch No actionable defects found			Route: SfP_SouthEast				Date: 16/04/2025	
Batch: 41225785 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route				Date: 10/04/2025	
Batch: 41224836 - Inspection Batch			Route: SE_Morningside_3Month				Date: 02/04/2025	
42180450	Cracked and broken asphalt surface approx 6mx2m	01/04/2025	Opposite no126	RD: CW Cracked/Broken	Internal		No Action Required	
42180454	1no BT box frame sunken on FW and needs raised Photos attached	01/04/2025	Opposite no150 Morningside road outside Waitrose shop	RU: Utility Apparatus	Internal		Uncommitted	50178004
42180449	1no missing whin kerb Infill with grano	01/04/2025	Next to parking machine no12246	RD: FW Kerbs Damaged/Missing	Internal		No Action Required	
42180440	1no broken 450 x 600 pcc slab 2no rocking pcc slabs	01/04/2025	Outside no128 the Gurkha restaurant	RD: FW Slabs Broken/Missing	Internal		Committed	50177998
42180436	Bus stop road markings need refreshed	01/04/2025	Outside no181	RD: Markings Refresh	Internal		No Action Required	
42180429	1no broken 300 x 300 pcc slab 8no rocking 300 x 300 and cut pcc slabs	01/04/2025	On fw outside no32 and chest heart and strike charity shop	RD: FW Slabs Broken/Missing	Internal		Committed	50177988
42180438	1no broken cut pcc slab	01/04/2025	Opposite cancer research shop On corner with Morningside place next to tactiles	RD: FW Slabs Broken/Missing	Internal		Committed	50177996
42180453	Bus stop road markings need refreshed	01/04/2025	Outside mirningside medical practice	RD: Markings Refresh	Internal		No Action Required	
42180452	Yellow box road markings need refreshed	01/04/2025	At junction with falcon avenue	RD: Markings Refresh	Internal		No Action Required	
42180446	Stop line and bicycle road markings need refreshed	01/04/2025	At approach to traffic lights north bound at junction with Churchill place	RD: Markings Refresh	Internal		No Action Required	
42180457	1no hole where pole has been cut away please flatten edges of pole and infill with grano	01/04/2025	Outside no257 picture framer shop	RD: FW Grano Pothole	Internal		Committed	50178006
42180443	2 x 4 patching required at bus stop	01/04/2025	Bus stop outside of 66	RD: CW Cracked/Broken	Internal		No Action Required	
42180447	Cw breaking up approximately 20m x 5m	01/04/2025	Outside no51 at Orenda shop near junction with churchill place	RD: CW Cracked/Broken	Internal		No Action Required	
42180428	2no rocking cut pcc slabs	01/04/2025	Outside artisan bakery on fw at kerb edge	RD: FW Slabs Rocking	Internal		Committed	50177987
42180458	12 broken 600x450 pcc slabs , please uplift and replace with new	01/04/2025	Outside West End Veterinary Clinic	RD: FW Slabs Broken/Missing	Internal		No Action Required	

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road		Feature Type: Road Asset			Area: South East Locality	
Batch: 41224836 - Inspection Batch		Route: SE_Morningside_3Month				Date: 02/04/2025		
42180445	1no broken 450 x 600 pcc slab	01/04/2025	Outside no20 the source clinic	RD: FW Slabs Broken/Missing	Internal		No Action Required	
42180444	2no sunken cut pcc slabs need raised 1no open grano joint at box	01/04/2025	Outside no20 the source clinic	RD: FW Slabs Rocking	Internal		Committed	50178001
42180456	Yellow box road markings need refreshed	01/04/2025	At junction with Falcon road west	RD: Markings Refresh	Internal		No Action Required	
42180442	Bus stop road markings need refreshed	01/04/2025	Outside no64 opposite Churchill theatre	RD: Markings Refresh	Internal		No Action Required	
42180455	3no uneven kerb 8no 450x600 pcc slabs	01/04/2025	Outside Home hardware	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42180451	1no rocking 600 x 600 pcc slab	01/04/2025	Outside British Red Cross charity shop	RD: FW Slabs Rocking	Internal		Committed	50178003
42180448	Patch required at bus stop approx 3x10m	01/04/2025	Outside 59	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41224502 - Inspection Batch No actionable defects found		Route: Mobile Inspection Strategic				Date: 30/03/2025		
Batch: 41224194 - Inspection Batch		Route: Ad hoc Route				Date: 26/03/2025		
42179821	Sunken track no1 pothole	26/03/2025	Heading into town .outside TECHFIXD at traffic lights near no 332	RD: CW Pothole	Internal		Committed	50177624
Batch: 41224029 - Inspection Batch No actionable defects found		Route: SfP_SouthEast				Date: 24/03/2025		
Batch: 41223913 - Inspection Batch No actionable defects found		Route: Mobile Inspection Strategic				Date: 24/03/2025		
Batch: 41222835 - Inspection Batch No actionable defects found		Route: Mobile Inspection Strategic				Date: 15/03/2025		
Batch: 41222740 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route				Date: 14/03/2025		
Batch: 41222581 - Inspection Batch		Route: Ad hoc Route				Date: 13/03/2025		
42178623	1no rocking 450 x 600 pcc slab	13/03/2025	Outside paper tiger shop	RD: FW Slabs Rocking	Internal		Committed	50176907
Batch: 41222577 - Inspection Batch		Route: Ad hoc Route				Date: 13/03/2025		
42178617	1no rocking 450 x 600 pcc slab	13/03/2025	Outside Pizza Hut	RD: FW Slabs Rocking	Internal		Committed	50176902
Batch: 41221641 - Inspection Batch No actionable defects found		Route: Mobile Inspection Strategic				Date: 06/03/2025		
Batch: 41221056 - Inspection Batch No actionable defects found		Route: Mobile Inspection Strategic				Date: 28/02/2025		
Batch: 41220826 - Inspection Batch		Route: Ad hoc Route				Date: 27/02/2025		
42177248	No1 pothole	27/02/2025	At bustop opposite church hill theartre	RD: CW Pothole	Internal		Committed	50176019
Batch: 41220461 - Inspection Batch No actionable defects found		Route: SfP_SouthEast				Date: 24/02/2025		

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road			Feature Type: Road Asset		Area: South East Locality	
Batch: 41220380 - Inspection Batch		Route: Ad hoc Route			Date: 24/02/2025			
42176890	Sign pole been hit n pushed up slabs at base so needs straightened n slabs replaced	24/02/2025	Outside Costa coffe	RD: FW Slabs Broken/Missing	Internal		Committed	50175772
Batch: 41220120 - Inspection Batch No actionable defects found		Route: Mobile Inspection Strategic			Date: 20/02/2025			
Batch: 41219521 - Inspection Batch		Route: Ad hoc Route			Date: 18/02/2025			
42176331	2 no potholes	18/02/2025	Outside morning side gallery at traffic lights at kerbside one in middle of road	RD: CW Pothole	Internal		Committed	50175356
Batch: 41218981 - Inspection Batch		Route: Ad hoc Route			Date: 13/02/2025			
42175895	No 1 pothole	13/02/2025	At morningside bustop at morningside medical practice	RD: CW Pothole	Internal		Committed	50175023
Batch: 41218555 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 11/02/2025			
Batch: 41218495 - Inspection Batch No actionable defects found		Route: Mobile Inspection Strategic			Date: 11/02/2025			
Batch: 41217830 - Inspection Batch		Route: Ad hoc Route			Date: 06/02/2025			
42175180	2 no potholes	06/02/2025	Outside no 32 nxt to post office CW	RD: CW Pothole	Internal		Committed	50174450
Batch: 41217827 - Inspection Batch		Route: Ad hoc Route			Date: 06/02/2025			
42175177	1 rocking 900x600 grey slab and 1 sunken broken 900x600 slab	06/02/2025	Outside entrance to Lucas ice cream shop	RD: FW Slabs Rocking	Internal		Committed	50174447
Batch: 41217825 - Inspection Batch		Route: Ad hoc Route			Date: 06/02/2025			
42175174	No 1 pothole	06/02/2025	outside number 16 Lucas ice cream shop middle of carriage way	RD: CW Pothole	Internal		Committed	50174446
Batch: 41217089 - Inspection Batch No actionable defects found		Route: Mobile Inspection Strategic			Date: 31/01/2025			
Batch: 41216796 - Inspection Batch No actionable defects found		Route: SfP_SouthEast			Date: 29/01/2025			
Batch: 41216198 - Inspection Batch		Route: Ad hoc Route			Date: 23/01/2025			
42173908	1 rocking 600x450 slab	23/01/2025	Outside no 388 nxt to save the children shop going into town	RD: FW Slabs Rocking	Internal		Committed	50173497
Batch: 41216193 - Inspection Batch		Route: Ad hoc Route			Date: 23/01/2025			
42173905	3 rocking 600x 450 grey slabs ...3 broken half 600x450 slabs2 rocking half 600x450 slabs.... And granite broken around manhole	23/01/2025	Outside. House no 398 next to Greggs going into town	RD: FW Slabs Rocking	Internal		Committed	50173494
Batch: 41215741 - Inspection Batch		Route: Mobile Inspection Strategic			Date: 21/01/2025			
42173603	1no pothole	21/01/2025	At the bus stop opposite the Bethany Shop	RD: CW Pothole	Internal		Committed	50173282

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road			Feature Type: Road Asset		Area: South East Locality	
Batch: 41214995 - Inspection Batch		Route: SE_Morningside_3Month				Date: 16/01/2025		
42173277	Yellow box road markings need refreshed	16/01/2025	At junction with Jordan lane / millar cres	RD: Markings Refresh	Internal		No Action Required	
42173258	Bollard damaged, please replace with new Pavement: Damaged / Defective (Enquiry 1671502)	16/01/2025	Outside of Paper Tiger	RD: Bollard Damage/Missing/Nev	Internal		Uncommitted	50149563
42173271	Yellow box road markings need refreshed	16/01/2025	At junction with falcon avenue	RD: Markings Refresh	Internal		No Action Required	
42173276	Relay and point rocking tactiles	16/01/2025	Morningside rd at steel's place	RD: FW Slabs Rocking	Internal		Uncommitted	50148685
42173269	1no missing whin kerb Infill with grano	16/01/2025	Next to parking machine no12246	RD: FW Kerbs Damaged/Missing	Internal		No Action Required	
42173263	1no damaged / missing section of whin kerb Infill with grano	16/01/2025	Outside no19 opposite luca ice cream shop	RD: FW Kerbs Damaged/Missing	Internal		Committed	50173017
42173264	Stop line and bicycle road markings need refreshed	16/01/2025	At approach to traffic lights north bound at junction with Churchill place	RD: Markings Refresh	Internal		No Action Required	
42173275	3x slabs rocking, please relay	16/01/2025	Outside of 199	RD: FW Slabs Rocking	Internal		Uncommitted	50141626
42173267	Patch required at bus stop approx 3x10m	16/01/2025	Outside 59	RD: CW Cracked/Broken	Internal		No Action Required	
42173254	1no broken 900 x 600 pcc slab 1no grano infill at manhole on fw	16/01/2025	Outside matti pizza restaurant	RD: FW Slabs Rocking	Internal		Committed	50173009
42173259	Bus stop road markings need refreshed	16/01/2025	Outside mirningside medical practice	RD: Markings Refresh	Internal		No Action Required	
42173253	Cw sunken 6mx1.5m	16/01/2025	Comiston rd opposite craiglea clocks no88	RD: CW Subsidence/Heaving	Internal		Uncommitted	50148689
42173252	3no broken 450 x 600 pcc slab 2no broken 450 x 300 pcc slabs	16/01/2025	Outside no394 Mia Italian kitchen	RD: FW Slabs Broken/Missing	Internal		Committed	50173008
42173255	1no pole stump in middle of fw please cut away / make safe and infill with grano	16/01/2025	Opposite cafe blush at junction with mirningside park	RD: FW Grano Pothole	Internal		Committed	50173010
42173274	Renew grano at box	16/01/2025	Outside St Columbus hospice	RD: FW Grano Cracked/Broken	Internal		Uncommitted	50143988
42173272	3no uneven kerb 8no 450x600 pcc slabs	16/01/2025	Outside Home hardware	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42173266	Cw breaking up approximately 20m x 5m	16/01/2025	Outside Orenda shop near junction with churchill place	RD: CW Cracked/Broken	Internal		No Action Required	
42173268	Patch required at bus stop approx 3x10m	16/01/2025	Outside 59	RD: CW Cracked/Broken	Internal		Uncommitted	50143983
42173270	Cracked and broken asphalt surface approx 6mx2m	16/01/2025	Opposite no126	RD: CW Cracked/Broken	Internal		No Action Required	
42173278	12 broken 600x450 pcc slabs , please uplift and replace with new	16/01/2025	Outside West End Veterinary Clinic	RD: FW Slabs Broken/Missing	Internal		No Action Required	
Batch: 41214387 - Inspection Batch		Route: Ad hoc Route				Date: 13/01/2025		
42172847	No 2 potholes	13/01/2025	Corner of Church Hill and Morningside road opposite body smart	RD: CW Pothole	Internal		Committed	50172720
Batch: 41213821 - Inspection Batch No actionable defects found		Route: SfP_SouthEast				Date: 10/01/2025		
Batch: 41213469 - Inspection Batch		Route: South Mobile Inspection Route				Date: 09/01/2025		
42172499	1no pothole	09/01/2025	At the bus stop outside no59	RD: CW Pothole	Internal		Committed	50172459

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road			Feature Type: Road Asset		Area: South East Locality	
Batch: 41212801 - Inspection Batch		Route: Ad hoc Route			Date: 06/01/2025			
42172045	No 1 pothole	06/01/2025	At bustop at active feet shop	RD: CW Pothole	Internal		Committed	50172097
Batch: 41210856 - Inspection Batch		Route: SfP_SouthEast			Date: 12/12/2024			
No actionable defects found								
Batch: 41210237 - Inspection Batch		Route: South Mobile Inspection Route			Date: 09/12/2024			
No actionable defects found								
Batch: 41210029 - Inspection Batch		Route: Ad hoc Route			Date: 09/12/2024			
42170727	1 no pothole	09/12/2024	Opposite the Bethany shop at bustop	RD: CW Pothole	Internal		Committed	50171016
Batch: 41209558 - Inspection Batch		Route: Ad hoc Route			Date: 04/12/2024			
42170390	1 no pothole	04/12/2024	Outside no 64 at bus stop	RD: CW Pothole	Internal		Committed	50170768
Batch: 41207793 - Inspection Batch		Route: SfP_SouthEast			Date: 15/11/2024			
No actionable defects found								
Batch: 41207278 - Inspection Batch		Route: South Mobile Inspection Route			Date: 11/11/2024			
No actionable defects found								
Batch: 41204748 - Inspection Batch		Route: SE_Morningside_3Month			Date: 22/10/2024			
42167323	3no broken cut buff tactile slabs	22/10/2024	At pedestrian crossing with cluny avenue next to bus stop	RD: FW Slabs Broken/Missing	Internal		Committed	50168498
42167320	1no rocking cross cut 900 x600 pcc slab	22/10/2024	Pedestrian crossing outside jardine Phillips estate agent	RD: FW Slabs Rocking	Internal		Committed	50168496
42167318	1no broken cut pcc slab	22/10/2024	Outside toys galore shop at telecom box	RD: FW Slabs Broken/Missing	Internal		Committed	50168494
42167315	1no fw pothole	22/10/2024	At bus stop opposite boots	RD: FW HRA Pothole	Internal		Committed	50168491
42167322	6x slabs rocking, please relay Pavement: Damaged / Defective (Enquiry 1722276)	22/10/2024	Bus stop at the junction with Cluny avenue	RD: FW Slabs Rocking	Internal		Uncommitted	50156576
42167319	1no rocking 450 x 350 pcc slab	22/10/2024	Outside first class barbers	RD: FW Slabs Rocking	Internal		Committed	50168495
42167317	1no rocking 600 z 600 pcc slab	22/10/2024	Outside British Red Cross shop	RD: FW Slabs Rocking	Internal		Committed	50168493
42167313	1no fw grano pothole	22/10/2024	At pedestrian crossing opposite the bank of Scotland	RD: FW Grano Pothole	Internal		Committed	50168489
42167321	1no broken 450 x 600 pcc slab	22/10/2024	Opposite watt terrace cafe	RD: FW Slabs Broken/Missing	Internal		Committed	50168497
42167316	1no rocking cut pcc slab	22/10/2024	Outside Bethany charity shop next to mono blocks	RD: FW Slabs Rocking	Internal		Committed	50168492
Batch: 41204443 - Inspection Batch		Route: SfP_SouthEast			Date: 21/10/2024			
No actionable defects found								
Batch: 41204422 - Inspection Batch		Route: Ad hoc Route			Date: 21/10/2024			
42167181	Relay 1 rocking tactile	21/10/2024	At junction with steels place	RD: FW Slabs Rocking	Internal		Committed	50168378
Batch: 41204023 - Inspection Batch		Route: Ad hoc Route			Date: 18/10/2024			
42167040	Cw x1 pothole Road: Defective / Damaged (Enquiry 1846032)	18/10/2024	Bus stop outside of Medical centre	RD: CW Pothole	Internal		Committed	50168260

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
	Asset: 1.00	Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road			Feature Type: Road Asset		Area: South East Locality	
	Batch: 41202902 - Inspection Batch No actionable defects found				Route: South Mobile Inspection Route		Date: 09/10/2024	
	Batch: 41202135 - Inspection Batch				Route: Ad hoc Route		Date: 03/10/2024	
42165856	Cw x1 pothole Road: Defective / Damaged (Enquiry 1839178)	03/10/2024	Southbound bus stop opposite Abbotsford Road	RD: CW Pothole	Internal		Committed	50167418
	Batch: 41201006 - Inspection Batch				Route: Ad hoc Route		Date: 19/09/2024	
42165163	Miising granite infill Approx 1.5m x 300mm	19/09/2024	Outside church hill theatre	RD: FW Grano Cracked/Broken	Internal		Committed	50166760
	Batch: 41200908 - Inspection Batch No actionable defects found				Route: SfP_SouthEast		Date: 18/09/2024	
	Batch: 41200477 - Inspection Batch				Route: Ad hoc Route		Date: 11/09/2024	
42164771	Cw x1 pothole	11/09/2024	Outside of 59	RD: CW Pothole	Internal		Committed	50166361
	Batch: 41200241 - Inspection Batch				Route: South Mobile Inspection Route		Date: 09/09/2024	
42164715	1no pothole	09/09/2024	At the bus stop outside no59	RD: CW Pothole	Internal		Committed	50166292
	Batch: 41198927 - Inspection Batch				Route: Ad hoc Route		Date: 16/08/2024	
42163735	1no 900x600x63 pcc slab , 3 no small elements loose and rocking/ Pavement: Damaged / Defective (Enquiry 1816815)	16/08/2024	Outside of 352	RD: FW Slabs Broken/Missing	Internal		Committed	50165431
	Batch: 41198663 - Inspection Batch No actionable defects found				Route: South Mobile Inspection Route		Date: 14/08/2024	
	Batch: 41198419 - Inspection Batch No actionable defects found				Route: SfP_SouthEast		Date: 12/08/2024	
	Batch: 41197781 - Inspection Batch				Route: Ad hoc Route		Date: 31/07/2024	
42162879	Grano patch reinstated , Pavement: Damaged / Defective (Enquiry 1808066)	31/07/2024	Outside of Churchill Theatre	RD: FW Grano Depression/Sunk	Internal		Committed	50164780
	Batch: 41197778 - Inspection Batch				Route: Ad hoc Route		Date: 31/07/2024	
42162874	Cw x1 pothole Road: Defective / Damaged (Enquiry 1808142)	31/07/2024	Outside of luca, s (city bound)	RD: CW Pothole	Internal		Committed	50164776
	Batch: 41197728 - Inspection Batch				Route: SE_Morningside_3Month		Date: 31/07/2024	
42162811	3no uneven kerb 8no 450x600 pcc slabs	30/07/2024	Outside Home hardware	RD: FW Kerb Dislodged/Rocking	Internal		No Action Required	
42162812	3 no rocking slabs 2no 300 x 300 pcc slabs 1no cut 300 x 300 pcc slab	30/07/2024	Outside old school house	RD: FW Slabs Rocking	Internal		Committed	50164717
42162816	Cw breaking up approximately 20m x 5m	30/07/2024	Outside or ends shop near junction with churchi hill place	RD: CW Cracked/Broken	Internal		No Action Required	
42162813	2 no rocking slabs	30/07/2024	Outside specsavers shop	RD: FW Slabs Rocking	Internal		Committed	50164720
42162814	Cracked and broken asphalt surface approx 6mx2m	30/07/2024	Opposite no126	RD: CW Cracked/Broken	Internal		No Action Required	

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road			Feature Type: Road Asset		Area: South East Locality	
Batch: 41197728 - Inspection Batch				Route: SE_Morningside_3Month				Date: 31/07/2024
42162815	Patch required at bus stop approx 3x10m	30/07/2024	Outside 59	RD: CW Cracked/Broken	Internal	No Action Required		
Batch: 41197233 - Inspection Batch				Route: SfP_SouthEast				Date: 22/07/2024
No actionable defects found								

Customer Services

Enquiry No.: 34010698		Logged by: [REDACTED]		on: 05/01/2026 11:43	
Service: Roads General		Subject: Road Markings: Defective		Classification: Request for service	
Desc.: Morningside Road/ Falcon Road West. Please inspect road markings due to car incident.					
Location: Morningside Road			Contact: 0		
Plot Number: 1.00		Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road			Feature Type: Road Asset
Job Number: 50189170		Defect Number: 42212341			
Enquiry No.: 34010647		Logged by: [REDACTED]		on: 09/12/2025 12:34	
Service: Roads General		Subject: Road: Defective / Damaged		Classification: Request for service	
Desc.: Please inspect damaged pothole at the bus stop on Morningside Road outside the Morningside Medical Practice					
Location: Morningside Road			Contact:		
Plot Number: 1.00		Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road			Feature Type: Road Asset
Job Number: 50188413		Defect Number: 42212344			
Enquiry No.: 34010436		Logged by: [REDACTED]		on: 07/10/2025 13:37	
Service: Roads General		Subject: Road Markings: Defective		Classification: Request for service	
Desc.: Please inspect the yellow lines in the box grids The junctions with Morningside Road at Maxwell Street					
Location: Morningside Road			Contact: 0		
Plot Number: 1.00		Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road			Feature Type: Road Asset
Job Number: 50185456		Defect Number: 42212321			
Enquiry No.: 34010434		Logged by: [REDACTED]		on: 07/10/2025 13:17	
Service: Roads General		Subject: Road Markings: Defective		Classification: Request for service	
Desc.: Please inspect yellow lines in the box grids Comiston Rd at Morningside Drive.					
Location: Comiston Road			Contact: 0		
Plot Number: 1.00		Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road			Feature Type: Road Asset
Job Number: 50185461		Defect Number: 42190979			
Enquiry No.: 34009347		Logged by: [REDACTED]		on: 25/11/2024 10:07	
Service: Roads General		Subject: Pavement: Damaged / Defective		Classification: Request for service	
Desc.: please inspect the junction of mornionside road the surfaces are all broken up. hazard for pedestrians when crossing.					
Location: Morningside Road			Contact:		
Plot Number: 1.00		Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road			Feature Type: Road Asset

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2180551 **Logged by:** Verint CRM Connector **on:** 16/07/2026 09:20
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: At the corner between Morningside Road and Maxwell Street outside of Matto Pizza **Contact:**
the slabs are cracked, loose, easy to lift and a trip hazard when stood on

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2180548 **Logged by:** Verint CRM Connector **on:** 16/07/2026 09:17
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Between La Matinee and Mia Italia up against the road the pavement is cracked and **Contact:**
loose with some slabs able to be lifted quite easily. Majority of the damage located
around water and other utility access points.

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2180541 **Logged by:** Verint CRM Connector **on:** 16/07/2026 09:12
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Slab in middle of pavement outside of La Matinee on Morningside Road is loose and **Contact:**
is lifted up when stood on, creating a tripping hazard especially for elder, disabled
and children

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2179537 **Logged by:** Verint CRM Connector **on:** 14/07/2026 14:19
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: The pavement outside Ian Brown's is in part uneven with some large dips and ridges **Contact:**
where pavers do not meet or are raised. My [REDACTED] tripped upon one particularly raised
flagstone. Fortunately [REDACTED] received only superficial, but painful injuries.
My [REDACTED] is not disabled nor mobility limited, that such a fall can happen to an
essentially fit person would indicate a much greater risk for those with such
problems.
I would like to think that this surface could be made smoother and safer.

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Job Number: 50199963 **Defect Number:** 42212319

Enquiry No.: 2175476 **Logged by:** Verint CRM Connector **on:** 07/07/2026 09:14
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Immediately outside the door for 388 Morningside road, the slab making up the **Contact:**
pavement around the gas mains is broken and springs up unexpectedly when
stepped on causing a trip hazard which I had caused many trips and near misses
especially with children, old and disabled persons.

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Job Number: 50199688 **Defect Number:** 42212320

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2173763 **Logged by:** Verint CRM Connector **on:** 03/07/2026 12:13
Service: Roads General **Subject:** RS Pedestrian Crossing Request **Classification:** General Enquiry
Desc.: Problem: Transferred from Legacy List. Original assessment undertaken 03/12/19 PV2 0.547

Location: 140, MORNINGSIDE ROAD, EDINBURGH, EH10 4PX

Location: **Contact:**

Enquiry No.: 2167141 **Logged by:** Verint CRM Connector **on:** 22/06/2026 14:32
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Adjacent to Morningside Health centre just before bus stop
Deep pothole on west side of Morningside road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2166810 **Logged by:** Verint CRM Connector **on:** 22/06/2026 08:53
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Pothole at bus stop on Morningside Road, as you head in to the direction of the city
centre. Just before turn off for Morningside place **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2166588 **Logged by:** Verint CRM Connector **on:** 21/06/2026 15:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Very large pothole in the bus stop. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2166249 **Logged by:** Verint CRM Connector **on:** 20/06/2026 14:12
Service: Roads General **Subject:** Pavement: Missing Slab / Kerb **Classification:** Customer Emergency
Desc.:

Location: Missing let stone caused my  to trip and fall into the road very dangerous **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2166177 **Logged by:** Verint CRM Connector **on:** 20/06/2026 11:06
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: At Morningside place bus stop **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Job Number: 50198931 **Defect Number:** 42209573

Enquiry No.: 2154230 **Logged by:** Verint CRM Connector **on:** 28/05/2026 10:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Opposite ms food hall at 221 Morningside road **Contact:**

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2148297 Service: Roads General Desc.: Location: Near Eric Liddell centre	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 17/05/2026 10:50 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50197040	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Defect Number: 42206631	Feature Type: Road Asset
Enquiry No.: 2148294 Service: Roads General Desc.: Location: Near holy corner	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 17/05/2026 10:47 Classification: Request for service Contact:
Enquiry No.: 2148293 Service: Roads General Desc.: Location: At bus stop	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 17/05/2026 10:43 Classification: Request for service Contact:
Enquiry No.: 2141061 Service: Roads General Desc.: Location: East side of Morningside Road at junction with Church Hill. Road surface leading to bus stop is giving way with potholes forming	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 03/05/2026 14:49 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50195622	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Defect Number: 42204473	Feature Type: Road Asset
Enquiry No.: 2135319 Service: Roads General Desc.: What type of sign is it? Road sign problem, type dontknow Street sign , hanging off building above shops at 342 morningside road, Edinburgh , concerned it might fall off Location: It needs removed or replaced	Logged by: Verint CRM Connector Subject: Traffic Sign:Defective/Damaged	on: 23/04/2026 08:58 Classification: Request for service Contact:
Enquiry No.: 2133514 Service: Roads General Desc.: Location: Amount of traffic turning onto Falcon Ave corner beside Waitrose has slowly degraded the surface. Pothole damage now presents a danger to pedestrians and cyclists and may lead to a serious accident. 5, Falcon Avenue, Church Hill, Morningside, City of Edinburgh, Alba / Scotland, EH10 4AJ,	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 20/04/2026 10:49 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50195622	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Defect Number: 42204473	Feature Type: Road Asset
Enquiry No.: 2131513 Service: Roads General Desc.: Location: Approaching the traffic lights on Morningside Road from the north (junction with Cluny Gardens). There is a pothole in the pink cycle section in from of the white line for the cars. It appears to be getting deeper.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 16/04/2026 08:06 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50195531	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Defect Number: 42204349	Feature Type: Road Asset

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2129414
Service: Roads General
Desc.:
Location: potholes where cars turning from church hill to morningside road, in front of Gratitude and Rettie

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 12/04/2026 16:28
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2129413
Service: Roads General
Desc.:
Location: potholes where cars turning from church hill to morningside road, in front of Gratitude and Rettie

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 12/04/2026 16:27
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2118503
Service: Roads General
Desc.: please can the light extender please now be picked up. It has been left at the side of the road No longer required as scaffolding remove.
Location: Outside Word of mouth restaurant

Logged by: 
Subject: Roadworks: General Enquiry

on: 23/03/2026 19:13
Classification: General Enquiry

Contact:

Enquiry No.: 2118474
Service: Roads General
Desc.:
Location: Multiple potholes

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 23/03/2026 18:19
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Job Number: 50194552 **Defect Number:** 42202999

Enquiry No.: 2116095
Service: Roads General
Desc.:
Location: There is a number of uneven paving stones and slabs surrounding a raised metal square just before the pedestrian crossing. This is a dangerous hazard as there is an inch gap tripping hazard, which is hard to detect due to the various angles and colouration.

Logged by: Verint CRM Connector
Subject: Pavement: Damaged / Defective

on: 19/03/2026 15:02
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2115747
Service: Roads General
Desc.: please see 3 documents attached...there is no attribute to describe the attached
Location: please see 3 documents attached...there is no attribute to describe the attached

Logged by: 
Subject: Traffic Sign: General Enquiry

on: 19/03/2026 08:54
Classification: Request for service

Contact:

Enquiry No.: 2113357
Service: Roads General
Desc.:
Location: Reported to Cllr Munro as a trip hazard - Broken paving slab close to the kerb, outside the former post office at 265 Morningside Road

Logged by: Verint CRM Connector
Subject: Roadworks: Defect

on: 16/03/2026 09:54
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2112280 **Logged by:** Verint CRM Connector **on:** 13/03/2026 17:25
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Missing stopcock cover in pavement outside 53 Moningside Rd (see photo). Serious trip hazard. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2109438 **Logged by:** Verint CRM Connector **on:** 09/03/2026 17:29
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole next to 19 Morningside Road. On the opposite side of the road to Luca's. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset
Job Number: 50193766 **Defect Number:** 42201858

Enquiry No.: 2104661 **Logged by:** Verint CRM Connector **on:** 01/03/2026 21:14
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole next to Morningside medical centre, just before the bus stop **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2104621 **Logged by:** [REDACTED] **on:** 01/03/2026 19:20
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: 01.03.2026 – Twitter - @edinhelp
deep pothole repair failure at the bus stop on Morningside Road at the junction with Morningside Place/outside the medical centre.
Location: Morningside road junction to Morningside Place **Contact:**

Enquiry No.: 2104550 **Logged by:** Verint CRM Connector **on:** 01/03/2026 17:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: very deep pothole approaching the bus stop, where the buses pull over **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2103257 **Logged by:** Verint CRM Connector **on:** 26/02/2026 23:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: areas of cracking and crumbling surface with potholes, all the way up the road and through traffic lights at churchill **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2103255 **Logged by:** Verint CRM Connector **on:** 26/02/2026 23:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: big dips in road, sunken sections and cracking **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2101833 **Logged by:** Verint CRM Connector **on:** 25/02/2026 09:06
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Big pothole / depression at the bus stop. As a cyclist this is forcing me out into the traffic in a dangerous way and adding significant risk to the road. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2101831 **Logged by:** Verint CRM Connector **on:** 25/02/2026 09:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Massive pothole - I would estimate at 6 inches deep. As a cyclist this is very dangerous. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset
Job Number: 50193129 **Defect Number:** 42201016

Enquiry No.: 2100923 **Logged by:** Verint CRM Connector **on:** 23/02/2026 20:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole at junction going out of Edinburgh **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2100922 **Logged by:** Verint CRM Connector **on:** 23/02/2026 20:37
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: big pothole just down from Marks & Spencer going down hill **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2100199 **Logged by:** Verint CRM Connector **on:** 22/02/2026 22:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Big pothole at bus stop **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2098036 **Logged by:** Verint CRM Connector **on:** 18/02/2026 18:05
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes by 47-49 Morningside Road, EH10 4AZ **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset
Job Number: 50192398 **Defect Number:** 42200064

Enquiry No.: 2096016 **Logged by:** Verint CRM Connector **on:** 16/02/2026 11:07
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: near the bus stop big holes being worn in the road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2095864	Logged by: 	on: 16/02/2026 08:39
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.: There is a loose paving slab outside Chest, Heart & Stroke/Pop Coffee. Many people have been tripping on it and this evening and elderly woman fell over it and bashed her head quite badly. An ambulance had to be called.		
Location:	Contact:	
Plot Number: 1.00	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road	Feature Type: Road Asset
Job Number: 50192442	Defect Number: 42200109	
Enquiry No.: 2094794	Logged by: Verint CRM Connector	on: 13/02/2026 19:42
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Potholes by 16 Morningside Rd, Edinburgh EH10 4DB (opposite S Luca - Ice cream shop).		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road	Feature Type: Road Asset
Enquiry No.: 2093013	Logged by: Verint CRM Connector	on: 11/02/2026 17:53
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: It's a big pothole right at the bus stop at Churchill. It's been making people get splashed at the bus stop for weeks! Most recently me getting soaked by a car driving through it really fast.		Contact:
Hopefully someone can come out and have a look!		
Plot Number: 1.00	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road	Feature Type: Road Asset
Enquiry No.: 2066427	Logged by: Verint CRM Connector	on: 30/12/2025 15:01
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: The pavement slabs around the corner of maxwell Street from Bennetts Bar around the corner of the pizza shop are in a dangerous state. Just seen someone trip over them		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road	Feature Type: Road Asset
Job Number: 50189166	Defect Number: 42212326	
Enquiry No.: 2059391	Logged by: Verint CRM Connector	on: 16/12/2025 13:05
Service: Roads General	Subject: Pavement: Damaged / Defective	Classification: Request for service
Desc.:		
Location: Metal box outside Cook shop has been hit and leaning at an angle		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road	Feature Type: Road Asset
Enquiry No.: 2058224	Logged by: Verint CRM Connector	on: 14/12/2025 11:28
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.:		
Location: Pothole at South west corner of the box junction at Holy corner on northbound carriageway		Contact:
Plot Number: 1.00	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road	Feature Type: Road Asset
Job Number: 50188690	Defect Number: 42195512	

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2045891 Service: Roads General Desc.: Location: Large pothole in bus stop. Northbound carriageway	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 19/11/2025 22:35 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road	Feature Type: Road Asset
Enquiry No.: 2045130 Service: Roads General Desc.: Location: Loose and aging slab outside 77 Morningside Road'Six Acres'	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 18/11/2025 15:21 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50187249	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Defect Number: 42193619	Feature Type: Road Asset
Enquiry No.: 2044834 Service: Roads General Desc.: Location: Collapsed pavement creating a hazard to pedestrians outside 398 Morningside Road.	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 18/11/2025 09:37 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road	Feature Type: Road Asset
Enquiry No.: 2044177 Service: Roads General Desc.: Bus stop at Morningside Medical Practice has huge pothole (presumably caused by bus wheel) Location:	Logged by:  Subject: Road: Defective / Damaged	on: 17/11/2025 08:36 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50187096	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Defect Number: 42193439	Feature Type: Road Asset
Enquiry No.: 2043884 Service: Roads General Desc.: Location: Just outside front door of 398, broken paving collapsed down leaving a 4-6in deep hole. Utilities covers nearby & looks as if just a void underneath	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 16/11/2025 12:28 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50187103	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Defect Number: 42193453	Feature Type: Road Asset
Enquiry No.: 2043583 Service: Roads General Desc.: Location: Very deep pothole in the road. Just before the bus stop, opposite Bethany charity shop. Layer beneath the tarmac is exposed.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 15/11/2025 12:57 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road	Feature Type: Road Asset
Enquiry No.: 2043481 Service: Roads General Desc.: Location: Enormous pothole at the bus stop	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 15/11/2025 09:36 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road	Feature Type: Road Asset

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2043393
Service: Roads General
Desc.:

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged
Classification: Request for service

on: 14/11/2025 20:23

Location: Right as you pull up to the bus stop. These potholes cause bus users to be thrust around right as you approach the bus stop which is incredibly unsafe. I have personally seen elderly users of the bus being knocked off balance due to these potholes, it is only a matter of time before someone is injured as a result of this.

Contact:

Plot Number: 1.00
Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road
Feature Type: Road Asset

Enquiry No.: 2043357
Service: Roads General
Desc.:

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged
Classification: Request for service

on: 14/11/2025 18:08

Location: Pothole

Contact:

Plot Number: 1.00
Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road
Feature Type: Road Asset

Enquiry No.: 2043247
Service: Roads General
Desc.:

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged
Classification: Request for service

on: 14/11/2025 14:32

Location: Large pothole at Morningside place bus stop
City bound

Contact:

Enquiry No.: 2040306
Service: Roads General
Desc.:

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged
Classification: Request for service

on: 09/11/2025 13:18

Location: Holy corner bus stop city bound

Contact:

Enquiry No.: 2034277
Service: Roads General
Desc.:

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged
Classification: Request for service

on: 28/10/2025 10:07

Location: The pedestrian crossing at Church Hill is not working - so the traffic is constant - had to help a lady with a pram across the road. Also a lot of old people in the area

Contact:

Plot Number: 1.00
Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road
Feature Type: Road Asset

Enquiry No.: 2023784
Service: Roads General
Desc.:

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged
Classification: Request for service

on: 05/10/2025 11:05

Location: Large pothole at the bus stop on Northbound carriageway outside The Morningside Medical Centre.

Contact:

Plot Number: 1.00
Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road
Feature Type: Road Asset

Job Number: 50185213
Defect Number: 42190599

Enquiry No.: 2023563
Service: Roads General
Desc.: Problem: Other.

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect
Classification: Request for service

on: 04/10/2025 14:40

Location:Footpath.
Type:Foliage / Bush

Location: At Morningside Station

Contact:

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 2021984 **Logged by:** Verint CRM Connector **on:** 01/10/2025 12:32
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Across the road from the Church Hill theatre, at the bus stop, a series of pot holes **Contact:**

Enquiry No.: 2021097 **Logged by:** Verint CRM Connector **on:** 29/09/2025 18:42
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole on west side of Morningside Road just before bus stop at Morningside Medical Centre. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2019004 **Logged by:** Verint CRM Connector **on:** 25/09/2025 08:35
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep pothole by the bus stop, danger to cyclists **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Job Number: 50185110 **Defect Number:** 42190453

Enquiry No.: 2015507 **Logged by:** Verint CRM Connector **on:** 17/09/2025 14:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There is a large pothole by the bus stop at this location. A danger to cyclists and buses dip down into it when stopping. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2012368 **Logged by:** Verint CRM Connector **on:** 11/09/2025 10:04
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Uneven and broken paving around 370 Morningside Rd and needs replacing. Why is is that a whole block in Bruntsfield was replaced but a lot of paving in Morningside is shocking. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2008900 **Logged by:** Verint CRM Connector **on:** 04/09/2025 11:03
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole at the bus stop at Morningside Road next to Vivio electronics (next to Kudos Bridal). **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 2003030 **Logged by:** Verint CRM Connector **on:** 25/08/2025 16:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole in the loading bay next to the church **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1997542 **Logged by:** Verint CRM Connector **on:** 16/08/2025 12:11
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole in the centre of the road, opposite the Eric Liddell centre. It is at the start of the yellow box as you drive up Morningside Road in the direction of the city centre. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 1985835 **Logged by:** Verint CRM Connector **on:** 27/07/2025 10:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Road next to bus stop is collapsing **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 1985805 **Logged by:** Verint CRM Connector **on:** 27/07/2025 09:29
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Pavement very uneven. Blocks are broken. Trip hazard Close to Sainsbury's **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Job Number: 50183155 **Defect Number:** 42212327

Enquiry No.: 1984482 **Logged by:** Verint CRM Connector **on:** 24/07/2025 11:20
Service: Roads General **Subject:** Pavement: Missing Slab / Kerb **Classification:** Customer Emergency
Desc.:
Location: There is a gap between the pavement slabs and a manhole cover just beyond Waitrose, on the right side of the pavement walking south. It's situated opposite the charity shop (something 'Hope'). I know this is a considerable gap as I fell because of it. I suffered multiple pains at the time (late afternoon on Monday 14th July 2025.) Unfortunately due to an early flight on Tuesday 15 July, I had no time to revisit for photos nor see the doctor. I will be following this up on my return. **Contact:**

Enquiry No.: 1976871 **Logged by:** Verint CRM Connector **on:** 11/07/2025 17:56
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Issue is directly outside "houseproud of morningsie" Pavement next to road (including kerb) has a significant hole in it, maybe about a quarter of a paving slab in area and 3 to 6 inches deep **Contact:**

Enquiry No.: 1970116 **Logged by:** Verint CRM Connector **on:** 27/06/2025 18:26
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type unlit A piece missing, also spray painted, also ancient and faded.
Location: **Contact:**

Enquiry No.: 1963772 **Logged by:** Verint CRM Connector **on:** 15/06/2025 11:48
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type unlit Carlisle/Peebles green sign - Half the sign has fallen off and is missing and the rest is badly deteriorated.
Location: Carlisle/Peebles green sign - Half the sign has fallen off and is missing and the rest is badly deteriorated. **Contact:**

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1953897 Logged by: Verint CRM Connector on: 27/05/2025 09:31
Service: Roads General Subject: Traffic Sign:Defective/Damaged Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type unlit Can I highlight rusted poles on traffic lights on Morningside Road. This is outside Oxfam 210 Morningside Rd, Edinburgh EH10 4QQ.
Location: Hi, Contact:

Can I highlight rusted poles on traffic lights on Morningside Road. This is outside Oxfam 210 Morningside Rd, Edinburgh EH10 4QQ.

Thanks,



Enquiry No.: 1953726 Logged by: Verint CRM Connector on: 26/05/2025 20:04
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
Desc.:
Location: Damage to pavement and curbstones outside Houseproud of Morningside 169 Morningside Road. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Feature Type: Road Asset
Job Number: 50180442 Defect Number: 42212365

Enquiry No.: 1953724 Logged by: Verint CRM Connector on: 26/05/2025 20:00
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Pothole and cracked road surface developing around a utility cover. This is at start of Morningside Road near to Eric Liddell Centre. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Feature Type: Road Asset
Job Number: 50180461 Defect Number: 42184412

Enquiry No.: 1953688 Logged by: Verint CRM Connector on: 26/05/2025 18:45
Service: Roads General Subject: Traffic Sign:Defective/Damaged Classification: Request for service
Desc.: What type of sign is it? Road sign problem, type unlit Pole with no sign on it. This is on Morningside Road at junction with Maxwell Street outside Neapolitan Pizza.

Location: Pole with no sign on it. This is on Morningside Road at junction with Maxwell Street outside Neapolitan Pizza. Contact:

Been missing since at least 2023.

Plot Number: 1.00 Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Feature Type: Road Asset
Job Number: 50180388 Defect Number: 42186528

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1953675 **Logged by:** Verint CRM Connector **on:** 26/05/2025 18:22
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type unlit Royal Edinburgh Direction Sign on Morningside Road at Morningside Park (Outside Holland and Barrett) needs straightened/secured on pole. Its pointing down and not straight.
Location: Royal Edinburgh Direction Sign on Morningside Road at Morningside Park (Outside Holland and Barrett) needs straightened/secured on pole. Its pointing down and not straight. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset
Job Number: 50180382 **Defect Number:** 42186526

Enquiry No.: 1953162 **Logged by:** Verint CRM Connector **on:** 25/05/2025 18:16
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Where the manhole cover is there is a chunk of pavement missing. An older man fell and injured himself on the unsafe pavement. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 1942371 **Logged by:** Verint CRM Connector **on:** 02/05/2025 14:02
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: pothole around here **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 1941497 **Logged by:** Verint CRM Connector **on:** 01/05/2025 09:29
Service: Roads General **Subject:** Road: Missing Setts / Blocks **Classification:** Customer Emergency
Desc.:
Location: Morningside Road as I attempted to cross there was an obstruction Ballard type thing that tapers. I tripped over this and fell heavily on my right knee also hurting my elbow. I spoke to Dr Blackwood who referred me to physio. Bursitis or diagnosed.

This was witnessed by two people in the car who saw me fall as they stopped at the lights and the lady came out to help me. The car behind me stopped thankfully.
This accident happened on the 13th of April 2025 at approximately 1 pm. **Contact:**

Enquiry No.: 1923065 **Logged by:** Verint CRM Connector **on:** 24/03/2025 18:28
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There is a large rectangular piece of tarmac stretching across the width of Morningside Road near the junctions with Jordan lane and Millar crescent that is loose and is gradually sinking. It needs attention before it gets worse! **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset
Job Number: 50177624 **Defect Number:** 42179821

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1908738 Service: Roads General Desc.: Location: Deep pothole on west side of Morningside Road just before the bus shelter.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 24/02/2025 14:30 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50176019	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Defect Number: 42177248	Feature Type: Road Asset
Enquiry No.: 1906139 Service: Roads General Desc.: Problem: Causing Obstruction. Location:Park. Type:Foliage / Bush Location: Significant tree branches (2) broke during storm Herminia from the north most tree in the park opposite Hermitage Terrace. They are hanging from the tree and could be a risk to the park users.	Logged by: Verint CRM Connector Subject: Trees & Foliage: Defect	on: 19/02/2025 16:50 Classification: Request for service Contact:
Enquiry No.: 1903950 Service: Roads General Desc.: Location: Pothole right beside pedestrian crossing, fills up with rainwater and soaks pedestrians.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 15/02/2025 11:05 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50175356	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Defect Number: 42176331	Feature Type: Road Asset
Enquiry No.: 1902651 Service: Roads General Desc.: Location: Once again a deep pothole has formed close to bus shelter outside morningside medical centre.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 12/02/2025 15:04 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50175023	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Defect Number: 42175895	Feature Type: Road Asset
Enquiry No.: 1898642 Service: Roads General Desc.: Location: Pothole on road city bound outside number 16	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 04/02/2025 17:04 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50174446	Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Defect Number: 42175174	Feature Type: Road Asset
Enquiry No.: 1895420 Service: Roads General Desc.: Problem: Other. Location:Verge / Grass area . Type:Foliage / Bush Location: See above	Logged by: Verint CRM Connector Subject: Trees & Foliage: Defect	on: 29/01/2025 21:41 Classification: Request for service Contact:

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1891094 **Logged by:** Verint CRM Connector **on:** 22/01/2025 20:55
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Morningside Road close to bus shelter outside Foot clinic.
Road surface is sinking down badly from junction with Church Hill **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 1890880 **Logged by:** Verint CRM Connector **on:** 22/01/2025 14:43
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Immediately outside the main door of 398, is a manhole cover. The cement surround
has crumble into big chunks, exposing an unsafe hole into manhole . Have already
seen a few people turn ankles in it. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset
Job Number: 50173494 **Defect Number:** 42173905

Enquiry No.: 1882308 **Logged by:** Verint CRM Connector **on:** 07/01/2025 17:48
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Corner of Church Hill and Morningside Rad
Road surface on Morningside Road eastern side heading south is very uneven and
looks as if it is giving way, especially as buses go over it.
Surface from corner to the bus shelter needs looking at **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset
Job Number: 50172720 **Defect Number:** 42172847

Enquiry No.: 1880561 **Logged by:** Verint CRM Connector **on:** 06/01/2025 07:32
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type dontknow
Location: Bus tracker information incorrect. Has been for last month. Morningside station
tracker. **Contact:**

Enquiry No.: 1873842 **Logged by:** Verint CRM Connector **on:** 20/12/2024 18:16
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: On Morningside Road just north of junction with Jordan Lane, there is a large piece
of tarmac in the middle of the road that looks as if it is starting to give way **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 1870460 **Logged by:** Verint CRM Connector **on:** 12/12/2024 15:36
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: There is water leaking from the pavement into our basement. The address is The
Open Door, 420 Morningside Road, EH10 5HY Email
[REDACTED] **Contact:**

It was spotted by my cleaner the evening of the torrential storm, Friday 6 December.

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1867591 **Logged by:** Verint CRM Connector **on:** 05/12/2024 14:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Morningside road just before the bus stop outside Morningside Health centre.
Pothole forming and pieces of tarmac are being thrown onto the pavement **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset
Job Number: 50171016 **Defect Number:** 42170727

Enquiry No.: 1867058 **Logged by:** Verint CRM Connector **on:** 04/12/2024 11:22
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: sunken iron work drian here near curb and bus shelter heading into town **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset
Job Number: 50170768 **Defect Number:** 42170390

Enquiry No.: 1846032 **Logged by:** Verint CRM Connector **on:** 17/10/2024 19:55
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep pothole on west side of Morningside Road close to bus stop near Waitrose **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset
Job Number: 50168260 **Defect Number:** 42167040

Enquiry No.: 1839389 **Logged by:** Verint CRM Connector **on:** 02/10/2024 14:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Temp tarmac repair and road sinking. New pothole starting to appear at bus stop **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 1839178 **Logged by:** Verint CRM Connector **on:** 02/10/2024 09:06
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large and deep pothole in the middle of the south bound side of Morningside Road. **Contact:**
This was repaired quickly after I last reported it, but the defect returned within 24
hours and is now back to its original state. This is dangerous for drivers and
pedestrians due to its size, depth and position.

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset
Job Number: 50167418 **Defect Number:** 42165856

Enquiry No.: 1838758 **Logged by:** Verint CRM Connector **on:** 01/10/2024 11:06
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole starting to form outside 49/51 Morningside Road on south bound side near **Contact:**
bus stop. Large area of tarmac starting to sink

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1830406 **Logged by:** Verint CRM Connector **on:** 11/09/2024 13:32
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Outside the bus stop **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 1829940 **Logged by:** Verint CRM Connector **on:** 10/09/2024 17:39
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: A sinkhole apperad at the bus stop in this location a couple of days ago. It has been filled with tarmac and has already developed into a worse sink hole than before. This needs investigated properly not just patched with tarmac. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 1829752 **Logged by:** Verint CRM Connector **on:** 10/09/2024 11:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Dangerous Large deep pothole. Approx 60cm x 60cm. **Contact:**
Next to bus stop

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 1829113 **Logged by:** Verint CRM Connector **on:** 09/09/2024 08:28
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Deep pothole
Location: Deep pothole / dip in surface, about 50cm diameter and 30cm deep. By junct with Abbotsord Park - southbound **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Ward 10 - From Colinton Road to Comiston Road **Feature Type:** Road Asset

Enquiry No.: 1828972 **Logged by:** Verint CRM Connector **on:** 08/09/2024 17:12
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Park.
Type:Foliage / Bush
Location: Major branch failure on a large tree in this tree and grassed area which is managed by the council. **Contact:**

Enquiry No.: 1824401 **Logged by:** Verint CRM Connector **on:** 29/08/2024 18:01
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Other.
Location:Verge / Grass area .
Type:Foliage / Bush
Location: See above **Contact:**

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Customer Services

Enquiry No.: 1816815 Logged by: Verint CRM Connector on: 15/08/2024 16:03
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
Desc.:
Location: Hi there. Contact:

The pavement is terrible generally on Morningside road with loose slaps and large lips which are a trip hazard. Last week were were in Alaburrito and had to run out to attend to an elderly couple who both feel after tripping. We drove them to A&E.

This afternoon my [redacted] so another [redacted] trip and hit [redacted] head at the same spot.

You absolutely need to repave this entire pavement on Morningside road. Many old people use it. Very dangerous. I have video.

Plot Number: 1.00 Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Feature Type: Road Asset
Job Number: 50165431 Defect Number: 42163735

Enquiry No.: 1808142 Logged by: Verint CRM Connector on: 30/07/2024 16:03
Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
Desc.:
Location: Pothole in second left, just before junction at Holy Corner, opposite entrance to Luca's. Direction is heading in to city. Contact:

Plot Number: 1.00 Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Feature Type: Road Asset
Job Number: 50164776 Defect Number: 42162874

Enquiry No.: 1808066 Logged by: Verint CRM Connector on: 30/07/2024 14:24
Service: Roads General Subject: Pavement: Damaged / Defective Classification: Request for service
Desc.:
Location: the "slope" outside Churchill theatre is very uneven and causing hazards to pedestrian Contact:

Plot Number: 1.00 Feature Id - Location: Ward 10 - From Colinton Road to Comiston Road Feature Type: Road Asset
Job Number: 50164780 Defect Number: 42162879

Enquiry No.: 1803940 Logged by: Verint CRM Connector on: 23/07/2024 19:28
Service: Roads General Subject: Trees & Foliage: Defect Classification: Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Bush overhanging pavement opposite Waitrose store. Partially sighted person is not expecting to walk into a bush at this place. Contact:

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road		Feature Type: Road Asset		Area: South East Locality	
50164717	3 no rocking slabs 2no 300 x 300 pcc slabs 1no cut 300 x 300 pcc slab (RD: FW Slabs Rocking)	Outside old school house	RD: Cat 3 - 60 Day	Job Complete	30/07/2024	31/07/2024	Act. ROAD/82095255

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road		Feature Type: Road Asset		Area: South East Locality	
50164720	2 no rocking slabs (RD: FW Slabs Rocking)	Outside specsavers shop	RD: Cat 3 - 60 Day	Job Complete	30/07/2024	31/07/2024	Act. ROAD/82095256
50164776	Cw x1 pothole Road: Defective / Damaged (Enquiry 1808142) (RD: CW Pothole)	Outside of luca, s (city bound)	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/07/2024	01/08/2024	Act. ROAD/82095280
50164780	Grano patch reinstated , Pavement: Damaged / Defective (Enquiry 1808066) (RD: FW Grano Depression/Sunken)	Outside of Churchill Theatre	RD: Cat 3 - 60 Day	Job Complete	31/07/2024	14/08/2024	Act. ROAD/82095283
50165431	1no 900x600x63 pcc slab , 3 no small elements loose and rocking/ Pavement: Damaged / Defective (Enquiry 1816815) (RD: FW Slabs Broken/Missing)	Outside of 352	RD: Cat 3 - 60 Day	Job Complete	16/08/2024	21/08/2024	Act. ROAD/82095677
50166292	1no pothole (RD: CW Pothole)	At the bus stop outside no59	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	09/09/2024	10/09/2024	Act. ROAD/82096158
50166361	Cw x1 pothole (RD: CW Pothole)	Outside of 59	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	11/09/2024	12/09/2024	Act. ROAD/82096193
50166760	Miising granite infill Approx 1.5m x 300mm (RD: FW Grano Cracked/Broken)	Outside church hill theatre	RD: Cat 3 - 60 Day	Job Complete	19/09/2024	23/09/2024	Act. ROAD/82096385
50167418	Cw x1 pothole Road: Defective / Damaged (Enquiry 1839178) (RD: CW Pothole)	Southbound bus stop opposite Abbotsford Road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/10/2024	03/10/2024	Act. ROAD/82096882
50168260	Cw x1 pothole Road: Defective / Damaged (Enquiry 1846032) (RD: CW Pothole)	Bus stop outside of Medical centre	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/10/2024	21/10/2024	Act. ROAD/82097419
50168378	Relay 1 rocking tactile (RD: FW Slabs Rocking)	At junction with steels place	RD: Cat 3 - 60 Day	Job Complete	21/10/2024	22/10/2024	Act. ROAD/82097524
50168489	1no fw grano pothole (RD: FW Grano Pothole)	At pedestrian crossing opposite the bank of Scotland	RD: Cat 3 - 60 Day	Job Complete	22/10/2024	24/10/2024	Act. ROAD/82097606
50168491	1no fw pothole (RD: FW HRA Pothole)	At bus stop opposite boots	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/10/2024	23/10/2024	Act. ROAD/82097608
50168492	1no rocking cut pcc slab (RD: FW Slabs Rocking)	Outside Bethany charity shop next to mono blocks	RD: Cat 3 - 60 Day	Job Complete	22/10/2024	23/10/2024	Act. ROAD/82097609
50168493	1no rocking 600 z 600 pcc slab (RD: FW Slabs Rocking)	Outside British Red Cross shop	RD: Cat 3 - 60 Day	Job Complete	22/10/2024	23/10/2024	Act. ROAD/82097610
50168494	1no broken cut pcc slab (RD: FW Slabs Broken/Missing)	Outside toys galore shop at telecom box	RD: Cat 3 - 60 Day	Job Complete	22/10/2024	24/10/2024	Act. ROAD/82097611
50168495	1no rocking 450 x 350 pcc slab (RD: FW Slabs Rocking)	Outside first class barbers	RD: Cat 3 - 60 Day	Job Complete	22/10/2024	23/10/2024	Act. ROAD/82097612
50168496	1no rocking cross cut 900 x600 pcc slab (RD: FW Slabs Rocking)	Pedestrian crossing outside jardine Phillips estate agent	RD: Cat 3 - 60 Day	Job Complete	22/10/2024	24/10/2024	Act. ROAD/82097613
50168497	1no broken 450 x 600 pcc slab (RD: FW Slabs Broken/Missing)	Opposite watt terrace cafe	RD: Cat 3 - 60 Day	Job Complete	22/10/2024	24/10/2024	Act. ROAD/82097614

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road		Feature Type: Road Asset		Area: South East Locality	
50168498	3no broken cut buff tactile slabs (RD: FW Slabs Broken/Missing)	At pedestrian crossing with cluny avenue next to bus stop	RD: Cat 3 - 60 Day	Job Complete	22/10/2024	29/10/2024	Act. ROAD/82097615
50170768	1 no pothole (RD: CW Pothole)	Outside no 64 at bus stop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/12/2024	05/12/2024	Act. ROAD/82099093
50171016	1 no pothole (RD: CW Pothole)	Opposite the Bethany shop at bustop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/12/2024	09/12/2024	Act. ROAD/82099287
50172097	No 1 pothole (RD: CW Pothole)	At bustop at active feet shop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/01/2025	06/01/2025	Act. ROAD/82100135
50172459	1no pothole (RD: CW Pothole)	At the bus stop outside no59	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/01/2025	13/01/2025	Act. ROAD/82100435
50172720	No 2 potholes (RD: CW Pothole)	Corner of Church Hill and Morningside road opposite body smart	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/01/2025	17/01/2025	Act. ROAD/82100649
50173008	3no broken 450 x 600 pcc slab 2no broken 450 x 300 pcc slabs (RD: FW Slabs Broken/Missing)	Outside no394 Mia Italian kitchen	RD: Cat 3 - 60 Day	Job Complete	16/01/2025	20/01/2025	Act. ROAD/82100870
50173009	1no broken 900 x 600 pcc slab 1no grano infill at manhole on fw (RD: FW Slabs Rocking)	Outside matti pizza restaurant	RD: Cat 3 - 60 Day	Job Complete	16/01/2025	20/01/2025	Act. ROAD/82100871
50173010	1no pole stump in middle of fw please cut away / make safe and infill with grano (RD: FW Grano Pothole)	Opposite cafe blush at junction with mirningside park	RD: Cat 3 - 60 Day	Job Complete	16/01/2025	20/01/2025	Act. ROAD/82100872
50173017	1no damaged / missing section of whin kerb Infill with grano (RD: FW Kerbs Damaged/Missing)	Outside no19 opposite luca ice cream shop	RD: Cat 3 - 60 Day	Job Complete	16/01/2025	20/01/2025	Act. ROAD/82100878
50173282	1no pothole (RD: CW Pothole)	At the bus stop opposite the Bethany Shop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/01/2025	22/01/2025	Act. ROAD/82101057
50173494	3 rocking 600x 450 grey slabs ...3 broken half 600x450 slabs2 rocking half 600x450 slabs.... And granite broken around manhole (RD: FW Slabs Rocking)	Outside. House no 398 next to Greggs going into town	RD: Cat 2 - 5 Day	Job Complete	23/01/2025	29/01/2025	Act. ROAD/82101211
50173497	1 rocking 600x450 slab (RD: FW Slabs Rocking)	Outside no 388 nxt to save the children shop going into town	RD: Cat 3 - 60 Day	Job Complete	23/01/2025	27/01/2025	Act. ROAD/82101213
50174446	No 1 pothole (RD: CW Pothole)	outside number 16 Lucas ice cream shop middle of carriage way	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2025	10/02/2025	Act. ROAD/82101939
50174447	1 rocking 900x600 grey slab and 1 sunken broken 900x600 slab (RD: FW Slabs Rocking)	Outside entrance to Lucas ice cream shop	RD: Cat 2 - 5 Day	Job Complete	06/02/2025	10/02/2025	Act. ROAD/82101940
50174450	2 no potholes (RD: CW Pothole)	Outside no 32 nxt to post office CW	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2025	10/02/2025	Act. ROAD/82101943

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road		Feature Type: Road Asset		Area: South East Locality	
50175023	No 1 pothole (RD: CW Pothole)	At morningside bustop at morningside medical practice	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/02/2025	14/02/2025	Act. ROAD/82102446
50175356	2 no potholes (RD: CW Pothole)	Outside morning side gallery at traffic lights at kerbside one in middle of road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/02/2025	19/02/2025	Act. ROAD/82102684
50175772	Sign pole been hit n pushed up slabs at base so needs straightened n slabs replaced (RD: FW Slabs Broken/Missing)	Outside Costa coffe	RD: Cat 3 - 60 Day	Job Complete	24/02/2025	27/02/2025	Act. ROAD/82103074
50176019	No1 pothole (RD: CW Pothole)	At bustop opposite church hill theartre	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/02/2025	27/02/2025	Act. ROAD/82103276
50176902	1no rocking 450 x 600 pcc slab (RD: FW Slabs Rocking)	Outside Pizza Hut	RD: Cat 3 - 60 Day	Job Complete	13/03/2025	14/03/2025	Act. ROAD/82103989
50176907	1no rocking 450 x 600 pcc slab (RD: FW Slabs Rocking)	Outside paper tiger shop	RD: Cat 3 - 60 Day	Job Complete	13/03/2025	14/03/2025	Act. ROAD/82103993
50177624	Sunken track no1 pothole (RD: CW Pothole)	Heading into town .outside TECHFIXD at traffic lights near no 332	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/03/2025	27/03/2025	Act. ROAD/82104472
50177987	2no rocking cut pcc slabs (RD: FW Slabs Rocking)	Outside artisan bakery on fw at kerb edge	RD: Cat 3 - 60 Day	Job Complete	01/04/2025	02/04/2025	Act. ROAD/82104717
50177988	1no broken 300 x 300 pcc slab 8no rocking 300 x 300 and cut pcc slabs (RD: FW Slabs Broken/Missing)	On fw outside no32 and chest heart and strike charity shop	RD: Cat 3 - 60 Day	Job Complete	01/04/2025	02/04/2025	Act. ROAD/82104718
50177996	1no broken cut pcc slab (RD: FW Slabs Broken/Missing)	Opposite cancer research shop On corner with Morningside place next to tactiles	RD: Cat 2 - 5 Day	Job Complete	01/04/2025	02/04/2025	Act. ROAD/82104722
50177998	1no broken 450 x 600 pcc slab 2no rocking pcc slabs (RD: FW Slabs Broken/Missing)	Outside no128 the Gurkha restaurant	RD: Cat 3 - 60 Day	Job Complete	01/04/2025	02/04/2025	Act. ROAD/82104724
50178001	2no sunken cut pcc slabs need raised 1no open grano joint at box (RD: FW Slabs Rocking)	Outside no20 the source clinic	RD: Cat 2 - 5 Day	Job Complete	01/04/2025	02/04/2025	Act. ROAD/82104726
50178002	1no broken 450 x 600 pcc slab (RD: FW Slabs Broken/Missing)	Outside no20 the source clinic	RD: Cat 4 - Programmed	Job Complete	01/04/2025	24/09/2025	Act. ROAD/82109170
50178003	1no rocking 600 x 600 pcc slab (RD: FW Slabs Rocking)	Outside British Red Cross charity shop	RD: Cat 3 - 60 Day	Job Complete	01/04/2025	03/04/2025	Act. ROAD/82104727
50178006	1no hole where pole has been cut away please flatten edges of pole and infill with grano (RD: FW Grano Pothole)	Outside no257 picture framer shop	RD: Cat 3 - 60 Day	Job Complete	01/04/2025	02/04/2025	Act. ROAD/82104728
50180382	Straighten signs and replace signs brackets (RD: Unlit Sign Damaged/Missing)	Royal Edinburgh Direction Sign on Morningside Road at junction with Morningside park	RD: Cat 3 - 60 Day	Job Complete	27/05/2025	29/07/2025	Act. ROAD/82106358

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road		Feature Type: Road Asset		Area: South East Locality	
50180388	Place No Through road sign on signs pole , signs diagram no 816, sign size 400mm x 400mm Pickup sign from Bankhead depot stores (RD: Unlit Sign Damaged/Missing)	Missing No through road sign On east footway at junction with Maxwell street	RD: Cat 3 - 60 Day	Job Complete	27/05/2025	12/08/2025	Act. ROAD/82106362
50180442	2 Whin kerb needs lifted and grano patch taken out and re slabbed 6 /7 roughly as cuts will be needed 450x 600 grey slabs (RD: FW Kerb Dislodged/Rocking)	Outside home hardware 169 Morningside Road.	RD: Cat 3 - 60 Day	Job Committed	27/05/2025	24/04/2026	Est. ROAD/82106380
50180461	No1 pothole around fire hydrant) (RD: CW Pothole)	Outside entrance to Eric Liddell Centre. At traffic lights	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/05/2025	27/05/2025	Act. ROAD/82106395
50182332	1no missing Grano area at box (RD: FW Grano Open Joint)	Outside Luca ice cream shop	RD: Cat 3 - 60 Day	Job Complete	04/07/2025	09/07/2025	Act. ROAD/82107559
50182334	1no missing Grano area at box 1no rocking 300 x 300 pcc slab (RD: FW Grano Open Joint)	Outside old school house next to cuddy lane	RD: Cat 3 - 60 Day	Job Complete	04/07/2025	09/07/2025	Act. ROAD/82107560
50182338	1no missing Grano area at gas Toby (RD: FW Grano Open Joint)	Outside no160	RD: Cat 3 - 60 Day	Job Complete	04/07/2025	09/07/2025	Act. ROAD/82107562
50182339	Broken Grano at box on fw (RD: FW Grano Cracked/Broken)	Outside no408	RD: Cat 2 - 5 Day	Job Complete	04/07/2025	07/07/2025	Act. ROAD/82107563
50182347	1no broken 450 x 600 pcc slab (RD: FW Slabs Broken/Missing)	Outside food for u shop	RD: Cat 3 - 60 Day	Job Complete	04/07/2025	09/07/2025	Act. ROAD/82107569
50182349	1no Fw pothole (RD: FW HRA Pothole)	At vehicle exit at church hill theatre	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	04/07/2025	07/07/2025	Act. ROAD/82107570
50182350	Broken Grano track on crossing approx 1m x 0.2m (RD: FW Grano Cracked/Broken)	At vehicle entrance into church hill theatre	RD: Cat 3 - 60 Day	Job Complete	04/07/2025	09/07/2025	Act. ROAD/82107571
50185110	No 1 pothole (RD: CW Pothole)	Opposite Churchill theatre at bustop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/10/2025	03/10/2025	Act. ROAD/82109333
50185213	No 1 pothole (RD: CW Pothole)	outside The Morningside Medical Centre.on CW at bustop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/10/2025	07/10/2025	Act. ROAD/82109408
50185906	1no open joint surrounding water Toby (RD: FW Grano Open Joint)	Outside no144	RD: Cat 3 - 60 Day	Job Complete	22/10/2025	28/10/2025	Act. ROAD/82109852
50185908	1no broken cut pcc slab at catv box Remove and infill with grano (RD: FW Slabs Broken/Missing)	At junction with Abbotsford park Outside shelter Scotland charity shop	RD: Cat 3 - 60 Day	Job Complete	22/10/2025	28/10/2025	Act. ROAD/82109853
50185909	1no Cw pothole (RD: CW Pothole)	Outside church Next to Lucas ice cream shop in Loading bay	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/10/2025	23/10/2025	Act. ROAD/82109854
50185928	2no rocking pcc slabs (RD: FW Slabs Rocking)	Outside specsavers	RD: Cat 3 - 60 Day	Job Complete	22/10/2025	28/10/2025	Act. ROAD/82109863

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road		Feature Type: Road Asset		Area: South East Locality	
50185931	3no rocking pcc slabs (RD: FW Slabs Rocking)	Opposite la matinee shop	RD: Cat 3 - 60 Day	Job Complete	22/10/2025	28/10/2025	Act. ROAD/82109865
50185933	1no broken 450 x 300 pcc slab 1no rocking 450 x 300 pcc slab (RD: FW Slabs Broken/Missing)	Opposite bus stop at no 378	RD: Cat 3 - 60 Day	Job Complete	22/10/2025	05/11/2025	Act. ROAD/82109866
50187095	RD: CW Pothole	At bustop at no 64 morningside road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/11/2025	19/11/2025	Act. ROAD/82110586
50187096	No 1 pothole (RD: CW Pothole)	At bustop at morningside medical practice	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/11/2025	19/11/2025	Act. ROAD/82110587
50187103	Hole in the granite around utility cover possible subsidence under slabs nxt to the hole (RD: FW Grano Depression/Sunken)	Just outside front door of 398,nxt to Greggs	RD: Cat 3 - 60 Day	Job Complete	18/11/2025	24/11/2025	Act. ROAD/82110590
50187249	Rocking 2x 2 slab (RD: FW Slabs Rocking)	outside 77 Morningside Road'Six Acres'	RD: Cat 3 - 60 Day	Job Complete	20/11/2025	03/12/2025	Act. ROAD/82110720
50188331	1no pothole (RD: CW Pothole)	Outside no20	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/12/2025	15/12/2025	Act. ROAD/82111535
50188690	No 1 pothole (RD: CW Pothole)	at South west corner of the yellow grid box junction at Holy corner heading north into town	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/12/2025	19/12/2025	Act. ROAD/82111806
50188735	1no pothole (RD: CW Pothole)	At the bus stop outside Morningside Medical Practice	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/12/2025	22/12/2025	Act. ROAD/82111844
50189413	1no pothole (RD: CW Pothole)	At the bus stop opposite no408	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/01/2026	12/01/2026	Act. ROAD/82112420
50189896	1no Cw pothole (RD: CW Pothole)	At pedestrian crossing opposite bodysmart physio	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/01/2026	21/01/2026	Act. ROAD/82112800
50191336	1no pothole (RD: CW Pothole)	At the bus stop outside no59	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/02/2026	09/02/2026	Act. ROAD/82113977
50192398	No 2 potholes (RD: CW Pothole)	Outside no 86 masti Indian street food in yellow grid box	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	20/02/2026	01/03/2026	Act. ROAD/82114881
50192442	Rocking 900x600 slab at entrance to shop (RD: FW Slabs Rocking)	Outside pop cafe	RD: Cat 3 - 60 Day	Job Complete	20/02/2026	05/03/2026	Act. ROAD/82114922
50193129	No 1 pothole (RD: CW Pothole)	At bustop at no 2 morningside medical practice	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/03/2026	03/03/2026	Act. ROAD/82115504
50193535	1no pothole (RD: CW Pothole)	At the bus stop opposite no408	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/03/2026	09/03/2026	Act. ROAD/82115814
50193538	1no pothole (RD: CW Pothole)	Opposite no420	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/03/2026	09/03/2026	Act. ROAD/82115817
50193766	No 1 pothole (RD: CW Pothole)	Outside no 19!	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/03/2026	23/03/2026	Act. ROAD/82116000
50194169	Gully blocked not running 100% when raining flooding footpath (Gully: Blocked - HP Jet Req'd)	outside 386 Morningside	RG: Gully - Standard Priority	Job Complete	19/03/2026	13/05/2026	Act. RDGC14/82007657

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road		Feature Type: Road Asset		Area: South East Locality	
50194552	No 2 potholes (RD: CW Pothole)	Outside no 15 the Eric Liddell centre at crossing point	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/03/2026	26/03/2026	Act. ROAD/82116603
50195531	No 1 pothole (RD: CW Pothole)	Outside no 271 heading to comiston road in red cyclist box opposite the bank of Scotland	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/04/2026	20/04/2026	Act. ROAD/82117379
50195622	No 2 potholes (RD: CW Pothole)	At junction of falcon avenue and morningside road at crossing point	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/04/2026	21/04/2026	Act. ROAD/82117454
50195778	1no broken 350 x 450 pcc slab Remove and infill with cold tar (RD: FW Slabs Broken/Missing)	Outside no 263 vets / building site	RD: Cat 3 - 60 Day	Job Complete	23/04/2026	25/04/2026	Act. ROAD/82117556
50195788	low grano area at kerb / make safe (RD: FW HRA Pothole)	Outside home hardware shop	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/04/2026	23/04/2026	Act. ROAD/82117559
50195793	5no broken 750 x 600 pcc slabs 3no broken 600 x 600 pcc slabs 1no broken 450 x 600 pcc slab (RD: FW Slabs Broken/Missing)	Outside no33 opposite mail boxes etc	RD: Cat 3 - 60 Day	Job Complete	23/04/2026	28/04/2026	Act. ROAD/82117566
50195795	Broken grano surrounding double manhole (RD: FW Grano Cracked/Broken)	Outside Eric Liddell community centre	RD: Cat 3 - 60 Day	Job Complete	23/04/2026	25/04/2026	Act. ROAD/82117591
50195798	low grano area at utility box / make safe (RD: FW HRA Pothole)	Outside Luca ice cream	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/04/2026	23/04/2026	Act. ROAD/82117594
50195801	2no cw potholes (RD: CW Pothole)	At junction with church hill place Outside	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/04/2026	28/04/2026	Act. ROAD/82117595
50195802	2no cw potholes (RD: CW Pothole)	Between studded area of pedestrian crossing outside Bodysmart physios	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	23/04/2026	23/04/2026	Act. ROAD/82117596
50195804	1no rocking cut pcc slab (RD: FW Slabs Rocking)	Outside the Gurkha takeaway	RD: Cat 3 - 60 Day	Job Complete	23/04/2026	25/04/2026	Act. ROAD/82117598
50195806	Grano open joint at Gas Toby (RD: FW Grano Open Joint)	Outside no160	RD: Cat 3 - 60 Day	Job Complete	23/04/2026	24/04/2026	Act. ROAD/82117600
50195811	3no rocking / sunken 900 x 600 pcc slabs (RD: FW Slabs Rocking)	At junction with millar cres outside Marie curie charity shop	RD: Cat 3 - 60 Day	Job Complete	23/04/2026	25/04/2026	Act. ROAD/82117601
50196177	Cw x1 pothole (RD: CW Pothole)	Pedestrian crossing outside of Techfixd , please uplift loose debris	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/05/2026	05/05/2026	Act. ROAD/82117869
50196279	No 1 pothole (RD: CW Pothole)	At crossing point outside gratitude Thai lounge bar opposite no 90	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	05/05/2026	05/05/2026	Act. ROAD/82117967
50197040	No 1 pothole around iron work (RD: CW Pothole)	Outside Eric Liddell heading south	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/05/2026	20/05/2026	Act. ROAD/82118525
50198250	No 2 potholes (RD: CW Pothole)	Outside. Costa coffee at crossing point	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/06/2026	10/06/2026	Act. ROAD/82119456

Site History Report

Effective: 20/07/2024 to 20/07/2026
Service: Roads General
Site: Morningside Road (7903068)

Asset Number: 1.00 to 1.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Ward 10 - From Colinton Road to Comiston Road		Feature Type: Road Asset		Area: South East Locality	
50198931	No 1 pothole (RD: CW Pothole)	At Morningside place bus stop outside morningside medical practice	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/06/2026	24/06/2026	Act. ROAD/82120001
50199688	Broken slab around gas Toby (RD: FW Slabs Broken/Missing)	Outside no 388 .	RD: Cat 3 - 60 Day	Job Committed	08/07/2026	30/09/2026	Est. ROAD/82120678
50199928	1no Cw pothole (RD: CW Pothole)	Opposite Elim church	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/07/2026	15/07/2026	Act. ROAD/82120852
50199963	Sunken cut off a slab (RD: FW Slabs Rocking)	Outside no 2	RD: Cat 3 - 60 Day	Job Committed	15/07/2026	07/10/2026	Est. ROAD/82120872