

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Site: Craigmillar Park (7901732)

Locality: Mayfield, Edinburgh, City of Edinburgh

Area: South East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41265288	- Inspection Batch No actionable defects found			Route: South Mobile Inspection Route		Date: 09/06/2026		
Batch: 41264897	- Inspection Batch No actionable defects found			Route: SfP_SouthEast		Date: 05/06/2026		
Batch: 41263481	- Inspection Batch No actionable defects found			Route: SfP_SouthEast		Date: 19/05/2026		
Batch: 41262755	- Inspection Batch No actionable defects found			Route: South Mobile Inspection Route		Date: 08/05/2026		
Batch: 41262092	- Inspection Batch No actionable defects found			Route: SfP_SouthEast		Date: 30/04/2026		
Batch: 41260828	- Inspection Batch			Route: Ad hoc Route		Date: 14/04/2026		
42204107	Sunken tar 5mx1 m	14/04/2026	outside no. 22 heading into town	RD: CW Cracked/Broken	Internal		Uncommitted	50195329
Batch: 41260824	- Inspection Batch			Route: Ad hoc Route		Date: 14/04/2026		
42204103	No 1 pothole	14/04/2026	At traffic lights heading south at lampost CVH20	RD: CW Pothole	Internal		Committed	50195328
Batch: 41260370	- Inspection Batch			Route: Ad hoc Route		Date: 08/04/2026		
42203787	No 1 pothole	08/04/2026	At bustop heading south outside no 3	RD: CW Pothole	Internal		Committed	50195059
Batch: 41260026	- Inspection Batch No actionable defects found			Route: South Mobile Inspection Route		Date: 01/04/2026		
Batch: 41259779	- Inspection Batch			Route: Ad hoc Route		Date: 31/03/2026		
42203335	No 1 pothole	31/03/2026	Outside no 10 st Margaret's Nursery in northbound lane at island	RD: CW Pothole	Internal		Committed	50194728
Batch: 41259704	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic		Date: 30/03/2026		
Batch: 41259230	- Inspection Batch			Route: Ad hoc Route		Date: 25/03/2026		
42202927	2 m x 2 m tar patch required	25/03/2026	Next to the crossing island, around water hydrant near lampost CVH21	RD: CW Cracked/Broken	Internal		Committed	50194501
Batch: 41258940	- Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic		Date: 23/03/2026		
Batch: 41258544	- Inspection Batch No actionable defects found			Route: SfP_SouthEast		Date: 18/03/2026		
Batch: 41258444	- Inspection Batch			Route: Ad hoc Route		Date: 18/03/2026		
42202313	No 1 pothole	18/03/2026	Craigmiller park at junction with east Suffolk road	RD: CW Pothole	Internal		Committed	50194072
Batch: 41258116	- Inspection Batch			Route: Mobile Inspection Strategic		Date: 16/03/2026		
42202072	1no pothole	16/03/2026	Outside Travelodge	RD: CW Pothole	Internal		Committed	50193903

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South East Locality	
Batch: 41258116 - Inspection Batch				Route: Mobile Inspection Strategic			Date: 16/03/2026	
42202071	1no pothole	16/03/2026	Outside no23	RD: CW Pothole	Internal		Committed	50193902
Batch: 41257830 - Inspection Batch				Route: Ad hoc Route			Date: 12/03/2026	
42201871	Cracked broken tar 2 m x 1.5	12/03/2026	Outside no 54 Craig miller park	RD: CW Cracked/Broken	Internal		Committed	50193779
Batch: 41257714 - Inspection Batch				Route: Ad hoc Route			Date: 11/03/2026	
42201808	Cracked broken tar 20 m x 1.5	11/03/2026	From no 12 a to no 14 Craig miller park	RD: CW Cracked/Broken	Internal		Committed	50193720
Batch: 41257335 - Inspection Batch				Route: Mobile Inspection Strategic			Date: 09/03/2026	
No actionable defects found								
Batch: 41256362 - Inspection Batch				Route: South Mobile Inspection Route			Date: 02/03/2026	
No actionable defects found								
Batch: 41256144 - Inspection Batch				Route: Mobile Inspection Strategic			Date: 02/03/2026	
No actionable defects found								
Batch: 41255452 - Inspection Batch				Route: Ad hoc Route			Date: 25/02/2026	
42200555	Sunken hydrant cover	25/02/2026	Nearest house no 60 Craig miller park at crossing point at traffic lights	RU: Utility Apparatus	Internal		Uncommitted	50192773
Batch: 41255449 - Inspection Batch				Route: Ad hoc Route			Date: 25/02/2026	
42200551	Noisy bt manhole cover	25/02/2026	Outside no 17 the kildonan lodge hotel heading south	RU: Utility Apparatus	Internal		Uncommitted	50192770
Batch: 41255447 - Inspection Batch				Route: Ad hoc Route			Date: 25/02/2026	
42200544	No 1 pothole	25/02/2026	Outside no 12 a heading north	RD: CW Pothole	Internal		Committed	50192769
Batch: 41254799 - Inspection Batch				Route: Mobile Inspection Strategic			Date: 23/02/2026	
42200279	1no Cw pothole	23/02/2026	At bus stop outside no3	RD: CW Pothole	Internal		Committed	50192570
Batch: 41253768 - Inspection Batch				Route: SfP_SouthEast			Date: 16/02/2026	
No actionable defects found								
Batch: 41253593 - Inspection Batch				Route: Mobile Inspection Strategic			Date: 15/02/2026	
42199550	2no potholes	15/02/2026	Outside the Travelodge near the lights	RD: CW Pothole	Internal		Committed	50191957
Batch: 41252403 - Inspection Batch				Route: Mobile Inspection Strategic			Date: 08/02/2026	
No actionable defects found								
Batch: 41252092 - Inspection Batch				Route: Ad hoc Route			Date: 06/02/2026	
42198658	No 2 potholes	06/02/2026	Outside no 14	RD: CW Pothole	Internal		Committed	50191243
Batch: 41251561 - Inspection Batch				Route: Ad hoc Route			Date: 02/02/2026	
42198286	Sunken manhole cover	02/02/2026	Outside no 27 Craigmillar park at kildonan lodge hotel	RU: Utility Apparatus	Internal		Uncommitted	50190959
Batch: 41251558 - Inspection Batch				Route: Ad hoc Route			Date: 02/02/2026	
42198282	No 1 pothole	02/02/2026	Outside travel lodge at lights heading south at lamppost CVH20	RD: CW Pothole	Internal		Committed	50190957

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South East Locality	
Batch: 41251466 - Inspection Batch No actionable defects found		Route: Mobile Inspection Strategic			Date: 01/02/2026			
Batch: 41250465 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 26/01/2026			
Batch: 41250103 - Inspection Batch		Route: Mobile Inspection Strategic			Date: 26/01/2026			
42197493	1no cw pothole	26/01/2026	Outside no3 at bus stop	RD: CW Pothole	Internal		Committed	50190333
Batch: 41249028 - Inspection Batch		Route: Mobile Inspection Strategic			Date: 19/01/2026			
42196947	1no pothole	19/01/2026	In the cycle box at the corner of Lady Road	RD: CW Pothole	Internal		Committed	50189900
Batch: 41248014 - Inspection Batch No actionable defects found		Route: SfP_SouthEast			Date: 12/01/2026			
Batch: 41247553 - Inspection Batch		Route: Mobile Inspection Strategic			Date: 10/01/2026			
42196280	1no pothole	10/01/2026	At the bus stop outside no2	RD: CW Pothole	Internal		Committed	50189398
Batch: 41246034 - Inspection Batch No actionable defects found		Route: Mobile Inspection Strategic			Date: 23/12/2025			
Batch: 41245518 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 19/12/2025			
Batch: 41244248 - Inspection Batch No actionable defects found		Route: Mobile Inspection Strategic			Date: 11/12/2025			
Batch: 41244056 - Inspection Batch		Route: Ad hoc Route			Date: 08/12/2025			
42194891	2 no potholes	08/12/2025	Outside 14/16Craigmillar park	RD: CW Pothole	Internal		Committed	50188230
Batch: 41244053 - Inspection Batch		Route: Ad hoc Route			Date: 08/12/2025			
42194889	Non1 pothole	08/12/2025	Outside no 3 at bustopn	RD: CW Pothole	Internal		Committed	50188228
Batch: 41243323 - Inspection Batch No actionable defects found		Route: SfP_SouthEast			Date: 01/12/2025			
Batch: 41241907 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 18/11/2025			
Batch: 41241376 - Inspection Batch		Route: Ad hoc Route			Date: 13/11/2025			
42193216	No1 pothole	13/11/2025	At bustop opposite lampost CVH03	RD: CW Pothole	Internal		Committed	50186878
Batch: 41240463 - Inspection Batch		Route: SfP_SouthEast			Date: 02/11/2025			
42192445	2no missing bollards	02/11/2025	Outside no26 and 32	RD: SFP Damaged Bollard	Internal		Committed	50186356
Batch: 41240281 - Inspection Batch		Route: Ad hoc Route			Date: 30/10/2025			
42192220	No 1 pothole	30/10/2025	Near lampost CVH 20 heading south just before traffic lights near kerb	RD: CW Pothole	Internal		Committed	50186245
Batch: 41239879 - Inspection Batch		Route: Ad hoc Route			Date: 26/10/2025			
42191919	2no missing Sfp bollards	26/10/2025	Outside no 34 / 28	RD: SFP Damaged Bollard	Internal		Committed	50186070

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South East Locality	
Batch: 41239024 - Inspection Batch				Route: South Mobile Inspection Route			Date: 16/10/2025	
No actionable defects found								
Batch: 41238670 - Inspection Batch				Route: Ad hoc Route			Date: 14/10/2025	
42191136	No 1 pothole	14/10/2025	At crossing point opposite lampost CVH20	RD: CW Pothole	Internal		Committed	50185551
Batch: 41237825 - Inspection Batch				Route: SfP_SouthEast			Date: 02/10/2025	
No actionable defects found								
Batch: 41236766 - Inspection Batch				Route: South Mobile Inspection Route			Date: 12/09/2025	
No actionable defects found								
Batch: 41235556 - Inspection Batch				Route: SfP_SouthEast			Date: 27/08/2025	
No actionable defects found								
Batch: 41235210 - Inspection Batch				Route: SE_CF1_MayfieldEast1			Date: 22/08/2025	
42188821	Blstop road markings need refreshed	21/08/2025	Outside Travelodge pedestrian crossing	RD: Markings Refresh	Internal		Uncommitted	50183911
42188818	Bicycle and stop road markings need refreshed	21/08/2025	At traffic lights junction with lady road	RD: Markings Refresh	Internal		Uncommitted	50183910
42188829	3no bollard stumps need removed/ made safe and infilled with grano	21/08/2025	Outside no40	RD: FW Grano Pothole	Internal		Committed	50183916
42188847	Renew 1no missing Edinburgh bollard	21/08/2025	At junction with Suffolk road	RD: Bollard Damage/Missing/Nev	Internal		Committed	50183924
42188842	1no pole needs straightened as pole is leaning, causing sign to face away from road	21/08/2025	Outside no7	TS: Sign Orientation Incorrect	Internal		Committed	50183922
Sign and pole undamaged								
Batch: 41234625 - Inspection Batch				Route: South Mobile Inspection Route			Date: 12/08/2025	
No actionable defects found								
Batch: 41233706 - Inspection Batch				Route: SfP_SouthEast			Date: 24/07/2025	
No actionable defects found								
Batch: 41232936 - Inspection Batch				Route: South Mobile Inspection Route			Date: 14/07/2025	
No actionable defects found								
Batch: 41231542 - Inspection Batch				Route: SfP_SouthEast			Date: 23/06/2025	
No actionable defects found								
Batch: 41230440 - Inspection Batch				Route: South Mobile Inspection Route			Date: 09/06/2025	
No actionable defects found								
Batch: 41228242 - Inspection Batch				Route: SfP_SouthEast			Date: 14/05/2025	
No actionable defects found								
Batch: 41228216 - Inspection Batch				Route: Ad hoc Route			Date: 14/05/2025	
42183494	1 no pothole)	14/05/2025	Outside the kildonan lodge hotel sound bound lane	RD: CW Pothole	Internal		Committed	50179889

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South East Locality	
	Batch: 41227863 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route			Date: 07/05/2025	
	Batch: 41226178 - Inspection Batch No actionable defects found			Route: SfP_SouthEast			Date: 16/04/2025	
	Batch: 41225726 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route			Date: 09/04/2025	
	Batch: 41224555 - Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic			Date: 30/03/2025	
	Batch: 41224023 - Inspection Batch No actionable defects found			Route: SfP_SouthEast			Date: 24/03/2025	
	Batch: 41223873 - Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic			Date: 24/03/2025	
	Batch: 41222817 - Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic			Date: 15/03/2025	
	Batch: 41222621 - Inspection Batch			Route: Ad hoc Route			Date: 14/03/2025	
42178650	2 no potholes	14/03/2025	Outside no 50 A opposite Northumberland hotel	RD: CW Pothole	Internal		Committed	50176933
	Batch: 41222387 - Inspection Batch No actionable defects found			Route: South Mobile Inspection Route			Date: 12/03/2025	
	Batch: 41221828 - Inspection Batch			Route: Ad hoc Route			Date: 07/03/2025	
42178064	No 1 pothole	07/03/2025	Just south of no 1 a	RD: CW Pothole	Internal		Committed	50176572
	Batch: 41221736 - Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic			Date: 06/03/2025	
	Batch: 41221200 - Inspection Batch			Route: Ad hoc Route			Date: 03/03/2025	
42177626	Gas toby low and tar surround making a loud noise when traffic going over it	03/03/2025	Outside no 1 James gall wynd	RU: Utility Apparatus	Internal		Uncommitted	50176248
	Batch: 41221029 - Inspection Batch No actionable defects found			Route: Mobile Inspection Strategic			Date: 28/02/2025	
	Batch: 41220458 - Inspection Batch No actionable defects found			Route: SfP_SouthEast			Date: 24/02/2025	
	Batch: 41220337 - Inspection Batch			Route: Ad hoc Route			Date: 24/02/2025	
42176834	No 1 pothole	24/02/2025	At crossing point at traffic lights heading into town at start of craigmiller park	RD: CW Pothole	Internal		Committed	50175729
	Batch: 41220228 - Inspection Batch			Route: Ad hoc Route			Date: 21/02/2025	
42176747	2no Cw potholes	21/02/2025	Craigmillar park at traffic lights south bound towards Cameron toll	RD: CW Pothole	Internal		Committed	50175663

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street			Feature Type: Road Asset		Area: South East Locality	
Batch: 41220099 - Inspection Batch				Route: Mobile Inspection Strategic		Date: 20/02/2025		
No actionable defects found								
Batch: 41218873 - Inspection Batch				Route: South Mobile Inspection Route		Date: 12/02/2025		
No actionable defects found								
Batch: 41218845 - Inspection Batch				Route: Mobile Inspection Strategic		Date: 12/02/2025		
No actionable defects found								
Batch: 41217311 - Inspection Batch				Route: Ad hoc Route		Date: 03/02/2025		
42174722	Track sunk 5 m length x 1 width	03/02/2025	Opposite no 18	RD: CW Subsidence/Heaving	Internal		Committed	50174110
Batch: 41217309 - Inspection Batch				Route: Ad hoc Route		Date: 03/02/2025		
42174719	No 1 pothole	03/02/2025	At junction of craigmiller park and Wilton road	RD: CW Pothole	Internal		Committed	50174107
Batch: 41217130 - Inspection Batch				Route: Mobile Inspection Strategic		Date: 31/01/2025		
42174605	1no pothole	31/01/2025	At the junction with East Suffolk Park	RD: CW Pothole	Internal		Committed	50174020
Batch: 41216802 - Inspection Batch				Route: SfP_SouthEast		Date: 29/01/2025		
No actionable defects found								
Batch: 41215841 - Inspection Batch				Route: Ad hoc Route		Date: 21/01/2025		
42173677	Tar squad has removed a Sfp bollard and haven't put it back	21/01/2025	on the pavement in front of No. 48	RD: SFP Damaged Bollard	Internal		Committed	50173335
Batch: 41215818 - Inspection Batch				Route: Mobile Inspection Strategic		Date: 21/01/2025		
No actionable defects found								
Batch: 41215194 - Inspection Batch				Route: Ad hoc Route		Date: 17/01/2025		
42173364	2 no potholes	17/01/2025	Opposite no 30 Kingsley guest house	RD: CW Pothole	Internal		Committed	50173091
Batch: 41214844 - Inspection Batch				Route: Ad hoc Route		Date: 15/01/2025		
42173164	Defective BT cover on cw photos attached	15/01/2025	Craigmillar park at lady road junction	RU: Utility Apparatus	Internal		Uncommitted	50172950
Batch: 41214271 - Inspection Batch				Route: SfP_SouthEast		Date: 13/01/2025		
No actionable defects found								
Batch: 41213887 - Inspection Batch				Route: South Mobile Inspection Route		Date: 10/01/2025		
42172656	2no potholes	10/01/2025	In the middle of the road at the junction with James Gall Wynd	RD: CW Pothole	Internal		Committed	50172597
Batch: 41211203 - Inspection Batch				Route: Ad hoc Route		Date: 16/12/2024		
42171337	Sunken manhole on pedestrian crossing photos attached	16/12/2024	sunken iron work here in the middle of carriageway of the junction	RU: Utility Apparatus	Internal		Uncommitted	50171531
Batch: 41210850 - Inspection Batch				Route: SfP_SouthEast		Date: 12/12/2024		
No actionable defects found								
Batch: 41210749 - Inspection Batch				Route: Ad hoc Route		Date: 12/12/2024		
42171106	No 1 pothole	12/12/2024	At lamppost cvh 20 at junction	RD: CW Pothole	Internal		Committed	50171332

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South East Locality	
Batch: 41210748 - Inspection Batch		Route: Ad hoc Route			Date: 12/12/2024			
42171105	No 1 pothole	12/12/2024	At junction at lamppost cvh20	RD: CW Pothole	Internal		Committed	50171331
Batch: 41210660 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 11/12/2024			
Batch: 41209803 - Inspection Batch		Route: Ad hoc Route			Date: 06/12/2024			
42170662	Damaged lane defender needs secured	06/12/2024	Opposite no 10	RD: SFP Damaged Bollard	Internal		Committed	50170949
Batch: 41207808 - Inspection Batch No actionable defects found		Route: SfP_SouthEast			Date: 15/11/2024			
Batch: 41207499 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 12/11/2024			
Batch: 41204941 - Inspection Batch		Route: Ad hoc Route			Date: 23/10/2024			
42167413	1no missing sfp bollard	23/10/2024	Outside no23	RD: SFP Damaged Bollard	Internal		Committed	50168570
Batch: 41204481 - Inspection Batch		Route: SfP_SouthEast			Date: 21/10/2024			
42167214	1no missing bollard	21/10/2024	Outside 25	RD: SFP Damaged Bollard	Internal		Committed	50168406
Batch: 41203631 - Inspection Batch		Route: Ad hoc Route			Date: 15/10/2024			
42166816	1no manhole sunken/loose causing surrounding Cw to break up	15/10/2024	Outside no1 Opposite bus stop next to Craigmillar park church	RU: Utility Apparatus	Internal		Uncommitted	50168130
Batch: 41203417 - Inspection Batch		Route: Ad hoc Route			Date: 14/10/2024			
42166586	Unknown cover sunken and damaged	14/10/2024	Outside of 1	RU: Utility Apparatus	Internal		Uncommitted	50168023
Batch: 41203178 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 11/10/2024			
Batch: 41200903 - Inspection Batch No actionable defects found		Route: SfP_SouthEast			Date: 18/09/2024			
Batch: 41200610 - Inspection Batch		Route: Ad hoc Route			Date: 13/09/2024			
42164919	Cw x5 potholes Road: Defective / Damaged - please inspect road surface between the southbound carriage between East Suffolk Road and East Suffolk Park. causing vibrations to houses when large vehcles driving by. (Enquiry 34009031)	13/09/2024	Southbound outside of 25	RD: CW Pothole	Internal		Committed	50166480
Batch: 41200332 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 10/09/2024			
Batch: 41198884 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 15/08/2024			
Batch: 41198800 - Inspection Batch		Route: Ad hoc Route			Date: 15/08/2024			
42163687	Bus stop has been taken away leaving a metal stump Please cut stump away and make safe	15/08/2024	Opposite lygon rd	RD: FW HRA Pothole	Internal		Committed	50165384

Site History Report

Effective: 01/06/2021 to 05/07/2026

Service: Roads General

Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street			Feature Type: Road Asset		Area: South East Locality	
Batch: 41198414 - Inspection Batch				Route: SfP_SouthEast			Date: 12/08/2024	
No actionable defects found								
Batch: 41198310 - Inspection Batch				Route: SE_CF1_MayfieldEast1			Date: 08/08/2024	
42163258	1no Fw pothole bollard stump please make safe	08/08/2024	At junction with Wilton road	RD: FW HRA Pothole	Internal		Committed	50165082
42163247		08/08/2024		RD: Bollard Damage/Missing/Nev	Internal		Uncommitted	50113487
42163261		08/08/2024		RD: CW Cracked/Broken	Internal		Uncommitted	50116944
42163269	1no manhole frame sunken/ loose causing surrounding CW to break up	08/08/2024	Outside no1 opposite bus stop next to craigmillar park church	RU: Utility Apparatus	Internal		Uncommitted	50165086
42163266	Cw breaking up approx 8m x 1.5m	08/08/2024	Outside no42 David horn house at bus stop	RD: CW Cracked/Broken	Internal		Committed	50165084
42163260	1no damaged bollard	08/08/2024	At junction with lygon road	RD: Bollard Damage/Missing/Nev	Internal		Uncommitted	50165083
42163245	1no Fw pothole at gas Toby	08/08/2024	Outside no6	RD: FW HRA Pothole	Internal		Committed	50165077
42163249	Missing bollard	08/08/2024	At junction with Suffolk road	RD: Bollard Damage/Missing/Nev	Internal		Uncommitted	50113488
Batch: 41197796 - Inspection Batch				Route: Ad hoc Route			Date: 31/07/2024	
42162904	Cover loose and noisy Road: Defective / Damaged (Enquiry 1807249)	31/07/2024	Outside of number 1 (southbound carriageway)	RU: Utility Apparatus	Internal		Uncommitted	50164804
Batch: 41197245 - Inspection Batch				Route: SfP_SouthEast			Date: 23/07/2024	
No actionable defects found								
Batch: 41197031 - Inspection Batch				Route: South Mobile Inspection Route			Date: 18/07/2024	
No actionable defects found								
Batch: 41195658 - Inspection Batch				Route: Ad hoc Route			Date: 01/07/2024	
42160620	Cw x2 potholes Road: Defective / Damaged (Enquiry 1789734)	01/07/2024	Outside of 23	RD: CW Pothole	Internal		Committed	50163154
Batch: 41194687 - Inspection Batch				Route: South Mobile Inspection Route			Date: 18/06/2024	
No actionable defects found								
Batch: 41194504 - Inspection Batch				Route: SfP_SouthEast			Date: 17/06/2024	
No actionable defects found								
Batch: 41193033 - Inspection Batch				Route: Ad hoc Route			Date: 29/05/2024	
42158368	Cw x1 pothole Road: Defective / Damaged (Enquiry 1766064)	29/05/2024	At the junction with Gordon Terrace	RD: CW Pothole	Internal		Committed	50161335
Batch: 41191993 - Inspection Batch				Route: South Mobile Inspection Route			Date: 14/05/2024	
No actionable defects found								
Batch: 41191576 - Inspection Batch				Route: SfP_SouthEast			Date: 09/05/2024	
No actionable defects found								
Batch: 41189912 - Inspection Batch				Route: SfP_SouthEast			Date: 18/04/2024	
No actionable defects found								

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South East Locality	
Batch: 41189809 - Inspection Batch		Route: Ad hoc Route			Date: 17/04/2024			
42155030	Railings damage approximately 2mts	17/04/2024	At the junction with Craigmiller Park Esslemont Road and Lady Road (pedestrian crossing	RD: Railing Damage/Missing/New	Internal		Committed	50158649
Batch: 41189325 - Inspection Batch		Route: Ad hoc Route			Date: 11/04/2024			
42154523	1no defective/noisy manhole causing surrounding damage.	11/04/2024	In middle of junction heading southbound just past pedestrian crossing at the foot of Craigmillar Park.	RU: Utility Apparatus	Internal		Uncommitted	50158175
Batch: 41188981 - Inspection Batch		Route: Ad hoc Route			Date: 09/04/2024			
42154112	Cw x1 pothole Road: Defective / Damaged (Enquiry 1728907)	09/04/2024	Outside of kildonan hotel (Southbound) painted but washed off	RD: CW Pothole	Internal		Committed	50157813
Batch: 41188929 - Inspection Batch		Route: Ad hoc Route			Date: 09/04/2024			
42154070	Cw x1 pothole Road: Defective / Damaged (Enquiry 1726710)	09/04/2024	Outside of 60 / heading into city centre	RD: CW Pothole	Internal		Committed	50157794
Batch: 41188875 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 09/04/2024			
Batch: 41187774 - Inspection Batch		Route: Ad hoc Route			Date: 27/03/2024			
42153172	Cycle lane bollard dislodged	27/03/2024	At the junction with East Suffolk Road	RD: SFP Damaged Bollard	Internal		Committed	50156946
Batch: 41187506 - Inspection Batch		Route: Ad hoc Route			Date: 25/03/2024			
42152952	Cw x1 pothole Road: Defective / Damaged (Enquiry 1723824)	25/03/2024	At the with Lady Road (Southbound)	RD: CW Pothole	Internal		Committed	50156781
Batch: 41187423 - Inspection Batch		Route: Ad hoc Route			Date: 24/03/2024			
42152901	Cw x1 pothole Road: Defective / Damaged (Enquiry 1722866)	24/03/2024	Outside of 19 after pedestrian crossing (Southbound)	RD: CW Pothole	Internal		Committed	50156747
Batch: 41187209 - Inspection Batch No actionable defects found		Route: SfP_SouthEast			Date: 22/03/2024			
Batch: 41187106 - Inspection Batch		Route: Ad hoc Route			Date: 21/03/2024			
42152495	Cw x1 pothole Road: Defective / Damaged (Enquiry 1721782)	21/03/2024	At the junction with East Suffolk Park	RD: CW Pothole	Internal		Committed	50156508
Batch: 41186139 - Inspection Batch		Route: Ad hoc Route			Date: 13/03/2024			
42151421	Cw x6 potholes Road: Defective / Damaged (Enquiry 1714473)	13/03/2024	Outside the Kildonan Lodge (southbound)	RD: CW Pothole	Internal		Committed	50155667
Batch: 41185916 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 12/03/2024			
Batch: 41183835 - Inspection Batch No actionable defects found		Route: SfP_SouthEast			Date: 26/02/2024			
Batch: 41183640 - Inspection Batch No actionable defects found		Route: South Mobile Inspection Route			Date: 23/02/2024			

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	South East Locality
Batch:	41182740 - Inspection Batch			Route:	Ad hoc Route			Date: 16/02/2024
42147979	Cw x1 pothole	16/02/2024	At the junction with Lady Road (Southbound)	RD: CW Pothole	Internal		Committed	50153211
Batch:	41182735 - Inspection Batch			Route:	Ad hoc Route			Date: 16/02/2024
42147975	Cw x1 pothole Road: Defective / Damaged (Enquiry 1700209)	16/02/2024	At the junction with East Suffolk Park	RD: CW Pothole	Internal		Committed	50153208
Batch:	41182355 - Inspection Batch			Route:	Ad hoc Route			Date: 13/02/2024
42147436	2 panel of railings damage and broken Fence: Damaged / Defective (Enquiry 1698073)	13/02/2024	Crossing island railings are damaged; esslemont road and Craigmillar park	RD: Railing Damage/Missing/New	Internal		Committed	50152862
Batch:	41181649 - Inspection Batch			Route:	Ad hoc Route			Date: 06/02/2024
42146662	Cw x1 pothole Road: Defective / Damaged (Enquiry 1693442)	06/02/2024	Outside of number 62	RD: CW Pothole	Internal		Committed	50152366
Batch:	41179917 - Inspection Batch			Route:	Ad hoc Route			Date: 24/01/2024
42144988	Cw x1 pothole Road: Defective / Damaged (Enquiry 1684586)	24/01/2024	At the pedestrian crossing heading southbound at th junction of East Suffolk Road	RD: CW Pothole	Internal		Committed	50151094
Batch:	41179753 - Inspection Batch			Route:	SfP_SouthEast			Date: 23/01/2024
	No actionable defects found							
Batch:	41179590 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 22/01/2024
	No actionable defects found							
Batch:	41179549 - Inspection Batch			Route:	Ad hoc Route			Date: 22/01/2024
42144701	Cw x2 potholes Road: Defective / Damaged (Enquiry 1682069)	22/01/2024	Outside the Northumberland Hotel	RD: CW Pothole	Internal		Committed	50150806
Batch:	41178073 - Inspection Batch			Route:	Ad hoc Route			Date: 10/01/2024
42143656	Cw x1 pothole Road: Defective / Damaged (Enquiry 1674782)	10/01/2024	At the junction with East Suffolk Park	RD: CW Pothole	Internal		Committed	50149817
Batch:	41177905 - Inspection Batch			Route:	Ad hoc Route			Date: 09/01/2024
42143543	Cw x 3 potholes Road: Defective / Damaged (Enquiry 1674284)	09/01/2024	Bus stop outside of number 40 and outside of number 50	RD: CW Pothole	Internal		Committed	50149696
Batch:	41176642 - Inspection Batch			Route:	Ad hoc Route			Date: 03/01/2024
42143071	Cw x 1 pothole Road: Defective / Damaged (Enquiry 1668191)	03/01/2024	Opposite number 32 , south bound	RD: CW Pothole	Internal		Committed	50149188
Batch:	41176639 - Inspection Batch			Route:	Ad hoc Route			Date: 03/01/2024
42143069	Cw x1 pothole Road: Defective / Damaged (Enquiry 1669060)	03/01/2024	Outside of number 62	RD: CW Pothole	Internal		Committed	50149186
Batch:	41175195 - Inspection Batch			Route:	South Mobile Inspection Route			Date: 20/12/2023
	No actionable defects found							

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41174244 - Inspection Batch		Route: Ad hoc Route			Date: 13/12/2023			
42141725		13/12/2023	Outside number 62 at pedestrian crossing	RD: CW Pothole	Internal		Committed	50147840
Batch: 41174072 - Inspection Batch		Route: Ad hoc Route			Date: 11/12/2023			
42141564	Cw x1 pothole Road: Defective / Damaged (Enquiry 1658465)	11/12/2023	At the junction with East Suffolk Park	RD: CW Pothole	Internal		Committed	50147682
Batch: 41172717 - Inspection Batch		Route: SfP_SouthEast			Date: 24/11/2023			
No actionable defects found								
Batch: 41172399 - Inspection Batch		Route: South Mobile Inspection Route			Date: 20/11/2023			
No actionable defects found								
Batch: 41171639 - Inspection Batch		Route: Ad hoc Route			Date: 10/11/2023			
42139279	Cw x1 pothole Road: Defective / Damaged (Enquiry 1641998)	10/11/2023	Outside of number 62	RD: CW Pothole	Internal		Committed	50145522
Batch: 41171248 - Inspection Batch		Route: Ad hoc Route			Date: 06/11/2023			
42138758	Cw x 1 pothole Road: Defective / Damaged (Enquiry 1638440)	06/11/2023	Outside of number 33	RD: CW Pothole	Internal		Committed	50145118
Batch: 41171247 - Inspection Batch		Route: Ad hoc Route			Date: 06/11/2023			
42138757	Cw x1 pothole Road: Defective / Damaged (Enquiry 1639037)	06/11/2023	Outside of number 27	RD: CW Pothole	Internal		Committed	50145117
Batch: 41169782 - Inspection Batch		Route: SfP_SouthEast			Date: 23/10/2023			
No actionable defects found								
Batch: 41168874 - Inspection Batch		Route: South Mobile Inspection Route			Date: 17/10/2023			
42137652	1 carriageway pothole	17/10/2023	Bottom of Craigmillar park at crossing	RD: CW Pothole	Internal		Committed	50144143
Batch: 41168541 - Inspection Batch		Route: Ad hoc Route			Date: 13/10/2023			
42137478	Scottish Water manhole cover noisy	13/10/2023	Outside of number 62 Craigmillar Park	RU: Utility Apparatus	Internal		Uncommitted	50143958
Batch: 41166235 - Inspection Batch		Route: South Mobile Inspection Route			Date: 21/09/2023			
No actionable defects found								
Batch: 41163512 - Inspection Batch		Route: South Mobile Inspection Route			Date: 22/08/2023			
No actionable defects found								
Batch: 41163211 - Inspection Batch		Route: Ad hoc Route			Date: 21/08/2023			
42134462	Cw x3 potholes	21/08/2023	Outside of number 12	RD: CW Pothole	Internal		Committed	50141284
Batch: 41163210 - Inspection Batch		Route: Ad hoc Route			Date: 21/08/2023			
42134461	Cw x3 potholes Road: Defective / Damaged (Enquiry 1601034)	21/08/2023	Outside of number 25 (heading out of town)	RD: CW Pothole	Internal		Committed	50141283
Batch: 41163144 - Inspection Batch		Route: Ad hoc Route			Date: 17/08/2023			
42134419	Cycle lane pole missing, please replace	17/08/2023	Outside of number 9	RD: SFP Damaged Bollard	Internal		Committed	50141228

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South East Locality	
Batch: 41162948 - Inspection Batch			Route: SE_CF1_MayfieldEast1				Date: 15/08/2023	
42134091		15/08/2023		RD: FW HRA Cracked/Broken	Internal		Uncommitted	50113485
42134099	Missing bollard	15/08/2023	O/S Newington Road bridge	RD: Bollard Damage/Missing/Nev	Internal		Uncommitted	50113466
42134082	Pothole pro 3.5 x 1.2	15/08/2023	Outside 16	RD: CW Cracked/Broken	Internal		Committed	50135326
42134073		15/08/2023		RD: FW HRA Cracked/Broken	Internal		Uncommitted	50113489
42134078	Pothole pro 2 x 4.5	15/08/2023	Opposite 24	RD: CW Cracked/Broken	Internal		Committed	50135322
42134077	Pothole pro 1 x 5	15/08/2023	Opposite 28	RD: CW Cracked/Broken	Internal		Committed	50135324
42134133		15/08/2023		RD: CW Cracked/Broken	Internal		Uncommitted	50113492
42134097		15/08/2023		RD: CW Cracked/Broken	Internal		Uncommitted	50113473
42134088	Pothole pro 2.2 x 1.2	15/08/2023	Outside 10	RD: CW Cracked/Broken	Internal		Committed	50135330
42134087	Damaged bollard	15/08/2023	At junction with Suffolk road	RD: Bollard Damage/Missing/Nev	Internal		No Action Required	
42134084	Pothole pro 1 x 2.2	15/08/2023	Outside 12A	RD: CW Cracked/Broken	Internal		Committed	50135329
42134076	Pothole 2 x 4.5	15/08/2023	Opposite 30	RD: CW Cracked/Broken	Internal		Committed	50135325
42134083	Pothole pro 4 x 1	15/08/2023	Outside 14	RD: CW Cracked/Broken	Internal		Committed	50135327
Batch: 41162318 - Inspection Batch			Route: Ad hoc Route				Date: 03/08/2023	
42133186	Cw x1 pothole Road: Defective / Damaged (Enquiry 1591252)	03/08/2023	At the crossroads of Lady Road Esslemont Road, heading into the city	RD: CW Pothole	Internal		Committed	50140324
Batch: 41161318 - Inspection Batch			Route: South Mobile Inspection Route				Date: 18/07/2023	
No actionable defects found								
Batch: 41159967 - Inspection Batch			Route: Ad hoc Route				Date: 26/06/2023	
42130697	Black pole missing from cycle lane bollard	26/06/2023	Outside of number 9	RD: SFP Damaged Bollard	Internal		Committed	50138337
Batch: 41159353 - Inspection Batch			Route: South Mobile Inspection Route				Date: 14/06/2023	
No actionable defects found								
Batch: 41158806 - Inspection Batch			Route: Ad hoc Route				Date: 07/06/2023	
42129638	Cw x1 pothole Road: Defective / Damaged (Enquiry 1563281)	07/06/2023	Opposite number 28 , heading out of town	RD: CW Pothole	Internal		Committed	50137446
Batch: 41157729 - Inspection Batch			Route: South Mobile Inspection Route				Date: 19/05/2023	
No actionable defects found								
Batch: 41156221 - Inspection Batch			Route: Ad hoc Route				Date: 01/05/2023	
42126417	Pothole pro x2 7 x 1.5 and 1 x 1	01/05/2023	Outside 3	RD: CW Cracked/Broken	Internal		Committed	50135334
Batch: 41156219 - Inspection Batch			Route: Ad hoc Route				Date: 01/05/2023	
42126415	Pothole pro 3 x 1.5	01/05/2023	Opposite Craigmillar park church	RD: CW Cracked/Broken	Internal		Committed	50135333
Batch: 41156218 - Inspection Batch			Route: Ad hoc Route				Date: 01/05/2023	
42126414	Pothole pro 1.8 x 1.4	01/05/2023	Opposite Cala developments	RD: CW Cracked/Broken	Internal		Committed	50135332
Batch: 41156217 - Inspection Batch			Route: Ad hoc Route				Date: 01/05/2023	
42126413	Pothole pro 3.5 x 1.5	01/05/2023	Opposite Cala development	RD: CW Cracked/Broken	Internal		Committed	50135331

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South East Locality	
Batch: 41156212 - Inspection Batch				Route: Ad hoc Route			Date: 01/05/2023	
42126411	Pothole pro 2.2 x 1.2	01/05/2023	Outside 10	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41156210 - Inspection Batch				Route: Ad hoc Route			Date: 01/05/2023	
42126408	Pothole pro 1 x 2.2	01/05/2023	Outside 12A	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41156209 - Inspection Batch				Route: Ad hoc Route			Date: 01/05/2023	
42126406	Pothole pro 4 x 1	01/05/2023	Outside 14	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41156208 - Inspection Batch				Route: Ad hoc Route			Date: 01/05/2023	
42126403	Pothole pro 3.5 x 1.2	01/05/2023	Outside 16	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41156206 - Inspection Batch				Route: Ad hoc Route			Date: 01/05/2023	
42126395	Pothole 2 x 4.5	01/05/2023	Opposite 30	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41156205 - Inspection Batch				Route: Ad hoc Route			Date: 01/05/2023	
42126394	Pothole pro 1 x 5	01/05/2023	Opposite 28	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41156203 - Inspection Batch				Route: Ad hoc Route			Date: 01/05/2023	
42126391	Pothole pro 2 x 4.5	01/05/2023	Opposite 24	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41155744 - Inspection Batch				Route: Ad hoc Route			Date: 26/04/2023	
42126044	Cw x1 1pothole Road: Defective / Damaged (Enquiry 1541798)	26/04/2023	At the junction with East Savile Road	RD: CW Pothole	Internal		Committed	50135051
Batch: 41155741 - Inspection Batch				Route: Ad hoc Route			Date: 26/04/2023	
42126041	Fw x1 pothole Pavement: Damaged / Defective (Enquiry 1541946)	26/04/2023	Outside of number 26	RD: FW HRA Pothole	Internal		Committed	50135048
Batch: 41155679 - Inspection Batch				Route: South Mobile Inspection Route			Date: 25/04/2023	
42125996	2 carriageway potholes	25/04/2023	Opposite 28	RD: CW Pothole	Internal		Committed	50135005
Batch: 41155499 - Inspection Batch				Route: Ad hoc Route			Date: 24/04/2023	
42125893	Cw x2, potholes Road: Defective / Damaged (Enquiry 1541599)	24/04/2023	Outside of number 60 at the junction with Lady Road crossroads	RD: CW Pothole	Internal		Committed	50134881
Batch: 41154883 - Inspection Batch				Route: Ad hoc Route			Date: 17/04/2023	
42125308	Cw x 1 pothole Road: Defective / Damaged (Enquiry 1537764)	17/04/2023	Outside of number 2	RD: CW Pothole	Internal		Committed	50134365
Batch: 41154879 - Inspection Batch				Route: Ad hoc Route			Date: 17/04/2023	
42125304	Road: Defective / Damaged (Enquiry 1537761)	17/04/2023	Opposite Cala homes development	RD: CW Pothole	Internal		Committed	50134361
Batch: 41154878 - Inspection Batch				Route: Ad hoc Route			Date: 17/04/2023	
42125303	Cw x3 potholes Road: Defective / Damaged (Enquiry 1537761)	17/04/2023	Opposite Cala homes development	RD: CW Pothole	Internal		Committed	50134360
Batch: 41154875 - Inspection Batch				Route: Ad hoc Route			Date: 17/04/2023	
42125300	Cw x 1,pothole Road: Defective / Damaged (Enquiry 1537766)	17/04/2023	Outside of St Margaret's School	RD: CW Pothole	Internal		Committed	50134357

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41154874 - Inspection Batch			Route: Ad hoc Route				Date: 17/04/2023	
42125299	Cw x2 potholes Road: Defective / Damaged (Enquiry 1537767)	17/04/2023	Outside of number 14	RD: CW Pothole	Internal		Committed	50134356
Batch: 41153640 - Inspection Batch			Route: Ad hoc Route				Date: 30/03/2023	
42124204	Cw c1 pothole	30/03/2023	Out of number 1 at ped crossing	RD: CW Pothole	Internal		Committed	50133298
Batch: 41153501 - Inspection Batch			Route: Ad hoc Route				Date: 29/03/2023	
42124054	Cw x 2 potholes Road: Defective / Damaged (Enquiry 1527401)	29/03/2023	Outside of number 12a	RD: CW Pothole	Internal		Committed	50133149
Batch: 41153268 - Inspection Batch			Route: South Mobile Inspection Route				Date: 27/03/2023	
42123788	1no pothole	27/03/2023	Outside no60	RD: CW Pothole	Internal		Committed	50132924
42123777	1no pothole	27/03/2023	Opposite no2	RD: CW Pothole	Internal		Committed	50132918
Batch: 41151349 - Inspection Batch			Route: Ad hoc Route				Date: 06/03/2023	
42121377	Cw x 1 pothole Road: Defective / Damaged (Enquiry 1518305)	06/03/2023	Outside of number 40	RD: CW Pothole	Internal		Committed	50131182
Batch: 41151188 - Inspection Batch			Route: Ad hoc Route				Date: 03/03/2023	
42120951	Cw x 2 Road: Defective / Damaged - Pothole (Enquiry 1517775)	03/03/2023	Outside of number 56-58	RD: CW Pothole	Internal		Committed	50130953
Batch: 41150740 - Inspection Batch			Route: Ad hoc Route				Date: 27/02/2023	
42120545	Cw x 2 potholes Road: Defective / Damaged (Enquiry 1513478)	27/02/2023	Outside of number 33/35	RD: CW Pothole	Internal		Committed	50130624
Batch: 41150363 - Inspection Batch			Route: South Mobile Inspection Route				Date: 24/02/2023	
42119796	1 cw pothole	24/02/2023	At junction with Gordon terrace	RD: CW Pothole	Internal		Committed	50130174
Batch: 41146704 - Inspection Batch			Route: Ad hoc Route				Date: 26/01/2023	
42116548	Cw pothole marked on site Road: Defective / Damaged (Enquiry 1493472)	26/01/2023	Craigmillar park outside 16	RD: CW Pothole	Internal		Committed	50127596
Batch: 41146479 - Inspection Batch			Route: South Mobile Inspection Route				Date: 25/01/2023	
No actionable defects found								
Batch: 41141281 - Inspection Batch			Route: Ad hoc Route				Date: 28/12/2022	
42113841	Cw pothole marked on site	28/12/2022	Craigmillar park at Cala development	RD: CW Pothole	Internal		Committed	50124977
Batch: 41140461 - Inspection Batch			Route: South Mobile Inspection Route				Date: 21/12/2022	
No actionable defects found								
Batch: 41140277 - Inspection Batch			Route: Ad hoc Route				Date: 20/12/2022	
42113527	Remove No cold calling sign and old faded sign from lighting column.	20/12/2022	On lighting column at junction with Ventnor Park	RD: Unlit Sign Damaged/Missing	Internal		Committed	50124633

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality		
Batch: 41139882 - Inspection Batch				Route: Ad hoc Route			Date: 19/12/2022	
42113353	Cycle defender broken away from road and needs fixed back to road asap as hazard for cyclists	19/12/2022		RD: SFP Damaged Bollard	Internal		Committed	50124467
Batch: 41137092 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route			Date: 29/11/2022	
Batch: 41133745 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route			Date: 24/10/2022	
Batch: 41132691 - Inspection Batch				Route: Ad hoc Route			Date: 14/10/2022	
42108378	Replaced damaged bollard	14/10/2022		RD: SFP Damaged Bollard	Internal		Committed	50120025
Batch: 41132571 - Inspection Batch				Route: Ad hoc Route			Date: 12/10/2022	
42108293	Replaced damaged bollard	12/10/2022		RD: SFP Damaged Bollard	Internal		Committed	50119917
Batch: 41132569 - Inspection Batch				Route: Ad hoc Route			Date: 12/10/2022	
42108292	Replaced damaged bollard	12/10/2022		RD: SFP Damaged Bollard	Internal		Committed	50119916
Batch: 41131644 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route			Date: 26/09/2022	
Batch: 41130168 - Inspection Batch				Route: Ad hoc Route			Date: 25/08/2022	
42106387	Cw patching 1.5x1.5 3x3 1.2x5	25/08/2022	Craigmillar park city bound inside Lane from liberton road	RD: CW Cracked/Broken	Internal		Committed	50117881
Batch: 41129902 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route			Date: 22/08/2022	
Batch: 41128444 - Inspection Batch				Route: Ad hoc Route			Date: 28/07/2022	
42105254	Patch required	28/07/2022	Craigmillar Park At the crossing at the junction with Lady Road	RD: CW Cracked/Broken	Internal		No Action Required	
Batch: 41128210 - Inspection Batch	No actionable defects found			Route: South Mobile Inspection Route			Date: 25/07/2022	
Batch: 41126418 - Inspection Batch				Route: Ad hoc Route			Date: 27/06/2022	
42103883	Cycle defender broken away from road and needs fixed back down please	27/06/2022		RD: SFP Damaged Bollard	Internal		Committed	50115751
Batch: 41125619 - Inspection Batch	No actionable defects found			Route: SE_CW1_North1			Date: 08/06/2022	
Batch: 41124061 - Inspection Batch	No actionable defects found			Route: SE_CW1_North1			Date: 12/05/2022	
Batch: 41123971 - Inspection Batch				Route: SE_CF1_MayfieldEast1			Date: 12/05/2022	
42101055	Cracked Broken cw	12/05/2022	At junction	RD: CW Cracked/Broken	Internal		Committed	50113468
42101074	Missing bollard	12/05/2022	O/S Newington Road bridge	RD: Bollard Damage/Missing/Nev	Internal		No Action Required	

Site History Report

Effective: 01/06/2021 to 05/07/2026

Service: Roads General

Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.:	Whole Street	Feature Type:	Road Asset		Area:	South East Locality
Batch:	41123971 - Inspection Batch			Route:	SE_CF1_MayfieldEast1		Date:	12/05/2022
42101053		12/05/2022		RD: CW Pothole	Internal		Uncommitted	50113465
42101057	Broken cw	12/05/2022	Outside number 26	RD: CW Cracked/Broken	Internal		Committed	50113471
42101083	Worn cw	12/05/2022	Just past lights near Lygon road	RD: CW Cracked/Broken	Internal		No Action Required	
42101060	Cracked Broken cw	12/05/2022	Outside driveway of number 1	RD: CW Cracked/Broken	Internal		No Action Required	
42101079	Missing bollard	12/05/2022	At junction with Suffolk road	RD: Bollard Damage/Missing/Nev	Internal		No Action Required	
42101076	Fw cracked and broken	12/05/2022	Outside number 4	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42101052	Missing bollard	12/05/2022	O/S Newington Road bridge	RD: Bollard Damage/Missing/Nev	Internal		No Action Required	
42101075	Cracked Cw	12/05/2022	At entrance to newington residence	RD: CW Cracked/Broken	Internal		Committed	50113484
42101081	Pothole on cw	12/05/2022	Outside number 40	RD: CW Pothole	Internal		Committed	50113490
42101078	Damaged bollard	12/05/2022	At junction with Suffolk road	RD: Bollard Damage/Missing/Nev	Internal		No Action Required	
42101080	Fw broken and worn	12/05/2022	Outside number 40	RD: FW HRA Cracked/Broken	Internal		No Action Required	
42101051	Pothole at track	12/05/2022	At Gordon Terrace	RD: CW Pothole	Internal		No Action Required	
Batch:	41122235 - Inspection Batch			Route:	SE_CW1_North1		Date:	11/04/2022
42099304	2no potholes	11/04/2022	Outside the Kildonan Lodgt	RD: CW Pothole	Internal		Committed	50111734
42099305	1no pothole	11/04/2022	Outside no25	RD: CW Pothole	Internal		Committed	50111735
Batch:	41120736 - Inspection Batch			Route:	Ad hoc Route		Date:	28/03/2022
42097909	Cycle defender broken away from road and needs fixed ASAP	28/03/2022		RD: SFP Damaged Bollard	Internal		Committed	50110487
Batch:	41120430 - Inspection Batch			Route:	Ad hoc Route		Date:	24/03/2022
42097524	Cw pothole marked on site	24/03/2022	Craigmillar park os 19	RD: CW Pothole	Internal		Committed	50110149
Batch:	41120062 - Inspection Batch			Route:	Ad hoc Route		Date:	21/03/2022
42097175	Cw potholes marked on site x3	21/03/2022	Craigmillar park city bound 16/14/12	RD: CW Pothole	Internal		Committed	50109814
Batch:	41119120 - Inspection Batch			Route:	SE_CW1_North1		Date:	11/03/2022
42095801	2no potholes	11/03/2022	Opposite no28	RD: CW Pothole	Internal		Committed	50108812
Batch:	41116330 - Inspection Batch			Route:	Ad hoc Route		Date:	21/02/2022
42093588	Cw pothole at crossing	21/02/2022	Craigmillar park at Suffolk rd	RD: CW Pothole	Internal		Committed	50106961
Batch:	41115944 - Inspection Batch			Route:	Ad hoc Route		Date:	17/02/2022
42093127	Cw potholes marked on site x2	17/02/2022	Craigmillar park os 16/14	RD: CW Pothole	Internal		Committed	50106543
Batch:	41115354 - Inspection Batch			Route:	SE_CW1_North1		Date:	11/02/2022
	No actionable defects found							
Batch:	41115202 - Inspection Batch			Route:	Ad hoc Route		Date:	10/02/2022
42092500	Cw pothole marked on site	10/02/2022	Craigmillar park at Suffolk rd	RD: CW Pothole	Internal		Committed	50105907
Batch:	41114289 - Inspection Batch			Route:	Ad hoc Route		Date:	31/01/2022
42091434	CW potholes marked on site x2	31/01/2022	Craigmillar park opposite A digger & driver hire park	RD: CW Pothole	Internal		Committed	50104786

Site History Report

Effective: 01/06/2021 to 05/07/2026

Service: Roads General

Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset			Area: South East Locality	
Batch: 41114288 - Inspection Batch		Route: Ad hoc Route			Date: 31/01/2022			
42091432	Cw pothole marked on site	31/01/2022	Craigmillar park city bound outside gate of Cala home site per map	RD: CW Pothole	Internal		Committed	50104784
Batch: 41114285 - Inspection Batch		Route: Ad hoc Route			Date: 31/01/2022			
42091427	CW pothole marked onsite	31/01/2022	Craigmillar park city bound outside no. 16	RD: CW Pothole	Internal		Committed	50104779
Batch: 41113304 - Inspection Batch No actionable defects found		Route: SE_CW1_North1			Date: 17/01/2022			
Batch: 41111894 - Inspection Batch		Route: Ad hoc Route			Date: 05/01/2022			
42088263	Replaced missing bollard	05/01/2022		RD: SFP Damaged Bollard	Internal		Committed	50101691
Batch: 41110775 - Inspection Batch No actionable defects found		Route: SE_CW1_North1			Date: 15/12/2021			
Batch: 41107874 - Inspection Batch		Route: Ad hoc Route			Date: 19/11/2021			
42084568	Replaced missing bollards	19/11/2021		RD: SFP Damaged Bollard	Internal		Committed	50097808
Batch: 41107498 - Inspection Batch No actionable defects found		Route: SE_CW1_North1			Date: 15/11/2021			
Batch: 41103942 - Inspection Batch No actionable defects found		Route: SE_CW1_North1			Date: 13/10/2021			
Batch: 41100495 - Inspection Batch No actionable defects found		Route: SE_CW1_North1			Date: 17/09/2021			
Batch: 41099128 - Inspection Batch		Route: Ad hoc Route			Date: 30/08/2021			
42076861	Replaced missing bollard	30/08/2021		RD: SFP Damaged Bollard	Internal		Committed	50090655
Batch: 41098199 - Inspection Batch		Route: SE_CW1_North1			Date: 17/08/2021			
42076022	Potholes x 3 as marked	17/08/2021	Opp no 28	RD: CW Pothole	Internal		Committed	50089748
Batch: 41098086 - Inspection Batch		Route: Ad hoc Route			Date: 16/08/2021			
42075867	Replaced missing bollard	16/08/2021		RD: SFP Damaged Bollard	Internal		Committed	50089493
Batch: 41096219 - Inspection Batch No actionable defects found		Route: SE_CW1_North1			Date: 13/07/2021			
Batch: 41094471 - Inspection Batch		Route: Ad hoc Route			Date: 16/06/2021			
42071299	Defective manhole and surround	16/06/2021	Craigmillar park at lady rd	RU: Utility Apparatus	Internal		Uncommitted	50085374
Batch: 41094055 - Inspection Batch No actionable defects found		Route: SE_CW1_North1			Date: 10/06/2021			

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 34010540 **Logged by:** [REDACTED] **on:** 11/11/2025 10:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Please inspect road surface between 20-30 craigmillar park. heading towards Cameron Toll from the town side
Location: Craigmillar Park **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 34010521 **Logged by:** [REDACTED] **on:** 04/11/2025 11:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Craigmillar Park, please inspect for road surface for potholes.
Location: Craigmillar Park **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 34010483 **Logged by:** [REDACTED] **on:** 20/10/2025 11:41
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Please inspect road surface o/s no 27 Craigmillar park.
Location: Craigmillar Park **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 34010416 **Logged by:** [REDACTED] **on:** 01/10/2025 09:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Please inspect road sufafce o/s no 27 craigmillar park
Location: Craigmillar Park **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 34010277 **Logged by:** [REDACTED] **on:** 19/08/2025 10:28
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: 25 Craigmillar Park and stretches of approximately 50m to north and south of this point. please inspect road surafce for pot holes.
Location: Craigmillar Park **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 34009804 **Logged by:** [REDACTED] **on:** 31/03/2025 09:43
Service: Roads General **Subject:** Drainage: General Enquiry **Classification:** General Enquiry
Desc.: please inspect water surface coming from o/s 58 or 58A Craigmillar Park. please see pics aatched
Location: Craigmillar Park **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 34009784 **Logged by:** [REDACTED] **on:** 24/03/2025 10:22
Service: Roads General **Subject:** Drainage: General Enquiry **Classification:** General Enquiry
Desc.: please inspect Water on pavement and cycle lane on Craigmillar Park.
Location: Craigmillar Park **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 34009048 **Logged by:** [REDACTED] **on:** 09/09/2024 10:06
Service: Roads General **Subject:** Road: General Enquiry **Classification:** Request for service
Desc.: o/s no 1 craigmillar park, please inspect noisy manhole cover. please see pics attached.
Location: Craigmillar Park **Contact:**

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 34009031	Logged by: [REDACTED]	on: 02/09/2024 14:00
Service: Roads General	Subject: Road: Defective / Damaged	Classification: Request for service
Desc.: please inspect road surface between the southbound carriage between East Suffolk Road and East Suffolk Park. causing vibrations to houses when large vehcles driving by.		
Location: Craigmillar Park	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50166480	Defect Number: 42164919	
Enquiry No.: 34007223	Logged by: [REDACTED]	on: 13/07/2023 13:48
Service: Roads General	Subject: Street Furniture: Defective	Classification: Request for service
Desc.: One of the poles is missing from the grey mounts that form the cycle lane on the night, and if a cyclist collides with one and is thrown off there is significant chance of serious or fatal injury given the road is a very busy bus route.		
Location: Mayfield gardens stretch of A701 going from town towards Cameron Toll. The missing pole is on the left hand side of the road (travelling towards Cameron Toll) a bit after the East Savile Road bus stop on left and I think before the St Margaret's care home on right.	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Job Number: 50141228	Defect Number: 42134419	
Enquiry No.: 34005999	Logged by: [REDACTED]	on: 02/11/2022 11:40
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Foliage around street light (CVH23) blocking lght		
Location: O/S NO 62	Contact:	
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2164305	Logged by: Verint CRM Connector	on: 17/06/2026 07:26
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction. Location:Pavement. Type:Foliage / Bush		
Location: Overgrown hedges and bushes causing obstruction to people walking past	Contact:	
Enquiry No.: 2160385	Logged by: Verint CRM Connector	on: 09/06/2026 11:24
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction. Location:Pavement. Type:Foliage / Bush		
Location: Badly overgrown foliage here which severely obstructs pedestrian passage along the pavement on the Crawford Road elevation	Contact:	
Enquiry No.: 2157305	Logged by: Verint CRM Connector	on: 03/06/2026 09:41
Service: Roads General	Subject: Trees & Foliage: Defect	Classification: Request for service
Desc.: Problem: Causing Obstruction. Location:Pavement. Type:Foliage / Bush		
Location: Really overgrown hedge here which is obstructing an already narrow and busy pavement near a pedestrian crossing	Contact:	

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2156587 **Logged by:** Verint CRM Connector **on:** 02/06/2026 09:37
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Sorry the photo isn't better but there's trees here which really need trimmed as they protrude well into the pavement and you can't walk past easily now **Contact:**

Enquiry No.: 2156585 **Logged by:** Verint CRM Connector **on:** 02/06/2026 09:35
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Really hard to walk past the trees here as they poke out a couple of feet into the pavement now **Contact:**

Enquiry No.: 2156583 **Logged by:** Verint CRM Connector **on:** 02/06/2026 09:34
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Trees are hanging so low that you need to step into bike lane to get past. Also the foliage is obscuring the traffic light at the pedestrian crossing. I'm worried this is going to cause an accident. **Contact:**

Enquiry No.: 2146471 **Logged by:** Verint CRM Connector **on:** 13/05/2026 10:45
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: The hedge here is overgrown and the pavement is already narrow as there is a bus shelter adjacent. So if you try to walk past you have to step into the road as there's no room between bus stop users and the overgrown hedge. **Contact:**

Enquiry No.: 2133715 **Logged by:** Verint CRM Connector **on:** 20/04/2026 14:17
Service: Roads General **Subject:** Roadworks: General Enquiry **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type unlit Temporary road signs require collection / uplift
Location: Temporary road signs require collection / uplift outside 10 Craigmillar Park EH16 5NE. **Contact:**

Enquiry No.: 2133036 **Logged by:** Verint CRM Connector **on:** 19/04/2026 10:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Several potholes between the 2 crossing islands heading north on Craigmillar Park between Suffolk and E Suffolk Roads **Contact:**

Plot Number: 1.00

Feature Id - Location: Whole Street

Feature Type: Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2133034 Service: Roads General Desc.: Location: Near the crossing island heading north.	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 19/04/2026 10:05 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2133032 Service: Roads General Desc.: Location: Near the crossing island as you turn onto Craigmillar Park heading north.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 19/04/2026 10:02 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2131572 Service: Roads General Desc.: Location: The whole road from Newington Road down to Cameron Toll is a disgrace with potholes, depressions and cracks everywhere!	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 16/04/2026 09:17 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2130790 Service: Roads General Desc.: Location: Road is crumbling and turning into potholes on northbound carriageway.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 14/04/2026 21:44 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2130789 Service: Roads General Desc.: Location: Recurring pothole on southbound carriageway at traffic lights.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 14/04/2026 21:43 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2130228 Service: Roads General Desc.: Location: big hole in road heading towards Edinburgh - outside number 14	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 14/04/2026 08:44 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2130225 Service: Roads General Desc.: Location: outside no. 22 heading into town	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 14/04/2026 08:42 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50195329	Feature Id - Location: Whole Street Defect Number: 42204107	Feature Type: Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2130224 Service: Roads General Desc.: Location: on the junction - huge hole	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 14/04/2026 08:41 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50195328	Feature Id - Location: Whole Street Defect Number: 42204103	Feature Type: Road Asset
Enquiry No.: 2130107 Service: Roads General Desc.: Location: Craigmillar Park from Crawford Road to East Suffolk Park is awful with hundreds of potholes. My bus goes over and in to these pot holes everyday as it's very difficult to avoid. I have disabilities and sadly last week when the bus went over a bad pot hole my back and neck went in to spasm and have now caused my disability to be worse and taking strong painkillers. Please repair this road before any one else's health gets worse!	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 13/04/2026 20:21 Classification: Request for service Contact:
Enquiry No.: 2127730 Service: Roads General Desc.: Location: Massive pothole southbound side of road	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 09/04/2026 10:13 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50194728	Feature Id - Location: Whole Street Defect Number: 42203335	Feature Type: Road Asset
Enquiry No.: 2125788 Service: Roads General Desc.: Location: The whole Road is crumbling away and full of massive potholes which is very dangerous! The whole Road iscan absolute disgrace	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 06/04/2026 10:26 Classification: Request for service Contact:
Enquiry No.: 2122253 Service: Roads General Desc.: Location: Near centre line outside St Margaret's Nursery in northbound lane	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 30/03/2026 14:09 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50194728	Feature Id - Location: Whole Street Defect Number: 42203335	Feature Type: Road Asset
Enquiry No.: 2121142 Service: Roads General Desc.: Location: The surface off this road is horrendous	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 27/03/2026 23:18 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50194728	Feature Id - Location: Whole Street Defect Number: 42203335	Feature Type: Road Asset
Enquiry No.: 2121141 Service: Roads General Desc.: Location: Pothole large	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 27/03/2026 23:13 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50194728	Feature Id - Location: Whole Street Defect Number: 42203335	Feature Type: Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2121140 Service: Roads General Desc.: Location: Road is covered in cracks n holes	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 27/03/2026 23:12 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2121093 Service: Roads General Desc.: Location: A stretch of around 100m heading towards Cameron toll is almost undriveable even though there is 2 lanes - there's not a part of the road you can actually drive on without running the risk of blowing a tyre! Runs from Kildonnán lodge right down passed the Northumberland hotel	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 27/03/2026 20:17 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2119226 Service: Roads General Desc.: Location: Pothole on the road, very poor surfacing all the way up, especially this part. Doesn't appear to be covered by a previous report. Dangerous as people swerve	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 24/03/2026 18:21 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2118258 Service: Roads General Desc.: Location: The road on both side is crumbling badly. It has been in a state of disrepair for a long time and nothing is being done. It is now resulting in traffic swerving to avoid holes (of which there is a huge number in a short stretch of road). At some point soon the state of the road is going to cause an accident.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 23/03/2026 13:05 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2117555 Service: Roads General Desc.: Location: About 20m+ metres of road with dozens of potholes of large sizes. Very hard to miss.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 22/03/2026 13:42 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2117428 Service: Roads General Desc.: Location: Next to the crossing island, massive pothole	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 22/03/2026 10:24 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50194501	Feature Id - Location: Whole Street Defect Number: 42202927	Feature Type: Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2116790 Service: Roads General Desc.: Location: By the island crossing, heading North	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 20/03/2026 14:59 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2116446 Service: Roads General Desc.: Location: Numerous sunken areas and potholes along entire section of road.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 20/03/2026 08:35 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2115905 Service: Roads General Desc.: Location: Category 1 pothole outside travelodge near the traffic lights at the top of lady road. Reported this previously NOTHING DONE!!!!	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 19/03/2026 11:48 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2115791 Service: Roads General Desc.: Location: Very large pothole on road beside kerb outside travel lodge beside traffic lights	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 19/03/2026 09:50 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2115529 Service: Roads General Desc.: Location: pothole outside no. 14	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 18/03/2026 19:26 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2115150 Service: Roads General Desc.: Location: The manhole cover in the carriageway outside of the Kildonan Park Hotel is loose and making a loud rattling sound when vehicles go over it - particularly buses and HGVs. This can be heard several hundred metres away. This is an annoyance and is disturbing the peace, particularly at night when trying to sleep. Please rectify as a matter of some urgency.	Logged by: Verint CRM Connector Subject: Public Utilities: General	on: 18/03/2026 12:02 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 2114203 Service: Roads General Desc.: Location: Pothole	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 17/03/2026 09:12 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026

Service: Roads General

Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 2113247 Logged by: Verint CRM Connector on: 16/03/2026 08:20
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: Multiple potholes from Cameron toll junction along Craigmillar park. Some are now unavoidable and causing damage to cars Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset
 Job Number: 50194072 Defect Number: 42202313

Enquiry No.: 2113156 Logged by: Verint CRM Connector on: 15/03/2026 21:50
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: Near number 23, Road is disintegrating for a long stretch of road Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 2112432 Logged by: Verint CRM Connector on: 14/03/2026 08:12
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: This whole road is a joke just drive on it or take a bus. Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 2112197 Logged by: Verint CRM Connector on: 13/03/2026 15:05
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: The whole bus lane in this section has alot of potholes some deeper than others both category 1 and 2 Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 2112193 Logged by: Verint CRM Connector on: 13/03/2026 15:02
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location: Large potholes at traffic lights outside the travelogue i would say category1 Contact:

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset

Enquiry No.: 2110732 Logged by: Verint CRM Connector on: 11/03/2026 16:57
 Service: Roads General Subject: Road: Defective / Damaged Classification: Request for service
 Desc.:
 Location:  Contact:

Mentioned @edinhelp
 3 minutes ago

@edinhelp hello. Just to report that the road surface has disintegrated on Craigmillar Park, roughly where it meets Wilton Road.

Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset
 Job Number: 50193779 Defect Number: 42201871

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2109641 **Logged by:** Verint CRM Connector **on:** 10/03/2026 08:19
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: The road here is a mess. At one part all the tarmac is gone and you can see the cobbles underneath. It's not just one pothole, the road is crumbling **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50193720 **Defect Number:** 42201808

Enquiry No.: 2108824 **Logged by:** Verint CRM Connector **on:** 08/03/2026 21:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: At traffic light **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 2107484 **Logged by:** Verint CRM Connector **on:** 06/03/2026 05:07
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Road surface southbound at cycle lane uneven and full of potholes. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 2104705 **Logged by:** Verint CRM Connector **on:** 02/03/2026 00:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: South bound carriageway (after morning side station) around the bus stop is converted entirely by potholes. One struggle to stand still on the bus because it's so bumpy **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 2102399 **Logged by:** Verint CRM Connector **on:** 25/02/2026 19:16
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: from 22 Craigmillar Park to just after Suffolk Road (at St Margarets Nursery) there is at least 6 huge holes in the road **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 2100129 **Logged by:** Verint CRM Connector **on:** 22/02/2026 19:20
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: The north bound road is in terrible condition for a few hundred yards. Multiple pot holes, depressions, gaps and large areas of broken surface **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2098012 **Logged by:** Verint CRM Connector **on:** 18/02/2026 17:30
Service: Roads General **Subject:** Covers: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Deep and severely disrupted manhole and associated road surface, caused a major thump on my cars suspension which has only recently been repaired at significant cost. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50192773 **Defect Number:** 42200555

Enquiry No.: 2097807 **Logged by:** Verint CRM Connector **on:** 18/02/2026 13:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: the whole of Craigmillar park and MINTO STREET potholes evey where **Contact:**

Enquiry No.: 2097402 **Logged by:** Verint CRM Connector **on:** 18/02/2026 06:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: there is a number of big holes between 22 Craigmillar Park and St Margarets Nursery just after Suffolk Road heading into town **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 2096688 **Logged by:** Verint CRM Connector **on:** 17/02/2026 08:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 2096035 **Logged by:** Verint CRM Connector **on:** 16/02/2026 11:22
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Bus number 37 at 1115am 16 feb hit a pothole so hard, i have a sore neck as a passenger! **Contact:**

Enquiry No.: 2095889 **Logged by:** Verint CRM Connector **on:** 16/02/2026 09:11
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The road near Kildonan Lodge Hotel on both sides of the road is crumbling and full of potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 2095790 **Logged by:** Verint CRM Connector **on:** 15/02/2026 21:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Entire road is full of potholes and crumbling tarmac, **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2094428 **Logged by:** Verint CRM Connector **on:** 13/02/2026 12:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: This stretch of road is a real embarrassment and danger as it is in essence a series of potholes both emerging and emerged. It has huge bus traffic volumes so desperately needs a proper sustainable fix. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 2094384 **Logged by:** Verint CRM Connector **on:** 13/02/2026 11:25
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Two large potholes on the north side at the traffic lights, on the southbound side of the road beside Travelodge. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 2094153 **Logged by:** Verint CRM Connector **on:** 13/02/2026 06:45
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 2 potholes needing repaired one on the inside lane near the traffic lights at the top of Lady Road and the other on the crossing around the same set of lights. I reported this last week and it was fixed now there is a hole appeared again. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 2093765 **Logged by:** Verint CRM Connector **on:** 12/02/2026 15:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The entirety of Craigmillar Park needs resurfaced. Especially south bound - it is a continuous row of potholes, depressions, and hazards. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 2093641 **Logged by:** Verint CRM Connector **on:** 12/02/2026 14:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole northbound carriageway **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50192769 **Defect Number:** 42200544

Enquiry No.: 2087151 **Logged by:** Verint CRM Connector **on:** 02/02/2026 10:27
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole in middle of road at southbound lights, end of Craigmillar park **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2086878 Service: Roads General Desc.: Location: Pothole at the top of Lady road outside travelogue at the traffic lights	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 01/02/2026 16:41 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50190957	Feature Id - Location: Whole Street Defect Number: 42198282	Feature Type: Road Asset
Enquiry No.: 2086621 Service: Roads General Desc.: Location: Road in poor condition either sunken areas and deeper potholes forming.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 01/02/2026 07:51 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50190959	Feature Id - Location: Whole Street Defect Number: 42198286	Feature Type: Road Asset
Enquiry No.: 2077332 Service: Roads General Desc.: Location: Manhole cover is loose/not closed properly and very noisy with buses driving over it all night long.	Logged by: Verint CRM Connector Subject: Covers: Damaged / Defective	on: 16/01/2026 05:50 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50190959	Feature Id - Location: Whole Street Defect Number: 42198286	Feature Type: Road Asset
Enquiry No.: 2067507 Service: Roads General Desc.: Location: Broken and sunken areas where services have been excavated	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 02/01/2026 12:32 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 2054858	Feature Id - Location: Whole Street Defect Number: 42198286	Feature Type: Road Asset
Enquiry No.: 2054858 Service: Roads General Desc.: Location: Next to cycle track about middle of left hand side of road.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 08/12/2025 12:52 Classification: Request for service Contact:
Enquiry No.: 2054735 Service: Roads General Desc.: Problem: Overgrown. Location:Footpath. Type:Foliage / Bush Location: There are a series of bushes on corner of Craigmillar Park / Lady Road (outside Travelodge) that have overgrown on to the pavement. Now the leaves have gone, it has left a large number of branches sticking out a body/eye level that are dangerous, especially when trying to pass a pedestrian coming in the other direction (as the bushes encroach on the current pavement). The bushes - particularly the spikey branches that are sticking out - need trimming urgently	Logged by: Verint CRM Connector Subject: Trees & Foliage: Defect	on: 08/12/2025 10:34 Classification: Request for service Contact:

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2054368 **Logged by:** Verint CRM Connector **on:** 07/12/2025 13:21
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Outside 14 Craigmillar Park. 3 large potholes and a section of broken road surface **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50188230 **Defect Number:** 42194891

Enquiry No.: 2051915 **Logged by:** Verint CRM Connector **on:** 01/12/2025 17:04
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Multiple sunken and areas of broken road surface. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 2042071 **Logged by:** Verint CRM Connector **on:** 12/11/2025 14:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The road surface between Peel Terrace all the way along the length of Craigmillar Park to Lady Road is a disgrace. This is a length of road which has what can only be described as a trench. This makes it impossible to miss during live bus lane times. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 2035310 **Logged by:** Verint CRM Connector **on:** 30/10/2025 07:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 12 inch potholes (multiple)
Report ID: 8354126 **Contact:**

Category: Potholes

These pot holes have been here for over a year and are getting worse. An old road repair has also collapsed.

Location:
Easting/Northing: 327046/671245 (55.928717, -3.169153)
Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 30, Craigmillar Park, Newington, City of Edinburgh, Alba / Scotland, EH16 5PS, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH1

Enquiry No.: 2035242 **Logged by:** Verint CRM Connector **on:** 29/10/2025 20:16
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pot holes southbound lane **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 2035033 Service: Roads General Desc.: Location: Very deep pothole just before traffic lights	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 29/10/2025 13:40 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50186245	Feature Id - Location: Whole Street Defect Number: 42192220	Feature Type: Road Asset
Enquiry No.: 2026519 Service: Roads General Desc.: Location: At traffic light, middle of road southbound	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 10/10/2025 14:31 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50185551	Feature Id - Location: Whole Street Defect Number: 42191136	Feature Type: Road Asset
Enquiry No.: 2024881 Service: Roads General Desc.: Problem: Obscuring sign/light. Location:Pavement. Type:Foliage / Bush Location: Unfortunately the big tree here is totally obstructing the streetlight (looks like CVH05) and so the street is black. I almost bumped into a man last night as I didn't see him until the last second. Please can this be addressed urgently? Thanks.	Logged by: Verint CRM Connector Subject: Trees & Foliage: Defect	on: 07/10/2025 12:34 Classification: Request for service Contact:
Enquiry No.: 2015336 Service: Roads General Desc.: Location: CRAIGMILLAR PARK Between junctions at East Savile Road and Lygon Road on both sides the surface of the road is irregular with numerous pits and troughs. Going south drivers switch between the various lanes to try to find a smooth route. This road is such a MAIN thoroughfare into the City and is in CONSTANT use and I feel it is time for a major upgrade. EAST MAYFIELD Surface eroded at some points - this is the worst at the east end.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 17/09/2025 10:36 Classification: Request for service Contact:
Enquiry No.: 2011981 Service: Roads General Desc.: Location: Like so many streets in the city this stretch of road has a series of pot holes which are increasing in size and number.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 10/09/2025 12:49 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1968298 Service: Roads General Desc.: Location: double iron work has sunk into the ground causing a sunken pothole as you go over it	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 24/06/2025 14:37 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1959370 **Logged by:** Verint CRM Connector **on:** 05/06/2025 23:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: there is a stretch of road starting at 18 Craigmillar Park down to 32 Craigmillar Park where the road is collapsed, has deep pot holes and is in a state of disrepair. Some of the pot holes are 10 cm deep **Contact:**

Enquiry No.: 1957870 **Logged by:** Verint CRM Connector **on:** 03/06/2025 13:11
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The road heading out of the city has a long row of potholes. I reported this already but the issue has not been flagged as in need of repair. There are holes of approx 10 cm in depth. Why will no repair be scheduled? I note that Gilmour Road has recently been re-tarmaced in full and there was little wrong with the road surface. Thank you. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1956679 **Logged by:** Verint CRM Connector **on:** 31/05/2025 23:58
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The lane heading out of the city has multiple pot holes in a row in front of our property. When large vehicles, for example buses, pass over the row of pot holes, it causes terrific noise and vibrates throughout our property. The situation must also cause significant wear and tear to our invaluable bus services. Could you please kindly come and check the situation and order a repair? Many thanks. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1953510 **Logged by:** Verint CRM Connector **on:** 26/05/2025 13:39
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Low hanging trees, unable to walk underneath without doing a limbo dance. Not at my age! **Contact:**

Enquiry No.: 1950638 **Logged by:** Verint CRM Connector **on:** 20/05/2025 11:41
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: Tress and bushes growing over onto pavement **Contact:**

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1947241 **Logged by:** Verint CRM Connector **on:** 13/05/2025 11:38
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole on Southern bound carriageway of Craigmillar Park. Hole in between 2 repaired areas of road. **Contact:**

I have photos but can't make them small enough for your system.

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50179889 **Defect Number:** 42183494

Enquiry No.: 1923136 **Logged by:** Verint CRM Connector **on:** 24/03/2025 21:51
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: There is a constant flow of water leaking from the entrance of the property at the pavement. The picture show the view southwards and the leak is soaking the pavement and filling the gutter. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1922904 **Logged by:** Verint CRM Connector **on:** 24/03/2025 14:39
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: opp number 18 there is a pot from where a bus stop pole is is a hole lady had a fall and hurt face **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1921847 **Logged by:** Verint CRM Connector **on:** 21/03/2025 19:01
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Pavement flooded outside No. 58 Craigmillar Park. **Contact:**
There appears a leaking drain causing the public footpath to be covered in water and silt. This problem has existed for 5+years and is getting worse.
This is now a hazard to all pedestrians walking past this property. During heavy rain and icy conditions results in the public having to use the highway to avoid the water and dirt on the footpath.

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1917748 **Logged by:** Verint CRM Connector **on:** 13/03/2025 16:07
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50176933 **Defect Number:** 42178650

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1916160 **Logged by:** Verint CRM Connector **on:** 11/03/2025 06:15
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:

Location: You recently reported an issue with a road (ref number 101002956732). The nearest property to the location is: 58A/2, CRAIGMILLAR PARK, EDINBURGH, EH16 5PT
We've checked this issue and found that it is the responsibility of another organisation or on private property.
We'll contact them to make them aware of the issue. They have not fixed the issue and it is just the same. Water running over pavement at 58B then along road to the drain.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1914593 **Logged by:** Verint CRM Connector **on:** 07/03/2025 11:22
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.

Location:Pavement.
Type:Foliage / Bush

Location: It's the railway bridge over the south suburban line, Craigmillar Park, east side of the street - there's foliage coming up from the embankment and it's now growing over the wall and obstructing the pavement. I got hit on the head by a branch last night. No injury but it is potentially dangerous.

Contact:

Enquiry No.: 1911708 **Logged by:** Verint CRM Connector **on:** 01/03/2025 20:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Gas pipe access cover is badly damaged & is being constantly impacted by traffic (mainly buses & heavy vehicles). Have previously smelt gas intermittently from the damaged cover over the last few days.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50176248 **Defect Number:** 42177626

Enquiry No.: 1908404 **Logged by:** Verint CRM Connector **on:** 24/02/2025 08:59
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Pothole on northbound carriageway
Category: Potholes

Contact:

Pothole around ironwork, tarmac has failed and is full of water

Location:
Easting/Northing: 327177/671006 (55.926594, -3.167004)
Nearest road to the pin placed on the map (automatically generated by OpenStreetMap): 62, Craigmillar Park, Newington, City of Edinburgh, Alba / Scotland, EH16 5PU, United Kingdom
Nearest postcode to the pin placed on the map (automatically generated): EH16 5PU (29m away)

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50175729 **Defect Number:** 42176834

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1906169
Service: Roads General
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Lots of branches extending well into the pavement area. Some are wee spindly things you can't see easily and you only know about it when they spike you in the face! For people's safety could this be trimmed back please.

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 19/02/2025 17:45
Classification: Request for service

Contact:

Enquiry No.: 1905199
Service: Roads General
Desc.:
Location: Reference Number: 101002903008.
I reported water pouring over the pavement on 10th January which had frozen into a sheet of ice. After this I noticed there was a barrier put around the leak at 38B Craigmillar Park, a hole dug, the hole tarred over and the barrier removed. However the water is still pouring over the pavement forom the samespot. See photos from 17th February.

Logged by: Verint CRM Connector
Subject: Pavement: Damaged / Defective

on: 18/02/2025 07:19
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1900970
Service: Roads General
Desc.:
Location: The road has a nasty pothole from Cameron toll shopping centre up towards touch of Poland shop. It is weird that this road is not fixed considering it is a main city road

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 09/02/2025 11:20
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1900966
Service: Roads General
Desc.:
Location: The road has a nasty pothole from Cameron toll shopping centre up towards touch of Poland shop. It is weird that this road is not fixed considering it is a main city road

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 09/02/2025 11:17
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1895438
Service: Roads General
Desc.:
Location: Area of road outside Kildonan Lodge hotel and beyond is all broken up. ??

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 29/01/2025 22:34
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50174110 **Defect Number:** 42174722

Enquiry No.: 1895395
Service: Roads General
Desc.:
Location: Potholes streching for 30 yards going towards cameron toll

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 29/01/2025 20:25
Classification: Request for service

Contact:

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1891662 Service: Roads General Desc.: Location: Sunken road in several places close to where bus lane starts.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 23/01/2025 23:55 Classification: Request for service Contact:
Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset		
Enquiry No.: 1890806 Service: Roads General Desc.: Problem: Causing Obstruction. Location:Pavement. Type:Foliage / Bush Location: There's a bush or little tree here which now goes way beyond the property boundary and eats into the pavement space. It's causing an obstacle for pedestrians, especially when the street is busy and you need to step into the bike lane to pass people.	Logged by: Verint CRM Connector Subject: Trees & Foliage: Defect	on: 22/01/2025 13:04 Classification: Request for service Contact:
Enquiry No.: 1889627 Service: Roads General Desc.: Called this afternoon to report that a cycle post & the concrete base that was removed by the team that were repairing the road (for access) have now left the area but have left the post & the concrete base on the pavement in front of No. 48. Please can this be removed asap as it is a trip hazard Location: on the pavement in front of No. 48	Logged by: Subject: Pavement: Damaged / Defective	on: 20/01/2025 13:34 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50173335 Feature Id - Location: Whole Street Defect Number: 42173677 Feature Type: Road Asset		
Enquiry No.: 1884649 Service: Roads General Desc.: Location: The whole road is a disgrace broken uneven surface full of potholes! Very dangerous!	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 11/01/2025 00:22 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50173091 Feature Id - Location: Whole Street Defect Number: 42173364 Feature Type: Road Asset		
Enquiry No.: 1884427 Service: Roads General Desc.: Location: Constant water or ice on pavement. Reported to Scottish water but no change. Pavement is hazardous. Attached photo was taken today when the rest of the pavement was dry.	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 10/01/2025 14:45 Classification: Request for service Contact:
Plot Number: 1.00 Feature Id - Location: Whole Street Feature Type: Road Asset		
Enquiry No.: 1884017 Service: Roads General Desc.: Location: 58 B Craigmillar ParkThere has been water running over the pavement for months. Due to the cold weather now this is now a sheet of ice	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 10/01/2025 06:29 Classification: Request for service Contact:

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1870850 Service: Roads General Desc.: Location: sunken iron work here in the middle of the junction	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 13/12/2024 14:16 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50171531	Feature Id - Location: Whole Street Defect Number: 42171337	Feature Type: Road Asset
Enquiry No.: 1870579 Service: Roads General Desc.: Location: Deep pothole just beyond traffic lights. Hard to avoid.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 12/12/2024 21:04 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50170949	Feature Id - Location: Whole Street Defect Number: 42170662	Feature Type: Road Asset
Enquiry No.: 1867457 Service: Roads General Desc.: Location: One of the cycle lane bollards is tipping over into the cycle lane. The pole is sticking into the cycle lane and the base of the bollard is detached from the road. b	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 05/12/2024 10:31 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50170949	Feature Id - Location: Whole Street Defect Number: 42170662	Feature Type: Road Asset
Enquiry No.: 1856110 Service: Roads General Desc.: Location: Picture the largest medicine ball you can think of - it would fit snugly inside this hole. Map location is approximate but within a hundred metres either side I think. Looks like the road surface is intact, but has sunk into the ground (and it has got deeper since the last time I passed it).	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 08/11/2024 12:39 Classification: Request for service Contact:
Enquiry No.: 1843602 Service: Roads General Desc.: Location: Opposite the kirk, just north of the Crawford Road junction, there is a large crumbling bit of tar around an inspection cover. Really dangerous for cyclists.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 11/10/2024 19:31 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50168023	Feature Id - Location: Whole Street Defect Number: 42166586	Feature Type: Road Asset
Enquiry No.: 1833904 Service: Roads General Desc.: Location: 20ft prior to bus stop, manhole sinking/collapsing	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 19/09/2024 11:51 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50168023	Feature Id - Location: Whole Street Defect Number: 42166586	Feature Type: Road Asset
Enquiry No.: 1832291 Service: Roads General Desc.: Pothole around cover - Craigmillar Park. Location: Opposite the kirk, just north of the Crawford Road junction,	Logged by:  Subject: Road: Defective / Damaged	on: 16/09/2024 09:08 Classification: Request for service Contact:

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1823354 **Logged by:** Verint CRM Connector **on:** 28/08/2024 08:09
Service: Roads General **Subject:** Traffic Sign:Defective/Damaged **Classification:** Request for service
Desc.: What type of sign is it? Road sign problem, type unlit
Location: Traffic lights not on **Contact:**

Enquiry No.: 1823012 **Logged by:** Verint CRM Connector **on:** 27/08/2024 13:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pedestrian crossing lights out. Extra traffic making crossing difficult **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1822847 **Logged by:** Verint CRM Connector **on:** 27/08/2024 09:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The pedestrian crossing lights are broken. This is causing a serious danger to pedestrians trying to cross the road! I was nearly hit by a car this morning as I crossed at the island at Ventnor Terrace when a car drove up the wrong side of the road, narrowly missing my dog. The pedestrian crossing is there for a reason! It has been out of action for some time now- why?! **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1821307 **Logged by:** Verint CRM Connector **on:** 23/08/2024 16:00
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The road surface is broken on the southbound carriageway causing excessive vibration and noise disturbance. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1819489 **Logged by:** Verint CRM Connector **on:** 20/08/2024 13:46
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Traffic lights not working (and haven't been for two days). Traffic lights are right next to craigmillar park church , the restaurant Haldi and meet the entrance to the Newington residence development. **Contact:**

Can't see where else to report this problem- note there's nothing wrong with the pavement or road. It's just traffic lights

Enquiry No.: 1815839 **Logged by:** Verint CRM Connector **on:** 14/08/2024 09:11
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: The road surface & sub surface around a access cover has broken up a lot, and the cover and it's mount is also now rocking **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1815280 **Logged by:** Verint CRM Connector **on:** 13/08/2024 10:58
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Big bush or tree which is very unkempt and takes up a lot of the pavement space **Contact:**

Enquiry No.: 1815276 **Logged by:** Verint CRM Connector **on:** 13/08/2024 10:55
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Really excessive foliage, cutting most of the pavement space. Impossible to get past people coming the other way without walking into the road **Contact:**

Enquiry No.: 1811421 **Logged by:** Verint CRM Connector **on:** 06/08/2024 10:02
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: The foliage is so overgrown here that pedestrians struggle to get by. And if someone is standing waiting at the traffic crossing you have no choice but to stop and wait for them to move on the green man, or to step into the traffic to get around them. Dangerous. **Contact:**

Enquiry No.: 1807249 **Logged by:** Verint CRM Connector **on:** 29/07/2024 14:21
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: On road outside 1 Craigmillar Park, there is a loose/broken manhole cover which clatters each time a vehicle drives over it. We cannot sleep due to the noise of this as there is traffic on that road through the night. PLEASE can you sort it for us? **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50164804 **Defect Number:** 42162904

Enquiry No.: 1792081 **Logged by:** Verint CRM Connector **on:** 03/07/2024 13:42
Service: Roads General **Subject:** Public Utilities: General **Classification:** Request for service
Desc.:
Location: sunnken ironwork causing bang when going over **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1789734 **Logged by:** Verint CRM Connector **on:** 29/06/2024 08:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50163154 **Defect Number:** 42160620

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1774436
Service: Roads General
Desc.: Problem: Overgrown.
Location: Road.
Type: Foliage / Bush
Location: Bus antenna and risk of broken windows possibly in church grounds

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 06/06/2024 15:10
Classification: Request for service

Contact:

Enquiry No.: 1774434
Service: Roads General
Desc.:
Location: Outside Craigmillar Park Church at the bus stop

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 06/06/2024 15:05
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1766064
Service: Roads General
Desc.:
Location: sunken man hole causing pothole here

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 29/05/2024 10:26
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50161335 **Defect Number:** 42158368

Enquiry No.: 1737662
Service: Roads General
Desc.:
Location: Railings on pedestrian crossing island at Craigmillar park/lady road have been damaged again

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 16/04/2024 15:36
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50158649 **Defect Number:** 42155030

Enquiry No.: 1734289
Service: Roads General
Desc.:
Location: Potholes over a whole section

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 10/04/2024 14:08
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1731381
Service: Roads General
Desc.:
Location: ALL ALONG THE ROAD FROM CRAWFURD ROAD TO THE MAJOR TRAFFIC LIGHTS TO TRAVEL LODGE OF LADY REAOD ALONG A701DAMAGED ROAD CARS ARE SWERVING BADLY ON THE OTHER SIDE TO DODGE THE DAMGED POT HOLES

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 06/04/2024 08:34
Classification: Request for service

Contact:

Enquiry No.: 1728907
Service: Roads General
Desc.:
Location: Pothole

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 03/04/2024 08:37
Classification: Request for service

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50157813 **Defect Number:** 42154112

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1726736 **Logged by:** Verint CRM Connector **on:** 29/03/2024 11:40
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: The cycle path full length of Craigmillar Park, lots of debris from numerous pot holes, uneven surfaces, sunken sections that gather water when raining. Needs a good clean and fixed. Its dangerous and a hazard to cyclists. The bollards also needs fixed at certain points as have been hit by cars and are a danger to cyclists **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1726732 **Logged by:** Verint CRM Connector **on:** 29/03/2024 11:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: The cycle path full length of Craigmillar Park, lots of debris from numerous pot holes, uneven surfaces, sunken sections that gather water when raining. Needs a good clean **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1726710 **Logged by:** Verint CRM Connector **on:** 29/03/2024 11:13
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Pot Hole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50157794 **Defect Number:** 42154070

Enquiry No.: 1725090 **Logged by:** Verint CRM Connector **on:** 26/03/2024 21:31
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: The bollard separating the cycle lane from the rest of the road is not bolted down onto the road and is causing a hazard for cyclists. It is the bollard at the corner of Craigmillar Park and East Suffolk Road as you are travelling to Cameron Toll. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50156946 **Defect Number:** 42153172

Enquiry No.: 1724573 **Logged by:** Verint CRM Connector **on:** 26/03/2024 09:08
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: CRAIGMILLAR PARK towards Cameron Toll, just after the junction with Suffolk Rd. There is a pothole in the middle of the line, just after pedestrian lights. Then the surface is damaged on both lines until crossing with Wilton Rd. **Contact:**

Enquiry No.: 1723824 **Logged by:** Verint CRM Connector **on:** 25/03/2024 06:36
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:

Location: Pothole just outside (south) of pedestrian crossing **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50156781 **Defect Number:** 42152952

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1723394 **Logged by:** Verint CRM Connector **on:** 23/03/2024 16:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.: Claim form emailed 5/4/24 - On Thursday 21 March I was travelling down Craigmillar Park road around 7:30pm when I had to park immediately emergency after going in a massive pothole. I really felt the pressure and it was quite frightening actually. My tyre was flat and I had to wait an hour and a half before a family friend who owns a garage on Ferry Road came to help me. I have reported the issue on the EC website but felt the need to write this email because of the time, stress and financial hardship this issue caused.
Location: Huge, deep pothole. Couldn't take photo as was heavy traffic but you can't miss it. **Contact:**
Closest address will probably be 16 craigmillar park.

Enquiry No.: 1722866 **Logged by:** Verint CRM Connector **on:** 22/03/2024 11:57
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Massive deep dangerous pothole in road on South bound side, outside no 19 Craig Park just past traffic light going south **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50156747 **Defect Number:** 42152901

Enquiry No.: 1721912 **Logged by:** Verint CRM Connector **on:** 21/03/2024 08:19
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Obscuring sign/light.
Location:Footpath.
Type:Foliage / Bush
Location: Tree completely obscuring the streetlight. Tree branches have grown through the lamp standard and completely engulfed the light. This issue will be exacerbated further when leaf growth begins. **Contact:**

Enquiry No.: 1721782 **Logged by:** Verint CRM Connector **on:** 20/03/2024 20:19
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Massive pothole which may have damaged my vehicle **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50156508 **Defect Number:** 42152495

Enquiry No.: 1714473 **Logged by:** Verint CRM Connector **on:** 08/03/2024 13:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: All along this stretch of road is terrible for potholes. There is a ditch pothole forming in the middle of the road. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50155667 **Defect Number:** 42151421

Enquiry No.: 1706115 **Logged by:** Verint CRM Connector **on:** 24/02/2024 16:46
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Huge deep pothole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1702161 Service: Roads General Desc.: Location: Rather deep pothole close to the pavement and in the line of left tyres of vehicles	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 19/02/2024 10:43 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50153208	Feature Id - Location: Whole Street Defect Number: 42147975	Feature Type: Road Asset
Enquiry No.: 1700209 Service: Roads General Desc.: Location: 12 inch circular pothole before stop line 3-4 inches deep	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 15/02/2024 16:23 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50152862	Feature Id - Location: Whole Street Defect Number: 42147436	Feature Type: Road Asset
Enquiry No.: 1698073 Service: Roads General Desc.: Location: Crossing island railings are damaged; esslemont road and Craigmillar park	Logged by: Verint CRM Connector Subject: Fence: Damaged / Defective	on: 12/02/2024 16:44 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50152862	Feature Id - Location: Whole Street Defect Number: 42147436	Feature Type: Road Asset
Enquiry No.: 1694308 Service: Roads General Desc.: Location: The pavements from Lygon road heading north into the city centre	Logged by: Verint CRM Connector Subject: Pavement: Damaged / Defective	on: 06/02/2024 15:18 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50152366	Feature Id - Location: Whole Street Defect Number: 42146662	Feature Type: Road Asset
Enquiry No.: 1693442 Service: Roads General Desc.: Location: Westbound, two potholes between traffic lines. One next to the manhole.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 05/02/2024 14:30 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50150806	Feature Id - Location: Whole Street Defect Number: 42144701	Feature Type: Road Asset
Enquiry No.: 1682069 Service: Roads General Desc.: Location: Middle of road close to 33	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 21/01/2024 10:47 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50149817	Feature Id - Location: Whole Street Defect Number: 42143656	Feature Type: Road Asset
Enquiry No.: 1674782 Service: Roads General Desc.: Location: Pot hole in cycle lane	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 09/01/2024 16:58 Classification: Request for service Contact:

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1674284 Service: Roads General Desc.: Location: Pothole near bus stop, direction to the city	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 09/01/2024 08:47 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50149696	Feature Id - Location: Whole Street Defect Number: 42143543	Feature Type: Road Asset
Enquiry No.: 1671163 Service: Roads General Desc.: Location: Failed iron work near the manhole cover	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 04/01/2024 11:26 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50149186	Feature Id - Location: Whole Street Defect Number: 42143069	Feature Type: Road Asset
Enquiry No.: 1669060 Service: Roads General Desc.: Location: Sunken drain creating pothole after road has been displaced	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 31/12/2023 15:22 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50149186	Feature Id - Location: Whole Street Defect Number: 42143071	Feature Type: Road Asset
Enquiry No.: 1668191 Service: Roads General Desc.: Location: Very long damage to road surface in bus lane adjacent to bus stop on northbound side of road . Lots of debris.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 29/12/2023 11:10 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50149188	Feature Id - Location: Whole Street Defect Number: 42143071	Feature Type: Road Asset
Enquiry No.: 1664786 Service: Roads General Desc.: Location: On 13/12/23 while heading to work, i ran through a huge pothole in middle of road located on map i selected. The car had a blowout due to hole left in tyre and was effectively stranded as car doesnt have a spare wheel. I was able to get to a nearby National tyres centre that also diagnosed a bulging and nicked rear tyre from pothole. They fitted a cheap temp tyre on front(only 1 in stock) and im getting it and the other damaged tyre replaced with the same make i had tomorrow 21/12/23	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 20/12/2023 17:15 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1661812 **Logged by:** Verint CRM Connector **on:** 14/12/2023 16:11
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large and very deep pot hole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1661171 **Logged by:** Verint CRM Connector **on:** 13/12/2023 17:47
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Hi, this one has recently opened up a lot when I cycled past it. Car suspension sounded like it was bottoming out. Thanks **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1659022 **Logged by:** Verint CRM Connector **on:** 10/12/2023 19:29
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: In the middle of the cycle lane. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1658465 **Logged by:** Verint CRM Connector **on:** 09/12/2023 13:04
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Dangerous large deep double pothole on corner of Craigmillar Park and East Suffolk Park , in cycleway on way out of town - towards Cameron Toll direction- will cause cycle accident if not urgently repaired **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50147682 **Defect Number:** 42141564

Enquiry No.: 1651210 **Logged by:** Verint CRM Connector **on:** 27/11/2023 08:21
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Other.
Location:Pavement.
Type:Foliage / Bush
Location: The pavement on the right hand side of Craigmillar park (heading south, out of the city centre) is still covered in fallen leaves. The worse area is between Lygon road and east saville road. A suction machine would lift these very quickly. Can you please help ? Thanks **Contact:**

Enquiry No.: 1649768 **Logged by:** Verint CRM Connector **on:** 23/11/2023 20:31
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service
Desc.: Problem: Causing Obstruction.
Location:Footpath.
Type:Foliage / Bush
Location: All craigmillar park footpaths are covered by huge amount of dead dump leaves which make the surface extremely slippery, obstruct gullies and footpaths. **Contact:**

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1647321 Service: Roads General Desc.: Location: Cones and wreckage on road	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 20/11/2023 11:23 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1644349 Service: Roads General Desc.: Location: Total chaos with traffic at the junctions	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 14/11/2023 18:30 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1643732 Service: Roads General Desc.: Location: Large sunken ironwork southbound lane. Please enforce repair	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 13/11/2023 19:08 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1641998 Service: Roads General Desc.: Location: About a foot across, six inch deep, would not want to hit on a bicycle	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 10/11/2023 08:33 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50145522	Feature Id - Location: Whole Street Defect Number: 42139279	Feature Type: Road Asset
Enquiry No.: 1639037 Service: Roads General Desc.: Location: The whole road is full of pot holes and crumbling tarmac very dangerous	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 05/11/2023 15:48 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50145117	Feature Id - Location: Whole Street Defect Number: 42138757	Feature Type: Road Asset
Enquiry No.: 1638440 Service: Roads General Desc.: Location: Huge pothole very deep on bus stop section of the road,. I nearly fell off my bike going over it. You will not miss it	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 03/11/2023 19:03 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50145118	Feature Id - Location: Whole Street Defect Number: 42138758	Feature Type: Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1627162 **Logged by:** Verint CRM Connector **on:** 12/10/2023 13:20
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: Two problems with this section of road, reflected by the Black and Red Arrows which I will address below, also this is taken from Google Street view since my image failed to save

Contact:

Black Arrow:

The cover here is loose and requires to be fixed into position again since it has become loose from its mountings can this be repaired

Red Arrow:

Right here is where a pothole has developed and could this be patched soon please?

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50143958 **Defect Number:** 42137478

Enquiry No.: 1623618 **Logged by:** Verint CRM Connector **on:** 05/10/2023 11:46
Service: Roads General **Subject:** Trees & Foliage: Defect **Classification:** Request for service

Desc.: Problem: Causing Obstruction.

Location:Pavement.

Type:Foliage / Bush

Location: The hedge cuts off most of the pavement here. It's also just about touching the adjacent postbox now, making a real pavement bottleneck.

Contact:

Enquiry No.: 1601034 **Logged by:** Verint CRM Connector **on:** 20/08/2023 20:32
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: The road surface is uneven and breaking up. This is causing a substantial increase in vibration and noise from vehicles which can be felt on the top floor of an adjacent building. The increase in noise and vibration causes noise and disturbance to residents and I am concerned that the vibration/rumbling will also cause structural damage to buildings.

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50141283 **Defect Number:** 42134461

Enquiry No.: 1591252 **Logged by:** Verint CRM Connector **on:** 02/08/2023 12:49
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service

Desc.:

Location: Outside 60 Craigmillar park there are massive puddles and they are soaking people as they pass

Contact:

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50140324 **Defect Number:** 42133186

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1572886
Service: Roads General
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: The hedge here is now very overgrown and takes up more than half of the pavement.

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 27/06/2023 17:23
Classification: Request for service

Contact:

Enquiry No.: 1572885
Service: Roads General
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: The hedge here is now so overgrown that I had to step into the cycle lane today as the usable pavement is only narrow enough (barely) for one person at a time. Can this be fixed asap please as it is potentially dangerous.

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 27/06/2023 17:21
Classification: Request for service

Contact:

Enquiry No.: 1571996
Service: Roads General
Desc.:
Location: Dear Team,

Logged by: Verint CRM Connector
Subject: Road: General Enquiry

on: 26/06/2023 09:59
Classification: Customer Emergency

Contact:

Just to let you know that again one of the poles is missing from the grey mounts that form the cycle lane on the Mayfield gardens stretch of A701 going from town towards Cameron Toll. The missing pole is on the left hand side of the road (travelling towards Cameron Toll) a bit after the East Savile Road bus stop on left and I think before the St Margaret's care home on right. Again it is potentially lethal to cyclists as the grey base mounts are pretty invisible without the poles,

Plot Number: 1.00
Job Number: 50138337

Feature Id - Location: Whole Street
Defect Number: 42130697

Feature Type: Road Asset

Enquiry No.: 1570887
Service: Roads General
Desc.:
Location: Bike lanes are completely broken up

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 22/06/2023 22:15
Classification: Request for service

Contact:

Plot Number: 1.00
Feature Id - Location: Whole Street
Feature Type: Road Asset

Enquiry No.: 1563281
Service: Roads General
Desc.:
Location: Deep pothole in main road caused punctured run flat tyre

Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged

on: 07/06/2023 10:21
Classification: Request for service

Contact:

Plot Number: 1.00
Job Number: 50137446

Feature Id - Location: Whole Street
Defect Number: 42129638

Feature Type: Road Asset

Enquiry No.: 1550383
Service: Roads General
Desc.:
Location: Broken footway surface. An elderly lady had a bad fall here.

Logged by: Verint CRM Connector
Subject: Pavement: Damaged / Defective

on: 12/05/2023 17:04
Classification: Request for service

Contact:

Plot Number: 1.00
Feature Id - Location: Whole Street
Feature Type: Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1545493 **Logged by:** Verint CRM Connector **on:** 01/05/2023 21:01
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Deep depression in road carriage between the kerb and cycle path bollard holder bolted to road. Due to the people for spaces bollard holder, it makes negotiating around the deep depression challenging **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1541946 **Logged by:** Verint CRM Connector **on:** 24/04/2023 13:13
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: There is a hole/trench in the pavement. I saw an elderly lady trip and have also previously seen a wheelchair stuck here. There are many smaller defects all along this section. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50135048 **Defect Number:** 42126041

Enquiry No.: 1541798 **Logged by:** Verint CRM Connector **on:** 24/04/2023 10:21
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: This road is full of potholes and ripples and a bad surface all the way down to the Lady Road junction. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50135051 **Defect Number:** 42126044

Enquiry No.: 1541599 **Logged by:** Verint CRM Connector **on:** 23/04/2023 17:28
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pot hole **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50134881 **Defect Number:** 42125893

Enquiry No.: 1537769 **Logged by:** Verint CRM Connector **on:** 15/04/2023 20:12
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Crumbling Road. 2 days ago new horizontal lines painted on top, shame! **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1537767 **Logged by:** Verint CRM Connector **on:** 15/04/2023 20:09
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 3x Crumbling surface and potholes **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50134356 **Defect Number:** 42125299

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1537766 Service: Roads General Desc.: Location: Pothole	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 15/04/2023 20:07 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50134357	Feature Id - Location: Whole Street Defect Number: 42125300	Feature Type: Road Asset
Enquiry No.: 1537764 Service: Roads General Desc.: Location: Big pothole	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 15/04/2023 19:59 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50134365	Feature Id - Location: Whole Street Defect Number: 42125308	Feature Type: Road Asset
Enquiry No.: 1527401 Service: Roads General Desc.: Location: Pothole/road crumbling is between numbers 12 & 14 Craigmillar Park heading in to town. Thank you.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 23/03/2023 16:21 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50133149	Feature Id - Location: Whole Street Defect Number: 42124054	Feature Type: Road Asset
Enquiry No.: 1518523 Service: Roads General Desc.: Location: Road is need of refurbishment from the start of Craigmillar Park to East Mayfield. The road is in a shocking state and isn't fit for public use.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 04/03/2023 12:12 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1518305 Service: Roads General Desc.: Location: There are 2 potholes in the northbound lane	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 03/03/2023 15:33 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50131182	Feature Id - Location: Whole Street Defect Number: 42121377	Feature Type: Road Asset
Enquiry No.: 1517775 Service: Roads General Desc.: Pothole Location: Near the travelodge, uptowards minto street on the opposite side	Logged by: [REDACTED] Subject: Road: Defective / Damaged	on: 02/03/2023 13:06 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50130953	Feature Id - Location: Whole Street Defect Number: 42120951	Feature Type: Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1515109 **Logged by:** Verint CRM Connector **on:** 24/02/2023 16:04
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Damaged and dislodged segregation unit post. Due to the missing post element the base unit is less visible and is a hazard to road users and pedestrians. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1515095 **Logged by:** Verint CRM Connector **on:** 24/02/2023 15:43
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Damaged and dislodged segregation unit which been moved off the carriageway as it was causing a hazard to road users and is now on the footway. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1513478 **Logged by:** Verint CRM Connector **on:** 21/02/2023 18:48
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Dangerous deep pothole in centre of road. **Contact:**
Category: Potholes

Pothole easily capable of breaking an alloy wheel.

Location:

Easting/Northing: 327095/671164 (55.928, -3.168354)

Nearest road to the pin placed on the map (automatically generated by Bing Maps):

33-35 Craigmillar Park, Cameron Toll, EH16 5PE, Scotland, United Kingdom

Nearest postcode to the pin placed on the map (automatically generated): EH16

5NZ (67m away)

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50130624 **Defect Number:** 42120545

Enquiry No.: 1493472 **Logged by:** Verint CRM Connector **on:** 16/01/2023 13:44
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: There are several potholes in the northbound lane, next to the cycle lane **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50127596 **Defect Number:** 42116548

Enquiry No.: 1483566 **Logged by:** Verint CRM Connector **on:** 03/01/2023 16:35
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: Until 3wks ago there was a well used pavement bin at the bus stop . This has been removed . Why? It is the only bin for quite some distance and was well used by both bus users and also locals collecting pavement litter in the area. As I am paying G band CT I feel we should have such facilities. . **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1480330 Service: Roads General Desc.: Location: LARGE DEVELOPING POTHOLE	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 28/12/2022 08:55 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50124977	Feature Id - Location: Whole Street Defect Number: 42113841	Feature Type: Road Asset
Enquiry No.: 1424909 Service: Roads General Desc.: Location: there is a trench just before the pedestrian crossing	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 18/08/2022 11:04 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1413809 Service: Roads General Desc.: Location: Depression in road around drain gully in the path of the cycle lane.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 27/07/2022 21:28 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1413808 Service: Roads General Desc.: Location: Depression next to drain gully in the path of the cycle lane.	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 27/07/2022 21:25 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1413807 Service: Roads General Desc.: Location: Crumbling road surface around drain gully and in the path of the cycle lane	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 27/07/2022 21:23 Classification: Request for service Contact:
Plot Number: 1.00 Job Number: 50116944	Feature Id - Location: Whole Street Defect Number: 42163261	Feature Type: Road Asset
Enquiry No.: 1413804 Service: Roads General Desc.: Location: Broken repair in road crumbling	Logged by: Verint CRM Connector Subject: Road: Defective / Damaged	on: 27/07/2022 21:21 Classification: Request for service Contact:
Plot Number: 1.00	Feature Id - Location: Whole Street	Feature Type: Road Asset
Enquiry No.: 1403492 Service: Roads General Desc.: Problem: Other. Location:Footpath. Type:Foliage / Bush Location: There is a tree swing in the park tied to one of the branches which needs to be cut down.	Logged by: Verint CRM Connector Subject: Trees & Foliage: Defect	on: 07/07/2022 13:43 Classification: Request for service Contact:

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1395191
Service: Roads General
Desc.: Problem: Overgrown.
Location:Pavement.
Type:Foliage / Bush
Location: Overgrown hedge and bushes causing the pavement to be obstructed at the corner of Wilton Road and Craigmillar Park
Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect
on: 20/06/2022 17:09
Classification: Request for service
Contact:

Enquiry No.: 1349986
Service: Roads General
Desc.:
Location: Large deep pothole in road. Some traffic veering partly onto other side of road to avoid it.
Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged
on: 23/03/2022 12:56
Classification: Request for service
Contact:

Plot Number: 1.00
Job Number: 50110149
Feature Id - Location: Whole Street
Defect Number: 42097524
Feature Type: Road Asset

Enquiry No.: 1347998
Service: Roads General
Desc.:
Location: 2large pot holes that are difficult to avoid due to cycle lane bollards
Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged
on: 20/03/2022 10:05
Classification: Request for service
Contact:

Plot Number: 1.00
Job Number: 50109814
Feature Id - Location: Whole Street
Defect Number: 42097175
Feature Type: Road Asset

Enquiry No.: 1345180
Service: Roads General
Desc.:
Location: There is a pothole in the northbound lane
Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged
on: 14/03/2022 18:48
Classification: Request for service
Contact:

Plot Number: 1.00
Feature Id - Location: Whole Street
Feature Type: Road Asset

Enquiry No.: 1340336
Service: Roads General
Desc.:
Location: a series of potholes on Craigmillar Park. When coming from Cameron Toll, they are just before St Margaret's Nursery (10 Craigmillar Park, Edinburgh EH16 5NE).
Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged
on: 06/03/2022 18:14
Classification: Request for service
Contact:

Enquiry No.: 1331909
Service: Roads General
Desc.:
Location: Failed reinstatement of tarmac across the entire lane.
Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged
on: 22/02/2022 13:19
Classification: Request for service
Contact:

Plot Number: 1.00
Feature Id - Location: Whole Street
Feature Type: Road Asset

Enquiry No.: 1330542
Service: Roads General
Desc.:
Location: Near the corner of Suffolk Road, a big pothole
Logged by: Verint CRM Connector
Subject: Road: Defective / Damaged
on: 20/02/2022 15:57
Classification: Request for service
Contact:

Plot Number: 1.00
Job Number: 50106961
Feature Id - Location: Whole Street
Defect Number: 42093588
Feature Type: Road Asset

Site History Report

Effective: 01/06/2021 to 05/07/2026

Service: Roads General

Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Customer Services

Enquiry No.: 1328542 **Logged by:** Verint CRM Connector **on:** 17/02/2022 12:26
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Sunken drain which has just got deeper...its been there for long long time...tyre can go right into it! **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Enquiry No.: 1328144 **Logged by:** Verint CRM Connector **on:** 16/02/2022 19:50
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: 2 large potholes, one next to the spaces for people bollards, one opposite **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50106543 **Defect Number:** 42093127

Enquiry No.: 1322909 **Logged by:** Verint CRM Connector **on:** 09/02/2022 07:45
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Pothole on road near island outside St Margaret's nursery near junction with Suffolk Road & Craigmillar park **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50105907 **Defect Number:** 42092500

Enquiry No.: 1318558 **Logged by:** Verint CRM Connector **on:** 02/02/2022 07:37
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole on road in front of 16 Craigmillar Park. **Contact:**

Enquiry No.: 1316709 **Logged by:** Verint CRM Connector **on:** 30/01/2022 13:11
Service: Roads General **Subject:** Pavement: Damaged / Defective **Classification:** Request for service
Desc.:
Location: On road in to the blind school large pothole. This caused me to fall while running and damage knees and shoulder **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50104784 **Defect Number:** 42091432

Enquiry No.: 1315800 **Logged by:** Verint CRM Connector **on:** 28/01/2022 16:56
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Large pothole has developed on the left hand side of the road, heading into town. **Contact:**

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset

Job Number: 50104779 **Defect Number:** 42091427

Enquiry No.: 1315181 **Logged by:** Verint CRM Connector **on:** 27/01/2022 18:41
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: Potholes **Contact:**

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1274174
Service: Roads General
Desc.: Problem: Obscuring sign/light.
Location:Pavement.
Type:Foliage / Bush
Location: Obstructing street light

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 13/11/2021 01:05
Classification: Request for service

Contact:

Enquiry No.: 1274173
Service: Roads General
Desc.: Problem: Obscuring sign/light.
Location:Pavement.
Type:Foliage / Bush
Location: Obstructing street light

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 13/11/2021 01:04
Classification: Request for service

Contact:

Enquiry No.: 1274172
Service: Roads General
Desc.: Problem: Obscuring sign/light.
Location:Pavement.
Type:Foliage / Bush
Location: Obstructing street light

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 13/11/2021 01:03
Classification: Request for service

Contact:

Enquiry No.: 1274171
Service: Roads General
Desc.: Problem: Obscuring sign/light.
Location:Pavement.
Type:Foliage / Bush
Location: Obstructing street light

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 13/11/2021 01:01
Classification: Request for service

Contact:

Enquiry No.: 1274170
Service: Roads General
Desc.: Problem: Obscuring sign/light.
Location:Pavement.
Type:Foliage / Bush
Location: Obstructing light

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 13/11/2021 00:59
Classification: Request for service

Contact:

Enquiry No.: 1274169
Service: Roads General
Desc.: Problem: Obscuring sign/light.
Location:Pavement.
Type:Foliage / Bush
Location: Obstructing sign

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 13/11/2021 00:56
Classification: Request for service

Contact:

Enquiry No.: 1274168
Service: Roads General
Desc.: Problem: Obscuring sign/light.
Location:Pavement.
Type:Foliage / Bush
Location: Tree obstructing light

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 13/11/2021 00:54
Classification: Request for service

Contact:

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1274167
Service: Roads General
Desc.: Problem: Obscuring sign/light.
Location:Pavement.
Type:Foliage / Bush
Location: Covering street sign

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 13/11/2021 00:52
Classification: Request for service

Contact:

Enquiry No.: 1273894
Service: Roads General
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Causing obstruction.

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 12/11/2021 13:17
Classification: Request for service

Contact:

Enquiry No.: 1234613
Service: Roads General
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Overgrown foliage here (for a very long time) which makes is hard for pedestrians to get past

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 26/08/2021 17:57
Classification: Request for service

Contact:

Enquiry No.: 1226189
Service: Roads General
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: Very overgrown hedge which makes the pavement narrow and cramped

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 11/08/2021 18:20
Classification: Request for service

Contact:

Enquiry No.: 1226188
Service: Roads General
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: The hedge is really overgrown

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 11/08/2021 18:19
Classification: Request for service

Contact:

Enquiry No.: 1198613
Service: Roads General
Desc.: Problem: Causing Obstruction.
Location:Pavement.
Type:Foliage / Bush
Location: The hedge here on the East Suffolk Road side of the property is badly overgrown and serious obstructs pedestrian passage along the pavement.

Logged by: Verint CRM Connector
Subject: Trees & Foliage: Defect

on: 29/06/2021 16:24
Classification: Request for service

Contact:

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Customer Services

Enquiry No.: 1191779 **Logged by:** Verint CRM Connector **on:** 16/06/2021 11:45
Service: Roads General **Subject:** Road: Defective / Damaged **Classification:** Request for service
Desc.:
Location: On the junction of Lady Road/Craigmillar Park. Large metal cover, sharp north edge **Contact:**
 exposed, with deep hole alongside, vary dangerous for bicycles.

Plot Number: 1.00 **Feature Id - Location:** Whole Street **Feature Type:** Road Asset
Job Number: 50085374 **Defect Number:** 42071299

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50089493	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	16/08/2021	16/08/2021	Act. ROAD/82053175
50089748	Potholes x 3 as marked (RD: CW Opp no 28 Pothole)		RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/08/2021	18/08/2021	Act. ROAD/82053261
50090655	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	30/08/2021	30/08/2021	Act. ROAD/82053801
50097808	Replaced missing bollards (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	19/11/2021	19/11/2021	Act. ROAD/82056566
50101691	Replaced missing bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	05/01/2022	05/01/2022	Act. ROAD/82058130
50104779	CW pothole marked onsite (RD: CW Pothole)	Craigmillar park city bound outside no. 16	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/01/2022	01/02/2022	Act. ROAD/82059531
50104784	Cw pothole marked on site (RD: CW Pothole)	Craigmillar park city bound outside gate of Cala home site per map	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/01/2022	01/02/2022	Act. ROAD/82059536
50104786	CW potholes marked on site x2 (RD: CW Pothole)	Craigmillar park opposite A digger & driver hire park	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	31/01/2022	01/02/2022	Act. ROAD/82059538
50105907	Cw pothole marked on site (RD: CW Pothole)	Craigmillar park at Suffolk rd	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/02/2022	14/02/2022	Act. ROAD/82060045
50106543	Cw potholes marked on site x2 (RD: CW Pothole)	Craigmillar park os 16/14	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/02/2022	18/02/2022	Act. ROAD/82060384
50106961	Cw pothole at crossing (RD: CW Pothole)	Craigmillar park at Suffolk rd	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/02/2022	23/02/2022	Act. ROAD/82060605
50108812	2no potholes (RD: CW Pothole)	Opposite no28	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/03/2022	14/03/2022	Act. ROAD/82061617
50109814	Cw potholes marked on site x3 (RD: CW Pothole)	Craigmillar park city bound 16/14/12	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/03/2022	23/03/2022	Act. ROAD/82062061
50110149	Cw pothole marked on site (RD: CW Pothole)	Craigmillar park os 19	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/03/2022	29/03/2022	Act. ROAD/82062284
50110487	Cycle defender broken away from road and needs fixed ASAP (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	28/03/2022	19/04/2022	Act. ROAD/82062426
50111734	2no potholes (RD: CW Pothole)	Outside the Kildonan Lodgt	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/04/2022	13/04/2022	Act. ROAD/82063082

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: South East Locality		
50111735	1no pothole (RD: CW Pothole)	Outside no25	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/04/2022	13/04/2022	Act. ROAD/82063083
50113468	Cracked Broken cw, 6 x 0.5m (RD: CW Cracked/Broken)	At junction	RD: Cat 4 - Programmed	Job Complete	12/05/2022	16/04/2023	Act. ROAD/82066445
50113471	Broken cw (RD: CW Cracked/Broken)	Outside number 26	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/05/2022	16/05/2022	Act. ROAD/82063985
50113484	Cracked Cw (RD: CW Cracked/Broken)	At entrance to newington residence	RD: Cat 4 - Programmed	Job Complete	12/05/2022	29/09/2024	Act. ROAD/82096548
50113490	Pothole on cw (RD: CW Pothole)	Outside number 40	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/05/2022	13/05/2022	Act. ROAD/82063990
50115751	Cycle defender broken away from road and needs fixed back down please (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	27/06/2022	27/06/2022	Act. ROAD/82065202
50117881	Cw patching x3 1.5x1.5 3x3 1.2x5 (RD: CW Cracked/Broken)	Craigmillar park city bound inside Lane from liberton road	RD: Cat 4 - Programmed	Job Complete	25/08/2022	25/09/2022	Act. ROAD/82066446
50119916	Replaced damaged bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	12/10/2022	12/10/2022	Act. ROAD/82067459
50119917	Replaced damaged bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	12/10/2022	12/10/2022	Act. ROAD/82067460
50120025	Replaced damaged bollard (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	14/10/2022	14/10/2022	Act. ROAD/82067539
50124467	Cycle defender broken away from road and needs fixed back to road asap as hazard for cyclists (RD: SFP Damaged Bollard)		RD: Cat 2 - 5 Day	Job Complete	19/12/2022	21/12/2022	Act. ROAD/82069685
50124633	Remove No cold calling sign and old faded sign from lighting column. (RD: Unlit Sign Damaged/Missing)	On lighting column at junction with Ventnor Park	RD: Cat 3 - 60 Day	Job Complete	20/12/2022	23/12/2022	Act. ROAD/82069784
50124977	Cw pothole marked on site (RD: CW Pothole)	Craigmillar park at Cala development	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	28/12/2022	29/12/2022	Act. ROAD/82070008
50127596	Cw pothole marked on site Road: Defective / Damaged (Enquiry 1493472) (RD: CW Pothole)	Craigmillar park outside 16	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/01/2023	03/02/2023	Act. ROAD/82071795
50130174	1 cw pothole (RD: CW Pothole)	At junction with Gordon terrace	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/02/2023	27/02/2023	Act. ROAD/82073328
50130624	Cw x 2 potholes Road: Defective / Damaged (Enquiry 1513478) (RD: CW Pothole)	Outside of number 33/35	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/02/2023	02/03/2023	Act. ROAD/82073558

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: South East Locality		
50130953	Cw x 2 Road: Defective / Damaged - Pothole (Enquiry 1517775) (RD: CW Pothole)	Outside of number 56-58	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/03/2023	03/03/2023	Act. ROAD/82073748
50131182	Cw x 1 pothole Road: Defective / Damaged (Enquiry 1518305) (RD: CW Pothole)	Outside of number 40	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/03/2023	06/03/2023	Act. ROAD/82073860
50132918	1no pothole (RD: CW Pothole)	Opposite no2	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/03/2023	27/03/2023	Act. ROAD/82074820
50132924	1no pothole (RD: CW Pothole)	Outside no60	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/03/2023	27/03/2023	Act. ROAD/82074825
50133149	Cw x 2 potholes Road: Defective / Damaged (Enquiry 1527401) (RD: CW Pothole)	Outside of number 12a	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/03/2023	29/03/2023	Act. ROAD/82074956
50133298	Cw c1 pothole (RD: CW Pothole)	Out of number 1 at ped crossing	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/03/2023	31/03/2023	Act. ROAD/82075066
50134356	Cw x2 potholes Road: Defective / Damaged (Enquiry 1537767) (RD: CW Pothole)	Outside of number 14	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/04/2023	18/04/2023	Act. ROAD/82075866
50134357	Cw x 1,pothole Road: Defective / Damaged (Enquiry 1537766) (RD: CW Pothole)	Outside of St Margaret's School	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/04/2023	18/04/2023	Act. ROAD/82075867
50134360	Cw x3 potholes Road: Defective / Damaged (Enquiry 1537761) (RD: CW Pothole)	Opposite Cala homes development	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/04/2023	18/04/2023	Act. ROAD/82075871
50134361	Road: Defective / Damaged (Enquiry 1537761) (RD: CW Pothole)	Opposite Cala homes development	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/04/2023	18/04/2023	Act. ROAD/82075872
50134365	Cw x 1 pothole Road: Defective / Damaged (Enquiry 1537764) (RD: CW Pothole)	Outside of number 2	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/04/2023	18/04/2023	Act. ROAD/82075877
50134881	Cw x2, potholes Road: Defective / Damaged (Enquiry 1541599) (RD: CW Pothole)	Outside of number 60 at the junction with Lady Road crossroads	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/04/2023	25/04/2023	Act. ROAD/82076255
50135005	2 carriageway potholes (RD: CW Pothole)	Opposite 28	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/04/2023	26/04/2023	Act. ROAD/82076311
50135048	Fw x1 pothole Pavement: Damaged / Defective (Enquiry 1541946) (RD: FW HRA Pothole)	Outside of number 26	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/04/2023	26/04/2023	Act. ROAD/82076383
50135051	Cw x1 1pothole Road: Defective / Damaged (Enquiry 1541798) (RD: CW Pothole)	At the junction with East Savile Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	26/04/2023	26/04/2023	Act. ROAD/82076385
50135322	Pothole pro 2 x 4.5 (RD: CW Cracked/Broken)	Opposite 24	RD: Cat 4 - Programmed	Job Complete	01/05/2023	10/09/2023	Act. ROAD/82076625
50135324	Pothole pro 1 x 5 (RD: CW Cracked/Broken)	Opposite 28	RD: Cat 4 - Programmed	Job Complete	01/05/2023	10/09/2023	Act. ROAD/82076624

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50135325	Pothole 2 x 4.5 (RD: CW Cracked/Broken)	Opposite 30	RD: Cat 4 - Programmed	RD: Made Safe Job Complete	01/05/2023	10/09/2023	Act. ROAD/82076623
50135326	Pothole pro 3.5 x 1.2 (RD: CW Cracked/Broken)	Outside 16	RD: Cat 4 - Programmed	Job Complete	01/05/2023	10/09/2023	Act. ROAD/82076622
50135327	Pothole pro 4 x 1 (RD: CW Cracked/Broken)	Outside 14	RD: Cat 4 - Programmed	Job Complete	01/05/2023	03/09/2023	Act. ROAD/82076621
50135329	Pothole pro 1 x 2.2 (RD: CW Cracked/Broken)	Outside 12A	RD: Cat 4 - Programmed	RD: Made Safe Job Complete	01/05/2023	10/09/2023	Act. ROAD/82076620
50135330	Pothole pro 2.2 x 1.2 (RD: CW Cracked/Broken)	Outside 10	RD: Cat 4 - Programmed	RD: Made Safe Job Complete	01/05/2023	10/09/2023	Act. ROAD/82076619
50135331	Pothole pro 3.5 x 1.5 (RD: CW Cracked/Broken)	Opposite Cala development	RD: Cat 4 - Programmed	Job Complete	01/05/2023	10/09/2023	Act. ROAD/82076618
50135332	Pothole pro 1.8 x 1.4 (RD: CW Cracked/Broken)	Opposite Cala developments	RD: Cat 4 - Programmed	Job Complete	01/05/2023	10/09/2023	Act. ROAD/82076617
50135333	Pothole pro 3 x 1.5 (RD: CW Cracked/Broken)	Opposite Craigmillar park church	RD: Cat 4 - Programmed	Job Complete	01/05/2023	03/09/2023	Act. ROAD/82076616
50135334	Pothole pro x2 7 x 1.5 and 1 x 1 (RD: CW Cracked/Broken)	Outside 3	RD: Cat 4 - Programmed	Job Complete	01/05/2023	03/09/2023	Act. ROAD/82076615
50137446	Cw x1 pothole Road: Defective / Damaged (Enquiry 1563281) (RD: CW Pothole)	Opposite number 28 , heading out of town	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/06/2023	08/06/2023	Act. ROAD/82078069
50138337	Black pole missing from cycle lane bollard (RD: SFP Damaged Bollard)	Outside of number 9	RD: Cat 4 - Programmed	Job Complete	26/06/2023	02/10/2023	Act. ROAD/82081158
50140324	Cw x1 pothole Road: Defective / Damaged (Enquiry 1591252) (RD: CW Pothole)	At the crossroads of Lady Road Esslemont Road, heading into the city	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/08/2023	03/08/2023	Act. ROAD/82079675
50141228	Cycle lane pole missing, please replace (RD: SFP Damaged Bollard)	Outside of number 9	RD: Cat 4 - Programmed	Job Complete	17/08/2023	02/10/2023	Act. ROAD/82081159
50141283	Cw x3 potholes Road: Defective / Damaged (Enquiry 1601034) (RD: CW Pothole)	Outside of number 25 (heading out of town)	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/08/2023	21/08/2023	Act. ROAD/82080124
50141284	Cw x3 potholes (RD: CW Pothole)	Outside of number 12	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/08/2023	21/08/2023	Act. ROAD/82080125
50144143	1 carriageway pothole (RD: CW Pothole)	Bottom of Craigmillar park at crossing	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/10/2023	17/10/2023	Act. ROAD/82081695
50145117	Cw x1 pothole Road: Defective / Damaged (Enquiry 1639037) (RD: CW Pothole)	Outside of number 27	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/11/2023	06/11/2023	Act. ROAD/82082373
50145118	Cw x 1 pothole Road: Defective / Damaged (Enquiry 1638440) (RD: CW Pothole)	Outside of number 33	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/11/2023	06/11/2023	Act. ROAD/82082374

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
	Asset: 1.00	Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50145522	Cw x1 pothole Road: Defective / Damaged (Enquiry 1641998) (RD: CW Pothole)	Outside of number 62	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/11/2023	13/11/2023	Act. ROAD/82082585
50147682	Cw x1 pothole Road: Defective / Damaged (Enquiry 1658465) (RD: CW Pothole)	At the junction with East Suffolk Park	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/12/2023	13/12/2023	Act. ROAD/82083790
50147840	RD: CW Pothole	Outside number 62 at pedestrian crossing	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/12/2023	15/12/2023	Act. ROAD/82083898
50149186	Cw x1 pothole Road: Defective / Damaged (Enquiry 1669060) (RD: CW Pothole)	Outside of number 62	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/01/2024	15/01/2024	Act. ROAD/82084796
50149188	Cw x 1 pothole Road: Defective / Damaged (Enquiry 1668191) (RD: CW Pothole)	Opposite number 32 , south bound	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/01/2024	05/01/2024	Act. ROAD/82084798
50149696	Cw x 3 potholes Road: Defective / Damaged (Enquiry 1674284) (RD: CW Pothole)	Bus stop outside of number 40 and outside of number 50	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/01/2024	15/01/2024	Act. ROAD/82085126
50149817	Cw x1 pothole Road: Defective / Damaged (Enquiry 1674782) (RD: CW Pothole)	At the junction with East Suffolk Park	RD: Cat 3 - 60 Day	Job Complete	10/01/2024	15/01/2024	Act. ROAD/82085189
50150806	Cw x2 potholes Road: Defective / Damaged (Enquiry 1682069) (RD: CW Pothole)	Outside the Northumberland Hotel	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	22/01/2024	05/02/2024	Act. ROAD/82085831
50151094	Cw x1 pothole Road: Defective / Damaged (Enquiry 1684586) (RD: CW Pothole)	At the pedestrian crossing heading southbound at th junction of East Suffolk Road	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	24/01/2024	25/01/2024	Act. ROAD/82086036
50152366	Cw x1 pothole Road: Defective / Damaged (Enquiry 1693442) (RD: CW Pothole)	Outside of number 62	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2024	15/02/2024	Act. ROAD/82086967
50152862	2 panel of railings damage and broken Fence: Damaged / Defective (Enquiry 1698073) (RD: Railing Damage/Missing/New)	Crossing island railings are damaged; esslemont road and Craigmillar park	RD: Cat 3 - 60 Day	Job Complete	13/02/2024	22/02/2024	Act. ROAD/82087329
50153208	Cw x1 pothole Road: Defective / Damaged (Enquiry 1700209) (RD: CW Pothole)	At the junction with East Suffolk Park	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	16/02/2024	18/02/2024	Act. ROAD/82087563
50153211	Cw x1 pothole (RD: CW Pothole)	At the junction with Lady Road (Southbound)	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/02/2024	27/02/2024	Act. ROAD/82087566
50155667	Cw x6 potholes Road: Defective / Damaged (Enquiry 1714473) (RD: CW Pothole)	Outside the Kildonan Lodge (southbound)	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/03/2024	19/03/2024	Act. ROAD/82089298
50156508	Cw x1 pothole Road: Defective / Damaged (Enquiry 1721782) (RD: CW Pothole)	At the junction with East Suffolk Park	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	21/03/2024	23/03/2024	Act. ROAD/82089861

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: South East Locality		
50156747	Cw x1 pothole Road: Defective / Damaged (Enquiry 1722866) (RD: CW Pothole)	Outside of 19 after pedestrian crossing (Southbound)	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	24/03/2024	26/03/2024	Act. ROAD/82090022
50156781	Cw x1 pothole Road: Defective / Damaged (Enquiry 1723824) (RD: CW Pothole)	At the with Lady Road (Southbound)	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/03/2024	28/03/2024	Act. ROAD/82090054
50156946	Cycle lane bollard dislodged (RD: SFP Damaged Bollard)	At the junction with East Suffolk Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	27/03/2024	18/04/2024	Act. ROAD/82090177
50157794	Cw x1 pothole Road: Defective / Damaged (Enquiry 1726710) (RD: CW Pothole)	Outside of 60 / heading into city centre	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/04/2024	10/04/2024	Act. ROAD/82090834
50157813	Cw x1 pothole Road: Defective / Damaged (Enquiry 1728907) (RD: CW Pothole)	Outside of kildonan hotel (Southbound) painted but washed off	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	09/04/2024	10/04/2024	Act. ROAD/82090846
50158649	Railings damage approximately 2mts (RD: Railing Damage/Missing/New)	At the junction with Craigmillar Park Esslemont Road and Lady Road (pedestrian crossing	RD: Cat 3 - 60 Day	Job Complete	17/04/2024	14/05/2024	Act. ROAD/82091477
50161335	Cw x1 pothole Road: Defective / Damaged (Enquiry 1766064) (RD: CW Pothole)	At the junction with Gordon Terrace	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	29/05/2024	30/05/2024	Act. ROAD/82093079
50163154	Cw x2 potholes Road: Defective / Damaged (Enquiry 1789734) (RD: CW Pothole)	Outside of 23	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	01/07/2024	03/07/2024	Act. ROAD/82094268
50165077	1no Fw pothole at gas Toby (RD: FW HRA Pothole)	Outside no6	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/08/2024	09/08/2024	Act. ROAD/82095506
50165082	1no Fw pothole bollard stump please make safe (RD: FW HRA Pothole)	At junction with Wilton road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/08/2024	09/08/2024	Act. ROAD/82095509
50165084	Cw breaking up approx 8m x 1.5m (RD: CW Cracked/Broken)	Outside no42 David horn house at bus stop	RD: Cat 4 - Programmed	RD: Made Safe Job Complete	08/08/2024	29/09/2024	Act. ROAD/82096549
50165384	Bus stop has been taken away leaving a metal stump Please cut stump away and make safe (RD: FW HRA Pothole)	Opposite lygon rd	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	15/08/2024	15/08/2024	Act. ROAD/82095651
50166480	Cw x5 potholes Road: Defective / Damaged - please inspect road surface between the southbound carriage between East Suffolk Road and East Suffolk Park. causing vibrations to houses when large vehcles driving by. (Enquiry 34009031) (RD: CW Pothole)	Southbound outside of 25	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/09/2024	13/09/2024	Act. ROAD/82096268
50168406	1no missing bollard (RD: SFP Damaged Bollard)	Outside 25	RD: Cat 3 - 60 Day	Job Complete	21/10/2024	28/10/2024	Act. ROAD/82097542

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: South East Locality		
50168570	1no missing sfp bollard (RD: SFP Outside no23 Damaged Bollard)		RD: Cat 3 - 60 Day	Job Complete	23/10/2024	28/10/2024	Act. ROAD/82097663
50170949	Damaged lane defender needs secured (RD: SFP Damaged Bollard)	Opposite no 10	RD: Cat 3 - 60 Day	Job Complete	06/12/2024	10/12/2024	Act. ROAD/82099227
50171331	No 1 pothole (RD: CW Pothole)	At junction at lamppost cvh20	RD: Cat 3 - 60 Day	Job Annulled	12/12/2024	12/12/2024	Act. ROAD/82099538
50171332	No 1 pothole (RD: CW Pothole)	At lamppost cvh 20 at junction	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/12/2024	12/12/2024	Act. ROAD/82099539
50172597	2no potholes (RD: CW Pothole)	In the middle of the road at the junction with James Gall Wynd	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	10/01/2025	14/01/2025	Act. ROAD/82100558
50173091	2 no potholes (RD: CW Pothole)	Opposite no 30 Kingsley guest house	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	17/01/2025	22/01/2025	Act. ROAD/82100932
50173335	Tar squad has removed a Sfp bollard and haven't put it back (RD: SFP Damaged Bollard)	on the pavement in front of No. 48	RD: Cat 3 - 60 Day	Job Complete	21/01/2025	03/02/2025	Act. ROAD/82101078
50174020	1no pothole (RD: CW Pothole)	At the junction with East Suffolk Park	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/01/2025	02/02/2025	Act. ROAD/82101615
50174107	No 1 pothole (RD: CW Pothole)	At junction of craigmiller park and Wilton road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	03/02/2025	04/02/2025	Act. ROAD/82101677
50174110	Track sunk 5 m length x 1 width (RD: CW Subsidence/Heaving)	Opposite no 18	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	03/02/2025	04/02/2025	Act. ROAD/82101679
50175663	2no Cw potholes (RD: CW Pothole)	Craigmillar park at traffic lights south bound towards Cameron toll	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	21/02/2025	27/02/2025	Act. ROAD/82102981
50175729	No 1 pothole (RD: CW Pothole)	At crossing point at traffic lights heading into town at start of craigmiller park	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	24/02/2025	24/02/2025	Act. ROAD/82103039
50176572	No 1 pothole (RD: CW Pothole)	Just south of no 1 a	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	07/03/2025	13/03/2025	Act. ROAD/82103727
50176933	2 no potholes (RD: CW Pothole)	Outside no 50 A opposite Northumberland hotel	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/03/2025	14/03/2025	Act. ROAD/82104012
50179889	1 no pothole) (RD: CW Pothole)	Outside the kildonan lodge hotel sound bound lane	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/05/2025	14/05/2025	Act. ROAD/82106017
50183916	3no bollard stumps need removed/ made safe and infilled with grano (RD: FW Grano Pothole)	Outside no40	RD: Cat 3 - 60 Day	Job Complete	21/08/2025	04/09/2025	Act. ROAD/82108517
50183922	1no pole needs straightened as pole is leaning, causing sign to face away from road Sign and pole undamaged (TS: Sign Orientation Incorrect)	Outside no7	RD: Cat 3 - 60 Day	Job Complete	21/08/2025	20/09/2025	Act. ROAD/82108521
50183924	Renew 1no missing Edinburgh bollard (RD: Bollard Damage/Missing/New)	At junction with Suffolk road	RD: Cat 3 - 60 Day	Job Complete	21/08/2025	22/09/2025	Act. ROAD/82108523

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street	Feature Type: Road Asset		Area: South East Locality		
50185551	No 1 pothole (RD: CW Pothole)	At crossing point opposite lampost CVH20	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/10/2025	17/10/2025	Act. ROAD/82109633
50186070	2no missing Sfp bollards (RD: SFP Damaged Bollard)	Outside no 34 / 28	RD: Cat 3 - 60 Day	Job Complete	26/10/2025	10/11/2025	Act. ROAD/82109953
50186245	No 1 pothole (RD: CW Pothole)	Near lampost CVH 20 heading south just before traffic lights near kerb	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	30/10/2025	03/11/2025	Act. ROAD/82110069
50186356	2no missing bollards (RD: SFP Damaged Bollard)	Outside no26 and 32	RD: Cat 3 - 60 Day	Job Complete	02/11/2025	10/11/2025	Act. ROAD/82110118
50186878	No1 pothole (RD: CW Pothole)	At bustop opposite lampost CVH03	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	13/11/2025	14/11/2025	Act. ROAD/82110448
50188228	Non1 pothole (RD: CW Pothole)	Outside no 3 at bustopn	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/12/2025	12/12/2025	Act. ROAD/82111465
50188230	2 no potholes (RD: CW Pothole)	Outside 14/16Craigmillar park	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	08/12/2025	12/12/2025	Act. ROAD/82111467
50189398	1no pothole (RD: CW Pothole)	At the bus stop outside no2	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	10/01/2026	12/01/2026	Act. ROAD/82112407
50189900	1no pothole (RD: CW Pothole)	In the cycle box at the corner of Lady Road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	19/01/2026	20/01/2026	Act. ROAD/82112802
50190333	1no cw pothole (RD: CW Pothole)	Outside no3 at bus stop	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	26/01/2026	27/01/2026	Act. ROAD/82113154
50190957	No 1 pothole (RD: CW Pothole)	Outside travel lodge at lights heading south at lampost CVH20	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	02/02/2026	03/02/2026	Act. ROAD/82113650
50191243	No 2 potholes (RD: CW Pothole)	Outside no 14	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	06/02/2026	06/02/2026	Act. ROAD/82113894
50191957	2no potholes (RD: CW Pothole)	Outside the Travelodge near the lights	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	15/02/2026	16/02/2026	Act. ROAD/82114485
50192570	1no Cw pothole (RD: CW Pothole)	At bus stop outside no3	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	23/02/2026	23/02/2026	Act. ROAD/82115031
50192769	No 1 pothole (RD: CW Pothole)	Outside no 12 a heading north	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/02/2026	02/03/2026	Act. ROAD/82115189
50193720	Cracked broken tar 20 m x 1.5 (RD: CW Cracked/Broken)	From no 12 a to no 14 Craig miller park	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	11/03/2026	20/04/2026	Act. ROAD/82115969
50193779	Cracked broken tar 2 m x 1.5 (RD: CW Cracked/Broken)	Outside no 54 Craig miller park	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	12/03/2026	20/04/2026	Act. ROAD/82116009
50193902	1no pothole (RD: CW Pothole)	Outside no23	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/03/2026	19/03/2026	Act. ROAD/82116104
50193903	1no pothole (RD: CW Pothole)	Outside Travelodge	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	16/03/2026	19/03/2026	Act. ROAD/82116105
50194072	No 1 pothole (RD: CW Pothole)	Craigmillar park at junction with east Suffolk road	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	18/03/2026	19/03/2026	Act. ROAD/82116237
50194501	2 m x 2 m tar patch required (RD: CW Cracked/Broken)	Next to the crossing island, around water hydrant near lampost CVH21	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	25/03/2026	19/04/2026	Act. ROAD/82116567

Site History Report

Effective: 01/06/2021 to 05/07/2026
Service: Roads General
Site: Craigmillar Park (7901732)

Asset Number: 1.00 to 9.00
Display Action Officer: No

Maintenance Management

Job No.	Description	Location	Priority	Job Status	Entered	Completion	Works Order
Asset: 1.00		Asset - Locn.: Whole Street		Feature Type: Road Asset		Area: South East Locality	
50194728	No 1 pothole (RD: CW Pothole)	Outside no 10 st Margaret's Nursery in northbound lane at island	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	31/03/2026	31/03/2026	Act. ROAD/82116711
50195059	No 1 pothole (RD: CW Pothole)	At bustop heading south outside no 3	RD: Cat 2 - 5 Day	RD: Made Safe Job Complete	08/04/2026	09/04/2026	Act. ROAD/82116994
50195328	No 1 pothole (RD: CW Pothole)	At traffic lights heading south at lampost CVH20	RD: Cat 3 - 60 Day	RD: Made Safe Job Complete	14/04/2026	14/04/2026	Act. ROAD/82117220