

63477 Pavement on Belford Road

Please confirm/ provide the following:

Information on whether the cover located on the pavement situated on Belford Road, outside Belford Hostel, Edinburgh, is recorded as a Road Authority asset.

The cover on footway outside Belford Hostel is not recorded as a Road Authority asset.

Information on whether the cover located on the pavement situated on Belford Road, outside Belford Hostel, Edinburgh, is associated with the cellar of the vault beneath the pavement.

The cover located on footway outside Belford Hostel is believed to be an old coal chute associated with Belford Hostel building.

Who is recorded as the owner of the cover and structure beneath?

We do not hold a record of the owner of the cover and structure beneath, associated with the Belford Hostel building.

Has the Council previously repaired or replaced the cover?

There are no records to show the Council previously repaired or replaced the cover.

Is the Council responsible for the inspection and maintenance of the cover?

The Council is not responsible for maintenance of covers that are owned privately or by third-party/statutory undertakers.

Information as to when the Council placed the plastic manhole cover on top of the damaged cover that is situated on Belford Road, outside Belford Hostel, Edinburgh.

The Council did not place the plastic manhole cover on top of the damaged cover situated outside Belford Hostel. The Council installed a walkboard on or around 18/02/2025.