

Site History Report

Effective: 12/07/2025 to 12/07/2026

Service: Roads General

Site: Graham Street (7901156)

Asset Number: 1.00 to 9.00

Display Action Officer: No

Site: Graham Street (7901156)

Locality: Bonnington, Edinburgh, City of Edinburgh

Area: North East Locality

Condition Survey

Defect No:	Description	Log Date	Location	Defect Type	Class.	Organisation	Status	Job No.
Asset:	1.00	Asset - Locn.: From Newhaven Rd east to end of setted cway. Area beyond ea			Feature Type: Road Asset		Area: North East Locality	
Batch: 41251633 - Inspection Batch			Route: NE_CF2_BonningtonCentral1				Date: 03/02/2026	
42198355	Missing bollard	03/02/2026	Outside 13	RD: Bollard Damage/Missing/Nev	Internal		Uncommitted	50173611
42198352	Refresh give way markings	03/02/2026	At newhaven road	RD: Markings Refresh	Internal		Uncommitted	50173585
42198353	.5x.5m patch	03/02/2026	Junction with newhaven road	RD: CW Cracked/Broken	Internal		Uncommitted	50191006